

---

# Title List of Documents made Publicly Available

July 1 - 31, 1979

---

Office of Administration  
U. S. Nuclear Regulatory  
Commission



Available from  
GPO Sales Program  
Division of Technical Information and Document Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

and

National Technical Information Service  
Springfield, Virginia 22161

---

# Title List of Documents made Publicly Available

July 1 - 31, 1979

---

**Division of Technical Information and Document Control  
Office of Administration  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555**







## CONTENTS

Preface .....	v
Arrangements of Items by Docket Number .....	ix
Arrangement of Docket 50 Facility Name .....	xix
Docketed Items .....	1
Low Level Radwaste Disposal Sites - Docket 27 .....	1
Domestic Licensing of Source Material - Docket 40 .....	1
Domestic Licensing of Production and Utilization Facilities - Docket 50 .....	5
Domestic Licensing of Special Nuclear Material - Docket 70 .....	303
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71 .....	314
Nondocketed Items .....	327
10CFR – Commission Meeting Records .....	327
ACRS – Advisory Committee on Reactor Safeguards .....	328
AGREEMENT – State Agreements and Programs .....	328
COMMISSION – NRC Commissioners .....	328
CONTRACT – NRC Contracts and Modifications .....	332
FOIA – Freedom of Information Act Requests and Releases .....	335
GEN TECH IS – Generic Technical Issues .....	342
I&E – Inspection and Enforcement .....	342
NUREG – NUREG Reports and Related Correspondence .....	342
ORG – Correspondence with other organizations .....	348
PR – Proposed Rule .....	349
PRM – Petition for Rulemaking .....	353
PROJ – Projects-Predocket Licensing .....	356
PT21 – Noncompliance Reports and Related Correspondence .....	357
QA999 – Quality Assurance Inspections .....	357
REGGD – Regulatory Guides .....	360
RES – Research and Technical Assistance Reports .....	365
REVIEW GRP – NRC Research Review Groups .....	366
RM – Rulemakings .....	366
SECY – Position Papers Before the Commission .....	366
TOPREP – Vendor Reports and Related Correspondence .....	368
WASTE MGT – Nuclear Waste Management .....	370
XPORTLIC – Export and Import Licenses .....	371
Personal Author Index .....	381
Corporate Source Index - By Corporate Types .....	433
Citizen Group/Individual/Media .....	433
Engineering/Construction/Consultants/Services .....	435
Educational Institutions .....	435

## CONTENTS (Cont'd.)

Foreign Governments and Agencies .....	435
Legal/Law Firms/Insurance Companies .....	435
Local Government and Agencies .....	437
Medical Institutions and Laboratories .....	437
Manufacturers/Equipment and Supplies .....	437
Professional/Industrial Institutions, Societies .....	440
State Governments and Agencies .....	440
U.S. Federal Government and Agencies .....	441
Utilities, Holding Companies, Investor Associations .....	442
Research Institutions and Laboratories .....	454
U.S. Nuclear Regulatory Commission Organizational Source Index .....	457
Report Number Index .....	495
Cross Reference of Enclosures to Principal Documents .....	497
Appendix A - Definitions of Docket 50 Categories .....	511
Appendix B - Definitions of Nondocketed Categories .....	519

## PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title *Power Reactor Docket Information* (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The *Title List* series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the *Title List* and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material. Near the end of 1979, subscriptions will be solicited for Calendar Year 1980 at a fee yet to be established.

## DOCKETED ITEMS


Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NONDOCKETED ITEMS

Beginning with Vol. 1, No. 6, the nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:


- 10CFR — Commission Meeting Records
- ACRS — Advisory Committee on Reactor Safeguards
- AGREEMENT — State Agreements and Programs
- COMMISSION — NRC Commissioners
- CONTRACT — NRC Contracts and Modifications
- FOIA — Freedom of Information Act Requests and Releases
- GEN TECH IS — Generic Technical Issues
- I&E — Inspection and Enforcement
- NUREG — NUREG Reports and Related Correspondence
- ORG — Correspondence with other organizations
- PR — Proposed Rule
- PRM — Petition for Rulemaking
- PROJ — Projects-Predocket Licensing
- PT21 — Noncompliance Reports and Related Correspondence

QA999 – Quality Assurance Inspections  
 REGGD – Regulatory Guides  
 RES – Research and Technical Assistance Reports  
 REVIEW GRP – NRC Research Review Groups  
 RM – Rulemakings  
 SECY – Position Papers Before the Commission  
 TOPREP – Vendor Reports and Related Correspondence  
 WASTE MGT – Nuclear Waste Management  
 XPORTLIC – Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

① NUREG – NUREG Reports and Related Correspondence



1. Nondocketed category
2. NRC Accession Number
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author
6. Corporate, agency or other nonindividual source
7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
8. Date of document described
9. Pages in document
10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St , N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

## NOTES:

1. The address for NTIS is:  
National Technical Information Service  
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

2. The address for GPO is:  
Superintendent of Documents  
Government Printing Office  
Washington, D.C. 20402

To place orders for or to obtain price information about NRC publications at GPO, either write to GPO or call the Inquiry Desk at (202) 783-3238. Publications can be charged to VISA or Master-charge credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:  
1717 H Street, N.W.  
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

## ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL , Nuclear Engineering Co., Inc.	1	40-8681	Energy Fuels Nuclear, Inc.	4
27-047	Barnwell, SC., Chem-Nuclear Systems, Inc.	1	40-8692	Cotter Corp.	4
27-048	Richland, WA., Nuclear Engineering Co.	1	40-8693	Ogle Petroleum, Inc.	4
40-0299	Union Carbide Corp.	1	40-8698	Plateau Resources, Ltd.	4
40-1162	Western Nuclear, Inc.	1	40-8712	Gulf Oil Corp.	4
40-1739	Metals and Control, Inc.	2	40-8714	Cleveland Chffs Iron Co.	4
40-2061	West Chicago Facility, Kerr-McGee Corp.	2	40-8721	Rocky Mountain Energy Co.	4
40-2259	Pathfinder Mines Corp.	2	40-8722	Brush-Wellman, Inc.	4
40-3392	Allied Chemical Corp.	2	40-8725	Gulf Mineral Resources Co.	4
40-3453	Atlas Minerals	2	40-8726	New Mexico Health-Environment Dept.	4
40-4492	Federal American Partners	2	40-8729	Pioneer Uravan, Inc.	4
40-6659	Petrotomics Co.	2	50-2	Univ. of Michigan Research Reactor	5
40-7983	NL Industries, Inc.	2	50-3	Indian Point Station, Unit 1	5
40-8006	Kerr-McGee Corp.	3	50-5	Pennsylvania State Univ. Research Reactor	6
40-8027	Kerr-McGee Corp.	3	50-10	Dresden Nuclear Power Station, Unit 1	6
40-8064	Exxon Minerals Co.	3	50-13	Babcock & Wilcox Co. Critical Facility	8
40-8102	Exxon Minerals Co.	3	50-16	Enrico Fermi Atomic Power Plant, Unit 1	8
40-8211	Chamberlain Manufacturing Corp.	3	50-20	Massachusetts Institute of Technology Research Reactor	8
40-8304	Wyoming Mineral Corp.	3	50-22	Westinghouse Test Reactor	8
40-8452	Bear Creek Uranium Co.	3	50-27	Washington State Univ. Research Reactor	8
40-8502	Wyoming Mining Corp., Irigary Mine	3	50-29	Yankee-Rowe Nuclear Power Station	8
40-8584	Union 76 Minerals Exploration Co.	3	50-47	Army Materials Research Reactor	10
40-8585	Wyoming Mineral Corp.	3	50-54	Union Carbide Research Reactor	10
40-8602	United Nuclear Corp.	3	50-57	State Univ. of New York Research Reactor	10
40-8616	American Cynamid Co.	4			
40-8663	Nuclear Dynamics, Inc.	4			

Docket	Name	Page	Docket	Name	Page
50-59	Texas A & M Univ. Research Reactor	11	50-147	Rockwell Intl Corp. Critical Facility	15
50-62	Univ. of Virginia Research Reactor	11	50-148	Univ. of Kansas Research Reactor	15
50-70	General Electric Test Reactor	11	50-150	Ohio State Univ Research Reactor	16
50-72	Univ. of Utah Research Reactor	11	50-151	Univ of Illinois Research Reactor	16
50-73	General Electric Nuclear Test Reactor	11	50-155	Big Rock Point Nuclear Power Plant	16
50-77	Catholic Univ. of America Research Reactor	12	50-156	Univ. of Wisconsin Research Reactor	17
50-83	Univ. of Florida Training Reactor	12	50-157	Cornell Univ. Research Reactor	17
50-87	Westinghouse Critical Experiment	12	50-160	Georgia Institute of Technology Research Reactor	17
50-89	General Atomic Co.	12	50-163	General Atomic Co.	18
50-94	Rockwell International Research Reactor	12	50-166	Univ. of Maryland Research Reactor	18
50-97	Cornell Univ. Zero Power Reactor	12	50-170	National Naval Medical Center	18
50-99	Babcock & Wilcox Test Reactor	12	50-171	Peach Bottom Atomic Power Station, Unit 1	18
50-106	Oregon State Univ.	12	50-182	Purdue Univ. Research Reactor	18
50-111	North Carolina State Univ. Research Reactor	12	50-184	National Bureau of Standards Reactor	18
50-112	Univ. of Oklahoma Research Reactor	13	50-186	Univ. of Missouri Research Reactor	18
50-113	Univ. of Arizona Research Reactor	13	50-187	Space Radiation Research Reactor	18
50-115	Elk River Reactor	13	50-188	Kansas State Univ. Research Reactor	19
50-116	Iowa State Univ. Research Reactor	13	50-192	Univ. of Texas Research Reactor	19
50-123	Univ. of Missouri Research Reactor	13	50-193	Rhode Island & Providence Plantations AEC	19
50-124	Virginia Polytech Inst. Training Reactor	13	50-199	Manhattan College Research Reactor	19
50-128	Texas A & M Univ. Research Reactor	13	50-201	West Valley Reprocessing Plant	19
50-129	West Virginia Research Reactor	14	50-206	San Onofre Nuclear Station, Unit 1	20
50-131	Omaha Veterans Administration Hospital Research Reactor	14	50-208	Columbia Univ. Research Reactor	22
50-133	Humboldt Bay Power Plant, Unit 3	14	50-213	Haddam Neck Plant	22
50-134	Worcester Polytech Inst. Research Reactor	15	50-219	Oyster Creek Nuclear Power Plant	24
50-139	Univ. of Washington Research Reactor	15	50-220	Nine Mile Point Nuclear Station, Unit 1	25
50-142	UCLA Training Reactor	15	50-223	Univ. of Lowell Research Reactor	27
			50-224	Univ. of California Research Reactor	27



Docket	Name	Page	Docket	Name	Page
50-225	RPI Critical Experiment	27	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	67
50-228	Aerotest Radiography & Research Reactor	28	50-276	Georgia Tech Research Reactor	69
50-237	Dresden Nuclear Power Station, Unit 2	28	50-277	Peach Bottom Atomic Power Station, Unit 2	69
50-241	Mississippi State Univ. Research Reactor	30	50-278	Peach Bottom Atomic Power Station, Unit 3	71
50-243	Oregon State Univ. Research Reactor	30	50-280	Surry Power Station, Unit 1	73
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	30	50-281	Surry Power Station, Unit 2	76
50-245	Millstone Nuclear Power Station, Unit 1	32	50-282	Prairie Island Nuclear Station, Unit 1	78
50-247	Indian Point Station, Unit 2	34	50-284	Idaho State Univ. Research Reactor	80
50-249	Dresden Nuclear Power Station, Unit 3	36	50-285	Fort Calhoun Station, Unit 1	80
50-250	Turkey Point Plant, Unit 3	37	50-286	Indian Point Station, Unit 3	82
50-251	Turkey Point Plant, Unit 4	40	50-287	Oconee Nuclear Station, Unit 3	83
50-252	Univ. of New Mexico Research Reactor	42	50-288	Reed College Research Reactor	86
50-254	Quad-Cities Station, Unit 1	42	50-289	Three Mile Island Nuclear Station, Unit 1	86
50-255	Palisades Nuclear Plant	44	50-293	Pilgrim Nuclear Power Station, Unit 1	88
50-259	Browns Ferry Nuclear Power Station, Unit 1	46	50-294	Michigan State Univ. Research Reactor	90
50-260	Browns Ferry Nuclear Power Station, Unit 2	48	50-295	Zion Nuclear Power Station, Unit 1	90
50-261	H.B. Robinson Plant, Unit 2	49	50-296	Browns Ferry Nuclear Power Station, Unit 3	93
50-262	Brigham Young Univ. Research Reactor	51	50-297	North Carolina State Univ. PUSTAR Reactor	95
50-263	Monticello Nuclear Generating Plant	51	50-298	Cooper Nuclear Station	95
50-264	Dow Chemical Co.	53	50-301	Point Beach Nuclear Plant, Unit 2	97
50-265	Quad-Cities Station, Unit 2	53	50-302	Crystal River Nuclear Plant, Unit 3	98
50-266	Point Beach Nuclear Plant, Unit 1	54	50-303	Crystal River Nuclear Plant, Unit 4	101
50-267	Fort St. Vrain Nuclear Generating Station	56	50-304	Zion Nuclear Power Station, Unit 2	101
50-269	Oconee Nuclear Station, Unit 1	58	50-305	Kewaunee Nuclear Power Plant	104
50-270	Oconee Nuclear Station, Unit 2	60	50-306	Prairie Island Nuclear Station, Unit 2	106
50-271	Vermont Yankee Nuclear Power Station	63	50-309	Maine Yankee Atomic Power Plant	107
50-272	Salem Nuclear Generating Station, Unit 1	64	50-311	Salem Nuclear Generating Station, Unit 2	109
50-274	U.S. Geological Survey Research Reactor	67	50-312	Rancho Seco Nuclear Generating Station	111

<b>Docket</b>	<b>Name</b>	<b>Page</b>	<b>Docket</b>	<b>Name</b>	<b>Page</b>
50-313	Arkansas Nuclear One, Unit 1	113	50-348	Joseph M. Farley Nuclear Plant, Unit 1	181
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	116	50-352	Limerick Generating Station, Unit 1	183
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	118	50-353	Limerick Generating Station, Unit 2	184
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	119	50-354	Hope Creek Nuclear Station, Unit 1	185
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	121	50-355	Hope Creek Nuclear Station, Unit 2	185
50-320	Three Mile Island Nuclear Station, Unit 2	122	50-356	Univ. of Illinois Lopra Research Reactor	186
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	137	50-358	William H. Zimmer Nuclear Station, Unit 1	186
50-322	Shoreham Nuclear Power Station	140	50-360	Battelle Memorial Inst. Critical Facility	189
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	141	50-361	San Onofre Nuclear Station, Unit 2	189
50-324	Brunswick Steam Electric Plant, Unit 2	143	50-362	San Onofre Nuclear Station, Unit 3	191
50-325	Brunswick Steam Electric Plant, Unit 1	145	50-363	Forked River Nuclear Station, Unit 1	193
50-326	Univ. of California at Irvine Research Reactor	147	50-364	Joseph M. Farley Nuclear Plant, Unit 2	193
50-327	Sequoyah Nuclear Plant, Unit 1	147	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	194
50-328	Sequoyah Nuclear Plant, Unit 2	148	50-367	Bailly Generating Station	197
50-329	Midland Plant, Unit 1	149	50-368	Arkansas Nuclear One, Unit 2	198
50-330	Midland Plant, Unit 2	152	50-369	William B. McGuire Nuclear Station, Unit 1	200
50-331	Duane Arnold Energy Center	155	50-370	William B. McGuire Nuclear Station, Unit 2	202
50-332	Barnwell Reprocessing Plant	156	50-373	LaSalle County Station, Unit 1	203
50-333	James A. Fitzpatrick Nuclear Power Plant	156	50-374	LaSalle County Station, Unit 2	204
50-334	Beaver Valley Power Station, Unit 1	159	50-375	Nuclear Examination Reactor	205
50-335	St. Lucie Plant, Unit 1	161	50-376	North Coast Nuclear Plant, Puerto Rico	205
50-336	Millstone Nuclear Power Station, Unit 2	162	50-382	Waterford Generating Station, Unit 3	205
50-338	North Anna Power Station, Unit 1	164	50-387	Susquehanna Steam Electric Station, Unit 1	207
50-339	North Anna Power Station, Unit 2	169	50-388	Susquehanna Steam Electric Station, Unit 2	209
50-341	Enrico Fermi Atomic Power Plant, Unit 2	174	50-389	St. Lucie Plant, Unit 2	211
50-344	Trojan Nuclear Plant, Unit 1	175	50-390	Watts Bar Nuclear Plant, Unit 1	212
50-346	Davis-Besse Nuclear Power Station, Unit 1	177	50-391	Watts Bar Nuclear Plant, Unit 2	214
			50-394	California State Polytech College Research Reactor	215

<b>Docket</b>	<b>Name</b>	<b>Page</b>	<b>Docket</b>	<b>Name</b>	<b>Page</b>
50-395	Virgil C. Summer Nuclear Station, Unit 1	215	50-444	Seabrook Nuclear Station, Unit 2	244
50-396	Univ. of Virginia Cavalier Reactor	217	50-445	Comanche Peak Steam Electric Station, Unit 1	245
50-397	WPPSS Nuclear Project, Unit 2	217	50-446	Comanche Peak Steam Electric Station, Unit 2	247
50-400	Shearon Harris Nuclear Power Plant, Unit 1	218	50-448	Douglas Point Nuclear Station, Unit 1	250
50-401	Shearon Harris Nuclear Power Plant, Unit 2	220	50-449	Douglas Point Nuclear Station, Unit 2	250
50-402	Shearon Harris Nuclear Power Plant, Unit 3	221	50-451	Summit Nuclear Power Station, Unit 2	250
50-403	Shearon Harris Nuclear Power Plant, Unit 4	223	50-452	Greenwood Energy Center, Unit 2	250
50-404	North Anna Power Station, Unit 3	224	50-453	Greenwood Energy Center, Unit 3	250
50-405	North Anna Power Station, Unit 4	225	50-454	Byron Station, Unit 1	250
50-406	Tuskegee Inst. Research Reactor	226	50-455	Byron Station, Unit 2	251
50-407	Univ. of Utah Research Reactor	226	50-456	Braidwood Station, Unit 1	252
50-409	La Crosse Boiling Water Reactor	226	50-457	Braidwood Station, Unit 2	253
50-410	Nine Mile Point Nuclear Station, Unit 2	228	50-458	River Bend Station, Unit 1	254
50-412	Beaver Valley Power Station, Unit 2	228	50-459	River Bend Station, Unit 2	255
50-413	Catawba Nuclear Station, Unit 1	229	50-460	WPPSS Nuclear Project, Unit 1	255
50-414	Catawba Nuclear Station, Unit 2	230	50-461	Clinton Power Station, Unit 1	256
50-416	Grand Gulf Nuclear Station, Unit 1	231	50-462	Clinton Power Station, Unit 2	257
50-417	Grand Gulf Nuclear Station, Unit 2	233	50-463	Fulton Generating Station, Unit 1	258
50-423	Millstone Nuclear Power Station, Unit 3	235	50-464	Fulton Generating Station, Unit 2	258
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	235	50-466	Allens Creek Nuclear Station, Unit 1	258
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	237	50-470	CESSAR System 80	260
50-426	Alvin W. Vogtle Nuclear Plant, Unit 3	238	50-471	Pilgrim Nuclear Power Station, Unit 2	260
50-427	Alvin W. Vogtle Nuclear Plant, Unit 4	238	STN-50-481	B-SAR-241	261
50-433	UC-Santa Barbara Research Reactor	238	STN-50-482	Wolf Creek Generating Station	261
STN-50-437	Floating Nuclear Plant	238	STN-50-483	Calloway Plant, Unit 1	263
50-438	Bellefonte Nuclear Plant, Unit 1	239	STN-50-484	Tyrone Energy Park, Unit 1	264
50-439	Bellefonte Nuclear Plant, Unit 2	240	STN-50-485	Sterling Power Project, Nuclear, Unit 1	265
50-440	Perry Nuclear Power Plant, Unit 1	241	STN-50-486	Calloway Plant, Unit 2	266
50-441	Perry Nuclear Power Plant, Unit 2	242	STN-50-488	Perkins Nuclear Station, Unit 1	266
50-443	Seabrook Nuclear Station, Unit 1	243	STN-50-489	Perkins Nuclear Station, Unit 2	267
			STN-50-490	Perkins Nuclear Station, Unit 3	268
			STN-50-491	Cherokee Nuclear Station, Unit 1	269

Docket	Name	Page	Docket	Name	Page
STN-50-492	Cherokee Nuclear Station, Unit 2	269	50-538	Memphis State Univ. Research Reactor	289
STN-50-493	Cherokee Nuclear Station, Unit 3	270	STN-50-546	Marble Hill Nuclear Station, Unit 1	289
STN-50-495	SWESSAR-PI	271	STN-50-547	Marble Hill Nuclear Station, Unit 2	290
STN-50-498	South Texas Project, Unit 1	271	50-549	Greene County Nuclear Power Plant	292
STN-50-499	South Texas Project, Unit 2	273	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	292
50-500	Davis-Besse Nuclear Power Station, Unit 2	275	STN-50-554	Phipps Bend Nuclear Plant, Unit 2	293
50-501	Davis-Besse Nuclear Power Station, Unit 3	276	STN-50-556	Black Fox Station, Unit 1	293
STN-50-502	Haven Nuclear Plant, Unit 1	276	STN-50-557	Black Fox Station, Unit 2	294
STN-50-503	Haven Nuclear Plant, Unit 2	276	50-564	Nuclear Fuels Recovery and Recycle Center	295
50-504	Koshkonong Nuclear Plant, Unit 1	276	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	295
50-505	Koshkonong Nuclear Plant, Unit 2	276	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	296
50-506	Koshkonong Nuclear Plant, Unit 3	276	STN-50-568	NEP Nuclear, Unit 1	296
50-507	Koshkonong Nuclear Plant, Unit 4	276	STN-50-569	NEP Nuclear, Unit 2	297
STN-50-508	WPPSS Nuclear Project, Unit 3	276	STN-50-574	Bagnac Nuclear Power Project	298
STN-50-509	WPPSS Nuclear Project, Unit 5	277	STN-50-580	Erie Nuclear Plant, Unit 1	298
50-510	Blue Hills Station, Unit 1	278	STN-50-581	Erie Nuclear Plant, Unit 2	298
50-511	Blue Hills Station, Unit 2	278	50-582	Sundesert, Unit 1	299
50-513	WPPSS Nuclear Project, Unit 4	278	50-582	Sundesert, Unit 2	299
50-514	Pebble Springs Nuclear Plant, Unit 1	279	STN-50-592	Palo Verde Nuclear Station, Unit 4	299
50-515	Pebble Springs Nuclear Plant, Unit 2	279	STN-50-593	Palo Verde Nuclear Station, Unit 5	300
STN-50-516	Jamesport Nuclear Station, Unit 1	280	50-596	New Haven, Unit 1	301
STN-50-517	Jamesport Nuclear Station, Unit 2	280	50-597	New Haven, Unit 2	301
STN-50-518	Hartsville Nuclear Plant, Unit 1	281	50-599	Carroll Facility I	302
STN-50-519	Hartsville Nuclear Plant, Unit 2	282	50-600	Carroll Facility II	303
STN-50-520	Hartsville Nuclear Plant, Unit 3	283	70-0008	Battelle Columbus Laboratories	303
STN-50-521	Hartsville Nuclear Plant, Unit 4	283	70-0025	Rockwell International Corp.	303
STN-50-522	Skagit Nuclear Power Project, Unit 1	284	70-0027	Babcock & Wilcox Co.	303
STN-50-523	Skagit Nuclear Power Project,	285	70-0033	Texas Instruments, Inc	304
			70-0036	Combustion Engineering, Inc.	304
			70-0049	Florida, Univ. of	304
			70-0135	Babcock & Wilcox Co.	304
STN-50-530	Palo Verde Nuclear Station, Unit 3	288	70-0143	Nuclear Fuel Services, Inc.	304
STN-50-535	GASSAR-6	289	70-0152	Purdue University	306
50-537	Clinch River Breeder Reactor	289			

Docket	Name	Page	Docket	Name	Page
70-0267	Nuclear Science and Technology Facility at SUNY	306	70-1309	Morris Operations, Sources & Standards, General	310
70-0797	Georgia Inst of Technology	306	70-1319	U.S. Nuclear, Inc.	311
70-0364	Parks Township Site, Babcock & Wilcox Co.	306	70-1375	Transnuclear, Inc.	311
70-0368	Georgia Inst of Technology	306	70-1379	Parkwell Laboratories, Inc.	311
70-0371	United Nuclear Corp.	306	70-1401	Veterans Administration Hosp , Dallas, TX	311
70-0432	Virginia, Univ. of	306	70-1406	Veterans Administration Hosp., New Orleans, LA	311
70-0462	Florida, Univ. of	306	70-1432	Recycle Fuels Plant, Westinghouse Electric Corp.	311
70-0572	Monsanto Research Corp.	306	70-1489	Goodyear Aerospace Corp.	311
70-0698	Waltz Mill Site, General Electric Corp.	306	70-1503	Westinghouse R&D Center	311
70-0734	General Atomic Co.	306	70-1710	St. Mary's Hospital, Waterbury, CT	311
70-0754	Vallecitos Nuclear Center, General Electric Co.	307	70-1738	Pacific Gas & Electric Co.	311
70-0820	United Nuclear Corp.	307	70-1739	Tri-State Motor Transit Co.	311
70-0824	Babcock & Wilcox Co.	307	70-2185	Hillcrest Medical Center, Tulsa, OK	311
70-0893	Florida Inst. of Technology	307	70-2219	Exxon Nuclear Co., Inc.	311
70-0925	Cimarron Facility, Kerr-McGee Corp.	308	70-2375	Pacific Gas & Electric Co.	311
70-0938	Massachusetts Inst. of Technology	308	70-2443	Tennessee Valley Authority	311
70-0959	Nuclear Fuel Services, Inc.	308	70-2560	Oklahoma Osteopathic Hosp., Tulsa, OK	311
70-0984	Pacific Northwest Laboratory	308	70-2584	Transnuclear, Inc.	311
70-0992	David Witherspoon, Inc.	308	70-2622	Transnuclear, Inc.	312
70-1007	General Electric Co.	308	70-2623	McGuire Spent Fuel Pool, Duke Power Co.	312
70-1068	Florida, Univ. of	308	70-2662	Monsanto Co.	314
70-1100	Combustion Engineering, Inc.	308	70-2838	Cincinnati Gas & Electric Co.	314
70-1113	General Electric Co.	308	70-2882	Southern California Edison Co.	314
70-1143	Westinghouse Electric Corp.	309	70-2909	Westinghouse Electric Corp. Power Systems	314
70-1151	Westinghouse Electric Corp.	309	71-0003	Exxon Nuclear, Inc.	314
70-1193	Cimarron Facility. Kerr-McGee Corp.	309	71-0005	Magnaflux Corp.	314
70-1201	UF <sub>6</sub> Conversion Facility, Babcock & Wilcox Co.	310	71-0009	Isomedix, Inc.	314
70-1207	Navy, Dept. of	310	71-0011	Arrow Tank & Engineering Co.	314
70-1220	General Electric Co.	310	71-0015	Chicago Bridge and Iron Co.	314
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	310	71-0022	Newport News Industrial Corp.	314
70-1308	Morris Operations, General Electric Co.	310			

<b>Docket</b>	<b>Name</b>	<b>Page</b>	<b>Docket</b>	<b>Name</b>	<b>Page</b>
71-0024	Hittman Nuclear and Development Corp	314	71-0105	Universal Testing Laboratories	316
71-0028	Borg-Warner Corp.	314	71-0110	Buckeye Steel Castings	316
71-0031	Maryland Shipbuilding and Dry Dock Co.	315	71-0113	Nooter Corp	316
71-0032	Panhandle Eastern Pipe Line Co.	315	71-0116	Navy, Dept of	317
71-0034	Babcock & Wilcox Co.	315	71-0119	Ingersoll-Rand Co.	317
71-0037	Navy, Dept. of	315	71-0120	Daniel International Corp	317
71-0039	Walworth Co.	315	71-0121	Neutron Products, Inc	317
71-0040	Technical Operations Inc.	315	71-0123	Herron Testing Labs, Inc	317
71-0046	Teledyne Energy Systems	315	71-0127	National Annealing Box Co.	317
71-0047	Capital International Airways, Inc.	315	71-0128	Amoco Oil Co.	317
71-0051	Harrison Steel Castings Co.	315	71-0130	Chicago Bridge and Iron Co	317
71-0054	Oklahoma Testing Laboratories	315	71-0132	Advanced Radiation Service	317
71-0055	H.R. Inspection Service	315	71-0133	Navy, Dept. of	317
71-0057	Exxon Co., USA	315	71-0134	Labarge, Inc.	317
71-0059	General Electric Co.	315	71-0136	Parker Ind. X-Ray Lab. Corp.	317
71-0061	Navy, Dept. of	315	71-0137	Metals Testing Co., Inc.	317
71-0066	Certified Testing Labs, Inc.	315	71-0140	Walworth Co.	317
71-0067	Medi-Physics, Inc.	315	71-0145	Thayer Inspection Service, Inc.	317
71-0074	Nuclear Welding, Inc.	315	71-0148	United Engineers and Construction, Inc.	317
71-0075	Norfolk Shipbuilding and Dry Dock Co.	316	71-0150	Peabody Testing Service	317
71-0076	Babcock & Wilcox Co.	316	71-0151	Hess Oil Virgin Islands Corp.	318
71-0077	Midstate Testing Laboratory	316	71-0152	Virginia Dept. of Highways and Transportation	318
71-0079	Babcock & Wilcox Co.	316	71-0153	Anchor-Darling Valve Co.	318
71-0080	Transworld Airlines, Inc.	316	71-0154	General Dynamics	318
71-0087	Navy, Dept. of	316	71-0156	Industrial Fabricating Co.	318
71-0089	Navy, Dept. of	316	71-0157	Froehling & Robertson, Inc.	318
71-0095	United States Testing Co., Inc.	316	71-0161	Curtiss-Wright Corp.	318
71-0096	Pan American World Airways	316	71-0162	Ebasco Services, Inc.	318
71-0099	Foster Wheeler Energy Corp.	316	71-0163	Clark Inspection Service Inc.	318
71-0102	Source Product and Equipment Co., Inc.	316	71-0166	New York Testing Labs, Inc.	318
71-0103	Twin City Testing & Engineering Laboratory	316	71-0168	Quality Assurance Labs	318
71-0104	Chicago Bridge and Iron Co.	316	71-0175	QC Services, Inc.	318
			71-0177	Federal Aviation Administration	318

Docket	Name	Page	Docket	Name	Page
71-0178	Energy Products Group	318	71-0279	Universal Testing, Inc	320
71-0181	Consolidated X-Ray Service Corp	318	71-0281	Delta Airlines, Inc	320
71-0184	Pullman Power Products	318	71-0284	Ultrasonic Specialists, Inc	320
71-0189	Todd Shipyards Corp.	318	71-0292	Industrial Gamma Inspection	320
71-0192	Nuclear Packaging Inc	319	71-0294	Applied Engineering Co	320
71-0198	Nuclear Fuel Services Inc.	319	71-0298	Steel Tank Construction Co	320
71-0205	Quality Testing, Inc.	319	71-0304	Teledyne Brown Engineering Co.	320
71-0208	Northeast Nuclear Energy Co.	319	71-0305	American X-Ray Inspection, Inc.	320
71-0209	Jacksonville Shipyards, Inc.	319	71-0306	Snyder Drilling-Well Servicing Co.	320
71-0210	Gulf Oil Corp.	319	71-0307	Texas Pipe Bending Co. of Puerto Rico	321
71-0214	Gas Rentals Inc.	319	71-0308	Alaska Industrial X-Ray	321
71-0215	Space Science Services	319	71-0310	Bucyrus-Erie Co.	321
71-0216	Nuclear Energy Services, Inc.	319	71-0314	Smith-Emery Co.	321
71-0217	Pullman Kellogg, Inc.	319	71-0316	Mason & Hanger-Silas Mason Co., Inc	321
71-0218	Cumberland Bridge Co.	319	71-0318	Marathon Oil Co.	321
71-0219	Terex Div./GM Corp.	319	71-0319	General Testing and Inspection Co.	321
71-0225	Navy, Dept. of	319	71-0320	Pittsburgh-Des Moines Steel Co.	321
71-0226	New York, State Univ. of	319	71-0321	Exam Co.	321
71-0228	Capital X-Ray Service	319	71-0322	Control Components International	321
71-0235	Army, Dept. of	319	71-0325	Consumers Power Co	321
71-0236	American Airlines	319	71-0326	Industrial Heat Treating & Metallurgical Co., Inc.	32
71-0239	Navy, Dept. of	319	71-0327	Portland General Electric Co	321
71-0246	Inspection Services Corp.	319	71-0328	Public Service Electric and Gas Co.	321
71-0247	IRT Corp	320	71-0334	Metropolitan Edison Co.	321
71-0248	Monsanto Research Corp.	320	71-0361	Model: PAT-1, Ramsey Engineering Co.	321
71-0251	Westinghouse Electric Corp.	320	71-4949	Model: UNC-1484, Combustion Engineering Co., Inc.	322
71-0252	Dayton X-Ray Co.	320	71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	
71-0257	Industrial Labs, Inc.	320	71-5026	Model: BC-48-220, Atcor Inc.	
71-0258	Nuclear Engineering Co., Inc.	320	71-5149	Model: 814A, Babcock & Wilcox Co.	
71-0262	Wisconsin Industrial Testing, Inc.	320	71-5341	Model: NFP-55, Babcock & Wilcox Co.	32
71-0263	Yuba Heat Transfer Corp.	320	71-5364	Model: NPI-67-0442 Neutron Products, Inc.	32
71-0264	Automation Industries, Inc.	320			
71-0265	Navy, Dept. of	320			
71-0268	Navy, Dept. of	320			

<b>Docket</b>	<b>Name</b>	<b>Page</b>	<b>Docket</b>	<b>Name</b>	<b>Page</b>
71-5395	Model: CC, Westinghouse Electric Corp.	322	71-6387	Model. 60, Battelle Memorial Institute	324
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	322	71-6400	Model: Super Tiger, Westinghouse Electric Corp.	324
71-5455	Model: RCC-1, -2, -3, Westinghouse Electric Corp	322	71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	324
71-5563	Model: 660C, Babcock & Wilcox Co.	322	71-6581	Model: 51032-1 & 1A, Exxon Nuclear Inc.	324
71-5754	Model: RMG-172, Nuclear Fuel Services Inc.	322	71-6601	Model: LL-50-100, Chem-Nuclear Systems, Inc.	324
71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	322	71-6642	Model: 4.5. Ton CF, DOE	325
71-5805	Model: Atcor VNDB Cask, Atcor, Inc.	322	71-6697	Model: 8500 PKG, General Electric Co.	325
71-5901	Model: NFS 100, Nuclear Fuel Services Inc.	322	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	325
71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co	323	71-9001	Model: IF-300, General Electric Co.	325
71-5910	Model: NNFD-SA-2, Babcock & Wilcox Co.	323	71-9005	Model: MAL-1	325
71-5942	Model: GE-700, General Electric Co.	323	71-9009	Model: FL-10-1, General Electric Co.	325
71-5977	Model: Core II Fuel, Todd Shipyards Corp.	323	71-9010	Model: NLI-1/2, NL Industries, Inc.	325
71-5980	Model: GE-600, General Electric Co.	323	71-9017	Model: SNAP-23A, MD1000, Navy, Dept. of	325
71-6058	Model: B3-1, Nuclear Engineering Co.	323	71-9018	Model: BU-6, General Electric Co.	325
71-6078	Model: 927 A1 and C1, Combustion Engineering, Inc.	323	71-9019	Model: BU-7, General Electric Co.	325
71-6104	Model: ANL-390-SPM, DOE, Chicago	323	71-9022	Model: CE-250-2, Combustion Engineering Co., Inc.	325
71-6144	Model: 6144, Nuclear Engineering Co.	323	71-9033	Model: 660 & 660E, Technical Operations, Inc.	325
71-6172	Model: 961A, Babcock & Wilcox Co.	323	71-9044	Model: GE-1600, General Electric Co.	325
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	323	71-9070	Model: N 55, Energy, Dept. of	325
71-6275	Model: LL-28-4, Chemical Nuclear Systems, Inc.	324	71-9074	Model: AP-100, Anefco, Inc.	325
71-6280	Model: A-0109	324	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	325
71-6291	Model: 400	324	71-9081	Model: CSNI-1600, Chem-Nuclear Systems, Inc.	325
71-6357	Model: NNFD-10, Babcock & Wilcox Co.	324	71-9108	Model: AL-33-90, Atcor, Inc.	325
71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	324	71-9113	Model: 7-100, Chem Nuclear Systems, Inc.	325



## ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Aerotest Radiography & Research Reactor	50-228	28	Brigham Young Univ. Research Reactor	50-262	51
Allens Creek Nuclear Station, Unit 1	50-466	258	Browns Ferry Nuclear Power Station, Unit 1	50-259	46
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	235	Browns Ferry Nuclear Power Station, Unit 2	50-260	48
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	237	Browns Ferry Nuclear Power Station, Unit 3	50-296	93
Alvin W. Vogtle Nuclear Plant, Unit 3	50-426	238	Brunswick Steam Electric Plant, Unit 1	50-325	145
Alvin W. Vogtle Nuclear Plant, Unit 4	50-427	238	Brunswick Steam Electric Plant, Unit 2	50-324	143
Arkansas Nuclear One, Unit 1	50-313	113	B-SAR-241	STN-50-481	261
Arkansas Nuclear One, Unit 2	50-368	198	Byron Station, Unit 1	50-454	250
Army Materials Research Reactor	50-470	10	Byron Station, Unit 2	50-455	251
Babcock & Wilcox Co. Critical Facility	50-13	8	California State Polytech College Research Reactor	50-394	215
Babcock & Wilcox Test Reactor	50-99	12	Calloway Plant, Unit 1	STN-50-483	263
Bagnac Nuclear Power Project	STN-50-574	298	Calloway Plant, Unit 2	STN-50-486	266
Bailly Generating Station	50-367	197	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	119
Barnwell Reprocessing Plant	50-332	156	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	121
Battelle Memorial Inst. Critical Facility	50-360	189	Carroll Facility I	50-599	302
Beaver Valley Power Station, Unit 1	50-334	159	Carroll Facility II	50-600	303
Beaver Valley Power Station, Unit 2	50-412	228	Catawba Nuclear Station, Unit 1	50-413	229
Bellefonte Nuclear Plant, Unit 1	50-438	239	Catawba Nuclear Station, Unit 2	50-414	230
Bellefonte Nuclear Plant, Unit 2	50-439	240	Catholic Univ. of America Research Reactor	50-77	12
Big Rock Point Nuclear Power Plant	50-155	16	CESSAR System 80	50-470	260
Black Fox Station, Unit 1	STN-50-556	293	Cherokee Nuclear Station, Unit 1	STN-50-491	269
Black Fox Station, Unit 2	STN-50-557	294	Cherokee Nuclear Station, Unit 2	STN-50-492	269
Blue Hills Station, Unit 1	50-510	278	Cherokee Nuclear Station, Unit 3	STN-50-493	270
Blue Hills Station, Unit 2	50-511	278	Clinch River Breeder Reactor	50-537	289
Braidwood Station, Unit 1	50-456	252			
Braidwood Station, Unit 2	50-457	253			

Name	Docket	Page	Name	Docket	Page
Clinton Power Station, Unit 1	50-461	256	Erie Nuclear Plant, Unit 1	STN-50-580	298
Clinton Power Station, Unit 2	50-462	257	Erie Nuclear Plant, Unit 2	STN-50-581	298
Columbia Univ. Research Reactor	50-208	22	Floating Nuclear Plant	STN-50-437	238
Comanche Peak Steam Electric Station, Unit 1	50-445	245	Forked River Nuclear Station, Unit 1	50-363	193
Comanche Peak Steam Electric Station, Unit 2	50-446	247	Fort Calhoun Station, Unit 1	50-285	80
Cooper Nuclear Station	50-298	95	Fort St. Vrain Nuclear Generating Station	50-267	56
Cornell Univ. Research Reactor	50-157	17	Fulton Generating Station, Unit 1	50-463	258
Cornell Univ. Zero Power Reactor	50-97	12	Fulton Generating Station, Unit 2	50-464	258
Crystal River Nuclear Plant, Unit 3	50-302	98	GASSAR-6	STN-50-535	289
Crystal River Nuclear Plant, Unit 4	50-303	101	General Atomic Co.	50-89	12
Davis-Besse Nuclear Power Station, Unit 1	50-346	177	General Atomic Co.	50-163	18
Davis-Besse Nuclear Power Station, Unit 2	50-500	275	General Electric Test Reactor	50-70	11
Davis-Besse Nuclear Power Station, Unit 3	50-501	276	General Electric Nuclear Test Reactor	50-73	11
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	67	Georgia Institute of Technology Research Reactor	50-160	17
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	141	Georgia Institute of Technology Research Reactor	50-276	69
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	116	Grand Gulf Nuclear Station, Unit 1	50-416	231
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	118	Grand Gulf Nuclear Station, Unit 2	50-417	233
Douglas Point Nuclear Station, Unit 1	50-448	250	Greene County Nuclear Power Plant	50-549	292
Douglas Point Nuclear Station, Unit 2	50-449	250	Greenwood Energy Center, Unit 2	50-452	250
Dow Chemical Co.	50-264	53	Greenwood Energy Center, Unit 3	50-453	250
Dresden Nuclear Power Station, Unit 1	50-10	6	H.B. Robinson Plant, Unit 2	50-261	49
Dresden Nuclear Power Station, Unit 2	50-237	28	Haddam Neck Plant	50-213	22
Dresden Nuclear Power Station, Unit 3	50-249	36	Hartsville Nuclear Plant, Unit 1	STN-50-518	281
Duane Arnold Energy Center	50-331	155	Hartsville Nuclear Plant, Unit 2	STN-50-519	282
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	137	Hartsville Nuclear Plant, Unit 3	STN-50-520	283
Edwin I. Hatch Nuclear Plant, Unit 2	50-366	194	Hartsville Nuclear Plant, Unit 4	STN-50-521	283
Elk River Reactor	50-115	13	Haven Nuclear Plant, Unit 1	STN-50-502	276
Enrico Fermi Atomic Power Plant, Unit 1	50-16	8	Haven Nuclear Plant, Unit 2	STN-50-503	276
Enrico Fermi Atomic Power Plant, Unit 2	50-341	174	Hope Creek Nuclear Station, Unit 1	50-354	185
			Hope Creek Nuclear Station, Unit 2	50-355	185
			Humboldt Bay Power Plant, Unit 3	50-133	14

Name	Docket	Page	Name	Docket	Page
Idaho State Univ. Research Reactor	50-284	80	Millstone Nuclear Power Station, Unit 2	50-336	162
Indian Point Station, Unit 1	50-3	5	Millstone Nuclear Power Station, Unit 3	50-423	235
Indian Point Station, Unit 2	50-247	34	Mississippi State Univ. Research Reactor	50-241	30
Indian Point Station, Unit 3	50-286	82	Monticello Nuclear Generating Plant	50-263	51
Iowa State Univ. Research Reactor	50-116	13	National Bureau of Standards Reactor	50-184	18
James A. Fitzpatrick Nuclear Power Plant	50-333	156	National Naval Medical Center	50-170	18
Jamesport Nuclear Station, Unit 1	STN-50-516	280	NEP Nuclear, Unit 1	STN-50-568	296
Jamesport Nuclear Station, Unit 2	STN-50-517	280	NEP Nuclear, Unit 2	STN-50-569	297
Joseph M. Farley Nuclear Plant, Unit 1	50-348	181	New Haven, Unit 1	50-596	301
Joseph M. Farley Nuclear Plant, Unit 2	50-364	193	New Haven, Unit 2	50-597	301
Kansas State Univ. Research Reactor	50-188	19	Nine Mile Point Nuclear Station, Unit 1	50-220	25
Kewaunee Nuclear Power Plant	50-305	104	Nine Mile Point Nuclear Station, Unit 2	50-410	228
Koshkonong Nuclear Plant, Unit 1	50-504	276	North Anna Power Station, Unit 1	50-338	164
Koshkonong Nuclear Plant, Unit 2	50-505	276	North Anna Power Station, Unit 2	50-339	169
Koshkonong Nuclear Plant, Unit 3	50-506	276	North Anna Power Station, Unit 3	50-404	224
Koshkonong Nuclear Plant, Unit 4	50-507	276	North Anna Power Station, Unit 4	50-405	225
LaCrosse Boiling Water Reactor	50-409	226	North Carolina State Univ. PULSTAR Reactor	50-297	95
LaSalle County Station, Unit 1	50-373	203	North Carolina State Univ. Research Reactor	50-111	12
LaSalle County Station, Unit 2	50-374	204	North Coast Nuclear Plant, Puerto Rico	50-376	205
Limerick Generating Station, Unit 1	50-352	183	Nuclear Examination Reactor	50-375	205
Limerick Generating Station, Unit 2	50-353	184	Nuclear Fuels Recovery and Recycle Center	50-564	295
Maine Yankee Atomic Power Plant	50-309	107	Oconoe Nuclear Station, Unit 1	50-269	58
Manhattan College Research Reactor	50-199	19	Oconoe Nuclear Station, Unit 2	50-270	60
Marble Hill Nuclear Station, Unit 1	STN-50-546	289	Oconoe Nuclear Station, Unit 3	50-287	83
Marble Hill Nuclear Station, Unit 2	STN-50-547	290	Ohio State Univ. Research Reactor	50-150	16
Massachusetts Institute of Technology Research Reactor	50-20	8	Omaha Veterans Administration Hospital Research Reactor	50-131	14
Memphis State Univ. Research Reactor	50-538	289	Oregon State Univ.	50-106	12
Michigan State Univ. Research Reactor	50-294	90	Oregon State Univ. Research Reactor	50-243	30
Midland Plant, Unit 1	50-329	149	Oyster Creek Nuclear Power Plant	50-219	24
Midland Plant, Unit 2	50-330	152			
Millstone Nuclear Power Station, Unit 1	50-245	32			

Name	Docket	Page	Name	Docket	Page
Palisades Nuclear Plant	50-255	44	River Bend Station, Unit 1	50-458	254
Palo Verde Nuclear Station, Unit 1	STN-50-528	287	River Bend Station, Unit 2	50-459	255
Palo Verde Nuclear Station, Unit 2	STN-50-529	287	Rockwell Intl. Corp. Critical Facility	50-147	15
Palo Verde Nuclear Station, Unit 3	STN-50-530	288	Rockwell Intl. Research Reactor	50-94	12
Palo Verde Nuclear Station, Unit 4	STN-50-592	299	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	30
Palo Verde Nuclear Station, Unit 5	STN-50-593	300	RPI Critical Experiment	50-225	27
Peach Bottom Atomic Power Station, Unit 1	50-171	18	Salem Nuclear Generating Station, Unit 1	50-272	64
Peach Bottom Atomic Power Station, Unit 2	50-277	69	Salem Nuclear Generating Station, Unit 2	50-311	109
Peach Bottom Atomic Power Station, Unit 3	50-278	71	San Onofre Nuclear Station, Unit 1	50-206	20
Pebble Springs Nuclear Plant, Unit 1	50-514	279	San Onofre Nuclear Station, Unit 2	50-361	189
Pebble Springs Nuclear Plant, Unit 2	50-515	279	San Onofre Nuclear Station, Unit 3	50-362	191
Pennsylvania State Univ. Research Reactor	50-5	6	Seabrook Nuclear Station, Unit 1	50-443	243
Perkins Nuclear Station, Unit 1	STN-50-488	266	Seabrook Nuclear Station, Unit 2	50-444	244
Perkins Nuclear Station, Unit 2	STN-50-489	267	Sequoyah Nuclear Plant, Unit 1	50-327	147
Perkins Nuclear Station, Unit 3	STN-50-490	268	Sequoyah Nuclear Plant, Unit 2	50-328	148
Perry Nuclear Power Plant, Unit 1	50-440	241	Shearon Harris Nuclear Power Plant, Unit 1	50-400	218
Perry Nuclear Power Plant, Unit 2	50-441	242	Shearon Harris Nuclear Power Plant, Unit 2	50-401	220
Phipps Bend Nuclear Plant, Unit 1	50-553	292	Shearon Harris Nuclear Power Plant, Unit 3	50-402	221
Phipps Bend Nuclear Plant, Unit 2	50-554	293	Shearon Harris Nuclear Power Plant, Unit 4	50-403	223
Pilgrim Nuclear Power Station, Unit 1	50-293	88	Shoreham Nuclear Power Station	50-322	140
Pilgrim Nuclear Power Station, Unit 2	50-471	260	Skagit Nuclear Power Project, Unit 1	STN-50-522	284
Point Beach Nuclear Plant, Unit 1	50-266	54	Skagit Nuclear Power Project, Unit 2	STN-50-523	285
Point Beach Nuclear Plant, Unit 2	50-301	97	South Texas Project, Unit 1	STN-50-498	271
Prairie Island Nuclear Station, Unit 1	50-282	78	South Texas Project, Unit 2	STN-50-499	273
Prairie Island Nuclear Station, Unit 2	50-306	106	Space Radiation Research Reactor	50-187	18
Purdue Univ. Research Reactor	50-182	18	State Univ. of New York Research Reactor	50-57	10
Quad-Cities Station, Unit 1	50-254	42	Sterling Power Project, Nuclear, Unit 1	STN-50-485	265
Quad-Cities Station, Unit 2	50-265	53	St. Lucie Plant, Unit 1	50-335	161
Sancho Seco Nuclear Generating Station	50-312	111	St. Lucie Plant, Unit 2	50-380	211
Sandhollow College Research Reactor	50-288	86			
Shoemaker Island & Providence Plantations AEC	50-193	19			

Name	Docket	Page	Name	Docket	Page
Summit Nuclear Power Station, Unit 2	50-451	250	Univ. of Missouri Research Reactor	50-123	13
Sundesert, Unit 1	50-582	299	Univ. of Missouri Research Reactor	50-186	18
Sundesert, Unit 2	50-582	299	Univ. of New Mexico Research Reactor	50-252	42
Surry Power Station, Unit 1	50-280	73	Univ. of Oklahoma Research Reactor	50-112	13
Surry Power Station, Unit 2	50-281	76	Univ. of Texas Research Reactor	50-192	19
Susquehanna Steam Electric Station, Unit 1	50-387	207	Univ. of Utah Research Reactor	50-72	11
Susquehanna Steam Electric Station, Unit 2	50-388	209	Univ. of Utah Research Reactor	50-407	226
SWESSAR-P1	STN-50-495	271	Univ. of Virginia Cavalier Reactor	50-396	217
Texas A & M Univ. Research Reactor	50-59	11	Univ. of Virginia Research Reactor	59-62	11
Texas A & M Univ. Research Reactor	50-129	13	Univ. of Washington Research Reactor	50-139	15
Three Mile Island Nuclear Station, Unit 1	50-289	86	Univ. of Wisconsin Research Reactor	50-156	17
Three Mile Island Nuclear Station, Unit 2	50-320	122	U.S. Geological Survey Research Reactor	50-274	67
Trojan Nuclear Plant, Unit 1	50-344	175	Vermont Yankee Nuclear Power Station	50-271	63
Turkey Point Plant, Unit 3	50-250	37	Virgil C. Summer Nuclear Station, Unit 1	50-395	215
Turkey Point Plant, Unit 4	50-251	40	Virginia Polytech Inst. Training Reactor	50-124	13
Tuskegee Inst. Research Reactor	50-406	226	Washington State Univ. Research Reactor	50-27	8
Tyrone Energy Park, Unit 1	STN-50-484	264	Waterford Generating Station, Unit 3	50-382	205
UCLA Training Reactor	50-142	15	Watts Bar Nuclear Plant, Unit 1	50-390	212
UC-Santa Barbara Research Reactor	50-433	238	Watts Bar Nuclear Plant, Unit 2	50-391	214
Union Carbide Research Reactor	50-54	10	Westinghouse Critical Experiment	50-87	12
Univ. of Arizona Research Reactor	50-113	13	Westinghouse Test Reactor	50-22	8
Univ. of California at Irvine Research Reactor	50-326	147	West Valley Reprocessing Plant	50-201	19
Univ. of California Research Reactor	50-224	27	West Virginia Univ. Research Reactor	50-129	14
Univ. of Florida Training Reactor	50-83	12	William B. McGuire Nuclear Station, Unit 1	50-369	200
Univ. of Illinois Research Reactor	50-151	16	William B. McGuire Nuclear Station, Unit 2	50-370	202
Univ. of Illinois Lopra Research Reactor	50-356	186	William H. Zimmer Nuclear Station, Unit 1	50-358	186
Univ. of Kansas Research Reactor	50-148	15	Wolf Creek Generating Station	STN-50-482	261
Univ. of Lowell Research Reactor	50-223	27	Worcester Polytech Inst. Research Reactor	50-134	15
Univ. of Maryland Research Reactor	50-166	18			
Univ. of Michigan Research Reactor	50-2	5			

<b>Name</b>	<b>Docket</b>	<b>Page</b>	<b>Name</b>	<b>Docket</b>	<b>Page</b>
WPPSS Nuclear Project, Unit 1	50-460	255	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	295
WPPSS Nuclear Project, Unit 2	50-397	217	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	296
WPPSS Nuclear Project, Unit 3	STN-50-508	276	Zion Nuclear Power Station, Unit 1	50-295	90
WPPSS Nuclear Project, Unit 4	50-513	278	Zion Nuclear Power Station, Unit 2	50-304	101
WPPSS Nuclear Project, Unit 5	STN-50-509	277			
Yankee-Rowe Nuclear Power Station	50-29	8			

# DOCKETED ITEMS

## LOW LEVEL RADWASTE DISPOSAL SITES

### DOCKET 27-039 SHEFFIELD, IL , NUCLEAR ENGINEERING CO

790713040B Seeks denial of Nuclear Engineering Co request to dismiss proceedings Co is responsible for buried radwaste. Proceedings must continue to determine method & terms of license termination Certificate of Bvc encl  
REIS,E J Branch 3 79/03/20 17pp

7907180387 Describes agreements reached by attys re low level radwaste disposal facility located at Sheffield, IL  
EILPERIN,S F Office of the General Counsel 79/04/23 2pp

7907180896 Ack receipt of 790328 ltr re license responsibilities of NFS & NY State Energy Research & Development Authority. Forwards 790423 ltr re settlement agreement w/Nuclear Engineering Co  
HENDRIE,J M Commission 79/05/23 1p

7907090386 Summary of review of updated renewal application for handling & disposal of SNM Unclear if company intends to continue to handle matl. Critical analysis underway  
SMITH,R D Low Level Waste Licensing Branch 79/06/01 1p

7907230743 Forwards LE Stratton 790523 ltr confirming telcons re D'Appolonia piezometers at site  
DRAGONNETTE,K S Low Level Waste Licensing Branch 79/06/01 2pp

--7907230771 Confirms 790522 telcons re D'Appolonia piezometers at site. Nuclear Engineering Co will remove piezometers Co has been asked to replace instruments w/std monitoring wells  
STRATTON,L E Illinois, State of 79/05/23 1p

7907240472 Forwards Revision 1 to branch position, "Low-Level Waste Burial Ground Site Closure & Stabilization"  
DRAGONNETTE,K S Low Level Waste Licensing Branch 79/06/05 2pp

--7907240491 Revision 1 to branch position, "Low Level Waste Burial Ground Site Closure & Stabilization"  
\* Low Level Waste Licensing Branch 79/05/17 7pp

7907160130 Corrects 790606 memo & order.  
CHILK,B J Office of the Secretary of the Commission 79/06/15 1p

7907020012 Nuclear Engineering Co motion for reconsideration & clarification of NRC 790606 notice of hearing & memo & order Certificate of Bvc encl.  
CONNER,T B Conner, Moore & Corber. 79/06/18 17pp

7907190703 Responds to FOIA request for documents re decommissioning of Elk River, MN reactor & shipment of decommissioned matl to Sheffield, IL low level nuclear waste site. Documents in microfiche being sent to Region 3 for insp  
FELTON,J M Division of Rules and Records. 79/07/17 1p

### DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS

7907060168 Submits addl info in support of request for amend to License 46-13536 which would authorize receipt, transport & disposal of radioactive wastes containing CaF2 & U enriched w/U-235. Supporting documentation encl  
REYNOLDS,L E Chem-Nuclear Systems, Inc 79/05/11 42pp

7907120016 Forwards Amend 15 to License 46-16536-01 Amend is result of NRC actions to assure proper burial of radioactive matl  
DIRCKS,W J Office of Nuclear Material Safety & Safeguards 79/05/23 2pp

--7907120022 Amend 15 to License 46-13536-01, disallowing transfer of buried nuclear matl by abandonment & requiring licensee to submit Updated plan every five years for review  
DIRCKS,W J Office of Nuclear Material Safety & Safeguards 79/05/23 3pp

--7907120031 Low-Level Waste Branch Position, Revision 1, low-level waste burial ground site closure & stabilization Site condition upon termination should require no ongoing maint & only passive surveillance  
\* Low Level Waste Licensing Branch 79/05/17 7pp

7907250582 "Economic Analysis of Funding Arrangements for Maint, Surveillance & Contingency Costs Associated w/Burial of Low Level Radioactive Waste in SC"  
ANDERSON,L P, GARRISON,D B Clemson Univ 74/12/31 36pp

### DOCKET 27-048 RICHLAND, WA , NUCLEAR ENGINEERING CO

7907090386 Summary of review of updated renewal application for handling & disposal of SNM Unclear if company intends to continue to handle matl. Critical analysis underway  
SMITH,R D Low Level Waste Licensing Branch 79/06/01 1p

7907230605 Confirms plans to visit Nuclear Engineering Co, Inc low-level waste disposal site on 790611 & to discuss license renewal on 790612. Forwards proposed agenda & itinerary  
SMITH,R D Low Level Waste Licensing Branch 79/06/05 3pp

## DOMESTIC LICENSING OF SOURCE MATERIAL

### DOCKET 40-0299 UNION CARBIDE CORP

7907110278 Notifies that License SUA-648 is amended to authorize operation of U heap leaching operation that replaces experimental heap leach facility at East Gas Hills mill site  
SCARANO,R A Uranium Recovery Licensing Branch. 79/04/23 3pp

7907190081 Submits comments on DEB  
REKEMEYER,P C Union Carbide Corp 79/05/31 17pp

--7907190093 Submits info re employee time spent on site  
JOHNSON,D L Union Carbide Corp 77/10/10 15pp

### DOCKET 40-1162 WESTERN NUCLEAR, INC

7907030290 Forwards "Summary Historical & Archeological Situation Repts, Tailings Disposal Sites, Jeffrey City Mill"  
BOGDEN,O Western Nuclear, Inc (subs. of Phelps Dodge Corp) 79/06/13 1p

--7907030296 "Summary Historical & Archeological Situation Repts, Tailings Disposal Sites, Jeffrey City Mill."  
\* Western Nuclear, Inc (subs. of Phelps Dodge Corp) 79/05/30 17pp.

7907020468 Forwards request for addl info re review of proposed dam raise. Requests response by 790611  
LINEHAN,J J Uranium Recovery Licensing Branch 79/05/21 3pp

7907310150 Responds to 790521 ltr. Forwards addl info re design wave height & runoff & upstream beach erosion at tailings embankment  
BOGDEN,O Western Nuclear, Inc (subs. of Phelps Dodge Corp) 79/06/09 25pp

#



# DOCKETED ITEMS

3

## DOCKET 40-8006 KERR-MCGEE CORP

7906140584 Ack receipt of 790329 ltr informing NRC of steps taken to correct violations noted in IE insp of License SUB-986 on 790226  
BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/04/20 1p

--7906140590 Responds to NRC 790313 ltr re violations noted in IE insp of License SUB-986 on 790226 Corrective actions signs have been ordered for affixing to cage in which natural U is stored & test drum of ore will be fenced in  
SHELLY, W J Kerr-McGee Corp 79/03/29 2pp

--7906140594 Discusses IE insp of License SUB-986 on 790226 & forwards notice of violation  
BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/03/13 2pp

---7906140597 Notice of violation from insp on 790226 Noncompliance noted signs not posted in area of natural U storage & container of natural U containing 1 mCi not labeled  
\* Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/03/13 1p

## DOCKET 40-8027 KERR-MCGEE CORP

7907060035 Forwards updated replacement pages to amended License SUB-1010 per 790420 request from AL Soong  
SHELLEY, W J Kerr-McGee Corp 79/05/10 7pp

7907310173 Forwards info re violation of Amend 4 to License SUB-1010 authorizing test distribution of treated raffinate  
Violation involves noncompliance w/NPDES re TSS limits  
SHELLEY, W J obsolete code 79/06/12 5pp

7907050418 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

## DOCKET 40-8064 EXXON MINERALS CO USA, EXXON CORP

7907180749 Requests amend to License SUA-1064 to make excursion monitoring & verification procedures consistent w/Amend 13 to License SUA-1139 & procedures approved by WY Dept of Environ Quality  
ORTLOFF, G D Exxon Minerals Co, USA 79/05/07 17pp

## DOCKET 40-8102 EXXON MINERALS CO USA, EXXON CORP

7907100706 Requests addl info re application for renewal of source mat'l license to complete review  
LINEHAN, J J Uranium Recovery Licensing Branch 79/05/23 31pp

7907230082 Notifies of amend to License SUA-1139 eliminating ref to individual named as radiation safety officer & establishing min qualifications for ofc Forwards Nov 1976 guidelines for decontamination of facilities & equipment  
SCARAND, R A Uranium Recovery Licensing Branch 79/05/31 7pp

7907230785 Notifies of receipt of 790321 ltr & of acceptance of deletion of individual named as radiation safety officer & establishment of min qualifications for position Forwards amend to license re guidelines for decontamination  
GARCIA, P J Uranium Recovery Licensing Branch 79/05/31 6pp

## DOCKET 40-8211 CHAMBERLAIN MANUFACTURING CORP

7907240043 IE Insp Findings & Licenses Ack dtd 790605 of License SUB-119B Insp findings no items of noncompliance  
\* Region 3, Chicago, Office of the Director 79/06/05 1p

## DOCKET 40-8304 WYOMING MINERAL CORP

7907100636 Forwards "Irigaray Mine Site, Third Quarterly Rept, " Jan-Mar 1979, submitted to State of WY  
SCHEDEL, K R Wyoming Mineral Corp 79/05/22 2pp

---7907100639 "Irigaray Mine Site, Third Quarterly Rept, " Jan-Mar 1979  
\* Wyoming Mineral Corp 79/05/22 90pp

7907180859 Request for renewal of License SUA-1204 for period of five years Check for \$17,000 encl  
SCHEDEL, K R Wyoming Mineral Corp 79/05/24 1p

## DOCKET 40-8452 BEAR CREEK URANIUM CO

7907060074 Forwards requests for info identified during geotechnical engineering review of Sept 1978 submittal Requests response by 790518  
LINEHAN, J J Uranium Recovery Licensing Branch 79/05/08 6pp

7907240331 Forwards info re Question 5 of 790426 ltr on tailings beach Meteorological data & info re atmospheric stability of site will be available 790531 Boundary air quality data & estimated reclamation cost for tailing sys encl  
ANDREWS, R D Rocky Mountain Energy Co 79/05/24 10pp

7907100056 Submits info requested by NRC re meteorological characteristics of mill site  
ANDREWS, R D Rocky Mountain Energy Co 79/05/30 23pp

7907230770 Summary of 790518 meeting w/Rocky Mountain Energy Co in Silver Spring, MD re proposed tailings reclamation plan & initial results of NRC environ assessment of util proposal to double mill throughput  
GARCIA, P J Uranium Recovery Licensing Branch 79/05/31 3pp

## DOCKET 40-8502 IRIGARY MINE, WYOMING MINING CORP

7907300201 Submits chronology of actions re shallow monitor wells of Irigary site that have been assigned excursion status  
SCHEDEL, K R Wyoming Mineral Corp 79/06/13 2pp

## DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

7907060512 Notifies of Amend 2 to License SUA-1350 to incorporate revised pages re stack monitoring requirements, location of radiation air monitoring & correlation of noncontinuous environ sampling data w/meteorological data  
SCARAND, R Fuel Process & Fab Branch 79/05/16 1p

7907100710 Recommends approval of amend to License SUA-1350 to delete semiannual monitoring of effluents from lab stacks & change effluents from lab stacks & change location for background radon air monitoring from Wamsutter to Rawlins  
LINEHAN, J J Uranium Recovery Licensing Branch 79/05/16 2pp

7907190350 Forwards first const insp rept by US Army Corp of Engineers on 790329  
HELLER, L W Geosciences Branch 79/06/05 2pp

---7907190358 Insp rept of initial operations on tailings basin const on 790329 Progress is satisfactory Work is proceeding according to design  
DEPHILLIPE, A A Army, Dept of, Corps of Engineers 79/05/10 5pp

## DOCKET 40-8585 WYOMING MINERAL CORP

7907110178 Summary of 790509 site visit to facility in Cooperton, UT to assess status of operation & to discuss anticipated operational/equipment changes  
COOPERSTEIN, R Uranium Recovery Licensing Branch 79/05/21 2pp

## DOCKET 40-8602 UNITED NUCLEAR CORP

7907060508 Forwards "Preoperational Radiological Environ Monitoring Program Rept, " Aug 1978-May 1979, update  
NOLFF, C E Nuclear Dynamics 79/05/25 1pp

---7907060511 "Preoperational Radiological Environ Monitoring Program Rept" Aug 1978-May 1979, update  
\* United Nuclear Corp 79/05/10, 153pp

7907020508 Forwards License SUA-1356  
SCARAND, R A Uranium Recovery Licensing Branch 79/05/10 2pp.

---7907020509 License SUA-1356 issued to United Nuclear Corp authorizing possession of byproduct mat'l in form of U waste tailings generated by licensee milling operations  
SCARAND, R A Uranium Recovery Licensing Branch 79/05/10 7pp

## DOCKETED ITEMS

## DOCKET 40-8616 AMERICAN CYANAMID CO

7907190851 Discusses IE insp of Licenses 24-14789-01 & SUB-1320 on 790312 & forwards notice of violation  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/01 2pp

--7907190865 Notice of violation from insp on 790312 Noncompliance noted failure to calibr survey instruments every 6 months & failure to post license conditions, amends & operating procedures  
\* Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/01 1p

## DOCKET 40-8663 NUCLEAR DYNAMICS, INC

7907110188 Summary of 790510 site visit to facility in Crook County, WY to view site & to discuss licensee proposed operational plans  
COOPERSTEIN, R Uranium Recovery Licensing Branch 79/05/23 2pp

7907060502 Forwards fourth quarterly rept for Feb-Apr 1979 for License SUA-1131  
STOICK, A F Nuclear Dynamics 79/05/25 1p

--7907060505 Fourth quarterly rept for Feb-Apr 1979 for License SUA-1131  
\* Nuclear Dynamics 79/05/25 65pp

## DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC

7907030221 Forwards "Tailings Mgt Sys," consisting of Apps A & B of license application  
BAKER, C E Energy Fuels Nuclear, Inc 79/06/19 1p

--7907030231 "Tailings Mgt Sys," consisting of App A & B to license application  
\* Energy Fuels Nuclear, Inc 79/06/30 50pp

7907020464 Forwards project site showing all identified archaeological sites Oversided drawing encl  
BAKER, C E Energy Fuels Nuclear, Inc 79/04/30 1p

7907020511 Requests place on agenda of 790627 meeting of Board of Oil, Gas & Mining Wishes to present reclamation & decommissioning plan for White Mesa U Mill & proposed surety arrangement for completion of reclamation & decommissioning are complete  
\* E F Uranium Group, Inc 79/05/22 1p

7907270374 Concurs w/recommendations & findings of White Mesa U Project FES  
KEENE, J Utah, State of 79/05/30 1p

7907240575 Requests rescheduling of presentation at 790627 meeting of Board of Oil, Gas & Mining requested in 790522 ltr  
Presentation at Jul meeting would allow addl time for preparation of rept re surety arrangements  
GLASIER, O E Energy Fuels Nuclear, Inc 79/05/31 1p

## DOCKET 40-8692 COTTER CORP

7907310367 Submits 790601 permit awarded to Cotter Corp by WY Dept of Environ Quality to mine Charlie test pit  
SMITH, T Cotter Corp 79/06/04 11pp

## DOCKET 40-8693 OGLE PETROLEUM, INC

7907310366 Submits plan for groundwater quality restoration for License SUA-1336 Project scheduled to begin 790806  
CATCHPOLE, G J Ogle Petroleum, Inc 79/06/08 4pp

## DOCKET 40-8698 PLATEAU RESOURCES, LTD

7907100687 Forwards EPA review of DES, NUREG-0504 Disagrees w/NRC assessment that environ costs would not decrease if Shootering Project was rejected, since impact would be shifted to other existing mill sites  
MERSON, A Environmental Protection Agency, 79/05/11 14pp

7907050546 Advises possible presence of Peregrine falcon & bald eagle in project area Outlines preparation of required biological assessment re endangered species  
REGAN, D H Interior, Dept. of, Fish & Wildlife Service 79/05/22 4pp

7907180856 Submits summary of 790220 meeting w/EPA & J Holtkamp, atty for Plateau Resources Ltd, re EPA permit requirements  
SEWELL, R B Plateau Resources, Ltd 79/05/29 2pp

7907310221 Forwards info re presence of endangered species at site, in response to DM Ryan 790922 ltr Surveys indicate no threatened plant or animal species in site vicinity  
SEWELL, R B Plateau Resources, Ltd 79/06/12 9pp

## DOCKET 40-8712 GULF OIL CORP

7907020465 Withdraws 790131 application for source matl license  
LINDLEY, P A Gulf Research & Development Co 79/05/10 1p

## DOCKET 40-8714 CLEVELAND CLIFFS IRON CO

7907060261 Forwards Radiation Handbook for Collins Draw Solution Extraction Recovery Plant  
SOMERVILLE, O K Cleveland-Cliffs Iron Co 79/04/26 1p

--7907060265 Radiation Handbook for Collins Draw Solution Extraction Recovery Plant  
\* Cleveland-Cliffs Iron Co 79/04/23 13pp

## DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

7907230101 Notifies of acceptance of environ rept re 790212 license application Copies of rept must be distributed per encl list  
SCARANO, R A Uranium Recovery Licensing Branch 79/06/05 4pp

## DOCKET 40-8722 BRUSH-WELLMAN, INC

7907110175 Summarizes 790508 site visit to facility in Delta Mill, UT to view site & to review responses to NRC questions re applicant submittals  
COOPERSTEIN, R Uranium Recovery Licensing Branch 79/05/22 2pp

7907120089 Notice that issuance of source matl license for U recovery operation will have no significant environ impact NRC has prepared environ/safety impact appraisal EIB not required  
SCARANO, R A Uranium Recovery Licensing Branch 79/06/06 1p

--7907120105 EIA re issuance of source matl license for U recovery from barren beryllium mill waste streams, Millard County, UT by Brush Wellman, Inc EIB not required per 10CFR91.5(b)  
COOPERSTEIN, R, SCARANO, R A Uranium Recovery Licensing Branch 79/06/06 42pp

7907270251 Notifies of license fee overpayment & intent to refund balance  
MILLER, W D License Fee Management Branch, 79/06/15 1p

## DOCKET 40-8725 GULF MINERAL RESOURCES CO

7907130457 Forwards "Groundwater Discharge Plan, Mt Taylor U Mill Project, NM"  
HOLFF, T A New Mexico, State of 79/05/25 1p

--7907130461 "Groundwater Discharge Plan, Mt Taylor U Mill Project, NM," prepared by Gulf Mineral Resources Co  
\* New Mexico, State of 79/05/31 175pp.

## DOCKET 40-8726 NEW MEXICO HEALTH - ENVIRONMENT DEPT

7907020481 Forwards matl re Bokum Resources Corp application W/o encl  
TOPP, A B New Mexico, State of 79/06/25 1p.

## DOCKET 40-8729 PIONEER URAVAN, INC

7907250399 Forwards radioactive matl license applications, as submitted to CO Dept of Health, Radiation & Hazardous Waste Control  
Div Follow up info will be submitted by 790801  
POLAK, R J Pioneer Nuclear, Inc, 79/06/04, 2pp

--7907250405 Application for State of CO radioactive matl license.  
STEWART, R B Pioneer Nuclear, Inc 79/04/18 80pp

--7907250412 Application for State of CD radioactive matl license Environ  
rept & investigation & design rept encl  
STEWART, R B Pioneer Nuclear, Inc 79/01/19 670pp

# DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

## DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

### G Inspection reports, IE Bulletins & correspondence

7907230433 Forwards IE Info Notice 79-16, "Nuclear Incident at TH1 "  
No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907250474 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## DOCKET 50-3 INDIAN POINT STATION, UNIT 1

### F Security, medical, emergency & fire protection plans

7907310449 Notices of completion & implementation of procedural  
changes for revised emergency plan, per 790327 ltr  
CAHILL, W J Consolidated Edison Co of New York 79/07/23 1p

### H General correspondence

7907170094 Forwards update of std distribution list for correspondence  
re facilities Requests incorporation of requested change  
CAHILL, W J Consolidated Edison Co of New York 79/07/09 2pp

7907190519 Requests organizational changes be incorporated into std  
distribution list  
CAHILL, W J Consolidated Edison Co of New York 79/07/09 2pp

### J Insurance & indemnity information

7907100591 Forwards Endorsements 90 & 91 to MAELU Policy MF-29 &  
Endorsements 102 & 103 to NELIA Policy NF-100  
CAHILL, W J Consolidated Edison Co of New York 79/06/28 3pp

7907270255 Forwards Con Ed 780413 ltr containing Amend 14 to Indemnity  
Agreement B-19  
CAHILL, W J Consolidated Edison Co of New York 79/07/23 1p

--7907270257 Forwards Amend 14 to Indemnity Agreement B-19  
CAHILL, W J Consolidated Edison Co of New York 78/04/13 3pp

### P Operating license stage documents & correspondence

7907310576 Forwards NRC 790515 ltr to licensees of Westinghouse  
two-loop plants re rod bank exchange method for verifying  
shutdown margin of two-loop NSSB  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15  
2pp.

7907060179 Responds to 790126, 0202 & 0316 ltrs re proposed license  
amend Meeting has been tentatively scheduled for early May  
to discuss proposed changes No hearings planned  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/18 4pp.

7907030322 "1976 Year-Class Rept for Multiplant Impact Study of Hudson  
River Estuary," prepared by TX Instruments Inc.  
\* Consolidated Edison Co of New York 79/05/31. 800pp

7907180158 Forwards NRC 790604 ltr to Westinghouse requesting addl info  
re small break LOCA analyses & analysis methods At some  
point, NRC will require documentation re applicability of  
Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11  
2pp

--7907180170 Requests addl info re small break LOCA analysis Info will be  
used in evaluating NRC licensing process in light of TH1  
accident.  
ROSS, D F Division of Project Management 79/06/04 9pp.

7907180618 Forwards NUREG-0560, "Staff Rept on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre  
790625). 79/06/11 2pp

7907050337 Forwards more clearly reproduced copies of revised page of  
ETS for 790412 application for amend re thermal plume  
mapping  
BLATT, M Consolidated Edison Co of New York 79/06/26 12pp

### G Inspection reports, IE Bulletins & correspondence

7907060376 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Licensee  
action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907180217 Forwards results of preliminary review of licensee responses  
to IE Bulletins 79-06, 79-06A & Amend 1 to 79-06 Meeting  
w/owners of operating plants having Westinghouse-designed  
sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22  
4pp

--7907180221 "Results of Preliminary Review of Licensee Responses to IE  
Bulletin 79-06A, Revision 1 "  
\* Office of Nuclear Reactor Regulation 79/05/22 52pp

7907030021 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907120409 Responds to IE Bulletins 78-12A & 12B re welds associated  
w/reactor vessels Since Unit 1 is in shutdown, requested info  
not available Presently awaiting info from supplier for Unit  
2 Will submit schedule when info is compiled  
CAHILL, W J Consolidated Edison Co of New York 79/05/29 2pp

7907200086 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190044 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907040083 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907110361 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230647 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts "   
Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240136 Forwards IE Circular 79-09, "Occurrences of Split or  
Punctured Regulator Diaphragms in Certain Self-Contained  
Breathing Apparatus " No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p.

7907120483 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907060177 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p.

7907100494 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director.  
79/06/28 1p

7907180753 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907250494 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
GRIER, B H Region 1, Philadelphia, Office of the Director.  
79/07/06 1p

## DOCKETED ITEMS

7907270320 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907250251 Forwards response to IE Bulletin 79-13 & discussion of cracking in feedwater sys piping Unit 1 presently in defueled condition awaiting until decision on ECCS installation  
CAHILL, W J Consolidated Edison Co of New York 79/07/16 4pp

7907310487 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R Periodic operating reports & related correspondence

7907180369 Forwards environ data for June 1979 re fish species & water discharge, as specified in Section 401  
MCNTI, W A Consolidated Edison Co of New York 79/07/10 18pp

7907180490 Forwards monthly operating rept for June 1979  
CAHILL, W J Consolidated Edison Co of New York 79/07/13 1p

--7907180494 Monthly operating rept for June 1979  
KAHULA, L Consolidated Edison Co of New York 79/07/05 8pp

#### B Reportable occurrences, LERs & related correspondence

7907160342 Forwards LER 79-019/04T-0  
O'TOOLE, J D Consolidated Edison Co of New York 79/07/09 1p

--7907160353 LER 79-019/04T-0 on 790619 activity of Eastview 790430 sample exceeded ten times control station level Caused by tritium releases of manufacturer near station  
SADLON, S Consolidated Edison Co of New York 79/07/06 2pp

#### DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

##### F Security, medical, emergency & fire protection plans

7907130420 Requests change to physical security plan Plan withheld (ref 10CFR 2790)  
CUNNINGHAM, R G Pennsylvania State Univ 79/07/05 3pp

#### I Inspection reports, IE Bulletins & correspondence

7907250460 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

#### DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

##### F Security, medical, emergency & fire protection plans

7907230513 Discusses safety evaluation review of fire protection sys mod Proposed mod acceptable Notes differing viewpoint supporting further evaluation re vent sys, valve supervision & interior hose stations  
HALL, R E Brookhaven National Laboratory 79/07/03 3pp

07310186 "Fire Protection in Operating Nuclear Power Stations, Dresden Unit 1, BER Review," Interim rept  
HALL, R E, MACDOUGALL, E A Brookhaven National Laboratory FIN 4-3107 7907310186 79/07/03 4pp

07110467 Forwards Unit Drawings 12E-143 & 12E-145 re conduit & tray layouts, per L Berderian request Drawings marked up to show able routing of power supply for sphere svc water booster jump 0-159 Drawings available in Central Files only  
LAUGHTON, W F Commonwealth Edison Co 79/07/05 1p

7907200381 Submits Classes I & III fees for safeguards contingency plans  
REED, C Commonwealth Edison Co 79/07/12 2pp

7907300330 Forwards Revision 2, interim physical security plan Plan withheld (ref 10CFR 2790)  
REED, C Commonwealth Edison Co 79/07/23 1p

#### G Adjudicatory correspondence

7907110720 Opposes several proposed actions re storage of Dresden spent fuel rods at Cordova plant & const of another plant in Erie-Springhill area Opposes nuclear energy in principle because of alleged inadequate storage methods for radwaste  
HGMAN, P Affiliation Unknown 79/05/31 2pp

#### H General correspondence

7907160298 Four ltrs opposing transport of 309 radioactive spent fuel rods between facilities  
WIRTH, S, RUNYON, J, QUILTY, J Affiliation Unknown 79/05/10 4pp

#### P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/BEP owner's group in Bethesda, MD re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625) 79/04/30 8pp

7907260089 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related re-evaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907310475 Discusses resolution of deterioration problem of Buna-N components in ASCO solenoid valves Response to IE Bulletin 78-14 has been revised to assure replacement of matl in necessary components by 801231  
REED, C Commonwealth Edison Co 79/05/31 3pp

7907250145 Forwards draft evaluation of BEP Topic VI-1, "Organic Matls & Post-Accident Chemistry  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 3pp

7907050224 Submits comments on BEP Topic XV-17 re radiological consequences of steam generator tube failure  
JANECEK, R F Commonwealth Edison Co 79/06/11 2pp

7907100449 Responds to NRC request re extent to which chemical cleaning facility complies w/Reg Guide 1.143 Plant meets requirements of Position 3 w/one exception, does not comply w/Position 5 & complies w/Position 6 in one area  
JANECEK, R F Commonwealth Edison Co 79/06/11 3pp

7907110631 Forwards Category 2 & 3 regulatory positions to be addressed in BEP Reg Guide 1.114 encl  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp

7907250176 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of BEP Topic VIII-3 B, "DC Power Bus Bus Voltage Monitoring & Annunciation "  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

7907090305 Submits addl info to 790102 ltr re current commitments to containment purging during normal plant operation Schedule for responding to issues re normal operation purging will be submitted by 790801  
REED, C Commonwealth Edison Co 79/07/02 3pp.

7907260031 Summary of 790628 meeting w/util in Bethesda, MD re purging & venting limits & performance of purge & vent valves during postulated LOCA  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/07/02 6pp

7907130322 Revises 790702 ltr re purging during normal operation No purging at power at Zion will be permitted until purge valves have been analyzed & determined to be capable of closure under DBA  
REED, C Commonwealth Edison Co 79/07/05 1p.

7907170055 Forwards responses to NRC concerns re calculation of local stresses in spherical shell at penetrations in Sargent & Lundy rept "Stress Rept for Primary Containment Penetration " Oversized drawings available in Central Files  
JANECEK, R F Commonwealth Edison Co, 79/07/10. 12pp

# DOCKETED ITEMS

## G Inspection reports, IE Bulletins & correspondence

7907190042 Forwards IE Insp Repts 50-010/79-05, 50-237/79-06 & 50-249/79-05 & on 790319-22 & 28 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 2pp

--7907190073 IE Insp Repts 50-010/79-05, 50-237/79-06 & 50-249/79-05 on 790319-22 & 28 No noncompliance noted Major areas inspected radiation protection program & licensee action on previously identified insp items  
FISHER, W L, MILLER, D E, HIATT, J W Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/23 6pp

7907190492 Forwards IE Insp Repts 50-010/79-08, 50-237/79-12 & 50-249/79-10 on 790402-30 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/14 2pp

--7907190497 Notice of violation from insp on 790402-30  
\* Region 3, Chicago, Office of the Director 79/05/10 1p

--7907190507 IE Insp Repts 50-010/79-08, 50-237/79-12 & 50-249/79-10 on 790402-30 Noncompliance noted exceeding limiting condition for operation  
BARKER, J L, SPESSARD, R L Region 3, Chicago, Office of the Director 79/05/10 12pp

7907060251 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit breakers in use or planned for use in any safety-related sys  
REED, C Commonwealth Edison Co 79/05/17 2pp

7907110068 Notifies that encl IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys," was sent to listed parties  
PAPPAS, H Region 3, Chicago, Office of the Director 79/05/24 1p

7907180101 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
REED, C Commonwealth Edison Co 79/05/25 7pp

7907200292 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907200296 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/07 1p

7907260223 Forwards IE Insp Repts 50-010/79-11, 50-237/79-14 & 50-249/79-12 on 790522 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/07 2pp

--7907260240 IE Insp Repts 50-010/79-11, 50-237/79-14 & 50-249/79-12 on 790522 No noncompliance noted Major areas inspected response of licensee organization during scheduled drill involving simulated contaminated injuries  
GRANT, W B, GREER, R J, ESSIG, T H Region 3, Chicago, Office of the Director 79/06/05 4pp

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures," was forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/21 1p

7907050441 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/22 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/25 1p

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/26 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/28 1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/02 1p

7907240273 Ack receipt of 790531 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/07/02 1p

--7907240274 Responds to NRC 790510 ltr re violations noted in IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06 Corrective actions administrative controls now minimize amount of combustible matl in safety-related areas  
REED, C Commonwealth Edison Co 79/05/31 4pp

7907130230 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
PAPPAS, H Region 3, Chicago, Office of the Director 79/07/03 2pp

7907240081 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/06 1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/18 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/20 1p

## R Periodic operating reports & related correspondence

7907170074 Forwards monthly operating rept for June 1979  
STEPHENSON, B B Commonwealth Edison Co 79/07/10 1p.

--7907170078 Monthly operating rept for June 1979.  
CIESZKIEWICZ, B Commonwealth Edison Co. 79/07/03 20pp

## DOCKETED ITEMS

## S Reportable occurrences, LERs &amp; related correspondence

7907290284 Forwards LER 79-002/03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/07/13 1p

--7907250291 LER 79-002/03L-0 on 780825 during monthly surveillance  
D15 5400-2, offgas Monitor 1 tripped at greater than 100%,  
which is not within setpoint limit Caused by instrument  
drift Setpoint recalibr  
MANCINI, B Commonwealth Edison Co 79/07/13 1p

## DOCKET 50-13 BADCOCK &amp; WILCOX CO CRITICAL FACILITY

## Q Inspection reports, IE Bulletins &amp; correspondence

7907240484 Forwards IE Info Notice 79-1B, "Skylab Reentry " No action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/06 1p

## DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

## D Advisory Committee on Reactor Safeguards reports &amp; correspondence

7907190246 Rept to ACRS, "Enrico Fermi Atomic Power Plant "  
\* Atomic Energy Commission (Pre 1975) 69/11/21 53pp

## P Operating license stage documents &amp; correspondence

7907190210 Forwards W Vivian ltr w/PA Bradford response  
BRADFORD, P A Commission 79/04/23 1p

--7907190214 FOIA request for rept describing events at 1966 Fermi-1  
nuclear incident  
VIVIAN, W Michigan Univ of 79/04/12 1p

--7907190219 Suggests that FOIA request be made to DDE Only rept on  
incident is technical assessment of accident & problems  
encountered in cleanup Ltr has been forwarded to ofc  
handling FOIA requests  
BRADFORD, P A Commission 79/04/23 1p

7907190221 Responds to FOIA request for rept describing events at 1966  
Fermi-1 nuclear incident  
FELTON, J M Division of Rules and Records 79/07/09 2pp

--7907190225 Summary of 661108 meeting w/WJ McCarthy & E Alexanderson re  
status rept on 661008 incident  
RIB, L N Atomic Energy Commission, Directorate of Licensing  
(Pre-1975) 66/11/17 5pp

--7907190231 Forwards 661025 Hart ltr to W Thomas & response to Hart  
request for info on question raised by Thomas  
KAVANAUGH, G M Atomic Energy Commission (Pre 1975) 66/11/21  
1p

--7907190235 Forwards "Preliminary Rept on Fuel Damage in Fermi Reactor,"  
w/conclusion determining reactor shutdown  
KAVANAUGH, G M Atomic Energy Commission (Pre 1975) 66/11/21,  
7pp

--7907190242 Forwards "Summary of Events Relating to Fermi Fuel Damage "  
HOBBS, F T Atomic Energy Commission (Pre 1975) 68/08/14 12pp

## R Periodic operating reports &amp; related correspondence

7907300362 Forwards annual rept for decommissioned facility,  
Jul 1978-June 1979  
WHITE, W W Detroit Edison Co 79/07/26 1p

--7907300375 Annual rept for decommissioned facility, Jul 1978-June 1979  
WHITE, W W, ALEXANDERSON, E Detroit Edison Co EF-125 79/07/23  
9pp

## DOCKET 50-20 MASSACHUSETTS INST OF TECH RES. REACTOR

## P Operating license stage documents &amp; correspondence

7907260579 Forwards Amend 16 to License R-37  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/06,  
pp

--7907260581 Amend 16 to License R-37, revising definitions section of  
Tech Specs to add definition of term frequency as applied to  
surveillance tests or other periodic activities  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/06  
5pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907230400 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/22 1p

7907250457 Forwards IE Info Notice 79-1B, "Skylab Reentry " No action  
required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## S Reportable occurrences, LERs &amp; related correspondence

7907100632 Notifies of RD 50-20/79-4 on 790622 possible fuel element  
cladding failure Reactor was shut down to identify & remove  
faulty element Cause unknown  
CLANCY, W, CLARK, L Massachusetts Institute of Technology  
79/07/02 4pp

7907110528 Forwards RD 50-20/79-04 on 790622 w/o encl  
CLARK, L Massachusetts Institute of Technology 79/07/06 1p

## DOCKET 50-22 WESTINGHOUSE TEST REACTOR

## P Operating license stage documents &amp; correspondence

7907020091 FOIA request for documents re compliance of NUMEC facility &  
Watts Mill plant w/NRC emission regulations, details on how  
wastes are removed & disposed of & any records of violations  
of NRC regulations & employee exposures  
GAZARIK, R, FRASER, J Tribune-Review Greenburg, PA 79/04/23 1p

7907020094 Responds to FOIA request for documents re NUMEC facility &  
Watts Mill plant w/NRC emission regulations, details on how  
waste disposal, violations, worker exposure to radiation &  
accident histories  
FELTON, J M Division of Rules and Records 79/06/13 1p

## Q Inspection reports, IE Bulletins &amp; correspondence

7907250357 Forwards IE Info Notice 79-1B, "Skylab Reentry " No action  
required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

## P Operating license stage documents &amp; correspondence

7907170123 Forwards Amend 9 to License R-76 Requests incorporation of  
revised SNM limits  
WILSON, W E Washington State Univ 79/07/09 1p

--7907170130 Amend 9 to License R-76, re SNM possession limits  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/07/02  
2pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907230602 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22 1p

7907230774 Forwards IE Info Notice 79-1B, "Skylab Reentry " No action  
required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/06 1p

## DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

## F Security, medical, emergency &amp; fire protection plans

7907090255 Submits info re conceptual design of plant fire protection  
sys  
MODDY, D E Yankee Atomic Electric Co 79/07/02 4pp

# DOCKETED ITEMS

79071302B3 Forwards modified amended physical security plan Plan withheld (ref 10CFR2 790)  
GRDCE,R H Yankee Atomic Electric Co 79/07/09 2pp

## J Insurance & indemnity information

79071B0495 Forwards Endorsements 88 & 89 to NELIA Policy NF-74 & Endorsements 74 & 75 to MAELU Policy MF-26  
NESBITT,J C Yankee Atomic Electric Co 79/07/11 5pp

## P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/SEP owner's group in Bethesda,MD re technical details of site-specific spectra project  
LEVIN,H A Systematic Evaluation Programs Branch (Pre 790625) 79/04/30 8pp

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design per TMI-2 event  
THADANI,A Reactor Systems Branch 79/05/02 39pp

7907060072 Forwards replacement pages which correct errors in Amends 57 & 58 to License DPR-3  
ZIEHANN,D L Operating Reactors Branch 2 (Pre 790625) 79/05/09 10pp

7907310560 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSS  
ZIEHANN,D L Operating Reactors Branch 2 (Pre 790625) 79/05/15 2pp

7907260090 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER,B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907180745 Requests registration as user of Hittman Nuclear & Development Corp shipping packages HN-200 & HN-600  
MOODY,D E Yankee Atomic Electric Co 79/05/29 1p

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related re-evaluations of operating plants  
KANE,W F Standardization Branch 79/05/31 4pp

7907310281 Requests addl info re SEP Topic VI-1, "Organic Matls & Post-Accident Chemistry " Forwards list of info needed  
ZIEHANN,D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 2pp

7907110641 Forwards Category 2 & 3 regulatory positions to be addressed in SEP Reg Guide 1 114 encl  
ZIEHANN,D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp

7907240569 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods  
Documentation re applicability of Westinghouse results to analyses at facility will eventually be required by NRC  
SCHNENCER,A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907230188 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation "  
ZIEHANN,D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

7907100427 Forwards specs for installation of containment vapor container coating sys NRC questions raised in 790606 ltr re aluminum,zinc & organic matl which may be subj to rust do not apply,as facility does not use containment spray  
GRDCE,R H Yankee Atomic Electric Co 79/06/26 1p.

--7907100433 "Specs for Vinyl Plastic Coating for Exterior & Interior of Vapor Container," prepared by BKW  
\* Yankee Atomic Electric Co 59/03/02 16pp

7907310427 Responds to NRC 790629 ltr re mgt & technical resources available to handle unusual events Util organization structure & summaries of combined offsite mgt resources encl  
MINNICK,L E. Yankee Atomic Electric Co. 79/06/26 22pp

7907100594 Responds to remaining items of NRC 790525 ltr re steam generator feedwater piping.  
GRDCE,R H Yankee Atomic Electric Co. 79/07/02 2pp

7907170145 Ack receipt of NRC 790618 ltr re SEP Topic VIII-3 B,DC Power Sys Bus Voltage Monitoring & Annunciation Provides list of alarms & voltage monitoring devices available to provide operability status indication  
GRDCE,R H Yankee Atomic Electric Co 79/07/12 2pp

## Q Inspection reports, IE Bulletins & correspondence

7907310023 Forwards summary of 790306 meeting w/utill in King of Prussia,PA Info presented resulted in withdrawal of Item B from 781222 notice of violation  
SMITH,G H Region 1, Philadelphia, Office of the Director 79/05/02 2pp

--7907310027 Summary of 790306 meeting w/utill in King of Prussia,PA re 781222 notice of violation Item 50-029/78-19-07 will be withdrawn  
SMITH,G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/06 2pp

--7907310158 Ack receipt of 790116 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/78-19  
SMITH,G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/02 2pp

--7907310163 Responds to NRC 781222 ltr re violations noted in IE Insp Rept 50-029/78-19 Corrective actions errors in record were corrected by inspector, responsible personnel were instructed in maint of records & radiation areas were posted  
MOODY,D E Yankee Atomic Electric Co 79/01/16 5pp

--7907310167 Forwards IE Insp Rept 50-29/78-19 on 781106-08 & notice of violation  
SMITH,G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/12/22 3pp

--7907310171 Notice of violation from insp on 781106-08  
\* Region 1, Philadelphia, Office of the Director 78/12/20 2pp

--7907310178 IE Insp Rept 50-029/78-19 on 791106-08 Noncompliance noted Failure to prepare rept on exposure of employees,failure to maintain rept on radiation monitoring & failure to post two radiation areas  
PLUMLEE,K E, CLEMONS,P E Region 1, Philadelphia, Fuel Facility & Materials Safety Branch CROCKER,H W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 78/12/20 9pp

7907090076 Responds to IE Bulletin 79-09 Undervoltage trip devices are not installed AK-2 circuit breaker used in diesel generator incoming lines,emergency bus-bus tie,pump feeder circuit breakers & emergency motor control ctr circuit breakers.  
GRDCE,R H Yankee Atomic Electric Co 79/05/18 2pp

7907090153 Responds to IE Bulletin 79-10 re examination of reactor operators  
MOODY,D E Yankee Atomic Electric Co 79/05/22 3pp

7907060436 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER,B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907240626 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06,06A & 06,Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda,MD.  
SCHNENCER,A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907190684 Responds to IE Bulletin 79-06A (Ref 6) Lists ECCB cutback or termination criteria & endorses termination of main coolant sys pumped flow as core cooling method following accident  
MOODY,D.E. Yankee Atomic Electric Co 79/05/24 2pp

7907030078 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER,B H Region 1, Philadelphia, Office of the Director 79/05/29 1p.

7907200156 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER,B H Region 1, Philadelphia, Office of the Director. 79/05/31 1p.

7907190123 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Boland Valves) " Action required  
GRIER,B H Region 1, Philadelphia, Office of the Director. 79/06/06 1p.

7907060140 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907100481 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907300441 Forwards supplemental response to IE Bulletin 79-06A Submits info re void formation in RCS, automatic trip valves, training instructions re safety features & reactor coolant pump operation during transient  
MOODY, D E Yankee Atomic Electric Co 79/06/20 4pp

7907230715 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240211 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907120585 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907020202 Forwards Revision 1 to inservice insp program for 7B0301-B10630  
EDWARDS, D W Yankee Atomic Electric Co 79/06/26 1p

--7907020207 Revision 1 to inservice insp program fulfilling requirement of ASME code Section XI re Class I, II & III pressure retaining components  
RANDALL, R G, EBERT, M W, MOODY, D E Yankee Atomic Electric Co  
79/06/26 87pp

7907100381 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100513 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180834 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907250532 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

7907270373 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310547 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R Periodic operating reports & related correspondence

790717016B Forwards monthly operating rept for June 1979  
MOODY, D E Yankee Atomic Electric Co 79/07/12 1p

--7907170172 Monthly operating rept for June 1979  
BJOGREN, R M Yankee Atomic Electric Co 79/07/12 5pp

#### B Reportable occurrences, LERs & related correspondence

7907030180 FOIA request for reportable event or abnormal occurrence files from 601110 through 1965  
QOSSELIN, P Q Affiliation Unknown, 79/04/04 1p

7907030174 Responds to FOIA request for reportable events or abnormal occurrences files for 601110 through 1965  
FELTON, J M Division of Rules and Records 79/06/05 1p

7907100485 Forwards LER 79-017/03L-0  
AUTIO, H A Yankee Atomic Electric Co 79/07/06 1p

--7907100489 LER 79-017/03L-0 on 790607 steam generator blowdown radiation monitor failed high Caused by failure of rate meter unit internal circuits Failed printed circuit cards replaced w/spares & channel returned to normal  
LONG, D G Yankee Atomic Electric Co 79/07/06 1p

7907100493 Forwards LER 79-016/03L-0  
AUTIO, H A Yankee Atomic Electric Co 79/07/06 1p

--7907100500 LER 79-016/03L-0 on 790607 steam generator B blowdown radiation monitor failed low Caused by failure of pre-amp unit in monitor Unit replaced w/spare & channel returned to normal  
LONG, D G Yankee Atomic Electric Co 79/07/06 1p

#### DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

##### G Inspection reports, IE Bulletins & correspondence

7907250440 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

#### DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

##### P Operating license stage documents & correspondence

7907030263 Forwards Amend 14 to License R-B1, safety evaluation & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/17 4pp

--7907030269 Amend 14 to License R-B1 changing Tech Specs to permit power increase from 100 to 250 KW in natural convection mode  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/17 3pp

--7907030270 Safety evaluation supporting Amend 14 to License R-B1  
\* Operating Reactors Branch 4 (Pre 790625) 79/05/17 10pp

--7907030271 App A to Tech Specs, reflecting Amend 14 change permitting power increase  
\* Operating Reactors Branch 4 (Pre 790625) 79/05/17 58pp

##### G Inspection reports, IE Bulletins & correspondence

790723038B Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/22 1p

7907250352 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

#### DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

##### P Operating license stage documents & correspondence

7907180897 Forwards Amend 17 to License R-77 & safety evaluation  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/07 2pp

--7907180843 Amend 17 to License R-77, incorporating Tech Specs contained in App A  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/07 7pp

--7907180867 Safety evaluation supporting Amend 17 to License R-77  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/07 5pp

##### G Inspection reports, IE Bulletins & correspondence

7907100230 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director,  
79/05/18, 2pp.



7907200395 Ack receipt of 790515 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-057/79-02  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/18 1p

--7907200400 Responds to NRC 790416 ltr re violation noted in IE Insp Rept 50-057/79-02 Not yet in compliance Hopes to have solution in six-eight weeks  
ORLOBSKY, P M New York, State Univ of, Buffalo 79/05/15 1p

--7907200406 Forwards IE Insp Rept 50-057/79-02 on 790313-15 & notice of violation  
BRUNNER, E J Region 1, Philadelphia, Office of the Director 79/04/16 2pp

--7907200416 Notice of violation from insp on 790313-15  
\* Region 1, Philadelphia, Office of the Director 79/04/16 1p

--7907200420 IE Insp Rept 50-057/79-02 on 790313-15 Noncompliance noted failure to provide NSC review of operating procedures  
RAYMOND, W J, MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/16 9pp

7907230467 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p

#### DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

##### J Insurance & indemnity information

7907090236 Submits executed Amend 14 to Indemnity Agreement E-12, increasing coverage to \$160,000,000  
MILLER, J E Texas A & M Univ 79/07/02 2pp

##### F Operating license stage documents & correspondence

7907030467 Forwards revised pages to Tech Spec App A, per 790425 Amend 12 to License R-23  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/24 9pp

7907090314 Forwards annual operations rept for June 1978-May 1979 re AGN-201M training reactor, License R-23  
COCHRAN, R G Texas A & M Univ 79/06/28 1p

--7907090317 Annual operations rept, June 1978-May 1979, for AGN-201M training reactor, License R-23  
ZOLICZYNSKI, J Texas A & M Univ 79/05/31 9pp

##### G Inspection reports, IE Bulletins & correspondence

7907100259 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p.

7907020030 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907230507 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

##### R Periodic operating reports & related correspondence

7907030247 Forwards "Annual Operations Rept of AGN-201M Training Reactor, License R-23," June 1978-May 1979  
COCHRAN, R G Texas A & M Univ 79/06/21 1p

--7907030247 "Annual Operations Rept of AGN-201M Training Reactor, License R-23," for June 1978-May 1979  
ZOLICZYNSKI, J B, COCHRAN, R G Texas A & M Univ 79/05/31 9pp

#### DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

##### G Inspection reports, IE Bulletins & correspondence

7907100081 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/18 1p

7907230415 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

#### DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

##### G Adjudicatory correspondence

7903230309 Informs of status of geology review license final documentation of geology investigations expected by 790228  
NRC review will take several months  
SHANSON, D T Branch 1 79/02/23 1p

7907130287 Orders each party to address ASLB in written memorandum re intervenor R Dellums Directs parties to discuss status of intervenor & whether case should be referred to DSJ  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/18 3pp

7907190631 Orders parties to respond to questions re intervention of Congressman Dellums & representation by Halterman & Snow  
Focus of questions standing & possible violation of federal criminal law  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/18 3pp

##### P Operating license stage documents & correspondence

7907240433 Forwards questions from US Geological Survey re seismological aspects of site Requests review of technical & policy issues  
JACKSON, R E Geosciences Branch 79/05/30 8pp

7907190616 Submits info re USGB paper on quaternary deposits & faults offsetting alluvial deposits in San Francisco Bay region  
Requests info be included in preparation of GER  
DARMITZEL, R W General Electric Co, Nuclear Energy Products Div 79/07/12 2pp

##### G Inspection reports, IE Bulletins & correspondence

7907130171 Forwards IE Insp Rept 50-070/79-01 No noncompliance noted  
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/04 2pp

--7907130179 IE Insp Rept 50-070/79-01 on 790327-29 No noncompliance noted Major areas inspected organization, logs & records & containment leak rate test  
CANTER, H L, JOHNSTON, O W, FAULKENSBERY, D Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/04 3pp

7907230542 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907230749 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

#### DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

##### G Inspection reports, IE Bulletins & correspondence

7907100263 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020028 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907230514 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI, " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

#### DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

##### P Operating license stage documents & correspondence

7906200236 Forwards "Requalification Program for GE Nuclear Test Reactor" as part of request for renewal application for License R-33  
DARMITZEL, R W General Electric Co, Nuclear Energy Products Div. 79/06/13 2pp

## DOCKETED ITEMS

--7906200240 "Requalification Program for GE Nuclear Test Reactor "  
 \* General Electric Co ,Nuclear Energy Products Div NEDO-12724  
 79/05/31 16pp

7907120383 Forwards responses to questions in NRC 790427 ltr re  
 structural mod for test reactor  
 DARMITZEL,R W General Electric Co ,Nuclear Energy Products Div  
 79/07/09 33pp

Q Inspection reports, IE Bulletins & correspondence

7907230542 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/06/22 1p

7907230749 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/07/06 1p

DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907230392 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 GRIER,B H Region 1, Philadelphia, Office of the Director  
 79/06/22 1p

7907250430 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 GRIER,B H Region 1, Philadelphia, Office of the Director  
 79/07/06 1p

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907200225 Forwards IE Insp Rept 50-083/79-01 on 790427 No  
 noncompliance noted  
 KENNA,W B Region 2, Atlanta, Safeguards Branch 79/05/11 2pp

--7907200241 IE Insp Rept 50-083/79-01 on 790427 No noncompliance noted  
 Major areas inspected security plans, protection of SNM,  
 security organization, access control, locks, procedures &  
 security program  
 MOORE,D E , TODIN,W J Region 2, Atlanta, Safeguards Branch  
 79/05/11, 4pp

7907100085 Forwards IE Circular 79-08, "Attempted Extortion - Low  
 Enriched U " No action required  
 O'REILLY,J P Region 2, Atlanta, Office of the Director  
 79/05/18 1p

7907230413 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 O'REILLY,J P Region 2, Atlanta, Office of the Director  
 79/06/22 1p

7907240474 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 O'REILLY,J P Region 2, Atlanta, Office of the Director  
 79/07/06 1p

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

Q Inspection reports, IE Bulletins & correspondence

7907230425 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 KEPPLER,J O Region 3, Chicago, Office of the Director 79/06/22  
 1p.

7907240016 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required.  
 KEPPLER,J O Region 3, Chicago, Office of the Director 79/07/09  
 1p

DOCKET 50-89 GENERAL ATOMIC CO

F Security, medical, emergency & fire protection plans

7907050308 Forwards five revised pages to modified physical security  
 plan for guard training & qualification plan Pages withheld  
 (ref 10CFR2 750).  
 MOHRV,W R General Atomic Co (subs. of Gulf Oil Corp ). 79/06/28  
 1p

Q Inspection reports, IE Bulletins & correspondence

7907230536 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/06/22 1p

7907230747 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/07/06 1p

DOCKET 50-94 ROCKWELL INTERNATIONAL RESEARCH REACTOR

J Insurance & indemnity information

7907120399 Forwards executed copy of Amend 13 to Indemnity Agreement  
 B-13  
 WHEELER,L W Rockwell International Corp 79/06/27 2pp

Q Inspection reports, IE Bulletins & correspondence

7907230547 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/06/22 1p

7907230754 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/07/06 1p

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907230396 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 GRIER,B H Region 1, Philadelphia, Office of the Director  
 79/06/22 1p

7907250453 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 GRIER,B H Region 1, Philadelphia, Office of the Director  
 79/07/06 1p

DOCKET 50-99 BARCOCK & WILCOX TEST REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907240484 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 O'REILLY,J P Region 2, Atlanta, Office of the Director  
 79/07/06 1p

DOCKET 50-106 OREGON STATE UNIV

Q Inspection reports, IE Bulletins & correspondence

7907230562 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/06/22 1p

7907230759 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required  
 ENGELKEN,R H Region 5, San Francisco, Office of the Director  
 79/07/06 1p

DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907100102 Forwards IE Circular 79-08, "Attempted Extortion - Low  
 Enriched U " No action required.  
 O'REILLY,J P Region 2, Atlanta, Office of the Director  
 79/05/18 1p.

7907230410 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
 No action required.  
 O'REILLY,J P Region 2, Atlanta, Office of the Director  
 79/06/22 1p

7907240468 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

## DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907100256 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020024 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907230510 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

## DOCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907230548 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907230741 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

## DOCKET 50-115 ELK RIVER REACTOR

P Operating license stage documents & correspondence

7907190703 Responds to FOIA request for documents re decommissioning of Elk River, MN reactor & shipment of decommissioned matl to Sheffield, IL low level nuclear waste site Documents in microfiche being sent to Region 3 for insp  
FELTON, J M Division of Rules and Records 79/07/17 1p

## DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907310180 Forwards IE Insp Rept 50-116/79-02 on 790522-24 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch, 79/06/14 2pp

--7907310189 IE Insp Rept 50-116/79-02 on 790522-24 No noncompliance noted Major areas inspected records, logs & organization, review & audit functions, requalification training, procedures, surveillance & maint  
SWANSON, E R, LITTLE, W B Region 3, Chicago, Office of the Director 79/06/14 4pp

7907230428 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907240022 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09 1p

## DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907230435 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI, " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907240033 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09 1p

## DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

P Operating license stage documents & correspondence

7907300143 Forwards review items & power increase SAR topics to facilitate renewal of License R-62, which expires 791116  
RCID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/01 10pp

Q Inspection reports, IE Bulletins & correspondence

790100078 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907230416 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907240476 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

## DOCKET 50-128 TEXAS A&amp;M UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7907100596 Forwards preliminary physical security plan Plan withheld (ref 10CFR2 790)  
MILLER, J E Texas A & M Univ 79/07/02 2pp

I Financial information

7907100624 Submits application for renewal of License R-B3 for continued operation of TRIGA pool-type reactor W/supporting documents & financial rept for year ending 780831  
MILLER, J E Texas A & M Univ 79/07/02 2pp

--7907100627 Annual financial rept of TX Engineering Experiment Station for year ending 780831  
BENSON, O J, FENNER, E H, WHITMORE, H E Texas A & M Univ 78/08/31 22pp

P Operating license stage documents & correspondence

7907100318 Forwards application for renewal of License R-B3, SNM requirements, SAR, Tech Specs, EIA, Emergency Plan & Operator Requalification Program  
MILLER, J E Texas A & M Univ 79/07/02 2pp

--7907100324 Application for renewal of License R-B3  
MILLER, J E Texas A & M Univ 79/07/03 2pp

--7907100340 SAR for License R-B3  
\* Texas A & M Univ 79/06/30 181pp

--7907100346 EIA for License R-B3  
\* Texas A & M Univ, 79/06/30 11pp

--7907100352 Emergency plan for License R-B3  
\* Texas A & M Univ 79/06/30 18pp

--7907100359 Tech Specs for License R-B3  
\* Texas A & M Univ 79/07/02 41pp

--7907100368 Reactor operator & senior reactor operator requalification program, Revision 2  
\* Texas A & M Univ 79/06/30 4pp

7907180445 Forwards corrected page 33 to Tech Specs for License R-B  
FELTZ, D E Texas A & M Univ 79/07/10 2pp

## DOCKETED ITEMS

## G Inspection reports, IE Bulletins &amp; correspondence

7907100259 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020030 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

79072300507 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

## R Periodic operating reports &amp; related correspondence

7907310392 Forwards "Fifteenth Progress Rept 1978," submitted to DOE  
RANDALL, J D Texas A & M Univ 79/07/23 2pp

--7907310393 "Fifteenth Progress Rept 1978," submitted to DOE  
BATES, E F, FELTZ, D E, HARRIS, C E Texas A & M Univ  
DRQ-4207-12 79/06/30 75pp

## S Reportable occurrences, LERs &amp; related correspondence

7907170040 Final RO rept re failure of experiment scram circuit to function during surveillance testing due to malfunction of reset switch. Caused by dust on moving parts. Switch cleaned & immediately functioned.  
FELTZ, D E Texas A & M Univ 79/06/25 2pp

## DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR

## P Operating license stage documents &amp; correspondence

7907240573 Forwards Amend 7 to License R-58 & safety evaluation  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/13 2pp

--7907240549 Amend 7 to License R-58 allowing transfer of fuel to licensed party  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/13 2pp

--7907240578 Safety evaluation supporting Amend 7 to License R-58  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/13 2pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907100193 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907230418 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907240478 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

## DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR

## Operating license stage documents &amp; correspondence

7907310614 Forwards FR notice of proposed renewal of amended License R-57  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/08 2pp

--7907310617 Notice of proposed renewal of amended License R-57  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/08 3pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907100245 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020017 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907230437 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907310615 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06 1p

## DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

## G Adjudicatory correspondence

7907180630 Order reiterating 790507 order, requesting util to submit rept re ongoing geologic investigation. First rept must be made within 10 days & then regularly every 60 days.  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/19 1p

## P Operating license stage documents &amp; correspondence

7907180657 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907230242 Notifies that requested info for review of corporate capabilities will be submitted by 790730. Info requested in Sections I & II B of NRC 790629 ltr will be submitted upon completion.  
CRANE, P A Pacific Gas & Electric Co 79/07/16 1p

## G Inspection reports, IE Bulletins &amp; correspondence

7904130346 Forwards PNO-79-67P  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/09 1p

7904160043 Forwards PNO-79-67Q  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/10 1p

7907110078 Forwards IE Insp Rept 50-133/79-01 on 790320-23 No noncompliance noted  
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/04 2pp

--7907110092 IE Insp Rept 50-133/79-01 on 790320-23 No noncompliance noted. Major areas inspected: changes to procedures, fire protection/prevention, followup on IE bulletins, circulars & LERs.  
BTERNBERG, D, MORRILL, P J Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/03 6pp

7906200052 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/29 1p

7907090161 Responds to IE Bulletin 79-04 No Velan swing check valves in use or planned for use.  
CRANE, P A Pacific Gas & Electric Co 79/05/30 1p

7907190417 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p

7907060029 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07 1p

# DOCKETED ITEMS

7907020448 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p

7907120008 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/21 1p

7907110200 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907120617 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/25 1p

7907060216 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907100529 Forwards IE Circular 79-12, "Potential Diesel Generator Turbcharger Problem " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/28 1p

7907130203 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p

7907230777 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

7907270377 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/11 1p

7907310396 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260270 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

## R Periodic operating reports & related correspondence

7907180402 Forwards monthly operating rept for June 1979 WEEKS, E D Pacific Gas & Electric Co 79/07/10 2pp

--7907180409 Monthly operating rept for June 1979 GETTY, B C Pacific Gas & Electric Co 79/07/02 3pp

## B Reportable occurrences, LERs & related correspondence

7905020227 Forwards PNO-79-67AF ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/04/28 1p

7905020256 Forwards PNO-79-67A0 ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/04/26 1p

7907020282 Forwards PNO-79-67AR ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/05 1p

7907020191 Forwards PNO-79-67AS ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/13 1p

7907030232 Forwards PNO-79-67AT, "Nuclear Incident at TMI " ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/19 1p

7907050531 Forwards PNO-79-67AU ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907130384 Forwards PNO-79-67AV ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/03 1p

## DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

### P Operating license stage documents & correspondence

7907200311 Requests 20-yr extension of License R-61 issued on 591216 & due to expire on 791123 Inst does not plan substantive changes in reactor operation Safety analysis & Tech Specs being revised BDLZ, R E Worcester Polytechnic Inst 79/07/16 2pp

### G Inspection reports, IE Bulletins & correspondence

7907250477 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required ORIER, D H Region 1, Philadelphia, Office of the Director 79/07/06 1p

## DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

### G Inspection reports, IE Bulletins & correspondence

7907230601 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907230772 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

## DOCKET 50-142 UCLA TRAINING REACTOR

### P Operating license stage documents & correspondence

7907090046 Requests authorization to ship irradiated fuel plates by placing threaded steel rod/plywood cask basket inside GE 700 cask ASHBAUGH, C E California, Univ of, Los Angeles 79/09/15 2pp

### G Inspection reports, IE Bulletins & correspondence

7907230594 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907230766 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

## DOCKET 50-147 ROCKWELL INTL CORP CRITICAL FACILITY

### J Insurance & indemnity information

7907120399 Forwards executed copy of Amend 13 to Indemnity Agreement B-13 WHEELER, L W Rockwell International Corp 79/06/27 2pp

## DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

### G Inspection reports, IE Bulletins & correspondence

7907100271 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required, BEYFRIT, K V Region 4, Dallas, Office of the Director. 79/05/18 1p

7907020022 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

## DOCKETED ITEMS

7907230508 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22  
1p

R Periodic operating reports & related correspondence

7907270151 Submits annual routine rept for License R-78  
HEBLER, R D Kansas, Univ of 79/07/16 2pp

DOCKET 50-150 OHIO STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907230430 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907240026 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09  
1p

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

7907230432 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907240030 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09  
1p

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

A Application/construction stage documents & correspondence

7907030428 Submits offer to provide NRC w/steel & concrete test  
specimens w/protective coating sys presently employed in  
nuclear facilities  
PUSCHEL, M A Consumers Power Co 79/06/27 3pp

F Security, medical, emergency & fire protection plans

7907190415 Submits mds to 790301 followup to fire protection  
administrative guidelines Audits are performed biennially,  
not biannually Fire protection needs must be identified when  
maint orders submitted  
HOFFMAN, D P Consumers Power Co 79/07/16 1p

7907300318 Forwards appropriate Class III payment in response to 790703  
request for fees for contingency plans & guard training  
plans  
FDOO, W G Consumers Power Co 79/07/24 1p

P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/BEP owner's group in Bethesda, MD  
re technical details of site-specific spectra project  
LEVIN, M A Systematic Evaluation Programs Branch (Pre 790625)  
79/04/30 8pp

7907180756 Discusses QA for radioactive matl transportation Util will  
use latest version of QA topical rept CPC-1-A for  
radioactive matl transportation & plant operations  
HOFFMAN, D P Consumers Power Co 79/05/15 1p

7907260095 Discusses plans to install communication links between NRC &  
nuclear facilities for emergency use. Direct lines from each  
facility to NRC headquarters & regional ofc will communicate  
operational & environ info  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22  
2pp

7907190325 Summary of 790321 meeting w/Exxon re role in TMI-related  
re-evaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907310273 Requests addl info re SEP Topic VI-1, "Organic Matls &  
Post-Accident Chemistry " Forwards list of info needed  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06  
3pp

7907110623 Forwards Category 2 & 3 regulatory positions to be addressed  
in SEP Reg Guide 114, Revision 1, encl  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11  
7pp

7907250178 Requests listing of alarms & voltage monitoring devices  
available to provide operability status indication to  
complete evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus  
Voltage Monitoring & Annunciation "  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18  
2pp

7907030428 Submits offer to provide NRC w/steel & concrete test  
specimens coated w/protective coating sys presently  
employed in nuclear facilities  
PUSCHEL, M A Consumers Power Co 79/06/27 3pp

7907170024 Responds to NRC 790606 ltr requesting addl info to  
evaluate SEP Topic VI-1, "Organic Matl & Post-Accident  
Chemistry "  
HOFFMAN, D P Consumers Power Co 79/07/12 2pp

7907190536 Forwards requests for Tech Spec changes  
HOFFMAN, D P Consumers Power Co 79/07/16 1p

--7907190340 Requests change to Tech Spec for License DPR-6 Changes made  
within Administrative Controls Section, Chapter 6  
DEWITT, R B Consumers Power Co 79/07/16 11pp

--7907190550 Requests change to Tech Spec for License DPR-20 Changes made  
within Administration Controls Section, Chapter 6  
DEWITT, R B Consumers Power Co 79/07/16 14pp

7907260727 Forwards list of alarms & voltage monitoring devices  
associated w/Class IE batteries, in response to NRC 790618  
request  
BIXEL, D A Carolina Power & Light Co 79/07/23 4pp

Q Inspection reports, IE Bulletins & correspondence

7907260290 Forwards IE Insp Rept 50-155/79-08 on 790417-12 No  
noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear  
Support Branch 79/05/08 2pp

--7907260300 IE Insp Rept 50-155/79-08 on 790417-20 No noncompliance  
noted Major areas inspected moderator temp coefficient,  
control rod sequence & reactivity checks, control rod scram  
time tests & shutdown margin determination  
CHOW, E T, HONG, B M K, STREETER, J F Region 3, Chicago, Office  
of the Director 79/05/07 6pp

7907180307 Forwards IE Insp Rept 50-155/79-09 on 790424-25 No  
noncompliance noted  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering  
Support Branch 79/05/15 2pp

--7907180319 IE Insp Rept 50-155/79-09 on 790424-25 No noncompliance  
noted Major areas inspected leakage at control rod drive  
penetration F2  
LEE, E W K Region 3, Chicago, Office of the Director 79/05/10  
3pp.

7907190289 Responds to IE Bulletin 79-10 re requalification training of  
reactor operators & senior operators Pertinent info encl  
BIXEL, D A Consumers Power Co 79/05/25 3pp.

7907160234 Responds to IE Bulletin 79-12B re atypical weld matl in  
reactor pressure vessel welds C-E will submit generic rept  
before 790608 Util will ref C-E rept in response by 790629  
Final response will be submitted by 790731  
BIXEL, D A Consumers Power Co 79/05/29 1p

7907190239 Responds to IE Bulletin 79-12B re atypical weld matl in  
reactor pressure vessel welds C-E is performing records  
search & will submit generic rept directly to NRC by 790608  
BIXEL, D A Consumers Power Co 79/05/29 1p

7907200310 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31  
1p

7907190245 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240252 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07  
1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp

7907020423 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20  
1p

7907120225 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907050445 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907120700 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

7907300479 Insp Rept 50-153/79-10 on 790506-10 & 0611-13 No noncompliance noted Major area inspected engineered safety features, operating procedures & operator training  
RIDGWAY, K R ; BOYD, D C Region 3, Chicago, Office of the Director 79/06/25 7pp

7907060310 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907180406 Forwards IE Circular 79-12, "Potential Diesel Generator Turbcharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130262 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p

7907240089 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06  
1p

7907310328 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310406 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907240324 Forwards "Special Rept 28 1979 Inservice Insp & "  
BIXEL, D A Consumers Power Co 79/07/18 1p

--7907240328 "Special Rept 28 1979 Inservice Insp & "  
\* Consumers Power Co 79/07/18 28pp

7907260168 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907260354 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Separated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907250228 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20  
1p

7907270215 Requests approval of 781222 request for relief from Section XI of ASME Boiler & Pressure Code re inservice insp program  
Proposals for specific code mods encl  
BIXEL, D A Consumers Power Co 79/07/25 24pp

R Periodic operating reports & related correspondence

7907130393 Forwards monthly operating rept for June 1979  
HARTMAN, C J Consumers Power Co 79/07/06 2pp

--7907130399 Monthly operating rept for June 1979  
HIMEBAUCH, N Consumers Power Co 79/07/06 4pp

S Reportable occurrences, LERs & related correspondence

7907200378 Forwards LER 79-021/03L-0  
HOFFMAN, D P Consumers Power Co 79/07/13 1p

--7907200384 LER 79-021/03L-0 on 790616 static inverter power supply for one containment vacuum relief loop found de-energized  
Caused by blow input fuse Fuse replaced & routine equipment checks undertaken  
\* Consumers Power Co 79/07/13 1p

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7907230436 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907240066 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09  
1p

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7907230396 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

7907250493 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p

DOCKET 50-160 GEORGINA INST OF TECH RESEARCH REACTOR

P Operating license stage documents & correspondence

7907060093 Forwards Amend 4 to License R-97 & safety evaluation  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/30  
2pp

--7907060098 Amend 4 to License R-97 incorporating organizational changes, reactivity limits & surveillance changes & permitting 2-mode power operation  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/30  
12pp

--7907060104 Safety evaluation supporting Amend 4 to License R-97  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/30  
5pp.

G Inspection reports, IE Bulletins & correspondence

7907100457 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

## DOCKETED ITEMS

7907230408 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

7907240464 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/06 1p

## DOCKET 50-163 GENERAL ATOMIC COMPANY

F Security, medical, emergency & fire protection plans

7907050308 Forwards five revised pages to modified physical security  
plan for guard training & qualification plan Pages withheld  
(ref 10CFR2 790)  
MOWRY, W R General Atomic Co (subs of Gulf Oil Corp ) 79/06/28  
1p

G Inspection reports, IE Bulletins & correspondence

7907230536 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22 1p

7907230747 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/06 1p

## DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7907250471 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

P Operating license stage documents & correspondence

7907090349 Forwards Amend 17 to Tech Specs for License R-84  
MCINDOE, D W Defense, Dept of, Defense Nuclear Agency 79/07/02  
1p

--7907090354 Amend 17 to Tech Specs for License R-84, developed per Reg  
Guide 1 16 & proposed ANSI Std 15 18  
\* Defense, Dept of, Defense Nuclear Agency 79/07/02 37pp

G Inspection reports, IE Bulletins & correspondence

7907250437 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

J Insurance & indemnity information

7907130374 Forwards executed Amend 20 to Indemnity Agreement B-2B  
BRADLEY, E J Philadelphia Electric Co 79/07/09 3pp

R Periodic operating reports & related correspondence

7907260432 Forwards Decommission Annual Rept 1978  
ALDEN, W M Philadelphia Electric Co 79/07/19 1p

--7907260439 Decommission Annual Rept 1978  
\* Philadelphia Electric Co 79/07/19 1p

U Congressional/Executive Correspondence

7907180696 Responds to 790507 ltr re facilities in light of accident at  
TMI Forwards actions taken at facilities as result of TMI  
incident  
HENDRIE, J M Commission 79/06/28 3pp

--7907180713 Requests thorough insp of facilities in light of accident at  
TMI Requests info re exact steps being taken to guard  
against TMI-type accident at facilities  
ROTH, W V Senate 79/05/07 1p

## DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7907230431 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/22  
1p

7907240027 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/09  
1p

## DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

G Inspection reports, IE Bulletins & correspondence

7907130156 Ack receipt of 790601 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Rept 50-184/79-02  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/06/08  
1p

--7907130160 Forwards IE Insp Rept 50-184/79-02 on 790122-25 & notice of  
violation info withheld (ref 10CFR2 790)  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch  
79/05/08 2pp

--7907130163 IE Insp Rept 50-184/79-02 on 790122-25 Noncompliance noted  
Failure to requalify members of security force annually  
Details withheld (ref 10CFR2 790)  
BAILEY, R, GALLINA, C, DEVLIN, J W Region 1, Philadelphia,  
Safeguards Branch 79/05/04 1p

7907250442 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7907260272 Forwards IE Insp Rept 50-186/79-03 on 790514-17 No  
noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety  
Branch 79/06/08 2pp

--7907260281 IE Insp Repts 50-186/79-03 on 790514-17 No noncompliance  
noted Major areas inspected radiation protection & radwaste  
mgmt programs, previous items of noncompliance & commitments  
& facility changes & mods  
DUBRY, N E, FISHER, W L Region 3, Chicago, Fuel Facility &  
Materials Safety Branch 79/06/06 7pp

7907230434 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/22  
1p

7907240035 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/09  
1p

S Reportable occurrences, LERs & related correspondence

7907050322 Discusses failure of nuclear instrumentation Channel 4 On  
790531, while operating at 10 MW, Channel 4 indication failed  
downscale Caused by failure of picometer Corrected by  
installation of spare picometer module  
MCKIBBEN, J C, DRUGGER, R M Missouri, Univ of 79/06/29 2pp

## DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7907230544 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22, 1p



7907230753 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENDELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/06 1p

## DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

## G Inspection reports, IE Bulletins &amp; correspondence

7907100273 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18  
1p

7907020020 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22  
1p

7907230506 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22  
1p

## DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

## J Insurance &amp; indemnity information

7907170186 Forwards Amend 11 to Indemnity Agreement E-25  
DUSEK, A J Texas, Univ of 79/07/11 2pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907200220 IE Insp Rept 50-192/79-02 on 790409-11 No noncompliance noted Major areas inspected plant status, facility organization, logs & records, review & audit functions, requalification training & emergency plan  
JOHNSON, E H, CUPP, E A, MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/25 10pp

7907200213 Forwards IE Insp Rept 50-192/79-02 on 790409-11 No noncompliance noted  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/30 2pp

7907100262 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18  
1p

7907200033 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22  
1p

7907230512 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22  
1p

## DOCKET 50-193 RHODE ISLAND &amp; PROVIDENCE PLANTATIONS AEC

## G Inspection reports, IE Bulletins &amp; correspondence

7907100239 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/18 2pp

7907230348 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

## G Inspection reports, IE Bulletins &amp; correspondence

7907230398 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/22 1p

7907230456 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

## DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

## H General correspondence

7907100666 Ack receipt of 790328 ltr re license responsibilities for West Valley facility co-licensees Response is inappropriate because of pending proceeding Forwards settlement agreement w/Nuclear Engineering Co W/o encl  
HENDRIE, J M Commission 79/05/23 1p

## I Financial information

7907060386 Forwards financial statements as of 781231, including comparative data for 1977 Statements withheld (ref 10CFR2 790)  
CONTL, P L Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/14 2pp

7907300410 Responds to 790615 FOIA request re projected cost of perpetual care for facility & wastes & perpetual care of nuclear wastes at other facilities Forwards App A, listing documents encl  
FELTON, J M Division of Rules and Records 79/07/18 2pp

--7907300415 Forwards Amend 2 to NFB 630130 CP application submitted by NY State Atomic & Space Development Authority  
RUEBHAUSEN, D M Debevoise & Lieberman 65/01/12 1p

--7907300418 Amend 2 to NFB 630130 CP application submitted by NY State Atomic & Space Development Authority Updates change in name of authority, financial qualifications & contractual relationship w/NFB  
TOWNSEND, D New York, State of 65/01/12 13pp

--7907300424 Transcript of AEC 630514 statement before JCAE re NFB proposal for commercial chemical reprocessing svc & contractual agreement w/AEC  
\* Atomic Energy Commission 63/05/14 17pp

--7907300427 Responds to 630308 ltr re Price-Anderson indemnification agreement w/NFB Agreement does not terminate until all radioactive matl has been removed & transportation of matl from location has ended  
LOWENSTEIN, R Atomic Energy Commission, Directorate of Licensing (Pre-1975) 63/09/13 1p

--7907300434 Forwards complete list of documents given to GAO re proposed contract between AEC & NFB  
VINCIGUERRA, J V Atomic Energy Commission 63/08/08 7pp

--7907300440 Suggests changes for AE Lueddecke testimony before JCAE re NFB 620726 CP application Describes status of licensing actions  
CONNER, T B Atomic Energy Commission 63/05/07 2pp

--7907300444 Notifies that NFB 620726 CP application & NY State Atomic R&D Authority 630130 CP application should be issued Forwards suggested form & content of provisional CP  
MCCONNELL, E R, WOLMAN, A, CALLIHAN, D Atomic Safety and Licensing Board Panel 63/04/20 20pp

--7907300466 Forwards documents to be received as part of decisional record subj to ASLB approval W/TB Conner 630314 ltr to A Stambler, CA Lovejoy 630403 testimony & NY State Atomic R&D Authority 630408 Amend 1 to CP encl  
CONNER, T B Atomic Energy Commission 63/04/15 2pp

--7907300492 Notifies that evaluation of financial qualification of applicants cannot be completed w/o addl info Itemized cost estimates for major components, financial guarantee from Bechtel & latest annual rpt should be granted  
CONNER, T B Atomic Energy Commission 63/03/14 2pp

--7907300497 Testimony of CA Lovejoy re financial info in NFB & NY State Atomic R&D Authority CP application Financial qualifications have been established; CP should be granted.  
LOVEJOY, C A Atomic Energy Commission 63/04/13 7pp

--7907300500 Notifies of review of cost estimate & supporting data in NFB application for CP Project estimate of \$30.7 million is reasonable Addl funds will not be necessary, provided scope of project remains unchanged.  
RADLEY, H M Monroe Radley 63/04/03 2pp

## DOCKETED ITEMS

--7907300509 Amend 1 to NRS 630130 CP application submitted by NY State Atomic & Space Development Authority. State of NY is responsible for maint of site & wastes stored at site  
TOWNSEND, D New York, State of 63/04/08 4pp

--7907300513 Responds to 630213 ltr re assurance that State of NY will be responsible for maint of storage tanks & burial site  
Forwards NY State Ofc of Atomic Development & NY State Atomic R&D Authority 630321 agreement  
TOWNSEND, D New York, State of 63/04/08 2pp

--7907300517 Memo of agreement between NY State Ofc of Atomic Development & NY State Atomic R&D Authority re responsibility for maint of storage tanks & burial site  
TOWNSEND, D , FERGUSON, W New York, State of 63/03/21 10pp

--7907300521 Discusses required financial protection for proposed chemical processing plant. Submits related questions re level of financial protection, Price-Anderson indemnification agreement & yearly fee for indemnification agreement  
TOWNSEND, D New York, State of 63/03/08 4pp

--7907300525 Requests early decision re level of financial protection for fuel reprocessing plant. Info is necessary to proceed w/const schedule  
RUNION, C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 63/02/27 2pp

--7907300532 Notifies of testimony for CP & GL 630304 hearing for chemical processing plant. State of NY should furnish assurance of responsibility for proper maint of storage tanks & burial site per Atomic Energy Act of 1954  
LOWENSTEIN, R Atomic Energy Commission, Directorate of Licensing (Pre-1975) 63/02/13 2pp

--7907300536 Forwards NY State Atomic R&D Authority 630130 application for CP  
RUEBHAUSEN, D M New York, State of 63/01/30 1p

--7907300538 Application for CP re fuel processing plant, submitted by NY State Atomic R&D Authority. NRS may enter into contractual or lease arrangements w/State of NY  
TOWNSEND, D New York, State of 63/01/29 14pp

--7907300544 Discusses briefing by NRS, State of NY Atomic R&D Authority & Stoller Associates re costs of storage of high level radioactive waste at site  
NUSSBAUMER, D A , RUSNACK, W Atomic Energy Commission-Deputy Director for Fuels and Materials (Pre-1975) 62/09/05 4pp

#### P Operating license stage documents & correspondence

7907260012 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907110238 Notification of 790711 meeting w/NRS in Silver Spring, MD to discuss progress of efforts to process available technical info to provide basis for future decontamination & decommissioning of facility  
HAUGHNEY, C F Fuel Reprocess & Recycle Branch 79/05/24 2pp

7907130079 Summary of 790316 meeting w/Nuclear Fuel Svc, Inc & NY Energy R&D Authority in Silver Spring, MD re processing of data for decontamination & decommissioning of facility & BD-2 pan defect study status  
HAUGHNEY, C J Fuel Reprocess & Recycle Branch 79/05/24 20pp

7907250547 FOIA request for all 1953-66 NRC documents re projected costs of perpetual care for wastes & waste facilities  
SHEA, J F New York, State of 79/06/14 2pp

7907300536 Requests accession list of 1953-66 documents on file at NRC re projected costs of perpetual care for facility & wastes & care of nuclear wastes at other facilities.  
SHEA, J F New York, State of 79/06/18 2pp

7907230241 Ack receipt of 790118 ltr re 1972 memo concerning violations at facility as reported in anonymous ltr. Forwards NRC interofc correspondence & insp repts from 1972  
HENDRIE, J M Commission 79/07/06 74pp

--7907230246 Expresses concern re AEC 720912 memo describing proposed action concerning possible violations at facility. Requests details of any action taken  
RESNIKOFF, M Sierra Club 79/01/18 1p

--7907230250 Forwards anonymous ltr re possible safety violations at facility. Possible courses of action discussed  
HENDRIE, J M Atomic Energy Commission, Directorate of Licensing (Pre-1975) 72/09/12 1p

7907250556 Responds to 790614 FOIA request for all 1953-66 NRC records re projected cost of perpetual care for wastes & waste facilities. Forwards accession list  
FELTON, J M Division of Rules and Records 79/07/11 2pp

#### G Inspection reports, IE Bulletins & correspondence

7907100233 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/18 2pp

#### R Periodic operating reports & related correspondence

7907190718 Forwards quarterly environ monitoring rept for Jan-Mar 1979  
OLDHAM, W A Nuclear Fuel Services, Inc, West Valley Reprocessing Plant 79/04/27 13pp

--7907190727 Quarterly environ monitoring rept for Jan-Mar 1979  
Nuclear Fuel Services, Inc, West Valley Reprocessing Plant 79/04/27 12pp

7907050417 Forwards discharge monitoring rept for Apr 1979  
OLDHAM, W A Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/05/09 4pp

#### S Reportable occurrences, LERs & related correspondence

7907180778 Ack receipt of 790329 rept of safety evaluation of pan BD-2 defect at West Valley, NY. Rept is inadequate. Situation is bordering on edge of major catastrophe. Suggests matl be removed & solidified as soon as possible.  
RESNIKOFF, M Sierra Club 79/05/16 2pp

#### U Congressional/Executive Correspondence

7907090005 Responds to 790328 ltr to JM Hendrie re license duties of NRS at Sheffield site & NY State Energy R&D authority for West Valley plant. Nuclear Fuel Svc cannot transfer responsibilities w/o NRC approval  
DIRKS, W J Office of Nuclear Material Safety & Safeguards 79/05/29 2pp

--7907090007 Requests info re NRC responsibility to terminate NRS license to operate waste disposal site at Sheffield, IL  
VOLKER, D M New York, State of 79/03/28 2pp

#### DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907310377 Forwards Jul 1979 "Final Environ Impact Rept" re proposed San Onofre-to-Mission 230 kV transmission line. Encl available in Central Files  
STEGER, D B California, State of 79/07/27 1p

##### P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/BEP owner's group in Bethesda, MD re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625) 79/04/30 4pp

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TH1-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310359 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSB.  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/15 2pp

7907310287 Requests addl info re BEP Topic VI-1, "Organic Matls & Post-Accident Chemistry" Forwards list of info needed  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 3pp

7907110658 Forwards Category 2 & 3 regulatory positions to be addressed in SEP Reg Guide 1 114 encl  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp

7907240360 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods  
Documentation re applicability of Westinghouse results to analyses at facility will eventually be required by NRC  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250187 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation"  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

7907300030 Forwards Amend 41 to License DPR-13 & notice of issuance & availability  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 3pp

--7907300033 Amend 41 to License DPR-13, increasing annual discharge limits of sulfate for CY79 & CY80  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 6pp

--7907300035 Notice of issuance & availability of Amend 41 to License DPR-13  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

7907030465 Forwards rept "Water Transport Through 5,000-Ft Long Section Along Outfall Line," per NRC request re SEP Hydrology topics  
HAYNES, J O Southern California Edison Co 79/06/20 1p

--7907030469 "Water Transport Through 5,000-Ft Long Section Along Outfall Line," Nov 1972  
\* Southern California Edison Co 72/11/30 200pp

7907030474 Submits info re SEP Topics III-12, "Environ Qualification of Safety-Related Equipment," & Topic VI-3, "Containment Pressure & Heat Removal Capability," in response to 790504 request  
HAYNES, J O Southern California Edison Co 79/06/22 5pp

7907170212 Forwards comments on list of topics deleted from SEP re combustible gas control & underdrain sys & accumulator isolation valves  
HAYNES, J O Southern California Edison Co 79/07/03 2pp

7907100629 Confirms 790626 telcon re Westinghouse generic small break LOCA analyses Because results of specific analyses may not be applicable to facility, vendor will further investigate design  
BASKIN, K P Southern California Edison Co 79/07/06 1p

7907090261 Summarizes actions taken prior to NRC 790824 meeting on pipe breaks. Work undertaken to identify high energy lines inside containment & sys required for safe shutdown Effects of postulated breaks in high energy lines examined  
HAYNES, J O Southern California Edison Co 79/07/09 1p

7907190349 Forwards "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit 1," Suppl 1  
BASKIN, K P Southern California Edison Co 79/07/12 2pp

--7907190351 "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit 1," Suppl 1, prepared by TERA Corp  
\* Southern California Edison Co 79/07/31 167pp

#### Q Inspection reports, IE Bulletins & correspondence

7907050413 Responds to IE Bulletin 79-04, "Incorrect Weights for Velan Swing Check Valves" No Velan valves installed or scheduled to be installed at facility.  
HEAD, J T Southern California Edison Co 79/04/30 1p

7907050442 Forwards info requested in IE Bulletin 79-07 re seismic stress analysis of safety-related piping  
HEAD, J T South Carolina Electric & Gas Co 79/04/30 7pp

7907050390 Responds to IE Bulletin 79-03 No ASME SA-312 Type 304 stainless steel pipe spools in use or planned for use in safety-related sys at facility  
HEAD, J T Southern California Edison Co 79/05/08 1

7907240618 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790930 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907200372 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/31 1p

7907260528 Forwards IE Insp Rept 50-206/79-05 on 790319-23 No noncompliance noted  
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/06/01 2pp

--7907260534 IE Insp Rept 50-206/79-05 on 790319-23 No noncompliance noted Major areas inspected environ monitoring & protection programs, review of program procedures, repts & QA audits  
CURTIS, J R, BAIRD, J B Region 5, San Francisco, Office of the Director BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/06/01 4pp

7907270009 Forwards IE Insp Rept 50-206/79-07 on 790501-03 No noncompliance noted  
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/01 2pp

--7907270015 IE Insp Rept 50-206/79-07 on 790501-03 No noncompliance noted Major areas inspected inservice insp data review & evaluation, LER followup & independent insp effort  
CANTER, H L, HAIST, D Region 5, San Francisco, Office of the Director FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/01 8pp

7907190426 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Bolonoid Valves)" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p

7907060032 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07 1p

7907090427 Notification of 790613 meeting w/util in Bethesda, MD to discuss results of examinations & analyses of feedwater nozzle cracking at facility & to identify cause of failure, method of repair & testing program  
JORDAN, E L Division of Reactor Operations Inspections 79/06/12 2pp

7907120365 Discusses finding of unacceptable indications in welds in main feedwater piping sys Based on info presented at 790613 meeting, understands util will conduct baseline inservice weld examinations & submit interim rept  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/14 2pp

7907020450 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p

7907120012 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/21 1p

7907110205 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/22 1p

7907120624 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/23 1p

7907300382 Forwards supplemental response to IE Bulletins 79-06A & 06A, Revision 1 Provides info re transient & accident conditions, containment isolation & training instructions for automatic safety injection  
HEAD, J T Southern California Edison Co 79/06/25 12pp.

## DOCKETED ITEMS

7907060219 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907100531 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/28 1p

7907130212 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/02 1p

7907230781 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/06 1p

7907250220 Forwards IE Insp Rept 50-206/79-08 on 790529-0601 & notice of violation Rept withheld (ref 10CFR2 790)  
NORDEHARD, L R Region 5, San Francisco, Safeguards Branch  
79/07/06 2pp

7907180706 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/11 1p

7907310399 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/13 1p

7907260277 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/18 1p

#### R Periodic operating reports & related correspondence

7907100375 Forwards "Annual Operating Rept, Vol IV Biological, Sedimentological & Oceanographic Data Analyses 1978 "  
CURRIE, R S Southern California Edison Co 79/06/27 1p

--7907100387 "Annual Operating Rept, Vol IV Biological, Sedimentological & Oceanographic Data Analyses 1978 " Prepared by Brown & Caldwell, Lockhead Center for Marine Research & Marine Biological Consultants, Inc  
\* Southern California Edison Co 79-RD-54 79/12/31 500pp

7907100593 Forwards monthly operating rept for June 1979  
CURRAN, J H Southern California Edison Co 79/07/15 1p

--7907100598 Monthly operating rept for June 1979  
RODRIGUEZ, J P Southern California Edison Co 79/07/05 5pp

#### S Reportable occurrences, LERs & related correspondence

7907020287 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/05 1p

7907030195 Forwards PNO-79-67AS  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907030238 Forwards PNO-79-67AT, "Nuclear Incident at TMI "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/19 1p

7907030338 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907100602 Forwards JB Moore 790619 ltr re cracked welds on snubber  
Cause was attributed to water hammers or vibration in feedwater sys  
BASKIN, K P Southern California Edison Co 79/07/03 2pp

--7907100603 Discusses actions taken to alleviate cracked snubber  
problem Cracked welds were repaired w/reactor at cold shutdown & feedwater regulating valve has been readjusted.  
MOORE, J B Southern California Edison Co 79/06/19 3pp

7907130387 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/03 1p

#### DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

##### G Inspection reports, IE Bulletins & correspondence

7907230394 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/22 1p

7907230451 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

#### DOCKET 50-213 HADDAM NECK PLANT

##### F Security, medical, emergency & fire protection plans

7907180543 Submits formal notification re change to commitment made in HQ Council 790424 ltr re amended security plan Tour restrictions will be removed in some areas of plant, per 790509 telcon among R Keimig, W Madden & RP Traggie  
COUNSIL, W G Connecticut Yankee Atomic Power Co 79/07/09 2pp

7907230578 Documents info provided verbally re delay in schedule of submittals for fire protection mods delay until 790731 due to TMI event & IE Bulletin requirements  
COUNSIL, W G Northeast Utilities 79/07/19 2pp

##### P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/BEP owner's group in Bethesda, MD re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625)  
79/04/30 4pp

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310580 Forwards NRC 790513 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSS  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 2pp

7907260042 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 2pp

7907310278 Requests addl info re SEP Topic VI-1, "Organic Matls & Post-Accident Chemistry " Forwards list of info needed  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 3pp

7907110723 Forwards "SEP Review of Safe Shutdown Sys for Haddam Neck Plant," draft evaluation of Topics V-10 B,V-11 B,VII-3 & X Requests response within 30 days.  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/07 2pp

--7907110729 "SEP Review of Safe Shutdown Sys for Haddam Neck Plant," draft evaluation of Topics V-10 B,V-11 B,VII-3 & X  
\* Operating Reactors Branch 2 (Pre 790625) 79/06/07 94pp

7907110676 Forwards Category 2 & 3 regulatory positions to be addressed in SEP Reg Guide 1 114 encl  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp.

7907260544 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods  
Documentation re applicability of Westinghouse results to analyses at facility will eventually be required by NRC  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp.

7907260505 Summary of 790516 meeting w/utill in Bethesda, MD re geology & seismology issues related to SEP review of tectonic province & seismic design  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625)  
79/06/11 6pp

7907250179 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation"  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

790703037B Notifies that review of draft evaluation SEP Topic IV-1 A for factual correctness is complete NRC assessment substantively correct  
COUNSIL, W G Connecticut Yankee Atomic Power Co 79/06/25 1p

7907300567 Summary of 790522 meeting w/util in Silver Spring, MD re NRC comments on submittal of proposed Tech Specs to implement 10CFR50 App I requirements  
WAKBACH, T V Operating Reactors Branch 2 79/07/05 4pp

7907260737 Requests extension until 790813 to respond to NRC 790629 request for PWR licensee capabilities to anticipate & respond to unusual incidents  
COUNSIL, W G Northeast Utilities 79/07/16 1p

#### Q Inspection reports, IE Bulletins & correspondence

7907090444 Discusses meeting held in Philadelphia, PA on 790316 Meeting was beneficial in providing util w/understanding of NRC concern w/mgt control of radiation protection programs  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/16 6pp

--7907090449 Summary of 790316 meeting w/util in Philadelphia, PA re Region 1 concerns w/mgt control in area of radiation protection program  
CROCKIER, H W Region 1, Philadelphia, Office of the Director 79/04/16 4pp

790706046B Responds to IE Bulletin 79-09 OE Type AK-2 circuit breakers are not used  
COUNSIL, W G Connecticut Yankee Atomic Power Co 79/05/17 1p

7907060377 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907240599 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06B, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907050160 Responds to IE Bulletin 78-12B re atypical weld mail in reactor pressure vessel C-E is performing requested search & will submit rept to NRC by 790608  
COUNSIL, W G Northeast Nuclear Energy Co (Northeast Utilities) 79/05/24 1p

7907030023 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200093 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/05/31 1p

7907190045 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060084 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/06/07 1p

7907110363 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230630 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/06/21 1p.

7907240140 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p

7907120487 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907060180 Forwards IE Circular 79-10, "Pipefittings Mfg From Unacceptable Matl" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100495 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907060167 Forwards "Inservice Testing Program for Pumps & Valves & Pressure Test Program for 790901-810501"  
COUNSIL, W G Connecticut Yankee Atomic Power Co 79/06/29 2pp

--7907060171 "Inservice Testing Program for Pumps & Valves & Pressure Test Program for 790901-810501"  
\* Connecticut Yankee Atomic Power Co 79/06/30 64pp

7907310006 Ack receipt of 790524 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/79-08  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/29 1p

--790731000B Responds to NRC 790509 ltr re violations noted in IE Insp Rept 50-213/79-08 Corrective actions new alarm mercoild was installed in refueling water storage tank  
COUNSIL, W G Connecticut Yankee Atomic Power Co 79/05/24 2pp

--7907310011 Forwards IE Insp Rept 50-213/79-08 on 790320-23 & notice of violation  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/09 2pp

--7907310014 Notice of violation from insp on 790320-23  
\* Region 1, Philadelphia, Office of the Director 79/05/08 1p

--7907310017 IE Insp Rept 50-213/79-08 on 790320-23 Noncompliance noted failure to prepare temporary change in procedure for surveillance of refueling water storage tank  
BAUNACK, W H, KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/08 9pp

790718075B Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/07/02 1p

7907250496 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p.

790730046B Draft supplemental responses to IE Bulletin 79-06A, Revision 1 Submits info re emergency procedures, inadvertent transference of radioactive matl outside containment, testing of safety-related sys & initiation of containment isolation.  
\* Connecticut Yankee Atomic Power Co 79/07/06 5pp

7907270326 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

790723052B Responds to IE Bulletin 79-13, 14 & 02 re feedwater sys piping Submits schedule for insp of feedwater piping sys, rept on operating adequacy, emergency procedures & method for leak detection  
COUNSIL, W G Connecticut Yankee Atomic Power Co 79/07/13 3pp.

7907310489 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p.

#### R Periodic operating reports & related correspondence

7907180525 Forwards monthly operating rept for June 1979  
GRAVES, R H Connecticut Yankee Atomic Power Co. 79/07/11 1p

## DOCKETED ITEMS

--7907180527 Monthly operating rept for June 1979  
 \* Connecticut Yankee Atomic Power Co 79/07/13 8pp

S Reportable occurrences, LERs & related correspondence

7907170017 Submits preliminary notification of RO 79-07/1P  
 During walkdown of Category I piping sys, one pipe support  
 on svc water piping was found not to be type specified on  
 blueprint  
 GRAVES, R H Connecticut Yankee Atomic Power Co 79/07/10 1p

7907260710 Forwards LER 79-007/01T-0  
 GRAVES, R H Connecticut Yankee Atomic Power Co 79/07/23 3pp

--7907260717 LER 79-007/01T-0 on 790707 one Category I pipe support on  
 svc water piping WS-121-3 found not to be seismic Type  
 WS-RES-1 specified on drawing Caused by human error Existing  
 pipe changed immediately  
 THOMAS, R H Connecticut Yankee Atomic Power Co 79/07/23 1p

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

7907020180 Discusses commitment to provide alternate means of supplying  
 water to yard loop Decision made to provide 300,000 gal tank  
 & pump to provide fire protection sys water demand  
 FINFROCK, I R Jersey Central Power & Light Co 79/06/26 1p

G Adjudicatory correspondence

7907130092 Memo & order that ETB become part of provisional DL Requests  
 NRC to submit evaluation of recent coolant flow reduction  
 incident  
 LAZO, R M Atomic Safety and Licensing Board Panel 79/05/31 2pp

7907180113 Responds to ASLB 790531 memo & order Forwards license amend  
 & safety evaluation re 790502 loss of coolant inventory Core  
 is undamaged & new Tech Specs are imposed Plant can resume  
 operation w/o undue risk  
 WOODHEAD, C P Branch 3 79/06/08 App

--7907180127 Summary of 790530 meeting in Washington, DC to discuss  
 status of 790502 event Plant may resume operation  
 CHILK, S J Office of the Secretary of the Commission 79/06/04  
 1p

--7907180143 Notifies of review completion of 790502 event re loss of  
 coolant inventory Forwards safety evaluation Proposed  
 changes to Tech Specs must be implemented prior to restart  
 Plant may resume operation Certificate of Svc encl  
 STELLO, V Division of Operating Reactors 79/05/30 3pp

--7907180160 Informs that restart core is undamaged Util has made  
 necessary changes to Tech Specs Operation of plant may be  
 resumed w/o undue risk to health & safety of public  
 \* Office of Nuclear Reactor Regulation 79/05/30 44pp

J Insurance & indemnity information

7907250315 Advises that notice of claim by QB Huey has been filed,  
 alleging mental stress incurred by family due to danger of  
 radioactive contamination from facility  
 ALTON, C G American Nuclear Insurers, 79/07/18 1p

P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/SEP owner's group in Bethesda, MD  
 re technical details of site-specific spectra project  
 LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625) 79/04/30 App

7907060496 Forwards request for addl info re test program for startup &  
 power ascension & appropriateness of annulus instruments  
 for describing water level over core.  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/15  
 3pp

790710728 Summary of 790503-04 site trip re 790502 triple low water  
 level.  
 JOWICKI, B J Operating Reactors Branch 2 (Pre 790625) 79/05/22  
 3pp

7907260052 Discusses plans to install communication links between NRC &  
 nuclear facilities for emergency use Direct lines from each  
 facility to NRC headquarters & regional ofc will communicate  
 operational & environ info  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/05/22 2pp

7907060242 Forwards safety evaluation presenting review & conclusions  
 re 790502 transient condition of core & corrective action  
 taken to prevent recurrence  
 STELLO, V Division of Operating Reactors 79/05/30 3pp

--7907060243 "Restart SER"  
 \* Division of Operating Reactors 79/05/30 42pp

7907100009 Forwards Amend 35 to License DPR-16, safety evaluation &  
 notice of issuance & availability  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/30  
 2pp

--7907100012 Amend 35 to License DPR-16, incorporating Tech Specs  
 contained in App A, as revised  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/30  
 4pp

--7907100015 Safety evaluation supporting Amend 35 to License DPR-16  
 \* Division of Operating Reactors 79/05/30 3pp

--7907100017 Notice of issuance & availability of Amend 35 to License  
 DPR-16  
 \* Division of Operating Reactors 79/05/30 3pp

7907110480 Notice of issuance of Amend 35 to License DPR-16, which  
 revises Tech Specs to allow operation w/one recirculation  
 loop out of svc, using max planar linear heat generation rate  
 limits  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/30  
 3pp

--7907110553 Safety evaluation supporting Amend 35 to License DPR-16  
 \* Office of Nuclear Reactor Regulation 79/05/30 3pp

7907130134 Forwards Amend 36 to License DPR-16, safety evaluation &  
 notice of issuance & availability  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/30  
 2pp

--7907130140 Amend 36 to License DPR-16 revising Tech Specs re fuel  
 cladding safety limits  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/30  
 7pp

--7907130146 Safety evaluation supporting Amend 36 to License DPR-16,  
 \* Office of Nuclear Reactor Regulation 79/05/30 3pp

--7907130184 Notice of issuance & availability of Amend 36 to License  
 DPR-16  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/30  
 3pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related  
 re-evaluations of operating plants  
 KANE, W F Standardization Branch 79/05/31 4pp

7907060424 Forwards Amend 37 to License DPR-16 & notice of issuance &  
 availability  
 REGAN, W H Environmental Projects Branch 2 79/06/06 2pp

--7907060426 Amend 37 to License DPR-16, establishing App B Tech Specs  
 \* Assistant Director for Environmental Projects 79/06/06  
 2pp

--7907060430 Notice of issuance & availability of Amend 37 to License  
 DPR-16,  
 REGAN, W H Environmental Projects Branch 2 79/06/06 2pp

--7907060434 Tech Specs for App B to License DPR-16  
 \* Jersey Central Power & Light Co 78/11/30 102pp.

7907310264 Requests addl info re SEP Topic VI-1, "Organic Metls &  
 Post-Accident Chemistry" Forwards list of info needed  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06  
 3pp.

7907110666 Forwards Category 2 & 3 regulatory positions to be addressed  
 in SEP Reg Guide 1 114 encl  
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11  
 7pp

7907110462 Confirms NRC 790717-1B site visit to observe site-specific features re seismic design Supporting documentation encl  
ZIEGMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/13  
200pp

7907250183 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation"  
ZIEGMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18  
2pp

7907110727 "Analysis of Populations of Boring & Fouling Organisms in Vicinity of Oyster Creek Nuclear Generating Station," quarterly rept, Sept-Nov 1978  
HOAGLAND, K E Lehigh Univ , NUREG/CR-0812 79/06/30 76pp

#### G Inspection reports, IE Bulletins & correspondence

7907030223 Responds to IE Bulletin 79-09 GE Type AK-2A-25 & AK-2A-30 circuit breakers are used in supplying power to equipment in safety-related sys  
FINFROCK, I R Jersey Central Power & Light Co 79/05/17, 4pp

7907060382 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907030030 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200103 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities" Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190052 Forwards suppl IE Bulletin 79-01A, "Environment Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060095 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907110348 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230649 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240150 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907120496 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907060187 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26, 1p.

7907100498 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180770 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director.  
79/07/02 1p

7907250303 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

7907270333 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310499 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R Periodic operating reports & related correspondence

7907100399 Forwards sixteenth quarterly progress rept, "Woodborer Study Associated w/Oyster Creek Generating Station," for 790209-0504  
FINFROCK, I R Jersey Central Power & Light Co 79/07/02 1p

--7907100402 "Woodborer Study Associated w/Oyster Creek Generating Station," sixteenth quarterly progress rept for 790209-0504, prepared by Battelle Columbus Labs.  
\* Jersey Central Power & Light Co 79/06/15 20pp

7907250350 Forwards monthly operating rept for June 1979  
ROBS, D A Jersey Central Power & Light Co 79/07/13 1p

--7907250354 Monthly operating rept for June 1979  
MCCLAIN, C M Jersey Central Power & Light Co 79/07/11 8pp.

#### S Reportable occurrences, LERs & related correspondence

7907030379 Forwards LER 79-020/01T-0  
ROBS, D A Jersey Central Power & Light Co 79/06/27 1p

--7907030381 LER 79-020/01T-0 on 790613 secondary containment integrity breached when reactor bldg airlock doors were opened simultaneously. Caused by failure of procedure to state correct method for securing airlock doors. Procedure revised  
ROBS, D A Jersey Central Power & Light Co 79/06/27 3pp

7907260587 Forwards LER 79-021/03L-0  
ROBS, D A Jersey Central Power & Light Co 79/07/20 1p

--7907260593 LER 79-021/03L-0 on 790620 during surveillance testing activities, instrument IP15A was found to trip at valve higher than allowed by Tech Specs. Instrument found to be within expected accuracy attainable  
ROBS, D A Jersey Central Power & Light Co 79/07/20 3pp

7907270170 Forwards RD 58-219/79/23-1P  
CARROLL, J T Jersey Central Power & Light Co 79/07/20 1p

--7907270202 RD 219/79/23-1P on 790719 recirculating pump A removed from svc for maint. in violation of Tech Specs which require min of four pumps in operation. Pump returned to svc & reactor restarted  
GUINTEZ, T E Jersey Central Power & Light Co 79/07/20 2pp

#### T Hearing transcripts on non-antitrust matters

7907090019 Transcript of 790530 meeting in Washington, DC re status of 790502 event at facility Pp 1-32 Documentation encl  
HENORIE, J M, OILINSKY, V, KENNEDY, R T Commission 79/05/30 48pp

7907090024 Highlights 790502 event. During surveillance tests, false reactor high pressure scram & subsequent events caused shutdown of all three feedwater pumps. Water level decreased to low-low-low level alarm.  
EISENHUT, D Division of Operating Reactors. 79/05/30 10pp

#### DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

##### J Insurance & indemnity information

7907030283 Forwards Endorsements 54, 55 & 56 to MAELU Policy MF-46  
RUSHMORE, J W Niagara Mohawk Power Corp 79/06/27 4pp

7907030304 Forwards Endorsements 64, 65 & 66 to NELIA Policy NF-161  
RUSHMORE, J W Niagara Mohawk Power Corp 79/06/27, 4pp.

## DOCKETED ITEMS

## P Operating license stage documents &amp; correspondence

7907260041 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional o/c will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 2pp

7907180644 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp.

7907240374 Forwards Amend 32 to License DPR-63, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/06/11 2pp

--7907240378 Amend 32 to License DPR-63, extending safety limit on min reactor vessel water level, limiting safety sys setting on low-low-low water level & adding requirement re open recirculation loops  
IPPOLITO, T A Operating Reactors Branch 4 (Pre 790625)  
79/06/11 8pp

--7907240380 Safety evaluation supporting Amend 32 to License DPR-63  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/06/11 3pp

--7907240382 Notice of issuance & availability of Amend 32 to License DPR-63  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625).  
79/06/11 2pp

7907200438 Forwards errata to facility "Aquatic Ecology Studies Data Rept 1978"  
SCHNEIDER, R R Niagara Mohawk Power Corp 79/07/11 10pp

7907230077 Forwards application for amend to License DPR-63 allowing rated power operation w/one recirculation loop isolated  
THOMAS, E D LeBoeuf, Lamb, Leiby & MacRae 79/07/19 2pp

--7907230151 Application for amend to License DPR-63 allowing rated power operated w/one recirculation loop isolated Certificate of Svc & supporting documentation encl  
DISE, D P Niagara Mohawk Power Corp 79/07/18 7pp

7907260654 Forwards info on THRBAP & ADLPIPE computer codes re verification of modeling techniques for seismic calculations on unit safety-related piping sys  
DISE, D P Niagara Mohawk Power Corp 79/07/24 500pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907230471 Forwards IE Insp Rept 50-220/79-09 on 790326-29 No noncompliance noted  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/02 2pp

--7907230479 IE Insp Rept 50-220/79-09 on 790326-29 No noncompliance noted Major areas inspected: refueling operations, IE Circular & Bulletin review & licensee actions re previous insp findings  
ARCHITZEL, R, MCCABE, E C Region 1, Philadelphia, Office of the Director 79/05/01 7pp

7907060420 Responds to IE Bulletin 79-09 OE Type AK-2 circuit breakers are used in safety-related sys using shunt trip devices  
Preventive maint program has been initiated  
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/07 1p.

7907270379 Forwards IE Insp Rept 50-220/79-08 on 790308-09, 20-23 & 27-30.  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/18 2pp

--7907270381 IE Insp Rept 50-220/79-08 on 790308-09, 20-23 & 27-30 No noncompliance noted Major areas inspected: torus mod activities, emergency condenser nozzle safe-end replacement, actions relative to LER 78-07 & inservice insps  
TRIPP, L E, MCOREARTY, R A, JERNIGAN, E P Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/16 12pp.

7907130129 Forwards info on requalification training program in response to IE Bulletin 79-10 re apparent operator failures at TMI  
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/21 3pp

7907060395 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907070094 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
LEONARD, J D Power Authority State of New York 79/05/22 3pp

7907030044 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200117 Forwards IE Bulletin 79-12, "Short Period Scrams at DWR Facilities" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907130178 Notification that civil penalties will be imposed, due to insp finding re weakness in implementation of physical security program Notice of proposed imposition of civil penalties encl App A withheld (ref 10CFR2 790)  
DAVIS, J G Office of Inspection & Enforcement 79/06/05 2pp

--7907130182 "Notice of Proposed Imposition of Civil Penalties"  
\* Office of Inspection & Enforcement 79/06/05 2pp

7907190084 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060109 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907300148 Responds to IE Bulletin 79-01 re environ qualification of electrical components Required electrical equipment in containment is qualified for LOCA environs Supporting documentation encl  
SCHNEIDER, R R Niagara Mohawk Power Corp 79/06/11 12pp

--7907300160 Rept re limitorque valve operator test for meeting general requirements of electrical valve actuator in nuclear reactor containment environ Prepared by Philadelphia Gear Corp  
\* Franklin Institute 69/01/02 8pp

--7907300166 Rept of test on Philadelphia Gear Corp SMBO-15 limitorque Prepared by Lockheed Electronics Co  
\* Franklin Institute 68/07/31 4pp.

--7907300175 Rept re limitorque valve operator test under simulated reactor containment post-accident steam & chemical Prepared for Philadelphia Gear Corp  
\* Niagara Mohawk Power Corp 68/11/30 41pp

--7907300181 Addendum I to test rept of limitorque valve actuator in nuclear reactor containment environ, prepared by Philadelphia Gear Corp Forwarding ltr encl  
\* Niagara Mohawk Power Corp 69/04/29 5pp

7907270384 Forwards IE Insp Rept 50-220/79-05 on 790207-10  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/13 2pp

--7907270386 IE Insp Rept 50-220/79-05 on 790207-10 Noncompliance noted access requirements, physical barriers & response records  
DEVLIN, J W, BAILEY, R J, THONUS, L Region 1, Philadelphia, Safeguards Branch 79/06/05 1p.

7907180401 Forwards safety evaluation of piping reanalysis, per IE Bulletin 79-07 Requirements of bulletin have been fulfilled Power operation may resume  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/06/19 2pp.

--7907180407 Safety evaluation of piping reanalysis per IE Bulletin 79-07 IE bulletin requirements adequately satisfied  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/19 3pp

7907100475 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p.



7907230689 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/21 1p

7907230029 Ack receipt of 790608 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/79-07  
 SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/22 1p

--7907230038 Responds to NRC 790608 ltr re violations noted in IE Insp Rept 50-220/79-07 Corrective actions radiation work permit requirement reviewed re access control  
 SCHNEIDER, R R Niagara Mohawk Power Corp 79/06/08 3pp

--7907230044 Forwards IE Insp Rept 50-220/79-07 on 790313-16 & notice of violation  
 SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/16 2pp

--7907230051 Notice of violation from insp on 790313-16  
 \* Region 1, Philadelphia, Office of the Director 79/05/11 3pp

--7907230057 IE Insp Rept 50-220/79-07 on 790313-16 Noncompliance noted failure to adhere to radiation protection procedures specified in Tech Specs  
 THOMAS, L H, NIMITZ, R L Region 1, Philadelphia, Office of the Director  
 CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/11 14pp

7907240182 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/23 1p

7907120510 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/25 1p

7907040198 Forwards IE Circular 79-10, "Pipe Fittings Mfg from Unacceptable Matl " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/26 1p

7907180782 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/02 1p

7907250910 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/06 1p

7907270347 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/11 1p

7907310911 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/16 1p

#### R Periodic operating reports & related correspondence

7907130444 Forwards monthly operating rept for June 1979  
 SCHNEIDER, R R Niagara Mohawk Power Corp 79/07/10 1p

--7907130448 Monthly operating rept for June 1979  
 PERKINS, T N Niagara Mohawk Power Corp 79/07/10 5pp

7907170225 Forwards monthly operating rept for June 1979  
 SCHNEIDER, R R Niagara Mohawk Power Corp 79/07/10 1p

#### B Reportable occurrences, LERs & related correspondence

7907050338 Forwards LER 79-015/03L-0  
 SCHNEIDER, R R Niagara Mohawk Power Corp 79/06/28 1p

--7907050354 LER 79-015/03L-0 on 790610, during refueling outage, time delay device in reactor protection sys would not operate in appropriate manner Caused by bad clutch coil Coil replaced & retested.  
 DUDA, E Niagara Mohawk Power Corp 79/06/28 1p.

7907130381 Forwards LER 79-016/03L-0 & LER 79-017/03L-0  
 SCHNEIDER, R R Niagara Mohawk Power Corp 79/07/09 1p

--7907130382 LER 79-016/03L-0 on 790626 failure to review temporary electrical maint procedure within seven days Review made & approvals received  
 DUDA, E Niagara Mohawk Power Corp 79/07/09 1p

--7907130385 LER 79-017/03L-0 on 790612 containment spray water intertie valves leaked causing failure of integrated leak rate test  
 Valves removed, cleaned & re-installed  
 DUDA, E Niagara Mohawk Power Corp 79/07/09 1p

#### DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

##### P Operating license stage documents & correspondence

7907100020 Forwards Amend 3 to License R-125 & safety evaluation  
 REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/29 2pp

--7907100024 Amend 3 to License R-125, changing frequency of conducting integrated leak rate tests of containment bldg  
 REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/29 4pp

--7907100027 Safety evaluation supporting Amend 3 to License R-125  
 \* Office of Nuclear Reactor Regulation 79/05/29 4pp

##### G Inspection reports, IE Bulletins & correspondence

7907250469 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/06 1p

#### DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

##### H General correspondence

7907090322 Notifies that S Kaplan will continue as reactor administrator  
 LIM, T H California, Univ of, Berkeley 79/06/27 1p

7907160370 Notifies that VE Schrock will be reactor administrator of Berkeley research reactor, as of 790710  
 LIM, T H California, Univ of, Berkeley 79/07/09 1p

##### G Inspection reports, IE Bulletins & correspondence

7907190478 Forwards IE Insp Rept 50-224/79-01 on 790424-25 No noncompliance noted  
 CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/17 2pp

--7907190484 IE Insp Rept 50-224/79-01 on 790424-25 No noncompliance noted Major areas inspected facility organization, logs & records, requalification training, procedures, surveillance, experiments, review & audit  
 MILLER, L F Region 5, San Francisco, Office of the Director  
 79/05/16 4pp

7907120094 Forwards IE Insp Rept 50-224/79-02 on 790521 No noncompliance noted. Encl withheld (ref 10CFR2 790)  
 NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 79/06/06 2pp

7907230584 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
 ENGELKEN, R H Region 5, San Francisco, Office of the Director  
 79/06/22 1p

7907230764 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
 ENGELKEN, R H Region 5, San Francisco, Office of the Director  
 79/07/06 1p

#### DOCKET 50-225 RPI CRITICAL EXPERIMENT

##### P Operating license stage documents & correspondence

7907050172 Notifies that License CX-22 will expire 790630 Renewal requires submission of application demonstrating safety of reactor operation over period of renewal W/list of items to be reviewed prior to renewal  
 REID, R W Operating Reactors Branch 4 (Pre 790625), 79/05/15 9pp

## DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

7907260257 Forwards IE Info Notice 79-1B, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

DOCKET 50-22B AEROTEST RADIOGRAPHY & RESEARCH REACTORQ Inspection reports, IE Bulletins & correspondence

7907230527 Forwards IE Info Notice 79-1d, "Nuclear Incident at TMI " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22 1p

7907230745 Forwards IE Info Notice 79-1B, "Skylab Reentry " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/06 1p

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2F Security, medical, emergency & fire protection plans

7907190155 Forwards draft suppl to fire protection safety evaluation  
LAINAS, G Plant Systems Branch 79/06/12 2pp

--7907190167 Draft suppl to fire protection safety evaluation  
\* Office of Nuclear Reactor Regulation 79/06/12 11pp

7907200381 Submits Classes I & III fees for safeguards contingency plans  
REED, C Commonwealth Edison Co 79/07/12 2pp

7907300330 Forwards Revision 2, interim physical security plan Plan withheld (ref 10CFR2 790)  
REED, C Commonwealth Edison Co 79/07/23 1p

G Adjudicatory correspondence

7907050423 Forwards NRDC annual rept & matls & Citizens for Better Environ matls supporting applicant position re involvement of both organizations in broad environ litigation Matl provided in response to 790419 memo & order Svc list encl  
STEPHENS, P Isham, Lincoln & Beale 79/05/03 51pp

7907110486 NRDC opposition to NRC motion for reconsideration of ASLB 790419 memo & order following special prehearing conference Certificate of Svc encl.  
ROISHAN, A Z Natural Resources Defense Council 79/05/10 2pp

7907110499 State of IL opposition to NRC 790504 motion & Comm Ed 790507 motion for reconsideration &/or clarification & referral of ASLB 790419 memo & order admitting Contentions 6 & 11  
SEKULER, S N Illinois, State of. 79/05/17 6pp

--7907110572 Forwards new info re analysis of sabotage & possible consequences, potentially relevant to McGuire proceedings W/o encl Certificate of Svc encl  
CARTER, T F Division of Safeguards 79/01/22. 3pp

7907200185 NRDC response in opposition to Comm Ed motion for reconsideration or, in alternative, for clarification or referral re adequacy of safeguards for spent fuel shipments Motion is unwarranted & inconsistent w/10CFR73  
ROISHAN, A Z Natural Resources Defense Council. 79/05/22 4pp

--7907200203 NRDC staff scientist statement re safeguards for spent fuel shipments Proposed rule to protect spent fuel shipments against sabotage, presented in 790429 memo to Commission is most likely Adequate Certificate of Svc encl  
COCHRAN, T B Natural Resources Defense Council. 79/05/18 3pp.

7907110720 Opposes several proposed actions re storage of Dresden spent fuel rods at Cordova plant & const of another plant in Erie-Springhill area. Opposes nuclear energy in principle because of alleged inadequate storage methods for radwaste  
HOMAN, P Affiliation Unknown 79/05/31 2pp

7907190539 Comment on proposed transfer of 509 spent fuel rods to Quad Cities nuclear facility in Cordova, IL. Opposes transfer on grounds that radioactive waste cannot be disposed of safely  
GUINN, C R Affiliation Unknown 79/06/01 2pp

H General correspondence

7907160298 Four ltrs opposing transport of 509 radioactive spent fuel rods between facilities  
WIRTH, B, RUNYON, J, GUILTY, J Affiliation Unknown 79/05/10 App

P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/SEP owner's group in Bethesda, MD re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625)  
79/04/30 4pp

7907260089 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional OFC will communicate operational & environ info  
KEPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907310475 Discusses resolution of deterioration problem of BUNA-N components in ASCO solenoid valves Response to IE Bulletin 7B-14 has been revised to assure replacement of matl in necessary components by 801231  
REED, C Commonwealth Edison Co 79/05/31 3pp

7907250145 Forwards draft evaluation of SEP Topic VI-1, "Organic Matls & Post-Accident Chemistry  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 3pp

7907110631 Forwards Category 2 & 3 regulatory positions to be addressed in SEP Reg Guide 1 114 encl  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp

7907050284 Forwards supplemental info to Special Rept 43 re spent fuel storage pool mods  
JANECEK, R F Commonwealth Edison Co 79/06/12 3pp

7907250176 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of SEP Topic VIII-3 B, "DC Power Bys Bus Voltage Monitoring & Annunciation "  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/10 2pp

7907090305 Submits addl info to 790102 ltr re current commitments to containment purging during normal plant operation Schedule for responding to issues re normal operation purging will be submitted by 790801  
REED, C Commonwealth Edison Co 79/07/02 3pp

7907260031 Summary of 790628 meeting w/util in Bethesda, MD re purging & venting limits & performance of purge & vent valves during postulated LOCA  
HANNON, J N Operating Reactors Branch 3 (Pre 790625). 79/07/02. 6pp

7907130322 Revises 790702 ltr re purging during normal operation. No purging at power at Zion will be permitted until purge valves have been analyzed & determined to be capable of closure under DBA  
REED, C Commonwealth Edison Co 79/07/05. 1p

7907120566 Provides info in response to DO Eisenhower 790621 ltr Analysis of reactor internal stress analysis from OE will be available by 790801 Turbine bldg design computation will be forwarded JA Blume evaluation of Reactor-Turbine Bldg encl  
JANECEK, R F Commonwealth Edison Co 79/07/06. 23pp.

--7907120570 "Rept B Stress Analysis Support Skirt, Revision 5" Parts A, B-12 & B-19, prepared by Nuclear Components Engineering, B&W  
\* Commonwealth Edison Co 70/10/13 49pp

7907190563 Forwards description & drawings from OEI-92807 for plant type control rod drive hydraulic control units, ac motor control ctr spec & OE drawing for motor control ctr  
JANECEK, R F Commonwealth Edison Co 79/07/16 2pp.

--7907190570 Instruction manual for OE hydraulic control units, parts 237891822-05. Thirteen oversized drawings available in Central Files  
\* Commonwealth Edison Co. 79/07/16. 101pp

7907230295 Forwards errata & addenda sheets for approved supplemental licensing submittal NEDO-24160. Changes addl stability data for extrapolated rod block line Revision anticipates license amend re expanded power flow  
JANECEK, R F Commonwealth Edison Co 79/07/16. 6pp

7907240345 Requests that GE rept NEDE-25090-P, "Analytical Model for T-Quencher Jet Loads on Submerged Structures," submitted 790531, be included in dockets  
JANECEK, R F Commonwealth Edison Co 79/07/18 1p

Q Inspection reports, IE Bulletins & correspondence

7907190042 Forwards IE Insp Repts 50-010/79-05, 50-237/79-06 & 50-249/79-05 & on 790319-22 & 28 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 2pp

--7907190073 IE Insp Repts 50-010/79-05, 50-237/79-06 & 50-249/79-05 on 790319-22 & 28 No noncompliance noted Major areas inspected radiation protection program & licensee action on previously identified insp items  
FISHER, W L, MILLER, D E, HIATT, J W Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/23 6pp

7907190492 Forwards IE Insp Repts 50-010/79-08, 50-237/79-12 & 50-249/79-10 on 790402-30 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/14 2pp

--7907190497 Notice of violation from insp on 790402-30  
\* Region 3, Chicago, Office of the Director 79/05/10 1p

--7907190507 IE Insp Repts 50-010/79-08, 50-237/79-12 & 50-249/79-10 on 790402-30 Noncompliance noted exceeding limiting condition for operation  
BARKER, J L, SPESSARD, R L Region 3, Chicago, Office of the Director 79/05/10 12pp

7907060251 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers in use or planned for use in any safety-related sys  
REED, C Commonwealth Edison Co 79/05/17, 2pp

7907180101 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
REED, C Commonwealth Edison Co 79/05/25 7pp

7907200295 Forwards IE Bulletin 79-12, "Short Period Scrams at DWR Facilities," Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907240134 Forwards IE Insp Rept 50-237/79-08 on 790320-22, 0409-10 & 0503 No noncompliance noted  
FIORILLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/31 2pp

--7907240138 IE Insp Rept 50-237/79-08 on 790320-22, 0409-10 & 0503 No noncompliance noted Major areas inspected inservice insp programs, procedures, work activities, data review & evaluation  
KEY, W J, DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/29 6pp

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves)," Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06, 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures," No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907260223 Forwards IE Insp Repts 50-010/79-11, 50-237/79-14 & 50-249/79-12 on 790522 No noncompliance noted.  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/07, 2pp

--7907260240 IE Insp Repts 50-010/79-11, 50-237/79-14 & 50-249/79-12 on 790522 No noncompliance noted Major areas inspected, response of licensee organization during scheduled drill involving simulated contaminated injuries  
GRANT, W B, GREER, R J, EBSIO, T H Region 3, Chicago, Office of the Director 79/06/05, 4pp..

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures," was forwarded to listed utils  
PAPPAS, H. Region 3, Chicago, Office of the Director. 79/06/08 2pp

7907300486 IE Insp Repts 50-237/79-13 & 50-249/79-11 on 790502-18. Noncompliance noted inadequate operating procedures for emergency safety features.  
WALKER, R D, BARKER, J L, SPESSARD, R L Region 3, Chicago, Office of the Director. 79/06/12 15pp

7907260810 Forwards IE Insp Repts 50-237/79-13 & 50-249/79-11 on 790502-18 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13 2pp.

--7907260815 Notice of violation from insp on 790502-18  
\* Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13 1p

--7907260822 IE Insp Repts 50-237/79-13 & 50-249/79-11 on 790502-18 Noncompliance noted inadequate operating procedures  
WALKER, R D, BARKER, J L, SPESSARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/12 15pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21, 1p

7907050441 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060272 Forwards "Inservice Insp & Testing Programs," Revision 1  
JANECEK, R F Commonwealth Edison Co 79/06/26 2pp

--7907060273 "Inservice Insp & Testing Programs," Revision 1  
\* Commonwealth Edison Co 79/06/26 313pp

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240273 Ack receipt of 790531 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/07/02 1p

--7907240274 Responds to NRC 790510 ltr re violations noted in IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06 Corrective actions: administrative controls now minimize amount of combustible matl in safety-related areas  
REED, C Commonwealth Edison Co 79/05/31, 4pp.

7907240081 Forwards IE Info Notice 79-18, "Skylab Reentry," No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/06 1p.

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/13 1p.

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p.

## DOCKETED ITEMS

7907260326 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Boreated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### R Periodic operating reports & related correspondence

7907170074 Forwards monthly operating rept for June 1979  
STEPHENSON, B B Commonwealth Edison Co 79/07/10 1p

--7907170078 Monthly operating rept for June 1979  
CIESZKIEWICZ, S Commonwealth Edison Co 79/07/03 20pp

#### S Reportable occurrences, LERs & related correspondence

7907030404 Forwards LER 79-037/03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/06/22 1p

--7907030408 LER 79-037/03L-0 on 790530 after operator closed Bus 24-1 auxiliary cabinet door, diesel generator differential fault alarmed, resulting in trip to fault relay w/target up Caused by closing auxiliary door excessively hard  
CHAN, J Commonwealth Edison Co 79/06/22 1p

7907110442 Forwards LER 79-042/03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/07/02 1p

--7907110443 LER 79-042/03L-0 on 790508 during instrument surveillance, HPCI steam line high flow switch DPIS 2353 tripped at 1.5 inches of water above Tech Spec Table 3.2.1 limit Caused by instrument drift Switch reset  
PARELL, M Commonwealth Edison Co 79/07/02 1p

7907110430 Forwards LER 79-040/03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/07/03 1p

--7907110433 LER 79-040/03L-0 on 790603 water discovered spraying into radwaste reboiler room, flooding radioactively contaminated floor & leaking onto ground around bldg Caused by rupture of clean water hose Area secured  
JONES, F Commonwealth Edison Co 79/07/03 1p

7907260709 Forwards LER 79-043/03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/07/19 1p

--7907260720 LER 79-043/03L-0 on 790621 samplings from floor drain sample tank A yielded concentration of 9.2 E06 picocurie w/total of 0.74 Ci exceeding Tech Specs Evaporation bottoms tank pressurized  
JONES, F A Commonwealth Edison Co 79/07/19 1p

#### DOCKET 50-241 MISSISSIPPI STATE UNIV RESEARCH REACTOR

##### G Inspection reports, IE Bulletins & correspondence

7907100097 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

#### DOCKET 50-243 OREGON STATE UNIV RESEARCH REACTOR

##### P Operating license stage documents & correspondence

7907180559 Forwards "OR State TRIQA Reactor Operating Procedures," rept 11, fuel handling procedures  
RINGLE, J C Oregon State Univ 79/07/11 1p

--7907180570 "OR State TRIQA Reactor Operating Procedures," rept 11, fuel handling procedures  
Oregon State Univ 79/07/11 17pp

##### G Inspection reports, IE Bulletins & correspondence

7907190145 Forwards IE Insp Rept 50-243/79-01 on 790514-15 No noncompliance noted. Rept withheld (ref 10CFR 790)  
NORDENHAUS, L R Region 3, San Francisco, Safeguards Branch 79/06/19 1p

7907230562 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907230759 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

#### DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

##### F Security, medical, emergency & fire protection plans

7907310597 Forwards NRC responses to licensee 790313 comments re fire protection safety evaluation Requests clarification of licensee commitments re appropriate mods  
LAINAS, G Plant Systems Branch 79/06/21 13pp

7907050361 Responds to Item 3.2.7 of fire protection safety evaluation dtd 790214 Performance tests on two fire pumps conducted on 790516 Presently analyzing test methods & instrumentation  
WHITE, L D Rochester Gas & Electric Corp 79/06/29 1p

7907110334 Forwards revised page to physical security plan, changing administrative controls for distribution of manual vital area keys to on-duty operations personnel Encl withheld (ref 10CFR 2.790)  
WHITE, L D Rochester Gas & Electric Corp 79/06/29 1p

##### P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/SEP owner's group in Bethesda, MD re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625) 79/04/30 4pp

7907120207 Summary of 790426 meeting w/utls to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907260073 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
ORIER, D H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907060233 Forwards revised safety assessment of SEP Topic IV-A operation w/less than all loops in svc  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/29 3pp

7907120494 Summary of 790510 meeting w/utl in Bethesda, MD re review of auxiliary feedwater sys & other related sys, as part of ongoing review following TMI incident  
SHEA, J J Operating Reactors Branch 2 (Pre 790625) 79/05/29 27pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related re-evaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907190807 Forwards request for addl info re revision levels of reg guides & description of QA procedures, in order to continue review of Revision 5 to Suppl IV of full-term license application  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/05 4pp

7907310226 Requests addl info re SEP Topic VI-1, "Organic Matls & Post-Accident Chemistry " Forwards list of info needed  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 3pp

7907110651 Forwards Category 2 & 3 regulatory positions to be addressed in SEP Reg Guide 1.114 encl  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp

7907240557 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods  
Documentation re applicability of Westinghouse results to analyses at facility will eventually be required by NRC  
SCHNENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250308 Forwards Amend 27 to License DPR-18, safety evaluation & notice of issuance & availability  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/15 2pp

--7907250312 Amend 27 to License DPR-18 proposing mods to safety injection actuation sys logics  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/15 4pp

--7907250319 Safety evaluation supporting Amend 27 to License DPR-18  
Operating Reactors Branch 2 (Pre 790625) 79/06/15 2pp

--7907250322 Notice of issuance & availability of Amend 27 to License DPR-18  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/15 2pp

7907250186 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of SEP Topic VII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation"  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

7907250055 Summary of 790612 meeting w/util in Pittsburgh, PA re review of progress to date on seismic qualification of mechanical equipment  
JABBOUR, K N Systematic Evaluation Programs Branch (Pre 790625) 79/06/21 6pp

7907030477 Forwards summary of status of mods & insp program re 731101 evaluation of OL effects of postulated high energy line breaks outside containment All mods completed & inservice insp program initiated  
WHITE, L D Rochester Gas & Electric Corp 79/06/27 6pp

7907090253 Responds to NRC 781129 ltr re containment purging during normal plant operation Discusses mfg analyses & confirmation that containment isolation valves will close under postulated design basis accident  
WHITE, L D Rochester Gas & Electric Corp 79/07/02 1p

7907050234 Forwards info re seismic qualification of mechanical & electrical equipment & fluid & electric distribution sys  
WHITE, L D Rochester Gas & Electric Corp 79/07/03 4pp

--7907050240 Submits info re seismic qualification of mechanical & electrical equipment & fluid & electric distribution sys Includes test repts, Tech Specs & oversized drawings  
\* Rochester Gas & Electric Corp 66/09/16 100pp

7907090267 Forwards Amend 10 to application to convert provisional OL to full-term OL & Revision 6 to Suppl IV to application Certificate of Evc encl.  
\* LeBoeuf, Lamb, Leiby & MacRae 79/07/06 4pp.

--7907090268 Amend 10 to application to convert provisional OL to full-term OL & Revision 6 to Suppl IV to technical suppl of application  
WHITE, L D Rochester Gas & Electric Corp. 79/07/02. 11pp

7907120594 Responds to 790618 request re info available to control room operator to indicate status of Class 1E batteries, associated chargers & direct current buses  
WHITE, L D Rochester Gas & Electric Corp 79/07/06 2pp

7907130250 Forwards addl info re pressure shielding steel diaphragm in response to questions raised during review of util 790517 submittal  
WHITE, L D Rochester Gas & Electric Corp 79/07/06 20pp

7907300572 Notification of 790724 meeting w/util in Bethesda, MD to discuss seismic reanalysis program  
WAMBACH, T V Operating Reactors Branch 2. 79/07/10 7pp

7907200236 Forwards addl SEP seismic review info including summary analysis of equipment inside containment, w/tank & foundation drawings for diesel generator air tanks, boric acid storage tanks & refueling water storage tank Encl in Central Files  
WHITE, L D Rochester Gas & Electric Corp. 79/07/16 2pp

7907230224 Forwards application for amend to License DPR-18 changing reactor overpressure protection sys requirements.  
FARGON, R B LeBoeuf, Lamb, Leiby & MacRae 79/07/19. 2pp

--7907230233 Application for amend to License DPR-18 changing reactor overpressure protection sys requirements w/Certificate of Evc & related info.  
WHITE, L D Rochester Gas & Electric Corp 79/07/17 8pp.

7907250353 Responds to 790620 telcon request Forwards NPDES & permit supporting info  
DEBEYN, R J Rochester Gas & Electric Corp 79/07/19 1p

--7907250362 NPDES Permit NY0000493 Stipulation dtd 780612 Supporting correspondence encl  
BCOLNICK, H Environmental Protection Agency 75/02/24 35pp

G Inspection reports, IE Bulletins & correspondence

7907050228 Requests extension to 790801 for response to IE Bulletins 78-12A & 78-12B  
WHITE, L D Rochester Gas & Electric Corp 79/03/18 1p

7907050396 Responds to IE Bulletin 79-09 No QE Type AK-2 circuit breakers installed or planned for use in safety-related sys at facility  
WHITE, L D Rochester Gas & Electric Corp 79/03/18 1p

7907060431 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907240614 Forwards results of preliminary review of licensee responses to IE Bulletin 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907300044 Forwards IE Insp Rept 50-244/79-07 on 780919-21. No noncompliance noted  
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/23 2pp.

--7907300050 IE Insp Rept 50-244/79-07 on 780919-21 No noncompliance noted Major areas inspected results of effluent sample split between licensee & NRC Region 1 during previous insp  
KOTTAN, J J, STOHR, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/21 4pp.

7907050230 Responds to IE Bulletin 79-10, "Requalification Training Program Statistics " Forwards util requalification training program statistics  
WHITE, L D Rochester Gas & Electric Corp 79/05/25 3pp

7907030074 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200151 Forwards IE Bulletin 79-12, "Short Period Screens at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p.

7907230481 Submits addl info to encl B&W 790313 response re IE Bulletins 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds " Forwards vendor 790313 ltr to Westinghouse Util maintains requirements met  
WHITE, L D Rochester Gas & Electric Corp. 79/06/01 3pp

--7907230493 Forwards response to IE Bulletins 78-12 & 78-12A, "Records Investigation Rept Re Off-Chemistry Welds in Matl Surveillance Specimens & Responses to Bulletin 78-12k78-12A Suppl. " Concludes Crystal River 3 isolated event  
TAYLOR, J H Babcock & Wilcox Co. 79/03/13 2pp

7907190116 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class 1E Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves)." Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06. 1p

7907060133 Forwards IE Info Notice 79-15, "Deficient Procedures. " No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907100480 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p.

7907230706 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21. 1p.

## DOCKETED ITEMS

7907300387 Forwards supplemental responses to IE Bulletins 79-06A & 06A, Revision 1 Submits info re summary of changes in operating procedures, containment isolation, schedule of review of training procedures & alignment  
WHITE, L D Rochester Gas & Electric Corp 79/06/22 32pp

7907240203 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p

790712057B Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100376 Forwards IE Circular 79-10, "Pipefittings Mfg From Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100510 Forwards IE Circular 79-12, "Potential Diesel Generator Turbopump Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907060441 Forwards inservice insp program for 1980-89 (App B of QA Manual)  
WHITE, L D Rochester Gas & Electric Corp 79/07/02 2pp

--7907060450 Inservice insp program for 1980-89 (App B of QA manual)  
CURTIS, A E, ANDERSON, C R Rochester Gas & Electric Corp 79/07/02 39pp

7907180822 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907250527 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p

7907270367 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310542 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

# 2 Periodic operating reports & related correspondence

7907090256 Forwards monthly operating rept for May 1979  
SNOW, B Rochester Gas & Electric Corp 79/06/12 1p

--7907090259 Monthly operating rept for May 1979  
BEPEW, L Rochester Gas & Electric Corp, 79/06/08 5pp

# Reportable occurrences, LERs & related correspondence

7907160401 Forwards LER 79-012/01X-1  
WHITE, L D Rochester Gas & Electric Corp 79/07/10 1p

7907160404 LER 79-012/01X-1 on 790327 several anchor bolts identified as not being in accordance w/drawing during inservice insp  
Caused by inadequate control of const installation Anchor bolts corrected  
BODINE, J Rochester Gas & Electric Corp 79/07/10 2pp

D7260394 Forwards LER 79-012/01T-0  
WHITE, L D Rochester Gas & Electric Corp 79/07/23 1p

7907260396 LER 79-013/01T-0 on 790707 during ultrasonic & radiographic examination of steam generator feedwater nozzle-to-elbow welds, small linear indications in elbows were found Cause not identified Elbows replaced  
CURTIS, A E, SPECTOR, B H Rochester Gas & Electric Corp 7/07/27 1p

DOCKET 80-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1  
F Security, medical, emergency & fire protection plans

790723057B Documents info provided verbally re delay in schedule of submittals for fire protection mods Delay until 790731 due to TMI event & IE Bulletin requirements  
COUNSIL, W O Northeast Utilities 79/07/19 2pp

# P Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/BEP owner's group in Bethesda, MD re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625) 79/04/30 4pp

7907050556 Advises of intention to apply requirements of QA topical rept NU-QA-1, Revision 3A, to meet criteria of 10CFR71.51  
COUNSIL, W O Northeast Utilities 79/05/15 1p

7907240060 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct links from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907120169 Forwards Amend 62 to License DPR-21, safety evaluation & notice of issuance & availability  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/01 2pp

--7907120179 Amend 62 to License DPR-21, revising Tech Specs re limiting of conditions for primary sys boundary  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/01 14pp

--7907120188 Safety evaluation supporting Amend 62 to License DPR-21  
\* Office of Nuclear Reactor Regulation 79/06/01, 3pp

--7907120199 Notice of issuance & availability of Amend 62 to License DPR-21  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/01 2pp

7907260919 Notification of 790828-29 meeting w/util to discuss seismic design considerations  
SHEA, J R Office of International Programs 79/06/01 1p

7907180881 Forwards request for addl info re degraded grid voltage in order to complete review of util 770801 submittal  
LAINAS, G Plant Systems Branch 79/06/06 3pp

7907310231 Requests addl info re BEP Topic VI-1, "Organic Matls & Post-Accident Chemistry " Forwards list of info needed  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 3pp

7907120091 Summary of 790517-18 meeting w/util & systematic evaluation program util owners' group at plant site re Topic III-3 A, "Effects of Pipe Break on Structures, Sys & Components Inside Containment "  
SHEA, J J Operating Reactors Branch 2 (Pre 790625) 79/06/07 24pp

7907110673 Forwards Category 2 & 3 regulatory positions to be addressed in SEP Reg Guide 114 encl  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp

7907250185 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of BEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation "  
ZIEHANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

7907050257 Forwards Offsite Dose Calculation Manual,  
COUNSIL, W O Northeast Utilities 79/06/29 1p

--7907050261 Offsite Dose Calculation Manual  
\* Northeast Utilities, 79/06/30, 88pp

7907120638 Forwards proposed amend to Licensee DPR-21 & DPR-65 revising ETB, MIT rept, "Analysis of Exposure Panel Data Collected at Millstone Point" encl.  
COUNSIL, W O Northeast Utilities 79/07/02 2pp

--7907120647 Proposed amend to ETB  
\* Northeast Utilities 79/07/02 68pp

--7907120637 "Analysis of Exposure Panel Data Collected at Millstone Point," prepared by MIT  
\* Northeast Utilities 77/07/31 126pp

7907200349 Forwards addl documentation re electrical equipment environ qualification discussed in WG Council 790305 ltr to DL Ziemann Present info modified to include limit switches on MSIV  
COUNCIL, W O Northeast Utilities 79/07/12 3pp

7907260737 Requests extension until 790813 to respond to NRC 790629 request for PWR licensee capabilities to anticipate & respond to unusual incidents  
COUNCIL, W O Northeast Utilities 79/07/16 1p

#### G Inspection reports, IE Bulletins & correspondence

7907110453 Forwards IE Insp Repts 50-245/79-07 & 50-336/79-07 on 790319-23 No noncompliance noted  
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/09 2pp

--7907110460 IE Insp Repts 50-245/79-07 & 50-336/79-07 on 790319-23 No noncompliance noted Major areas inspected radiation program refueling outage conditions, solid radwaste mgt & followup on previous insp findings  
YUHAS, G P Region 1, Philadelphia, Office of the Director  
GRICKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/08 10pp

7907110607 Responds to IE Bulletin 79-09 re OE Type AK-2 circuit breakers in safety-related sys Circuit breakers are in use at facility, but do not have failure-causing undervoltage tripping device  
COUNCIL, W O Northeast Utilities 79/05/11 2pp

7907020225 Responds to items of IE Bulletin 79-08 No Tech Spec changes required  
COUNCIL, W O Northeast Utilities 79/05/14 1p

7907030233 Responds to IE Bulletin 79-10, "Requalification Training Program Statistics " Forwards util requalification training program statistics  
COUNCIL, W O Northeast Utilities 79/05/22 5pp

7907060392 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907050160 Responds to IE Bulletin 78-12B re atypical weld matl in reactor pressure vessel C-E is performing requested search & will submit rept to NRC by 790608  
COUNCIL, W O Northeast Nuclear Energy Co (Northeast Utilities), 79/05/24 1p

7907030041 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/05/29 1p

7907200115 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190049 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060106 Forwards IE Info Notice 79-15, "Deficient Procedures," No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/06/07 1p

7907260183 Responds to IE Bulletin 79-02 "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Program initiated 790501 to replace all load carrying shell type anchors w/wedge type anchors on most base plates.  
COUNCIL, W O Northeast Utilities 79/06/08 2pp

7907100473 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230681 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907240174 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p

7907120507 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907060195 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907110027 Forwards IE Circular 79-12, "Potential Diesel Generator Turbopump Problem " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180779 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907250509 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/07/06 1p

7907270342 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310509 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

#### R Periodic operating reports & related correspondence

7907200256 Forwards monthly operating rept for June 1979  
OPEKA, J F Northeast Utilities 79/07/16 1p

--7907200259 Monthly operating rept for June 1979  
YOUNG, R Northeast Utilities 79/07/12 7pp

#### S Reportable occurrences, LERs & related correspondence

7907090304 Forwards LER 79-016/03L-0  
OPEKA, J.F. Northeast Utilities 79/06/27 1p

--7907090306 LER 79-016/03L-0 on 790530: pressure switches 263-32A, 263-32C, 263-34A & 263-34B tripped outside allowable band Caused by setpoint drift Switches reset within required range & tested  
YOUNG, R.H Northeast Utilities, 79/06/27 3pp.

7907090300 Forwards LER 79-017/03L-0  
OPEKA, J.F. Northeast Utilities, 79/06/29 1p

--7907090302 LER 79-017/03L-0 on 790602, steam tunnel switch tripped at setpoint higher than specified in Tech Specs. Caused by setpoint drift. Switch adjusted & tested satisfactorily  
\* Northeast Utilities, 79/06/28 3pp.

7907260725 Submits RD-79-18/1P on 790713 sodium pentaborate concentration in standby liquid control sys was found to be in nonconservative error by 15% Caused by error in computation procedure  
OPEKA, J.F. Northeast Utilities, 79/07/16 1p

## DOCKETED ITEMS

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emergency &amp; fire protection plans

7907310449 Notices of completion & implementation of procedural changes for revised emergency plan, per 790327 ltr  
CAHILL, W J Consolidated Edison Co of New York 79/07/23 1p

G Adjudicatory correspondence

7907180754 Affidavit stating familiarity w/contents of June 1979 document on efficiency of epibenthic sled for collecting perch in 1978 Rept prepared by TX Instruments, Inc for util  
JANNARONE, J R Consolidated Edison Co of New York 79/06/06 1p

7907120512 Avers familiarity w/contents of "1976 Year Class Rept for Multipiant Impact Study of Hudson River Estuary," May 1979  
Contents of rept are true  
JANNARONE, J R Consolidated Edison Co of New York 79/06/15 1p

H General correspondence

7907170094 Forwards update of std distribution list for correspondence re facilities Requests incorporation of requested change  
CAHILL, W J Consolidated Edison Co of New York 79/07/09 2pp

7907190519 Requests organizational changes be incorporated into std distribution list  
CAHILL, W J Consolidated Edison Co of New York 79/07/09 2pp

P Operating license stage documents &amp; correspondence

7907120207 Summary of 790426 meeting w/utis to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 3pp

7907310576 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSS  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 2pp

7907060179 Responds to 790126, 0202 & 0316 ltrs re proposed license amend Meeting has been tentatively scheduled for early May to discuss proposed changes No hearings planned  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/18 4pp

7907260040 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional nrc will communicate operational & environ info  
ORTER, D H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907030322 "1976 Year-Class Rept for Multipiant Impact Study of Hudson River Estuary," prepared by TX Instruments Inc  
\* Consolidated Edison Co of New York 79/05/31 B00pp

7907180697 Summary of 790522-23 meeting w/utis & United Engineers & Constructors in NY re seismic analysis  
OLSHAN, L Operating Reactors Branch 1 (Pre 790625) 79/06/01 3pp

7907190609 Forwards Amend 54 to License DPR-26, safety evaluation & notice of issuance & availability  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/07 2pp.

--7907190614 Amend 54 to License DPR-26 changing Tech Specs to permit waiving turbine stop & control valve testing at end of cycle  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/07 5pp

--7907190620 Safety evaluation supporting Amend 54 to License DPR-26  
\* Office of Nuclear Reactor Regulation 79/06/07 2pp.

--7907190623 Notice of issuance & availability of Amend 54 to License DPR-26  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625). 79/06/07 2pp.

7907180158 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods. At some point, NRC will require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625). 79/06/11 2pp.

7907180618 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRINES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907240403 Forwards Amend 55 to License DPR-26, safety evaluation & notice of issuance & availability  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/12 2pp

--7907240411 Amend 55 to License DPR-26 to reduce amount of hydraulic snubbers required by Tech Specs, reflecting redesign of safety-related pipeline support sys  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/12 21pp

--7907240415 Safety evaluation supporting Amend 55 to License DPR-26  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/12 2pp

--7907240418 Notice of issuance & availability of Amend 55 to License DPR-26  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/12 3pp

7907050337 Forwards more clearly reproduced copies of revised pages of ETB for 790412 application for amend re thermal plume mapping.  
BLATT, M Consolidated Edison Co of New York 79/06/26 12pp

7907190803 Responds to FOIA request for NRC Annual Rept 1978, recent NRC studies of TMI rept indicating methods to cool down TMI core & EIS for Indian Point facility & BNL Forwards NRC Annual Rept 1978 w/o encl  
FELTON, J M Division of Rules and Records 79/07/06 1p

7907170132 Provides supplemental response to 781128 ltr re containment purging during normal operation & safety actuation electrical circuitry manual override capability review  
CAHILL, W J Consolidated Edison Co of New York 79/07/09 5pp

7907310249 Discusses facility applicability of WCAP-9600, "Rept on Small Break Accidents for Westinghouse NSSS Sys" Rept was forwarded to DF Ross in 790627 ltr.  
CAHILL, W J Consolidated Edison Co of New York 79/07/23 1p

7907300393 Forwards "Efficiency of 100-Ft Beach Seine for Estimating Shore Zone Densities at Night of Juvenile Striped Bass, Juvenile White Perch & Yearling & Older White Perch" Affidavit & Certificate of Svc encl  
CAHILL, W J Consolidated Edison Co of New York 79/07/24 5pp

--7907300409 "Efficiency of 100-Ft Beach Seine for Estimating Shore Zone Densities at Night of Juvenile Striped Bass, Juvenile White Perch & Yearling & Older White Perch," submitted on behalf of Con Ed  
\* Texas Instruments, Inc 79/07/24 122pp

G Inspection reports, IE Bulletins &amp; correspondence

7907120656 Forwards State of NY 790425 ltr re pressurizer level bistables, for use in preparing response to IE Bulletin 79-06A  
ROSS, D Division of Project Management 79/05/03 1p

7907050218 Discusses proposed steam generator insp during refueling outage proposal fulfills all requirements Requests insp of cracks discovered in last insp & determination of support plate-to-wrappier contact progress  
SCHWENGER, A Operating Reactors Branch 2 (Pre 790625) 79/05/15 2pp

7907180471 Forwards IE Insp Rept 50-247/79-04 on 790204-0303 No noncompliance noted  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/16 2pp

--7907180483 IE Insp Rept 50-247/79-04 on 790204-0303, No noncompliance noted Major areas inspected plant operations, access control area physical protection, preparations for site emergency drill & radiation protection.  
REBELOWSKI, J, JOHNSON, D Region 1, Philadelphia, Office of the Director  
KEIMIO, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/05/14 10pp

7907180389 Forwards IE Insp Rept 50-247/79-06 on 790320-23 No noncompliance noted  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/17. 2pp



--7907180399 IE Insp Rept 50-247/79-06 on 790320-23 No noncompliance noted Major areas inspected fire protection & prevention program, status of mods & implementation of procedures outlined in Amends 36 & 43 re fire protection PAOLINO, R J, KOLTAY, P S, EBNETER, B D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/15 12pp

7907060376 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/22, 1p

7907180217 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 79-06A & Amend 1 to 79-06 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790830 in Bethesda, MD SCHWENCER, A Operating Reactors Branch 1 (Pre 790623) 79/05/22 4pp

--7907180221 "Results of Preliminary Review of Licensee Responses to IE Bulletin 79-06A, Revision 1 "  
\* Office of Nuclear Reactor Regulation 79/05/22 52pp

7907030021 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907120409 Responds to IE Bulletins 78-12A & 12B re welds associated w/reactor vessels Since Unit 1 is in shutdown, requested info not available Presently awaiting info from supplier for Unit 2 Will submit schedule when info is compiled  
CAHILL, W J Consolidated Edison Co of New York 79/05/29 2pp

7907200086 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities." No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190044 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060083 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907110361 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/20, 1p

7907230647 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/21, 1p

7907300457 Forwards supplemental response to IE Bulletin 79-06A. Submits info re operating procedures for dealing w/transients & accidents, review of training instructions for engineered safety features & safety-related valves  
ZARAKAS, P Consolidated Edison Co of New York. 79/06/22 12pp.

7907240136 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p

7907120483 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." Licensee action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907060177 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/06/26, 1p

7907100494 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/28, 1p

7907180753 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907280494 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p

7907270320 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907250231 Forwards response to IE Bulletin 79-13 & discussion of cracking in feedwater sys piping Unit 1 presently in defueled condition awaiting util decision on ECCS installation  
CAHILL, W J Consolidated Edison Co of New York 79/07/16 4pp

7907310487 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

7907250337 Responds to IE Bulletins 79-01 & 79-01A ASCO solenoid valves are used in safety-related sys Evaluation is under way  
Detailed rept forthcoming  
CAHILL, W J Consolidated Edison Co. of New York 79/07/18 1p

R Periodic operating reports & related correspondence

7907180569 Forwards environ data for June 1979 re fish species & water discharge, as specified in Section 401  
MONTI, W A Consolidated Edison Co. of New York 79/07/10 18pp

7907180490 Forwards monthly operating rept for June 1979  
CAHILL, W J Consolidated Edison Co of New York 79/07/13 1p

--7907180494 Monthly operating rept for June 1979  
KAHULA, L Consolidated Edison Co of New York 79/07/05 8pp

S Reportable occurrences, LERs & related correspondence

7907110420 Confirms RD 79-018/01 Addl info received on 790626 from Westinghouse For high energy line breaks inside containment, potential level bias could result in delayed protection signals of low steam generator water levels  
MONTI, W A Consolidated Edison Co of New York 79/06/28 2pp

7907190469 Confirms notification of RD-79-018/01 Advised by Westinghouse that during high energy line breaks inside containment, level bias could result in delayed protection signals Corrective action will be taken before plant startup  
MONTI, W A. Commonwealth Edison Co. 79/06/28 2pp

7907160342 Forwards LER 79-019/04T-0  
O'TOOLE, J D Consolidated Edison Co. of New York 79/07/09 1p

--7907160353 LER 79-019/04T-0 on 790619 activity of Eastview 790430 sample exceeded ten times control station level Caused by tritium releases of manufacturer near station.  
BADLON, B. Consolidated Edison Co. of New York 79/07/06 2pp

7907200389 Forwards LER 79-018/01T-0  
CAHILL, W J Consolidated Edison Co of New York 79/07/10, 1p

--7907200401 LER 79-018/01T-0 on 790626 formal notice received from Westinghouse that, for high energy breaks in containment, potential level bias could result in delayed protection signals based on low-low steam generator water level.  
MAKEPEACE, J M Consolidated Edison Co of New York 79/07/10 2pp.

7907240389 Forwards LER 79-016/03L-0  
CAHILL, W J Consolidated Edison Co. of New York 79/07/13, 1p

--7907240397 LER 79-016/03L-0 on 790613 during end of cycle operation, snubber SR-M24 on line MB-3 had less than required fluid level. Cause could not be determined Snubber to be replaced  
MAKEPEACE, J M Consolidated Edison Co of New York 79/07/13, 1p

7907300287 Forwards LER 79-017/031-0.  
CAHILL, W. J. Consolidated Edison Co of New York 79/07/24, 1p.

## DOCKETED ITEMS

--7907300293 LER 79-017/03L-0 on 790626 one of two high temp series shutoff valves PCV-1310B in steam supply to auxiliary boiler feed pump 22 would not close full stroke Caused by valve operating sluggishly Valve exercised  
HAKEPEACE, J M Consolidated Edison Co of New York 79/07/24 1p

## DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

7907050290 Describes addl mod to cable tunnel sprinkler for fire protection sys  
JANECEK, R F Commonwealth Edison Co 79/06/11 1p

7907190155 Forwards draft suppl to fire protection safety evaluation  
LAINAS, G Plant Systems Branch 79/06/12 2pp

--7907190167 Draft suppl to fire protection safety evaluation  
\* Office of Nuclear Reactor Regulation 79/06/12 11pp

7907190200 Forwards 790612 Automatic Sprinkler Corp drawing 26-1782, Sheet 10B of 10, Revision 4 Drawing indicates cable tunnel sprinkler sys mod  
JANECEK, R F Commonwealth Edison Co 79/07/13 1p

7907300330 Forwards Revision 2, interim physical security plan Plan withheld (ref 10CFR2 790)  
REED, C Commonwealth Edison Co 79/07/23 1p

7907200381 Submits Classes I & III fees for safeguards contingency plans  
REED, C Commonwealth Edison Co 79/07/12 2pp

## G Adjudicatory correspondence

7907050423 Forwards NRDC annual rept & matls & Citizens for Better Environ matls supporting applicant position re involvement of both organizations in broad environ litigation Matl provided in response to 790419 memo & order Svc list encl  
STEPTOE, P Isham, Lincoln & Beale 79/05/03 51pp

7907110486 NRDC opposition to NRC motion for reconsideration of ASLB 790419 memo & order following special prehearing conference Certificate of Svc encl  
ROISHAN, A Z Natural Resources Defense Council 79/05/10 2pp

7907110499 State of IL opposition to NRC 790504 motion & Comm Ed 790507 motion for reconsideration &/or clarification & referral of ASLB 790419 memo & order admitting Contentions 6 & 11  
SEKULER, S N Illinois, State of 79/05/17 6pp

7907110750 Opposes several proposed actions re storage of Dresden spent fuel rods at Cordova plant & const of another plant in Erie-Springhill area Opposes nuclear energy in principle because of alleged inadequate storage methods for radwaste  
HOMAN, P Affiliation Unknown 79/05/31 2pp

7907200185 NRDC response in opposition to Comm Ed motion for reconsideration or, in alternative, for clarification or referral re adequacy of safeguards for spent fuel shipments Motion is unwarranted & inconsistent w/10CFR73  
ROISHAN, A Z Natural Resources Defense Council 79/05/22 4pp

--7907200203 NRDC staff scientist statement re safeguards for spent fuel shipments Proposed rule to protect spent fuel shipments against sabotage, presented in 790429 memo to Commission, is most likely adequate Certificate of Svc encl  
COCHRAN, T B Natural Resources Defense Council 79/05/18 3pp

## H General correspondence

7907160298 Four ltrs opposing transport of 509 radioactive spent fuel rods between facilities  
WIRTH, S, RUNYON, J, QUILTY, J, Affiliation Unknown 79/05/10 4pp

## P. Operating license stage documents &amp; correspondence

7907260089 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional o/c will communicate operational & environ info  
KEPLER, J O, Region 3, Chicago, Office of the Director, 79/05/22 3pp

7907310475 Discusses resolution of deterioration problem of Buna-N components in ASCO solenoid valves Response to IE Bulletin 78-14 has been revised to assure replacement of matl in necessary components by 801231.  
REED, C Commonwealth Edison Co 79/05/31 3pp

7907180610 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, J K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907050284 Forwards supplemental info to Special Rept 43 re spent fuel storage pool mods  
JANECEK, R F Commonwealth Edison Co 79/06/12 3pp

7907090305 Submits addl info to 790102 ltr re current commitments to containment purging during normal plant operation Schedule for responding to issues re normal operation purging will be submitted by 790801  
REED, C Commonwealth Edison Co 79/07/02 3pp

7907260031 Summary of 790628 meeting w/util in Bethesda, MD re purging & venting limits & performance of purge & vent valves during postulated LDCA  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/07/02 6pp

7907130322 Revises 790702 ltr re purging during normal operation No purging at power at Zion will be permitted until purge valves have been analyzed & determined to be capable of closure under DBA  
REED, C Commonwealth Edison Co 79/07/05 1p

7907240345 Requests that GE rept NEDE-25090-P, "Analytical Model for T-Quencher Jet Loads on Submerged Structures," submitted 790531, be included in dockets  
JANECEK, R F Commonwealth Edison Co 79/07/18 1p

## G Inspection reports, IE Bulletins &amp; correspondence

7907190042 Forwards IE Insp Repts 50-010/79-05, 50-237/79-06 & 50-249/79-05 & on 790319-22 & 28 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 2pp

--7907190073 IE Insp Repts 50-010/79-05, 50-237/79-06 & 50-249/79-05 on 790319-22 & 28 No noncompliance noted Major areas inspected radiation protection program & licensee action on previously identified insp items  
FISHER, W L, MILLER, D E, HIATT, J W Region 3, Chicago, Fuel Facility & Materials Safety Branch, 79/04/23 6pp

7907190492 Forwards IE Insp Repts 50-010/79-08, 50-237/79-12 & 50-249/79-10 on 790402-30 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/14 2pp

--7907190497 Notice of violation from insp on 790402-30  
\* Region 3, Chicago, Office of the Director 79/05/10 1p

--7907190507 IE Insp Repts 50-010/79-08, 50-237/79-12 & 50-249/79-10 on 790402-30 Noncompliance noted exceeding limiting condition for operation  
BARKER, J L, SPESSARD, R L Region 3, Chicago, Office of the Director 79/05/10, 12pp

7907060231 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers in use or planned for use in any safety-related sys  
REED, C Commonwealth Edison Co 79/05/17 2pp

7907180101 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
REED, C Commonwealth Edison Co 79/05/25 7pp

7907200296 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities," Action required  
KEPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907190230 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
KEPLER, J O Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
KEPLER, J O Region 3, Chicago, Office of the Director 79/06/07 1p

7907260223 Forwards IE Insp Repts 50-010/79-11, 50-237/79-14 & 50-249/79-12 on 790522 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/07 2pp

--7907260240 IE Insp Repts 50-010/79-11, 50-237/79-14 & 50-249/79-12 on 790522 No noncompliance noted Major areas inspected response of licensee organization during scheduled drill involving simulated contaminated injuries  
GRANT, W B, GREER, R J, EBBIO, T H Region 3, Chicago, Office of the Director 79/06/05 4pp

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utility  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907300486 IE Insp Repts 50-237/79-13 & 50-249/79-11 on 790502-18 Noncompliance noted inadequate operating procedures for engineered safety features  
WALKER, R D, BARKER, J L, SPESSARD, R L Region 3, Chicago, Office of the Director 79/06/12 15pp

7907260810 Forwards IE Insp Repts 50-237/79-13 & 50-249/79-11 on 790502-18 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13 2pp

--7907260815 Notice of violation from insp on 790502-18  
\* Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13 1p

--7907260822 IE Insp Repts 50-237/79-13 & 50-249/79-11 on 790502-18 Noncompliance noted inadequate operating procedures  
WALKER, R D, BARKER, J L, SPESSARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/12 15pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907030441 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Freshwater Sys Piping" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060272 Forwards "Inservice Insp & Testing Programs," Revision 1  
JANECEK, R F Commonwealth Edison Co. 79/06/26 2pp

--7907060273 "Inservice Insp & Testing Programs," Revision 1  
\* Commonwealth Edison Co. 79/06/26 313pp

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240273 Ack receipt of 790531 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06.  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/07/02. 1p

--7907240274 Responds to NRC 790510 ltr re violations noted in IE Insp Repts 50-010/79-06, 50-237/79-07 & 50-249/79-06 Corrective actions administrative controls now minimize amount of combustible matl in safety-related areas  
REED, C Commonwealth Edison Co 79/05/31 4pp

7907240081 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### R. Periodic operating reports & related correspondence

7907170074 Forwards monthly operating rpt for June 1979  
STEPHENSON, B B Commonwealth Edison Co 79/07/10 1p

--7907170078 Monthly operating rpt for June 1979  
CIESZKIEWICZ, B Commonwealth Edison Co 79/07/03 20pp

#### S. Reportable occurrences, LERs & related correspondence

7907100300 Forwards LER 79-015-03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/07/03 1p

--7907100311 LER 79-015-03L-0 on 790608 source range monitor hi count initiated rod block in excess of Tech Specs max Caused by electronic instrument drift Source range monitor readjusted  
DUNBAR, J Commonwealth Edison Co 79/07/03 1p

7907110548 Forwards LER 79-014/03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/07/03 1p

--7907110554 LER 79-014/03L-0 on 790606 core spray pump 3A gland supply line found leaking at connection to pump casing Caused by leaky fitting Fitting replaced  
SMITH, G. Commonwealth Edison Co 79/07/03 1p

7907250364 Forwards LER 79-016/03L-0  
STEPHENSON, B B Commonwealth Edison Co 79/07/19 1p

--7907250372 LER 79-016/03L-0 on 790621 hi flow isolation switch DPIS 3-216-20 tripped at 116.5 psid Caused by failed mercury switch Replaced w/Harcoid Type 3-11 switch. DPIS 3-261-20 adjusted & verified  
LINDBERG, C Commonwealth Edison Co. 79/06/21 1p

#### DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

#### F. Security, medical, emergency & fire protection plans

7907260661 Forwards appropriate Class III fee for Safeguards Contingency Plans, in response to RM Diggs 790703 ltr W/o encl.  
UHRIG, R E Florida Power & Light Co 79/07/19. 1p.

#### G. Adjudicatory correspondence

7907110668 FL Power & Light response to 790509 order in which applicant & NRC were requested to submit position re petitioner MP Onavaga 790502 new contentions Petitioner requests do not meet requirements Certificate of BvC encl.  
BAUSER, M A. Lowenstein, Neuman, Reis, Axelrad & Toll. 79/05/21. 13pp.

## DOCKETED ITEMS

790709061 Petitioner MP Oncavage supplemental submission Requests  
intervenor status per 790531 order  
ROGDH, B S Rogow, B 79/06/05 9pp

--790709066 Notice of appearance on behalf of petitioner MP Oncavage  
Certificate of Svc encl  
ROGDH, B S Rogow, B 79/06/05 3pp

7907190472 Florida Power & Light opposition to MP Oncavage supplemental  
submission for intervention in proceeding New Scientist  
790405 article & Certificate of Svc encl  
REIS, H F, BAUSER, M A Lowenstein, Neuman, Reiss, Axelrad & Toll  
79/06/20 25pp

7907190457 NRC answer to MP Oncavage 790605 submission in support of  
original petition to intervene, as revised per 790605  
suppl Certificate of Svc encl  
GOLDBERG, B C Branch 2 79/06/25 5pp

#### F Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse  
plant design re TH1-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310584 Forwards NRC 790515 ltr to licensees of Westinghouse  
two-loop plants re rod bank exchange method for verifying  
shutdown margin of two-loop NSSS w/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15  
1p

7907130990 Requests solid waste process control program & Offsite Dose  
Calculation Manual in order to complete review of proposed  
Tech Specs  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22  
2pp

7907130133 Ack receipt of util 770321 ltr responding to NRC request for  
evaluation of postulated fuel handling accident inside  
containment Potential consequences of postulated accident  
are within 10CFR100 guidelines & are acceptable  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/30  
2pp

--7907130141 Safety evaluation re fuel handling accident inside  
containment Doses for one assembly failure are  
appropriately within 10CFR100 guideline values & therefore  
acceptable  
\* Operating Reactors Branch 1 (Pre 790625) 79/05/30 4pp

7907110694 Summary of 790529 meeting w/FL Power & Light Co re  
containment purge during normal plant operation  
GROTEHUIS, M Operating Reactors Branch 1 (Pre 790625)  
79/06/03 4pp

7907110730 Forwards errata sheet for BER issued 790514  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/05  
3pp

7907240546 Forwards NRC 790604 ltr to Westinghouse requesting addl info  
re small break LOCA analyses & analysis methods NRC will  
eventually require documentation re applicability of  
Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11  
2pp

7907250008 Forwards NUREG-0560, "Staff Rept on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp

7907260035 Requests registration as user of Model NLI-1/2  
UHRIG, R E Florida Power & Light Co 79/06/11 1p

7907250535 Forwards Amends 49 & 41 to Licenses DPR-31 & DPR-41,  
respectively, safety evaluation & notice of issuance &  
availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/15  
3pp

--7907250543 Amends 49 & 41 to Licenses DPR-31 & DPR-41, respectively,  
approving operation w/peaking factor of 2.10, assuming no  
more than 22% of steam generator tubes are plugged  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625)  
79/06/15 16pp

--7907250549 Safety evaluation supporting Amends 49 & 41 to Licenses  
DPR-31 & DPR-41, respectively.  
\* Operating Reactors Branch 1 (Pre 790625) 79/06/15 8pp

--7907250557 Notice of issuance & availability of Amends 49 & 41 to  
Licenses DPR-31 & DPR-41, respectively  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625)  
79/06/15 2pp

7907300514 Discusses 790526 emergency power diesel generator control  
sys failure during sustained 24-h load test at facility  
Based on corrections & 790214 meeting w/utill, Unit 3 was  
permitted to go to full power  
GROTEHUIS, M Operating Reactors Branch 1 79/06/20 5pp

#### G Inspection reports, IE Bulletins & correspondence

7907020366 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
TH1 - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110722 Confirms 790502 telcon during which util agreed to  
establish procedures & instructions to operators re HPI  
Initiation Agreement conflicts w/response to IE Bulletin  
79-06A, Item 7c  
SCHMIDT, A D Florida Power & Light Co 79/05/04 1p

7907110325 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907060263 Responds to IE Bulletin 79-06A, Item 13 Tech Specs mod re  
safety injection trip logic approved on 790504 as Amends 4B  
& 4C to Licenses DPR-31 & DPR-41, respectively No other mods  
identified  
UHRIG, R E Florida Power & Light Co 79/05/15 1p

7907130152 Ack 790306 request for delay in development of inservice  
insp program pending decision on proposed changes to  
10CFR50.55a Delay is unacceptable  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/16  
3pp

7907100184 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907110103 Forwards IE Bulletin 79-13, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys" Action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 2pp

7907240602 Forwards results of preliminary review of licensee responses  
to IE Bulletins 79-06, 06A & 06A, Amend 1 Meeting  
w/owners of operating plants having Westinghouse-designed  
sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22  
4pp

7907240170 Forwards IE Insp Repts 50-250/79-13 & 50-251/79-13 on  
790508-11 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support  
Branch 79/05/23 2pp

--7907240184 IE Insp Repts 50-250/79-13 & 50-251/79-13 on 790508-11 No  
noncompliance noted Major areas inspected startup testing  
results for Unit 3 & refueling activities for Unit 4  
VOGT-LOWELL, R J Region 2, Atlanta, Office of the Director  
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear  
Support Branch 79/05/22 5pp

7907120280 Responds to IE Bulletin 79-10 Forwards operator & senior  
operator examination results & related statistics  
UHRIG, R E Florida Power & Light Co 79/05/24 3pp

7907180180 Supplements response to IE Bulletin 79-07 Uses ADLPIPE to  
perform seismic analyses of safety-related piping changes &  
mods None of methods specified in bulletin are used  
UHRIG, R E Florida Power & Light Co 79/05/24 2pp

7907100094 Responds to IE Bulletins 79-06 & 06B Responsibility for  
initiation & verification of auxiliary feedwater flow to  
steam generators is primary duty of designated operator  
during transients & accidents  
UHRIG, R E Florida Power & Light Co 79/05/25 1p

7907030096 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907130305 Forwards status rept describing progress in responding to IE Bulletin 78-12B re atypical weld matl  
UHRIG, R E Florida Power & Light Co 79/05/29 2pp

7907260302 Forwards IE Insp Repts 50-250/79-05 & 50-251/79-05 on 790501-03 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/29 2pp

--7907260508 IE Insp Repts 50-250/79-05 & 50-251/79-05 on 790501-03 No noncompliance noted Major areas inspected verification of engineered safeguards feature sys valve breaker & switch alignments & review of facility operating procedures  
VERDEY, E H Region 2, Atlanta, Office of the Director 79/05/29 5pp

7907200192 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907190233 Responds to IE Bulletin 79-06A re possibility of steam bubble formation or release of noncondensable gases in primary sys Completed control circuit mods automatically initiate safety injection  
UHRIG, R E Florida Power & Light Co 79/06/04 5pp

7907090140 Suppl response to IE Bulletin 79-03 Further investigation has revealed that pipe sizes between 6-24 inches are in use at facility  
UHRIG, R E Florida Power & Light Co 79/06/05 2pp

7907190172 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp

7907060056 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907250158 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp

7907190142 Responds to IE Bulletin 79-01 Unable to submit requested rept re environ qualification of Class IE equipment until 790702  
UHRIG, R E Florida Power & Light Co 79/06/12 1p

7907240004 Ack receipt of 790529 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-07 & 50-251/79-07  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/19 1p

--7907240020 Responds to NRC 790503 ltr re violation noted in IE Insp Repts 50-250/79-07 & 50-251/79-07 Corrective actions individuals who performed local leak rate tests were certified on 790302  
UHRIG, R E Florida Power & Light Co 79/05/29 2pp

--7907240029 Forwards IE Insp Repts 50-250/79-07 & 50-251/79-07 on 790220-23 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/03 2pp

--7907240065 Notice of violation from insp on 790220-23  
\* Region 2, Atlanta, Office of the Director 79/04/26 1p

--7907240070 IE Insp Repts 50-250/79-07 & 50-251/79-07 on 790220-23 Noncompliance noted failure to use certified personnel per Tech Specs in performance of leak testing between Dec 1978-Feb 1979  
JOHNSON, A H Region 2, Atlanta, Office of the Director  
MARTIN, D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/26 6pp

7907020386 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120075 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110226 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907310019 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 2pp

7907110269 Forwards IE Circular 79-10, "Pipe Fittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907180435 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907230001 Forwards IE Insp Rept 50-250/79-21 & 50-251/79-21 on 790606 No noncompliance noted  
O'REILLY, J P Region 1, Philadelphia, Office of the Director 79/06/28 2pp

--7907230002 IE Insp Repts 50-250/79-21 & 50-251/79-21 on 790606 No noncompliance noted Major areas inspected meeting discussing QA insp conducted 790312-16 & 19-21  
RUHLMAN, W A Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/21 2pp

7907310240 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp

7907310379 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 2pp

7907240362 Requests that util owners group 790629 rept forwarding info requested by IE Bulletins 79-06 & 06A re postulated small break accidents be included in dockets  
UHRIG, R E Florida Power & Light Co 79/07/17 1p

#### B Reportable occurrences, LERs & related correspondence

7907090303 Forwards LER 79-019/03L-0  
SCHMIDT, A D Florida Power & Light Co 79/06/14 1p

--7907090311 LER 79-019/03L-0 on 790515 during power operation, fewer than three required intake cooling water pumps were operable  
Caused by debris at pump suction well Pump backflushed & tested satisfactorily  
SCHOPPMAN, M A Florida Power & Light Co 79/06/14 1p

7907090337 RO 1979-22 on 790626 loss of 4a-4160 volt bus did not result in shared O motor control automatic transfer Will control motor ctr manually Design change will be long-term action  
YAEGER, H E Florida Power & Light Co 79/06/27 1p

7907170098 Forwards LER 79-022/01T-0  
SCHMIDT, A D Florida Power & Light Co 79/07/10 1p

--7907170101 LER 79-022/01T-0 on 790626 loss of 3B 4160 V bus would not result in automatic transfer of shared D motor ctr to alternative supply from 4A 4160 V bus Operating procedures are being revised to correct situation  
SCHOPPMAN, M A Florida Power & Light Co 79/06/26 2pp

7907170179 Forwards LER 79-021/01T-0  
SCHMIDT, A D Florida Power & Light Co 79/07/10 1p

--7907170195 LER 79-021/01T-0 on 790626 NBSB vendor notified util of potential level bias which could delay reactor trip & feedwater initiation or cause false level indications  
License amend will be proposed to increase sys setpoint  
SCHOPPMAN, M A Florida Power & Light Co 79/07/10 2pp

#### U Congressional/Executive Correspondence

7906260590 Forwards D Browning 790404 questions re FL nuclear power situation Requests necessary info for reply  
MICA, D A House of Rep 79/04/05 2pp

## DOCKETED ITEMS

--7906260593 Ack receipt of 790405 ltr re D Browning info request re FL nuclear power situation Forwards instructions to operators re steps to prevent occurrence like TMI & JM Hendrie 790410 testimony to Subcommittee on Nuclear Regulation W/o encl  
HANHERER, C Office of Congressional Affairs 79/04/18 1p

7907250157 Forwards petitioner MP Onccavage 790312 ltr addressed to Senator Stone re pleadings relating to petitioner contentions presented at prehearing conference Requests consideration of petition & return of findings & views  
STONE, R Senate, 79/03/31 1p

--7907250175 Forwards MP Onccavage 790424 reply to Florida Power & Light 790330 & NRC 790406 responses  
ONCAVAGE, M P Mark Onccavage 79/05/12 1p

--7907250184 Reply to licensee 790330 & NRC 790406 responses Area will suffer economic dislocations if plant is allowed to continue to operate List of contentions encl  
ONCAVAGE, M P Mark Onccavage 79/04/24 9pp

## DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

## F Security, medical, emergency &amp; fire protection plans

7907260661 Forwards appropriate Class III fee for Safeguards Contingency Plans, in response to RM Diggs 790703 ltr W/o encl  
UHRIG, R E Florida Power & Light Co 79/07/19 1p

## G Adjudicatory correspondence

7907110669 FL Power & Light response to 790509 order in which applicant & NRC were requested to submit position re petitioner MP Onccavage 790502 new contentions Petitioner requests do not meet requirements Certificate of Svc encl.  
BAUSER, M A Lowenstein, Newman, Reis, Aselrad & Toll 79/05/21 13pp

7907090661 Petitioner MP Onccavage supplemental submission Requests intervenor status per 790531 order  
ROGOW, B S Rogow, B 79/06/05 9pp

--7907090666 Notice of appearance on behalf of petitioner MP Onccavage Certificate of Svc encl.  
ROGOW, B S Rogow, B 79/06/05 3pp

7907190472 Florida Power & Light opposition to MP Onccavage supplemental submission for intervention in proceeding New Scientist 790405 article & Certificate of Svc encl.  
REIS, M F, BAUSER, M A Lowenstein, Newman, Reis, Aselrad & Toll 79/05/20 25pp

7907190457 NRC answer to MP Onccavage 790603 submission in support of original petition to intervene, as revised per 790603 suppl Certificate of Svc encl  
GOLDBERG, B C Branch 2 79/06/25 5pp

## P Operating license stage documents &amp; correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch, 79/05/02 38pp

7907310584 Forwards NRC 790315 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSS W/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p

7907130090 Requests solid waste process control program & Offsite Dose Calculation Manual in order to complete review of proposed Tech Specs  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 2pp

7907130133 Ack receipt of util 790321 ltr responding to NRC request for evaluation of postulated fuel handling accident inside containment Potential consequences of postulated accident are within 10CFR100 guidelines & are acceptable  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/30 2pp.

--7907130141 Safety evaluation re fuel handling accident inside containment Doses for one assembly failure are appropriately within 10CFR100 guideline values & therefore acceptable.  
\* Operating Reactors Branch 1 (Pre 790625) 79/05/30 4pp.

7907110694 Summary of 790329 meeting w/FL Power & Light Co re containment purge during normal plant operation  
GROTHENHUIS, M Operating Reactors Branch 1 (Pre 790625) 79/06/05 6pp

7907110730 Forwards errata sheet for SER issued 790514  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/03 3pp

7907240546 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp.

7907250008 Forwards NUREG-0560, "Staff Rpt on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
ORMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907260035 Requests registration as user of Model NLI-1/R  
UHRIG, R E Florida Power & Light Co 79/06/11 1p

7907250535 Forwards Amends 49 & 41 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/15 3pp.

--7907250543 Amends 49 & 41 to Licenses DPR-31 & DPR-41, respectively, approving operation w/peaking factor of 2.10, assuming no more than 22% of steam generator tubes are plugged  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/15 16pp

--7907250549 Safety evaluation supporting Amends 49 & 41 to Licenses DPR-31 & DPR-41, respectively  
\* Operating Reactors Branch 1 (Pre 790625) 79/06/15 8pp

--7907250557 Notice of issuance & availability of Amends 49 & 41 to Licenses DPR-31 & DPR-41, respectively  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/15 2pp

7907300514 Discusses 790526 emergency power diesel generator control sys failure during sustained 24-h load test at facility Based on corrections & 790214 meeting w/utill, Unit 3 was permitted to go to full power  
GROTHENHUIS, M Operating Reactors Branch 1 79/06/20 5pp.

## G Inspection reports, IE Bulletins &amp; correspondence

7907020366 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI - Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110722 Confirms 790502 telcon during which util agreed to establish procedures & instructions to operators re HPI initiation, Agreement conflicts w/response to IE Bulletin 79-06A, Item 7c  
SCHMIDT, A D Florida Power & Light Co 79/05/04 1p

7907110325 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907060623 Responds to IE Bulletin 79-06A, Item 13 Tech Specs mod re safety injection trip logic approved on 790504 as Amends 4B & 4D to Licenses DPR-31 & DPR-41, respectively No other mods identified.  
UHRIG, R E Florida Power & Light Co 79/05/15 1p

7907130152 Ack 790306 request for delay in development of inservice insp program pending decision on proposed changes to 10CFR50.55a Delay is unacceptable.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 3pp.

7907100184 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110103 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp.

7907240602 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790930 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790623) 79/05/22 4pp

7907240170 Forwards IE Insp Repts 50-250/79-13 & 50-251/79-13 on 790508-11 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/23 2pp

--7907240184 IE Insp Repts 50-250/79-13 & 50-251/79-13 on 790508-11 No noncompliance noted Major areas inspected startup testing results for Unit 3 & refueling activities for Unit 4  
VOGT-LOWELL, R J Region 2, Atlanta, Office of the Director  
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/22 5pp

7907120280 Responds to IE Bulletin 79-10 Forwards operator & senior operator examination results & related statistics  
UHRIO, R E Florida Power & Light Co 79/05/24 5pp

7907180180 Supplements response to IE Bulletin 79-07 Uses ADLPIPE to perform seismic analyses of safety-related piping changes & mods None of methods specified in bulletin are used  
UHRIO, R E Florida Power & Light Co 79/05/24 2pp

7907100094 Responds to IE Bulletins 79-06 & 06B Responsibility for initiation & verification of auxiliary feedwater flow to steam generators is primary duty of designated operator during transients & accidents  
UHRIO, R E Florida Power & Light Co 79/05/25 1p

7907030096 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907130305 Forwards status rept describing progress in responding to IE Bulletin 78-12B re atypical weld matl  
UHRIO, R E Florida Power & Light Co 79/05/29 2pp

7907260502 Forwards IE Insp Repts 50-250/79-05 & 50-251/79-05 on 790501-03 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/29 2pp

--7907260508 IE Insp Repts 50-250/79-05 & 50-251/79-05 on 790501-03 No noncompliance noted Major areas inspected verification of engineered safeguards feature sys valve breaker & switch alignments & review of facility operating procedures  
VERBEY, E H Region 2, Atlanta, Office of the Director 79/05/29 5pp

7907200192 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp.

7907190233 Responds to IE Bulletin 79-06A re possibility of steam bubble formation or release of noncondensable gases in primary sys Completed control circuit mods automatically initiate safety injection  
UHRIO, R E Florida Power & Light Co 79/06/04 5pp

7907090140 Suppl response to IE Bulletin 79-03 Further investigation has revealed that pipe sizes between 6-24 inches are in use at facility  
UHRIO, R E Florida Power & Light Co 79/06/05 2pp.

7907190172 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp

7907060056 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp.

7907250158 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp.

7907190142 Responds to IE Bulletin 79-01. Unable to submit requested rept re environ qualification of Class IE equipment until 790702.  
UHRIO, R. E. Florida Power & Light Co 79/06/12 1p

7907240004 Ack receipt of 790529 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-07 & 50-251/79-07  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/19 1p

--7907240020 Responds to NRC 790503 ltr re violation noted in IE Insp Repts 50-250/79-07 & 50-251/79-07 Corrective actions individuals who performed local leak rate tests were certified on 790302  
UHRIO, R. E Florida Power & Light Co 79/05/29 2pp

--7907240029 Forwards IE Insp Repts 50-250/79-07 & 50-251/79-07 on 790220-23 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/03 2pp

--7907240065 Notice of violation from insp on 790220-23  
\* Region 2, Atlanta, Office of the Director 79/04/26 1p

--7907240070 IE Insp Repts 50-250/79-07 & 50-251/79-07 on 790220-23 Noncompliance noted failure to use certified personnel per Tech Specs in performance of leak testing between Dec 1978-Feb 1979.  
JOHNSON, A H Region 2, Atlanta, Office of the Director  
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/26 6pp

7907020386 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/06/20 1p

7907120075 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110226 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907310019 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/23 2pp

7907110269 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907180435 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/06/28 2pp

7907230001 Forwards IE Insp Rept 50-250/79-21 & 50-251/79-21 on 790606 No noncompliance noted  
O'REILLY, J P Region 1, Philadelphia, Office of the Director 79/06/28 2pp

--7907230002 IE Insp Repts 50-250/79-21 & 50-251/79-21 on 790606 No noncompliance noted Major areas inspected, meeting discussing QA insp conducted 790312-16 & 19-21  
RUHLMAN, W A Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/21 2pp

7907310240 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp

7907310379 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 2pp.

7907240362 Requests that util owners group 790629 rept forwarding info requested by IE Bulletin 79-06 & 06A re postulated small break accidents be included in dockets  
UHRIO, R. E. Florida Power & Light Co. 79/07/17 1p

S Reportable occurrences, LERs & related correspondence

7907110408 Forwards LER 78-007/03L-0  
SCHMIDT, A D Florida Power & Light Co 78/08/07. 1p

## DOCKETED ITEMS

--7907110412 LER 78-007/03L-O on 780710 for 11 5-4, condensate storage tank level was below Tech Spec limits Caused by condenser leaks in both units Water treatment was shut down & storage tanks filled  
SCHOPPMAN, M A Florida Power & Light Co 78/08/07 2pp

7907090350 Forwards LER 79-008/03L-O  
SCHMIDT, A D Florida Power & Light Co 79/06/25 1p

--7907090371 LER 79-009/03L-O on 790526 emergency diesel generator stopped due to lockout relay activation Caused by improper settings on undervoltage time delay relays Relays reset & tested Test procedures will be revised  
SCHOPPMAN, M A Florida Power & Light Co 79/06/25 1p

7907170158 Forwards LER 79-010/01T-O  
SCHMIDT, A D Florida Power & Light Co 79/07/10 1p

--7907170164 LER 79-010/01T-O on 790626 NSSS vendor notified util of potential level bias which could delay reactor trip & feedwater initiation or cause false level indications License amend will be proposed to increase svr setpoint  
SCHOPPMAN, M A Florida Power & Light Co 79/07/10 2pp

7907180557 Forwards LER 79-009/03L-O  
SCHMIDT, A D Florida Power & Light Co 79/07/11 1p

--7907180565 LER 79-009/3L-O on 790611 mechanical snubber on C steam generator feedwater line found in locked-up condition Cause unknown Snubber replaced  
SCHOPPMAN, M A Florida Power & Light Co 79/07/11 1p

#### U Congressional/Executive Correspondence

7907250157 Forwards petitioner MP Oncavage 790512 ltr addressed to Senator Stone re pleadings relating to petitioner contentions presented at prehearing conference Requests consideration of petition & return of findings & views  
STONE, R Senate 79/05/31 1p

--7907250175 Forwards MP Oncavage 790424 reply to Florida Power & Light 790330 & NRC 790406 responses  
ONCAVAOE, M P Mark Oncavage 79/05/12 1p

--7907250184 Reply to licensee 790330 & NRC 790406 responses Area will suffer economic dislocations if plant is allowed to continue to operate List of contentions encl  
ONCAVAOE, M P Mark Oncavage 79/04/24 9pp

#### DOCKET 50-252 UNIV OF NEW MEXICO RESEARCH REACTOR

##### Q Inspection reports, IE Bulletins & correspondence

7907100268 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020023 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus"  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

#### DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

##### F Security, medical, emergency & fire protection plans

7907200391 Submits Classes I & III fees for safeguards contingency plans  
REED, C Commonwealth Edison Co 79/07/12 2pp

7907300330 Forwards Revision 2, interim physical security plan Plan withheld (re 10CFR2 790)  
REED, C Commonwealth Edison Co. 79/07/23 1p

##### G Adjudicatory correspondence

7907050423 Forwards NRDC annual rept & matls & Citizens for Better Environ matls supporting applicant position re involvement of both organizations in broad environ litigation Matl provided in response to 790419 memo & order Svc list encl  
STEPTOE, P Isham, Lincoln & Beale 79/05/03 51pp

7907110486 NRDC opposition to NRC motion for reconsideration of ASLB 790419 memo & order following special prehearing conference Certificate of Svc encl  
ROISHMAN, A Z Natural Resources Defense Council 79/05/10 2pp

7907110499 State of IL opposition to NRC 790504 motion & Comm Ed 790513 motion for reconsideration &/or clarification & referral of ASLB 790419 memo & order admitting Contentions 6 & 11  
SEKULER, S N Illinois, State of 79/05/17 6pp

7907200185 NRDC response in opposition to Comm Ed motion for reconsideration or, in alternative, for clarification or referral re adequacy of safeguards for spent fuel shipments Motion is unwarranted & inconsistent w/10CFR73  
ROISHMAN, A Z Natural Resources Defense Council 79/05/22 4pp

--7907200203 NRDC staff scientist statement re safeguards for spent fuel shipments Proposed rule to protect spent fuel shipments against sabotage, presented in 790429 memo to Commission, is most likely adequate Certificate of Svc encl  
COCHRAN, T B Natural Resources Defense Council 79/05/18 3pp

#### H General correspondence

7907160298 Four ltrs opposing transportation of 509 radioactive spent fuel rods between facilities  
WIRTH, S Affiliation Unknown 79/05/10 4pp

#### P Operating license stage documents & correspondence

7907260089 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907310475 Discusses resolution of deterioration problem of Buna-N components in ASCO solenoid valves Response to IE Bulletin 78-14 has been revised to assure replacement of matl in necessary components by B01231  
REED, C Commonwealth Edison Co 79/05/31 3pp

7907290004 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
ORINES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907310462 Requests substitution of encl instruction sheet & addition of Tech Spec pages to Amend 50 to License DPR-29  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/12 6pp

7907190023 Forwards summary status of fuel performance, end of Cycle 4, Feb 1979  
KALIVIANAKIS, N Commonwealth Edison Co 79/06/15 25pp

7907260645 Summary of 790604 meeting w/util in Bethesda, MD re proposed App I Tech Specs & related matters  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625) 79/06/22 3pp

7907090305 Submits addl info to 790102 ltr re current commitments to containment purging during normal plant operation Schedule for responding to issues re normal operation purging will be submitted by 790801  
REED, C Commonwealth Edison Co 79/07/02 3pp

7907260031 Summary of 790628 meeting w/util in Bethesda, MD re purging & venting limits & performance of purge & vent valves during postulated LOCA  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/07/02 6pp

7907130322 Revises 790702 ltr re purging during normal operation No purging at power at Zion will be permitted until purge valves have been analyzed & determined to be capable of closure under DBA  
REED, C Commonwealth Edison Co 79/07/05 1p

7907160294 Forwards responses to NRC comments at 790606 meeting re offsite Dose calculation manual, for NRC review prior to 790716 meeting  
NAUGHTON, W F Commonwealth Edison Co 79/07/05 4pp

7907190543 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," 790219-22 Requests NRC approval of plans to schedule next Type A test for Dec 1980  
KALIVIANAKIS, N Commonwealth Edison Co 79/07/05 1p



7907190545 "Reactor Containment Bldg Integrated Leak Rate Test,"  
790219-22  
\* Commonwealth Edison Co 79/07/05 60pp

7907300341 Notification of 790712 meeting w/util in Bethesda, MD to  
discuss proposed App 1 Tech Specs  
BEVAN, R B Operating Reactors Branch 3 79/07/06 2pp

7907170070 Forwards corrected page 1 of Facility startup test rept  
transmitted w/790521 ltr  
JANECEK, R F Commonwealth Edison Co 79/07/11 2pp

7907240345 Requests that GE rept NEDE-25090-P, "Analytical Model for  
T-Quencher Jet Loads on Submerged Structures," submitted  
790531, be included in dockets  
JANECEK, R F Commonwealth Edison Co 79/07/18 1p

#### G Inspection reports, IE Bulletins & correspondence

7907060251 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit  
breakers in use or planned for use in any safety-related  
sys  
REED, C Commonwealth Edison Co 79/05/17 2pp

7907180101 Responds to IE Bulletin 79-10 Submits requalification  
training program statistics  
REED, C Commonwealth Edison Co 79/05/25 7pp

7907200296 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31  
1p

7907190266 Notification of 790606 meeting w/util in Bethesda, MD to  
discuss App 1 to Tech Specs & related matters, including  
process control program  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625) 79/06/05  
2pp

7907190230 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCD Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07  
1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures"  
forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp

7907310080 Forwards IE Insp Repts 50-254/79-09 & 50-265/79-07 on  
790315-16, 21, 22, 0403-05, 18, 19, 23, 24, 27 & 0508 & notice  
of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear  
Support Branch 79/06/13 2pp

--7907310086 Notice of violation from insp on 790315-16, 21, 22, 0403-05,  
18, 19, 23, 24, 27 & 0508  
\* Region 3, Chicago, Office of the Director 79/06/12 1p

--7907310096 IE Insp Repts 50-254/79-09 & 50-265/79-07 on 790315-16, 21,  
22, 0403-05, 18, 19, 23, 24, 27 & 0508 Noncompliance noted  
automatic function of vacuum breakers not available  
CHRISTOTIMOS, N, SPESSARD, R L Region 3, Chicago, Office of the  
Director 79/06/12 5pp

7907300491 IE Insp Repts 50-254/79-12 & 50-265/79-10 on 790501-24 No  
noncompliance noted Major areas inspected, operator training,  
safety features, surveillance test procedures & procedures  
for verification of sys alignment  
CHRISTOTIMOS, N, MONO, B M, SPESSARD, R L Region 3, Chicago,  
Office of the Director 79/06/14 13pp

7907180304 Forwards IE Insp Repts 50-254/79-12 & 50-265/79-10 on  
790501-24 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear  
Support Branch 79/06/15 2pp

--7907180455 IE Insp Repts 50-254/79-12 & 50-265/79-10 on 790501-24 No  
noncompliance noted Major areas inspected licensee response  
to IE Bulletin 79-08 re TMI implications for BWRs  
CHRISTOTIMOS, N, MONO, B M, SPESSARD, R L Region 3, Chicago,  
Office of the Director 79/06/14 13pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage From Misfit Between Assembly & Reactor Upper Grid  
Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20  
1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907050441 Forwards IE Circular 79-09, "Occurrences of Split or  
Punctured Regulator Diaphragms in Certain Self-Contained  
Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p

7907240081 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06  
1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant  
Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for  
As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20  
1p

#### R Periodic operating reports & related correspondence

7907240369 Monthly performance rept for May 1979  
HANNUM, D Commonwealth Edison Co 79/05/31 25pp

7907240322 Monthly operating rept for June 1979  
HANNUM, D Commonwealth Edison Co 79/06/30 28pp.

#### S Reportable occurrences, LERs & related correspondence

7907110458 Forwards LER 79-020/03L-0  
KALIVIANAKIS, N Commonwealth Edison Co 79/06/20 1p

--7907110462 LER 79-020/03L-0 on 790525 quarterly MBIV closure timing  
surveillance performed & MBIV closed in 6-s instead of 3-s  
caused by varied speed control valve adjustment on hydraulic  
cylinder  
CLARK, D Commonwealth Edison Co 79/06/20 3pp

## DOCKETED ITEMS

7907110444 Forwards LER 79-021/03L-0  
KALIVIANAKIS, N Commonwealth Edison Co 79/06/27 1p

--7907110445 LER 79-021/03L-0 on 790601 drywell-to-suppression chamber  
vacuum breaker Div 11 alarm sys breaker found tripped on  
790410 & reported as non-reportable Should be reclassified  
Cause of breaker trip unknown  
VAHRENWALD, J Commonwealth Edison Co 79/06/27 1p

7907250366 Forwards LER 79-022/03L-0  
KALIVIANAKIS, N Commonwealth Edison Co 79/07/13 1p

--7907250378 LER 79-022/03L-0 on 790622 after returning Unit 1 diesel  
generator to svc, following monthly preventive maint insp,  
fuel line leak was discovered Caused by worn gasket on fuel  
line filter Filter gasket replaced  
VAHRENWALD, J Commonwealth Edison Co 79/07/13 1p

DOCKET 50-295 PALISADES NUCLEAR PLANT

A Application/construction stage documents & correspondence

7907030428 Submits offer to provide NRC w/steel & concrete test  
specimens w/protective coating sys presently employed in  
nuclear facilities  
PUSCHEL, M A Consumers Power Co 79/06/27 3pp

F Security, medical, emergency & fire protection plans

7907190415 Submits memo to 790301 Followup to fire protection  
administrative guidelines Audits are performed biennially,  
not biannually Fire protection needs must be identified when  
maint orders submitted  
HOFFMAN, D P Consumers Power Co 79/07/16 1p.

7907300318 Forwards appropriate Class III payment in response to 790703  
request for fees for contingency plans & guard training  
plans.  
FBOO, W O Consumers Power Co 79/07/24 1p

G Adjudicatory correspondence

7907090461 Forwards O Hart 790215 ltr to JM Hendrie re replacement of  
defective steam generators at Surry & JM Hendrie 790313  
response  
BARTH, C A Branch 3 79/05/17 1p.

7907200222 NRC further opposition to petitioners new contentions  
submitted at 790309 prehearing conference Recommends  
issuance of order terminating proceeding. Statement of  
contentions & Certificate of Svc encl  
BARTH, C A Branch 3. 79/05/29 6pp

7907130047 Consumers Power opposition to Great Lakes Energy Alliance  
790309 prehearing conference statement, amended contentions  
& request for financial assistance Certificate of Svc encl  
MILLER, M L, OBBES, M E Isham, Lincoln & Deale 79/05/30 25pp

J Advisory Committee on Reactor Safeguards reports & correspondence

7907110216 Forwards pages from plant operating procedures re addition  
of feedwater to hot dry steam generators Number of  
transients which are acceptable might be explored W/o encl  
BATES, A ACRB - Advisory Committee on Reactor Safeguards 79/05/25  
1p.

Operating license stage documents & correspondence

7906190135 Summary of 790417 meeting w/SEP owner's group in Bethesda, MD  
re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625)  
79/04/30. App.

107180756 Discusses QA for radioactive matl transportation Util will  
use latest version of QA topical rept CPC-1-A for  
radioactive matl transportation & plant operations  
HOFFMAN, D P. Consumers Power Co. 79/05/15 1p

07060498 Forwards request for addl info re radiological assessment  
for review of steam generator repair rept.  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/16.  
App.

37260095 Discusses plans to install communication links between NRC &  
nuclear facilities for emergency use. Direct lines from each  
facility to NRC headquarters & regional ope will communicate  
operational & environ info.  
IEPLER, J. Q. Region 3, Chicago, Office of the Director. 79/05/22  
2pp

7907060217 Forwards Amend 49 to License DPR-20, safety evaluation &  
notice of issuance & availability  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/29  
2pp

--7907060221 Amend 49 to License DPR-20 increasing enrichment limit for  
fuel assemblies in new & spent fuel storage racks  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625)  
79/05/29 5pp

--7907060225 Safety evaluation supporting Amend 49 to License DPR-20  
\* Operating Reactors Branch 2 (Pre 790625) 79/05/29 3pp

--7907060230 Notice of issuance & availability of Amend 49 to License  
DPR-20  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625)  
79/05/29 2pp

7907110637 Confirms 790614-15 site visit of Seismic Review Team  
Proposed agenda, info required for evaluation & Seismic  
Category I electrical instrumentation & mechanical equipment  
qualification encl  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/29  
130pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related  
reevaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907190759 Forwards request for addl info re degraded grid voltage  
in order to continue review of 781002 submittal  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06  
3pp

7907310273 Requests addl info re SEP Topic VI-1, "Organic Matls &  
Post-Accident Chemistry " Forwards list of info needed  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06  
3pp

7907110623 Forwards Category 2 & 3 regulatory positions to be addressed  
in SEP Reg Guide 1 114, Revision 1, encl  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11  
7pp

7907250178 Requests listing of alarms & voltage monitoring devices  
available to provide operability status indication to  
complete evaluation of SEP Topic VII-3 B, "DC Power Sys Bus  
Voltage Monitoring & Annunciation "  
ZIEHMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18  
2pp.

7907120331 Forwards request for change to Tech Specs of License DPR-20,  
re heatup & cooldown curves Class III fee encl Also forwards  
Battelle Columbus Labs rept, "Reactor Vessel Surveillance  
Program Capsule A-240 "  
HOFFMAN, D P Consumers Power Co 79/07/02 1p

--7907120337 Request for change to Tech Specs of License DPR-20, re  
heatup & cooldown curves.  
\* Consumers Power Co 79/07/02 19pp

--7907120344 "Final Rept on Palisades Nuclear Plant Reactor Pressure  
Vessel Surveillance Program Capsule A-240," by Battelle  
Columbus Labs  
\* Consumers Power Co BCL-585-12 79/03/13 90pp.

7907260761 Notification of 790711 meeting w/util in Bethesda, MD to  
discuss SEP Topic III-5 A, "Effects of Pipe Break on  
Structures, Sys & Components Inside Containment "  
JABBODUR, K Systematic Evaluation Programs Branch (Pre 790625).  
79/07/06. 1p

7907190536 Forwards requests for Tech Spec changes.  
HOFFMAN, D P. Consumers Power Co 79/07/16 1p

--7907190550 Requests change to Tech Spec for License DPR-20 Changes made  
within Administration Controls Section, Chapter 6.  
DEWITT, R B. Consumers Power Co 79/07/16 14pp.

7907260727 Forwards list of alarms & voltage monitoring devices  
associated w/Class IE batteries, in response to NRC 790618  
request.  
BIXEL, D. A. Carolina Power & Light Co 79/07/23 4pp

7907310299 Forwards request for amend to Tech Specs to provide std  
method for determining future operating allowances which  
will allow repair efforts to proceed w/o delay during  
refueling outages.  
HOFFMAN, D P Consumers Power Co. 79/07/26. 1p.

# DOCKETED ITEMS

--7907310308 Application for amend to Tech Specs authorizing change from coordinated phosphate to volatile chemistry control for secondary side of steam generators Change will reduce corrosion rate to essentially zero  
DEWITT, R B Consumers Power Co 79/07/26 6pp

7907310432 Submits remainder of info requested in NRC 790925 ltr re feedwater lines design & fabrication history  
HOFFMAN, D P Consumers Power Co 79/07/27 3pp

## G Inspection reports, IE Bulletins & correspondence

7907110715 Supplements 790427 response to IE Bulletin 79-06D Lists disposition of items stated to be resolved by 790518  
HOFFMAN, D P Consumers Power Co 79/05/18 2pp

7907180394 Forwards IE Insp Rept 50-255/79-07 on 790430-0504 & 09-11 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/18 2pp

--7907180411 IE Insp Rept 50-255/79-07 on 790430-0504 & 09-11 No noncompliance noted Major areas inspected licensee response to IE Bulletin 79-06B re operability & availability of engineered safety features & operator training procedures  
JORGENSEN, B L, WRIGHT, G C, WARNICK, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/17 10pp

7907110278 Responds to IE Bulletin 79-10 Forwards requalification training program statistics  
HOFFMAN, D P Consumers Power Co 79/05/23 3pp

7907160234 Responds to IE Bulletin 79-12B re atypical weld matl in reactor pressure vessel welds C-E will submit generic rept before 790608 Util will ref C-E rept in response by 790629 Final response will be submitted by 790731  
BIXEL, D A Consumers Power Co 79/05/29 1p

7907190239 Responds to IE Bulletin 79-12B re atypical weld matl in reactor pressure vessel welds C-E is performing records search & will submit generic rept directly to NRC by 790608  
BIXEL, D A Consumers Power Co 79/05/29 1p

7907200308 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190245 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Bolenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907250206 Forwards IE Insp Rept 50-255/79-06 on 790321-23 & 27-30 & notice of violation  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/06 2pp

--7907250209 Notice of violation from insp on 790321-23 & 27-30  
\* Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/04, 1p

--7907250211 IE Insp Rept 50-255/79-06 on 790321-23 & 27-30 Noncompliance noted, failure to adhere to approved procedure & failure to control access to high radiation areas  
HUETER, L J, OREGON, L R, FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/04 17pp

7907300067 Forwards IE Insp Rept 50-255/79-08 on 790514-16 & 22-23 No noncompliance noted  
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/06 2pp

--7907300071 IE Insp Rept 50-255/79-08 on 790514-16 & 22-23 No noncompliance noted Major areas inspected plant seismic mod, including review of calculation & pipe analysis, installation & insp procedures, QC records & workmanship.  
YIN, E. T. Region 3, Chicago, Office of the Director  
DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/04 7pp

7907190336 Responds to IE Bulletin 79-06B supplementing 790605 response. Submits info concerning containment penetrations & valves  
HOFFMAN, D. P Consumers Power Co 79/06/07 6pp

7907240252 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020423 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120225 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907050445 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907120676 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060310 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907180406 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130262 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240089 Forwards IE Info Notice 79-18, "Skylab Reentry, " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310328 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310406 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260148 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260354 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Boreated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250228 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/07/20 1p

## R Periodic operating reports & related correspondence

7907170178 Forwards monthly operating rept for June 1979  
ADAMS, W E Consumers Power Co 79/07/10 1p.

--7907170181 Monthly operating rept for June 1979  
BODTKE, P J Consumers Power Co 79/07/09 4pp

7907190512 Forwards bimonthly status rept re long-term cooling equipment mod for May-June 1979, W/o encl  
HOFFMAN, D P. Consumers Power Co 79/07/13 1p

## DOCKETED ITEMS

## S Reportable occurrences, LERs &amp; related correspondence

7907030476 Forwards LER 79-024/03L-0  
HOFFMAN, D P Consumers Power Co 79/06/25 1p

--7907030479 LER 79-024/03L-0 on 790608 level in safety injection tank  
fell below Tech Spec limit Caused by annunciation of  
independent level switch Switch adjusted  
\* Consumers Power Co 79/06/25 1p

7907090284 Forwards LER 79-025/01T-0  
HOFFMAN, D P Consumers Power Co 79/07/03 1p

--7907090288 LER 79-025/01T-0 on 790619 during Cycle II heat transfer  
coefficients for component cooling water heat exchangers  
were less than design valves used in FSAR accident analyses  
Caused by tube sides of heat exchangers being fouled  
\* Consumers Power Co 79/07/03 1p

7907100319 Forwards LER 79-026/03L-0  
HOFFMAN, D P Consumers Power Co 79/07/06 1p

--7907100330 LER 79-026/03L-0 on 790604 steam generator chemistry pH  
dropped below Tech Spec min when condensate polishers  
placed in svc Caused by resin leakage from polishers due to  
defective septums Resin mixture changed; chemical feed ended  
\* Consumers Power Co 79/07/06 1p

7907170037 Forwards LER 79-027/03L-0  
HOFFMAN, D P Consumers Power Co 79/07/12 1p

--7907170044 LER 79-027/03L-0 on 790614 during normal power operation,  
conductivity of B steam generator increased to 7.65  
micro/mhos per cm beyond Tech Spec limit Caused by condenser  
in leakage  
\* Consumers Power Co 79/07/12 1p

7907300383 Forwards LER 79-028/03L-0  
HOFFMAN, D P Consumers Power Co 79/07/24 1p.

--7907300398 LER 79-028/03L-0 on 790623 conductivity & sodium  
concentration in steam generator A exceeded Tech Spec  
limits Caused by combination of condenser tube in leakage  
& chemical hideout return as result of power reduction  
\* Consumers Power Co 79/07/24 1p.

## U Congressional/Executive Correspondence

7907260358 Responds to inquiry re effectiveness testing of air masks &  
other protective devices for use at nuclear facilities  
Discusses rules & regulations governing use of respiratory  
devices & programs.  
GOSBICK, C V Office of the Executive Director for Operations  
79/06/07 2pp

--7907260368 Forwards W Watts & M Sinclair ltrs re gas masks for plant  
workers & release of radioactive gas from facility  
RIEDEL, D Senate 79/03/07 3pp

## DOCKET 50-259 BROWN'S FERRY NUCLEAR POWER STATION, UNIT 1

## Q Adjudicatory correspondence

7907100615 Forwards revised pages to 790320 request for reliefs H-9 &  
H-11 re hydrostatic pressure testing proposed  
MILLS, L M Tennessee Valley Authority 79/07/03 3pp.

## P. Operating license stage documents &amp; correspondence

7907060085 Notification of 790601 meeting to discuss containment vent  
& purging Proposed agenda encl  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/05/31 2pp

7907130048 Notification of 790601 meeting w/TVA in Bethesda, MD to  
discuss vent & purging operations; design of vent & purge  
system; qualification of valves & electrical circuitry  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/05/31,  
2pp

7907250018 Forwards NUREG-0364, "Staff Rept on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W" W/O encl.  
GRIMES, B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp.

7907250120 Summary of 790601 meeting w/TVA, BNL & LLL re containment  
purging during operation  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/06/12  
7pp

7907060188 Forwards requested amend to Licenses DPR-33, DPR-52 & DPR-68,  
changing Tech Specs & providing justifications for proposed  
changes re administration, clarification & new organization  
GILLELAND, J E Tennessee Valley Authority 79/06/29 67pp

7907060354 Forwards proposed Tech Specs changes revising App A & B re  
radiological effluents Disputes NRC position that changes  
require submission of Class III fees  
GILLELAND, J E Tennessee Valley Authority 79/06/29 150pp.

--7907060357 Offsite Dose Calculation Manual  
\* Tennessee Valley Authority 79/06/21 86pp

7907110452 Responds to NRC 780119 ltr re suppression pool temp  
transients Forwards suppression pool analysis describing  
temp transients resulting from safety relief valve sticking  
open  
MILLS, L M Tennessee Valley Authority 79/07/02 28pp

7907100599 Forwards revised pages to inservice pump & valve testing  
program, submitted per JE Gilleland 790416 ltr Forwards addl  
request for relief from ASME Section XI code requirement  
MILLS, L M Tennessee Valley Authority 79/07/03 6pp

7907170190 Discusses 790301 ltr re potentially atypical reactor vessel  
weld matl Per B&W 790313 assessment of matl as adequate,  
requests concurrence in shifting 130 F min boltup temp back  
to 100 F  
MILLS, L M Tennessee Valley Authority 79/07/09 1p

7907250272 Discusses util investigation of need for periodic response  
time testing of recirculation pump trip sys Further response  
time testing of pump trip sys at each refueling is  
unnecessary  
MILLS, L M Tennessee Valley Authority 79/07/20 1p

7907260764 Forwards proposed amends to Licenses DPR-33, DPR-52 & DPR-68,  
changing Tech Specs to allow flexibility during refueling  
outage work whenever entire nuclear core is unloaded  
MILLS, L M Tennessee Valley Authority 79/07/20 22pp

--7907260770 Proposed Tech Spec changes to allow flexibility during  
refueling outage work whenever entire nuclear core is  
unloaded  
\* Tennessee Valley Authority 79/07/20 20pp

7907260819 Forwards revised proposed Tech Specs re radiological  
effluents  
MILLS, L M Tennessee Valley Authority 79/07/20 2pp

--7907260828 Revised proposed Tech Specs for Unit 1 re radiological  
effluents  
\* Tennessee Valley Authority 79/07/20 6pp

--7907260838 Revised proposed Tech Specs for Unit 2 re radiological  
effluents  
\* Tennessee Valley Authority 79/07/20 4pp

--7907260854 Revised proposed Tech Specs for Unit 3 re radiological  
effluents  
\* Tennessee Valley Authority 79/07/20 6pp

7907260837 Requests amend to Licenses DPR-33 & DPR-52 revising Tech  
Specs to be consistent w/ASME Section XI inservice pump &  
valve testing program No addl Class III fees necessary  
MILLS, L M Tennessee Valley Authority 79/07/20 2pp.

--7907260843 Proposed revised Tech Specs for Unit 1 re ASME Section XI  
inservice pump & valve testing program.  
\* Tennessee Valley Authority 79/07/20 11pp.

--7907260846 Proposed revised Tech Specs for Unit 2 re ASME Section XI  
inservice pump & valve testing program  
\* Tennessee Valley Authority 79/07/20 11pp

7907270156 Forwards addl revision of ASME Section XI inservice pump &  
valve testing program Requests review.  
MILLS, L M Tennessee Valley Authority 79/07/20 3pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907310155 Forwards IE Insp Repts 50-259/79-09, 50-260/79-09 &  
50-296/79-09 on 790312-15 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support  
Branch 79/03/29 2pp.

--7907310159 Notice of violation from insp on 790312-15  
\* Region 2, Atlanta, Office of the Director 79/03/26 1p

--7907310165 IE Insp Repts 50-259/79-09, 50-260/79-09 & 50-296/79-09  
Noncompliance noted failure to follow QA procedures  
PRICE, D S , DANCE, H C Region 2, Atlanta, Office of the Director 79/03/26 5pp

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
TMI - Suppl " O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 3pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New  
Fuel Assemblies " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907040364 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Licensee  
action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907100179 Responds to IE Bulletin 79-10 Submits table of  
requalification training statistics  
GILLELAND, J E Tennessee Valley Authority 79/05/25 4pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 3pp

7907200206 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907180864 Requests addl analysis of environ qualification of  
stem-mounted light switches, per util response to IE Bulletin  
79-01 Lists criteria to be met if unqualified switches are  
not replaced  
LAINAS, G Plant Systems Branch 79/06/06 2pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907230056 Forwards response to IE Bulletin 79-01 No unprotected  
terminal blocks which must function in post-accident environ  
used in plant ASCO solenoid valves qualified per plant  
equipment design memo  
GILLELAND, J E Tennessee Valley Authority 79/06/11 10pp

7907250165 Requests that Region 2 measurements can be granted access  
privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp

7907230748 Ack receipt of 790523 ltr informing NRC of steps taken to  
correct violation noted in IE Insp Repts 50-259/79-10,  
50-260/79-10 & 50-296/79-10  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support  
Branch 79/06/18 1p

--7907230763 Responds to NRC 790501 ltr re violation noted in IE Insp  
Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 Corrective  
actions reactor cleanup pump locked Door closures & alarms  
will be installed by Sept 1979  
GILLELAND, J E Tennessee Valley Authority 79/05/23 2pp

--7907230775 Forwards IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/  
79-10 on 790305-30 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear  
Support Branch 79/05/01 2pp

--7907230784 Notice of violation from insp on 790305-30  
\* Region 2, Atlanta, Office of the Director 79/05/01 1p

--7907230790 IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 on  
790305-30 Noncompliance noted failure to lock doors to high  
radiation areas  
SULLIVAN, R F Region 2, Atlanta, Office of the Director  
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear  
Support Branch 79/04/27 6pp

7907020393 Forwards IE Info Notice 79-11, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate " O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907110230 Forwards IE Circular 79-09, "Occurrences of Split or  
Punctured Regulator Diaphragms in Certain Self-Contained  
Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 3pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 3pp

7907170058 Forwards proposal for concurrent cycles of inservice insps &  
testing per 10CFR50.55a(g), to reduce unnecessary delays  
MILLS, L M Tennessee Valley Authority 79/07/11 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "   
Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 3pp

R Periodic operating reports & related correspondence

7906220369 Forwards revision to "Environ Radioactivity Levels, Annual  
Rept 1978" to supersede rept issued 790427 Revision corrects  
some radioactive levels Conclusions in original rept are  
still valid  
GILLELAND, J E Tennessee Valley Authority 79/06/18 1p

7907170120 Forwards monthly operating rept for June 1979  
DEWEASE, J O Tennessee Valley Authority 79/07/10 1p

--7907170126 Monthly operating rept for June 1979  
GREEN, D , THOM, T Tennessee Valley Authority 79/07/01 37pp

S Reportable occurrences, LERs & related correspondence

7907110349 LER 78-012 has been voided  
\* Tennessee Valley Authority 79/06/27 1p

7907110352 LER 78-011 has been voided  
\* Tennessee Valley Authority 79/06/27 1p

7907170107 Forwards LER 79-008/03L-0  
FOX, H B Tennessee Valley Authority 79/07/11 1p

## DOCKETED ITEMS

--7907170113 LER 79-008/03L-0 on 790612 during normal operation, pressure switches PS-1-B1 A & B & PS-1-91 A & B setpoints exceeded Tech Specs by 3-15 psig Caused by model B2T-A1258 switches drifting  
\* Tennessee Valley Authority 79/07/11 2pp

## DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

## G Adjudicatory correspondence

7907100615 Forwards revised pages to 790320 request for reliefs H-9 & H-11 re hydrostatic pressure testing proposed  
MILLS,L M Tennessee Valley Authority 79/07/03 3pp

## P Operating license stage documents &amp; correspondence

7907130406 Forwards Amend 46 to License DPR-52, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/05/25 2pp

--7907130411 Amend 46 to License DPR-52 changing Tech Specs to permit facility operation in Cycle 3 following refueling outage  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/05/25 4pp

--7907130418 Safety evaluation supporting Amend 46 to License DPR-52  
\* Office of Nuclear Reactor Regulation 79/05/25 1pp

--7907130421 Notice of issuance & availability of Amend 46 to License DPR-52  
ROONEY, V L Operating Reactors Branch 3 (Pre 790625)  
79/05/25 2pp

7907060085 Notification of 790601 meeting to discuss containment vent & purging Proposed agenda encl  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/05/31 2pp

7907130048 Notification of 790601 meeting w/TVA in Bethesda, MD to discuss vent & purging operations, design of vent & purge sys, qualification of valves & electrical circuitry  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/05/31 2pp

7907250018 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/O encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907250120 Summary of 790601 meeting w/TVA, BNL & LLL re containment purging during operation  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/06/12 7pp

7907060188 Forwards requested amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs & providing justifications for proposed changes re administration, clarification & new organization  
GILLELAND, J E Tennessee Valley Authority 79/06/29 67pp

7907060354 Forwards proposed Tech Specs changes revising App A & B re radiological effluents Disputes NRC position that changes require submission of Class III fees  
GILLELAND, J E Tennessee Valley Authority 79/06/29 190pp

--7907060357 Offsite Dose Calculation Manual  
\* Tennessee Valley Authority 79/06/21 86pp

7907110452 Responds to NRC 780613 ltr re suppression pool temp transients Forwards suppression pool analysis describing temp transients resulting from safety relief valve sticking open  
MILLS,L M Tennessee Valley Authority 79/07/02 28pp

7907100899 Forwards revised pages to inservice pump & valve testing program, submitted per JE Gilleland 790416 ltr Forwards addl request for relief from ASME Section XI code requirement  
MILLS,L M Tennessee Valley Authority 79/07/03 6pp

7907260764 Forwards proposed amends to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to allow flexibility during refueling outage work whenever entire nuclear core is unloaded  
MILLS,L M Tennessee Valley Authority 79/07/20 22pp

--7907260770 Proposed Tech Spec changes to allow flexibility during refueling outage work whenever entire nuclear core is unloaded  
\* Tennessee Valley Authority 79/07/20 20pp

7907260819 Forwards revised proposed Tech Specs re radiological effluents  
MILLS,L M Tennessee Valley Authority 79/07/20 2pp

--7907260838 Revised proposed Tech Specs for Unit 2 re radiological effluents  
\* Tennessee Valley Authority 79/07/20 6pp

7907260837 Requests amend to Licenses DPR-33 & DPR-52 revising Tech Specs to be consistent w/ASME Section XI inservice pump & valve testing program No addl Class III fees necessary  
MILLS,L M Tennessee Valley Authority 79/07/20 2pp

--7907260843 Proposed revised Tech Specs for Unit 1 re ASME Section XI inservice pump & valve testing program  
\* Tennessee Valley Authority 79/07/20 1pp

--7907260846 Proposed revised Tech Specs for Unit 2 re ASME Section XI inservice pump & valve testing program  
\* Tennessee Valley Authority 79/07/20 1pp

7907270156 Forwards addl revision of ASME Section XI inservice pump & valve testing program Requests review  
MILLS,L M Tennessee Valley Authority 79/07/20 3pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907310155 Forwards IE Insp Repts 50-259/79-09, 50-260/79-09 & 50-296/79-09 on 790312-15 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/29 2pp

--7907310159 Notice of violation from insp on 790312-15  
\* Region 2, Atlanta, Office of the Director 79/03/26 1p

--7907310163 IE Insp Repts 50-259/79-09, 50-260/79-09 & 50-296/79-09 Noncompliance noted failure to follow QA procedures  
PRICE, D S, DANCE, H C Region 2, Atlanta, Office of the Director 79/03/26 5pp

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 3pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907060364 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 1p

7907100179 Responds to IE Bulletin 79-10 Submits table of requalification training statistics  
GILLELAND, J E Tennessee Valley Authority 79/05/25 4pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 3pp

7907200206 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907180864 Requests addl analysis of environ qualification of stem-mounted light switches, per util response to IE Bulletin 79-01 Lists criteria to be met if unqualified switches are not replaced.  
LAINAS, G Plant Systems Branch, 79/06/06 2pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 3pp

7907060064 Forwards IE Info Notice 79-1B, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907230056 Forwards response to IE Bulletin 79-01 No unprotected terminal blocks which must function in post-accident environ used in plant ASCO solenoid valves qualified per plant equipment design memo  
GILLELAND, J E Tennessee Valley Authority 79/06/11 10pp

7907230165 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp

7907230748 Ack receipt of 790523 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/18 1p

--7907230763 Responds to NRC 790501 ltr re violation noted in IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 Corrective actions, reactor cleanup pump locked Door closures & alarms will be installed by Sept 1979  
GILLELAND, J E Tennessee Valley Authority 79/05/23 2pp

--7907230775 Forwards IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 on 790305-30 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp

--7907230784 Notice of violation from insp on 790305-30  
\* Region 2, Atlanta, Office of the Director 79/05/01 1p

--7907230790 IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 on 790305-30 Noncompliance noted failure to lock doors to high radiation areas  
SULLIVAN, R F Region 2, Atlanta, Office of the Director  
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/27 6pp

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate,"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20, 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21, 1p

7907110230 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/22, 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25, 3pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28, 3pp.

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02, 3pp

7907170058 Forwards proposal for concurrent cycles of inservice insps & testing per 10CFR50.55a(g), to reduce unnecessary delays.  
HILLS, L M Tennessee Valley Authority 79/07/11 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp.

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 3pp

R Periodic operating reports & related correspondence

7907170120 Forwards monthly operating rept for June 1979  
DEWEASE, J G Tennessee Valley Authority 79/07/10 1p

--7907170126 Monthly operating rept for June 1979  
GREEN, D, THOM, T Tennessee Valley Authority 79/07/01 37pp

B Reportable occurrences, LERs & related correspondence

7907110316 LER 78-012 has been voided  
\* Tennessee Valley Authority 79/06/27 1p

7907110522 LER 78-007 has been voided  
\* Tennessee Valley Authority 79/06/27 1p

7907110525 LER 78-013 has been voided  
\* Tennessee Valley Authority 79/06/27 1p

7907080304 Forwards LER 79-013/03L-0  
FOX, H S Tennessee Valley Authority 79/06/28 1p

--7907050305 LER 79-013/03L-0 on 790530 reactor core isolation cooling tripped on overspeed during flow test w/reactor at rated temp & pressure Loss of speed signal in control room occurred, Caused by malfunction of actuator  
\* Tennessee Valley Authority 79/06/28 2pp

7907090348 Forwards LER 79-016/03L-0  
FOX, H S Tennessee Valley Authority 79/07/03 1p

--7907090356 LER 79-016/03L-0 on 790605 pressure switches PB-1-81A & B & setpoints PB-1-91A & B exceeded Tech Spec limits during test Caused by instrument drift Switches recalibr & tested satisfactorily  
\* Tennessee Valley Authority 79/07/03 1P

\* 7907100479 Forwards LER 79-015/03L-0  
FOX, H S Tennessee Valley Authority 79/07/05 1p

--7907100482 LER 79-015/03L-0 on 790607 HPCI tripped on mechanical overspeed Caused by damaged ball & tappet assembly due to improper setting of trip weight Ball & tappet assembly replaced & trip weight properly set  
\* Tennessee Valley Authority 79/07/05 2pp.

7907180531 Forwards LER 79-017/03L-0  
FOX, H S Tennessee Valley Authority 79/07/12 1p.

--7907180536 LER 79-017/03L-0 on 790615 during normal operation, setpoint on pressure switch PB-3-22B exceeded specified limit Caused by drift in Model B2T-A1288 switch Switch recalibr & satisfactorily tested.  
\* Tennessee Valley Authority, 79/07/12 2pp.

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

0 Adjudicatory correspondence

7907250462 Forwards notes on 790424 conference call.  
LEWIS, B H Branch 2, 79/04/26 1p.

--7907250468 Notes on 790423 conference telcon of NRC, Union Carbide & CP&L re procedures & technical info concerning disposition of proceeding  
LEWIS, B H Branch 2 79/04/23 2pp

790727000B Forwards V Stello 790525 ltr & DV Shaller 790526 memo re cracking of feedwater lines at DC Cook plant.  
CHRISTENBURY, E Hearings Division 79/06/20 1p

--7907270016 Recommends transmittal of V Stello 790525 ltr & DV Shaller 790526 memo to HB Robinson Board.  
STELLO, V Division of Operating Reactors 79/06/08 1p

--7907270023 Informs all PWR licensees that some circumferential throughwall cracks & inside-of-pipe indications occurred at DC Cook, Requests submittal of info on PWR feedwater lines List of info requested encl.  
STELLO, V Division of Operating Reactors, 79/05/25 1p

## DOCKETED ITEMS

7907200228 Order granting Carolina Power & Light 790508 motion to terminate proceeding  
COLE, R F, WOLF, J F Atomic Safety and Licensing Board Panel  
79/06/26 2pp

P Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event  
THADANIL, A Reactor Systems Branch 79/05/02 3pp

7907310579 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSS W/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p

7907130167 Responds to 790427 & 0521 ltrs reporting results of seismic reanalysis of reactor coolant piping using updated version of WESTOYN code which uses absolute sum technique Issue successfully resolved Forwards safety evaluation  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 2pp

--7907130174 Safety evaluation re seismic reanalysis of reactor coolant piping Reanalysis performed w/acceptable computer code & results meet applicable requirements of util SAR  
\* Operating Reactors Branch 1 (Pre 790625) 79/05/22 1p

7907090216 Forwards Amend 3B to License DPR-23, safety evaluation & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/24 2pp

--7907090217 Amend 3B to License DPR-23, deleting pressurizer level as input safety injection actuation & requiring actuation of safety injection based on two out of three channels of low pressurizer pressure  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/24 7pp

--7907090218 Safety evaluation supporting Amend 3B to License DPR-23  
\* Operating Reactors Branch 1 (Pre 790625) 79/05/24 3pp

--7907090221 Notice of issuance & availability of Amend 3B to License DPR-23  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/24 2pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related reevaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907110096 Forwards safety evaluation re mod to safety injection actuation sys  
LAINAS, O Plant Systems Branch 79/06/04 2pp

--7907110106 Safety evaluation supporting mod to safety injection actuation sys  
\* Plant Systems Branch 79/06/04 2pp

7907180899 Forwards request for addl info re degraded grid voltage in order to review util 790124 submittal  
LAINAS, O Plant Systems Branch 79/06/06 3pp

7907180620 Forwards NUREG-0560, "Staff Rpt on Generic Assessment of Feedwater Transients in PWRs Designed by D&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907240539 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907310524 Confirms 790615 telcon re indicated cracking in welds of main feedwater piping sys Requests info re technical evaluation of causes of defects, corrective actions taken to prevent recurrence & sample of defective area  
O'REILLY, J P Region 2, Atlanta, Office of the Director 7/06/15, 1p

0323 RD on 790625 noted that Tech Specs could cause reactor operate in less conservative manner than assumed in analysis Plant operating manual provides safety

V, R D, ROBINSON, H B Carolina Power & Light Co. 79/06/26

7907260533 Notification of 790629 meeting w/util in Bethesda, MD to discuss repair of cracked feedwater lines  
NEJGHBORS, J D Operating Reactors Branch 1 (Pre 790625) 79/06/28 2pp

7907180061 Forwards Amend 39 to License DPR-23 & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/29 2pp

--7907180064 Amend 39 to License DPR-23 revising Tech Specs to increase max power level to 2,300 MW  
GAMMILL, W F Assistant Director for Operating Reactor Projects 79/06/29 20pp

--7907180068 Notice of issuance & availability of Amend 39 to License DPR-23  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/29 3pp

7907060176 Forwards revised pages to requested revision to DL Reflects corporate organizational changes, revised audit frequency of security plan & appropriate Class II amend fee  
UTLEY, E E Carolina Power & Light Co 79/07/02 12pp

7907300141 Summary of 790629 meeting w/util in Bethesda, MD re feedwater piping weld cracks & repair program  
TRAMMELL, C M Operating Reactors Branch 1 (Pre 790625) 79/07/03 16pp

Q Inspection reports, IE Bulletins & correspondence

7907020332 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110314 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907020476 Responds to IE Bulletin 79-09 EQ Type AK-2 circuit breakers not in use or planned for use in safety-related sys  
UTLEY, E E Carolina Power & Light Co 79/05/18 1p

7907100180 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907100217 Responds to IE Bulletin 79-02 Review of records revealed that GC documentation is not available to sufficiently support proper installation of existing expansion anchor bolts  
UTLEY, E E Carolina Power & Light Co 79/05/22 3pp

7907110084 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907240536 Forwards results of preliminary review of licensee responses to IE Bulletins 79-04, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907270048 Forwards IE Insp Rept 50-261/79-08 on 790423-25 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/22 2pp

--7907270053 IE Insp Rept 50-261/79-08 on 790423-25 No noncompliance noted Major areas inspected licensee event followup, IE circulars & notices followup & independent insp effort  
MCHEENRY, T J, DANCE, H C Region 2, Atlanta, Office of the Director, 79/05/21, 4pp

7907300032 Forwards IE Insp Rept 50-261/79-07 on 790430-0503, No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp



--7907300037 IE Insp Rept 50-261/79-07 on 790430-0503 No noncompliance noted Major areas inspected preparation for refueling, refueling, new fuel receipt & testing of anchor bolts in response to IE Bulletin 79-02  
JULIAN, C , MARTIN, R D Region 2, Atlanta, Reactor Operations  
Nuclear Support Branch 79/05/17 3pp

7907030090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/03/29 2pp

7907190111 Responds to IE Bulletin 79-12B re possible atypical weld matl in reactor pressure vessel welds NSSS vendor unable to meet requested schedule Data to be supplied by 790801  
UTLEY, E E Carolina Power & Light Co 79/05/30 1p

7907200165 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190578 Responds to IE Bulletin 79-04 All 3, 4 & 6-inch, 1,500-lb Valan check valves were supplied by Westinghouse No mods are required; valve weights did not increase significantly  
UTLEY, E E Carolina Power & Light Co 79/06/01 4pp

7907190591 Responds to IE Bulletin 79-10 Submits operator requalification statistics  
UTLEY, E E Carolina Power & Light Co 79/06/01 2pp

7907190148 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 1p

7907060043 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907250151 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp.

7907190376 Responds to IE Bulletin 79-01 Transmitter replacement will continue as new units are delivered & plant conditions permit Unable to find any actual testing data on ASCO solenoid valves used in containment  
UTLEY, E E Carolina Power & Light Co 79/06/12 2pp

7907020375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120036 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907160427 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310229 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/02. 1p

7907310362 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

7907190576 Forwards response to IE Bulletin 79-01, originally omitted as encl to 790612 ltr Response available in Central Files only  
UTLEY, E E Carolina Power & Light Co 79/07/16 1p

#### R. Periodic operating reports & related correspondence

7907130431 Forwards monthly operating rept for June 1979.  
BANKS, H R Carolina Power & Light Co. 79/07/09. 1p

--7907130436 Monthly operating rept for June 1979  
WATFORD, M L Carolina Power & Light Co 79/07/03 3pp

#### S Reportable occurrences, LERs & related correspondence

7907100357 Forwards LER 79-01B/3L-0  
BANKS, H R Carolina Power & Light Co 79/07/05 1p

--7907100378 LER 79-01B/3L-0 on 790604 auxiliary feedwater pump motor breaker tripped after pump startup & declared inoperable  
Caused by cracked & broken rotor bars due to excessive start-stop cycling of pump Motor cleaned and rewelded  
STARKEY, R B Carolina Power & Light Co 79/07/05 2pp

7907130348 Forwards LER 79-019/01T-0  
FURR, B J Carolina Power & Light Co 79/07/10 1p

--7907130353 LER 79-019/01T-0 on 790625 determined plant Tech Specs could have permitted reactor operation in manner less conservative than assumed in safety analysis Tech Specs change requested  
STARKEY, R B Carolina Power & Light Co 79/07/10 2pp

7907170020 Forwards summary of util 790627 presentation re investigation of feedwater line cracks & corrective actions  
UTLEY, E E Carolina Power & Light Co 79/07/10 2pp

--7907170026 Summary of util 790627 presentation in feedwater line cracking  
\* Carolina Power & Light Co 79/07/10 12pp

7907240348 Forwards LER 79-020/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/19 1p

--7907240353 LER 79-020/03L-0 on 790625 engine-driven fire pump failed to start during periodic testing Caused by small particles of foreign matl preventing fuel shutoff valve from closing  
fully Matl removed & valve reinstalled  
STARKEY, R B Carolina Power & Light Co 79/07/19 2pp

#### DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

##### G Inspection reports, IE Bulletins & correspondence

7907100251 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020026 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

#### DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

##### F Security, medical, emergency & fire protection plans

7907100618 Forwards revised util fire protection program superseding 790518 revision  
MAYER, L D Northern States Power Co 79/07/05 16pp

7907310381 Forwards supplemental info re physical security plan Plan withheld (ref 10CFR2 790)  
MAYER, L D Northern States Power Co 79/07/30 1p

##### P Operating license stage documents & correspondence

7907050022 Forwards Amend 39 to License DPR-22, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/05/15 2pp

--7907050026 Amend 39 to License DPR-22, permitting mod to low pressure coolant injection subsys pump performance requirements.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625).  
79/05/15 4pp

--7907050028 Safety evaluation supporting Amend 39 to License DPR-22  
\* Office of Nuclear Reactor Regulation. 79/05/15 4pp

--7907050033 Notice of issuance & availability of Amend 39 to License DPR-22  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/05/15 2pp

## DOCKETED ITEMS

- 7907260103 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp
- 7907240414 Ack receipt of 790502 request for info re problems w/diesel engine lube sys & turbochargers bearing damage from lack of lubrication is not unusual. Intends to recommend issuance of IE Circular Supporting correspondence encl.  
CLEMENSON, F Plant Systems Branch 79/05/30 11pp
- 7907110683 Notice of issuance of Amend 40 to License DPR-22, which deletes ref to respiratory protection equipment.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/05 2pp
- 7907240387 Forwards Amend 40 to License DPR-22, safety evaluation & notice of issuance & availability.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/05 2pp
- 7907240392 Amend 40 to License DPR-22 to delete respiratory protection program.  
IPPOLITO, T A Operating Reactors Branch 4 (Pre 790625) 79/06/05 5pp
- 7907240396 Safety evaluation supporting Amend 40 to License DPR-22.  
IPPOLITO, T A Operating Reactors Branch 4 (Pre 790625) 79/06/05 2pp
- 7907240563 Notice of issuance & availability of Amend 40 to License DPR-22.  
IPPOLITO, T A Operating Reactors Branch 4 (Pre 790625) 79/06/05 2pp
- 7907090428 Intends to ship radioactive matl from facilities, using package B3-1.  
HAYER, L D Northern States Power Co 79/06/08 1p
- 7907090432 Notifies that Certificate of Compliance 605B for Model B3-1 expires on 791231. Licensee must request continuation as user.  
MACDONALD, C E Transportation Branch 79/05/16 2pp
- 7907180396 Summary of 790516 meeting w/util & MN Pollution Control Agency in Roseville, MN re spent fuel storage racks.  
KEVERN, T A Operating Reactors Branch 3 (Pre 790625) 79/06/08 2pp
- 7907180647 Forwards NUREG-0540, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl.  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp
- 0 Inspection reports, IE Bulletins & correspondence  
-----
- 7907020346 Submits info in response to IE Bulletin 79-08 No Tech Spec changes identified as result of implementing Items 1-10.  
WACHTER, L J Northern States Power Co 79/05/16 1p
- 7907060250 Responds to IE Bulletin 79-09 65 OE Type AK-2 circuit breakers in use to supply essential motor control ctrs. Many safety sys involved. Items 2, 4 & 6 of svc alert are applicable to all Type AK-2 breakers.  
WACHTER, L J Northern States Power Co 79/05/16 2pp
- 7907100116 Responds to IE Bulletins 78-12, 12A & 12B No deviations found in welding matl used.  
WACHTER, L J Northern States Power Co 79/05/24 2pp
- 7907200326 Forwards IE Bulletin 79-12, "Short Period Strains at BWR Facilities." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p
- 7907130028 Ack recent info re diesel engines manufactured by Electro-Motive Div of General Motors Corp having potential diesel engine turbocharger problem. Believes IE circular would be useful. Draft IE circular encl.  
GRIMES, B Assistant Director for Engineers & Projects (Pre 790625) 79/06/01 5pp
- 7907300274 Forwards IE Insp Rept 50-263/79-07 on 790507-11 Notice of violation withheld (ref 10CFR2 790).  
HIND, J A Region 3, Chicago, Safeguards Branch 79/06/01 2pp
- 7907300285 IE Insp Rept 50-263/79-07 on 790507-11 Noncompliance noted re detection aids, testing & maint & response force Details withheld (ref 10CFR2 790).  
BELANGER, J L, HOWELL, J C, HIND, J A Region 3, Chicago, Safeguards Branch 79/05/25 2pp
- 7907190285 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves)." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p
- 7907240432 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p
- 7907270187 Forwards IE Insp Rept 50-263/79-06 on 790502-03, 08-11 & 15-18 No noncompliance noted.  
HEISHMAN, R F Region 3, Chicago, Office of the Director 79/06/07 2pp
- 7907270133 IE Insp Rept 50-263/79-06 on 790502-03, 08-11 & 15-18 No noncompliance noted. Major areas inspected licensee activities in response to IE Bulletin 79-08, as outlined in util 790501 response.  
HARSTER, T L, KENNINO, J E, WARNICK, R F Region 3, Chicago, Office of the Director 79/06/04 22pp
- 7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils.  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp
- 7907300331 Forwards IE Insp Rept 50-263/79-05 on 790515-18 No noncompliance noted.  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/11 2pp
- 7907300339 IE Insp Rept 50-263/79-05 on 790515-18 No noncompliance noted. Major areas inspected control rod scram time tests, control rod sequence & reactivity checks & core thermal power evaluation.  
CHOW, E T, STREETEY, J F Region 3, Chicago, Office of the Director 79/06/08 5pp
- 7907020435 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p
- 7907120248 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p
- 7907050451 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p
- 7907130136 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p
- 7907060318 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p
- 7907180422 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p
- 7907130282 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p
- 7907240104 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310342 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/11 1p

7907310414 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/13 1p

7907260199 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/18 1p

7907260402 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Bys at PWR Plants " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/18 1p.

#### R Periodic operating reports & related correspondence

7907170001 Forwards monthly operating rept for June 1979  
MAYER, L O Northern States Power Co 79/07/13 1p

--7907170003 Monthly operating rept for June 1979  
MYRABO, A L Northern States Power Co 79/07/05 4pp

#### B Reportable occurrences, LERs & related correspondence

7907300072 Forwards Electro-Motive Div (EMD) notice to owners of EMD engines reporting possible thrust bearing damage which may cause turbocharger failure Suggested IE circular presently in concurrence process Relevant LERs encl  
CLEMENSSEN, F Plant Systems Branch 79/06/01 4pp

7907030340 Forwards LER 79-011/03L-O  
MAYER, L O Northern States Power Co 79/06/28 1p

--7907030344 LER 79-011/03L-O on 790529 no min flow in B train standby gas treatment sys Caused by dilution flow from compressed storage not isolated by BV-5 Replaced positioner & installed filter in cylinder supply/return line  
IVERSON, O N Northern States Power Co 79/06/28 1p

#### DOCKET 50-264 DOW CHEMICAL CO

##### H General correspondence

7907240338 Notifies of two personnel changes to radiation safety committee & TRIGA distribution list  
FARGONS, T W Dow Chemical Co., Dow Chemical U S A Div 79/07/20 1p.

##### G Inspection reports, IE Bulletins & correspondence

7907230424 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/22, 1p

7907310161 Forwards IE Info Notice 79-18, "Bkylab Reentry " No action required.  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/09 1p.

#### DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

##### F. Security, medical, emergency & fire protection plans

7907200381 Submits Classes I & III fees for safeguards contingency plans.  
REED, C Commonwealth Edison Co 79/07/12, 2pp.

7907300330 Forwards Revision 2, interim physical security plan Plan withheld (ref 10CFR2 790).  
REED, C Commonwealth Edison Co. 79/07/23, 1p.

##### Q Adjudicatory correspondence

7907050423 Forwards NRDC annual rept & matls & Citizens for Better Environ matls supporting applicant position re involvement of both organizations in broad environ litigation. Matls provided in response to 790419 memo & order Bvc list encl.  
STEPHENS, P. Isham, Lincoln & Beale. 79/05/03, 51pp.

7907110486 NRDC opposition to NRC motion for reconsideration of ASLB 790419 memo & order following special prehearing conference Certificate of Bvc encl  
ROISMAN, A Z Natural Resources Defense Council 79/05/10 2pp

7907110499 State of IL opposition to NRC 790504 motion & Comm Ed 790507 motion for reconsideration &/or clarification & referral of ASLB 790419 memo & order admitting Contentions 6 & 11  
SEKULER, S N Illinois, State of 79/05/17 6pp

7907200185 NRDC response in opposition to Comm Ed motion for reconsideration or, in alternative, for clarification or referral re adequacy of safeguards for spent fuel shipments Motion is unwarranted & inconsistent w/10CFR73  
ROISMAN, A Z. Natural Resources Defense Council 79/05/22 4pp

--7907200203 NRDC staff scientist re safeguards for spent fuel shipments Proposed rule to protect spent fuel shipments against sabotage, presented in 790429 memo to Commission, is most likely adequate Certificate of Bvc encl  
COCHRAN, T B Natural Resources Defense Council 79/05/18 3pp

##### H General correspondence

7907160298 Four ltrs opposing transportation of 509 radioactive spent fuel rods between facilities  
WIRTH, B Affiliation Unknown 79/05/10 4pp

##### P Operating license stage documents & correspondence

7907260089 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility NRC headquarters & regional o/c will communicate operational & environ info  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/22 2pp

7907310475 Discusses resolution of deterioration problem of Buna-N components in ABCD solenoid valves Response to IE Bulletin 78-14 has been revised to assure replacement of matl in necessary components by 801231  
REED, C Commonwealth Edison Co 79/05/31 3pp

7907250004 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907260445 Summary of 790606 meeting w/util in Bethesda, MD re proposed App I Tech Specs & related matters  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625) 79/06/22, 3pp

7907040305 Submits addl info to 790102 ltr re current commitments to containment purging during normal plant operation Schedule for responding to issues re normal operation purging will be submitted by 790801  
REED, C Commonwealth Edison Co 79/07/02 3pp

7907260031 Summary of 790628 meeting w/util in Bethesda, MD re purging & venting limits & performance of purge & vent valves during postulated LOCA  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/07/02 6pp.

7907130322 Revises 790702 ltr re purging during normal operation No purging at power at Zion will be permitted until purge valves have been analyzed & determined to be capable of closure under DBA  
REED, C Commonwealth Edison Co 79/07/05 1p

7907160294 Forwards responses to NRC comments at 790606 meeting re offsite Dose calculation manual, for NRC review prior to 790716 meeting.  
NAUGHTON, W F Commonwealth Edison Co. 79/07/05 4pp

7907300341 Notification of 790712 meeting w/util in Bethesda, MD to discuss proposed App I Tech Specs  
BEVAN, R B Operating Reactors Branch 3 79/07/06, 2pp.

7907240345 Requests that OE rept NEDE-25090-P, "Analytical Model for T-Guencer Jet Loads on Submerged Structures," submitted 790531, be included in dockets  
JANECEK, R F, Commonwealth Edison Co. 79/07/18 1p.

##### Q. Inspection reports, IE Bulletins & correspondence

7906290493 Responds to IE Bulletin 79-08 Forwards info re review of TMI incident Existing line isolation not important to ECCB injection.  
REED, C Commonwealth Edison Co 79/04/27 22pp

## DOCKETED ITEMS

7907040251 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit breakers in use or planned for use in any safety-related sys  
REED, C Commonwealth Edison Co 79/05/17 2pp

7907180101 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
REED, C Commonwealth Edison Co 79/05/25 7pp

7907200296 Forwards IE Bulletin 79-12 "Short Period Scrums at BWR Facilities " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190230 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures " Forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907310080 Forwards IE Insp Repts 50-254/79-09 & 50-265/79-07 on 790315-16, 21, 22, 0403-05, 18, 19, 23, 24, 27 & 0508 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13 2pp

--7907310086 Notice of violation from insp on 790315-16, 21, 22, 0403-05, 18, 19, 23, 24, 27 & 0508  
\* Region 3, Chicago, Office of the Director 79/06/12 1p

--7907310096 IE Insp Repts 50-254/79-09 & 50-265/79-07 on 790315-16, 21, 22, 0403-05, 18, 19, 23, 24, 27 & 0508 Noncompliance noted automatic function of vacuum breakers not available  
CHRISOTIMOS, N, SPESSARD, R L Region 3, Chicago, Office of the Director 79/06/12 5pp

7907300491 IE Insp Repts 50-254/79-12 & 50-265/79-10 on 790501-24 No noncompliance noted Major areas inspected operator training, safety features, surveillance test procedures & procedures for verification of sys alignment  
CHRISOTIMOS, N, WONG, B M, SPESSARD, R L Region 3, Chicago, Office of the Director 79/06/14 13pp

7907180304 Forwards IE Insp Repts 50-254/79-12 & 50-265/79-10 on 790501-24 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/15 2pp

--7907180455 IE Insp Repts 50-254/79-12 & 50-265/79-10 on 790501-24 No noncompliance noted Major areas inspected licensee response to IE Bulletin 79-08 re TMI implications for BWRs  
CHRISOTIMOS, N, WONG, B M, SPESSARD, R L Region 3, Chicago, Office of the Director 79/06/14 13pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907050441 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
EPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240081 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### R Periodic operating reports & related correspondence

7907240369 Monthly performance rept for May 1979  
HANNUM, D Commonwealth Edison Co 79/05/31 25pp

7907240322 Monthly operating rept for June 1979  
HANNUM, D Commonwealth Edison Co 79/06/30 28pp

#### S Reportable occurrences, LERs & related correspondence

7907250297 Forwards LER 79-011/03L-1  
KALIVIANAKIS, N Commonwealth Edison Co 79/07/05 1p

--7907250313 LER 79-011/03L-1 on 790521 investigation of cable pans found three cables not installed per tabulation drawings Caused by error in cable routing made during metal const Cables to be rerouted during Nov 1979 refueling outage  
WILLEHSEN, B Commonwealth Edison Co 79/05/21 2pp

7907250264 Forwards LER 79-012/03L-0  
KALIVIANAKIS, N Commonwealth Edison Co 79/07/13 1p

--7907250283 LER 79-012/03L-0 on 790622 nut inadvertently dropped into diesel generator winding during preventive maint Outage time of generator extended 20 minutes beyond 1 5-h time limit Caused by personnel error  
VAHRENWALD, J Commonwealth Edison Co 79/06/22 1p

#### DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

#### F Security, medical, emergency & fire protection plans

7907300353 "Fire Protection in Operating Nuclear Power Stations Point Beach Units 1 & 2 SER Review," interim rept  
HALL, R E, MACDOUGALL, E A Brookhaven National Laboratory FIN A-3107 7907300353 79/04/27 4pp

7907130097 Requests addl info re review of safeguards contingency plan transmitted w/790202 ltr details withheld (ref 10CFR2 790)  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/31 2pp

#### P Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utls to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907260110 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907310329 Forwards safety evaluation re util reanalysis of ECCS performance Requirements fulfilled re 79042B order for mod of license  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/04 3pp

--7907310336 Safety evaluation re util reanalysis of ECCS performance operation acceptable w/max of 10% steam generator tubes plugged & peaking factor limit of 2.32  
\* Operating Reactors Branch 1 (Pre 790625) 79/06/04 2pp

7907240564 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250021 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director For Engineers & Projects (Pre 790625) 79/06/11 2pp

7907240479 Notifies of review of util 79072B submittal re TAC 10042 & 10043, degraded grid voltage Forwards request for addl info  
LAINAS, G Plant Systems Branch 79/06/13 3pp

7907310466 Forwards safety evaluation of safety injection actuation sys resulting from mods proposed in response to IE Bulletin 79-06A  
LAINAS, G Plant Systems Branch 79/06/13 2pp

--7907310550 Safety evaluation of safety injection actuation sys submitted in response to IE Bulletin 79-06A, Item-3  
\* Plant Systems Branch 79/06/13 3pp

7907300154 Notification of 790717 meeting w/Intl Brotherhood of Electrical Workers in Two Rivers, WI to discuss NRC requirements w/respect to gatehouse personnel screening & psychological testing  
TRAMMELL, C M Operating Reactors Branch 1 79/07/09 2pp

7907160321 Submits Tech Spec Change Request 59 to amend Licenses DPR-24 & DPR-27 Mods address qualification requirements of Reg Guide 1.6 for radiation protection manager & provide flexibility for plant staffing  
BURSTEIN, B Wisconsin Electric Power Co 79/07/10 4pp

g Inspection reports, IE Bulletins & correspondence

7907240622 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625), 79/05/22 4pp

7907110240 Responds to IE Bulletin 79-10 Forwards info re requalification training of reactor operators & senior operators  
FAY, C W Wisconsin Electric Power Co 79/05/24 3pp

7907130162 Responds to IE Bulletin 78-12, "Atypical Weld Matl in Reaction Pressure Vessel Welds," Forwards Westinghouse rept re B&W rept on welds Final rept re Unit 2 will be forwarded before 790713  
BURSTEIN, B Wisconsin Electric Power Co 79/05/29 4pp

7907250076 Forwards IE Insp Repts 50-266/79-05 & 50-301/79-04 on 790302, 0402-06 & 10-11 & notice of violation.  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/30 2pp

--7907250079 Notice of violation from insp on 790302, 0402-06 & 10-11  
\* Region 3, Chicago, Office of the Director 79/05/29 1p

--7907250083 IE Insp Repts 50-266/79-05 & 50-301/79-04 on 790302, 0402-06 & 10-11 Noncompliance noted failure to log axial flux difference w/flux differences alarm out of svc  
CHOLEB, N C, WARNICK, R F Region 3, Chicago, Office of the Director 79/05/29 9pp

7907200336 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907240144 Forwards IE Insp Repts 50-266/79-06 & 50-301/79-07 on 790303-04 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/01 2pp

--7907240152 IE Insp Repts 50-266/79-06 & 50-301/79-07 on 790303-04 No noncompliance noted Major areas inspected operator awareness re details of TMI event & procedural changes resulting from IE Bulletins 79-06, 06A & 06A, Revision 1  
BOYD, D C, REYES, L A, SPESSARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/29 9pp

7907190296 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240448 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures " forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907300191 Forwards IE Insp Repts 50-266/79-07 & 50-301/79-09 on 790531 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/13 2pp

--7907300194 IE Insp Repts 50-266/79-07 & 50-301/79-09 on 790531 No noncompliance noted Major areas inspected emergency drill, including accident assessment, licensee response, offsite agency response & drill critique  
AKELSON, W L, HIATT, J W, ESSIQ, T H Region 3, Chicago, Office of the Director 79/06/11 3pp

7907020440 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120268 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907050455 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907130165 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping," Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060004 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl," No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/06/26 1p.

7907100526 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p.

7907130297 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240113 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/07/06 1p

## DOCKETED ITEMS

7907310354 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310419 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260220 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260422 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Treated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907300286 Provides addl info to 790423 & OSOR ltr re IE Bulletin 79-07 Confirms that code limits referred to in reanalysis of four safety-related piping lines are same as in final facility description & SAR  
FAY, C W Wisconsin Electric Power Co 79/07/18 1p

#### R Periodic operating reports & related correspondence

7907170160 Forwards monthly operating rept for June 1979  
BURSTEIN, S Wisconsin Electric Power Co 79/07/10 1p

--7907170163 Monthly operating rept for June 1979  
\* Wisconsin Electric Power Co 79/07/05 8pp

#### S Reportable occurrences, LERs & related correspondence

7907250267 Forwards LER 79-010/01T-0  
FAY, C W Wisconsin Electric Power Co 79/07/03 3pp

--7907250277 LER 79-010/01T-0 on 790620 plant safeguards actuation circuitry review indicated need for circuitry changes Caused by changes in IEEE std since plant design Mods to four applicable safeguard circuits will be performed  
BURSTEIN, S Wisconsin Electric Power Co 79/07/03 1p

#### DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

#### P Operating license stage documents & correspondence

7907240445 Notifies that reinsp completed of all specified Class 1 valves in response to AEG Operations Bulletin 79-10 One valve had defective tack weld No further action required List of valves not encl  
FULLER, J K Public Service Co of Colorado 79/05/09 2pp

7907260129 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC Headquarters & regional ofc will communicate operational & environ info  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22 2pp

7907240449 Summary of 790605 meeting w/util in Bethesda, MD re inservice insp program  
KUZHYCZ, G Advanced Reactors Branch 79/06/05 7pp

--7907240456 "Progress Rept on Program to Review Fort St Vrain Inservice Insp & Testing "  
\* Advanced Reactors Branch 79/06/05, 44pp

7907260143 Forwards Amend 21 to License DPR-34 & safety evaluation  
GAMMILL, W P Assistant Director for Standard & Advanced Reactors 79/06/06 2pp

--7907260149 Amend 21 to License DPR-34, modifying fire protection sys to convert interin alternate cooling method to test reactor bldg bouwer sys & eliminating manual isolation of high pressure helium supply  
GAMMILL, W P Assistant Director for Standard & Advanced Reactors 79/06/06 26pp.

--7907260155 Safety evaluation supporting Amend 21 to License DPR-34  
\* Assistant Director for Standard & Advanced Reactors 79/06/06 33pp

7907090214 Accepts extension until 790615 of temporary relief from limiting conditions for Operation 4 3 10  
GAMMILL, W P Assistant Director for Standard & Advanced Reactors 79/06/13 1p

7907030351 Forwards list of outstanding ltrs & requests for Tech Spec changes  
WAREMBOURG, D Public Service Co of Colorado 79/06/26 3pp

7907170156 Submits estimate of time required to complete power ascension program Requests removal of 70% power restraints due to increased peak power demand  
WAREMBOURG, D Public Service Co of Colorado 79/07/09 1p

7907180487 Forwards numerical listing of all correspondence from util to govt regulatory agencies, Dec 1978-June 1979  
WAREMBOURG, D Public Service Co of Colorado 79/07/09 16pp

7907180314 Discusses deferment of use of thorium oxide in future reload segments Requests that thorium oxide review be suspended  
FISHER, C R General Atomic Co (subs of Gulf Oil Corp) 79/07/12 1p

7907200264 Forwards Rise-to-Power Test Program RT-50B, Revision 3 Purpose of test was to define instrumentation & instrumentation utilization methods for fluctuation testing under Test RT 500E  
WAREMBOURG, D Public Service Co of Colorado 79/07/12 1p

--7907200267 "Rise to power test program, RT-50B, Revision 3 "  
\* Public Service Co of Colorado RT-50B 79/07/09 24pp

7907250332 Forwards memo of agreement between State of CO & EPA re operation of NPDES & associated federal regulations  
ALEXANDER, D R Public Service Co of Colorado 79/07/18 15pp

7907050142 Forwards IE Insp Rept 50-267/79-07 on 790402-06 No noncompliance noted  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/26 2pp

--7907050146 IE Insp Rept 50-267/79-07 on 790402-06 No noncompliance noted Major areas inspected calibr specified by Tech Specs, plant operations & followup on unresolved problems identified by inspector  
DICKERSON, M W, VERDUZCO, G H, WESTERMAN, T F Region 4, Dallas, Office of the Director 79/04/20 8pp

7907050165 Forwards IE Insp Rept 50-267/79-08 on 790416-20 No noncompliance noted  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/05/01 2pp

--7907050168 IE Insp Rept 50-267/79-08 on 790416-20 No noncompliance noted Major areas inspected Facility mod, surveillance & review of special repts  
DICKERSON, M W, WESTERMAN, T F Region 4, Dallas, Office of the Director 79/05/01 6pp

7907260166 Responds to IE Bulletin 79-04 One 6-inch Velan check valve found in emergency condensate line to Loop 1 steam generators Conservative seismic analysis rate provides adequate safety margin  
FULLER, J K Public Service Co of Colorado 79/05/04 2pp

7907100293 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/05/18 1p

7907060329 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22 1p

7907190699 Responds to IE Bulletin 79-09 OE Type AK-2 circuit breakers not installed in safety-related sys  
MILLEN, C K Public Service Co of Colorado. 79/05/22 1p

7907190707 Responds to IE Bulletin 79-10 re requalification training program statistics Forwards operator examination info  
MILLEN, C K Public Service Co of Colorado 79/05/23 3pp

7907200363 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31 1p

7907270110 Forwards IE Insp Rept 50-267/79-10 on 790514-18 No noncompliance noted  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/05 2pp

--7907270118 IE Insp Rept 50-267/79-10 on 790514-19 No noncompliance noted Major areas inspected procedures, plant operations, Followup on previous items of noncompliance & Followup on inspector identified unresolved items  
DICKERSON, M W, WESTERMAN, T F Region 4, Dallas, Office of the Director 79/06/01 7pp

7907190408 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06 1p

7907300103 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/73-04  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/06 1p

--7907300116 Responds to NRC 730703 ltr re violations noted in IE Insp Rept 50-267/73-04 Corrective actions encl corrosion monitoring program was established  
FULLER, J K Public Service Co of Colorado 79/05/23 17pp

7907060022 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07 1p

7907020446 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20 1p

7907120377 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21 1p

7907060015 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907120586 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25 1p

7907100398 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26 1p

7907180385 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28 1p

7907270385 Forwards IE Insp Rept 50-267/79-09 on 790514-17 No noncompliance noted Rept withheld (ref 10CFR2 790)  
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch, 79/07/02 1p

7907310217 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02 1p

7907190506 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11 1p

7907240405 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13, 1p

7907260334 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/17, 1p

7907260242 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18 1p

#### R Periodic operating reports & related correspondence

7907060212 Forwards monthly operating rept for May 1979  
WAREMBOURG, D Public Service Co of Colorado 79/06/29 1p

--7907060229 Monthly operating rept for May 1979  
GAHM, J W Public Service Co of Colorado 79/06/01 8pp

7907120101 Forwards monthly operating rept for June 1979  
WAREMBOURG, D Public Service Co of Colorado 79/07/05 1p

--7907120106 Monthly operating rept for June 1979  
GAHM, J W Public Service Co of Colorado 79/07/01 6pp

#### S Reportable occurrences, LERs & related correspondence

7907030254 Forwards PNO-79-67A8, "Nuclear Incident at TMI "  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/31 1p

7907020301 Forwards PNO-79-67AR  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/05 1p

7907030183 Forwards PNO-79-67A8  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/13 1p

7907030226 Forwards PNO-79-67AT, "Nuclear Incident at TMI "  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/19 1p

7907130330 Forwards PNO-79-67AU  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/27 1p

7907120632 Forwards RD 50-267/79-13/03-L-O & LER 79-013/03L-O  
WAREMBOURG, D Public Service Co of Colorado 79/07/03 1p

--7907120638 RD 50-267/79-13/03-L-O on 790412 365 hydraulic snubbers found to be inoperable during first functional test, causing both unacceptable lockup & bleed characteristics Caused by setpoint drift, dirty oil & clogged valves All repaired  
FROST, R R Public Service Co of Colorado 79/07/03 3pp

--7907120643 LER 79-013/03L-O on 790412 during test of snubbers many found inoperable due to unacceptable lockup & bleed characteristics Caused by setpoint drift, dirty oil & clogged valves All snubbers repaired & adjusted  
GAHM, J W Public Service Co of Colorado 79/07/03 1p

7907130388 Forwards LER 79-017/01T-O  
WAREMBOURG, D Public Service Co of Colorado 79/07/10 1p

--7907130391 LER 79-017/01T-O on 790626 fault current trip occurred, causing reactor scram & interrupted reactor cooling Caused by water spray in switchgear, resulting in short circuit due to voltage perturbation  
GAHM, J W Public Service Co of Colorado 79/07/10 8pp

7907180677 Forwards PNO-79-67AV & AM  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch, 79/07/10 1p

7907180442 Forwards RD 50-267/76-19A  
WAREMBOURG, D Public Service Co of Colorado, 79/07/12 1p

--7907180444 RD 50-267/76-19A on 760617 while reactor was in shutdown condition, one steam water dump valve in each loop opened Caused by design problem Failure modes & effects analyzed & steam water dump circuits revised  
GAHM, J W Public Service Co. of Colorado, 79/07/12 7pp

7907180568 Forwards RD 50-267/77-17(14)1, final.  
WAREMBOURG, D Public Service Co of Colorado 79/07/12 1p

--7907180575 RD 50-267/77-17(14)1, final on 770806 during plant startup at 15% power, incorrect feedwater flow trip existed in 1 of 2 plant protective sys logics Caused by logic chip failure in circular trip module CT-282  
GAHM, J W Public Service Co of Colorado, 79/07/12 6pp,

## DOCKETED ITEMS

- DOCKET 50-249 DUCHE NUCLEAR STATION, UNIT 1  
F Security, medical, emergency & fire protection plans
- 7907050312 Advises that some mods required by fire protection safety evaluation will not be completed by 790701 Submits schedule of current status of mods  
PARKER, W D Duke Power Co 79/05/29 3pp
- 7907190223 Forwards license fee for 790223 safeguards contingency plan  
submittal  
PARKER, W D Duke Power Co 79/07/13 1p
- G Adjudicatory correspondence
- 7907050475 Denies util petition for reconsideration of Commission 790707 order re shutdown of facilities Petition is moot re timing of shutdown  
CHILK, S J Office of the Secretary of the Commission 79/05/18 1p
- 7907070431 Denies request for immediate plant shutdown & revocation of OLS Copy of decision encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p
- 7907070440 Decision denying request by Palmetto Alliance for immediate shutdown of facility & revocation of OLS  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 2pp
- 7907070445 Requests immediate shutdown of facility & revocation of OLS  
HELF, B Palmetto Alliance 79/04/27 1p
- H General correspondence
- 7907060454 Notifies of 790425 review of inner cavity measurement for NAC-1B fuel shipping case  
WHITENEM, H L Region 2, Atlanta, Office of the Director 79/05/09 3pp
- P Operating license stage documents & correspondence
- 7901170158 Forwards rept "B&W 177 Fuel Assembly Owner's Group Asymmetric LOCA Loads Evaluation Program, Phase 2"  
PARKER, W D Duke Power Co 79/01/11 1p
- 7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation Pressurizer level info request list encl  
SHEMANSKI, P Division of Project Management 79/04/19 2pp
- 7907120742 Forwards util 790425 ltr re augmented auxiliary feedwater provisions  
MATTHEW, R J Division of Systems Safety 79/04/26 1p
- 7907140361 Forwards consensus of 790501 meeting re extrapolated conclusions for Rancho Seco & proposed changes to Oconee order  
ROSS, D Systematic Evaluation Programs Branch (Pre 790625) 79/05/02 30pp
- 7907100200 Forwards Duke Power Co ltr indicating planned changes in response to TMI-2 events & IE Bulletins  
BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/08 1p
- 7907060448 Summarizes 790503-07 trip rept Emergency feedwater test & NAC-1 fuel shipment case measurements observed  
HARDIN, A K Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 3pp
- 7907020312 Requests util demonstrate acceptable flow rates & flow stability w/two operating steam-driven emergency feedwater pumps Seeks development of Tech Specs for limiting conditions Safety evaluation & FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/18 4pp
- 7907020316 Evaluation of licensee compliance w/NRC 790507 790507 order  
Office of Nuclear Reactor Regulation 79/05/18 23pp
- 7907020319 Notice of authorization to resume operation  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/18 3pp
- 7907310235 Evaluation of util compliance w/NRC 790507 order Util has documented actions taken in response to order Util must provide schedule of long-term mods Operation of plant may resume  
\* Office of Nuclear Reactor Regulation 79/05/18 23pp
- 7906260196 Summary of 790518 briefing in Washington, DC re decisions concerning restart when sufficient number of operators complete simulator training  
CHILK, S J Office of the Secretary of the Commission 79/06/04 1p
- 7906260292 Summary of 790507 affirmation session in Washington, DC re proposed orders to shut down facility Orders approved which add safety changes to feedwater transients  
CHILK, S J Office of the Secretary of the Commission 79/05/08 1p
- 7907110114 Forwards safety evaluation supporting util application for OLS amend to increase authorized capacity of spent fuel pool  
LAINAS, G Plant Systems Branch 79/06/04 2pp
- 7907110121 Safety evaluation supporting util application for amend to OLS to increase authorized capacity of spent fuel pool  
\* Division of Operating Reactors 79/06/04 3pp
- 7907250007 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp
- 7907300573 Submits info rept re imminent issuance of spent fuel pool capacity increase Due to contractual commitments, economic penalties may be imposed upon util if work does not begin by 790818 NRC to issue license amend by 790618  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/15 1p
- 7907250589 Forwards Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation, EIA & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/19 2pp
- 7907250595 Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55, respectively, changing common Tech Specs to allow increase in spent fuel storage capacity from 336 to 750 fuel assemblies in Units 1 & 2 common spent fuel pool  
GRIMES, B K Operating Reactors Branch 4 (Pre 790625) 79/06/19 12pp
- 7907250600 Safety evaluation supporting Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/19 13pp
- 7907250601 EIA re mod of spent fuel pool  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/19 27pp
- 7907250606 Notice of issuance & availability of Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/19 2pp
- 7907230495 Forwards Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22 3pp
- 7907230502 Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to support operation at full-rated power during Cycle 5  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22 32pp
- 7907230517 Safety evaluation supporting Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/22 7pp
- 7907230532 Notice of issuance & availability of Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22 2pp
- 7907200211 Forwards notice of issuance of Amends 73, 73 & 70 to DPR-38, DPR-47 & DPR-55, respectively.  
INGRAM, R Operating Reactors Branch 4 (Pre 790625) 79/06/28 1p



# DOCKETED ITEMS

- 7907200224 Notice of issuance of Amends 73, 73 & 70 to DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs re core reload & power level cutoff  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22 2pp
- 7907190335 Submits check for 790321 license amend application Amend concerns qualifications of site health physicist  
PARKER, W O Duke Power Co 79/07/13 1p
- 7907260734 Forwards addl info re proposed license amend permitting unmonitored individuals in area surrounding Warehouse 4 for unlimited periods of time  
PARKER, W O Duke Power Co 79/07/17 4pp
- 7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
GEISLER, G O Babcock & Wilcox Co 79/07/20 2pp
- 7907300311 Discusses Phase 2 of multiphase program to evaluate effects of asymmetric LOCA loads in conjunction w/B&W 177 fuel assembly owners' group Program is in response to NRC 780125 ltr described Phase 2 of program  
PARKER, W O Duke Power Co 79/07/23 1p
- 0 Inspection reports, IE Bulletins & correspondence  
-----
- 7907160072 Comments on licensee 790410 response to IE Bulletins 79-05 & 05A  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/10 3pp
- 7907020065 Forwards IE site inspector daily repts of B&W reactors for 790419  
DAVIS, J O Office of Inspection & Enforcement 79/04/20 1p
- 7907020072 B&W site inspector daily rept on 790419 Plant status no major engineering safety feature sys equipment out of svc  
Discussed plant supervisor shift logs  
JAPE, F Region 2, Atlanta, Office of the Director 79/04/19 1p
- 7907020108 B&W site inspector daily rept on 790416 Plant status all reactors operating at nearly full power No major maint & all engineering safety feature equipment operational  
BELIBL, G A, MOON, B T Region 2, Atlanta, Office of the Director 79/04/16 2pp
- 7907020139 B&W site inspector daily rept on 790418 Plant status reactor at full power w/no major engineering safety feature equipment out of svc No major maint scheduled  
JAPE, F Region 2, Atlanta, Office of the Director 79/04/18 1p
- 7907160023 Forwards IE Region 2 evaluation of licensee response to IE Bulletin 79-05A  
VARQA, S A Light Water Reactors Branch 4 79/04/19 1p
- 7907160030 Comments on licensee 790413 response to IE Bulletins 79-05 & 05A  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/19 2pp
- 7907020349 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp
- 7907110319 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp
- 7906200115 Ack receipt of IE Insp Rept 50-269/79-20 on 790327-29 No proprietary info  
PARKER, W O Duke Power Co 79/05/14 1p
- 7906200120 Forwards IE Insp Rept 50-269/79-20 on 790327-29, No noncompliance noted.  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 2pp
- 7906200127 IE Insp Rept 50-369/79-20 on 790327-29 No noncompliance noted Major areas inspected preoperational test procedure & preliminary preoperational test results  
DYER, J A, WEBBMAN, R H Region 2, Atlanta, Office of the Director  
MARTIN, R D Region 2, Atlanta, Safeguards Branch 79/04/20 3pp
- 7907050277 Forwards proposed amend to DL in response to IE Bulletin 79-05B Proposed revision reflects changes to setpoints of pressurizer electromagnetic relief valve & RCB high pressure trip  
PARKER, W O Duke Power Co 79/05/21 1pp
- 7907110627 Forwards response to Items 5 & 7 of IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl" N/A encl  
PARKER, W O Duke Power Co 79/05/21 1p
- 7907110095 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp
- 7907100106 Responds to IE Bulletin 79-10 Submits table of requalification training program statistics  
PARKER, W O Duke Power Co 79/05/25 3pp
- 7907030093 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/27 2pp
- 7907180883 Responds to IE Bulletin 79-04 Review of all Seismic Category I piping sys determined that 1,500 psi Velan check valves installed in 3-inch discharge line of each HPI pump Reanalysis of affected piping initiated  
PARKER, W O Duke Power Co 79/05/30 2pp
- 7907200186 Forwards IE Bulletin 79-12, "Short Period Scrams at DWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp
- 7907110574 Ack receipt of 790524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/04 1p
- 7907110579 Responds to NRC 790430 ltr re violations noted in IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 Corrective actions new calibr technique has been approved & space efficiency factors determined for swipe detectors  
PARKER, W O Duke Power Co 79/05/24 3pp
- 7907110583 Forwards IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 on 790314-15 & notice of violation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 2pp
- 7907110590 Notice of violation from insp on 790314-15  
\* Region 2, Atlanta, Office of the Director 79/04/24 2pp
- 7907110596 IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 on 790314-15 Noncompliance noted Failure to follow calibr procedure & failure to use proper calibr source  
MONTGOMERY, D M, GIBSON, Q T, HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/24, 4pp
- 7907190409 Responds to IE Bulletin 79-01 B&W notified util that operator for valve ZHR-20 did not meet environ qualification requirements Cold shutdown executed to replace valve  
PARKER, W O Duke Power Co 79/06/03 2pp
- 7907190153 Forwards suppl IE Bulletin 79-01A, "Environment Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Bolandoid Valves)" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp
- 7907100161 Forwards IE Info Notice 79-15  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/06/07 2pp
- 7907250155 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp
- 7907020382 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/06/20 1p

## DOCKETED ITEMS

- 7907260550 Act receipt of IE Insp Repts 90-269/79-12, 90-270/79-12 & 90-287/79-12 No proprietary info  
PARKER, W O Duke Power Co 79/06/20 1p
- 7907120061 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p
- 7907110217 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p
- 7907310009 Forwards IE Bulletin 79-12, "Cracking in Feedwater Sys Piping " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp
- 7907110263 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/26 2pp
- 7907180597 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp
- 7907310234 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp
- 7907310369 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p
- 7907200245 Forwards revised pages of inservice insp program, adding request for relief for full-stroke testing valves LP-29 & 30 & modifying request for relief for valve HP-20  
PARKER, W O Duke Power Co 79/07/16 6pp
- R Periodic operating reports & related correspondence
- 7907180476 Forwards monthly operating rpt for June 1979  
PARKER, W O Duke Power Co 79/07/13 1p
- 7907180481 Monthly operating rpt for June 1979  
REAVIS, L A Duke Power Co 79/07/13 6pp
- S Reportable occurrences, LERs & related correspondence
- 7907110537 Forwards LER 78-011/01T-0 Implications of event apply to all three units  
PARKER, W O Duke Power Co 78/04/21 2pp
- 7907110540 LER 78-011/01T-0 on 780412 during ECCS small break analysis, B&W discovered that worst case small break location of newer generation plants differed from Oconee plants due to analytical error Cause unknown Procedures changed  
WILSON, K R Duke Power Co 78/04/26 1p
- 7907110552 Forwards RO 78-011 re ECCS analysis at pump suction of reactor coolant piping  
PARKER, W O Duke Power Co 78/04/26 1p
- 7907110560 RO 78-011 ECCS analysis of 0.04 square ft break revealed that break occurring at pump discharge would be more limiting if assumed that HPI pump is available for core cooling Results indicate core is always covered by fluid  
PARKER, W O Duke Power Co 78/04/14 2pp
- 7907110546 Forwards LER 78-012/03L-0 Implications of event apply to all three units  
PARKER, W O Duke Power Co 78/03/19 1p
- 7907110557 LER 78-012/03L-0 on 780417 instrumented relay in Keowee Unit 2 field flashing breaker trip circuitry activated Cause possibly due to spurious trip signal Corrective actions include monitoring of field flash breaker circuitry  
WILSON, K R Duke Power Co 78/05/19 3pp
- 7110376 Forwards LER 78-014/03L-0  
PARKER, W O Duke Power Co 78/06/08 1p
- 7907110393 LER 78-014/03L-0 on 780425 between 780425-0515, field flashing breaker failed to operate properly Caused by malfunctioning breaker Breaker replaced  
WILSON, K R Duke Power Co 78/06/08, 8pp
- 7907110576 Forwards LER 78-018/03L-0  
PARKER, W O Duke Power Co 78/09/19 1p
- 7907110582 LER 78-018/03L-0 on 780818 quadrant power tilt in excess of error-corrected limit of 2.24% Cause is unknown, still under investigation  
WILSON, K R Duke Power Co 78/09/19 3pp
- 7907110543 LER 78-008 has been voided  
Duke Power Co 79/06/27 1p
- 7907090262 Forwards LER 79-016/03L-0  
PARKER, W O Duke Power Co 79/07/02 1p
- 7907090266 LER 79-016/03L-0 on 790602 water leaked from high pressure svc pump 8 motor cooler Caused by faulty joint connecting cooler supply line to motor cooling tubing Joint resoldered & coolers to be replaced  
LEWIS, B R Duke Power Co 79/07/02 3pp
- 7907170159 Forwards LER 79-017/03L-0  
PARKER, W O Duke Power Co 79/07/13 3pp
- 7907170165 LER 79-017/03L-0 on 790614, steam generator sample line penetration isolation valve failed to indicate closure when cycled during performance of stroke test Caused by defective limit switch Valve closed to ensure isolation if required.  
LEWIS, B R Duke Power Co 79/07/13 1p
- 7907180485 Forwards LER 79-018/03L-0.  
PARKER, W O Duke Power Co 79/07/13 1p
- 7907180488 LER 79-018/03L-0 on 790615 containment isolation valve on monitors inlet line failed to close, rendering gaseous radiation monitors inoperable Caused by valve shaft binding Valve diaphragm, bonnet assembly & torque switch replaced  
LEWIS, B R Duke Power Co 79/07/13, 3pp
- 7907230359 Forwards LER 79-019/03L-0.  
PARKER, W O Duke Power Co 79/07/17 1p.
- 7907230363 LER 79-019/03L-0 on 790617 quadrant power tilt for two quadrants exceeded error-adjusted steady state limit. Caused by slight cold leg temp mismatch Startup level control will be monitored during next startup.  
LEWIS, B R Duke Power Co 79/07/17 1p.
- 7907240290 Notifies that two potentially malfunctioning valves noted in RO 269/78-27 were examined 790629 & found in proper working condition Valves no longer in use due to mods  
PARKER, W O Duke Power Co 79/07/18 1p.
- 7907240322 Informs that RO-269/79-21 re leak from low pressure injection cooler, due 790718, is still under investigation & will be submitted by 790730,  
PARKER, W O Duke Power Co 79/07/18, 1p.
- V Operator Examinations
- 7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 780101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20 2pp
- 7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp
- DOCKET 90-270 OCONEE NUCLEAR STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 7907050312 Advises that some mods required by fire protection safety evaluation will not be completed by 790701 Submits schedule of current status of mods.  
PARKER, W O Duke Power Co 79/06/29 3pp
- 7907190228 Forwards license fee for 790323 safeguards contingency plan submittal  
PARKER, W O Duke Power Co 79/07/13, 1p

# DOCKETED ITEMS

6

## Q Adjudicatory correspondence

7907020475 Denies util petition for reconsideration of Commission  
790507 order re shutdown of facilities Petition is moot re  
timing of shutdown  
CHELKS, S J Office of the Secretary of the Commission 79/05/18  
1p

7907090431 Denies request for immediate plant shutdown & revocation of  
OLs Copy of decision encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907090440 Decision denying request by Palmetto Alliance for immediate  
shutdown of facility & revocation of OLs  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 2pp

--7907090445 Requests immediate shutdown of facility & revocation of  
OLs  
HOLT, B Palmetto Alliance 79/04/27 1p

## P Operating license stage documents & correspondence

7907020442 Submits list of B&W licensees who have provided info on  
pressurizer level instrumentation Pressurizer level info  
request list encl  
SHEMANSKI, P Division of Project Management 79/04/19 2pp

7907120742 Forwards util 790425 ltr re augmented auxiliary  
feedwater provisions  
MATTSON, R J Division of Systems Safety 79/04/26 1p

7907160361 Forwards consensus of 790501 meeting re extrapolated  
conclusions for Rancho Seco & proposed changes to Dconee  
order  
ROSS, D Systematic Evaluation Programs Branch (Pre 790625)  
79/05/02 30pp

7907100200 Forwards Duke Power Co ltrs indicating planned changes in  
response to TMI-2 events & IE Bulletins  
BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/08  
1p

7907060448 Summarizes 790503-07 trip rept Emergency feedwater test  
& MAC-1 fuel shipment cask measurements observed  
HARDIN, A K Region 2, Atlanta, Reactor Operations Nuclear Support  
Branch 79/05/10 3pp

7907020312 Requests util demonstrate acceptable flow rates & flow  
stability w/two operating steam-driven emergency feedwater  
pumps Beeks development of Tech Specs for limiting  
conditions Safety evaluation & FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/18 4pp

--7907020316 Evaluation of licensee compliance w/NRC 790507 790507 order  
\* Office of Nuclear Reactor Regulation 79/05/18 23pp

--7907020319 Notice of authorization to resume operation  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/18  
3pp

79070310235 Evaluation of util compliance w/NRC 790507 order Util has  
documented actions taken in response to order Util must  
provide schedule of long-term mods. Operation of plant may  
resume  
\* Office of Nuclear Reactor Regulation 79/05/18 23pp

7907110114 Forwards safety evaluation supporting util application for  
OL amend to increase authorized capacity of spent fuel pool  
LAINAS, G Plant Systems Branch, 79/06/04 2pp

--7907110121 Safety evaluation supporting util application for amend to  
OL to increase authorized capacity of spent fuel pool  
\* Division of Operating Reactors 79/06/04 5pp

7907250007 Forwards NUREG-0560: "Staff Rept on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W" W/o encl.  
GRIMES, B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp

7907300573 Submits info rept re imminent issuance of spent fuel pool  
capacity increase Due to contractual commitments, economic  
penalties may be imposed upon util if work does not begin  
by 790618, NRC to issue license amend by 790618  
DENTON, H R Office of Nuclear Reactor Regulation, 79/06/15 1p.

7907250589 Forwards Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 &  
DPR-55, respectively, safety evaluation, EIA & notice of  
issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/19  
2pp

--7907250595 Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55,  
respectively, changing common Tech Specs to allow increase in  
spent fuel storage capacity from 336 to 750 fuel assemblies  
in Units 1 & 2 common spent fuel pool  
GRIMES, B K Operating Reactors Branch 4 (Pre 790625)  
79/06/19 12pp

--7907250600 Safety evaluation supporting Amends 72, 72 & 69 to Licenses  
DPR-38, DPR-47 & DPR-55, respectively  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/19 13pp

--7907250601 EIA re mod of spent fuel pool  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/19 27pp

--7907250606 Notice of issuance & availability of Amends 72, 72 & 69 to  
Licenses DPR-38, DPR-47 & DPR-55, respectively  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/19  
2pp

7907230495 Forwards Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 &  
DPR-55, respectively, safety evaluation & notice of issuance  
& availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22  
3pp

--7907230502 Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55,  
respectively, revising Tech Specs to support operation at  
full-rated power during Cycle 5  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22  
52pp

--7907230517 Safety evaluation supporting Amends 73, 73 & 70 to Licenses  
DPR-38, DPR-47 & DPR-55, respectively  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/22 7pp

--7907230532 Notice of issuance & availability of Amends 73, 73 & 70 to  
Licenses DPR-38, DPR-47 & DPR-55, respectively  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22  
2pp

7907200211 Forwards notice of issuance of Amends 73, 73 & 70 to DPR-38,  
DPR-47 & DPR-55, respectively  
INGRAM, R Operating Reactors Branch 4 (Pre 790625) 79/06/28  
1p

--7907200224 Notice of issuance of Amends 73, 73 & 70 to DPR-38, DPR-47 &  
DPR-55, respectively, revising Tech Specs re core reload &  
power level cutoff  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22  
2pp

7907190535 Submits check for 790321 license amend application Amend  
concerns qualifications of site health physicist  
PARKER, W D Duke Power Co 79/07/13 1p

7907260734 Forwards addl info re proposed license amend permitting  
unmonitored individuals in area surrounding Warehouse 4 for  
unlimited periods of time  
PARKER, W D Duke Power Co 79/07/17 4pp.

7907270182 Forwards form ltr to B&W operating plants re revised  
operating guidelines in event of engineered safety features  
sys actuation caused by low reactor coolant pressure  
OEIBSLER, G D Babcock & Wilcox Co 79/07/20 2pp

7907300311 Discusses Phase 2 of multiphase program to evaluate effects  
of asymmetric LOCA loads in conjunction w/B&W 177 fuel  
assembly owners' group. Program is in response to NRC 780125  
ltr described Phase 2 of program  
PARKER, W. D. Duke Power Co, 79/07/23, 1p.

## Q Inspection reports, IE Bulletins & correspondence

7907160072 Comments on licensee 790410 response to IE Bulletins 79-05 &  
05A  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support  
Branch 79/04/10, 3pp.

7907020065 Forwards IE site inspector daily repts of B&W reactors for  
790419  
DAVIS, J. Q. Office of Inspection & Enforcement, 79/04/20, 1p.

## DOCKETED ITEMS

-7907020072 B&W site inspector daily rept on 790419 Plant status no major engineering safety feature sys equipment out of svc  
Discussed plant supervisor shift logs  
JAPE.F Region 2, Atlanta, Office of the Director 79/04/19 1p

7907020108 B&W site inspector daily rept on 790416 Plant status all reactors operating at nearly full power No major maint & all engineering safety feature equipment operational  
BELISLE, G A , MODN, B T Region 2, Atlanta, Office of the Director 79/04/16 2pp

7907020139 B&W site inspector daily rept on 790418 Plant status reactor at full power w/no major engineering safety feature equipment out of svc No major maint scheduled  
JAPE.F Region 2, Atlanta, Office of the Director 79/04/18 1p

7907140023 Forwards IE Region 2 evaluation of licensee response to IE Bulletin 79-05A  
VARON, B A Light Water Reactors Branch 4 79/04/19 1p

--7907160030 Comments on licensee 790413 response to IE Bulletins 79-05 & 05A  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/19 2pp

7907020349 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110319 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907050277 Forwards proposed amend to OL in response to IE Bulletin 79-05B Proposed revision reflects changes to setpoints of pressurizer electromagnetic relief valve & RCS high pressure trip  
PARKER, W D Duke Power Co 79/05/21 11pp

7907110627 Forwards response to Items 5 & 7 of IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl" W/o encl  
PARKER, W D Duke Power Co 79/05/21 1p

7907110095 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907100106 Responds to IE Bulletin 79-10 Submits table of requalification training program statistics  
PARKER, W D Duke Power Co 79/05/25 3pp

7907030073 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907180883 Responds to IE Bulletin 79-04 Review of all Seismic Category 1 piping sys determined that 1,500 psi Volan check valves installed in 3-inch discharge line of each HPI pump  
Reanalysis of affected piping initiated  
PARKER, W D Duke Power Co 79/05/30 2pp

7907200186 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907110574 Ack receipt of 790524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/04 1p

--7907110579 Responds to NRC 790430 ltr re violations noted in IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08. Corrective actions: new calibr technique has been approved & space efficiency factors determined for guipe detectors  
PARKER, W D Duke Power Co 79/05/24 3pp.

7110583 Forwards IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 on 790314-13 & notice of violation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30, 2pp

--7907110590 Notice of violation from insp on 790314-13  
\* Region 2, Atlanta, Office of the Director 79/04/24 2pp

--7907110596 IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 on 790314-13 Noncompliance noted failure to follow calibr procedure & failure to use proper calibr source  
MONTGOMERY, D M , GIBSON, G T , HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/24 4pp

7907190409 Responds to IE Bulletin 79-01 B&W notified util that operator for valve 2HP-20 did not meet environ qualification requirements Cold shutdown executed to replace valve  
PARKER, W D Duke Power Co 79/06/05 2pp

7907190133 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp

7907100161 Forwards IE Info Notice 79-15  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907230155 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp

7907020382 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907260350 Ack receipt of IE Insp Repts 50-269/79-12, 50-270/79-12 & 50-287/79-12 No proprietary info  
PARKER, W D Duke Power Co 79/06/20 1p

7907120061 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110217 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907310009 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 2pp

7907110263 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907180597 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907310234 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp

7907310369 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 1p

7907200245 Forwards revised pages of inservice insp program, adding request for relief for full-stroke testing valves LP-29 & 30 & modifying request for relief for valve HP-20  
PARKER, W D Duke Power Co 79/07/16 6pp

R Periodic operating reports & related correspondence

7907180476 Forwards monthly operating rept for June 1979  
PARKER, W D Duke Power Co 79/07/13 1p

--7907180481 Monthly operating rept for June 1979  
REAVIE, L A Duke Power Co 79/07/13, 4pp.

## B Reportable occurrences, LERs &amp; related correspondence

7907110537 Forwards LER 78-011/01T-0 Implications of event apply to all three units  
PARKER, W O Duke Power Co 78/04/21 2pp

7907110552 Forwards RD 78-011 re ECCB analysis at pump suction of reactor coolant piping  
PARKER, W O Duke Power Co 78/04/26 1p

--7907110560 RD 78-011 ECCB analysis of O 04 square ft break revealed that break occurring at pump discharge would be more limiting if assumed that HPI pump is available for core cooling Results indicate core is always covered by fluid  
PARKER, W O Duke Power Co 78/04/14 2pp

7907110448 Forwards LER 78-005/03L-0  
PARKER, W O Duke Power Co 78/05/01 1p

--7907110450 LER 78-005/03L-0 on 780401 during normal operation observed that narrow-range pressure indications differed by more than 0.6 psig Caused by pressure transmitter being of caliber due to amplifier drift Amplifier replaced  
WILSON, K R Duke Power Co 78/05/01 2pp

7907110546 Forwards LER 78-012/03L-0 Implications of event apply to all three units  
PARKER, W O Duke Power Co 78/05/19 1p

7907110376 Forwards LER 78-014/03L-0  
PARKER, W O Duke Power Co 78/06/08 1p

--7907110393 LER 78-014/03L-0 on 780425 between 780425-0515, field flashing breaker failed to operate properly Caused by malfunctioning breaker Breaker replaced  
WILSON, K R Duke Power Co 78/06/08 8pp

7907180502 Forwards LER 79-004/03L-0  
PARKER, W O Duke Power Co 79/07/13 1p

--7907180505 LER 79-004/03L-0 on 790615 RCS leakage observed & unit shut down for repairs Caused by leak on packing on pressurizer spray control bypass valve Valve was backseated & leakage terminated  
LEWIS, S R Duke Power Co 79/07/13 3pp

## V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 780101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20 2pp

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp

## DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

## F Security, medical, emergency &amp; fire protection plans

7907170230 Submits results of discussions & agreements reached re fire protection sys changes in lieu of installing guard piping on fuel line, will install curb in diesel fire pump area  
MOODY, D E Vermont Yankee Nuclear Power Corp 79/06/11 1p

7907170149 Requests extension for installation of fire barrier penetration seals until end of 1980 refueling outage Evaluation of different products on market is time-consuming  
MOODY, D E Vermont Yankee Nuclear Power Corp 79/07/11 2pp

## Q Adjudicatory correspondence

7907050539 Endorses reopening record before ABLB to answer questions re indefinite storage of spent fuel per DC Court of Appeals 790523 decision  
WEISS, E. R. Sheldon, Harman & Roisman 79/05/29 2pp

## P Operating license stage documents &amp; correspondence

7907060087 Notifies licensee of change in NRC procedure, making IE Region 1 responsible for technical review of util latest submittal for plan, formal correspondence & issuance of safety evaluation rest w/Div of Operating Reactors  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/05/08 2pp

7907260077 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907060127 Responds to 790515 TUX request NRC will send notification prior to approval of any abnormal operating procedures due to employee strike at facility  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/05/23 2pp

7907180663 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PHWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907030375 Responds to request for submittal of Class III fee for licensing review of Proposed Change 74, Suppl 1 Unable to respond to request until review & resolution of issue is settled  
JOHNSON, W P Vermont Yankee Nuclear Power Corp 79/06/28 1p

7907120372 Submits info re feedwater & control rod drive return line nozzle insp plans for Sept 1979 refueling outage  
GRUCE, R H Vermont Yankee Nuclear Power Corp 79/07/05 4pp

7907170009 Forwards "Treatment of Cooling Water w/Sodium Hypochlorite " GRUCE, R H Vermont Yankee Nuclear Power Corp 79/07/10 1p

--7907170013 "Treatment of Cooling Water w/Sodium Hypochlorite," May 1973 \* Vermont Yankee Nuclear Power Corp 73/05/31 28pp

7907310434 Forwards Class III payment to cover review costs of security contingency plan Fee submitted under protest due: NRC-revised fee schedule considered illegal  
GRUCE, R H Vermont Yankee Nuclear Power Corp 79/07/25 1p

7907300305 Submits info requested in 780807 ltr re reactor protection sys power supply QE has conducted failure modes & effects analysis & seismic performance evaluation test & concluded risk of failure is low No more studies & mods required  
MOODY, D E Vermont Yankee Nuclear Power Corp 79/07/27 2pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907310023 Forwards summary of 790306 meeting w/util in King of Prussia, PA Info presented resulted in withdrawal of Item D from 781222 notice of violation  
SMITH, O H Region 1, Philadelphia, Office of the Director 79/05/02 2pp

--7907310027 Summary of 790306 meeting w/util in King of Prussia, PA re 781222 notice of violation Item 50-029/78-19-07 will be withdrawn  
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/06 2pp

7907020455 Submits response to Item II of IE Bulletin 79-08 No Tech Spec changes submitted at this time  
MOODY, D E Vermont Yankee Nuclear Power Corp 79/05/18 1p

7907060433 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907050255 Forwards response to IE Bulletin 79-10 re reactor operator training  
MOODY, D E Vermont Yankee Nuclear Power Corp 79/05/25 3pp

7907030077 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200133 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190119 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Bolonoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060139 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907110394 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230712 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240208 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907120584 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907100379 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907030373 Forwards corrected page 1 to table of contents of inservice insp program submitted on 790625  
ORDCE, R H Vermont Yankee Nuclear Power Corp 79/06/28 2pp

7907100512 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180831 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907250529 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

7907270371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310544 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R Periodic operating reports & related correspondence

7907170148 Forwards monthly operating rept for June 1979  
MODDY, D E Vermont Yankee Nuclear Power Corp 79/07/12 1p.

--7907170152 Monthly operating rept for June 1979  
BJOGREN, R M Vermont Yankee Nuclear Power Corp 79/07/12 7pp

#### S Reportable occurrences, LERs & related correspondence

7907260595 Forwards LER 79-012/03L-0  
CONWAY, W F Vermont Yankee Nuclear Power Corp. 79/07/23 1p

7907260599 LER 79-012/03L-0 on 790622 during weekly review of completed surveillance data, discovered that weekly functional test of main steam line radiation monitors was not done within prescribed intervals caused by oversight  
CONWAY, W F Vermont Yankee Nuclear Power Corp 79/07/23 2pp

DOCKET 30-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

D NRC Draft/Final Environmental Statements, suppl's & correspondence

7907110319 Discusses 790525 approval of 316(b) plan of study re environ Plan has been updated as required Agrees to participate in Quarter progress meetings Proposes delay of Emergency Response Team discussion to Jul 1979 meeting  
SHIBBIA, J A Public Service Electric & Gas Co of New Jersey  
79/07/01 22pp

#### Q Adjudicatory correspondence

7907050080 Notifies text of 790413 limited appearance has been placed in public record  
MILMOLLIN, G L Atomic Safety and Licensing Board Panel 79/05/15 1p

--7907050086 Submits limited appearance written testimony opposing approval of amend for increasing storage of spent fuel assemblies  
DIERNARD, M Utility Users for Reasonable Rates 79/04/13 5pp

7907100715 Requests info re follow-up testimony re seismic concerns  
LEWIS, M I Environmental Coalition on Nuclear Power 79/05/19 1p

7907180401 Requests extension to file testimony on NRC 790601 objection to part of Question 3 re explosion or meltdown Seeks extension until 30 days after final disposition on 790601 objection Certificate of Svc encl.  
BHITH, B H, MOORE, J E Branch 2 79/06/08 4pp

7907180573 Forwards brief of intervenors Colemans opposing NRC 790601 objection to ASLB consideration of Class 9 accidents States of NJ & DE join consolidated opposition to NRC position Requests oral argument on matter  
GNSBORFF, K A New Jersey, State of 79/06/14 1p

--7907180585 Request for denial of NRC 790601 objection to ASLB consideration of Class 9 accidents submitted by intervenors States of NJ & DE & Colemans Class 9 accidents are legitimate safety concern, germane to admitted contentions  
GNSBORFF, K A New Jersey, State of 79/06/14 10pp

7907180476 Request submitted by intervenor Lower Alloways Creek that ASLB grant extension until 790626 to file response to NRC 790601 objection to ASLB question Affidavits of RN McAllister & SE Donaldson & Certificate of Svc encl  
MCALLISTER, R N Valore, C 79/06/15 7pp

7907180481 Forwards testimony of EA Gulbransen on behalf of intervenor Township of Lower Alloways Creek Responds to Questions 1-3 of ASLB 79041B order re storage of spent fuel pools at reactor sites  
VALORE, C Valore, C 79/06/15 2pp

--7907180687 Testimony of EA Gulbransen re Questions 1-3 of ASLB 79041B order Storage of spent fuel pools at reactor sites involves large amounts of radioactive matl in event of serious nuclear accident Certificate of Svc encl  
GULBRANSEN, E A Affiliation Unknown 79/06/15 36pp

7907060471 Supports NRC 790601 objection to ASLB 79041B consideration of Question 3 re explosion & meltdown Supports NRC 790612 motion for extension of 30 days to file testimony re final disposition Certificate of Svc encl  
WETTERHAHN, M J Conner, Moore & Corber 79/06/18 29pp

7907260388 Responds to 790531 ltr re status of spent fuel proceeding Notice of hearing was published in 780208 FR Issues involve alternatives to proposed expansion & ability of matl to maintain integrity during design life.  
GOSBICK, L V Office of the Executive Director for Operations  
79/06/18 2pp.

--7907260390 Requests detailed rept on status of spent fuel proceeding w/supporting documentation Expansion of waste storage site poses threat to health & safety of population Comprehensive matl storage program is necessary  
DUPONT, P B Delaware, State of. 79/05/31 1p

--7907260396 Notice of intent to prepare EIS on handling & storage of spent LWR fuel.  
CHILK, B J. Office of the Secretary of the Commission. 79/09/19. 3pp

--7907260403 Affidavit of GQ Zech re intervenor Township of Lower Alloways Creek Contention 1. Possibility of disposing of spent fuel outside US is nonexistent.  
ZECH, G Q. Operating Reactors Branch 1 79/03/30 2pp

--7907260412 Affidavit of JR Weeks re Colemans contentions Boral matl will continue to maintain properties of radioactivity control throughout 40-yr design life of spent fuel pool WEEKS, J R Brookhaven National Laboratory 79/03/29 5pp

--7907260431 Forwards SCR & EIS re 77111B 1tr SCHWENCER, A Operating Reactors Branch 1 79/01/15 2pp

7907130309 Forwards util response to ASLB 790418 questions Question 1 has been withdrawn by ASLB & objection taken to second part of Question 3 Matl specs of fuel are proprietary to Westinghouse Elec Corp Affidavit of TO Eckhart encl WETTERHAHN, M J Conner, Moore & Corber 79/06/19 3pp

--7907130314 Answer submitted by util to ASLB 790418 questions re impact of TMI type incident on spent fuel pool Question 1 has been withdrawn & objection taken to second part of Question 3 Postulated series of events could not occur at plant WETTERHAHN, M J Conner, Moore & Corber 79/06/19 4pp

--7907130319 Rebuttal testimony of R L Mittl reconsideration of alternatives Describes function of licensing & environ dept, roles of depts re expansion of spent fuel pool & alternatives considered by util MITTL, R L Public Service Electric & Gas Co of New Jersey 79/06/19 9pp

7907180667 No objection to intervenor Township of Lower Alloways Creek 790611 motion for extension to respond to NRC objection to ASLB question Certificate of Bvc encl HITH, B H Branch 2 79/06/20 3pp

7907240231 Response by intervenor Township of Lower Alloways Creek to NRC 790601 objection to ASLB 790418 Question 3 Question concerns extent of explosion on spent fuel pool Objection should be overruled Certificate of Bvc encl VALORE, C Valore, C 79/06/25 6pp

7907240239 Request that ASLB reconsider Contention 7 submitted by intervenor Colemans ASLB order would comply w/mandate in MN vs NRC re storage of radwaste beyond term of OL Supports brief support of motion ONSDORFF, K A New Jersey, State of 79/06/25 2pp

--7907240243 Brief in support of motion for reconsideration of Contention 7 submitted by intervenors Colemans ASLB order would comply w/mandate in MN vs NRC re storage of radwaste beyond term of OL Certificate of Bvc encl ONSDORFF, K A New Jersey, State of 79/06/25 15pp.

7907240342 Request that ASLB compel util to supplement answers to Interrogatories 1, 3 & 6 submitted by intervenor Colemans Weeks rept re safety & refueling cycle Brief is forwarded in support of motion ONSDORFF, K A New Jersey, State of 79/06/26 1p

--7907240390 Brief by intervenor Colemans in support of request that ASLB compel util to suppl answers to Interrogatories 1, 3 & 6 ASLB has responsibility to determine significance of facts re issues in controversy ONSDORFF, K A New Jersey, State of 79/06/26 5pp

7907240361 Notice of reconstitution of ASLB PJ Shon replaces L Kornblith LAZO, R M Atomic Safety and Licensing Board Panel 79/06/27 1p

7907240255 Forwards util objection to intervenor Lower Alloways Creek Township testimony. Also forwards utils outline of cross-examination Filings are one day late WETTERHAHN, M J Conner, Moore & Corber 79/06/30 1p

--7907240283 Objections submitted by util to intervenor Lower Alloways Creek Township 790425 testimony re ASLB 790418 questions Oulbransen & R Webb testimony is beyond scope of order & issues in proceeding & should not be heard. WETTERHAHN, M J Conner, Moore & Corber 79/06/30 7pp

--7907240291 Outline of util cross-examination of R Webb & Oulbransen testimony on behalf of intervenor Lower Alloways Creek Township Matl will be used to extent 790630 objections to testimony are overruled Certificate of Bvc encl WETTERHAHN, M J Conner, Moore & Corber 79/06/30 6pp

#### H. General correspondence

7907250037 Ack receipt of 790322 1tr submitting Board Resolution 79-109, "Resolution Opposing Storage of High Level Radioactive Wastes in Salem County." Renacking & Increased storage are safe & acceptable. DENTON, H R Office of Nuclear Reactor Regulation 79/05/15 5pp

--7907250039 Forwards Board Resolution 79-109, "Resolution Opposing Storage of High Level Radioactive Wastes in Salem County," adopted by Board of Chosen Freeholders of County of Salem at regular meeting on 790321 AYRES, G W Salem County Board of Chosen Freeholders 79/03/22 3pp

#### P Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310594 Forwards NRC 790515 1tr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NBSS w/o encl SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p

7907260071 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info ORTER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907190674 Summary of 790525 meeting w/util & Westinghouse re damage observed to fuel grid assemblies during refueling outage ZECH, G O Operating Reactors Branch 1 (Pre 790625) 79/05/30 5pp

7907110571 Notice of issuance of license Amend 16, which revises Tech Specs re moderator temp coefficient, range of condenser outlet temp detectors & Type C containment isolation valve leakage tests SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/01 3pp

7907310177 Forwards Amend 16 to License DPR-70, safety evaluation & notice of issuance & availability SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/01 2pp

--7907310183 Amend 16 to License DPR-70, clarifying moderator temp coefficient specs, reducing required range of condenser outlet temp detectors & authorizing removal of part-length control rods SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/01 50pp

--7907310187 Safety evaluation supporting Amend 16 to License DPR-70 \* Operating Reactors Branch 1 (Pre 790625) 79/06/01 10pp

--7907310196 Notice of issuance & availability of Amend 16 to License DPR-70, SCHWENCER, A Operating Reactors Branch 1 79/06/01 3pp

7907240589 Forwards Amend 17 to License DPR-70 & safety evaluation SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/07 2pp

--7907240597 Amend 17 to License DPR-70, changing Tech Specs to require actuation of safety injection based on two-out-of-three channels of low pressurizer pressure SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/07 12pp.

--7907240603 Safety evaluation supporting Amend 17 to License DPR-70 \* Operating Reactors Branch 1 (Pre 790625) 79/06/07 3pp

7907180659 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907240556 Forwards NRC 790604 1tr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp.

7907110402 Submits addl info re PWR feedwater lines, in response to 790525 request. SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 79/07/02 17pp.

7907260022 Notification of 790717 meeting w/util in Bethesda, MD to discuss damage observed to fuel spacer grid & control rod assemblies during refueling outage ROBB, W J Operating Reactors Branch 1 (Pre 790625) 79/07/06 2pp

## DOCKETED ITEMS

## Q Inspection reports, IE Bulletins &amp; correspondence

7907230549 Forwards IE Insp Repts 50-272/79-06 & 50-311/79-14 on 790218-0324 & notice of violation  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/27 2pp

--7907230557 Notice of violation from insp on 790218-0324  
\* Region 1, Philadelphia, Office of the Director 79/04/27 1p

--7907230570 IE Insp Repts 50-272/79-06 & 50-311/79-14 on 790218-0324 Noncompliance noted failure to perform surveillance of rod position indication w/deviation alarm inoperable  
KEJMI0, R R, HORNHOLM, L J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/27 9pp

7907110534 Forwards IE Insp Repts 50-272/79-10 & 50-311/79-20 on 790320-22 & 27-28 No noncompliance noted  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/10 2pp

--7907110544 IE Insp Repts 50-272/79-10 & 50-311/79-22 on 790320-20 & 27-28 No noncompliance noted Major areas inspected containment integrated leak rate test procedure, pipe supports & restraints & refueling preparations  
SMITH, T H, KALMAN, O, CAPHTON, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/04 10pp

790200 Requests extension for response to IE Bulletin 79-06A to 790331 Response involves possible change to Tech Specs & dentifying design changes Facility currently out of svc for refueling  
CHNEIDER, F W Public Service Electric & Gas Co of New Jersey 9/05/11 1p

790456 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers st in use or planned for use  
CHNEIDER, F W Public Service Electric & Gas Co of New Jersey 7/05/15 1p

7907060428 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 7/05/22 1p

7904613 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting owners of operating plants having Westinghouse-designed & scheduled for 790530 in Bethesda, MD  
HWEINER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 1p

030064 Forwards IE Info Notice 79-13, "Indication of Low Water level in Oyster Creek Reactor " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 7/05/29 1p

300144 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Mixtures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 7/05/31 1p

90104 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of ss IE Equipment (Deficiencies in Environ Qualification of O Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 7/06/06 1p

060126 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 7/06/07 1p

180203 Notification of 790517 meeting w/util in Bethesda, MD to discuss licensee response to IE Bulletin 79-07 re seismic sign of safety-related sys at facility & future schedules  
submittal of supplemental info  
I, O Q Operating Reactors Branch 1 (Pre 790625) 79/06/13

0478 Forwards IE Info Notice 79-17, "Source Holder Assembly e from Misfit Between Assembly & Reactor Upper Grid  
\*  
\* B H Region 1, Philadelphia, Office of the Director 7/20 1p

7907230704 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907240202 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p

7907120539 Forwards IE Bulletin 79-13, "Cracking in Feedwater Gas Piping " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100367 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100508 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180814 Forwards IE Bulletin 79-14, "Seismic Analysis for As Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907250522 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p

7907270363 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310533 Forwards IE Circular 79-13, "Replacement of Diesel fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

## R Periodic operating reports &amp; related correspondence

7907170227 Impingement Monitoring Program Rept 26 for May 1979  
\* Public Service Electric & Gas Co of New Jersey 79/06/20 62pp

7907170226 Forwards Impingement Monitoring Program Rept 26 for May 1979  
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 79/06/20 1p

7907160307 Forwards monthly operating rept for June 1979  
MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/07/10 1p

--7907160311 Monthly operating rept for June 1979  
MILLER, L K Public Service Electric & Gas Co of New Jersey 79/07/10 10pp

## S Reportable occurrences, LERs &amp; related correspondence

7907090213 RO 79-46/01P on 790614 radiographic insp of steam generator 13 feed nozzle to pipe weld revealed linear indication 5 inches in length Detailed rept to be submitted  
MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/06/15 1p

7907050301 Forwards LER 79-046/01T-0  
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 79/06/28 1p

--7907050302 LER 79-046/01T-0 on 790614 during refueling outage, linear indications discovered in weld areas of all steam generators Cause presently unknown Corrective action will be initiated when investigation results are evaluated  
KAPPLER, A W Public Service Electric & Gas Co of New Jersey 79/06/28 2pp

7907090276 Forwards LER 79-047/03L-0  
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 79/06/30 1p



--7907090277 LER 79-047/03L-O on 790531 during refueling core shuffle, six control rod spider fingers affecting eight control rodlets found to be broken Cause to be determined Twenty-five rods in rod cluster control assembly replaced  
KAPPLE, A W Public Service Electric & Gas Co of New Jersey  
79/06/30 2pp

7907260582 Forwards LER 79-04B/01T-O  
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey  
79/07/20 1p

--7907260586 LER 79-04B/01T-O on 790709 during normal maint operations, significant wear marks found on tubes adjacent to tube lane blocking devices Caused by movement of blocking devices Steam adjacent to blocking devices were plugged  
KAPPLE, A W Public Service Electric & Gas Co of New Jersey  
79/07/20 3pp

7907260713 Forwards LER 79-050/01T-O  
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey  
79/07/20 2pp

--7907260724 LER 79-050/01T-O on 790710 notified by Westinghouse that reactor trip & auxiliary feedwater indication based on low-low steam generator water level could be delayed in event of main feedline rupture inside containment  
KAPPLE, A W Public Service Electric & Gas Co of New Jersey  
79/07/20 1p

7907270160 LER 79-033 has been voided  
\* Public Service Electric & Gas Co of New Jersey 79/07/20 1p

7907270168 LER 79-028 has been voided  
\* Public Service Electric & Gas Co of New Jersey 79/07/20 1p

7907310364 Forwards LER 79-049/01T-O  
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey  
79/07/24 1p

--7907310372 LER 79-049/01T-O on 790710 during refueling outage, insp of pipe support concrete anchors showed 9% needed replacement Cause to be determined when test results are evaluated Design change 1EC-593 made to correct deficiencies  
KAPPLE, A W Public Service Electric & Gas Co of New Jersey  
79/07/24 2pp

#### U Congressional/Executive Correspondence

7907180696 Responds to 790507 ltr re facilities in light of accident at TMI Forwards actions taken at facilities as result of TMI incident  
HENDRIE, J M Commission 79/06/28 3pp

--7907180713 Requests thorough insp of facilities in light of accident at TMI Requests info re exact steps being taken to guard against TMI type accident at facilities  
ROTH, W V Senate 79/05/07 1p

#### DOCKET 50-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR

#### G Inspection reports, IE Bulletins & correspondence

7907100248 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020018 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus"  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907230439 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907310610 Forwards IE Info Notice 79-18, "Bkylab Reentry" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06 1p

#### DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

#### A Application/construction stage documents & correspondence

7907160109 Draft memo re licensing strategy for plants w/fuel load dates in CY79  
BOYD, R S Division of Project Management 79/03/28 6pp

7907100691 Responds to 790317 ltr re earthquake potential & existence of Hosgri fault CP could be issued based on current seismic criteria Some parts of plant do not provide degree of safety currently required Discusses waste disposal & exposures  
BOYD, R S Division of Project Management 79/05/18 6pp

7907090206 Submits addl info requested in NRC 790516 ltr re high voltage penetration, thermal cycling, fault current protection for containment penetrations, fire protection program & inservice testing OE 790605 ltr to util  
FURBUSH, M H Pacific Gas & Electric Co 79/07/02 9pp

7907230242 Notifies that requested info for review of corporate capabilities will be submitted by 790730 Info requested in Sections I & II B of NRC 790629 ltr will be submitted upon completion  
CRANE, P A Pacific Gas & Electric Co 79/07/16 1p

#### F Security, medical, emergency & fire protection plans

7907240234 Clarifies statement in 790702 ltr re Item 6 fire protection program Intends to comply w/Section 5 c 2 of Branch Tech Position ASD 9 5-1, Revision 1 re surveillance of control & sectionalizing valves in firewater sys  
CRANE, P A Pacific Gas & Electric Co 79/07/18 1p

7907260643 Forwards summaries of recent plant mods, including mod identified in SER Suppl B, fire protection mod according to fire zones, other commitments not in SER Suppl B & mods different from those listed in SER Suppl B  
CRANE, P A Pacific Gas & Electric Co 79/07/20 19pp

#### G Adjudicatory correspondence

7907130496 Submits addl correction to proposed findings of fact & conclusions of law  
CRANE, P A Pacific Gas & Electric Co 79/05/07 1p

7907160075 Responds to Joint Intervenor's 790509 request to ASLB Motion to reopen should be deferred pending completion of NRC rept on TMI Seeks denial of request for certification of certain legal issues re Class 9 accidents Certificate of Svc encl  
DAVIS, L D Anti-Trust Division 79/05/24 6pp

7907060144 Responds to 790504 ltr to JM Hendrie which requested moratorium on licensing of facility NRC is evaluating TMI accident extensively No new reactor licenses will be issued until evaluation is complete  
GOSBICK, L V Office of the Executive Director for Operations 79/05/30 2pp

--7907060149 Urges suspension of OL proceeding until TMI accident is investigated, emergency preparedness completed & seismic design bolstered  
BRDWN, E G California, State of 79/05/04 3pp

7907130110 Util request for denial of Joint Intervenor's 790509 motion for ASLB to reopen record re emergency plans & for directed certification. Both requests require regulation & mods through inappropriate procedures Certificate of Svc encl  
NORTON, B Bruce Norton MORRISSEY, J C Pacific Gas & Electric Co, GEHR, A C, Snell & Wilmer 79/06/01 13pp

--7907130118 Comments on EQ Brown, Governor of CA, 790511 ltr requesting suspension of licensing proceedings No indication of need for substantial changes in design or operating procedures  
BONNER, J F Pacific Gas & Electric Co 79/05/11 2pp

7907130347 Motion by San Luis Obispo Mothers for Peace for copy of security plan, discovery schedule for examination of plan & for hearings to determine adequacy of plan Certificate of Svc encl  
BALDWIN, W A San Luis Obispo Mothers for Peace 79/06/08 8pp

7907200235 Opposes intervenors San Luis Obispo Mothers for Peace 790608 request that ASLB reopen record re security plan Intervenor's waived right to participate in security hearings & have not shown good cause to reopen issue, w/Certificate of Svc  
DAVIS, L D Branch 4 79/06/28 10pp

## DOCKETED ITEMS

## H General correspondence

7907120333 Responds to 740511 ltr to JM Hendrie expressing concern re Governor Brown request for moratorium on issuing OL New safety requirements arising from TMI investigation will be applied to all plants where applicable  
BOYD, R S Division of Project Management 79/06/14 2pp

--7907120349 Responds to 790504 ltr to JM Hendrie re moratorium on licensing plants until TMI evaluation is complete, no new licenses will be issued ASLB will consider testimony re adequacy of plant to withstand earthquakes  
OOSBICK, L V Office of the Executive Director for Operations 79/05/30 2pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907160243 Reviews Westinghouse rept, "Qualification Testing of Barton Pressure & Differential Pressure Transmitters"  
SAYTERFIELD, R Electric, Instrumentation & Control Systems Branch 79/04/17 1p

7907190381 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breaker not used or planned for use  
CRANE, P A Pacific Gas & Electric Co 79/05/15 1p

7907270140 Forwards IE Insp Repts 50-275/79-11 & 50-323/79-06 on 790401-20 No noncompliance noted  
CRENSH, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/15 2pp

--7907270141 IE Insp Repts 50-275/79-11 & 50-323/79-06 on 790401-20 No noncompliance noted Major areas inspected preoperational testing, emergency procedures & fire prevention & protection  
YOUNG, T Region 5, San Francisco, Office of the Director  
STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/14 4pp

7907090398 Forwards response to IE Bulletins 79-06 & 79-06A, Revision 1 Info & training sessions scheduled Revising emergency operating procedures to include possibility of void formation in vessel  
CRANE, P A Pacific Gas & Electric Co 79/05/24 12pp

7907020482 Submits unsolicited response to IE Bulletin 79-06A, re sys transients, plant equipment features & operating procedures as result of TMI incident  
GDRMLY, H J Pacific Gas & Electric Co 79/05/25 13pp

7907260543 Forwards IE Insp REpt 50-275/79-10 on 790502-03 & 07 No noncompliance noted  
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/05/25 2pp

--7907260549 IE Insp Rept 50-275/79-10 on 790502-03 & 07, No noncompliance noted Major areas inspected emergency planning & coordination w/offsite agencies, radiation protection, staffing & training & instruments & equipment  
NORTH, H S Region 5, San Francisco, Office of the Director  
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/05/25 5pp

7906200052 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/29 1p

37190423 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Bolenoid Valves)" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p

07060029 Forwards IE Info Notice 79-13, "Deficient Procedures" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/07 1p

7907020265 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/11 1p

0268 Forwards IE Insp Rept 50-275/79-14 on 790514-31, No compliance noted.  
J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/14 2pp

--7907270280 IE Insp Rept 50-275/79-14 on 790514-31 No noncompliance noted Major areas inspected preoperational testing, environ protection, emergency planning, testing in progress & QA for preoperational testing  
YOUNG, T, STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/14 4pp

7907020448 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p

7907120006 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/21 1p

7907120621 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/25 1p

7907060216 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907030492 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/27 1p

7907100529 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/28 1p

7907130205 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p

7907180700 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/07/11 1p

7907310396 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260270 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

## B Reportable occurrences, LERs &amp; related correspondence

7907020282 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/05 1p

7907030191 Forwards PNO-79-67AS  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/13 1p

7907030232 Forwards PNO-79-67AT, "Nuclear Incident at TMI"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/19 1p

7907030531 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907130384 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/03 1p

## U Congressional/Executive Correspondence

7907180651 Responds to 790330 request for investigation into accident at TMI & comparison of facility designs. Investigations are under way. Forwards IE bulletins relevant to facility & public announcement re TMI task force  
HENDRIE, J M. Commission 79/06/28 2pp

# DOCKETED ITEMS

69

--7907180673 Requests full & immediate investigation into TMI accident & analysis of comparative structural & operational design of facilities  
PANETTA, L E House of Rep 79/03/30 1p

7907310145 Responds to 790601 ltr re constituent concerns over facilities. Discusses measures taken to prevent Class 9 accident, seismic problems & emergency response procedures  
GOSBICK, L V Office of the Executive Director for Operations 79/06/29 2pp

--7907310164 Urges NRC to review Class 9 accidents & seismic problems & to re-evaluate emergency response procedures at facilities  
LAODMARBINO, R J House of Rep 79/06/01 1p

## DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

### G Inspection reports, IE Bulletins & correspondence

7907100114 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907230408 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907240464 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

## DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

### F Security, medical, emergency & fire protection plans

7907110933 Forwards suppl to fire protection study safe shutdown analysis. Discusses items contained in NRC 781117 ltr re hot & cold shutdown analysis. Will implement improvements to enhance safe shutdown capabilities  
DALYROFF, B L Philadelphia Electric Co 79/07/03 39pp

### G Adjudicatory correspondence

7907160131 Requests summary disposition of intervenors Ecology Action of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of fact. Certificate of Svc encl  
BORDENICK, D M Branch 4 79/05/25 29pp

7907090171 Notifies of typographical errors in Met Ed joint motion for summary disposition re radon issues. Mistakes were in accompanying affidavits  
GILBERG, J E Shaw, Pittman, Potts, & Trowbridge 79/06/05 9pp

7907180188 Responds to utils motion for summary disposition re radon issues. Twenty-one alleged deficiencies in Perkins record advanced by intervenors are supported in part & opposed in part. Certificate of Svc encl  
BORDENICK, D M, LEWIS, B H Branch 4 79/06/14 27pp

### J Insurance & indemnity information

7907130326 Forwards Endorsements 85-87 to NELIA Policy NF-140 & Endorsements 42-44 to MAELU Policy MF-67  
BRADLEY, E J Philadelphia Electric Co 79/07/09 7pp

7907130374 Forwards executed Amend 20 to Indemnity Agreement B-28  
BRADLEY, E J Philadelphia Electric Co 79/07/09 3pp

### P Operating license stage documents & correspondence

7907240069 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907110698 Notice of issuance of Amend 54 to Licenses DPR-44 & DPR-56, as requested in util 790430 application. Amend revises definition section of Tech Spec to extend specified time interval to coincide w/refueling cycle length.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 2pp

7907120180 Forwards Amends 54 & 54 to Licenses DPR-44 & DPR-56, respectively, & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 3pp

--7907120190 Amends 54 & 54 to Licenses DPR-54 & DPR-56, respectively, revising Tech Specs to extend specified time intervals re surveillance testing frequency to coincide w/refueling cycle length of 18 months  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 8pp

--7907120200 Notice of issuance & availability of Amends 54 & 54 to Licenses DPR-44 & DPR-56, respectively  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 2pp

7907250014 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PHWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907180888 Forwards request for addl info re degraded grid voltage in order to review util 771222 submittal  
LAINAS, G Plant Systems Branch 79/06/13 3pp

7907250107 Forwards Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/15 2pp

--7907250110 Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to permit decrease in discharge pressure of high pressure svc water pumps from 280 to 233 psig  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/15 18pp

--7907250115 Safety evaluation supporting Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/15 4pp

--7907250116 Notice of issuance & availability of Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/06/15 2pp

7907110466 Submits info requested by NRC re control sys characteristics for use in transient simulations. Control sys characteristics not required for evaluation of flux & pressure response for turbine trip experiments  
CDOCK, K W General Electric Co, Nuclear Energy Products Div 79/06/29 10pp

7907120361 Forwards "Chlorine Minimization Study, 1978"  
WILLBEY, W B Philadelphia Electric Co 79/07/06 1p

--7907120368 "Chlorine Minimization Study, 1978"  
\* Philadelphia Electric Co 79/07/06 14pp

### G Inspection reports, IE Bulletins & correspondence

7907020090 Responds to IE Bulletin 79-08 No Tech Spec changes required or anticipated  
DALYROFF, B L Philadelphia Electric Co 79/05/14 1p

7907050446 Supplements response to IE Bulletin 79-08 Review under way. No Tech Spec changes anticipated  
DALYROFF, B L Philadelphia Electric Co 79/05/14 1p

7907060401 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907090089 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
QALLAHER, J W Philadelphia Electric Co 79/05/23 3pp

7907180914 Completes responses to IE Bulletins 78-12, 78-12A & 78-12B re atypical weld metl Chicago Bridge & Iron rept was sent to NRC on 790424  
QALLAHER, J W Philadelphia Electric Co 79/05/23 2pp

7907030093 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
1	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
2	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
3	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
4	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
5	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81																			

--7907180713 Requests thorough insp of facilities in light of accident at  
TMI Requests info re exact steps being taken to guard  
against TMI-type accident at facilities  
ROTH,W.V. Senate 79/05/07 lp

## DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

## F Security, medical, emergency &amp; fire protection plans

790710533 Forwards suppl to fire protection study safe shutdown analysis. Discusses items contained in NRC 781117 ltr re hot & cold shutdown analysis. Will implement improvements to enhance safe shutdown capabilities.  
DALTROFF, B L Philadelphia Electric Co 79/07/03 38pp

## G Adjudicatory correspondence

7907160131 Requests summary disposition of intervenors Ecology Action of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of mat'l fact. Certificate of Svc encl.  
BORDENICK, B M Branch 4 79/05/25 29pp

7907090171 Notifies of typographical errors in Met Ed joint motion for summary disposition re radon issues. Mistakes were in accompanying affidavits.  
SILBERG, J E Shaw, Pittman, Potts, & Trowbridge 79/06/05 7pp

7907180189 Responds to utils motion for summary disposition re radon issues. Twenty-one alleged deficiencies in Perkins record advanced by intervenors are supported in part & opposed in part. Certificate of Svc encl.  
BORDENICK, B M, LEWIS, S H Branch 4 79/06/14 29pp

## J Insurance &amp; indemnity information

7907130324 Forwards Endorsements 85-87 to NELIA Policy NF-140 & Endorsements 42-44 to MAELU Policy MF-67.  
BRADLEY, E J Philadelphia Electric Co 79/07/09 7pp

7907130374 Forwards executed Amend 20 to Indemnity Agreement B-28.  
BRADLEY, E J Philadelphia Electric Co 79/07/09 3pp

## P Operating license stage documents &amp; correspondence

7907260069 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907110698 Notice of issuance of Amend 54 to Licenses DPR-44 & DPR-56, as requested in util 790430 application. Amend revises definition section of Tech Spec to extend specified time interval to coincide w/refueling cycle length.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 2pp

7907120180 Forwards Amends 54 & 54 to Licenses DPR-44 & DPR-56, respectively, & notice of issuance & availability.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 3pp

--7907120190 Amends 54 & 54 to Licenses DPR-54 & DPR-56, respectively, revising Tech Specs to extend specified time intervals re surveillance testing frequency to coincide w/refueling cycle length of 18 months.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 8pp

--7907120200 Notice of issuance & availability of Amends 54 & 54 to Licenses DPR-44 & DPR-56, respectively.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/06 2pp

7907250014 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PHRs Designed by B&W." W/o encl.  
GRINES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907180888 Forwards request for addl info re degraded grid voltage in order to review util 771222 submittal.  
LAINAS, G Plant Systems Branch 79/06/13 3pp

7907250107 Forwards Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/15 2pp

--7907250110 Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to permit decrease in discharge pressure of high pressure svc water pumps from 280 to 233 psig.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/15 18pp

--7907250115 Safety evaluation supporting Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively.  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/15 4pp.

--7907250116 Notice of issuance & availability of Amends 55 & 55 to Licenses DPR-44 & DPR-56, respectively.  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/06/15 2pp

7907120361 Forwards "Chlorine Minimization Study, 1978"  
WILLBEY, W B Philadelphia Electric Co 79/07/06 1p

--7907120368 "Chlorine Minimization Study, 1978"  
\* Philadelphia Electric Co 79/07/06 14pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907020090 Responds to IE Bulletin 79-08 No Tech Spec changes required or anticipated.  
DALTROFF, B L Philadelphia Electric Co 79/05/14 1p

7907050446 Supplements response to IE Bulletin 79-08 Review under way. No Tech Spec changes anticipated.  
DALTROFF, B L Philadelphia Electric Co 79/05/14 1p

7907060401 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licenses action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907090089 Responds to IE Bulletin 79-10 Submits requalification training program statistics.  
GALLAGHER, J W Philadelphia Electric Co 79/05/23 3pp

7907180914 Completes responses to IE Bulletins 78-12, 78-12A & 78-12B re atypical weld mat'l Chicago Bridge & Iron rept was sent to NRC on 790424.  
GALLAGHER, J W Philadelphia Electric Co 79/05/23 2pp

7907030093 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200131 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190080 Completes response to IE Bulletin 79-03 No spools mfg by Youngstown Welding & Engineering Co are installed in safety-related sys.  
DALTROFF, B L Philadelphia Electric Co 79/06/06 1p

7907190094 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves)." Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060121 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907110633 Ack receipt of 790510 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-11 & 50-278/79-12.  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/15 1p

--7907110644 Responds to NRC 790420 ltr re violations noted in IE Insp Repts 50-277/79-11 & 50-278/79-12. Corrective actions, unlocked valves secured & procedures to be revised.  
GALLAGHER, J W Philadelphia Electric Co 79/05/10 4pp

7907110710 Ack receipt of 790430 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-04 & 50-278/79-03.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/15 1p

## DOCKETED ITEMS

--7907110719 Responds to NRC 790222 ltr re violations noted in IE Insp Repts 80-277/79-04 & 80-278/79-03 Corrective actions test procedures & tests completed & addl mgt controls implemented  
DALTROFF, S L Philadelphia Electric Co 79/04/30 2pp

7907110381 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230693 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240198 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907120526 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907250087 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-277/78-17 & 80-278/78-21  
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/25 1p

--7907250093 Responds to NRC 780823 ltr re violations noted in IE Insp Repts 80-277/78-17 & 80-278/78-21 Provides updated schedule for const work  
DALTROFF, S L Philadelphia Electric Co 79/04/11 2pp

7907050200 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907110031 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180799 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907250521 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

7907270358 Forwards IE Bulletin 79-19, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310528 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R Periodic operating reports & related correspondence

7907130428 Forwards monthly operating rept for June 1979  
COONEY, M J Philadelphia Electric Co 79/07/10 1p

--7907130431 Monthly operating rept for June 1979  
ALDEN, W M Philadelphia Electric Co 79/07/10 3pp.

#### B Reportable occurrences, LERs & related correspondence

707050221 Confirms 790518 telcon w/Greeman re inoperable startup electrical source w/inoperable diesel generator. Caused by hydraulic fitting leak on diesel governor. Governor leak repaired.  
LEISCHMANN, R Philadelphia Electric Co 79/05/18 2pp.

7907300115 RO 3-79-13/1p on 790613 w/Unit 3 at 95% power, main steam relief valve lifted, causing torus water vol to exceed Tech Spec limits Reactor was manually scrammed Cause unknown Main steam relief valve will be replaced  
ULLRICH, M T Philadelphia Electric Co 79/06/14 2pp

7907190367 RO 5-79-19/1P on 790621 anchor associated w/reactor core isolation cooling piping had two bolts that could not be torqued Caused by improper installation of wall anchor bolts Anchors replaced  
ULLRICH, M T Philadelphia Electric Co 79/06/22 2pp

7907190406 RO 5-79-20/1P on 790621 reactor removed from svc due to loss of condenser vacuum recombiner sys Primary coolant pressure reduced Caused by introduction of non-condensable gases w/significant fission inventories into condenser  
ULLRICH, M T Philadelphia Electric Co 79/06/22 2pp

7907090296 Forwards LER 79-013/01T-0  
COONEY, M J Philadelphia Electric Co 79/06/27 1p

--7907090298 LER 79-013/01T-0 on 790613 main steam relief valve RV3-2-71L lifted, causing torus water vol to exceed Tech Spec limit by 2.6% Reactor manually scrammed Valve replaced & sent to Wiley Lab to determine cause for failure  
COONEY, M J Philadelphia Electric Co 79/06/27 2pp

7907190331 RO 2-79-32/1P on 790626 as followup to IE Bulletin 79-02 Revision 1, 92 Class 1 supports identified as possibly failing during DBE Caused by inadequate design Mods will be implemented  
ULLRICH, M T Philadelphia Electric Co. 79/06/27 2pp

7907120592 Forwards LER 79-020/01T-0  
COONEY, M J Philadelphia Electric Co 79/07/06 3pp

--7907120597 LER 79-020/01T-0 on 790621 radioactive release rate at main stack during plant startup exceeded Tech Specs Caused by deficiency in procedure for depressurization following shutdown Investigation underway to improve procedure  
COONEY, M J Philadelphia Electric Co 79/07/06 1p

7907170157 Forwards LER 79-019/01T-0  
COONEY, M J Philadelphia Electric Co 79/07/06 2pp

--7907170166 LER 79-019/01T-0 on 790621 during seismic support insp program, reactor core isolation cooling piping anchor discovered to have two bolts that could not be torqued Caused by improper installation of bolt shells  
COONEY, M J Philadelphia Electric Co 79/07/06 1p

7907230522 Discusses LER 79-017/03L-0 While reactor subcritical & less than 212 F, main steam line D radiation monitor HI-HI trip failed Caused by dirty trip relay or dirty test switch contacts. Repeated testing corrected condition  
COONEY, M J Philadelphia Electric Co. 79/07/09 1p

7907180504 Forwards LER 79-032/01T-0.  
COONEY, M J Philadelphia Electric Co 79/07/11 2pp

--7907180509 LER 79-032/01T-0 on 790626 during analysis of Seismic Category I supports, discovered that 100 supports are safety deficient Caused by inadequate initial support design Pipe support mod expected to be completed by 790713  
COONEY, M J Philadelphia Electric Co. 79/07/11 1p

7907270206 Forwards LER 79-031/03L-0  
COONEY, M J Philadelphia Electric Co. 79/07/20 3pp.

--7907270221 LER 79-031/03L-0 on 790622 during electrical storm, lost main stack sampling sys & automatic initiation capability. Caused by blown fuses from lightning-induced electrical transient Fuses replaced  
COONEY, M J Philadelphia Electric Co. 79/07/20 1p.

7907270238 LER 79-016/03L-0 on 790628, while at power, routine surveillance test revealed setpoint of Switch 2 was below Tech Spec min Caused by Barton Model 288 instrument out of calibr from drift. Instrument recalibr.  
COONEY, M J. Philadelphia Electric Co. 79/07/24 1p.

7907270247 LER 79-018/03L-0 on 790630 during surveillance testing, reactor water sample line isolation valve failed to close. Caused by lack of valve operator spring tension Valve operator spring tension was increased.  
COONEY, M J. Philadelphia Electric Co. 79/07/24. 1p

## U Congressional/Executive Correspondence

7907180596 Responds to 790507 ltr re facilities in light of accident at TMI Forwards actions taken at facilities as result of TMI incident  
HENDRIE, J M Commission 79/06/28 3pp

--7907180713 Requests thorough insp of facilities in light of accident at TMI Requests info re exact steps being taken to guard against TMI type accident at facilities  
ROTH, W V Senate 79/05/07 1p

## DOCKET 50-280 SURREY POWER STATION, UNIT 1

## Q Adjudicatory correspondence

7907120284 Ack receipt of 790313 ltr commenting on shutdown of five nuclear power plants in eastern US Objective is to review situation in expedited & disciplined manner so that plants can be returned to operation  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/22 1p

7907120513 Notifies of receipt of Potomac Alliance 790418 petition to suspend steam generator repair program Federal Register notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/08 1p

--7907120532 Notice that action will be taken on Potomac Alliance 790418 petition to suspend steam generator repair program  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/08 1p

--7907120555 Forwards 790418 petition by Potomac Alliance, Citizens Energy Forum, VA Sunshine Alliance & Truth in Power requesting suspension of steam generator repair program & const of long-term waste storage facility  
DOUGHERTY, J B Potomac Alliance 79/04/18 2pp

--7907120556 Request by Potomac Alliance, Citizens Energy Forum, VA Sunshine Alliance & Truth in Power that NRC suspend steam generator repair program & const of long-term waste storage facility on site  
DOUGHERTY, J B Potomac Alliance 79/04/18 65pp

7907130464 Forwards Potomac Alliance 790418 request for order to suspend further action on steam generator repair program pending preparation of EIS  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/15 2pp

## H General correspondence

7907120332 Comments on closing of five nuclear plants due to seismic testing inconsistencies NRC was unjustly criticized for doing right thing  
WASSERBACH, A E Affiliation Unknown 79/03/26 1p

7907060343 Responds to 790314 ltr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord w/accepted engineering practice Failed piping could cause LOCA Plant review is being expedited  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/09 3pp

--7907060356 Comments on incidence of seismic activity in northeast US  
SMITH, E T Affiliation Unknown 79/03/14 3pp

7907090440 Responds to 790316 telegram re orders closing five power plants in eastern US Analysis techniques used in seismic design of safety-related piping not in accord w/proven & generally accepted engineering practice  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 3pp

7907050542 Responds to 790315 ltr re shutdown of five nuclear plants Plants shut down due to inadequacy of seismic analysis techniques W/map showing previous earthquakes in area  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907050548 Expresses outrage at closing of five nuclear power plants due to possible consequences resulting from earthquakes.  
DRUM, D E Peter Bent Brigham Hosp BD, Massachusetts 79/03/15 1p

7907060293 Responds to 790315 telegram opposing plant shutdown due to seismic design concerns Forwards earthquake maps  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907060299 Opposes shutdown of plants Plants should be allowed to continue to operate while seismic improvements are developed.  
KUS, C M Affiliation Unknown 79/03/15 1p

## J Insurance &amp; indemnity information

7907120074 Amend 8 to Indemnity Agreement B-45, increasing amount of financial protection  
SALTZMAN, J Antitrust & Indemnity Group 79/06/28 2pp

7907170129 Forwards signed & accepted Amend 8 to Indemnity Agreement B-45, raising amount of financial protection  
PROFFITT, W L Virginia Electric & Power Co 79/07/13 3pp

## P Operating license stage documents &amp; correspondence

7907120408 Responds to 790320 ltr to JM Hendrie re pipestress reanalysis Explains seismic analyses techniques to be used while plants are shutdown  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/01 2pp

--7907120415 Requests speedy resolution to issues re facility shutdown & ensuing seismic reanalysis  
COLEMAN, M Virginia, State of 79/03/20 2pp

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 3pp

7907120053 Summary of 790510 meeting w/utill & S&W re pipe stress analysis  
NEIGHBOR, D Operating Reactors Branch 1 (Pre 790625) 79/05/10 18pp

7907030045 Summary of 790522 meeting w/utills & S&W in Boston, MA re review of soil structure interaction methodology  
NEIGHBOR, J D Operating Reactors Branch 1 (Pre 790625) 79/05/25 3pp

7907110142 Forwards safety evaluation on environ qualification of safety-related cable  
LAINAS, Q Plant Systems Branch 79/05/30 2pp

--7907110148 Safety evaluation on environ qualification of safety-related cable.  
\* Plant Systems Branch 79/05/30 8pp

7907110738 Summary of 790524 meeting w/utill & S&W re use of soil structure interaction in pipe stress analyses  
NEIGHBOR, J D Operating Reactors Branch 1 (Pre 790625) 79/05/30 3pp

7907130071 Notification of 790605 meeting w/utill in Bethesda, MD to discuss util proposal for interim operation of facility while completing remainder of pipestress analysis  
NEIGHBOR, J D Operating Reactors Branch 1 (Pre 790625) 79/06/01 2pp

7907240562 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250020 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907130407 Discusses reanalysis of piping sys Overall analysis is of greater magnitude than originally thought Large percentage of analyses should be completed before startup can be permitted Appreciates NRC responsiveness  
RAGONE, S Virginia Electric & Power Co 79/06/27 2pp

7907310440 Forwards supplemental info to proposed Tech Spec Mod 73 Revised Table 3 7-5 re radioactive effluent monitoring instrumentation should be included in Offsite Dose Calculation Manual.  
STALLINGS, C M Virginia Electric & Power Co 79/07/26 2pp

7907310255 Forwards supplemental response to NRC 790525 request for info re PWR feedwater lines. Describes design, fabrication history & insp & operating history.  
STALLINGS, C M Virginia Electric & Power Co 79/07/27 3pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907020336 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

## DOCKETED ITEMS

7907110344 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907200404 Forwards IE Insp Rept 50-280/79-17 & 50-281/79-25 on 790403-06 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/07 2pp

--7907200411 IE Insp Rept 50-280/79-17 & 50-281/79-25 on 790403-06 No noncompliance noted Major areas inspected seismic reanalysis of safety-related piping & protection of reactor plant components  
ELROD, S A, CANTRELL, F S Region 2, Atlanta, Office of the Director 79/05/04 3pp

7907230708 Forwards IE Insp Repts 50-280/79-16 & 50-281/79-24 on 790327-30 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/16 2pp

--7907230724 IE Insp Repts 50-280/79-16 & 50-281/79-24 on 790327-30 No noncompliance noted Major areas inspected reactor coolant pipe decontamination & radiation protection aspects of steam generator replacement project  
EWALD, S E, HOSEY, C M Region 2, Atlanta, Office of the Director JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/15 5pp

7907100222 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907260004 Forwards IE Insp Repts 50-280/79-14 & 50-281/79-20 on 790320-23 notice of violation & notice of deviation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/18 2pp

--7907260005 Notice of violation from insp on 790320-23  
\* Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
79/05/17 1p

--7907260007 Notice of deviation from insp on 790320-23  
\* Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
79/05/17 2pp

7907050366 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
9/05/22 1p

7907240276 Forwards IE Insp Rept 50-280/79-20 & 50-281/79-31 on 790319-0427 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/22 2pp

--7907240279 IE Insp Rept 50-280/79-20 & 50-281/79-31 on 790319-0427 No noncompliance noted Major areas inspected plant operations, physical protection barriers, maint & followup on LERs & IE Bulletin 79-06A  
BURKE, D J, CANTRELL, F S Region 2, Atlanta, Office of the Director 79/05/19 5pp

7907240619 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting  
owners of operating plants having Westinghouse-designed ys scheduled for 790530 in Bethesda, MD  
WENCER, A Operating Reactors Branch 1 (Pre 790629) 79/05/22 p

00062 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
STALLINGS, C M Virginia Electric & Power Co 79/05/24 5pp

79030114 Forwards IE Info Notice 79-13, "Indication of Low Water level in Oyster Creek Reactor"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
7/05/29 2pp

180145 Responds to IE Bulletin 78-12, 78-12A & 78-12B, "Atypical ID Metal in Reactor Pressure Vessel Welds " Info requested  
ID be forwarded to NRC by 790501  
STALLINGS, C M Virginia Electric & Power Co 79/05/29 1p

10223 Forwards IE Bulletin 79-12, "Short Period Scrums at BHR facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
15/31 2pp

7907300021 Forwards IE Insp Repts 50-280/79-21 & 50-281/79-32 on 790514-18 & 21-22 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/31 2pp

--7907300028 IE Insp Repts 50-280/79-21 & 50-281/79-32 on 790514-18 & 21-22 No noncompliance noted Major areas inspected radiation protection  
EWALD, S C Region 2, Atlanta, Office of the Director JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/30 4pp

7907300075 Forwards IE Insp Repts 50-280/79-19 & 50-281/79-28 on 790416-19 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/31 2pp

--7907300082 IE Insp Repts 50-280/79-19 & 50-281/79-28 on 790416-19 No noncompliance noted Major areas inspected seismic reanalysis of safety-related piping, Unit 2 retest program, radiation work permit documentation & radiation exposure rept  
ELROD, S A Region 2, Atlanta, Office of the Director KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/30 4pp

7907090195 Suppl response to IE Bulletin 79-03 Further investigation reveals purchase order for piping contained requirement for 100% x-ray of all delivered pipes No abnormal indications found Volumetric examination of pipe not needed  
STALLINGS, C M Virginia Electric & Power Co 79/06/01 1p

7907190252 Responds to IE Bulletin 79-02 re pipe support baseplate designs using concrete expansion anchor bolts Effect of baseplate flexibility was not considered in calculation of anchor bolt loads Loads to be recalculated  
STALLINGS, C M Virginia Electric & Power Co 79/06/04 7pp

7907190050 Act receipt of 790524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-08 & 50-281/79-09  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/06 1p

--7907190061 Responds to NRC 790501 ltr re violations noted in IE Insp Repts 50-280/79-08 & 50-281/79-09 Corrective actions all uncontrolled & unidentified matl inventoried & placed under warehouse control  
STALLINGS, C M Virginia Electric & Power Co 79/05/24 4pp

--7907190066 Forwards IE Insp Repts 50-280/79-08 & 50-281/79-09 on 790213-16 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp

--7907190070 Notice of violation from insp on 790213-16  
\* Region 2, Atlanta, Office of the Director 79/04/26 2pp

--7907190078 IE Insp Repts 50-280/79-08 & 50-281/79-09 on 790213-16 Noncompliance noted Failure to maintain records, failure to provide identification & control of matl, parts & components & failure to provide care of items in storage  
BROWNLEE, V L, ASHENDEN, M C, KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/26 11pp

7907190209 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class 50 Equipment (Deficiencies in Environ Qualification of ABCO Bolonoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/04 2pp

7907060049 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907180652 Ack receipt of 790531 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-18 & 50-281/79-26  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/08 1p

--7907180670 Responds to NRC 790510 ltr re violations noted in IE Insp Repts 50-280/79-18 & 50-281/79-26 Corrective actions tents inspected, procedure HP-BORP-10 filed & frequency of subsurface drain sys sampling changed  
STALLINGS, C M Virginia Electric & Power Co 79/05/31 4pp

--7907180679 Forwards IE Insp Repts 50-280/79-18 & 50-281/79-26 on 790409-13 & notice of violation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/10 2pp



--7907180686 Notice of violation from insp on 790409-13  
 \* Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
 79/05/10 2pp

--7907180695 IE Insp Repts 50-280/79-18 & 50-281/79-26 on 790409-13  
 Noncompliance noted failure to follow test procedures &  
 checks of vents, inadequate surveys of subsurface drain  
 sys effluent release & unposted radiation area  
 MOSEY, C M Region 2, Atlanta, Office of the Director  
 GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety  
 Branch 79/05/07 8pp

7907240612 Summary of 790605 meeting w/VERCO & B&W in Bethesda, MD re  
 startup  
 NEIGHBOR, J D Operating Reactors Branch 1 (Pre 790625)  
 79/06/08 5pp

7907250167 Requests that Region 2 measurements can be granted access  
 privileges of "licensee designated vehicle"  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/11 3pp

790720401 Forwards IE Info Notice 79-17, "Source Holder Assembly  
 Damage from Misfit Between Assembly & Reactor Upper Grid  
 Plate"  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/20 1p

7907120142 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
 Plate Designs Using Concrete Expansion Anchor Bolts" Action  
 required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/21 1p

7907300265 Ack receipt of 790614 ltr informing NRC of steps taken to  
 correct violations noted in IE Insp Repts 50-280/79-14 &  
 50-281/79-20  
 SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials  
 Safety Branch 79/06/21 1p

--7907300342 Responds to NRC 790518 ltr re violations noted in IE Insp  
 Repts 50-280/79-14 & 50-281/79-20 Corrective actions reactor  
 coolant pipe slag removal area posted & decontaminated  
 Requests sent for previous exposure records  
 STALLINGS, C M Virginia Electric & Power Co 79/06/14 5pp

7907110234 Forwards IE Circular 79-09, "Occurrences of Split or  
 Punctured Regulator Diaphragms in Certain Self-Contained  
 Breathing Apparatus" No action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/22 1p

7907310043 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys  
 Piping" Action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/23 2pp

7907180446 Forwards IE Circular 79-12, "Potential Diesel Generator  
 Turbocharger Problem" No action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/28 2pp

7907300456 Forwards response to Items 2-4 & 8-11 of IE Bulletin 79-06A,  
 Revision 1 Submits info re primary operator action required  
 to prevent voids, changes in startup procedures, containment  
 isolation & loss of reactor coolant pressure  
 STALLINGS, C M Virginia Electric & Power Co 79/07/06 6pp

7907310389 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies"  
 Action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/07/11 1p

#### R Periodic operating reports & related correspondence

7907050286 Forwards 790401-0531 Progress Rpt 2 for steam generator  
 repair program  
 STALLINGS, C M Virginia Electric & Power Co 79/07/02 1p

--7907050289 "Steam Generator Repair Program," Progress Rpt 2 for  
 790401-0531  
 \* Virginia Electric & Power Co 79/07/02 33pp

7907170002 Forwards monthly operating rpt for June 1979  
 STALLINGS, C M Virginia Electric & Power Co 79/07/11 1p

--7907170004 Monthly operating rpt for June 1979  
 COSTELLO, D J, WILSON, J Virginia Electric & Power Co 79/07/01  
 42pp

#### S Reportable occurrences, LERs & related correspondence

7907300072 Forwards Electro-Motive Div (EMD) notice to owners of EMD  
 engines reporting possible thrust bearing damage which may  
 cause turbocharger failure Suggested IE circular presently  
 in concurrence process Relevant LERs encl  
 CLEMENSON, F Plant Systems Branch 79/06/01 4pp

7907200394 RD on 790621 Westinghouse notified util of nonconservatism  
 in accident analysis Increase in steam generator ref  
 resulted from rise in containment temp not properly  
 accounted for Corrective action being evaluated  
 STEWART, W L Virginia Electric & Power Co 79/06/22 1p

7907200392 RD on 790622 radiography of facility steam generator  
 feedwater nozzles & reducers revealed crack indications at  
 counterbore region Westinghouse & util to evaluate problem  
 \* Virginia Electric & Power Co 79/06/25 1p

7907060291 Forwards LER 79-021/03L-0  
 STALLINGS, C M Virginia Electric & Power Co 79/07/02 1p

--7907060298 LER 79-021/03L-0 on 790608 during cold shutdown, isolation  
 valve MOV-BW-104C to recirculation spray heat exchanger C  
 would not close properly Caused by momentary steam binding  
 Valve cycled electrically & returned to svc  
 STEWART, W L Virginia Electric & Power Co 79/07/02 2pp

7907090372 Forwards LERs 79-022/01T-0 & 79-023/01T-0  
 STALLINGS, C M Virginia Electric & Power Co 79/07/05 1p

--7907090380 LER 79-022/01T-0 on 790621 notified by Westinghouse of  
 non-conservatism in accident analysis Potential increase in  
 steam generator ref log temp not properly accounted for in  
 analysis Caused by deficiency in accident analysis  
 STEWART, W L Virginia Electric & Power Co 79/07/05 2pp

--7907090384 LER 79-023/01T-0 on 790622 cracks discovered in base metal &  
 weld metal at counterbore regions of steam generators Cause  
 undetermined Deviation rept submitted & Westinghouse  
 contacted re corrective actions  
 STEWART, W L Virginia Electric & Power Co 79/07/05 2pp.

7907310424 Forwards LER 79-024/03L-0  
 STALLINGS, C M Virginia Electric & Power Co 79/07/27 1p

--7907310427 LER 79-024/03L-0 on 790630 64 fire barrier penetrations not  
 properly sealed in safety-related areas Caused by failure to  
 properly seal penetrations during initial const Work orders  
 issued & fire watches established  
 STEWART, W L Virginia Electric & Power Co. 79/07/27 2pp

#### U Congressional/Executive Correspondence

7907310585 Responds to 790322 ltr re shutdown of facilities due to  
 concerns about postulated earthquakes Forwards FR  
 notice summarizing info which led to 790313  
 decision to shut down facilities  
 HENDRIE, J M Commission 79/06/06 1p

7907230739 Responds to 790426 memo re shutdown of facilities, Forwards  
 790514 FR notice re shutdown of five plants due to  
 unacceptable pipe stress levels in event of earthquake  
 No seismic fault discovered in area.  
 OGBSICK, L V Office of the Executive Director for Operations  
 79/06/19 2pp.

--7907230752 Notice describing reasons for shutdown of five plants  
 CHILK, S J Office of the Secretary of the Commission 79/05/14  
 8pp

--7907230757 Forwards B Whitley 790403 ltr requesting info re shutdown of  
 facilities & location of seismic fault in area.  
 TRIBLE, P House of Rep 79/04/26 2p

7907180588 Responds to 790323 ltr re shutdown of facilities None of  
 proposed alternatives would have adequately dealt  
 w/situation Forwards summary of code verification program,  
 IE Bulletin 79-07 & chronology table of pipe stress issue  
 HENDRIE, J M Commission. 79/06/27 17pp

--7907180633 Requests info re evaluation of feasibility & effectiveness  
 of safe alternative responses to error in seismic codes  
 rather than shutdown of facilities Requests info re  
 possibility of similar errors at other plants.  
 DINI, J D House of Rep, Interstate & Foreign Commerce  
 79/03/23 2pp

## DOCKETED ITEMS

DOCKET 50-281 SURRY POWER STATION, UNIT 2

## 0 Adjudicatory correspondence

7907120284 Ack receipt of 790313 ltr commenting on shutdown of five nuclear power plants in eastern US Objective is to review situation in expedited & disciplined manner so that plants can be returned to operation  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/22 1p

7907120513 Notifies of receipt of Potomac Alliance 790418 petition to suspend steam generator repair program Federal Register notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/08 1p

--7907120532 Notice that action will be taken on Potomac Alliance 790418 petition to suspend steam generator repair program  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/08 1p

--7907120555 Forwards 790418 petition by Potomac Alliance, Citizens Energy Forum, VA Sunshine Alliance & Truth in Power requesting suspension of steam generator repair program & const of long-term waste storage facility  
DOUGHERTY, J B Potomac Alliance 79/04/18 2pp

--7907120556 Request by Potomac Alliance, Citizens Energy Forum, VA Sunshine Alliance & Truth in Power that NRC suspend steam generator repair program & const of long-term waste storage facility on site  
DOUGHERTY, J B Potomac Alliance 79/04/18 65pp

7907120464 Forwards Potomac Alliance 790418 request for order to suspend further action on steam generator repair program pending preparation of EIS  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/15 2pp

## H General correspondence

7907120332 Comments on closing of five nuclear plants due to seismic testing inconsistencies NRC was unjustly criticized for doing right thing  
HABERDACH, A E Affiliation Unknown 79/03/26 1p

7907060343 Responds to 790314 ltr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord w/accepted engineering practice Failed piping could cause LOCA Plant review is being expedited  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/09 3pp

--7907060356 Comments on incidence of seismic activity in northeast US  
SMITH, E T Affiliation Unknown 79/03/14 3pp

7907090460 Responds to 790316 telegram re orders closing five power plants in eastern US Analysis techniques used in seismic design of safety-related piping not in accord w/proven & generally accepted engineering practice  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 3pp

7907050542 Responds to 790315 ltr re shutdown of five nuclear plants Plants shut down due to inadequacy of seismic analysis techniques Wmap showing previous earthquakes in area  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907050548 Expresses outrage at closing of five nuclear power plants due to possible consequences resulting from earthquakes  
BRUM, D E Peter Bent Brigham Hosp BD, Massachusetts 79/03/15 1p

7907060293 Responds to 790315 telegram opposing plant shutdown due to seismic design concerns. Forwards earthquake maps.  
DENTON, H R Office of Nuclear Reactor Regulation 79/03/24 3pp

--7907060299 Opposes shutdown of plants Plants should be allowed to continue to operate while seismic improvements are developed  
KUB, C M Affiliation Unknown 79/03/15 1p

## J Insurance &amp; indemnity information

7907120074 Amend B to Indemnity Agreement B-45, increasing amount of financial protection.  
BALTZMAN, J. Antitrust & Indemnity Group. 79/06/28 2pp

790710129 Forwards signed & accepted Amend B to Indemnity Agreement B-45, raising amount of financial protection.  
PROFFITT, W L Virginia Electric & Power Co. 79/07/13 3pp

## P Operating license stage documents &amp; correspondence

7907120408 Responds to 790320 ltr to JM Handrie re pipestress reanalysis Explains seismic analyses techniques to be used while plants are shutdown  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/01 2pp

--7907120415 Requests speedy resolution to issues re facility shutdown & ensuing seismic reanalysis  
COLEMAN, M Virginia, State of 79/03/20 2pp

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907120053 Summary of 790510 meeting w/utill & S&W re pipe stress analysis  
NEIGHBOR, D Operating Reactors Branch 1 (Pre 790628) 79/05/10 18pp

7907030045 Summary of 790522 meeting w/utills & S&W in Boston, MA re review of soil structure interaction methodology  
NEIGHBOR, J D Operating Reactors Branch 1 (Pre 790625). 79/05/25 3pp

7907110142 Forwards safety evaluation on environ qualification of safety-related cable  
LAINAS, G Plant Systems Branch 79/05/30 2pp

--7907110148 Safety evaluation on environ qualification of safety-related cable  
" Plant Systems Branch 79/05/30 8pp

7907110738 Summary of 790524 meeting w/utill & S&W re use of soil structure interaction in pipe stress analyses  
NEIGHBOR, J D Operating Reactors Branch 1 (Pre 790625) 79/05/30 31pp

7907240542 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790628) 79/06/11 2pp

7907250020 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907130407 Discusses reanalysis of piping sys Overall analysis is of greater magnitude than originally thought Large percentage of analyses should be completed before startup can be permitted Appreciates NRC responsiveness  
RADONE, S Virginia Electric & Power Co 79/06/27 2pp

7907200327 Forwards addl Class III amend fee re LOCA-ECCS analysis results & proposed Tech Spec Change 7B  
STALLINGS, C M Virginia Electric & Power Co 79/07/17 1p

7907250316 Forwards Part 1 of Cycle 5 reload application covering design of reload core & refabricated demonstration assembly  
THOMAS, W N Virginia Electric & Power Co 79/07/23 16pp

7907310440 Forwards supplemental info to proposed Tech Spec Mod 73 Revised Table 3 7-5 re radioactive effluent monitoring instrumentation should be included in Offsite Dose Calculation Manual  
STALLINGS, C M Virginia Electric & Power Co 79/07/26 2pp

7907310255 Forwards supplemental response to NRC 790325 request for info re PWR feedwater lines Describes design, fabrication history & insp & operating history  
STALLINGS, C M Virginia Electric & Power Co 79/07/27 3pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907020336 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl"  
O'REILLY, J. P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110344 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J. P Region 2, Atlanta, Office of the Director 79/03/07 2pp

7907200404 Forwards IE Insp Rept 50-280/79-17 & 50-281/79-25 on 790403-06 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/07 2pp

--7907200411 IE Insp Rept 50-280/79-17 & 50-281/79-25 on 790403-06 No noncompliance noted Major areas inspected seismic reanalysis of safety-related piping & protection of reactor plant components  
ELROD, S A, CANTRELL, F S Region 2, Atlanta, Office of the Director 79/05/04 3pp

7907090434 Forwards IE Insp Rept 50-281/79-27 on 790417-20 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Office of the Director 79/05/08 2pp

--7907090438 IE Insp Rept 50-281/79-27 on 790417-20 No noncompliance noted Major areas inspected const status, field changes, noncompliance repts, licensee action on previous insp findings, safety-related work activities  
WILCOX, J D Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/07 5pp

7907200278 Forwards IE Insp Rept 50-281/79-30 on 790418-20 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 2pp

--7907200290 IE Insp Rept 50-281/79-30 on 790418-20 No noncompliance noted Major areas inspected removal activities, welding operations & welding procedures for steam generator replacement  
ERR, C M, LIVERMORE, H H Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/08 3pp

7907230708 Forwards IE Insp Repts 50-280/79-16 & 50-281/79-24 on 790327-30 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/16 2pp

--7907230724 IE Insp Repts 50-280/79-16 & 50-281/79-24 on 790327-30 No noncompliance noted Major areas inspected reactor coolant pipe decontamination & radiation protection aspects of steam generator replacement project  
EWALD, S E, HOSEY, C M Region 2, Atlanta, Office of the Director  
JENKINS, O R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/15 5pp

7907100222 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907260004 Forwards IE Insp Repts 50-280/79-14 & 50-281/79-20 on 790320-23, notice of violation & notice of deviation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/18 2pp

--7907260005 Notice of violation from insp on 790320-23  
\* Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/17 1p

--7907260007 Notice of deviation from insp on 790320-23  
\* Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/17 2pp

--7907260023 IE Insp Repts 50-280/79-14 & 50-281/79-20 on 790320-23. Noncompliance noted failure to follow a radiation work permit, failure to maintain records of efforts to obtain previous radiation doses, failure to follow ALARA program  
COLLINS, P M Region 2, Atlanta, Office of the Director  
JENKINS, O R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/17 7pp

7907060366 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 1p.

7907240276 Forwards IE Insp Rept 50-280/79-20 & 50-281/79-31 on 790319-0427. No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/22 2pp.

--7907240279 IE Insp Rept 50-280/79-20 & 50-281/79-31 on 790319-0427. No noncompliance noted Major areas inspected, plant operations, physical protection barriers, maint & followup on LERs & IE Bulletin 79-06A.  
BURKE, D J., CANTRELL, F S Region 2, Atlanta, Office of the Director 79/05/19 5pp

7907240619 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907100042 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
STALLINGS, C M Virginia Electric & Power Co 79/05/24 5pp

7907030114 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907180145 Responds to IE Bulletins 78-12, 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds " Info requested will be forwarded to NRC by 790901  
STALLINGS, C M Virginia Electric & Power Co 79/05/29 1p

7907200223 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907300021 Forwards IE Insp Repts 50-280/79-21 & 50-281/79-32 on 790514-18 & 21-22 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/31 2pp

--7907300028 IE Insp Repts 50-280/79-21 & 50-281/79-32 on 790514-18 & 21-22 No noncompliance noted Major areas inspected radiation protection  
EWALD, S C Region 2, Atlanta, Office of the Director  
JENKINS, O R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/30 4pp

7907300075 Forwards IE Insp Repts 50-280/79-19 & 50-281/79-28 on 790416-19. No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/31 2pp

--7907300082 IE Insp Repts 50-280/79-19 & 50-281/79-28 on 790416-19 No noncompliance noted Major areas inspected seismic reanalysis of safety-related piping, Unit 2 retest program, radiation work permit documentation & radiation exposure rept  
ELROD, S A Region 2, Atlanta, Office of the Director  
KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/30 6pp

7907090195 Suppl response to IE Bulletin 79-03 Further investigation reveals purchase order for piping contained requirement for 100% x-ray of all delivered pipes No abnormal indications found Volumetric examination of pipe not needed  
STALLINGS, C M Virginia Electric & Power Co 79/06/01 1p

7907190252 Responds to IE Bulletin 79-02 re pipe support baseplate designs using concrete expansion anchor bolts Effect of baseplate flexibility was not considered in calculation of anchor bolt loads Loads to be recalculated  
STALLINGS, C M Virginia Electric & Power Co 79/06/04 7pp

7907190050 Ack receipt of 790524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-08 & 50-281/79-09  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/06 1p

--7907190061 Responds to NRC 790501 ltr re violations noted in IE Insp Repts 50-280/79-08 & 50-281/79-09 Corrective actions all uncontrolled & unidentified matl inventoried & placed under warehouse control  
STALLINGS, C M Virginia Electric & Power Co. 79/05/24 4pp.

--7907190066 Forwards IE Insp Repts 50-280/79-08 & 50-281/79-09 on 790213-16 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp.

--7907190070 Notice of violation from insp on 790213-16  
\* Region 2, Atlanta, Office of the Director 79/04/26 2pp

--7907190078 IE Insp Repts 50-280/79-08 & 50-281/79-09 on 790213-16. Noncompliance noted: failure to maintain records, failure to provide identification & control of matl, parts & components & failure to provide care of items in storage  
BROWNLEE, V L, ABHENDEN, H C, KELLOGG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/26 11pp.

## DOCKETED ITEMS

7907190209 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060069 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907180652 Ack receipt of 790931 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-280/79-18 & 50-281/79-26  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
79/06/08 1p

--7907180670 Responds to NRC 790510 ltr re violations noted in IE Insp Repts 50-280/79-18 & 50-281/79-26 Corrective actions tents inspected, procedure HP-SORP-10 filed & frequency of subsurface drain sys sampling changed  
STALLINGS, C M Virginia Electric & Power Co 79/05/31 4pp

--7907180679 Forwards IE Insp Repts 50-280/79-18 & 50-281/79-26 on 790409-13 & notice of violation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
79/05/10 2pp

--7907180686 Notice of violation from insp on 790409-13  
\* Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
79/05/10 2pp

--7907180695 IE Insp Repts 50-280/79-18 & 50-281/79-26 on 790409-13 Noncompliance noted failure to follow test procedures & checks of tents, inadequate surveys of subsurface drain sys effluent release & unposted radiation area  
HOBBS, C M Region 2, Atlanta, Office of the Director  
O'BRYEN, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
79/05/07 2pp

07250169 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp

07020401 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

07120142 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7300265 Ack receipt of 790614 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-14 & 50-281/79-20  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch  
79/06/21 1p

7907300342 Responds to NRC 790518 ltr re violations noted in IE Insp Repts 50-280/79-14 & 50-281/79-20 Corrective actions reactor coolant pipe slag removal area posted & decontaminated  
Requests sent for previous exposure records  
STALLINGS, C M Virginia Electric & Power Co 79/06/14 5pp

10234 Forwards IE Circular 79-09, "Occurrences of Split or ruptured Regulator Diaphragms in Certain Self-Contained Steaming Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
16/22 1p

0043 Forwards IE Bulletin 79-13, "Cracking in Feedwater System " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
16/25 2pp

30446 Forwards IE Circular 79-12, "Potential Diesel Generator Recharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
16/28 2pp

10456 Forwards response to Items 2-4 & 8-11 of IE Bulletin 79-06A, Revision 1 Submits info re primary operator action required to prevent voids, changes in startup procedures, containment violation & loss of reactor coolant pressure  
STALLINGS, C M Virginia Electric & Power Co 79/07/06 4pp

7907310389 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### R Periodic operating reports & related correspondence

7907050286 Forwards 790401-0531 Progress Rept 2 for steam generator repair program  
STALLINGS, C M Virginia Electric & Power Co 79/07/02 1p

--7907050289 "Steam Generator Repair Program," Progress Rept 2 for 790401-0531  
\* Virginia Electric & Power Co 79/07/02 33pp

7907170002 Forwards monthly operating rept for June 1979  
STALLINGS, C M Virginia Electric & Power Co 79/07/11 1p

--7907170004 Monthly operating rept for June 1979  
COSTELLO, D J, WILSON, J Virginia Electric & Power Co 79/07/01 42pp

#### S Reportable occurrences, LERs & related correspondence

7907310276 Discusses potential deficiency bolt hole on pad 19D of steam generator 2973 discovered to have 1/2 & 3/4 inch thread missing Caused unstated All helicoils removed & new coils installed  
STALLINGS, C M Virginia Electric & Power Co 79/05/31 2pp

7907090282 Submits info re potential significant deficiency on substantial safety hazard Chromium level for pipe in steam generator was below min amount Pipe w/affected heat number will not be used  
STALLINGS, C M Virginia Electric & Power Co 79/06/25 2pp

#### U Congressional/Executive Correspondence

7907310585 Responds to 790322 ltr re shutdown of facilities due to concerns about postulated earthquakes Forwards FR notice summarizing info which led to 790313 decision to shut down facilities  
HENDRIE, J M Commission 79/06/06 1p

7907230739 Responds to 790426 memo re shutdown of facilities Forwards 790514 FR notice re shutdown of five plants due to unacceptable pipe stress levels in event of earthquake  
No seismic fault discovered in area  
GOSBICK, L V Office of the Executive Director for Operations  
79/06/19 2pp

--7907230752 Notice describing reasons for shutdown of five plants  
CHILK, B J Office of the Secretary of the Commission 79/05/14 8pp

--7907230757 Forwards B Whitley 790403 ltr requesting info re shutdown of facilities & location of seismic fault in area  
TRIBLE, P House of Rep 79/04/26 2p

7907180588 Responds to 790323 ltr re shutdown of facilities None of proposed alternatives would have adequately dealt w/situation Forwards summary of code verification program, IE Bulletin 79-07 & chronology table of pipe stress issue  
HENDRIE, J M Commission 79/06/27 17pp

--7907180633 Requests info re evaluation of feasibility & effectiveness of safe alternative responses to error in seismic codes rather than shutdown of facilities Requests info re possibility of similar errors at other plants  
DINGELL, J D House of Rep, Interstate & Foreign Commerce  
79/03/23 2pp

#### DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

##### F Security, medical, emergency & fire protection plans

7907100533 Approves fire protection program developed by Brookhaven & NRC Offers exceptions for NRC evaluation electrical valve supervision should be provided on all valves controlling fire water sys  
HALL, R E Brookhaven National Laboratory 79/06/21 3pp

7907310175 "Fire Protection in Operating Nuclear Power Stations, Prairie Island Station SER Review," interim rept  
HALL, R E, MACDOUGALL, E A Brookhaven National Laboratory FIN  
A-3107 7907310175 79/06/21 4pp

7907100618 Forwards revised util fire protection program superseding  
790518 revision  
MAYER, L O Northern States Power Co 79/07/05 16pp

7907310388 Forwards supplemental info re physical security plan info  
withheld (ref 10CFR2 790)  
MAYER, L O Northern States Power Co 79/07/30 1p

F Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse  
plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907260103 Discusses plans to install communication links between NRC &  
nuclear facilities for emergency use Direct lines from each  
facility to NRC headquarters & regional ofc will communicate  
operational & environ info  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22  
2pp

7907190325 Summary of 790821 meeting w/Exxon re role in TMI-related  
reevaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

790709042B Intends to ship radioactive matl from facilities, using  
package BG-1  
MAYER, L O Northern States Power Co 79/06/08 1p

7907240550 Forwards NRC 790604 ltr to Westinghouse requesting addl info  
re small break LOCA analyses & analysis methods NRC will  
eventually require documentation re applicability of  
Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11  
2pp

7907250012 Forwards NUREG-0560, "Staff Rpt on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIHES, B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp

7907190211 Provides info re results of stress & fatigue analyses, in  
response to NRC 790525 request Allowable stresses have not  
been exceeded  
MAYER, L O Northern States Power Co 79/07/16 2pp

G Inspection reports, IE Bulletins & correspondence

7907180369 Forwards IE Insp Rept 80-282/79-12 on 790503-04 No  
noncompliance noted  
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering  
Support Branch 79/05/16 2pp

--7907180382 IE Insp Rept 80-282/79-12 on 790503-04 No noncompliance  
noted Major areas inspected surveillance of safety-related  
pipe supports & restraints  
VIN, I T, DANIELSON, D H Region 3, Chicago, Reactor  
Construction & Engineering Support Branch 79/05/15 5pp

7907240607 Forwards results of preliminary review of licensee responses  
to IE Bulletins 79-06, 05A & 06, Amend 1 Meeting  
w/owners of operating plants having Westinghouse-designed  
sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22  
4pp

7907110291 Responds to IE Bulletin 79-10 Submits requalification  
training program statistics  
WACHTER, L J Northern States Power Co 79/05/25 3pp

790716014B Notifies of delay in response to IE Bulletins 78-12, 12A &  
12B due to late submittal by vendor of info re reactor  
vessel welds  
WACHTER, L J Northern States Power Co. 79/05/29 1p

7907240195 Forwards IE Insp Repts 80-282/79-11 & 80-306/79-09 on  
790401-30. No noncompliance noted  
HEIBMAN, R F Region 3, Chicago, Reactor Operations Nuclear  
Support Branch. 79/05/30 2pp

--7907240200 IE Insp Rept 80-282/79-11 & 80-306/79-09 on 790401-0430 No  
noncompliance noted Major areas inspected, operations,  
maint, security, refueling activities, review & audit, training  
& reportable events followup  
FEIERABEND, C D, DANIELS, P T, WARNICK, R F Region 3, Chicago,  
Office of the Director 79/05/29 9pp

7907200328 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31  
1p

7907190285 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240432 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07  
1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures"  
forwarded to listed utills  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp

7907020435 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20  
1p

7907120248 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907050451 Forwards IE Circular 79-09, "Occurrences of Split or  
Punctured Regulator Diaphragms in Certain Self-Contained  
Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907300455 Responds to Items 1-13 of IE Bulletin 79-06A, Revision 1, &  
NRC request for addl info Submits info re emergency  
procedures for coping w/transients & accidents, mod of  
pressurizer pressure & containment isolation sys  
WACHTER, L J Northern States Power Co 79/06/22 18pp

790713013B Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

790706031B Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907180422 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130282 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p

7907240104 Forwards IE Info Notice 79-18, "Skylab Roentry " No action  
required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06  
1p

7907310342 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11.  
1p.

7907310414 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260199 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p.

7907260402 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant  
Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p.

## DOCKETED ITEMS

## R Periodic operating reports &amp; related correspondence

7907130196 Notifies that results of noise monitoring program performed per ETS 4.2 App D are deemed satisfactory. No further action required.  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/29 2pp

7907030272 Forwards "Environ Monitoring & Ecological Studies Program 1978 Annual Rept." Vols 1 & 2  
WARD, E C Northern States Power Co 79/06/29 1p

--7907030275 "Environ Monitoring & Ecological Studies Program 1978 Annual Rept." Vols 1 & 2  
HESTICK, M L Northern States Power Co 79/04/30 608pp

7907180511 Forwards monthly operating rept for June 1979  
HAYER, L O Northern States Power Co 79/07/13 1p

--7907180516 Monthly operating rept for June 1979  
HUNSTAD, A A Northern States Power Co 79/07/02 4pp

## S Reportable occurrences, LERs &amp; related correspondence

7907050300 Forwards LER 79-021/03L-0  
HAYER, L O Northern States Power Co 79/06/29 1p

--7907050303 LER 79-021/03L-0 on 790611 steam generator level channel ILT471 responded slowly to level changes. Cause unstated.  
Transmitter diaphragm assembly replaced.  
HUNSTAD, A A Northern States Power Co 79/06/29 1p

7907050404 Forwards LER 79-018/03L-0  
HAYER, L O Northern States Power Co 79/06/29 1p

--7907050414 LER 79-018/03L-0 on 790531 SP-1187 diesel fire pump weekly battery insp not performed in fifth week of Jan 1979.  
Procedures changed to require fifth signature block on data sheets for months w/five weekly insps.  
HUNSTAD, A A Northern States Power Co 79/06/29 1p

7907090202 Environ event rept 79-05 for June 1979 daily average blowdown flow of plant circulating water sys was in excess of 150 cfs for 26 days. Caused by need to accommodate cooling tower preventive maint.  
WARD, E C Northern States Power Co 79/07/02 1p

7907120469 Forwards LER 79-020/03L-0  
HAYER, L O Northern States Power Co 79/07/09 1p

--7907120473 LER 79-020/03L-0 on 790609 failure of pressurizer power-operated relief isolation to close on demand. Caused by torque switch failure in limit torque SMB-00 operator switch replaced.  
HUNSTAD, A A Northern States Power Co 79/07/09 1p

7907160346 Notifies of discrepancy in design analyses performed for containment purge valves. Info supplements LER 79-019. Valves will remain closed above cold shutdown conditions until closure can be assured.  
HAYER, L O Northern States Power Co 79/07/10 1p

## DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR

## Q Inspection reports, IE Bulletins &amp; correspondence

7907100267 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020035 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus."  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907230501 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

## DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

## F Security, medical, emergency &amp; fire protection plans

7907110675 Requests add info re 790320 proposed security contingency plan within 30 days of receipt of ltr.  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/11 2pp

7907200364 Submits info indicating ability of fire-rated silicone foam penetration seals to withstand differential pressure.  
Largest penetration 1.924 square inches. Max fire loading 97 minutes. Max differential pressure 0.5 inches water.  
SHORT, T E Omaha Public Power District 79/07/11 1p

7907250262 Notifies that util will lock close fire barrier door when not in use rather than electrically supervise & alarm roll-up doors. Safety will be enhanced by eliminating unnecessary wiring.  
SHORT, T E Omaha Public Power District 79/07/18 1p

7907260772 Forwards required fee for submittal of safeguards contingency plan in response to 790703 ltr w/o encl.  
SHORT, T E Omaha Public Power District 79/07/19 2pp

## P Operating license stage documents &amp; correspondence

7907260126 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22 2pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related reevaluations of operating plants.  
KANE, W F Standardization Branch 79/05/31 4pp

7907180649 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W." W/o encl.  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907030346 Submits summary of 790516 telcon re potential for adverse consequences in event of fire in power-operated relief valve recorder cabinet.  
SHORT, T E Omaha Public Power District 79/06/26 2pp

7907030485 Submits justification for ensuring leak tightness of valves re inservice insp plan review. Leak testing in accordance w/ASME Section XI not necessary.  
SHORT, T E Omaha Public Power District 79/06/26 2pp

7907030442 Forwards application for amend of DL providing relief from implementation dates specified for installation of halon sys in control room cabinets. Certificate of Bvc encl.  
\* LeBoeuf, Lamb, Leiby & MacRae 79/06/29 3pp

--7907030444 Application for amend to DL DPR-40 to provide relief from implementation dates specified re halon sys & oil tanks. Proposed changes to Tech Specs & safety discussion encl.  
SHORT, T E Omaha Public Power District 79/06/27 4pp

7907090198 Submits qualitative rept re effects of rupture of fire water piping on safety-related equipment w/four oversized drawings.  
SHORT, T E Omaha Public Power District 79/06/29 4pp

7907090291 Forwards alternative shutdown capability conceptual design description. Requests NRC review of description. Anticipates mod for installation during refueling scheduled for 810301.  
SHORT, T E Omaha Public Power District 79/06/29 1p

--7907090293 Alternative shutdown capability conceptual design description.  
\* Omaha Public Power District 79/06/07 9pp

7907090228 Forwards 790702 application for amend of License DPR-40, w/proposed Tech Specs & safety discussion. Certificate of Bvc encl.  
\* LeBoeuf, Lamb, Leiby & MacRae 79/07/05 3pp

--7907090230 Application for amend of License DPR-40 to remove requirement for cycling nonredundant pumps & valves in one train when other train of redundant sys is inoperable. Proposed Tech Specs & safety discussion encl.  
SHORT, T E Omaha Public Power District 79/07/02 4pp

7907160310 Forwards revision to 780928 cable separation analysis. Responses to questions re cable analysis & on 790108 fire detector analysis w/o oversized drawings.  
SHORT, T E Omaha Public Power District 79/07/09 42pp

7907180577 Forwards application for amend to License DPR-40 to permit cycle & operation following core reload at increased power level of 1,500 MW. Certificate of Bvc & Class 5 amend fee determination encl.  
\* LeBoeuf, Lamb, Leiby & MacRae 79/07/17 3pp

--7907180584 Application for amend to License DPR-40 to increase thermal power level to 1,500 MW, commencing w/Cycle & operation following core reload  
SHORT, T E Omaha Public Power District 79/07/13 2pp

--7907180593 Application for amend to License DPR-40 to permit Cycle & operation following core reload  
SHORT, T E Omaha Public Power District 79/07/13 2pp

--7907180599 Environ assessment re consequences of proposed increase in thermal power level to 1,500 MW  
\* Omaha Public Power District 79/07/17 199pp

--7907180609 "LOCA Analyses at 1,500 MW Using Exxon Nuclear Co WREM-11A PWR ECCB Evaluation Model, Large Break Example Problem"  
BRAUN, D J, KRAJICEK, J E, DIMENNA, R A Exxon Nuclear Co, Inc (subs of Exxon Corp), XN-NF-79-45 79/05/29 59pp

--7907180621 "Exxon Nuclear Co Setpoint Methodology for C-E Reactors"  
NIELSEN, L A Exxon Nuclear Co, Inc (subs of Exxon Corp) XN-NF-507 79/06/25 59pp

#### Q Inspection reports, IE Bulletins & correspondence

7907020213 Corrects two minor errors on part numbers in 790423 response to IE Bulletin 79-06B requesting review of operational errors & sys misalignments resulting from TMI incident  
SHORT, T E Omaha Public Power District 79/05/10 1p

7907060258 Provides current status of effort to resolve concerns of IE Bulletin 78-12B, dtd 790319 C-E performing records search requested by IE Bulletin 78-12 & plans to submit generic rept to NRC covering all reactor vessels mfg before 790629  
SHORT, T E Omaha Public Power District 79/05/15 1p

7907060268 Submits info requested by IE Bulletin 79-09 OE Type AK-2 circuit breakers presently used in entire 480-volt plant distribution sys  
SHORT, T E Omaha Public Power District 79/05/18 3pp

7907100290 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907060254 Forwards response to IE Bulletin 79-10 re requalification training program statistics  
SHORT, T E Omaha Public Power District 79/05/21, 3pp

7907060328 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22 1p

7907020206 IE Insp Rept 50-285/79-07 on 790430-0503 & 05-10 No noncompliance noted Major areas inspected licensee response to IE Bulletin 79-06B  
KELLY, D L, WESTERMAN, T F, MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/24, 1pp

7907030128 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director, 79/05/29 1p.

7907200361 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31 1p.

7907110742 Ack receipt of 790511 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/79-05 Requests addl info re security force retraining  
MADSEN, G L Region 4, Dallas, Office of the Director 79/06/06 1p

7907190407 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" No action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06 1p.

7907060020 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07 1p.

7907020445 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20 1p

7907120375 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21 1p

7907020014 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus"  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907120588 Notifies util of error on 790625 forwarding ltr for IE Bulletin 79-13 No action will be required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25 1p

7907100395 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26 1p

7907180381 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28 1p

7907210212 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02 1p

7907190503 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11 1p

7907240401 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13 1p

7907260332 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Dewatered Water Sys at PWR Plants" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/17 1p

7907260239 Notifies that written responses to IE Bulletin 79-13, Suppl 1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director, 79/07/18 1p

#### R Periodic operating reports & related correspondence

7907180395 Forwards monthly operating rept for June 1979  
SHORT, T E Omaha Public Power District 79/07/12 1p

--7907180398 Monthly operating rept for June 1979  
HICKLE, B J Omaha Public Power District, 79/07/09 10pp

#### S Reportable occurrences, LERs & related correspondence

7907030258 Forwards PNO-79-67AQ, "Nuclear Incident at TMI"  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch, 79/05/31 1p

7907020298 Forwards PNO-79-67AR  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/05 1p

7907030181 Forwards PNO-79-67AB  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/13 1p.

7907030284 Forwards PNO-79-67AT, "Nuclear Incident at TMI."  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch, 79/06/19 1p

7907180327 Forwards PNO-79-67AU  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/27, 1p

# DOCKETED ITEMS

0674 Forwards PND-79-67AV & AW  
EN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
ch 79/07/10 1p

0933 Forwards LER 79-013/03L-0  
EHS, R L Omaha Public Power District 79/07/16 1p

230543 LER 79-013/03L-0 on 790625 during normal operation, hot leg  
up indications C/TI-122H failed low Caused by power supply  
failure due to blown fuse GE/MAC power supply Model GR700  
placed & sys returned to normal  
IE, M R Omaha Public Power District 79/06/25 3pp

## 50-286 INDIAN POINT STATION, UNIT 3

ity, medical, emergency & fire protection plans

0717 Forwards request for addl info re proposed alternate  
down capability & NRC position re fire protection at  
ity  
NCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/21

0301 Forwards Class III application fee for review of safeguard  
agency plans under protest pending final determination  
quality of fee schedule  
P J Power Authority State of New York 79/07/13 2pp

1462 Submits responses to request for addl info & NRC positions  
re protection program review Fire barriers will be  
lled between cable trays having redundant safety  
ed cables w/four oversized drawings  
P J Power Authority State of New York 79/07/17 23pp

## dicatory correspondence

794 Affidavit stating familiarity w/contents of June 1979  
ent on efficiency of epibenthic sled for collecting  
in 1978 Rept prepared by TX Instruments, Inc for util  
ONE, J R Consolidated Edison Co of New York 79/06/06 1p

312 Avers familiarity w/contents of "1976 Year Class Rept for  
plant Impact Study of Hudson River Estuary," May 1979.  
its of rept are true  
ONE, J R Consolidated Edison Co of New York 79/06/15 1p

## iting license stage documents & correspondence

07 Summary of 790426 meeting w/utls to discuss Westinghouse  
design re TMI-2 event  
A Reactor Systems Branch 79/05/02 39pp

090 Forwards NRC 790315 ltr to licensees of Westinghouse  
op plants re rod bank exchange method for verifying  
own margin of two-loop NSSB  
ICER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15

79 Responds to 790126, 0202 & 0316 ltrs re proposed license  
Meeting has been tentatively scheduled for early May  
cess proposed changes No hearings planned  
H M R Office of Nuclear Reactor Regulation 79/05/18 4pp

67 Discusses plans to install communication links between NRC &  
r facilities for emergency use Direct lines from each  
ty to NRC headquarters & regional ofc will communicate  
ional & environ info  
H H Region 1, Philadelphia, Office of the Director  
22 2pp

## 77 Notice of issuance & availability of Amend 26 to License

ICER, A Operating Reactors Branch 1 (Pre 790625) 79/05/31

81 Forwards Amend 26 to License DPR-64, safety evaluation &  
of issuance & availability  
ICER, A Operating Reactors Branch 1 (Pre 790625) 79/05/31

0587 Amend 26 to License DPR-64 to require actuation of safety  
mentation based on two-out-of-three channels of low  
surizer pressure  
ENCER, A Operating Reactors Branch 1 (Pre 790625)  
5/31, 15pp.

0592 Safety evaluation supporting Amend 26 to License DPR-64  
Operating Reactors Branch 1 (Pre 790625). 79/05/31 4pp

7907180697 Summary of 790522-23 meeting w/utls & United Engineers &  
Constructors in NY re seismic analysis  
OLSHAN, L Operating Reactors Branch 1 (Pre 790625) 79/06/01  
3pp

7907190126 Forwards safety evaluation of safety injection sys actuation  
Tech Specs change request  
LAINAS, G Plant Systems Branch 79/06/08 2pp

--7907190131 Safety evaluation supporting safety injection sys actuation  
Tech Spec change request  
\* Plant Systems Branch 79/06/08 2pp

7907240554 Forwards NRC 790604 ltr to Westinghouse requesting addl info  
re small break LOCA analyses & analysis methods NRC will  
eventually require documentation re applicability of  
Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11  
2pp

7907250013 Forwards NUREG-0560, "Staff Rept on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W " w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp

7907050337 Forwards more clearly reproduced copies of revised pages of  
ETB for 790412 application for amend re thermal plume  
mapping  
BLATT, M Consolidated Edison Co of New York 79/06/26 12pp

7907100590 Submits info requested on PWR feedwater lines, in response to  
NRC 790525 request Two oversized drawings encl  
EARLY, P J Power Authority State of New York 79/07/03 37pp

7907190803 Responds to FOIA request for NRC Annual Rept 1978, recent NRC  
studies of TMI rept indicating methods to cool down TMI core  
& EIS for Indian Point facility & BNL Forwards NRC Annual  
Rept 1978 w/o encl  
FELTON, J M Division of Rules and Records 79/07/06 1p

7907240293 Requests that "Rept on Small Break Accident for Westinghouse  
NSSB Sys," WCAP-7600, transmitted to NRC on 790629, be  
included in docket  
EARLY, P J Power Authority State of New York 79/07/20 1p

7907300393 Forwards "Efficiency of 100-Ft Beach Seine for Estimating  
Shore Zone Densities at Night of Juvenile Striped Bass,  
Juvenile White Perch & Yearling & Older White Perch "  
Affidavit & Certificate of Svc encl  
CAHILL, W J Consolidated Edison Co of New York 79/07/24 5pp

--7907300409 "Efficiency of 100-Ft Beach Seine for Estimating Shore  
Zone Densities at Night of Juvenile Striped Bass, Juvenile  
White Perch & Yearling & Older White Perch," submitted on  
behalf of Con Ed  
\* Texas Instruments, Inc 79/07/24 122pp

## G Inspection reports, IE Bulletins & correspondence

7907130299 Forwards IE Insp Rept 50-286/79-07 on 790321-23 No  
noncompliance noted  
CARLSON, R T Region 1, Philadelphia, Reactor Construction &  
Engineering Support Branch 79/04/25 2pp

--7907130306 IE Insp Rept 50-286/79-07 on 790321-23 No noncompliance  
noted Major areas inspected eddy current testing & plugging  
of steam generator tubes  
SANDERS, W F, TRIPP, L E Region 1, Philadelphia, Office of the  
Director. 79/04/12 4pp

7907180430 Forwards IE Insp Rept 50-286/79-05 on 790218-0317 No  
noncompliance noted  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear  
Support Branch 79/05/17 3pp

--7907180437 IE Insp Rept 50-286/79-05 on 790218-0317 No noncompliance  
noted Major areas inspected plant operations, access control  
area, physical protection, site emergency drill & radioactive  
waste mgmt sys  
REBELOWSKI, T, JOHNSON, D, KEITH, R Region 1, Philadelphia,  
Reactor Operations Nuclear Support Branch 79/05/15 11pp

7907060398 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys." licensee  
action required  
GRIER, B. H Region 1, Philadelphia, Office of the Director  
79/05/22 1p



7907240608 Forwards results of preliminary review of licensee responses to IE Bulletin 79-04, 06A & 06A Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907120030 Forwards requalification training program statistics as requested in IE Bulletin 79-10  
BAYNE, J P Power Authority State of New York 79/05/25 3pp

7907030050 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907050249 Responds to IE Bulletin 79-11 Westinghouse Type DB50 or DB75 breakers w/overcurrent protection are not utilized in safety-related sys  
BAYNE, J P Power Authority State of New York 79/05/31 1p

7907190861 Submits addl info to 790525 response to IE Bulletin 19-10 Corrects typographical errors Requalification training program statistics encl  
BAYNE, J P Power Authority State of New York 79/05/31 3pp

7907200126 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190694 Responds to IE Bulletin 79-04 re Velan valve weight data compared to actual weights Attachment lists seismic category one lines containing Velan valves w/identification & tabulation of weights used in original piping analysis  
EARLY, P J Power Authority State of New York 79/06/01 3pp

7907190087 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060114 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907100476 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230689 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907240185 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p

7907120519 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100348 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Metl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907110029 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907020228 Provides further response re IE Bulletin 79-07 & supplements 790424, 0522, 24, 27 & 31 ltrs, justifying continued operation while pipe stress reanalysis & re-evaluation continue  
EARLY, P J Power Authority State of New York 79/06/29 10pp

7907180790 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907090383 Submits suppl info for IE Bulletin 79-07 re backing of plates & anchor bolt assemblies possessing insufficient DBE conservatism Mods are now being designed  
EARLY, P J Power Authority State of New York 79/07/03 2pp

7907250520 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p

7907170046 Forwards weekly status rept as of 790706 re IE Bulletin 79-07 on pipe stress reanalysis  
EARLY, P J Power Authority State of New York 79/07/10 2pp

7907270349 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907200283 Forwards map of Westinghouse Model 44 steam generator tubes to be inspected Requests comments on proposed insp program by 790813  
EARLY, P J Power Authority State of New York 79/07/16 2pp

7907310520 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

7907270218 Forwards IE Bulletin 79-07 weekly status rept as of 790720 Discusses United Engineers & Constructors piping reanalysis efforts for critical lines per util 790531 ltr  
EARLY, P J Power Authority State of New York 79/07/23 2pp

#### R Periodic operating reports & related correspondence

7907170007 Forwards monthly operating rept for June 1979  
BAYNE, J P Power Authority State of New York 79/07/11 1p

--7907170010 Monthly operating rept for June 1979  
CONNELL, C Power Authority State of New York 79/07/02 6pp

7907200291 Forwards 790712 weekly status rept re pipe stress reanalysis efforts for critical lines  
EARLY, P J Power Authority State of New York 79/07/16 2pp

#### S Reportable occurrences, LERs & related correspondence

7907100423 Forwards LER 79-006/01T-0  
BAYNE, J P Power Authority State of New York 79/07/05 1p

--7907100432 LER 79-006/01T-0 on 790621 advised by vendor Westinghouse of error in analysis of high energy line breaks inside containment No corrective action needed, since suggested setpoint change is already in effect  
QUIMBLE, F W Power Authority State of New York 79/07/05 2pp

7907160342 Forwards LER 79-019/04T-0  
O'TOOLE, J D Consolidated Edison Co of New York 79/07/09 1p

--7907160353 LER 79-019/04T-0 on 790619 activity of Eastview 790430 sample exceeded ten times control station level Caused by tritium releases of manufacturer near station  
BADLON, S Consolidated Edison Co of New York 79/07/06 2pp

#### DOCKET 90-287 OCONEE NUCLEAR STATION, UNIT 3

#### F Security, medical, emergency & fire protection plans

7907030312 Advises that some mods required by fire protection safety evaluation will not be completed by 790701 Submits schedule of current status of mods  
PARKER, W D Duke Power Co 79/06/29 3pp

7907190228 Forwards license fee for 790323 safeguards contingency plan submittal  
PARKER, W D Duke Power Co 79/07/13 1p

#### G. Adjudicatory correspondence

7906220164 Forwards petition for reconsideration of 790507 order permitting Units 1 & 2 to remain in operation w/encl "Effect of Closing Oconee Nuclear Plants on Ability to Meet Summer Peak Demands "  
WEISS, E.R. Union of Concerned Scientists 79/03/10 1p

# DOCKETED ITEMS

--790622016B Union of Concerned Scientists petition for immediate reconsideration of order of 790308 & for immediate shutdown of Oconee Units 1 & 2  
WEISS, E R Union of Concerned Scientists 79/05/10 6pp

7907020475 Denies util petition ofr reconsideration of Commissioner 790307 order re shutdown of Facilities Petition is moot re timing of shutdown  
CHILK, S J Office of the Secretary of the Commission 79/05/18 1p

7907090431 Denies request for immediate plant shutdown & revocation of OLS Copy of decision encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907090440 Decision denying request by Palmetto Alliance for immediate shutdown of Facility & revocation of OLS  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 2pp

--7907090445 Requests immediate shutdown of Facility & revocation of OLS  
HOLT, B Palmetto Alliance 79/04/27 1p

Operating license stage documents & correspondence

907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation Pressurizer level info request list encl  
SHEHANSKI, P Division of Project Management 79/04/19 2pp

907120742 Forwards Duke Power 790425 ltr re augmented auxiliary feedwater provisions  
MATTHEW, R J Division of Systems Safety 79/04/26 1p

707140361 Forwards consensus of 790501 meeting re extrapolated conclusions for Rancho Seco & proposed changes to Oconee order  
ROBB, D Systematic Evaluation Programs Branch (Pre 790625) 79/05/02. 30pp.

07100200 Forwards Duke Power Co ltrs indicating planned changes in response to TH1-2 events & IE Bulletins  
BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/08 1p

07060448 Summarizes 790503-07 trip rept. Emergency feedwater test & NAC-1 fuel shipment cask measurements observed  
HARDIN, A K Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 79/05/10 3pp

95230543 Forwards revised sys concept & analysis re addition of two motor-driven emergency feedwater pumps Supersedes 790510 submittal. W/oversized drawing  
PARKER, W O Duke Power Co 79/05/17. 10pp

79020312 Requests util demonstrate acceptable flow rates & flow stability w/two operating steam driven emergency feedwater pumps Requests development of Tech Specs for limiting conditions SER & FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/18 4pp

907020316 SER of licensee's compliance w/NRC order dtd 790507  
\* Office of Nuclear Reactor Regulation 79/05/18 23pp

907020319 "Notice of Authorization to Resume Operation."  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/18 3pp

7310235 Evaluation of util compliance w/NRC 790507 order. Util has documented actions taken in response to order Util must provide schedule of long-term mods. Operation of plant may resume  
Office of Nuclear Reactor Regulation 79/05/18 23pp

710225 Forwards LER re loss of pressurizer level indication presents questions to be addressed during review of long-term implications of TH1 W/o encl  
BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/25 1p

020397 Submits 790530 daily digest for Westinghouse reactors.  
SB, D. F. Division of Project Management 79/05/30 1p

230589 Forwards Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & 7-55, respectively, safety evaluation, EIA & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625). 79/06/19 3.

--7907230595 Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55, respectively, changing common Tech Specs to allow increase in spent fuel storage capacity from 336 to 750 fuel assemblies in Units 1 & 2 common spent fuel pool  
ORMES, B K Operating Reactors Branch 4 (Pre 790625) 79/06/19 12pp

--7907250600 Safety evaluation supporting Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/19 13pp

--7907250601 EIA re mod of spent fuel pool  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/19 27pp

--7907250606 Notice of issuance & availability of Amends 72, 72 & 69 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/19 2pp

7907230495 Forwards Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22 3pp

--7907230502 Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to support operation at full-rated power during Cycle 5  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22 52pp.

--7907230517 Safety evaluation supporting Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/22 7pp

--7907230532 Notice of issuance & availability of Amends 73, 73 & 70 to Licenses DPR-38, DPR-47 & DPR-55, respectively  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22. 2pp

7907200211 Forwards notice of issuance of Amends 73, 73 & 70 to DPR-38, DPR-47 & DPR-55, respectively  
INGRAM, R Operating Reactors Branch 4 (Pre 790625) 79/06/28 1p

--7907200224 Notice of issuance of Amends 73, 73 & 70 to DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs re core reload & power level cutoff  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/22 2pp

7907190535 Submits check for 790321 license amend application Amend concerns qualifications of site health physicist  
PARKER, W O Duke Power Co 79/07/13 1p

7907240734 Forwards addl info re proposed license amend permitting unmonitored individuals in area surrounding Warehouse 4 for unlimited periods of time  
PARKER, W O Duke Power Co 79/07/17 4pp

7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
WEISLER, O O Babcock & Wilcox Co 79/07/20 2pp

7907300311 Discusses Phase 2 of multiphase program to evaluate effects of asymmetric LOCA loads in conjunction w/B&W 177 fuel assembly owners' group Program is in response to NRC 780125 ltr described Phase 2 of program  
PARKER, W O Duke Power Co 79/07/23 1p

Q Inspection reports, IE Bulletins & correspondence

7907160072 Comments on 790410 licensee response to IE Bulletins 79-05 & QSA.  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/10. 3pp.

7907020072 B&W site inspector daily rept on 790419 Plant status, no major engineering safety feature sys equipment out of svc Discussed plant supervisor shift logs  
JAPPE, F Region 2, Atlanta, Office of the Director 79/04/19. 1p

7907020108 B&W site inspector daily rept on 790416 Plant status; all reactors operating at nearly full power No major maint & all engineering safety feature equipment operational  
BELISLE, O A. Region 2, Atlanta, Office of the Director 79/04/16 2pp

7907020139 B&W site inspector daily rept on 790418 Plant status reactor at full power w/no major engineering safety feature equipment out of svc No major maint scheduled  
JAFE,F Region 2, Atlanta, Office of the Director 79/04/18 1p

7907160023 Forwards I&E Region 11 evaluation of licensee's response to IE Bulletin 79-05A  
VARGA,B A Light Water Reactors Branch 4 79/04/19 1p

--7907160030 Comments on licensee 790413 response to IE Bulletin 79-05 & 05A  
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/19 2pp

7905240452 Responds to IE Bulletin 79-05, Item 3, re TH1 incident Reactor protective sys high RCB pressure setpoint lowered to not greater than 2,300 psig Pressurizer power operated relief valve raised nominally to 2,450 psig  
PARKER,W O Duke Power Co 79/04/21 1p

7907020349 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl."  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110319 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907050277 Forwards proposed amend to OL in response to IE Bulletin 79-05B Proposed revision reflects changes to setpoints of pressurizer automatic relief valve & RCB high pressure trip  
PARKER,W O Duke Power Co 79/05/21 11pp

7907110427 Forwards response to Items 5 & 7 of IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl." W/o encl  
PARKER,W O Duke Power Co 79/05/21 1p

7907110095 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907100106 Responds to IE Bulletin 79-10 Submits table of requalification training program statistics  
PARKER,W O Duke Power Co 79/05/25 3pp

7907030093 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907180883 Responds to IE Bulletin 79-04 Review of all Seismic Category I piping sys determined that 1,500 psi Velan check valves installed in 3-inch discharge line of each HPI pump Reanalysis of affected piping initiated.  
PARKER,W O Duke Power Co 79/05/30 2pp

7907200186 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required.  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907110574 Ack receipt of 790524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08.  
SUTHERLAND,J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/04 1p.

--7907110579 Responds to NRC 790430 ltr re violations noted in IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 Corrective actions new calibr technique has been approved & space efficiency factors determined for swipe detectors  
PARKER,W.O. Duke Power Co 79/05/24 3pp

--7907110583 Forwards IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 on 790314-15 & notice of violation  
SUTHERLAND,J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 2pp.

--7907110590 Notice of violation from insp on 790314-15  
\* Region 2, Atlanta, Office of the Director 79/04/24 2pp.

--7907110596 IE Insp Repts 50-269/79-08, 50-270/79-08 & 50-287/79-08 on 790314-15 Noncompliance noted failure to follow calibr procedure & failure to use proper calibr source  
MONTGOMERY,D M, GIBSON,G T, HUFHAM,J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/24 4pp

7907190193 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/06 2pp

7907100161 Forwards IE Info Notice 79-15  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907260155 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/11 3pp.

7907020382 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907260350 Ack receipt of IE Insp Repts 50-269/79-12, 50-270/79-12 & 50-287/79-12 No proprietary info  
PARKER,W O Duke Power Co 79/06/20 1p

7907120061 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110217 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907310009 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/25 2pp

7907110263 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907260055 Ack receipt of IE Insp Rept 50-287/79-13 on 790531-0601 & 0606-08 No proprietary info  
PARKER,W O Duke Power Co 79/06/26 1p

--7907260062 Forwards IE Insp Rept 50-287/79-13 on 790531-0601 & 0606-08 No noncompliance noted  
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/21 2pp.

--7907260076 IE Insp Rept 50-287/79-13 on 790531-0601 & 0606-08 No noncompliance noted Major areas inspected concrete expansion anchor testing procedures, work activities & records.  
AND,W P., HERDT,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/19 4pp

7907180597 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/28 2pp.

7907310234 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/02 2pp.

7907310369 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/11 1p.

7907200245 Forwards revised pages of inservice insp program adding request for relief for full-stroke testing valves LP-29 & 30 & modifying request for relief for valve HP-20.  
PARKER,W.O Duke Power Co 79/07/16 6pp

## DOCKETED ITEMS

## R Periodic operating reports &amp; related correspondence

7907180476 Forwards monthly operating rept for June 1979  
PARKER, W D Duke Power Co 79/07/13 1p

--7907180481 Monthly operating rept for June 1979  
REAVIS, L A Duke Power Co 79/07/13 6pp

## S Reportable occurrences, LERs &amp; related correspondence

7907110537 Forwards LER 78-011/01T-0 Implications of event apply to all three units  
PARKER, W D Duke Power Co 78/04/21 2pp

7907110552 Forwards RD 78-011 re ECCS analysis at pump suction of reactor coolant piping  
PARKER, W D Duke Power Co 78/04/26 1p

--7907110560 RD 78-011 ECCS analysis of 0.04 square ft break revealed that break occurring at pump discharge would be more limiting if assumed that HP1 pump is available for core cooling. Results indicate core is always covered by fluid  
PARKER, W D Duke Power Co 78/04/14 2pp

7907110546 Forwards LER 78-012/03L-0 Implications of event apply to all three units  
PARKER, W D Duke Power Co 78/05/19 1p

7907110376 Forwards LER 78-014/03L-0  
PARKER, W D Duke Power Co 78/06/08 1p

--7907110393 LER 78-014/03L-0 on 780425 between 780425-0513, field flashing breaker failed to operate properly. Caused by malfunctioning breaker. Breaker replaced  
WILSON, K R Duke Power Co 78/06/08 8pp

## U Congressional/Executive Correspondence

7907160184 Ack receipt of KE Cornell 790930 memo re records requested by Senate Subcommittee on Nuclear Regulation Documents  
790606 telcon re Ofc of Nuclear Regulatory Research risk assessment review of Oconee 3  
SCROGGINS, R M Administrative and Resource Control Staff  
79/06/06 1p

## V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present.  
AHRENDY, B Jefferson Pilot Broadcasting 79/06/20 2pp

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp

## DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

## G Inspection reports, IE Bulletins &amp; correspondence

7907230564 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22 1p

7907230760 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/06 1p

## DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

## F Security, medical, emergency &amp; fire protection plans

7907110514 Submits calculation results re fire protection safety evaluation. Item 3 & 11, interior hose station standpipes less than 4 inches in diameter.  
HERBEIN, J O Metropolitan Edison Co 79/07/05 1p.

7907170077 Forwards summary of study re adequacy of fire detection sys. Requests approval of proposed additions contained in 790316 ltr & concurrence w/existing detection sys when supplemented w/proposed additions.  
HERBEIN, J O Metropolitan Edison Co 79/07/11 2pp

7907190568 Advises of 790705-06 tests confirming adequacy of asbestos board fire barriers  
HERBEIN, J O Metropolitan Edison Co 79/07/13 1p

--7907190581 Notifies of revised conceptual design of alternate shutdown station as result of TMI incident. Will submit design for review by 790930. Proposed implementation date of end of 1981 remains unchanged.  
HERBEIN, J O Metropolitan Edison Co 79/07/13 1p

## G Adjudicatory correspondence

7907300447 Request by Environ Coalition on Nuclear Power that Director of Nuclear Reactor Regulation, NMSS & IE permanently revoke DL w/prejudice  
JOHNSRUD, J H Environmental Coalition on Nuclear Power 79/06/29 10pp

## H General correspondence

7906200417 Forwards list of NRC personnel receiving access key & cards for TMI-1. Info partially withheld Social Security numbers (ref FOIA Exemption 6)  
SLODDIEN, M J Region 1, Philadelphia, Office of the Director  
79/05/04 5pp

## P Operating license stage documents &amp; correspondence

7907190724 FOIA request for communications between TMI personnel & NRC, between various NRC ofcs & for log books of licensing & operating project managers for TMI  
WEISS, E R Sheldon, Harmon & Roisman 79/04/06 2pp

7907060136 FOIA request for documents relating to TMI  
RUBY, R The Sun Baltimore, MD 79/04/10 1p

7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation. Pressurizer level info request list encl  
SHEHANSKI, P Division of Project Management 79/04/19 2pp

7907260054 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
GRIER, D H Region 1, Philadelphia, Office of the Director  
79/05/22 2pp.

7907060131 Responds to FOIA request for documents & communications re TMI Forwards "Title List - Publicly Available Documents - TMI Unit 2 - Docket 50-320" & printout w/o encl  
FELTON, J M Division of Rules and Records 79/06/07 1p

7907240399 Notification of 790611 meeting w/util to discuss open items for TMI-1 startup  
DIANNI, D Operating Reactors Branch 4 (Pre 790625) 79/06/07 1p

7907180639 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 1p

7907110236 Summary of 790611 meeting w/util to discuss proposed actions prior to TMI startup  
TAM, P ACRS - Advisory Committee on Reactor Safeguards 79/06/13 2pp

--7907110241 Emergency plan for facility  
\* Metropolitan Edison Co 79/06/11 11pp

7907190268 Discusses cracks in decay heat piping. Additional leaks have been found. J Collins & A Yaboda will be on site 790628 or 29 to obtain more info.  
NOONAN, V B Engineering Branch 79/06/26 1p.

7907050379 Submits short-term mods/actions to be taken prior to startup. Recertification of TMI-1 operators requested from NRC. Long-term mods & accomplishment of addl items will be undertaken. Description of mods encl  
HERBEIN, J O Metropolitan Edison Co 79/06/28 6pp

7907300471 Notifies of tentative arrangements for initial meeting w/General Public Util re TMI-1 restart. Requests comments re format & scope of meeting, attendees & actions to be completed before meeting.  
HELFEMEYER, C J Standardization Branch 79/07/03 3pp

7907190731 Responds to FOIA request for communications between TMI personnel & NRC between various NRC ofcs & for log books of licensing & operating project managers for TMI  
FELTON, J M Division of Rules and Records 79/07/06 2pp

7907200302 Forwards info re feedwater line cracking, in response to NRC 790523 request Rept by B&W on Feedwater header & nozzle weld procedures will be forwarded by 790727  
HERBEIN, J G Metropolitan Edison Co 79/07/13 4pp

7907170189 Advises of inability to meet 790715 deadline for draft radiological effluent Tech Spec submittal Requests approval of 15-day extension  
HERBEIN, J G Metropolitan Edison Co 79/07/17 1p

7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
GEISSLER, G O Babcock & Wilcox Co 79/07/20 2pp

#### Q Inspection reports, IE Bulletins & correspondence

7907120740 "Form NRC-766 Statistical Data Audit Rept, June 1973-Apr 1977"  
\* Office of I&E, Executive Officer for Management & Analysis  
79/04/11 400pp

7907060388 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907030037 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200108 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907200501 Forwards IE Insp Rept 50-289/79-11 on 790419-21 No noncompliance noted  
BRUNNER, E J Region 1, Philadelphia, Office of the Director  
79/05/31 2pp

--7907200504 IE Insp Rept 50-289/79-11 on 790419-21 No noncompliance noted. Major areas inspected plant operations areas in cold shutdown  
HAVERKAMP, D R ; KEIMIG, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/30 4pp

7907190662 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060103 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907090240 Responds to IE Bulletin 79-01 Completed rereview program described in IE Circular 78-08 Use of stem-mounted limit switches on safety-related sys inside containment does not include model numbers identified  
HERBEIN, J G Metropolitan Edison Co. 79/06/07 2pp.

7907110510 Ack receipt of 790208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/78-25 & 50-320/78-38  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/08 1p

--7907110521 Responds to NRC 790117 ltr re violations noted in IE Insp Repts 50-289/78-25 & 50-320/79-38 Corrective actions: soldering iron was unplugged & cardboard boxes were removed from cable spreading room  
HERBEIN, J G Metropolitan Edison Co 79/02/08 4pp

--7907110529 Forwards IE Insp Repts 50-289/78-25 & 50-320/78-38 on 781212-15 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/01/17 2pp

--7907110538 Notice of violation from insp on 781212-15.  
\* Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/01/15, 2pp.

--7907110542 IE Insp Repts 50-289/78-25 & 50-320/78-38 on 791212-15 Noncompliance noted failure to control combustibles, failure to fully implement procedures & failure to implement SER commitment  
GAIGE, L W ; EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/01/15 9pp

7907180854 Notifies that response to IE Bulletin 79-01A will be forwarded 790712 More time is needed for preparation of response  
HERBEIN, J G Metropolitan Edison Co 79/06/15 1p

7907110370 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230677 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240154 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907180365 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys Piping" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director.  
79/06/25 1p

7907060190 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907180615 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907310505 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R Periodic operating reports & related correspondence

7907100653 Forwards monthly operating rept for May 1979  
HERBEIN, J G Metropolitan Edison Co 79/07/03 1p

--7907100654 Monthly operating rept for May 1979  
STANLEY, W S Metropolitan Edison Co 79/06/28 3pp

7907270190 Forwards monthly operating rept for June 1979  
HERBEIN, J G Metropolitan Edison Co 79/07/17 1p

--7907270194 Monthly operating rept for June 1979  
MITCHELL, D G Metropolitan Edison Co 79/07/05 3pp

#### S Reportable occurrences, LERs & related correspondence

7907190514 RO 79-12/1P on 790619 during insp of phosphor bronze operating rods on relays, relay 62X2B/RC1A failed in energized position Caused by wear on operating rod  
Corrective action under investigation  
SEELINGER, J L Metropolitan Edison Co 79/06/19 1p

7907190598 RO 79-13/1P on 790620 leakage noted in 10-inch suction piping from borated water storage tank between valves  
BH-V5A/R & MU-V14A/B Probably caused by residual stress resulting in intergranular stress corrosion cracking  
SEELINGER, J L Metropolitan Edison Co 79/06/21 1p

7907110323 Updates LER 79-011/03X-0, dtd 790516, re abnormal degradation of spent fuel cooling sys Cracks in valve SF-V17 were caused by intergranular stress corrosion Crack sections will be replaced w/304L stainless steel  
HERBEIN, J G Metropolitan Edison Co 79/06/30 4pp

7907180472 Forwards LER 79-013/01T-Q.  
HERBEIN, J G Metropolitan Edison Co. 79/07/05 1p

## DOCKETED ITEMS

--7907180475 LER 79-013/01T-O on 790620 leakage discovered on 10-inch suction piping from borated water storage tank between valves DH-V5A/B & MU-V14A/B Caused by residual weld stresses  
STANLEY, W S Metropolitan Edison Co 79/07/05 1p

7907180477 Forwards LER 79-012/01T-O  
HERBEIN, J G Metropolitan Edison Co 79/07/06 1p

--7907180482 LER 79-012/01T-O on 790618 relay 62x2B/RC1A failed to drop out when coil was de-energized Caused by notch in operating rod of 4B relays inspected, 25 notches were found & removed  
STANLEY, W S Metropolitan Edison Co 79/07/06 2pp

#### T Hearing transcripts on non-antitrust matters

7907170093 Transcript of 790629 public meeting in Washington, DC re order on TMI-1 Pg 1-17  
HENDRIE, J M, GILINSKY, V, BRADFORD, P A Commission 79/06/29 18pp

#### DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

#### F Security, medical, emergency & fire protection plans

7907060488 Notifies that NRC method of dealing w/licenses has changed IE Region 1 presently has responsibility for technical review of emergency plan  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/05/08 2pp

7907060078 Concurs w/finding that changes to security plan do not decrease effectiveness of plan Approved security plan now consists of submittals dtd 790108 & 0214. Documents will be withheld (ref 10CFR2 790).  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/05/10 2pp

7907160304 Forwards responses to NRC request for supplementary info to proposed OL amend re fire protection program Oversized drawing encl  
CORRY, A F Boston Edison Co 79/07/06 7pp

7907240253 Proposes to qualify existing fire protection pipe within suitable distance to withstand worst case quake loads, in lieu of BER requirement for guard pipe to protect motor control center B-18 from pipe failure  
ANDOGNINI, G C Boston Edison Co 79/07/17 1p

#### G Adjudicatory correspondence

7907090357 Notifies of receipt of summons & complaint, Outaoukas vs Boston Edison Co & GE, alleging exposure to fuel rods sold by GE caused death of AD Outaoukas from widespread cancer  
ALTON, C G American Nuclear Insurers, 79/07/02 1p

7907100647 Forwards complaint LA Outaoukas vs Boston Edison Co & GE re alleged death of plant employee from overexposure  
ANDOGNINI, G C Boston Edison Co 79/07/02 7pp

#### H. General correspondence

7907260708 Forwards license fee  
ANDOGNINI, G C Boston Edison Co 79/07/18 2pp

#### F Operating license stage documents & correspondence

7907260033 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907180898 Forwards request for addl info re degraded grid voltage in order to complete review of Util 770824 submittal  
LAINAS, G Plant Systems Branch 79/06/06 3pp

7907180607 Forwards NUREG-0360, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl.  
GRINES, B K Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 2pp

7907310470 Discusses points made during 790511 telcon re replacement of position indication limit switches on MBIV at first unscheduled shutdown of reactor after receipt of environmentally-qualified equipment.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/07/06 2pp

7907190004 Summarizes 790601 site visit to inspect breakwater  
JOHNSON, T L Hydrology Meteorology Branch 79/06/19 2pp

7907250404 FOIA request for all documentation of any facility wastewater discharges into Plymouth Bay  
RING, D C Silver Lake News Pembroke, MA 79/06/22 1p

7907030250 Forwards corrections to typographical errors in 790221 submittal re Proposed Change 79-2, "Radiological Effluents & Environ Monitoring Tech Specs"  
HOWARD, J E Boston Edison Co 79/07/02 14pp

7907230447 Forwards proposed Tech Spec mod to App A of License DPR-35 w/appropriate Class IV fee, re average power range monitor setpoints, duration of integrated primary containment leak rate test & auto blowdown timer  
CORRY, A F Boston Edison Co 79/07/06 1p

--7907230449 Proposed Tech Specs modifying App A of License DPR-35 re average power range monitor setpoints, duration of integrated primary containment leak rate test & auto blowdown timer  
\* Boston Edison Co 79/07/23 18pp

7907190396 Forwards GE rept on seismic analysis of recirculation sys using P18YS & Teledyne Engineering rept on seismic analysis of C main steam line using STARDYNE Rept available in Central Files only  
ANDOGNINI, G C Boston Edison Co 79/07/11 1p

7907250413 Ack receipt of 790622 & 26 FOIA requests for records of wastewater discharges from facility info available in LPDR  
FELTON, J M Division of Rules and Records 79/07/13 4pp

#### G Inspection reports, IE Bulletins & correspondence

7907020225 Responds to items of IE Bulletin 79-08 No Tech Spec changes required  
COUNSIL, W G Northeast Utilities 79/05/14 1p

7907020221 Submits supplemental response to IE Bulletin 79-08 No Tech Spec changes required as result of implementing items 1-10  
ANDOGNINI, G C Boston Edison Co 79/05/15 1p

7907060373 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/05/22 1p

7907090374 Summary of 790518 meeting w/util, GE & Teledyne Engineering Svc in Bethesda, MD to discuss results of seismic piping stress reanalysis conducted in connection w/IE Bulletin 79-07  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/05/23 13pp

7907190680 Responds to IE Bulletin 79-09 GE Type AK-2 Circuit Breakers used in safety-related sys, but do not contain undervoltage device  
ANDOGNINI, G C Boston Edison Co, 79/05/23 2pp

7907240616 Concludes that requirements set forth in IE Bulletin 79-07 re seismic piping stress reanalysis will be adequately met to allow resumption of operation on completion of mod Safety evaluation encl  
IPPOLITO, R A Operating Reactors Branch 3 (Pre 790625), 79/05/25 2pp

--7907240627 Safety evaluation re review of piping reanalysis per IE Bulletin 79-07  
\* Engineering Branch, 79/05/25 3pp

7907030016 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/27 1p

7907200078 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/05/31 1p

7907190040 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves)" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/06/06 1p

7907060079 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/07 1p

7907200431 Ack receipt of 790320 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-293/79-04  
 BRUNNER, E J Region 1, Philadelphia, Office of the Director  
 79/06/19 1p

--7907200444 Responds to NRC 790426 ltr re violation noted in IE Insp Rept 50-293/79-04 Corrective actions necessary steps taken to conform w/Tech Spec requirement of 50% reactor power limitation  
 ANDRONINI, G C Boston Edison Co 79/05/20 2pp

--7907200453 Forwards IE Insp Rept 50-293/79-04 on 790320-23 & notice of violation  
 BRUNNER, E J Region 1, Philadelphia, Office of the Director  
 79/04/26 2pp

--7907200460 Notice of violation from insp on 790320-23  
 \* Region 1, Philadelphia, Office of the Director 79/04/25 1p

--7907200469 IE Insp Rept 50-293/79-04 Noncompliance noted failure to conduct surveillance test per Tech Specs re reactor power limitation  
 ZIMMERMAN, R P, KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 79/04/25 6pp

7907100466 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/20 1p

7907200462 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts"  
 Action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/21 1p

7907240128 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/23 1p

7907120476 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/25 1p

7907060172 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required.  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/26 1p

7907100491 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/28 1p

7907180746 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/02 1p

7907250490 Forwards IE Info Notice 79-18, "Bkylab Reentry" No action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/06 1p

7907270316 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required.  
 ORIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/11 1p

7907310482 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
 ORIER, B H Region 1, Philadelphia, Office of the Director.  
 79/07/16 1p

#### R. Periodic operating reports & related correspondence

7907200231 Forwards monthly operating rept for June 1979.  
 MCCQUIRE, P J Boston Edison Co. 79/07/12. 1p.

--7907200232 Monthly operating rept for June 1979  
 WHITNEY, G G Boston Edison Co 79/07/09 6pp

#### S Reportable occurrences, LERs & related correspondence

7907110307 RO 79-019/01X-0 on 790705 informed that Bechtel had discovered calculation error re Amend 34 to FBAR that could have effect of higher analyzed compartment peak pressures for assumed pipe breaks Caused by erroneous assumption  
 MATHIS, C J Boston Edison Co 79/07/05 1p

7907190308 RO 79-019/01X-0 on 790705 informed of Bechtel miscalculation in support of Amend 34 to FBAR, causing higher compartment peak pressures for assumed pipe breaks Caused by erroneous assumption that truck lock doors open  
 MATHIS, C J Baltimore Gas & Electric Co 79/07/05 1p

7907160315 Forwards LER 79-020/03L-0  
 MCCQUIRE, P J Boston Edison Co 79/07/09 1p

--7907160324 LER 79-020/03L-0 on 790610 broken belts found on standby gas treatment sys exhaust fan 210A Caused by belt age Belts replaced & sys returned to svc  
 MATHIS, C J Boston Edison Co 79/07/09 2pp

7907200309 Forwards LER 79-024/03X-0  
 MCCQUIRE, P J Boston Edison Co 79/07/09 1p

7907200314 LER 79-024/03X-0 on 790619 surveillance test S.M 3-11 re reactor protection sys instrument response time not performed since Nov 1975 Caused by scheduling inadequacy  
 Test performed satisfactorily on 790630  
 FULTON, J M Boston Edison Co 79/07/09 1p

7907170191 LER 79-021/01X-0 on 790710 water observed dripping from lagging on control rod drive return line Cause unknown  
 Visual surveillance increased to every 4-h & plans in progress to shutdown for repairs  
 MATHIS, C J Boston Edison Co 79/07/11 1p

7907190323 RO 79-021/01X-0 on 790710 during performance of maint in steam tunnel area, water observed dripping from lagging on control rod drive line return Cause unknown  
 MATHIS, C J Pacific Gas & Electric Co 79/07/11 1p

7907190322 Forwards LER 79-023/03L-0  
 MCCQUIRE, P J Boston Edison Co. 79/07/16 1p

--7907190525 LER 79-023/03L-0 on 790616 during routine testing, noted that closing times for AO-203-1A & E greater than allowable limits. Caused by changes in characteristics of hydraulic operators Operators adjusted  
 MATHIS, C J Boston Edison Co 79/07/16 1p

7907200275 RO 79-022/01X-0 on 790713 during evaluation of seismic restraints, discovered that two pipe supports did not meet original specs Caused by design error Made in progress  
 MATHIS, C J Boston Edison Co 79/07/16 1p

7907240237 RO 79-025/01X-0 on 790717 during final valve lineup in preparation for plant startup, both doors to drywell were inadvertently opened simultaneously w/coolant temp 212 F Caused by failure of latch for inner door Door sealed  
 MATHIS, C J Boston Edison Co 79/07/17 1p

7907260486 Forwards LER 79-021/01T-0  
 MCCQUIRE, P J Boston Edison Co 79/07/19 1p

--7907260492 LER 79-021/01T-0 on 790710: water dripping from lagging on control rod drive line. Caused by pinhole leak adjacent to inboard weld on 3-inch inboard manual isolation valve Unit shut down Valve replaced w/pipe.  
 FULTON, J M Boston Edison Co. 79/07/18 2pp.

7907260495 Forwards LER 79-019/01T-0.  
 MCCQUIRE, P J Boston Edison Co 79/07/19 1p

--7907260703 LER 79-019/01T-0 on 790708 error discovered in calculation utilized to support Amend 34 to FBAR. Model assumed reactor bldg truck lock door open to atmosphere. Erroneous computer runs corrected & new analysis performed.  
 FULTON, J M Boston Edison Co 79/07/18 2pp

7907260738 Forwards LER 79-022/01T-0  
 MCCQUIRE, P J Boston Edison Co 79/07/19 1p.

## DOCKETED ITEMS

7907240745 LER 79-022/01T-0 on 790713 during evaluation of seismic restraints, pipe supports on HPC1 test line downstream of test valve & on RHR crossline failed to meet SSE specs Caused by design error Supports modified  
FULTON, J M Boston Edison Co 79/07/19 1p

7907240667 Forwards LER 79-025/01T-0  
MCQUIRE, P J Boston Edison Co 79/07/20 1p

--7907260679 LER 79-025/01T-0 on 790717 while completing valve lineup for startup w/coolant temp of 212 F, doors in drywell personnel hatch left open Caused by incomplete startup list instructions Procedure revised to incorporate instructions  
FULTON, J M Boston Edison Co 79/07/19 1p

7907300310 Forwards LER 79-026/03L-0  
MCQUIRE, P J Boston Edison Co 79/07/24 1p

--7907300312 LER 79-026/03L-0 on 790708 while performing surveillance test B 7 4 4, MSIV timing, MSIV A-203-ID(inboard) closed within 2 s-s Caused by leaking nipple in hydraulic sys on valve operator leak repaired & hydraulic sys refilled  
FULTON, J M Boston Edison Co 79/07/25 1p

#### DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

##### P Operating license stage documents & correspondence

7907310605 Discusses Interagency Policy Committee of Personnel Radiation Monitoring activities re Univ of MI test program of personnel dosimetry which shows large numbers of dosimetry processors are not able to meet new std  
LEISS, J E Commerce, Dept of 79/04/06 2pp

7907310602 Ack receipt of NRC 790404 ltr re Univ of MI pilot testing program of personnel dosimeters Reviews results of NBS insp of irradiation facilities, irradiation geometries examinations, calibr procedures & recordkeeping plans  
EISENHOWER, E H Commerce, Dept of 79/03/01 2pp

##### Q Inspection reports, IE Bulletins & correspondence

7907240266 Ack receipt of 790518 ltr informing NRC of steps taken to correct violations noted in IE insp rept  
HIND, J A Region 3, Chicago, Safeguards Branch 79/06/05 1p

--7907240267 Responds to NRC 790430 ltr re violation noted in IE insp rept Corrective actions withheld (ref 10CFR2 790)  
TERRY, S H, CARRICK, J T Michigan State Univ 79/03/18 1p

7907230429 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/22 1p

7907240025 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/09 1p

#### DOCKET 50-293 ZION NUCLEAR POWER STATION, UNIT 1

##### F Security, medical, emergency & fire protection plans

7907200381 Submits Classes III & I fees for Safeguards Contingency Plans  
REED, C Commonwealth Edison Co 79/07/12 2pp

7907200330 Forwards Revision 2, interim physical security plan. Plan withheld (ref 10CFR2 790)  
REED, C, Commonwealth Edison Co 79/07/23 1p

##### G Adjudicatory correspondence

7907050437 Discusses options for scheduling depositions Addl round of depositions necessary to cover NRC expert witness on accidents  
STEPTOE, P Isham, Lincoln & Beale 79/05/08 2pp

7907170250 Forwards SAND77-1371, NUREG/CR-0649, "Spent Fuel Heatup Following Loss of Water During Storage " W/o encl.  
GOODDARD, R J Branch 2 79/05/11. 1p.

7907060248 Third set of interrogatories & request for production of documents directed to applicant Certificate of Svc encl  
SCOTT, W J Illinois, State of, 79/05/14 6pp

7907090475 Advises of util support for NRC 790427 motion for summary dispositions 2(a)-(c) No further util response will be forthcoming  
STEPTOE, P Commonwealth Edison Co 79/05/21 1p

7907180134 Testimony of GC Minor on behalf of State of IL re spent fuel racking relating to Contentions 2(e), 2(f), 2(h), 2(j) & 4(a) Resume & Certificate of Svc encl  
SEKULER, B N Illinois, State of 79/05/22 27pp

7907200175 State of IL opposition to NRC motion for summary disposition of Contentions 2(a)-2(d) Certificate of Svc, supporting documentation, GC Minor 790522 Affidavit & IL Commerce Commission 790509 order encl  
SCOTT, W J Illinois, State of 79/05/22 45pp

7907180346 Commonwealth Edison Co response to intervenors third set of interrogatories & request for documents Supporting documentation & Certificate of Svc encl  
BIELAWSKI, A P Isham, Lincoln & Beale 79/05/23 9pp

7907060344 Forwards testimony of TR Tramm, GJ Pliml, RL Kraatz, GA Hussein, LB Bean, AB Johnson, et al, addressing issues of ASLB 790122 order following prehearing conference Certificate of Svc encl  
BIELAWSKI, A P Isham, Lincoln & Beale 79/03/29 6pp

--7907060345 Testimony on Contentions 2(a), 2(f) & 2(g) re environ effects, heavy drops causing liner tear & pool boiling & ASLB Questions 4(c), 4(d) & 4(f) re postulated accidents Supporting documentation encl  
TRAMM, T R Commonwealth Edison Co 79/05/29 60pp

--7907060347 Testimony on Contention 2(b) re present need to increase spent fuel storage capacity  
PLIML, G J Commonwealth Edison Co 79/05/29 7pp

--7907060349 Testimony on Contention 2(c) re economic benefits of continued operation of facility  
KRAATZ, R L Commonwealth Edison Co 79/05/25 7pp

--7907060351 Testimony on Contention 2(f)(i) re analysis of fuel bundle drop  
HOBSEIN, G A Nuclear Services Corp 79/05/25 12pp

--7907060355 Testimony re Contention 2(f), administrative controls to avoid stored fuel damage during racking, Contention 2(i) re QA & ASLB Question 4(e) re fuel handling accident emergency procedures  
LEIDER, J P Commonwealth Edison Co 79/05/29 22pp

--7907060360 Testimony re ASLB Questions 4(a) & 4(b) covering security program & risk of theft & sabotage  
BEAN, L B Commonwealth Edison Co, 79/05/25 13pp

--7907060365 Testimony re Contentions 2(h) & 2(i) covering spent fuel & pool rack matl long-term performance Spent fuel storage studies written & published by AB Johnson encl  
JOHNSON, A B Battelle Memorial Institute, Pacific Northwest Laboratory 79/05/31 118pp

--7907060369 Testimony re Contentions 2(k) & 2(e) covering QA for neutron absorbing spent storage racks for facility  
SHEWSKI, W J Commonwealth Edison Co 79/05/25 11pp

--7907060371 Testimony re ASLB Question 4(b) covering emergency planning Supporting documentation encl  
PEOPLES, D L Commonwealth Edison Co 79/05/25 22pp

7907130004 Intervenor State of IL fourth set of interrogatories & request for documents directed to Comm Ed Certificate of Svc encl  
SEKULER, B N Illinois, State of 79/05/29 4pp

7907130009 Notice requesting Comm Ed to produce JC Bukovski for deposition, w/all documents re current estimates of reserve capacity for 1979-1985 Certificate of Svc encl  
MARKEY, A K Illinois, State of, 79/05/29 3pp.

7907130276 Testimony of PQ Cleary on behalf of State of IL re mod of spent fuel pool Since uncertainty re adequacy of emergency plan already exists, increased hazard makes re-evaluation of plans essential Supporting documentation encl  
CLEARY, P Q Citizens for a Better Environment 79/05/29 56pp.

7907130488 Requests permission to make appearance at 790611 public hearing.  
PETERSON, B Affiliation Unknown, 79/05/29 1p



7907230186 Forwards NRC supplemental testimony by GG Zech, Al Tolston, FM Almeter, E Lantz, JJ Zudans, JE Kohler, RM Lobel, JN Donohew & DM Kunihiro  
QDDARD, R G Branch 2 79/05/29 1p

--7907230208 Testimony re Contentions 2(a) & (b) Adopts 790329 EIA on proposed mod Prof qualifications encl  
ZECH, G G Division of Operating Reactors 79/05/29 4pp

--7907230213 Testimony re Contention 2(c) re necessity of closing facility Adopts Sections 7 5 & 7 6 of EIA re proposed mod of spent fuel pool at facilities Prof qualifications encl  
TOLSTON, A L Antitrust & Indemnity Group 79/05/29 4pp

--7907230226 Testimony re Contentions 2(a)(3), 2(a)(4), 2(b)-(k) re spent fuel components Prof qualifications encl  
ALMETER, F M Engineering Branch LANTZ, E Division of Operating Reactors 79/05/29 21pp

--7907230239 Testimony re Contention 2(f)(1) Adopts JL Zudans testimony & Section 2 3 of NRC safety evaluation rept on proposed mod re installation of racks & fuel handling  
ZECH, G G Division of Operating Reactors 79/05/29 2pp

--7907230268 NRC testimony re Contention 2(f)(2) on development of all credible accident scenarios Proposed mod does not give rise to any unreviewed scenarios Prof qualifications encl  
ZUDANS, J J Engineering Branch 79/05/29 4pp

--7907230276 Supplemental testimony re Contention 2(f)(2), relating to possible accident damage to spent fuel assemblies during installation & fuel assembly transfers Prof qualifications encl  
KOHLE, J E Region 3, Chicago, Office of the Director 79/05/29 3pp

--7907230345 Testimony re Contention 2(g) relating to applicant discussion of spent fuel boiling Prof qualifications encl  
LOBEL, R M Division of Operating Reactors DONOHEW, J N Plant Systems Branch LANTZ, E Environmental Evaluation Branch (Pre 790625) 79/05/29 12pp

--7907230351 Testimony re Contention 2(i) relating to failure of applicant to describe procedures preventing use & installation of defective racks  
KOHLE, J E Region 3, Chicago, Office of the Director 79/05/29 4pp

--7907230356 Testimony on ASLB Questions 4(a) & (b) re whether proposed mod increase risk of threats, theft or industrial sabotage, or decrease physical protection level Testimony of JR Bears re Question 4(b) encl  
KUNIHIRO, D M Division of Operating Reactors 79/05/29 13pp

--7907230361 Testimony re ASLB Questions 4(c)-(f) relating to postulated accidents analyzed in FSAR, BER, environ rept & FES utilized in CP & OL licensing reviews  
DONOHEW, J N Plant Systems Branch, ZUDANS, J J Engineering Branch 79/05/29 9pp

--7907230364 Testimony re ASLB Question (4)(e) relating to procedures developed for protection of workmen from accidents during mods of spent fuel pool  
KOHLE, J E Region 3, Chicago, Office of the Director 79/05/29 2pp

7907130059 Testimony of M Resnikoff on behalf of State of IL re possibility of water boiling in spent fuel pool & consequences of coolant accident  
RESNIKOFF, M Illinois, State of 79/05/30 26pp

7907110706 Testimony re Contentions 2(a)(3), 2(a)(4), 2(f) & 2(k) relating to corrosion in general, surveillance program, possible boreal corrosion & swelling & possible degeneration of boreal density, W/supporting documents  
DRALEY, J E Argonne National Laboratory 79/05/31 79pp.

7907130013 Affidavit forwarding JR Bears supplemental testimony on ASLB Question 4(b), re emergency planning issue Affidavit & Certificate of Svc encl  
QDDARD, R J Branch 2, 79/05/31, 12pp.

7907310138 State of IL motion requesting adoption of suggested schedule for 790611-23 hearing re conduct & presentation of evidence. Certificate of Svc encl  
BEKUL, B N Illinois, State of, 79/06/01 6pp

7907060342 Grants NRC 790427 motion for summary disposition re State of IL Contentions 2(b) & 2(c) Denies motion re Contention 2(a) Contention 2(d) withdrawn per stipulation between IL & NRC  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/04, 1p

7907230528 Forwards 790611 limited appearance statement  
TIPPEL, J Affiliation Unknown 79/06/14 1p

--7907230533 Limited appearance statement re spent fuel assemblies stored in util & consequent radioactive waste products produced through fissioning process  
TIPPEL, J Affiliation Unknown 79/06/11 8pp

#### P Operating license stage documents & correspondence

7907030142 FOIA request for records re leaks in spent fuel pool  
GUIO, C Pollution Environmental Problems 79/04/20 1p

7907120207 Summary of 790426 meeting w/utls to discuss Westinghouse plant design re TH1-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310569 Forwards NRC 790515 ltr to licensee of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSS W/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p

7907060133 FOIA request for documents re incidents, accidents & mishaps involving facilities  
HANDLER, B J Zion, IL 79/05/21 2pp

7907260089 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907300306 Corrects 790525 rept on confirmatory measurements program for second quarter of 1979  
FIROVED, J L, WANDKE, N E Commonwealth Edison Co 79/06/04 1p

7907060150 Responds to 790521 FOIA request for records re facility incidents, accidents or mishaps Records available at LPDR, Zion-Benton Public Library, 2600 Emmaus Avenue, Zion, IL Submits list of categories of info at LPDR  
FELTON, J M Division of Rules and Records 79/06/05 5pp

7907240540 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods, NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250006 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907030139 Responds to FOIA request for records re leaks in spent fuel pool Forwards list of documents available in LPDR.  
FELTON, J M Division of Rules and Records 79/06/12 5pp.

7907270189 Forwards Amends 50 & 47 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/18 2pp

--7907270193 Amends 50 & 47 to Licenses DPR-39 & DPR-48, respectively, changing Tech Specs to modify pressure-temp operating limits to meet requirements of 10CFR50  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/18 20pp

--7907270198 Safety evaluation supporting Amends 50 & 47 to Licenses DPR-39 & DPR-48, respectively  
\* Office of Nuclear Reactor Regulation 79/06/18 3pp

--7907270204 Notice of issuance & availability of Amends 50 & 47 to Licenses DPR-39 & DPR-48, respectively  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/18, 2pp

7907090305 Submits addl info to 790102 ltr re current commitments to containment purging during normal plant operation Schedule for responding to issues re normal operation purging will be submitted by 790801.  
REED, G, Commonwealth Edison Co, 79/07/02, 3pp.

# DOCKETED ITEMS

790740031 Summary of 790628 meeting w/util in Bethesda, MD re purging & venting limits & performance of purge & vent valves during postulated LOCA  
HANNON, J N Operating Reactors Branch 3 (Pre 790628) 79/07/02 5pp

79130322 Revises 790702 ltr re purging during normal operation No purging at power at Zion will be permitted until purge valves have been analyzed & determined to be capable of closure under DBA  
REED, C Commonwealth Edison Co 79/07/05 1p

79190475 Forwards Tech Spec revisions deleting sensitivity requirements for radiation monitors measuring noble gases  
REED, C Commonwealth Edison Co 79/07/12 2pp

7907190482 Tech Spec revisions deleting sensitivity requirements for radiation monitors measuring noble gases  
\* Commonwealth Edison Co 79/07/12 2pp

7900426 Requests expeditious review & approval of request for license amend to increase allowable LOCA peaking factor limit to 1.93 based on ECCS reanalysis  
REED, C Commonwealth Edison Co 79/07/16 2pp

Inspection reports, IE Bulletins & correspondence

79180492 Forwards IE Insp Repts 50-295/79-04 & 50-304/79-05 on 90321-23 & 26-30. No noncompliance noted  
AVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/15 2pp

907180500 IE Insp Repts 50-295/79-04 & 50-304/79-05 on 790321-23 & 26-30 No noncompliance noted Major areas inspected radiation protection program review of ROs & followup of previous noncompliance items & deviations  
SCHUMACHER, M C, DUBNY, N E Region 3, Chicago, Office of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/11 11pp

79180274 Forwards IE Insp Repts 50-295/79-08 & 50-304/79-09 on 790406, 10, 11 & 23-27 & notice of violation  
EISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/16 2pp

7907180294 Notice of violation from insp on 790406, 10, 11 & 23-27  
\* Region 3, Chicago, Office of the Director 79/05/14 1p

7907180323 IE Insp Repts 50-295/79-08 & 50-304/79-09 on 790406, 10, 11 & 23-27 Noncompliance noted Tech Specs for Unit 1 violated when cross tie breaker from Unit 2 auxiliary transformer was taken out of svc  
KOHLE, J E, BOYD, D C, SPESSARD, R L Region 3, Chicago, Office of the Director 79/05/14 4pp

050004 Forwards addl response to IE Bulletin 79-06A. No need for any her Tech Spec changes Updates Items 4 & 12. Identifies lves which have control switches allowing return to accident position after resetting injection signal  
ED, C Commonwealth Edison Co 79/05/17 3pp

060281 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit breakers in use or planned for use in any safety-related s.  
ED, C Commonwealth Edison Co 79/05/17 2pp

240593 Forwards results of preliminary review of licensee responses IE Bulletins 79-06, 06A & 06A. Amend 1 Meeting owners of operating plants having Westinghouse-designed s scheduled for 790530 in Bethesda, MD  
HENCER, A Operating Reactors Branch 1 (Pre 790628) 79/05/22 1p.

180554 Forwards IE Insp Rept 50-295/79-07 & 50-304/79-08 on 790410-12, 16 & 18. notice of violation & notice of deviation  
FIS, A. B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/05/24 2pp

79180560 Notice of violation from insp on 790410-12, 16 & 18  
\* Region 3, Chicago, Office of the Director 79/05/18 1p

79180574 Notice of deviation from insp on 790410-12, 16 & 18.  
\* Region 3, Chicago, Office of the Director. 79/05/18 1p

79180587 IE Insp Repts 50-295/79-07 & 50-304/79-08 on 790410-12, 16 & 18 Noncompliance noted Failure to collect & analyze fish semiannually.  
EISMANN, M. J., ESSIG, T H Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/18. 8pp

7907180101 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
REED, C Commonwealth Edison Co 79/05/25 7pp

7907200287 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190230 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907300392 IE Insp Repts 50-295/79-11 & 50-304/79-11 on 790430-0518 No noncompliance noted Major areas inspected operator training as result of TMI. engineered safety features sys & mods to safety injection logic  
KOHLE, J E, SPESSARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/14 9pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907300280 Ack receipt of 790607 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/79-08 & 50-304/79-09  
EISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/21 1p

--7907300338 Responds to NRC 790516 ltr re violations noted in IE Insp Repts 50-295/79-08 & 50-304/79-09 Corrective actions. reinstruction of shift personnel & addition of three reviews to periodic test procedure PT-14  
REED, C Commonwealth Edison Co 79/06/07 2pp

7907050441 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907300401 Forwards supplemental response to IE Bulletins 79-06A & 79-06A, Revision 1 Submits info re transient & accident conditions, procedural reviews for engineered safety features & alignment requirements  
REED, C Commonwealth Edison Co 79/06/22 8pp

7907120691 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p.

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p.

7907100567 Forwards revised inservice insp program. Summarizes changes to classification & testing requirements of certain valves  
NAUGHTON, W F. Commonwealth Edison Co 79/06/28. 3pp

--7907100572 "Inservice Insp Program for Unit 1."  
\* Commonwealth Edison Co. 79/07/10 96pp

--7907100578 "Inservice Insp Program for Unit 2 "  
\* Commonwealth Edison Co 79/07/10. 3pp pp.

# DOCKETED ITEMS

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907250376 Ack receipt of 790611 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/79-07 & 50-304/79-08  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/29 1p

--7907250583 Responds to NRC 790824 ltr re violations noted in IE Insp Repts 50-295/79-07 & 50-304/79-08 Corrective actions addl fish sample collected & analyzed during first semiannual period of 1979  
REED, C Commonwealth Edison Co 79/06/11 3pp

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240081 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907170093 Submits addl info re insp procedures & schedule for Bergen-Patterson hydraulic shock absorbers Future reporting will be accomplished via LER process  
REED, C Commonwealth Edison Co 79/07/12 2pp

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

## R. Periodic operating reports & related correspondence

7907180094 Submits results of analyses for second quarter of 1979 confirmatory measurements program  
FIROVED, J L Commonwealth Edison Co 79/05/25 2pp.

## S Reportable occurrences, LERs & related correspondence

7907110440 Forwards LER 79-045/03L-0,  
HANDKE, N. E. Commonwealth Edison Co. 79/06/28 1p

--7907110441 LER 79-045/03L-0 on 790610 during cold shutdown, pipe tunnel iodine radiation monitor IRTRO7B failed Caused by defective Motorola-supplied transistor 2N3711 in trip circuit Transistor replaced  
TRZYNA, G Commonwealth Edison Co 79/06/28. 1p

7907110435 Forwards LER 79-047/03L-0,  
HANDKE, N. E. Commonwealth Edison Co 79/07/02 1p

--7907110436 LER 79-047/03L-0 on 790602: fan belt for blower for pipe funnel rad monitor IRT-PRO7 failed. Caused by normal wear. Fan belt replaced w/Durkee-Atwood 390, functionally tested & returned to svc  
OBT, F. Commonwealth Edison Co. 79/07/02. 1p

7907250274 Forwards LER 79-046/03L-0  
HANDKE, N. E. Commonwealth Edison Co. 79/07/13 1p

--7907250281 LER 79-046/03L-0 on 790613 Channel 2L-459 acted erratically while in constant speed drive for nozzle insp Caused by defective zero potentiometer on Barton transmitter Component replaced & transmitter recalibr  
ROGERS, C L Commonwealth Edison Co 79/07/13 2pp

## T Hearing transcripts on non-antitrust matters

7907120249 Transcript of 790620 hearing in Zion, IL re spent fuel pool expansion Pp 1,366-1,618 Testimony of GC Minor & M Resnikoff encl  
WOLF, J, REMICK, F J, LITTLE, L W Atomic Safety and Licensing Board Panel 79/06/20 296pp

7907120201 Transcript of 790621 hearing in Zion, IL re spent fuel pool expansion Pp 1,619-1,873 Testimony of RM Label, JN Donohew, E Lantz & GA Hossain encl  
WOLF, J F, REMICK, F J, LITTLE, L W Atomic Safety and Licensing Board Panel 79/06/21 279pp

7907300184 Transcript of 790622 hearing in Zion, IL Pp 1874-2064 NRC & applicant testimony encl  
WOLF, J F, REMICK, F J, LITTLE, L W Atomic Safety and Licensing Board Panel 79/06/22 259pp  
/

## DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

### P Operating license stage documents & correspondence

7907060085 Notification of 790601 meeting to discuss containment vent & purging Proposed agenda encl  
IPPOLITO, T A. Operating Reactors Branch 3 (Pre 790625) 79/05/31 2pp

7907130048 Notification of 790601 meeting w/TVA in Bethesda, MD to discuss vent & purging operations, design of vent & purge sys, qualification of valves & electrical circuitry  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/05/31 2pp

7907250120 Summary of 790601 meeting w/TVA, BNL & LLL re containment purging during operation  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/06/12 7pp

7907060188 Forwards requested amend to Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Specs & providing justifications for proposed changes re administration, clarification & new organization  
GILLELAND, J E Tennessee Valley Authority 79/06/29 67pp

7907060354 Forwards proposed Tech Specs changes revising App A & B re radiological effluents Disputes NRC position that changes require submission of Class III fees  
GILLELAND, J E Tennessee Valley Authority 79/06/29 180pp

--7907060357 Offsite Dose Calculation Manual  
\* Tennessee Valley Authority 79/06/21 86pp

7907110452 Responds to NRC 780113 ltr re suppression pool temp transients Forwards suppression pool analysis describing temp transients resulting from safety relief valve sticking open  
MILLS, L M Tennessee Valley Authority 79/07/02. 28pp

7907260627 Forwards revised Tech Specs re inservice insp program  
MILLS, L M Tennessee Valley Authority 79/07/20 2pp

--7907260631 Revised Tech Specs re inservice insp program  
\* Tennessee Valley Authority 79/07/20 4pp

7907260764 Forwards proposed amends to Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Specs to allow flexibility during refueling outage work whenever entire nuclear core is unloaded  
MILLS, L M Tennessee Valley Authority 79/07/20 22pp

--7907260770 Proposed Tech Spec changes to allow flexibility during refueling outage work whenever entire nuclear core is unloaded  
\* Tennessee Valley Authority 79/07/20. 20pp

7907260819 Forwards revised proposed Tech Specs re radiological effluents  
MILLS, L M Tennessee Valley Authority 79/07/20. 2pp.

--7907260854 Revised proposed Tech Specs for Unit 3 re radiological effluents.  
\* Tennessee Valley Authority 79/07/20 4pp.

## DOCKETED ITEMS

7907270156 Forwards addl revision of ASME Section XI inservice pump & valve testing program Requests review  
MILLS,L M Tennessee Valley Authority 79/07/20 3pp

G Inspection reports, IE Bulletins & correspondence

7907310155 Forwards IE Insp Repts 50-259/79-09, 50-260/79-09 & 50-296/79-09 on 790312-15 & notice of violation  
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/29 2pp

--7907310159 Notice of violation from insp on 790312-15  
\* Region 2, Atlanta, Office of the Director 79/03/26 1p

--7907310165 IE Insp Repts 50-259/79-09, 50-260/79-09 & 50-296/79-09 Noncompliance noted failure to follow QA procedures  
PRICE,D S , DANCE,H C Region 2, Atlanta, Office of the Director 79/03/26 5pp

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl "  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/21 3pp

7907110339 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907060364 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/22 1p

7907100179 Responds to IE Bulletin 79-10 Submits table of requalification training statistics  
GILLELAND,J E Tennessee Valley Authority 79/05/25 4pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/29 3pp

7907200206 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907180864 Requests addl analysis of environ qualification of stem-mounted light switches,per util response to IE Bulletin 79-01 Lists criteria to be met if unqualified switches are not replaced  
LAINAS,G Plant Systems Branch 79/06/06 2pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907230056 Forwards response to IE Bulletin 79-01 No unprotected terminal blocks which must function in post-accident environ used in plant ASCO solenoid valves qualified per plant equipment design memo  
GILLELAND,J E Tennessee Valley Authority 79/06/11 10pp

7907250165 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/11 3pp.

7907230748 Ack receipt of 790523 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10  
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/18 1p

--7907230763 Responds to NRC 790501 ltr re violation noted in IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 Corrective actions reactor cleanup pump locked Door closures & alarms will be installed by Sept 1979  
GILLELAND,J E Tennessee Valley Authority 79/05/23 2pp

--7907230775 Forwards IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 on 790305-30 & notice of violation  
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp

--7907230784 Notice of violation from insp on 790305-30  
\* Region 2, Atlanta, Office of the Director 79/05/01 1p

--7907230790 IE Insp Repts 50-259/79-10, 50-260/79-10 & 50-296/79-10 on 790305-30 Noncompliance noted failure to lock doors to high radiation areas  
SULLIVAN,R F Region 2, Atlanta, Office of the Director  
DANCE,H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/27 6pp

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120104 Forwards IE Bulletin 79-02,Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110230 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/25 3pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director. 79/07/02 3pp

7907170058 Forwards proposal for concurrent cycles of inservice ineps & testing per 10CFR50.55a(g), to reduce unnecessary delays  
MILLS,L M Tennessee Valley Authority 79/07/11 3pp

7907180566 Submits revisions to requests for relief for inservice insp program forwarded 781211 & 790329 Inservice insp & hydrostatic pressure testing programs should be reviewed as soon as practical  
MILLS,L M Tennessee Valley Authority 79/07/11 6pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Dissel Fire Pump Starting Contactors." No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/07/13 3pp

R Periodic operating reports & related correspondence

7907170120 Forwards monthly operating rept for June 1979  
DENEABE,J G Tennessee Valley Authority 79/07/10 1p

--7907170126 Monthly operating rept for June 1979  
GREEN,D , THOM,T Tennessee Valley Authority 79/07/01. 37pp.

## B Reportable occurrences, LERs &amp; related correspondence

790719084B LER 78-007 is voided  
\* Tennessee Valley Authority 79/06/27 1p

7907170200 Forwards LER 79-007/03L-0  
FOX,H S Tennessee Valley Authority NRC 79/07/11 1p

--7907170205 LER 79-007/03L-0 on 790612 during performance of procedure  
SI 4.1 A-14, turbine first stage permissive pressure switches  
PS-1-B1A & D & PS-1-91A & B setpoints exceeded Tech Specs  
Caused by setpoint drift Switches recalibr  
\* Tennessee Valley Authority 79/07/11 2pp

## DOCKET 50-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR

## P Operating license stage documents &amp; correspondence

790723047B Submits proposed changes to Tech Specs  
THOMAS,J L North Carolina State Univ 79/07/10 10pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907100102 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/18 1p

7907230410 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

790724046B Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/07/06 1p

## DOCKET 50-298 COOPER NUCLEAR STATION

## F Security, medical, emergency &amp; fire protection plans

7907110741 Ack receipt of 790323 submittal re facility contingency  
plan Forwards request for addl info Request withheld (ref  
10CFR2 790)  
IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625)  
79/06/11 2pp

7907110424 Forwards design info re specific fire protection mods 90  
days prior to actual implementation, as requested in 790523  
fire protection safety evaluation  
PILANT,J M Nebraska Public Power District 79/06/28 4pp

7907200353 Forwards proposed change to Tech Spec 4.1.3 specifying  
requirements re 5-man fire brigade, to become effective  
90 days after issuance of BER  
PILANT,J M Nebraska Public Power District 79/07/17 3pp

7907240325 Forwards revised contingency plan Plan withheld  
(ref 10CFR2 790)  
PILANT,J M Nebraska Public Power District 79/07/19 1p

7907260752 Forwards Class III fee for review of safeguards contingency  
plan, in response to 790703 ltr  
PILANT,J M Nebraska Public Power District 79/07/19 2pp

## P. Operating license stage documents &amp; correspondence

7907030113 Notification that IE Region 4 has been given responsibility  
for technical review of emergency plan.  
IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625)  
79/05/08. 2pp.

7907060470 Summary of 790510 meeting w/util in Bethesda, MD re questions  
concerning Section B.O of GA program which identifies  
exceptions to NRC guidance on GA  
ROONEY,V L Operating Reactors Branch 3 (Pre 790625) 79/05/16.  
3pp

790710064B Concludes GA program description is acceptable pending  
review of exceptions to "Orange Book"(Wash+284) Exceptions  
were submitted as Section B d on 790109 & are presently  
under review  
IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625).  
79/05/21 2pp

7907260125 Discusses plans to install communication links between NRC &  
nuclear facilities for emergency use Direct lines from each  
facility to NRC headquarters & regional ofc will communicate  
operational & environ info  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/22  
2pp

790717006B Forwards Amend 57 to License DPR-46, safety evaluation &  
notice of issuance & availability  
IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625)  
79/05/23 2pp

--7907170076 Amend 57 to License DPR-46, modifying Tech Specs to permit  
operation up to 1% rated thermal power while performing  
training startups w/RHR pumps in shutdown cooling mode  
IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625)  
79/05/23 15pp

--7907170095 Safety evaluation supporting Amend 57 to License DPR-46  
\* Operating Reactors Branch 3 (Pre 790625) 79/05/23 4pp

--7907170109 Notice of issuance & availability of Amend 57 to License  
DPR-46,  
IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625)  
79/05/23 2pp

790718064B Forwards NUREG-0560, "Staff Rpt on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMSB,B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp

7907170194 Forwards proposed changes to ETS Requests separate review &  
approval by 790901 re deletion of App B ETS Section 4.1.1.1  
PILANT,J M Nebraska Public Power District 79/07/10 3pp

--7907170198 Proposed change to ETS, requesting deletion of Section  
4.1.1.1, "Surveillance, Study & Evaluation Program "  
\* Nebraska Public Power District 79/07/10 13pp

7907200260 Forwards NPDES permit & 730416 Section 401 State  
Certification Ltr, per NRC 790705 request  
PILANT,J M Nebraska Public Power District 79/07/13 2pp

--7907200262 NPDES permit, effective 751212, authorizing discharge into MO.  
River Section 401 Certification encl  
\* Nebraska, State of 75/12/12 17pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907260162 Responds to IE Bulletin 78-12 re atypical weld matl in  
reactor vessel welds Data compilation is currently under way  
by C-E, GE & util Requests extension to 790504 for info  
submittal  
PILANT,J M Nebraska Public Power District 79/03/20 1p

7907090392 Responds to NRC 790307 ltr re violation noted in IE Insp  
Rept 50-298/79-03 Corrective actions instrument 15-25299  
sent to manufacturer for calibr check & repair if required  
PILANT,J M Nebraska Public Power District 79/03/21 2pp

790703013B Forwards IE Insp Rept 50-298/79-05 on 790219-23 No  
noncompliance noted  
MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/04/19 2pp

--7907030140 IE Insp Rept 50-298/79-05 on 790219-23 No noncompliance  
noted Major areas inspected licensee Surveillance test  
program for June 1977-May 1978  
SHAFFER,W.D., JOHNSON,E.H., WHITT,K Region 4, Dallas, Office of  
the Director. 79/04/18 5pp

7907030191 Forwards IE Insp Rept 50-298/79-07 on 790416-19 No  
noncompliance noted  
MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/05/03 2pp.

--7907030195 IE Insp Rept 50-298/79-07 on 790416-19 No noncompliance  
noted Major areas inspected inservice insp program;  
procedures & work activities  
OILBERT,L.D., TOMLINSON,D.P., CONSTABLE,G.L. Region 4, Dallas,  
Reactor Operations Nuclear Support Branch 79/05/03. 4pp

7907060402 Notifies that permission has been obtained to extend  
submittal date of responses to IE Bulletins 78-12, 78-12B &  
78-12B to 790629  
PILANT,J.M. Nebraska Public Power District 79/05/07 1p.

## DOCKETED ITEMS

7907100289 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18  
1p

7907060327 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22  
1p

7907090379 Ack receipt of 790321 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-298/79-03  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/29 1p

7907190038 Forwards IE Insp Rept 50-298/79-08 on 790430-0504 No noncompliance noted  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/31 2pp

7907190049 IE Insp Rept 50-298/79-08 on 790430-0504 No noncompliance noted Major areas inspected radiation protection during refueling activities & analytical measurement results  
MURRAY, B., CAIN, C Region 4, Dallas, Office of the Director  
BROWN, O D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/05/30 9pp

07200360 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31  
1p

07190403 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06  
1p

07300472 Forwards IE Insp Rept 50-298/79-10 on 790501-04 & 14-15 & notice of violation  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/06 2pp

7907300478 Notice of violation from insp on 790501-04 & 14-15  
\* Region 4, Dallas, Office of the Director 79/06/04 1p

7907300484 IE Insp Rept 50-298/79-10 on 790501-04 & 14-15 Noncompliance noted failure to perform safety-related maint activity using latest approved revision of appropriate procedures  
JOHNSON, E H., CUPP, E A., WEBSTERMAN, T F Region 4, Dallas, Office of the Director 79/06/04 8pp

79060018 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07  
1p.

79180643 Forwards IE Insp Rept 50-298/79-09 on 790430-0503 Notice of violation withheld (ref 10CFR2 790)  
MADSEN, O L Region 4, Dallas, Office of the Director 79/06/08  
1pp

7907180653 IE Insp Rept 50-298/79-09 on 790430-0503 Two items of noncompliance found & three unresolved items noted. Details withheld (ref 10CFR2 790)  
CALDWELL, R. A., EVANS, C A. Region 4, Dallas, Office of the Director  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/08 1p

79020444 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20  
1p

7120373 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21  
1p.

79030423 Responds to IE Bulletins 79-01 & 79-01A, "Environ Qualification of Class IE Equipment." Forwards info re equipment inside & outside primary containment. Preventive maint program re ASCO solenoid valves initiated  
ILANT, J M Nebraska Public Power District 79/06/22 12pp

7240298 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." Action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/06/25  
1p.

7907100389 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26  
1p

7907120591 Notifies util of error on 790625 forwarding ltr for IE Bulletin 79-13 No action will be required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27  
1p.

7907180379 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28  
1p.

7907310210 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02  
1p

7907310623 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06  
1p

7907190502 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11  
1p

7907240316 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13  
1p.

7907260328 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Barated Water Sys at PWR Plants." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/17  
1p

7907260235 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18  
1p.

#### R Periodic operating reports & related correspondence

7907170233 Forwards monthly operating rept for June 1979  
LESSOR, L C Nebraska Public Power District 79/07/09 1p

--7907170234 Monthly operating rept for June 1979  
BORER, P J Nebraska Public Power District 79/07/09 4pp

#### B Reportable occurrences, LERs & related correspondence

7907170061 LER 79-015/03L-0 on 790525 breaker 1A8 failed to close automatically. Caused by improper operation of switch S2 in breaker 1AN Switch contacts cleaned & tested satisfactorily  
BEDNAR, L Nebraska Public Power District 79/06/23 1p

7907170054 Forwards LER 79-012/03L-0  
LESSOR, L C Nebraska Public Power District 79/05/30 2pp

--7907170057 LER 79-012/03L-0 on 790503 vessel water temp increased to 220 F w/primary containment integrity not established. Caused by omission in operating procedures. Setpoint of interlock verified & procedures revised  
WILLIAMS, M G Nebraska Public Power District 79/05/30 1p

7907170063 Forwards LER 79-013/03L-0  
LESSOR, L C Nebraska Public Power District. 79/05/30 2pp

--7907170065 LER 79-013/03L-0 on 790508 correct drywell to suppression chamber reading not established. Caused by leaking inlet purge valve. Valve repaired & leak tested  
WILLIAMS, M G Nebraska Public Power District. 79/05/30 1p

7907030252 Forwards PNO-79-67AQ, "Nuclear Incident at TMI"  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/31 1p

7907020299 Forwards PNO-79-67AR  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/06/05 1p

7907170079 Forwards LER 79-014/03L-0  
LESSOR, L C Nebraska Public Power District 79/06/08 2pp

--7907170082 LER 79-014/03L-0 on 790509 chamber vent valve for torus level transmitter was left closed. Caused by technician error. Vent valve opened & PC-LT-12 placed back into svc  
LAWRENCE, L I Nebraska Public Power District 79/06/08 1p

7907030177 Forwards PNO-79-67AB  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/13 1p

7907030223 Forwards PNO-79-67AT, "Nuclear Incident at TMI"  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/19 1p

7907170027 Forwards LER 79-015/03L-0 on 790625  
LEBBOR, L C Nebraska Public Power District 79/06/23 3pp

7907130325 Forwards PNO-79-67AU  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/27 1p

7907180671 Forwards PNO-79-67AV & AW  
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/10 1p

#### DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

##### F Security, medical, emergency & fire protection plans

7907300353 "Fire Protection in Operating Nuclear Power Stations Point Beach Units 1 & 2 BER Review," interim rept  
HALL, R E ; MACDOUGALL, E A Brookhaven National Laboratory FIN A-3107 7907300353 79/04/27 4pp

7907130097 Requests addl info re review of safeguards contingency plan transmitted w/790202 ltr Details withheld (ref IOCFR2 790)  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/31 2pp

##### G Adjudicatory correspondence

7907230213 Testimony re Contention 2(c) re necessity of closing facility. Adopts Sections 7.5 & 7.6 of EIA re proposed mod of spent fuel pool at facilities. Prof qualifications encl  
TOALSTON, A L Antitrust & Indemnity Group 79/05/29 4pp

##### P Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7906250325 Forwards Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively. safety evaluation & notice of issuance & availability  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/11 2pp

--7906250326 Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively, requiring actuation of safety injection, revising opening logic for pressurizer power operated relief valves & modifying power supplies  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/11 14pp

--7906250327 Safety evaluation supporting Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/11 5pp

--7906250328 Notice of issuance & availability of Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/11 2pp

7907260110 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
KEPPLER, J O Region 3, Chicago, Office of the Director, 79/05/22 2pp

7907310329 Forwards safety evaluation re util reanalysis of ECCS performance. Requirements fulfilled re 790428 order for mod of license.  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/04 3pp

--7907310336 Safety evaluation re util reanalysis of ECCS performance. Operation acceptable w/max of 10% steam generator tubes plugged & peaking factor limit of 2.32  
\* Operating Reactors Branch 1 (Pre 790625) 79/06/04 2pp

7907240564 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods. NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250021 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907240479 Notices of review of util 770728 submittal re TAC 10042 & 10043, degraded grid voltage. Forwards request for addl info  
LAINAS, G Plant Systems Branch 79/06/13 3pp

7907310466 Forwards safety evaluation of safety injection actuation sys resulting from mods proposed in response to IE Bulletin 79-06A  
LAINAS, G Plant Systems Branch 79/06/13 2pp

7907030372 Revises equation & definitions provided in 790524 submittal re rod worth measurements used in startup physics testing. Conclusions of 790624 ltr remain unchanged. Predictions adequate  
FAY, C W Wisconsin Electric Power Co 79/06/20 2pp

7907250094 Notification of 790706 meeting w/utill to discuss repair of cracked feedwater lines  
TRAMMELL, C M Operating Reactors Branch 1 (Pre 790625) 79/07/05 1p

7907300154 Notification of 790717 meeting w/Int'l Brotherhood of Electrical Workers in Two Rivers, WI to discuss NRC requirements w/respect to gatehouse personnel screening & psychological testing  
TRAMMELL, C M Operating Reactors Branch 1 79/07/09 2pp

7907160321 Submits Tech Spec Change Request 59 to amend Licenses DPR-24 & DPR-27. Mods address qualification requirements of Reg Guide 1.8 for radiation protection manager & provide flexibility for plant staffing  
BURSTEIN, S Wisconsin Electric Power Co 79/07/10 4pp

##### G Inspection reports, IE Bulletins & correspondence

7907260524 Forwards IE Insp Rept 50-301/79-06 on 790402-03. No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/07 2pp

--7907260526 IE Insp Rept 50-301/79-06 on 790402-03. No noncompliance noted. Major areas inspected: preparation for refueling outage, pre-fuel & fuel handling activities & maint during refueling outage  
SWANSON, E R Region 3, Chicago, Office of the Director 79/05/04 3pp

7907240622 Forwards results of preliminary review of license responses to IE Bulletins 79-06, 06A & 06, Amend 1. Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907110240 Responds to IE Bulletin 79-10. Forwards info re requalification training of reactor operators & senior operators.  
FAY, C W Wisconsin Electric Power Co 79/05/24 3pp

7907130162 Responds to IE Bulletin 78-12, "Atypical Weld Matl in Reaction Pressure Vessel Welds." Forwards Westinghouse rept re B&W rept on welds. Final rept re Unit 2 will be forwarded before 790713  
BURSTEIN, S Wisconsin Electric Power Co 79/05/29 4pp

7907240106 Forwards IE Insp Rept 50-301/79-08 on 790512. No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/29 2pp

--7907240112 IE Insp Rept 50-301/79-08 on 790512. No noncompliance noted. Major areas inspected: engineered safety features initiation logic & subsequent verification testing  
CHOULEB, N C ; WARNICK, R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/24 3pp

## DOCKETED ITEMS

7907250076 Forwards IE Insp Repts 50-266/79-03 & 50-301/79-04 on 790302.0402-06 & 10-11 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/30 2pp

--7907250079 Notice of violation from insp on 790302.0402-06 & 10-11  
Region 3, Chicago, Office of the Director 79/03/29 1p

-7907250083 IE Insp Repts 50-266/79-05 & 50-301/79-04 on 790302.0402-06 & 10-11 Noncompliance noted Failure to log axial flux difference w/flux difference alarm out of svc  
CHOULES, N C, WARRICK, R F Region 3, Chicago, Office of the Director 79/03/29 9pp

907200336 Forwards IE Bulletin 79-12, "Short Period Screams at BHR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/31 1p.

907240144 Forwards IE Insp Repts 50-266/79-06 & 50-301/79-07 on 790303-04 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/01 2pp

-7907240152 IE Insp Repts 50-266/79-06 & 50-301/79-07 on 790303-04 No noncompliance noted Major areas inspected operator awareness re details of TMI event & procedural changes resulting from IE Bulletins 79-06, 06A & 06A, Revision 1  
BOYD, D C, REYES, L A, SPEESARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/29 9pp

07190296 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

07240448 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

07060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed units  
APPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp.

07300191 Forwards IE Insp Repts 50-266/79-07 & 50-301/79-09 on 790303-04 No noncompliance noted  
MAVIB, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/13 2pp

907300194 IE Insp Repts 50-266/79-07 & 50-301/79-09 on 790303-04 No noncompliance noted Major areas inspected emergency drill, including accident assessment, licensee response, offsite agency response & drill critique  
AXELSON, W L, HIATT, J W, EBBIG, T H Region 3, Chicago, Office of the Director 79/06/11 3pp.

7020440 Forwards IE Info Notice 79-17, "Source Holder Assembly image from Misfit Between Assembly & Reactor Upper Grid late "  
EPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7120248 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base late Designs Using Concrete Expansion Anchor Bolts " Action required  
PPLER, J G Region 3, Chicago, Office of the Director 79/06/21. 1p

050455 Forwards IE Circular 79-09, "Occurrences of Split or ruptured Regulator Diaphragms in Certain Self-Contained Sealing Apparatus. " No action required  
PPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

130165 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys piping. " Action required  
PPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

060004 Forwards IE Circular 79-10, "Pipefittings Mfg from acceptable Matl " No action required  
PPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p.

100526 Forwards IE Circular 79-12, "Potential Diesel Generator Recharger Problem " No action required  
PPLER, J G Region 3, Chicago, Office of the Director. 79/06/28 1p.

7907130297 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240113 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310354 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies. " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310419 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260220 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260422 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907300286 Provides addl info to 790425 & 0502 ltr re IE Bulletin 79-07 Confirms that code limits referred to in reanalysis of four safety-related piping lines are same as in final facility description & SAR  
FAY, C W Wisconsin Electric Power Co 79/07/18 1p

R Periodic operating reports & related correspondence

7907170160 Forwards monthly operating rept for June 1979  
BURSTEIN, S Wisconsin Electric Power Co 79/07/10 1p

--7907170163 Monthly operating rept for June 1979  
\* Wisconsin Electric Power Co 79/07/03 8pp

S Reportable occurrences, LERs & related correspondence

7907250267 Forwards LER 79-010/01T-0.  
FAY, C W Wisconsin Electric Power Co 79/07/03 3pp

--7907250277 LER 79-010/01T-0 on 790620 plant safeguards actuation circuitry review indicated need for circuitry changes Caused by changes in IEEE std since plant design Mode to four applicable safeguard circuits will be performed  
BURSTEIN, S Wisconsin Electric Power Co 79/07/03 1p

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

7907190328 Forwards licensing fee for NRC review of safeguards contingency plan, per NRC 790703 ltr  
STEWART, W P Florida Power Corp 79/07/10 1p

--7907190330 Requests payment for safeguards contingency plan review & approval. Ack receipt of util 790322 ltr  
DIQGB, R M License Fee Management Branch 79/07/03 1p

H General correspondence

7907300499 Forwards list of addl NRC personnel to be admitted to facility Requests site orientation for personnel  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/08 2pp

J Insurance & indemnity information

7907230524 Forwards executed Amend 6 to Indemnity Agreement B-54.  
FREITA, J D Florida Power Corp. 79/07/17 3pp.

P. Operating license stage documents & correspondence

7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation Pressurizer level info request list encl.  
SHEMANSKI, P Division of Project Management 79/04/19 2pp.



# DOCKETED ITEMS

7907300001 Requests addl info re implementation schedule for mod acceptable as permanent solution to small break LOCA issue & economic impact of requiring mod to be installed during current outage Safety evaluation encl  
REID,R W Operating Reactors Branch 4 (Pre 790625) 79/05/29 2pp

--7907300011 Safety evaluation supporting proposed mod, to assure that for all postulated single failure conditions, HPI sys will be capable of supplying enough flow to reactor to mitigate small break LOCA  
\* Operating Reactors Branch 4 (Pre 790625) 79/05/29 7pp

7907020397 Submits 790530 daily digest for Westinghouse reactors ROSS,D F Division of Project Management 79/05/30 1p

7907110199 Forwards safety evaluation of electrical instrumentation & control aspects of proposed ECCS mod for small break LOCA  
LATINAS,O Plant Systems Branch 79/05/30 2pp

--7907110210 Safety evaluation of electrical instrumentation & control aspects of proposed ECCS mod for small break LOCA  
\* Plant Systems Branch 79/05/30 5pp

7907180905 Forwards request for addl info re degraded grid voltage in order to complete review of util 790725 submittal  
LATINAS,O Plant Systems Branch 79/06/06 3pp

7907180628 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRINES,D K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907250062 Requests registration as user of Model PB-1  
BAYNARD,P Y Florida Power Corp 79/06/15 1p

7907100393 Forwards Tech Spec Change Request 39 to delete ref to reactor coolant power pump monitors, which will not be installed prior to initial Cycle 2 startup Certificate of Bvc encl  
STEWART,W P Florida Power Corp 79/06/25 2Bpp

7907030384 Notifies that pressure alarm & recorders will be installed to augment present overpressure mitigating sys  
STEWART,W P Florida Power & Light Co 79/06/27 2pp

7907030377 Provides test results of suitability of poison matl for B4C composite proposed for high density fuel storage racks  
MOORE,Q C Florida Power Corp 79/06/27 3pp

7907030454 Summary of response to NRC 790517 order All short-term design, procedural & training commitments complete  
MOORE,Q C Florida Power Corp 79/06/29 13pp

7907100515 Forwards Tech Spec Change Request 49 (Sodium Hydroxide - Deboratation) requesting amend to App A of License DPR-72 Licensing fee & Certificate of Bvc encl  
STEWART,W P Florida Power Corp 79/07/03 4pp

--7907100519 Tech Spec Change Request 49 to amend License DPR-72 App A, changing shutdown margin requirement for Modes 4 & 5  
\* Florida Power Corp 79/07/03 11pp

7907300454 Forwards draft ltr, FR notice & safety evaluation rept re restart of plant  
DENTON,H R Office of Nuclear Reactor Regulation. 79/07/03 1p

--7907300460 Draft ltr re NRC 790516 order requiring increase in capability & reliability of plant to respond to various transient events Plant may resume operations. Schedule for long-term mod will be forwarded within 30 days  
DENTON,H R Office of Nuclear Reactor Regulation 79/07/06 2pp

--7907300463 Safety evaluation rept re license compliance w/NRC 790516 order. Requirements of order were fulfilled Plant may resume operations Long-term mod must be completed  
\* Office of Nuclear Reactor Regulation 79/07/02 31pp

--7907300476 Notice that licensee has satisfactorily completed actions, per NRC 790516 shutdown order Plant may resume operation  
REID,R W Operating Reactors Branch 4 79/07/06 2pp.

7907130397 Forwards NPDES permit FLO000159 Permit replaces previously issued permit & constitutes final determination W/780305 & 790207 ltr from FL Dept of Environ Regulations to EPA  
HARVEY,S W Environmental Protection Agency 79/07/09. 21pp

7907170119 Forwards Tech Spec Change Requests 42 & 47 re amend to App A of DPR-72 Change is required prior to startup after completion of planned ECCS mod, which could be accomplished as early as 790722  
MOORE,Q C Florida Power Corp 79/07/13 4pp

--7907170127 Tech Spec Change Requests 42 & 47 re mod to ECCS  
\* Florida Power Corp 79/07/13 25pp

7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
GEISLER,Q O Babcock & Wilcox Co 79/07/20 2pp

G Inspection reports, IE Bulletins & correspondence

7907020069 B&W site inspector daily rept on 790419 Plant status one reactor coolant pump secured to prevent seal degradation ReFueling to begin 790424  
MCHESTRY,T J Region 2, Atlanta, Office of the Director 79/04/19 1p

7907020103 B&W site inspector daily rept on 790416 Plant status reactor operating at 74% power w/one coolant pump secured to prevent seal degradation  
MCHESTRY,T J Region 2, Atlanta, Office of the Director 79/04/16 2pp

7907020145 B&W site inspector daily rept on 790418 Plant status one reactor coolant pump secured to prevent seal degradation Insp performed on control room operations  
MCHESTRY,T J Region 2, Atlanta, Office of the Director 79/04/18 1p

7907160037 Forwards IE Region 2 evaluation of licensee 790412 response to IE Bulletin 79-05A  
VAROA,B A Light Water Reactors Branch 4 79/04/19 1p

--7907160040 Comments on licensee 790412 response to IE Bulletins 79-05 & 05A  
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/19 3pp

7907020357 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl "  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/21 1p

7907160368 Draft ltr forwarding draft NRC evaluation of licensee 790409 & 12 responses to IE Bulletin 79-05A. Request for addl info encl Response required within 30 days  
\* Division of Project Management 79/04/25 22pp

7907050198 Forwards IE Insp Rept 50-302/79-11 on 790221-23 No noncompliance noted  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/04/30. 2pp

--7907050203 IE Insp Rept 50-302/79-11 on 790221-23 No noncompliance noted Major areas inspected offsite support agencies, emergency equipment, medical facilities & emergency procedures  
GIBSON,O T Region 2, Atlanta, Office of the Director  
HUFHAM,J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/27 4pp

7907110322 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/07 1p

7907100177 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director. 79/05/18. 2pp

7907060358 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director. 79/05/22 1p

7907030095 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/29. 2pp.

## DOCKETED ITEMS

907130422 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-07  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/27 1p

--7907130499 Responds to NRC 790316 ltr re violations noted in IE Insp Rept 50-302/79-07 Corrective actions portal monitor requirement will be deleted from Emergency Plan EK-100  
STEWART, W P Florida Power Corp 79/04/07 1p

--7907130500 Forwards IE Insp Rept 50-302/79-07 on 790122-26 & notice of violation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/16 2pp

--7907130504 Notice of violation from Insp on 790122-26  
\* Region 2, Atlanta, Office of the Director 79/02/26 1p

--7907130511 IE Insp Rept 50-302/79-07 on 790122-26 Noncompliance noted failure to have adequate auxiliary bldg evacuation sys & failure to have working portal monitor at guardhouse  
O'BRIEN, G T, KUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/02/26 7pp

907300040 Forwards IE Insp Rept 50-302/79-16 on 790514-15 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/30 2pp

--7907300043 IE Insp Rept 50-302/79-16 on 790514-15 No noncompliance noted Major areas inspected review of identified items of concern & followup on Part 21 repts  
DYER, J A, BURNETT, P T Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/24 3pp

907200188 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

907230481 Submits addl info to encl B&W 790313 response re IE Bulletins 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds " Forwards vendor 790313 ltr to Westinghouse Util maintains requirements met  
WHITE, L D Rochester Gas & Electric Corp 79/06/01 3pp

--7907230493 Forwards response to IE Bulletins 78-12 & 78-12A, "Records Investigation Rept Re Off-Chemistry Welds in Matl Surveillance Specimens & Responses to Bulletin 78-12&78-12A Suppl 3 " Concludes Crystal River 3 isolated event  
TAYLOR, J H Babcock & Wilcox Co, 79/03/13 2pp

907180186 Responds to IE Bulletin 79-11 Westinghouse Type DB-50 & DB-75 circuit breakers are not used in safety-related sys  
STEWART, W P Florida Power Corp 79/06/06 1p

907190168 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P, Region 2, Atlanta, Office of the Director 79/06/06 2pp

907060053 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

907250156 Requests that Region 2 measurement van be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp

907020384 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P, Region 2, Atlanta, Office of the Director, 79/06/20 1p

907120071 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p.

907110220 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/06/22 1p

7907310018 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 2pp

7907110266 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907230711 Ack receipt of 790615 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-04  
LEWIS, R C Region 2, Atlanta, Office of the Director 79/06/26 1p

--7907230721 Responds to NRC 790524 ltr re violations noted in IE Insp Rept 50-302/79-04 Corrective actions training program for electricians & mechanics implemented & improvements made to QA plan  
STEWART, W P Florida Power Corp 79/06/15 18pp

7907180433 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907310227 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 1p

7907270393 Ack receipt of 790618 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-15  
SUTHERLAND, J C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/07/03 1p.

--7907270401 Responds to NRC 790529 ltr re violations noted in IE Insp Rept 50-302/79-15 Corrective actions procedure entitled "Radioactive Matl Tagging, RP-217" prepared in review cycle  
STEWART, W P Florida Power Corp 79/06/18 2pp

--7907270402 Forwards IE Insp Rept 50-302/79-15 on 790507-11 & notice of violation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/29 2pp

--7907270403 Notice of violation from Insp on 790507-11  
\* Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/29 1p

--7907270406 IE Insp Rept 50-302/79-15 on 790507-11 Noncompliance noted failure to prepare procedures for identifying containers of radioactive matl & improper shipments of solid wastes  
JENKINS, G R, ZAVADOSKI, R W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/25 6pp

7907310378 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P, Region 2, Atlanta, Office of the Director 79/07/11 2pp

7907160253 Comments on licensee 790409 response to IE Bulletins 79-05 & 05A  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/07/17 2pp

7907300343 Submits response to NRC 790308 request for addl info re CR3 pump & valve inservice insp program. Revision to CR3 procedures will be completed within 90 days from date of NRC approval  
STEWART, W P, Florida Power Corp 79/07/25, 131pp

#### R Periodic operating reports & related correspondence

7907190440 Forwards monthly operating rept for June 1979  
STEWART, W P Florida Power Corp 79/07/16 1p

--7907190445 Monthly operating rept for June 1979.  
STEPHENSON, W A, Florida Power Corp 79/07/05 5pp

#### B Reportable occurrences, LERs & related correspondence

7907110490 LER 78-042/03L-0 on 780819 inverter VB1T-1A failed, causing isolation of decay heat removal. Caused by electronic component failure in inverter VB1T-1A inverter undergoing rectifier mods to improve reliability  
COOPER, J Florida Power Corp 78/09/11 2pp

7907030452 Forwards LER 79-055/03L-0  
STEWART, W P Florida Power Corp 79/06/28 1p

--7907030455 LER 79-055/03L-0 on 790604 reactor bldg audible source  
range neutron flux monitor & direct communication sys  
inoperable Caused by blown fuse in public address sys due to  
shorted headset Headset repaired & fuse renewed  
COOPER, J Florida Power Corp 79/06/21 2pp

7907030483 Forwards LER 79-056/03L-0  
STEWART, W P Florida Power Corp 79/06/28 1p

--7907030486 LER 79-056/03L-0 on 790604 auxiliary bldg ventilation sys  
inoperable Fan motor & blading damaged Cause unknown Fan  
motor & blading replaced  
COOPER, J Florida Power Corp 79/06/25 2pp

7907090232 Forwards LER 79-057/03L-0  
STEWART, W P Florida Power Corp 79/07/02 1p

--7907090234 LER 79-057/03L-0 on 790606 during engineered safeguards time  
response test, emergency diesel generators A & B tripped  
Caused by imbalance in reactive load on diesel generator  
Test has been revised to control imbalance of reactive load  
COOPER, J Florida Power Corp 79/06/27 2pp

7907180544 Forwards supplemental info for LER 79-058/04L-0  
STEWART, W P Florida Power Corp 79/07/02 1p

--7907180556 LER 79-058/04L-0 on 790614, supplemental info census of  
gardens producing vegetables for human consumption was not  
conducted per ETB Caused by lack of aircraft Future efforts  
will be more diligent  
\* Florida Power Corp 79/07/02 1p

7907130364 Forwards LER 79-059/03L-0  
STEWART, W P Florida Power Corp 79/07/09 1p

--7907130367 LER 79-059/03L-0 on 790613 containment leakage tests  
B&C exceeded due date of 781118, contrary to Tech Spec  
4 & 11 d Caused by personnel error. Limitations of  
surveillance procedures w/ time intervals discussed  
COOPER, J Florida Power Corp 79/07/03 2pp

7907180518 Forwards LER 79-060/03L-0  
STEWART, W P Florida Power Corp 79/07/10 1p

--7907180524 LER 79-060/03L-0 on 790613 containment purge isolation  
valves had excessive seat leakage Caused by improper seating  
of Valves Adjustments were made  
COOPER, J Florida Power Corp 79/07/06 2pp

7907180548 Forwards LER 79-061/01T-0  
STEWART, W P Florida Power Corp 79/07/12 1p

--7907180553 LER 79-061/01T-0 on 790702 pipe supports did not meet  
requirements of IE Bulletin 79-02, Revision 1 Caused by  
improper design Evaluation is being performed to upgrade  
supports to safety factor of four.  
COOPER, J Florida Power Corp 79/07/09 2pp.

7907300344 Forwards LER 79-062/01T-0  
STEWART, W P Florida Power Corp 79/07/20 1p

--7907300358 LER 79-062/01T-0 on 790717 valve operators for chemical  
addition valves CAV-1, 3, 4 & 5 had not been environmentally  
qualified for intended use. Caused by nonqualified valve  
operators. Correct operators to be installed  
COOPER, J Florida Power Corp 79/07/18 2pp

#### DOCKET 90-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4

##### P Operating license stage documents & correspondence

7907020397 Submits 790530 daily digest for Westinghouse reactors  
ROSS, D. F. Division of Project Management 79/05/30, 1p

##### Q Inspection reports, IE Bulletins & correspondence

7907160253 Comments on licensee 790409 response to IE Bulletins 79-05 &  
05A  
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support  
Branch, 79/07/17, 2pp.

#### DOCKET 90-304 ZION NUCLEAR POWER STATION, UNIT 2

##### F Security, medical, emergency & fire protection plans

7907200381 Submits Classes III & I fees for Safeguards Contingency  
Plans  
REED, C. Commonwealth Edison Co 79/07/12 2pp

7907300330 Forwards Revision 2, interim physical security plan Plan  
withheld (ref 10CFR2 790)  
REED, C Commonwealth Edison Co 79/07/23 1p

##### Q Adjudicatory correspondence

7907050457 Discusses options for scheduling depositions Addl round of  
depositions necessary to cover NRC expert witness on  
accidents  
STEPTOE, P Isham, Lincoln & Beale 79/05/05 2pp

7907170250 Forwards SAND77-1371, NUREG/CR-0649, "Spent Fuel Heatup  
Following Loss of Water During Storage " W/o encl  
GODDARD, R J Branch 2 79/05/11 1p

7907060248 Third set of interrogatories & request for production of  
documents directed to applicant Certificate of Bvc encl  
SCOTT, W J Illinois, State of 79/05/14 5pp

7907090475 Advises of util support for NRC 790427 motion for summary  
dispositions 2(a)-(c) No further util response will be  
forthcoming  
STEPTOE, P Commonwealth Edison Co 79/05/21 1p

7907180154 Testimony of QC Minor on behalf of State of IL re spent fuel  
reracking relating to Contentions 2(e), 2(f), 2(h), 2(j) &  
4(a) Resume & Certificate of Bvc encl  
BEKULER, B N Illinois, State of 79/05/22 27pp

7907200175 State of IL opposition to NRC motion for summary disposition  
of Contentions 2(a)-2(d) Certificate of Bvc, supporting  
documentation, QC Minor 790522 Affidavit & IL Commerce  
Commission 790509 order encl  
SCOTT, W J Illinois, State of 79/05/22 43pp

7907180346 Commonwealth Edison Co response to intervenors third set of  
interrogatories & request for documents Supporting  
documentation & Certificate of Bvc encl  
BIELAWSKI, A P Isham, Lincoln & Beale 79/05/23, 9pp.

7907060344 Forwards testimony of TR Tramm, QJ Pliml, RL Kraatz, GA  
Hossein, LB Bean, AB Johnson, et al, addressing issues of ABLB  
790122 order following prehearing conference Certificate of  
Bvc encl  
BIELAWSKI, A P Isham, Lincoln & Beale 79/05/29 6pp

--7907060345 Testimony on Contentions 2(a), 2(f) & 2(g) re  
environ effects, heavy drops causing liner tear & pool  
boiling & ABLB Questions 4(c), 4(d) & 4(f) re  
postulated accidents Supporting documentation encl  
TRAHM, T R Commonwealth Edison Co 79/05/29 60pp

--7907060347 Testimony on Contention 2(b) re present need to increase  
spent fuel storage capacity.  
PLIML, G J Commonwealth Edison Co. 79/05/29 7pp

--7907060349 Testimony on Contention 2(c) re economic benefits of  
continued operation of facility  
KRAATZ, R L Commonwealth Edison Co 79/05/25, 7pp

--7907060351 Testimony on Contention 2(f)(i) re analysis of fuel bundle  
drop  
HOSSEIN, G. A. Nuclear Services Corp 79/05/25 12pp

--7907060355 Testimony re Contention 2(f), administrative controls to  
avoid stored fuel damage during reracking, Contention 2(i) re  
GA & ABLB Question 4(e) re fuel handling accident emergency  
procedures  
LEIDER, J P Commonwealth Edison Co 79/05/29, 22pp

--7907060360 Testimony re ABLB Questions 4(a) & 4(b) covering security  
program & risk of theft & sabotage.  
BEAN, L. B. Commonwealth Edison Co. 79/05/25 13pp

--7907060365 Testimony re Contentions 2(h) & 2(i) covering spent fuel  
& pool rack mabl long-term performance. Spent fuel storage  
studies written & published by AB Johnson encl  
JOHNSON, A. B Battelle Memorial Institute, Pacific Northwest  
Laboratory, 79/05/31 118pp

## DOCKETED ITEMS

- 7907060369 Testimony re Contentions 2(k) & 2(e) covering QA for neutron absorbing spent storage racks for facility  
SHEWSKI, W J Commonwealth Edison Co 79/05/25 11pp
- 7907060371 Testimony re ABLD Question 4(b) covering emergency planning Supporting documentation encl  
PEOPLES, D L Commonwealth Edison Co 79/05/25 22pp
- 7907130004 Intervenor State of IL fourth set of interrogatories & request for documents directed to Comm Ed Certificate of Svc encl  
SEKULER, S N Illinois, State of 79/05/29 4pp
- 7907130009 Notice requesting Comm Ed to produce JC Bukovski for deposition, w/all documents re current estimates of reserve capacity for 1979-1985 Certificate of Svc encl  
MARKEY, A K Illinois, State of 79/05/29 3pp
- 7907130276 Testimony of PQ Cleary on behalf of State of IL re mod of spent fuel pool Since uncertainty re adequacy of emergency plan already exists, increased hazard makes re-evaluation of plans essential Supporting documentation encl  
CLEARV, P Q Citizens for a Better Environment 79/05/29 56pp
- 7907130488 Requests permission to make appearance at 790611 public hearing  
PETERSON, B Affiliation Unknown 79/05/29 1p
- 7907230186 Forwards NRC supplemental testimony by GG Zech, AI Toalston, FM Almeter, E Lantz, JJ Zudans, JC Kohler, RM Lobel, JN Donohew & DM Kunihiro  
GODDARD, R Q Branch 2 79/05/29 1p
- 7907230208 Testimony re Contentions 2(a) & (b) Adopts 790329 EIA on proposed mod Prof qualifications encl  
ZECH, G O Division of Operating Reactors 79/05/29 4pp
- 7907230226 Testimony re Contentions 2(e)(3), 2(a)(4), 2(h)-(k) re spent fuel components Prof qualifications encl  
ALMETER, F M Engineering Branch LANTZ, E Division of Operating Reactors 79/05/29 21pp.
- 7907230239 Testimony re Contention 2(f)(1) Adopts JL Zudans testimony & Section 2 3 of NRC safety evaluation rept on proposed mod re installation of racks & fuel handling  
ZECH, G O Division of Operating Reactors 79/05/29 2pp
- 7907230268 NRC testimony re Contention 2(f)(2) on development of all credible accident scenarios Proposed mod does not give rise to any unreviewed scenarios Prof qualifications encl  
ZUDANS, J J Engineering Branch 79/05/29 6pp
- 7907230276 Supplemental testimony re Contention 2(f)(2), relating to possible accident damage to spent fuel assemblies during installation & fuel assembly transfers Prof qualifications encl  
KOHLER, J E Region 3, Chicago, Office of the Director 79/05/29 3pp
- 7907230345 Testimony re Contention 2(g) relating to applicant discussion of spent fuel boiling Prof qualifications encl  
LOBEL, R M Division of Operating Reactors DONOHEW, J N Plant Systems Branch LANTZ, E Environmental Evaluation Branch (Pre 790625) 79/05/29 12pp
- 7907230381 Testimony re Contention 2(i) relating to failure of applicant to describe procedures preventing use & installation of defective racks  
KOHLER, J E Region 3, Chicago, Office of the Director 79/05/29 4pp
- 7907230354 Testimony on ABLD Questions 4(a) & (b) re whether proposed mods increase risk of threats, theft or industrial sabotage, or decrease physical protection level Testimony of JR Bears re Question 4(b) encl  
KUNIHIRO, D M Division of Operating Reactors 79/05/29 13pp
- 7907230361 Testimony re ABLD Questions 4(c)-(f) relating to postulated accidents analyzed in FSAR, BER, environ rept & FEB utilized in CP & DL licensing reviews  
DONOHEW, J N Plant Systems Branch ZUDANS, J J Engineering Branch 79/05/29 9pp.
- 7907230364 Testimony re ABLD Question 4(e) relating to procedures developed for protection of workmen from accidents during mods of spent fuel pool  
KOHLER, J E Region 3, Chicago, Office of the Director 79/05/29 2pp
- 7907130059 Testimony of M Resnikoff on behalf of State of IL re possibility of water boiling in spent fuel pool & consequences of coolant accident  
RESNIKOFF, M Illinois, State of 79/05/30 26pp
- 7907110706 Testimony re Contentions 2(e)(3), 2(e)(4), 2(j) & 2(k) relating to corrosion in general, surveillance program, possible boral corrosion & swelling & possible degeneration of boral density W/supporting documents  
DRALEY, J E Argonne National Laboratory 79/05/31 79pp
- 7907130013 Affidavit forwarding JR Bears supplemental testimony on ABLD Question 4(b), re emergency planning issue Affidavit & Certificate of Svc encl  
GODDARD, R J Branch 2 79/05/31 12pp
- 7907310138 State of IL motion requesting adoption of suggested schedule for 790611-23 hearing re conduct & presentation of evidence Certificate of Svc encl  
SEKULER, S N Illinois, State of 79/06/01 6pp
- 7907060342 Grants NRC 790427 motion for summary disposition re State of IL Contentions 2(b) & 2(c) Denies motion re Contention 2(a) Contention 2(d) withdrawn per stipulation between IL & NRC  
LUTOM, E Atomic Safety and Licensing Board Panel 79/06/04 1p
- 7907250528 Forwards 790611 limited appearance statement  
TIPPEL, J Affiliation Unknown 79/06/14 1p
- 7907250533 Limited appearance statement re spent fuel assemblies stored in util & consequent radioactive waste products produced through fissioning process  
TIPPEL, J Affiliation Unknown 79/06/11 8pp
- P Operating license stage documents & correspondence
- 7907030142 FOIA request for records re leaks in spent fuel pool  
GUIGO, C Pollution Environmental Problems 79/04/20 1p
- 7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TH1-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp
- 7907060153 FOIA request for documents re incidents, accidents & mishaps involving facilities  
HANDLER, S J Zion, IL 79/05/21 2pp
- 7907240089 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22, 2pp
- 7907060150 Responds to 790521 FOIA request for records re facility incidents, accidents or mishaps. Records available at LPDR, Zion-Benton Public Library, 2600 Emmaus Avenue, Zion, IL Submits list of categories of info at LPDR  
FELTON, J M Division of Rules and Records 79/06/05 5pp
- 7907240540 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp
- 7907250006 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 2pp.
- 7907030139 Responds to FOIA request for records re leaks in spent fuel pool Forwards list of documents available in LPDR  
FELTON, J M Division of Rules and Records 79/06/12 5pp
- 7907270189 Forwards Amends 50 & 47 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability.  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/18 2pp
- 7907270193 Amends 50 & 47 to Licenses DPR-39 & DPR-48, respectively, changing Tech Specs to modify pressure-temp operating limits to meet requirements of 10CFR50  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/18 20pp

--7907270198 Safety evaluation supporting Amends 50 & 47 to Licenses DPR-39 & DPR-4B, respectively  
\* Office of Nuclear Reactor Regulation 79/06/18 3pp

--7907270204 Notice of issuance & availability of Amends 50 & 47 to Licenses DPR-39 & DPR-4B, respectively  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/18 2pp

7907090305 Submits addl info to 790102 ltr re current commitments to containment purging during normal plant operation  
Schedule for responding to issues re normal operation purging will be submitted by 790801  
REED, C Commonwealth Edison Co 79/07/02 3pp

7907260031 Summary of 790628 meeting w/util in Bethesda, MD re purging & venting limits & performance of purge & vent valves during postulated LOCA  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/07/02 6pp

7907130322 Revises 790702 ltr re purging during normal operation  
No purging at power at Zion will be permitted until purge valves have been analyzed & determined to be capable of closure under DBA  
REED, C Commonwealth Edison Co 79/07/05 1p

7907190475 Forwards Tech Spec revisions deleting sensitivity requirements for radiation monitors measuring noble gases  
REED, C Commonwealth Edison Co 79/07/12 2pp

--7907190482 Tech Spec revisions deleting sensitivity requirements for radiation monitors measuring noble gases  
\* Commonwealth Edison Co 79/07/12 2pp

7907200426 Requests expeditious review & approval of request for license amend to increase allowable LOCA peaking factor limit to 1.93 based on ECCS reanalysis  
REED, C Commonwealth Edison Co 79/07/16 2pp

#### G Inspection reports, IE Bulletins & correspondence

7907050549 Forwards IE Insp Rept 50-304/79-04 on 790312-13 & 790403-04 & notice of violation  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/18, 2pp

--7907050552 Notice of violation from insp on 790312-13 & 790403-04  
\* Region 3, Chicago, Office of the Director 79/04/11 1p

--7907050553 IE Insp Rept 50-304/79-04 on 790312-13 & 0403-04  
Noncompliance noted failure to provide certified calibr stds for checking measuring equipment  
KEY, W J, DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/11 14pp

7907180492 Forwards IE Insp Repts 50-295/79-04 & 50-304/79-05 on 790321-23 & 26-30 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch, 79/05/15 2pp

--7907180500 IE Insp Repts 50-295/79-04 & 50-304/79-05 on 790321-23 & 26-30 No noncompliance noted Major areas inspected: radiation protection program, review of ROs & followup of previous noncompliance items & deviations  
SCHUMACHER, M C, DUBRYN, N E Region 3, Chicago, Office of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch, 79/05/11 11pp

7907310569 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSB w/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p.

7907180274 Forwards IE Insp Repts 50-295/79-08 & 50-304/79-09 on 790406, 10, 11 & 23-27 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/16 2pp

--7907180294 Notice of violation from insp on 790406, 10, 11 & 23-27.  
\* Region 3, Chicago, Office of the Director, 79/05/14 1p

--7907180323 IE Insp Repts 50-295/79-08 & 50-304/79-09 on 790406, 10, 11 & 23-27 Noncompliance noted Tech Specs for Unit 1 violated when cross tie breaker from Unit 2 auxiliary transformer was taken out of svc  
KOHLER, J E, BOYD, D. C., SPESSARD, R. L. Region 3, Chicago, Office of the Director 79/05/14, 4pp

7907050004 Forwards addl response to IE Bulletin 79-06A. No need for any other Tech Spec changes Updates Items 4 & 12 identifies valves which have control switches allowing return to preaccident position after resetting injection signal.  
REED, C Commonwealth Edison Co 79/05/17, 3pp.

7907060251 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit breakers in use or planned for use in any safety-related sys  
REED, C Commonwealth Edison Co 79/05/17 2pp

7907240593 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06A, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907180554 Forwards IE Insp Rept 50-295/79-07 & 50-304/79-08 on 790410-12, 16 & 18, notice of violation & notice of deviation  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/24 2pp

--7907180560 Notice of violation from insp on 790410-12, 16 & 18  
\* Region 3, Chicago, Office of the Director 79/05/18 1p

--7907180574 Notice of deviation from insp on 790410-12, 16 & 18  
\* Region 3, Chicago, Office of the Director 79/05/18 1p.

--7907180587 IE Insp Repts 50-295/79-07 & 50-304/79-08 on 790410-12, 16 & 18 Noncompliance noted failure to collect & analyze fish semiannually  
GERTHMAN, H J, ESSIG, T H Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/18 8pp

7907180101 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
REED, C Commonwealth Edison Co 79/05/25 7pp

7907200287 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907270104 Ack receipt of 790517 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-304/79-04  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/05 1p

--7907270115 Responds to NRC 790418 ltr re violation noted in IE Insp Rept 50-304/79-04 Corrective actions none Requests inspector to reevaluate apparent item of noncompliance & change it to observation  
REED, C Commonwealth Edison Co 79/05/17 3pp

7907190230 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director, 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp.

7907300392 IE Insp Repts 50-295/79-11 & 50-304/79-11 on 790430-0518 No noncompliance noted Major areas inspected operator training as result of TMI, engineered safety features sys & mods to safety injection logic  
KOHLER, J E., SPESSARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/14 9pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J. O Region 3, Chicago, Office of the Director 79/06/21 1p

7907300280 Ack receipt of 790607 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/79-08 & 50-304/79-09  
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/21, 1p.

## DOCKETED ITEMS

--7907300338 Responds to NRC 790516 ltr re violations noted in IE Insp Repts 50-295/79-08 & 50-304/79-09 Corrective actions reinstruction of shift personnel & addition of three reviews to periodic test procedure PT-14  
REED, C Commonwealth Edison Co 79/06/07 2pp

7907050441 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required.  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/22 1p

7907300401 Forwards supplemental response to IE Bulletins 79-06A & 79-06A, Revision 1 Submits info re transient & accident conditions, procedural reviews for engineered safety features & alignment requirements  
REED, C Commonwealth Edison Co 79/06/22 8pp

7907120691 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/25 1p

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/26 1p

907100567 Forwards revised inservice insp program Summarizes changes to classification & testing requirements of certain valves  
NAUGHTON, W F Commonwealth Edison Co 79/06/28 3pp

--7907100572 "Inservice Insp Program for Unit 1 "  
\* Commonwealth Edison Co 79/07/10 96pp

--7907100578 "Inservice Insp Program for Unit 2 "  
\* Commonwealth Edison Co 79/07/10 3pp pp

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turb charger Problem " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/28 1p

7907250576 Ack receipt of 790611 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/79-07 & 50-304/79-08  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/29 1p

7907250583 Responds to NRC 790524 ltr re violations noted in IE Insp Repts 50-295/79-07 & 50-304/79-08 Corrective actions addl fish sample collected & analyzed during first semiannual period of 1979  
REED, C Commonwealth Edison Co 79/06/11 3pp

07130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/02 1p

07240081 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required.  
KEPPLER, J Q Region 3, Chicago, Office of the Director, 79/07/06 1p

07310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/11 1p

07170053 Submits addl info re insp procedures & schedule for Jergen-Patterson hydraulic shock absorbers Future reporting will be accomplished via LER process  
REED, C Commonwealth Edison Co. 79/07/12 2pp.

07310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
EPPLER, J Q Region 3, Chicago, Office of the Director 79/07/13 1p

07260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
EPPLER, J Q Region 3, Chicago, Office of the Director, 79/07/18 1p

7260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant orated Water Sys at PWR Plants." No action required.  
EPPLER, J Q Region 3, Chicago, Office of the Director 79/07/18 1p.

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/20 1p.

#### R Periodic operating reports & related correspondence

7907180094 Submits results of analyses for second quarter of 1979 confirmatory measurements program  
FIROVED, J L Commonwealth Edison Co 79/05/25 2pp

#### T Hearing transcripts on non-antitrust matters

7907120249 Transcript of 790620 hearing in Zion, IL re spent fuel pool expansion Pp 1,366-1,618 Testimony of GC Minor & M Resnikoff encl  
WOLF, J, REMICK, F J, LITTLE, L W Atomic Safety and Licensing Board Panel 79/06/20 296pp

7907120201 Transcript of 790621 hearing in Zion, IL re spent fuel pool expansion Pp 1,619-1,873 Testimony of RM Lobel, JN Donohew, E Lantz & QA Hossein encl  
WOLF, J F, REMICK, F J, LITTLE, L W Atomic Safety and Licensing Board Panel 79/06/21 279pp.

7907300184 Transcript of 790622 hearing in Zion, IL Pp 1874-2064 NRC & applicant testimony encl  
WOLF, J F, REMICK, F J, LITTLE, L W Atomic Safety and Licensing Board Panel 79/06/22 289pp

#### DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

#### F Security, medical, emergency & fire protection plans

7907300354 Forwards modified physical security plan Plan withheld (ref 10CFR2 790)  
MATHEWS, E R Wisconsin Public Service Corp 79/07/26 1p

#### G Adjudicatory correspondence

7907180654 Orders cancellation of 790621 prehearing conference, pending further notification Parties are approaching settlement or withdrawal of action  
SMITH, I W Atomic Safety and Licensing Board Panel 79/06/20 1p

#### P Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utls to discuss Westinghouse plant design re TH1-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907260112 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/22 2pp.

7907190325 Summary of 790521 meeting w/Exxon re role in TH1-related reevaluations of operating plants  
KANE, W F Standardization Branch, 79/05/31 4pp.

7907240567 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods. NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp.

7907250025 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W." W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625). 79/06/11 2pp

7907250125 Notification of 790703 meeting w/WI Public Svc, Westinghouse & Fluor Pioneer in Bethesda, MD to discuss cracking in feedwater sys piping.  
BLEHMAN, L Operating Reactors Branch 1 79/06/28. 2pp

7907190555 Forwards "Feedwater Line Cracking," summary rept Cracks have been removed under design change program All new & repaired welds have been tested to establish baseline data & will be retested at next refueling outage.  
MATHEWS, E R Wisconsin Public Service Corp 79/07/13. 1p.

--7907190560 "Feedwater Line Cracking," summary rept.  
\* Wisconsin Public Service Corp 79/07/13 35pp.

# DOCKETED ITEMS

100

7907180521 Agrees to limit purging of containment during power operation to 90-h/yr Total purge time for yr will be under 90-h Valves to close against dynamic forces of design basis LOCA  
MATTHEWS,E R Wisconsin Public Service Corp 79/07/13 1p

## G Inspection reports, IE Bulletins & correspondence

7907050147 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/03/30 1p

7907110120 Forwards IE Insp Rept 50-305/79-05 on 790428-29 No noncompliance noted  
HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/04 2pp

--7907110136 IE Insp Rept 50-305/79-05 on 790428-29 No noncompliance noted Major areas inspected mods & verification of engineered safety features initiation logic  
SMITH,J D , STREETER,J F Region 3, Chicago, Office of the Director 79/05/03 2pp

7907050112 Forwards IE Insp Rept 50-305/79-03 on 790322-23 & 0423-24 No noncompliance noted  
FIORELLI,Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/10 2pp

--7907050117 IE Insp Rept 50-305/79-03 on 790322-23 & 0423-24 No noncompliance noted Major areas inspected spent fuel racks, QA/QC programs,implementing welding & nondestructive examination procedures & facility records  
WARD,K D , DANIELSON,D H Region 3, Chicago, Office of the Director 79/05/08 6pp

7907240625 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06,06A & 06,Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790930 in Bethesda,MD  
SCHWENGER,A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907200338 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907240623 Forwards IE Insp Rept 50-305/79-06 on 790501-02 No noncompliance noted  
HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/31 2pp

--7907240630 IE Insp Rept 50-305/79-06 on 790501-02 No noncompliance noted, Major areas inspected specific plant conditions & verify licensee actions in response to IE Bulletins 79-06, 06A & 06A,Revision 1  
BOYD,D C Region 3, Chicago, Office of the Director  
STREETER,J F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/25 7pp

7907190299 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required.  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240450 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS,H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907300419 Forwards IE Insp Rept 50-305/79-07 on 790522-24 No noncompliance noted.  
DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/11 2pp

--7907300430 IE Insp Rept 50-305/79-07 on 790522-24 No noncompliance noted Major areas inspected radwaste sys,including effluent releases,records & rept,reactor coolant water quality & solid radwaste.  
FISHER,W L , MILLER,D E Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/06/07 4pp

7907300403 Forwards IE Insp Rept 50-305/79-08 on 790531 No noncompliance noted  
DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/13 2pp

--7907300412 IE Insp Rept 50-305/79-08 on 790531 No noncompliance noted Major areas inspected licensee lab analysis,including effluent samples & liquid radwaste  
AKELSON,W L , EBSIO,T H , HIATT,J W Region 3, Chicago, Office of the Director 79/06/07 4pp

7907020441 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907300452 Responds to IE Bulletin 79-06A,Revision 1 Forwards updated & expanded responses re operating procedures for coping w/transients & accidents,containment isolation initiation design & procedures & safety-related valve positions  
MATHEWS,E R Wisconsin Public Service Corp 79/06/20 17pp

7907120269 Forwards IE Bulletin 79-02,Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907300481 Forwards IE Insp Rept 50-305/79-10 on 790611-13 No noncompliance noted  
FIORELLI,Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/21 2pp

--7907300526 IE Insp Rept 50-305/79-10 on 790611-13 No noncompliance noted Major areas inspected followup to IE Bulletin 79-02, test program & quality records.  
GALLAGHER,E J , HAYES,D W Region 3, Chicago, Office of the Director 79/06/20 5p

7907050458 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907130169 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required.  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060005 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required.  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907100521 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130300 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240120 Forwards IE Info Notice 79-18, "Btlyab Reentry " No action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310355 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/11 1p.

7907310420 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/13 1p.

7907260224 Notifies that written responses to IE Bulletin 79-15,Suppl 1, should be directed to IE Div of Reactor Const Insp.  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/18 1p.

7907260425 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants." No action required.  
KEPPLER,J G Region 3, Chicago, Office of the Director 79/07/18 1p

## DOCKETED ITEMS

## R Periodic operating reports &amp; related correspondence

7907130436 Forwards monthly operating rept for June 1979  
MATHEWS, E R Wisconsin Public Service Corp 79/07/06 1p

--7907130438 Monthly operating rept for June 1979  
WALLACE, J J Wisconsin Public Service Corp 79/07/06 4pp

## S Reportable occurrences, LERs &amp; related correspondence

7907050307 Forwards LERs 79-011/03L-0 & 79-012/03L-0  
MATHEWS, E R Wisconsin Public Service Corp 79/06/29 1p

--7907050309 LER 79-011/03L-0 on 790530 during refueling shutdown, testing indicated three of four pressurizer pressure transmitters were out of calibr Caused by instrument drift of Foxboro pressure transmitters Transmitters recalibr  
RUITER, G H Wisconsin Public Service Corp 79/06/29 1p

--7907050313 LER 79-012/03L-0 on 790530 valve S1302A had to be opened manually during maint work for line flushing Definite cause of failure not determined Procedures will be changed to allow S1302A & S1302B valves to remain open  
RUITER, G H Wisconsin Public Service Corp 79/06/29 1p

7907090281 Forwards LERs 79-013/03L-0, 79-014/03L-0 & 79-015/03L-0  
MATHEWS, E R Wisconsin Public Service Corp 79/07/02 1p

--7907090287 LER 79-013/03L-0 on 790602 four RCS flow transmitters out of calibr so that low flow reactor trip settings fell below required setpoint Caused by instrument drift of Foxboro flow transmitters Transmitters recalibr  
RUITER, G H Wisconsin Public Service Corp 79/07/02 1p

--7907090294 LER 79-014/03L-0 on 790603 containment integrity not established during refueling operations Airlift doors open while rod unlatching procedure performed Caused by absence of requirement in procedure  
RUITER, G H Wisconsin Public Service Corp 79/07/02 1p

--7907090299 LER 79-015/03L-0 on 790604 steam flow transmitter out of calibr so that steam line isolation signal trip setting was above specified setpoint Caused by instrument drift of Barton D/P transmitter Instrument recalibr  
RUITER, G H Wisconsin Public Service Corp 79/07/02 1p

7907090309 Forwards LER 79-016/01T-0  
MATHEWS, E R Wisconsin Public Service Corp 79/07/03 1p

--7907090312 LER 79-016/01T-0 on 790619 error noted in Tech Spec requirements for radioactive water storage tank water vol levels Caused by nonconservative shift in instrument readout Error corrected after pre-operational  
RUITER, G H Wisconsin Public Service Corp 79/07/03 3pp

7907170081 Forwards LERs 79-017/01T-0 & 79-018/01T-0  
MATHEWS, E R Wisconsin Public Service Corp 79/07/10 1p

--7907170085 LER 79-017/01T-0 on 790626 test results identify linear indications on inside diameter of feedwater piping at nozzles of steam generator nozzles Caused by stress/corrosion cracking Investigation underway  
RUITER, G H Wisconsin Public Service Corp 79/07/10 2pp

--7907170090 LER 79-018/01T-0 on 790626 vendor reported high energy line breaks inside containment can cause buildup of steam generator level ref lags, delaying protection signals from 1p-to steam generator trip channels Cause analysis error  
RUITER, G H Wisconsin Public Service Corp 79/07/10 2pp

7907170022 Forwards LER 79-019/04T-0  
MATHEWS, E R Wisconsin Public Service Corp 79/07/12 1p

--7907170033 LER 79-019/04T-0 on 790627 during refueling shutdown, discharge from waste neutralizing tank exceeded total solids limit Caused by personnel error Tech Specs amend will be submitted, deleting ETS from license  
RUITER, G H Wisconsin Public Service Corp 79/07/12 1p

## DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

## F Security, medical, emergency &amp; fire protection plans

7907100533 Approves fire protection program developed by Brookhaven & NRC Offers exceptions for NRC evaluation electrical valve supervision should be provided on all valves controlling fire water sys  
HALL, R E Brookhaven National Laboratory 79/06/21 3pp

7907310175 "Fire Protection in Operating Nuclear Power Stations, Prairie Island Station SER Review," interim rept  
HALL, R E, MACDOUGALL, E A Brookhaven National Laboratory FIN  
A-3107 7907310175 79/06/21 4pp

7907100618 Forwards revised util fire protection program superseding 790518 revision  
MAYER, L O Northern States Power Co 79/07/05 16pp

7907310388 Forwards supplemental info re physical security plan info withheld (ref 10CFR2 790)  
MAYER, L O Northern States Power Co 79/07/30 1p

## P Operating license stage documents &amp; correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907260103 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related reevaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907090428 Intends to ship radioactive matl from facilities, using package B3-1  
MAYER, L O Northern States Power Co 79/06/08 1p

7907240530 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250012 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIHES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907190211 Provides info re results of stress & fatigue analyses, in response to NRC 790525 request Allowable stresses have not been exceeded  
MAYER, L O Northern States Power Co 79/07/16 2pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907240607 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06A, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907110291 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
WACHTER, L J Northern States Power Co 79/05/25 3pp

7907160148 Notifies of delay in response to IE Bulletins 78-12, 12A & 12B due to late submittal by vendor of info re reactor vessel welds  
WACHTER, L J Northern States Power Co 79/05/29 1p

7907240193 Forwards IE Insp Repts 50-282/79-11 & 50-306/79-09 on 790401-30 No noncompliance noted  
HEIBMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/30 2pp

--7907240200 IE Insp Rept 50-282/79-11 & 50-306/79-09 on 790401-0430 No noncompliance noted Major areas inspected, operations, maint, security, refueling activities, review & audit, training & reportable events followup  
FEIERABEND, C D, DANIELS, F T, WARNICK, R F Region 3, Chicago, Office of the Director 79/05/29 9pp

7907200328 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p



7907190285 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240432 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07  
1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp

7907020439 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20  
1p

7907120248 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907050431 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907300455 Responds to Items 1-13 of IE Bulletin 79-06A, Revision 1, & NRC request for addl info Submits info re emergency procedures for coping w/transients & accidents, mod of pressurizer pressure & containment isolation sys  
WACHTER, L J Northern States Power Co 79/06/22 13pp

7907130138 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

7907060318 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907180422 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130282 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p

7907240104 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06  
1p.

7907310342 Forwards IE Bulletin 79-19, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310414 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260199 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/18.  
1p

7907260402 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

#### R Periodic operating reports & related correspondence

7907130196 Notifies that results of noise monitoring program performed per ETS 4 2 App B, are deemed satisfactory No further action required  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/29  
2pp.

7907030272 Forwards "Environ Monitoring & Ecological Studies Program 1978 Annual Rept," Vols 1 & 2  
WARD, E C Northern States Power Co 79/06/29 1p

--7907030275 "Environ Monitoring & Ecological Studies Program 1978 Annual Rept," Vols 1 & 2  
HESTICK, M L Northern States Power Co 79/04/30 608pp

7907180511 Forwards monthly operating rept for June 1979  
MAYER, L D Northern States Power Co 79/07/13 1p

--7907180516 Monthly operating rept for June 1979  
HUNSTAD, A A Northern States Power Co 79/07/02 4pp

#### S Reportable occurrences, LERs & related correspondence

7907090202 Environ event rept 79-05 for June 1979 daily average blowdown flow of plant circulating water sys was in excess of 150 cfs for 26 days Caused by need to accommodate cooling tower preventive maint  
WARD, E C Northern States Power Co 79/07/02 1p

7907160346 Notifies of discrepancy in design analyses performed for containment purge valves Info supplements LER 79-019 Valves will remain closed above cold shutdown conditions until closure can be assured  
MAYER, L D Northern States Power Co 79/07/10 1p

#### DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

#### F Security, medical, emergency & fire protection plans

7907250138 Notification of 790718 meeting w/util & LASL to discuss LASL confirmatory vital area analysis  
NELSON, C C Operating Reactors Branch 4 (Pre 790625) 79/06/19  
2pp

#### G Adjudicatory correspondence

7907120284 Ack receipt of 790313 ltr commenting on shutdown of five nuclear power plants in eastern US Objective is to review situation in expedited & disciplined manner so that plants can be returned to operation  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/22 1p

7907060155 Forwards termination of order to show cause, discussion of conservatism in seismic design & safety evaluation  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/24  
9pp

--7907060159 Termination of 790313 order to show cause allowing facil to be restarted  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 6p

--7907060163 Safety evaluation supporting restarting of facility  
\* Office of Nuclear Reactor Regulation 79/05/24 11pp

#### H General correspondence

7907120332 Comments on closing of five nuclear plants due to seismic testing inconsistencies NRC was unjustly criticized for doing right thing  
WASSERBACH, A E Affiliation Unknown. 79/03/26 1p

7907060147 Responds to ltr re facility shutdown info partially withheld name & address of recipient (ref FOIA Exemption 6)  
BRADFORD, P A Commission 79/04/10 1p

7907060343 Responds to 790314 ltr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord w/accepted engineering practice. Failed piping could cause LOGA Plant review is being expedited  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/09 3pp

--7907060356 Comments on incidence of seismic activity in northeast US  
SMITH, E T Affiliation Unknown 79/03/14 3pp

7907090460 Responds to 790316 telegram re orders closing five power plants in eastern US Analysis techniques used in seismic design of safety-related piping not in accord w/proven & generally accepted engineering practice  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 3pp

# DOCKETED ITEMS

90049 Responds to ltr re NRC 790313 orders to shut down plants  
' prefers to review situation in expedited & disciplined  
ner & return plants to operation w/no threat to public  
lth & safety  
NTON, H R Office of Nuclear Reactor Regulation 79/05/22 3pp

79190055 Encourages NRC to reconsider closing plant until current  
fuel crisis is resolved  
JEAN, J Affiliation Unknown 79/05/22 3pp

790498 Responds to 790315 telegram expressing opposition to plant  
shutdown due to seismic concerns Forwards earthquake maps  
NTON, H R Office of Nuclear Reactor Regulation 79/05/24 4pp

790504 Responds to 790324 ltr opposing plant shutdown due to  
seismic design concern Forwards earthquake maps  
NTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

79020506 Opposes plant shutdown Economic considerations & established  
plant safety mandate continuing operation  
ALDRICH, H N Maine Bag Co 79/03/23 2pp

7905124 Responds to 790322 ltr opposing plant shutdown due to  
seismic design concerns Forwards earthquake maps  
NTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

79050128 Opposes plant shutdown due to seismic design concerns  
MOODY, J L Maine, State of 79/03/22 1p

7905042 Responds to 790315 ltr re shutdown of five nuclear plants  
ants shut down due to inadequacy of seismic analysis  
chniques w/map showing previous earthquakes in area  
NTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

79050548 Expresses outrage at closing of five nuclear power plants  
due to possible consequences resulting from earthquakes  
BRUM, D E Peter Bent Brigham Hosp 80, Massachusetts 79/03/15  
1p

79060293 Responds to 790315 telegram opposing plant shutdown due to  
seismic design concerns Forwards earthquake maps  
NTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

79060299 Opposes shutdown of plants Plants should be allowed to  
continue to operate while seismic improvements are  
developed  
KUS, C M Affiliation Unknown 79/03/15 1p

790075 Ack receipt of 790306 ltr to PA Bradford Every effort being  
de to ensure continued protection of health & safety of  
blic at all nuclear power plants  
NTON, H R Office of Nuclear Reactor Regulation 79/06/05

79190079 Opposes nuclear power Favors permanent shutdown of nuclear  
plant in Hiscasset, ME  
BANNISTER, R W Affiliation Unknown 79/05/06 1p

790685 Ack receipt of 790423 ltr expressing concern re safety of  
cility Assures that NRC is making every effort to ensure  
ant safety  
NTON, H R Office of Nuclear Reactor Regulation 79/06/06 1p

79110691 Urges NRC to keep facility shut down until problems are  
solved  
CORREA, A G Affiliation Unknown 79/04/23 1p

790020 Responds to 790518 ltr re earthquake which occurred on  
0417. New seismic design analyses have led to mod of two  
ping supports  
NTON, H R Office of Nuclear Reactor Regulation 79/06/06 1p

790790452 Comments on 790417 earthquake near nuclear facility  
Expresses anger at being subjected to experiments for  
determining plant capacity to withstand earthquakes  
ROTH, M W Affiliation Unknown 79/05/18 1p

79180906 Responds to 790529 ltr to JM Hendrie re improvements made to  
ring facility into compliance w/NRC regulations Mods were  
ade to two piping supports for containment spray sys  
ENTON, H R Office of Nuclear Reactor Regulation 79/06/11 2pp.

79190025 Responds to 790602 ltr. Facility shut down while certain  
safety-related piping sys reanalyzed to determine response  
o earthquakes. Reanalysis completed satisfactorily & mod of  
wo piping supports initiated  
ENTON, H R Office of Nuclear Reactor Regulation 79/06/11, 1p.

--7907190082 Comments on shutdown of five east coast nuclear plants  
Objects to being forced to pay higher util rates  
MONROE, A Affiliation Unknown 79/06/02 3pp

7907190760 Discusses evacuation plan, release of radioactive matl during  
shutdown & disposal of radwaste, in response to 790525 ltr  
to President Carter  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/11 2pp

--7907190768 Opposes reopening of plant, because of lack of evacuation  
plan & lack of safe method for radwaste disposal Requests  
info re leaks of low level radiation  
NOWERS, E G. Affiliation Unknown 79/05/25 2pp

P Operating license stage documents & correspondence

7907020467 Evaluates util response to IE Bulletin 79-06B Items which  
have not been adequately addressed include containment  
isolation & continued operation of radiological control  
program  
LAZARUS, W J Region 1, Philadelphia, Office of the Director  
79/05/05 1p

7907180235 Requests info from currently operating PWRs re small break  
analysis, as followup to TMI-2 incident review  
GRIMES, D K Assistant Director for Engineers & Projects (Pre  
790625) 79/05/09 8pp

7906060069 Response to FOIA request for documents re discrepancy  
between results of original piping analysis for seismic  
stresses Info partially denied, documents w/NRC opinions  
& recommendations (ref FOIA Exemption 5)  
FELTON, J M Division of Rules and Records 79/05/21 3pp

7907260058 Discusses plans to install communication links between NRC &  
nuclear facilities for emergency Use Direct lines from each  
facility to NRC headquarters & regional ofc will communicate  
operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 2pp

7907110219 Summary of 790501 meeting w/util re SHOCK-O computer codes  
NELSON, C C Operating Reactors Branch 4 (Pre 790625), 79/05/23  
2pp

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related  
reevaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907180641 Forwards NUREG-0560, "Staff Rept on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B. K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11, 2pp

7907310411 Forwards request for addl info re degraded grid voltage in  
order to continue review of 790625 submittal  
REID, R W Operating Reactors Branch 4 (Pre 790625), 79/06/11  
3pp

7907260590 Discusses preliminary asymmetrical LOCA loads evaluation  
rept prepared by Babco Bvc, Inc Addl analyses will be  
performed on supports for pumps & steam generator to ensure  
adequacy  
GROCE, R. H. Maine Yankee Atomic Power Co 79/07/23 2pp.

7907300441 Responds to remaining items from util 790525 ltr re steam  
generator feedwater piping Response includes radiograph of  
nozzle-to-piping welds following welding No inservice insp  
has been performed on piping.  
GROCE, R. H Maine Yankee Atomic Power Co 79/07/23 2pp

7907310247 Notifies of completion of SHOCK-O/NUPIPE-SW comparisons  
which confirm conclusions re adequacy of piping analyzed by  
SHOCK-O program  
GROCE, R. H Maine Yankee Atomic Power Co 79/07/24 1p

G. Inspection reports, IE Bulletins & correspondence

7907310023 Forwards summary of 790306 meeting w/util in King of  
Prussia, PA. Info presented resulted in withdrawal of Item B  
from 781222 notice of violation  
SMITH, G. H Region 1, Philadelphia, Office of the Director  
79/05/02 2pp

--7907310027 Summary of 790306 meeting w/util in King of Prussia, PA re  
781222 notice of violation. Item 50-029/78-19-07 will be  
withdrawn  
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials  
Safety Branch 79/03/06 2pp.

# DOCKETED ITEMS

7907090102 Responds to IE Bulletin 79-09 Many GE Type K-2 circuit breakers are being used Only reactor trip breakers utilize breaker undervoltage trip device  
GROCE, R H Maine Yankee Atomic Power Co 79/05/21 3pp

7907060389 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers For Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907050258 Forwards response to IE Bulletin 79-10 re reactor operator training  
MOODY, D E Maine Yankee Atomic Power Co 79/05/23 3pp

7907050262 Submits results of records search for spec of weld matl used for fabrication of reactor pressure vessel, in response to IE Bulletins 78-12, 78-12A & 78-12B  
MOODY, D E Maine Yankee Atomic Power Co 79/05/25 2pp

7907030038 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200110 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190064 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060105 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907110373 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230679 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907240166 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p

7907120504 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907060192 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100503 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180776 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907250505 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/06 1p.

7907270339 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p.

7907310506 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

R Periodic operating reports & related correspondence

7907170116 Forwards monthly operating rept for June 1979  
WOODY, D E Maine Yankee Atomic Power Co 79/07/12 1p

--7907170118 Monthly operating rept for June 1979  
BJOGREN, R H Maine Yankee Atomic Power Co 79/07/12 3pp

E Reportable occurrences, LERs & related correspondence

7907110561 Forwards LER 79-014/03L-0  
WOOD, E C Maine Yankee Atomic Power Co 79/06/28 1p

--7907110566 LER 79-014/03L-0 on 790607 remote operating linkage for B train spray header manual isolation valve found disconnected, w/valve not fully open Caused by loose linkage set screws Valve lineup check sheet modified  
ANDERSON, P L Maine Yankee Atomic Power Co 79/06/28 1p

U Congressional/Executive Correspondence

7907230752 Notice describing reasons for shutdown of five plants  
CHILK, B J Office of the Secretary of the Commission 79/05/14 8pp

7907260009 Responds to R Shadis 790405 questions re reopening of facility, per 790426 request  
GOSBICK, L V Office of the Executive Director for Operations 79/06/19 15pp

--7907260050 Forwards R Shadis 790405 questions re reopening of facilities  
MUSKIE, E S Senate 79/04/24 3pp

7907180588 Responds to 790323 ltr re shutdown of facilities None of proposed alternatives would have adequately dealt w/situation Forwards summary of code verification program, IE Bulletin 79-07 & chronology table of pipe stress issue.  
HENDRIE, J M Commission 79/06/27 17pp

--7907180633 Requests info re evaluation of feasibility & effectiveness of safe alternative responses to error in seismic codes rather than shutdown of facilities Requests info re possibility of similar errors at other plants  
DINGELL, J D House of Rep , Interstate & Foreign Commerce 79/03/23. 2pp

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

7907160109 Draft memo re licensing strategy for plants w/fuel load dates in CY79.  
BOYD, R S Division of Project Management 79/03/28 6pp.

7907260072 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp.

7907110262 Summary of 790509 meeting w/util in Bethesda, MD re seismic qualification of 600-volt vital switchgear used at facility.  
CHEN, P Y Mechanical Engineering Branch 79/06/01 2pp

7907110281 Requests addl info re instrumentation qualification for manually controlling reactor conditions & basis for acceptability of Barton 763 measured error re Westinghouse rept on Barton pressure testing.  
PARR, O D Light Water Reactors Branch 3. 79/06/01. 2pp

7907060435 Notifies that application fee has not been received. Payment should be forwarded within 15 days.  
MILLER, W O License Fee Management Branch 79/06/05. 1p

7907030099 Notification of 790614 meeting w/Public Svc Electric & Gas Co in Bethesda, MD to discuss steam generator cladding  
DROMERICK, A. Light Water Reactors Branch 3 79/06/11. 2pp.

7907180659 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PHRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625). 79/06/11. 2pp.

## DOCKETED ITEMS

7907090319 Concurs w/NRC determination re fee assessment for amend  
extending provisional CP to 790501 Class II amend fee encl  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/06/19 2pp

7907100543 Ack receipt of NRC 790613 ltr responding to request for OL  
No basis from safety standpoint for delaying OL issuance  
W/790619 ltr to JM Hendrie  
SMITH,R I Public Service Electric & Gas Co of New Jersey  
79/06/25 2pp

--7907100544 Submits schedule for startup, testing & preliminary  
operation & fact sheet to support application for OL  
SMITH,R I Public Service Electric & Gas Co of New Jersey  
79/06/19 App

7907250052 Summary of 790614 meeting w/util & Westinghouse in Bethesda,  
MD re primary head cladding insp  
BRQHERICK,A Light Water Reactors Branch 3 79/06/26 App

7907050347 Submits add info in support of request for extension of  
CPRF-53 until 791031 Requests NRC dispense  
w/notice & publication requirements permitted under  
Atomic Energy Act of 1954 Section 169(a)  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/06/28 2pp

7907170028 Forwards updated listing of items including preoperational  
tests which may not be complete until after initial fuel  
loading Updates & supercedes 790504 ltr  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/07/06 3pp

7907190514 Summarizes actions taken since Util 790515 ltr re single  
rod drop issue Meeting held between Westinghouse & NRC  
resulted in recommendation that former perform safety  
analysis  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/07/13 1p

7907190527 Submits updated response re seismic data for electrical,  
instrumentation & mechanical components Updates 790323  
submittal re Item II-b concerning seismic qualification of  
vital appurtenances associated w/diesel generators  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/07/16 3pp

7907250247 Requests deferment for certain incomplete items, including  
preoperational tests which may not be complete until after  
initial fuel loading Updates info in 790706 ltr  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/07/18 1p

7907250330 Responds to 790614 meeting re stainless steel cladding  
cracks Notifies that util will monitor selected area in  
steam generator channel head 21 by ultrasonic examination  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/07/19 1p

#### D NRC Draft/Final Environmental Statements, suppl & correspondence

7907110519 Discusses 790525 approval of 314(b) plan of study re  
environ Plan has been updated as required Agrees to  
participate in quarter progress meetings Proposes delay of  
Emergency Response Team discussion to Jul 1979 meeting  
SHISSIAS,J A Public Service Electric & Gas Co of New Jersey  
79/07/01 22pp

#### E NRC Safety Evaluation Report (SER), suppl & correspondence

7907250375 Forwards Conax test rept IPS-400, "Qualification of  
Electrical Connection Terminal Blocks/Junction Boxes in  
Containment Environ of LOCA or Steam Line Break Accident "  
Addresses open item in Section B 4 B of SER Suppl 3  
MITTL,R L Public Service Electric & Gas Co of New Jersey  
79/07/17 2pp

--7907250382 "Qualification of Electrical Connection Terminal  
Blocks/Junction Boxes in Containment Environ of LOCA or  
Steam Line Break Accident "  
DEPASQUALE,J D , ILLIO,F J Conax Corp PAVINCICH,W M Public  
Service Electric & Gas Co of New Jersey IPS-400 79/05/17  
140pp

#### F Security, medical, emergency & fire protection plans

7907190588 Forwards latest revisions to emergency instructions, per ACRS  
request Revisions available in Central Files only.  
ITTL,R L Public Service Electric & Gas Co of New Jersey  
/07/17 3pp

#### G Inspection reports, IE Bulletins & correspondence

7907230549 Forwards IE Insp Repts 50-272/79-06 & 50-311/79-14 on  
790218-0324 & notice of violation  
BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear  
Support Branch 79/04/27 2pp

--7907230557 Notice of violation from insp on 790218-0324  
\* Region 1, Philadelphia, Office of the Director 79/04/27  
1p

--7907230570 IE Insp Repts 50-272/79-06 & 50-311/79-14 on 790218-0324  
Noncompliance noted failure to perform surveillance of rod  
position indication w/deviation alarm inoperable  
KEIMIG,R R , NORNHOLM,L J Region 1, Philadelphia, Reactor  
Operations Nuclear Support Branch 79/04/27 9pp

7907110489 Forwards IE Insp Rept 50-311/79-22 on 790329-0409 No  
noncompliance noted  
BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear  
Support Branch 79/05/08 2pp

--7907110494 IE Insp Rept 50-311/79-22 on 790329-0409 No noncompliance  
noted Major areas inspected preoperational test program,  
containment, diesel generator rooms, battery & relay rooms &  
equipment storage  
NICHOLAS,H H , CAPTON,D L Region 1, Philadelphia, Reactor  
Operations Nuclear Support Branch 79/05/04 6pp

7907110534 Forwards IE Insp Repts 50-272/79-10 & 50-311/79-20 on  
790320-22 & 27-28 No noncompliance noted  
BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear  
Support Branch 79/05/10 2pp

--7907110544 IE Insp Repts 50-272/79-10 & 50-311/79-22 on 790320-20 &  
27-28 No noncompliance noted Major areas inspected  
containment integrated leak rate test procedure, pipe  
supports & restraints & refueling preparations  
SMITH,T H , KALMAN,G , CAPTON,D L Region 1, Philadelphia,  
Reactor Operations Nuclear Support Branch 79/05/04 10pp

7907050456 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers  
not in use or planned for use  
SCHNEIDER,F W Public Service Electric & Gas Co of New Jersey  
79/05/15 1p

7907060425 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Licensee  
action required  
GRIER,B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907030061 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor "  
GRIER,B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200142 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
GRIER,B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190102 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Bolonoid Valves) " Action required  
GRIER,B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060128 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
GRIER,B H Region 1, Philadelphia, Office of the Director,  
79/06/07 1p

7907020052 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys "  
GRIER,B H Region 1, Philadelphia, Office of the Director  
79/06/11 1p

7907110389 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
GRIER,B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230005 Ack receipt of 790504 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Rept 50-311/79-12  
CARLSON,R T Region 1, Philadelphia, Reactor Construction &  
Engineering Support Branch 79/06/21 1p

--790723000B Responds to NRC 790406 ltr re violations noted in IE Insp Rept 50-311/79-12, Corrective actions table trays cleaned, tray 2PQ27 replaced & tray 2PQ66 reworked  
MARTIN, T J Public Service Electric & Gas Co of New Jersey  
79/05/04 2pp

--7907230011 Forwards IE Insp Rept 50-311/79-12 on 790213-14 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Office of the Director  
79/04/06 2pp

--7907230015 Notice of violation from insp on 790213-14  
\* Region 1, Philadelphia, Office of the Director 79/04/05  
1p

--7907230023 IE Insp Rept 50-311/79-12, Noncompliance noted failure to maintain installed cable trays in accordance w/procedures  
FINKE, A E Region 1, Philadelphia, Office of the Director  
EBNETER, B D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/05 5pp

7907230700 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"  
Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907120536 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys Piping" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907100363 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100429 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/27 1p

790710035 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180811 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907270361 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310536 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### B Reportable occurrences, LERs & related correspondence

7907300522 Ack receipt of 790502 ltr forwarding 10CFR50 55(e) rept re 4 kV bus differential protection Rept will be reviewed & evaluated  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/14 1p

--7907300571 Discusses significant deficiency re 4 kV vital bus differential protection caused by relay plunger mechanism which is susceptible to seismic vibration Spurious relay operation could cause loss of all 4 kV buses  
MARTIN, T J Public Service Electric & Gas Co of New Jersey  
79/05/02 3pp

7907270160 LER 79-033 has been voided  
\* Public Service Electric & Gas Co of New Jersey 79/07/20 1p

#### U. Congressional/Executive Correspondence

7907180696 Responds to 790507 ltr re facilities in light of accident at TMI Forwards actions taken at facilities as result of TMI incident  
MENDRIE, J M Commission 79/06/28 3pp

--7907180713 Requests thorough insp of facilities in light of accident at TMI Requests info re exact steps being taken to guard against TMI type accident at facilities  
ROTH, W V Senate 79/05/07 1p

#### DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

##### F Security, medical, emergency & fire protection plans

7907050215 Forwards modified physical security plan updated 1979-80 engineering & const schedule Plan withheld (ref 10CFR2 790)  
MATTIMOE, J J Sacramento Municipal Utility District 79/06/25 1p

7907300300 Submits fee for contingency plan submitted w/Amend 2 & 3 to modified amended security plan, in response to NRC 790703 request License fee paid under protest  
MATTIMOE, J J Sacramento Municipal Utility District 79/07/11 1p

##### G Adjudicatory correspondence

7907020512 Forwards telegram from Sacramento Municipal Util District facility  
CUNNINGHAM, G H Branch 2 79/05/29 1p

--7907020513 Requests hearing be held in Sacramento, CA re continued operation & short-term mod  
CASTRO, R D, HURSH, G Sacramento Municipal Utility District  
79/05/25 2pp

7907020474 NRC response to hearing requests filed by Friends of Earth, RD Castro & G Hursh & members of Sacramento Municipal Util District Board of Directors w/draft response & Certificate of Svc  
CUNNINGHAM, G H Branch 2 79/06/01 17pp

7907180727 Orders ASLB to select Board to determine personal interest & requests for hearings from Friends of Earth & BMUD Util has satisfactorily completed requirements of NRC 790507 order  
CHILK, B J Office of the Secretary of the Commission 79/06/21 3pp

##### H General correspondence

7907100637 Expresses support for reopening of facility  
FALKENSBY, E J Affiliation Unknown 79/07/01 1p

7907300414 Responds to 790607 ltr NRC briefing of CA Energy Commission was held 790621 to discuss issues re shutdown order  
DENTON, H R Office of Nuclear Reactor Regulation 79/07/03 1p

--7907300583 Submits draft response to 790607 ltr Info conveyed at 790621 briefing of CA Energy Commission on 790621 should stand w/no further elaboration  
DENTON, H R Office of Nuclear Reactor Regulation 79/07/03 1p

##### P Operating license stage documents & correspondence

790710206 Discusses 780320 severe thermal transient caused by loss of electrical power to substantial portion of non-nuclear instrumentation  
GREEN, I D Babcock & Wilcox Co 78/08/09 8pp

7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation Pressurizer level info request list encl  
SHEMANSKI, P Division of Project Management 79/04/19 2pp

7907160361 Forwards consensus of 790501 meeting re extrapolated conclusions for Rancho Seco & proposed changes to Oconee order  
ROSS, D, Systematic Evaluation Programs Branch (Pre 790625)  
79/05/02 30pp

7906260292 Summary of 790507 affirmation session in Washington, DC re proposed orders to shut down facility Orders approved which add safety changes to feedwater transients  
CHILK, B J Office of the Secretary of the Commission 79/05/08 1p

7907250015 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 1p

## DOCKETED ITEMS

7907100509 Forwards Tech Spec changes as proposed in Amend 32, Revision 3 to License DPR-54, in response to NRC 750228 ltr Changes limit operation re air filter sys & specify methyl iodide removal efficiency of charcoal filters  
WALBRIDGE, W C , KAPLAN, D Sacramento Municipal Utility District  
79/06/21 50pp

7907300426 Discusses NRC 790507 order requiring increase in capacity & reliability of plant to respond to various transient events  
Plant may resume operation Schedule for long-term mod to be forwarded within 30 days  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/27 3pp

--7907300435 Safety evaluation re licensee compliance w/NRC 790507 order  
Requirements of order have been fulfilled Plant may resume operation Long-term mod must be completed  
\* Office of Nuclear Reactor Regulation 79/06/27 28pp

--7907300446 Notice that licensee has satisfactorily completed actions per NRC 790516 shutdown order Plant may resume operations  
REID, R W Operating Reactors Branch 4 79/06/27 3pp

7907300445 Forwards findings of inspectors re plant mod & procedural changes resulting from NRC 790507 shutdown order Operators & senior operators understand procedures  
MOSELEY, N C Division of Reactor Operations Inspections 79/06/27 1p

--7907300450 Discusses actions taken in response to NRC 790507 shutdown order Licensee has complied w/requirements specified in order  
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/18 2pp

7907050317 Forwards proposed Amend 64 to Tech Specs for safety limits & limiting safety sys settings  
MATTHOE, J J Sacramento Municipal Utility District 79/07/02 15pp

7907170080 Requests further review of plant earthquake design criteria due to new geotechnical data from Sierra Foothills fault  
sys  
GREW, P C , DAVIS, J F California, State of 79/07/05 2pp

7907170089 Forwards proposed Amend 62 to OL, submitted as revised Tech Specs which include requirements of NUREG-0472  
MATTHOE, J J Sacramento Municipal Utility District 79/07/13 2pp

--7907170011 Proposed Amend 62 to OL, submitted as revised Tech Specs incorporating process control program & offsite dose calculation manual  
\* Sacramento Municipal Utility District 79/05/31 90pp

--7907170014 Offsite Dose Calculation Manual  
\* Sacramento Municipal Utility District 79/05/31 61pp

7907250391 Forwards transcript of util 790201 Board of Directors' meeting re NRC rept on alleged design deficiencies in facility cooling towers, per NRC 790709 request.  
MATTHOE, J J Sacramento Municipal Utility District 79/07/19 12pp

7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
GEIBLER, Q O Babcock & Wilcox Co 79/07/20 2pp

7907310352 Responds to 790627 ltr re long-term mod & small break model analysis Submits info re auxiliary feedwater sys, control sys failure modes, safety-grade anticipatory trips & operator training, per NRC 790507 order  
BOSSENHAUER, W B Sacramento Municipal Utility District 79/07/26 2pp

#### Q Inspection reports, IE Bulletins & correspondence

7907160067 Provides results of review of licensee response to IE Bulletin 79-05A  
FAULKENBERRY, B Region 5, San Francisco, Office of the Director 79/04/13 1p

7907020080 B&W site inspector daily rept on 790419 Plant status full power w/no known problems Surveyed control room activities w/Congressman Bhunway & util representatives  
JOHNSON, A , JOHNSON, P Region 5, San Francisco, Office of the Director 79/04/19 2pp

7907020123 B&W site inspector daily rept on 790416 Plant status reactor operating at full power w/no known problems Next scheduled outage on 790517  
JOHNSON, A , MILLER, L Region 5, San Francisco, Office of the Director 79/04/16 2pp

7907020157 B&W site inspector daily rept on 790418 Plant status reactor at full power w/no known problems One day outage scheduled for 790512 for insp of snubbers  
JOHNSON, A , JOHNSON, P Region 5, San Francisco, Office of the Director 79/04/18 2pp

7907160046 Forwards IE Region 5 evaluation of licensee 790416 response to IE Bulletin 79-05A  
VAROA, S A Light Water Reactors Branch 4 79/04/19 1p

--7907160048 Comments on licensee 790416 response to IE Bulletin 79-05A  
FAULKENBERRY, B Region 2, Atlanta, Office of the Director 79/04/17 2pp

7907090320 FOIA request for access to all documents compiled by Mechanical Engineering & Matl Engineering Branches re IE Bulletins 79-12, 12A & 12B & info re atypical weld matl in B&W reactors  
RUTLAND, O KRON TV 79/05/11 2pp

7907090377 Responds to IE Bulletin 79-05B Anticipatory filling of once-through steam generator prior to securing reactor coolant pumps deemed beneficial  
MATTHOE, J J Sacramento Municipal Utility District 79/05/11, 7pp

7907020471 Forwards corrected Figure 1, in response to IE Bulletin 79-05B Requests that revised figure be substituted for figure in 790511 ltr w/o encl  
MATTHOE, J J Sacramento Municipal Utility District 79/05/14 1p

7907020293 Provides util responses to Items 5 & 7 of IE Bulletin 79-05B Evaluation of anticipatory trips on turbine trip, loss of main feedwater & low steam generator level show low steam generator level is not anticipatory  
WALBRIDGE, W C Sacramento Municipal Utility District 79/05/21 5pp

7907180871 Responds to Items 5 & 7 of IE Bulletin 79-05B Evaluation for anticipatory trips on turbine trip, loss of main feedwater & low steam generator level is complete Evaluation showed low steam generator level not anticipatory  
WALBRIDGE, W C Sacramento Municipal Utility District 79/05/21 5pp

7907190431 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p

7907060034 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07 1p

7907300404 IE Insp Rept 50-312/79-10 on 790507-08, 14, 17, 22, 29-31, 0601-02, 04-08 & 10-11 No noncompliance noted major areas inspected plant operations, response to IR Bulletin 78-05B & operator retraining re TMI  
JOHNSON, A , JOHNSON, E , FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/15 5pp

7907020451 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20, 1p

7907120015 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/21 1p

7907090327 Responds to FOIA request for documents re IE Bulletins 78-12, 12A & 12B & info on atypical weld matl at facility.  
Forwards FSAR "Weld Matl Rept, CBI Nuclear Co 1979, Vols 1-4," & responses to NRC questions re Midland facility.  
FELTON, J. M. Division of Rules and Records 79/06/22 36pp

--7907090341 Advises that revised pressure/temp limits were based on technical evaluation by B&W Fracture mechanics evaluation demonstrates structural integrity of reactor vessel has not been compromised by possible presence of atypical matl  
MATTIMOE, J J Sacramento Municipal Utility District 78/08/18 3pp

--7907090347 Forwards revision to Tech Spec Section 3.1.2, "Pressurization, Heatup & Coldown Limitations"  
MATTIMOE, J J Sacramento Municipal Utility District 78/08/02 9pp

--7907090352 Forwards \$4,000 fee for application to amend License DPR-54  
MATTIMOE, J J Sacramento Municipal Utility District 78/08/02 1p

--7907090358 Provides proposed Amend 59, Revision 1 to DPR-54 Amend revises Tech Spec Section 3.1.2, "Pressurization, Heatup & Coldown Limitations"  
MATTIMOE, J J Sacramento Municipal Utility District 78/08/11 8pp

--7907090362 Responds to IE Bulletins 78-12 & 78-12A Forwards CBI Nuclear Co. "Weld Matl Rept 1978, Vols 1-4"  
OEHLKERS, W G CBI Nuclear Co 79/05/01 1p

--7907090367 CBI Nuclear Co. "Weld Matl Rept 1978," Vol 1  
\* CBI Nuclear Co 79/05/01 47pp

--7907090396 CBI Nuclear Co. "Weld Matl Rept 1978," Vol 2  
\* CBI Nuclear Co 79/05/01 78pp

--7907090400 CBI Nuclear Co. "Weld Matl Rept 1978," Vol 3  
\* CBI Nuclear Co 79/05/01 290pp

--7907090407 CBI Nuclear Co. "Weld Matl Rept 1978," Vol 4  
\* CBI Nuclear Co 79/05/01 306pp

--7907090412 CBI Nuclear Co. "Weld Matl Rept 1978," Vol 4A  
\* CBI Nuclear Co. 79/05/01 500pp

7907110208 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907190138 Forwards IE Insp Rept 50-312/79-09 on 790521-0401 No noncompliance noted Rept withheld (ref 10CFR2 790)  
NORDEHAWO, L R Region 5, San Francisco, Safeguards Branch 79/06/22 1p

7907120627 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" Licensee action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/25 1p

7907060224 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p.

7907100532 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/28 1p

7907130218 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p

7907230783 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p.

7907180708 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/07/11 1p

7907310400 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260278 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

7907300408 Forwards inservice insp & testing program for 40-month period ending 780530 Includes info re nondestructive examination, hydro & leak testing, pumps & valve testing & waiver requests  
MATTIMOE, J J Sacramento Municipal Utility District 79/07/18 1p

#### R Periodic operating reports & related correspondence

7907180506 Forwards monthly operating rept for June 1979  
RODRIGUEZ, R J Sacramento Municipal Utility District 79/07/09 1p

--7907180508 Monthly operating rept for June 1979  
COLOMBO, R W Sacramento Municipal Utility District 79/06/30 5pp.

#### S Reportable occurrences, LERs & related correspondence

7907020288 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/05 1p

7907030198 Forwards PNO-79-67AS  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907030242 Forwards PNO-79-67AT, "Nuclear Incident at TMI."  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/19 1p

7907050541 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p.

7907130389 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/03 1p

7907260759 Notifies of RO 79-06 reported by B&W on 790720. App K criteria may be exceeded for low probability event involving certain range of small breaks Recommends change in engineered safety features actuation sys procedures  
MATTIMOE, J J Sacramento Municipal Utility District 79/07/20 1p

7907270180 RO 79-07 on 790720 six piping supports determined not to meet safety factors required per IE Bulletin 79-02 Unit brought to hot shutdown & sys modified Rept to follow in 14 days  
MATTIMOE, J J Sacramento Municipal Utility District 79/07/23 1p

#### U Congressional/Executive Correspondence

7907180130 Responds to 790419 request to evaluate NRC program to license power plant operators Provides examples of operator error & suggestions for improving training & qualifications  
STAATS, E B General Accounting Office 79/05/15 16pp

#### DOCKET 50-313 ARKANBAS NUCLEAR ONE, UNIT 1

#### F Security, medical, emergency & fire protection plans

7907300560 Ack receipt of 790430 submission of Revision 2 to fire protection plan Forwards discussion of two points found unacceptable. Plan should apply to both Unit 1 & Unit 2.  
REID, R W Operating Reactors Branch 4 BTOLZ, J F Light Water Reactors Branch 1. 79/06/13. 3pp

#### O. Adjudicatory correspondence

7907020469 Order requiring licensee to assume cold shutdown condition & not restart unit until IE acting director has confirmed, in writing, that necessary actions have been accomplished  
DAVIS, J Q Office of Inspection & Enforcement. 79/06/02. 3pp

7907190628 Order authorizing licensee to resume operation of facility Conditions required per 790602 order have been satisfactorily accomplished  
STELLO, V Office of Inspection & Enforcement. 79/06/14. 3pp

## DOCKETED ITEMS

J Insurance & indemnity information

7907050211 Forwards Endorsements 36-39 to NELIA Policy NF-210 & Endorsements 32-35 to MAELU Policy MF-74  
TRIMBLE, D C Arkansas Power & Light Co 79/06/28 9pp

P Operating license stage documents & correspondence

7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation Pressurizer level info request list encl  
SHEMANSKI, P Division of Project Management 79/04/19 2pp

7907040407 Provides status of IE Bulletin 79-01 response Projected submittal date is 790714  
TRIMBLE, D C Arkansas Power & Light Co 79/05/03 1p

7907260122 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC Headquarters & regional ofc will communicate operational & environ info  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22 2pp

7907090430 Forwards info re examinations administered to licensed operators & senior operators Includes examination & grading key summary of test results Individual answer sheets encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/28 50pp

7907100277 Notifies that AR Power & Light Co has performed immediate actions re NRC 790517 order Operating restrictions may be removed  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/30 1p

--7907100288 Draft ltr notifying of satisfactory completion of immediate actions required by NRC 790517 order Operating restrictions may be removed Modified Tech Specs must be submitted  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/30 4pp

--7907100292 Draft SER AR Power & Light Co has performed immediate actions required by NRC 790517 order  
\* Office of Nuclear Reactor Regulation 79/05/30 14pp

--7907100304 Draft notice announcing that AR Power & Light Co has satisfactorily completed actions required by NRC 790517 order Operating restrictions may be removed  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/30 2pp

7907110397 Notice of authorization for util to resume operation. Util has confirmed completion actions re NRC 790517 order  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/31 2pp

7907190096 Summary of actions taken to increase capability & reliability of plant to respond to various transient events Forwards notice of authorization to resume operation & safety evaluation  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/31 6pp

--7907190105 Safety evaluation of licensee compliance w/NRC 790517 order Approves restart of plant  
\* Operating Reactors Branch 4 (Pre 790625) 79/05/31 14pp

7907180637 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 1p

7907310144 Requests submission of Tech Specs addressing solidification, solid waste process control program & Offsite Dose Calculation Manual no later than 790709  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/13 2pp

7907020514 Draft ltr re satisfactory upgrading of timeliness & reliability of emergency feedwater sys & procedures to initiate emergency feedwater independence Draft safety evaluation & FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/21 20pp

7907020669 Forwards NRC draft ltr & FR notice re resumption of operation of facility  
VIBIANO, G Operating Reactors Branch 4 (Pre 790625) 79/06/25 7pp

7907230324 Summary of 790621 meeting w/util in Bethesda, MD re emergency feedwater sys reliability  
CAPRA, R A Division of Project Management 79/06/28 7pp

7907060321 Responds to 790531 request Submits schedule for completion of long-term mods to feedwater sys described in Section II of 790517 order  
TRIMBLE, D C Arkansas Power & Light Co 79/06/29 8pp

7907110373 Submits info requested 790320 re review of ECCB subvys for single failure No single failure or operator error could result in significantly adverse consequences to ECCB performance No Tech Spec mods are proposed  
TRIMBLE, D C Arkansas Power & Light Co 79/06/29 2pp

7907170125 Forwards 790709 draft offsite dose calculation manual  
TRIMBLE, D C Arkansas Power & Light Co 79/07/09 1p

--7907170128 Draft Offsite Dose Calculation Manual  
\* Arkansas Power & Light Co 79/07/09 105pp

7907200272 Submits addl info re degraded grid voltage, in response to NRC 790620 request Thirteen oversized drawings available in Central Files  
TRIMBLE, D C Arkansas Power & Light Co 79/07/12 29 pp

7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
GEISSLER, G O Babcock & Wilcox Co 79/07/20 2pp

G Inspection reports, IE Bulletins & correspondence

7907160062 Comments on licensee response to IE Bulletin 79-03A  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/13 3pp

7907020078 B&W site inspector daily rept on 790419 Plant status reactor shutdown for refueling Inspected control room activities  
SPANGLER, R G Region 4, Dallas, Office of the Director 79/04/19 3pp

7907020117 B&W site inspector daily rept on 790416 Plant status reactor shutdown for refueling Work continuing on low pressure turbine rotor replacement  
SPANGLER, R G Region 4, Dallas, Office of the Director 79/04/16 3pp

7907020153 B&W site inspector daily rept on 790418 Plant status in refueling shutdown, w/refueling snuffles 60% complete Remaining items unchanged from 790417  
SPANGLER, R G, KELLEY, D L Region 4, Dallas, Office of the Director 79/04/18 3pp

7907160009 Forwards evaluation by IE Region 4 of licensee 790416 responses to IE Bulletin 79-03A  
VARGAS, S A Light Water Reactors Branch 4 79/04/20 1p

--7907160017 Evaluates licensee 790416 response to IE Bulletin 79-03A  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/14 3pp

7907160373 Draft ltr forwarding draft NRC evaluation of 790411 & 16 licensee responses to IE Bulletin 79-03A Request for addl info encl Response required within 30 days  
\* Division of Project Management 79/04/25 27pp.

--7907160377 Summarizes problems in connection w/TMI bulletin responses Deficiency noted in auxiliary feedwater sys at facility  
WILLIAMS, F J Division of Project Management 79/04/25 1p

7907120001 Forwards IE Insp Rept 50-313/79-07 & 50-368/79-07 on 790319-0413 & notice of violation  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/01 2pp.

--7907120003 Notice of violation from insp on 790319-0413.  
\* Region 4, Dallas, Office of the Director 79/05/01. 2pp.

--7907120007 IE Insp Rept 50-313/79-07 & 50-368/79-07 on 790319-0413 Noncompliance noted failure to adhere to procedures.  
JOHNSON, W D, SPANGLER, R G, WESTERMAN, T F Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/01 20pp

7907060417 Forwards partial response to IE Bulletin 79-03 re use of Youngstown longitudinal welded pipe in safety-related sys Volumetric examination of longitudinal welds has begun Fully developed program will be submitted by 790622  
TRIMBLE, D C Arkansas Power & Light Co 79/05/14 1p



7907090439 Forwards IE Insp Repts 50-313/79-08 & 50-368/79-08 on 790426-27 No noncompliance noted  
MADSEN, G L Region 4, Dallas, Office of the Director 79/05/17  
2pp

--7907090446 IE Insp Repts 50-313/79-08 & 50-368/79-08 on 790516 No noncompliance noted Major areas inspected radiation protection program, respiratory protection program, posting & controls & radiological surveys  
MURRAY, B , BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/05/16 App

7907100283 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18  
1p

7907060325 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22  
1p

7907180225 Submits info requested in IE Bulletin 79-10 re requalification training program statistics  
TRIMBLE, D C Arkansas Power & Light Co 79/05/25 5pp

7907200343 Forwards IE Bulletin 79-12, "Short Period Scrams at BHR Facilities " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31  
1p

7907050008 Forwards draft IE info notice "Deficient Procedures" re controls of emergency feedwater sys Requests review & comment  
BRYAN, S E Division of Reactor Operations Inspections 79/06/04  
5pp

--7907050011 Draft IE info notice, "Deficient Procedures " \* Office of Inspection & Enforcement 79/06/04 App

7907190390 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06  
1p

7907060010 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/06/07  
1p

7907020443 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "   
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20  
1p

7907310537 Forwards IE Insp Rept 50-313/79-14 on 790607-08 No noncompliance noted  
MADSEN, G L Region 4, Dallas, Office of the Director 79/06/20  
2pp

--7907310552 IE Insp Rept 50-313/79-14 on 790607-08 No noncompliance noted Major areas inspected gaseous radwaste sys, including operation of waste gas holdup sys, repts of gaseous effluent releases & effluent control instrumentation  
EVERETT, R J Region 4, Dallas, Office of the Director  
BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/06/18. App

7907120370 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/06/21  
1p

7907020013 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus, "   
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22.  
1p.

7907120590 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/06/25.  
1p

7907100385 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/06/26  
1p

7907180376 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28  
1p

7907240271 Ack receipt of 790423 & 0612 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-05 & 50-368/79-05  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/29 1p

7907310207 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02  
1p

7907310619 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/06  
1p

7907190489 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11  
1p

7907240299 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13  
1p

7907260325 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/17  
1p

7907260231 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18  
1p

#### R Periodic operating reports & related correspondence

7907060322 Notifies that monthly impingement rept for May 1979 was not prepared since plant was in cold shutdown  
TRIMBLE, D C Arkansas Power & Light Co 79/06/27 1p

7907090278 Forwards corrected monthly operating rept for May 1979  
TRIMBLE, D C Arkansas Power & Light Co 79/06/28 1p

--7907090279 Corrected monthly operating rept for May 1979  
SHIVELY, C N Arkansas Power & Light Co 79/06/28 2pp

7907190385 Forwards monthly operating rept for June 1979  
TRIMBLE, D C. Arkansas Power & Light Co 79/07/11 1p

--7907190388 Monthly operating rept for June 1979  
SHIVELY, C N Arkansas Power & Light Co 79/07/11 4pp

#### B Reportable occurrences, LERs & related correspondence

7907030256 Forwards PNO-79-67AQ, "Nuclear Incident at TMI "   
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/05/31 1p

7907020297 Forwards PNO-79-67AR  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/05 1p

7907170032 Confirms 790607 telcon re RO 50-313/79-06 tests revealed that under certain repeat start operating modes, turbocharger thrust bearing on emergency diesel generator could be damaged Unit in cold shutdown  
O'HANLON, J. P. Arkansas Power & Light Co 79/06/08. 2pp

7907030175 Forwards PNO-79-67AS.  
MADSEN, G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/13. 1p

7907030218 Forwards PNO-79-67AT  
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/06/19. 1p.

7907030396 Forwards LER 79-N/A/99X-0  
TRIMBLE, D C. Arkansas Power & Light Co 79/06/27 1p.

## DOCKETED ITEMS

--7907030398 LER 79-N/A/79X-0 on 790522 during routine maint investigation, cable leads at location C-46, 1-8-3, termination 2 & 6 found to be lifted, but not tagged Cause unknown Leads reconnected  
SHIVELY, C N Arkansas Power & Light Co 79/06/27 1p

7907130307 Forwards PND-79-67AV  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/06/27 1p

7907180669 Forwards PND-79-67AV & AH  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/07/10 1p

7907230349 Forwards LER 79-007/03L-0  
TRIMBLE, D C Arkansas Power & Light Co 79/07/16 1p

--7907230354 LER 79-007/03L-0 on 790616 during heatup, emergency feedwater pump automatically started w/inadvertent actuation Caused by valve lineup error Outboard pump bearing found to be hot due to faulty installation Maint procedure revised  
SHIVELY, C N Arkansas Power & Light Co 79/07/16 1p

7907310444 Forwards LER 79-008/03L-0  
TRIMBLE, D C Arkansas Power & Light Co 79/07/25 1p

--7907310453 LER 79-008/03L-0 on 790621 emergency feed actuation received when once-through steam generator A startup level transmitter selection was shifted Caused by overspeed trips due to water in steam supply line  
SHIVELY, C N Arkansas Power & Light Co 79/07/25 1p

#### U. Congressional/Executive Correspondence

7907260059 Responds to 790521 ltr re possible shutdown of all B&W reactors Plant was shut down per agreement w/util, to avoid repetition of design errors which occurred at TMI Forwards relevant documents W/o encl  
GOSBICK, L V Office of the Executive Director for Operations 79/06/13 2pp

--7907260065 Requests info re possible shutdown of facility Forwards J Mooney 790424 telegram re resulting costs of shutdown  
MOORE, W H House of Rep 79/05/21 2pp

#### DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

##### Q Adjudicatory correspondence

7907270008 Forwards V Stello 790525 ltr & DV Shaller 790526 memo re cracking of feedwater lines at DC Cook plant  
CHRISTENBURY, E Hearings Division 79/06/20 1p

--7907270016 Recommends transmittal of V Stello 790525 ltr & DV Shaller 790526 memo to HB Robinson Board.  
STELLO, V Division of Operating Reactors 79/06/08 1p

--7907270023 Informs all PWR licensees that some circumferential throughwall cracks & inside-of-pipe indications occurred at DC Cook Requests submittal of info on PWR feedwater lines List of info requested encl  
STELLO, V Division of Operating Reactors 79/05/25 1p

#### J Insurance & indemnity information

7907260705 Forwards Endorsements 33 & 34 to MAELU Policy MF-79 & Endorsements 40 & 41 to ANI Policy NF-206, W/o encl.  
DOLAN, J E Indiana & Michigan Power Co 79/07/20 2pp.

#### . Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utilis to discuss Westinghouse plant design per TMI-2 event.  
THADANI, A Reactor Systems Branch 79/05/02 39pp.

07310588 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re red bank exchange method for verifying shutdown margin of two-loop NSSS W/o encl.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p.

37260086 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
LEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22 2pp

7907130209 Requests addl info re structural analysis of spent fuel storage pool expansion Encl questions should be answered within 30 days of receipt  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/30 1p

7907110731 Notifies that application for amend to Licenses DPR-58 & DPR-74 are Classes III & I, not II & I Addl fee should be promptly forwarded  
DIGGS, R H License Fee Management Branch 79/05/31 1p

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related reevaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907240288 Notification of 790611 meeting w/American Electric Power in Bethesda, MD to discuss results of examinations & analyses of feedwater nozzle cracking & to identify cause of failure method of repair & testing program  
JORDAN, E L Division of Reactor Operations Inspections 79/06/08 2pp

7907240547 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250009 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
ORINEB, B K Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 2pp

7907240493 Summary of 790514 meeting w/util in Bethesda, MD re status of containment purge review & related subj  
WIGGINTON, D Operating Reactors Branch 1 79/06/12 9pp

7907260177 Forwards Amends 29 & 11 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/21 2pp

--7907260195 Amends 29 & 11 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs to require actuation of safety injection based on two of three channels of low pressurizer pressure & changing P-11 permissive setpoint.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/21 24pp

--7907260208 Safety evaluation supporting Amends 29 & 11 to Licenses DPR-58 & DPR-74, respectively  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/21 2pp.

--7907260230 Notice of issuance & availability of Amends 29 & 11 to Licenses DPR-58 & DPR-74, respectively.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625), 79/06/21 2pp.

7907030457 Forwards addl info requested during 790531 meeting w/NRC re unrestricted containment purging  
JURGENSEN, R W Indiana & Michigan Power Co 79/06/29 12pp

7907100470 Responds to A Schwencer 790530 ltr requesting addl info re spent fuel storage capacity extension program Forwards revised pages to 781122 ltr re refined dimension of spent fuel rack storage cells  
DOLAN, J E American Electric Power Co, Inc 79/06/29 30pp

7907250611 Notification of 790731 meeting w/util in Bethesda, MD to discuss remaining issues re radiological Tech Specs  
WIGGINTON, D Light Water Reactors Branch 1 79/07/05 2pp

7907230365 Updates 781220 & 790418 ltrs re placement of fuel assemblies for Cycle 4 Discusses changes due to damage to Exxon Nuclear Co fuel assemblies during refueling outage & reinsertion of two assemblies into core  
HUNTER, R B Indiana & Michigan Power Co. 79/07/16 2pp.

7907260697 Supplements 771222 response which addressed potential sodium hydroxide flow paths to RCS. Forwards revised schematic diagram of piping arrangements from spray additive tank to discharge points  
DOLAN, J E Indiana & Michigan Power Co 79/07/20 4pp

#### G. Inspection reports, IE Bulletins & correspondence

7907270392 Forwards IE Insp Repts 50-315/79-05 & 50-316/79-05 on 790305-09, 18-16, 19-23, 26-31 & 0401-06 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/08 2pp.

--7907270399 Notice of violation from insp on 790305-09, 12-16, 19-23, 26-31 & 0401-06  
\* Region 3, Chicago, Reactor Operations Nuclear Support Branch  
79/05/08 1p

--7907270407 IE Insp Repts 50-315/79-05 & 50-316/79-08 on 790305-09, 12-16, 19-23, 26-31 & 0401-06 Noncompliance noted failure to implement locked & sealed valve procedure & failure to use jumper logs as directed  
MASSE, R E, BAKER, K R, WARNICK, R F Region 3, Chicago, Office of the Director 79/05/03 17pp

7907130351 Forwards IE Insp Rept 50-315/79-08 on 790501-02 No noncompliance noted  
FIORRELLI, G Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/18 2pp

--7907130354 IE Insp Rept 50-315/79-08 on 790501-02 No noncompliance noted Major areas inspected licensee action on previously identified item, safety-related snubber insp program provisions, records & installation conditions  
VIN, I. T, DANIELSON, D H Region 3, Chicago, Office of the Director 79/05/16 3pp

7907180325 Forwards IE Insp Rept 50-315/79-06 on 790412-13 & 0501-02 No noncompliance noted.  
FIORRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/05/18 2pp

--7907180335 IE Insp Rept 50-315/79-06 on 790412-13 & 0501-02 No noncompliance noted Major areas inspected review of inservice insp program & procedures, observation of work activities & review of collected inservice insp data  
KEY, W J, DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/16 9pp

7907180345 Forwards IE Insp Rept 50-315/79-09 on 790109-10 No noncompliance noted  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18 2pp

--7907180354 IE Insp Rept 50-315/79-09 on 790109-10 No noncompliance noted Major areas inspected radioactive liquid release procedures & records, review of pertinent records, insp of equipment & interviews w/personnel  
FOSTER, J E, SCHUMACHER, M C, FISHER, W L Region 3, Chicago, Office of the Director 79/05/11 13pp.

7907240405 Forwards results of preliminary review of licensee responses to IE Bulletin 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Wastehouse-designed sgs scheduled for 790530 in Bethesda, MD  
SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907050046 Forwards tabular response to IE Bulletin 79-10 re reactor operator training.  
DOLAN, J. E Indiana & Michigan Power Co. 79/05/24 3pp

7907200320 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p.

7907190272 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
KEPPLER, J. G Region 3, Chicago, Office of the Director 79/06/06 1p.

7907240427 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required.  
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/07 1p.

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures," was forwarded to listed utility  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08. 2pp.

7907300083 Forwards IE Insp Repts 50-315/79011 & 50-316/79-08 on 790407-0504 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13, 2pp

--7907300086 Notice of violation from insp on 790407-0504  
\* Region 3, Chicago, Office of the Director. 79/06/13 1p.

--7907300092 IE Insp Repts 50-315/79-11 & 50-316/79-08 on 790407-0504 Noncompliance noted: failure to implement procedure from LER & failure to review mod of containment structure.  
MASSE, R. E. Region 3, Chicago, Office of the Director 79/06/11. 10pp

7907310197 Forwards IE Insp Rept 50-315/79-12 on 790605-06 No noncompliance noted  
FIORRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/14 2pp

--7907310206 IE Insp Rept 50-315/79-12 on 790605-06 No noncompliance noted Major areas inspected followup to IE Bulletin 79-02 & pipe support base plate designs using concrete expansion anchor bolts List of sgs in test program encl  
GALLAGHER, E J, HAYES, D W Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/13 7pp

7907020431 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate"  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120238 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907050448 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907120476 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907300480 Forwards supplemental response to IE Bulletin 79-06A, Revision 1 Submits info re containment isolation, emergency procedures & safety-related valves  
JURGENSEN, R W American Electric Power Co., Inc 79/06/25 7pp

7907060302 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p.

7907180390 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130271 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240097 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
KEPPLER, J. G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310305 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/11 1p.

7907310402 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p.

7907260148 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p.

7907260398 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants" No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/18 1p.

7907250229 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.  
KEPPLER, J. G Region 3, Chicago, Office of the Director 79/07/20 1p

H. Periodic operating reports & related correspondence

7907200317 Forwards monthly operating rept for June 1979  
BHALLER, D. V. Indiana & Michigan Power Co. 79/07/11. 1p

## DOCKETED ITEMS

--7907200321 Monthly operating rept for June 1979  
GILLET, W T Indiana & Michigan Power Co 79/07/05 4pp

B Reportable occurrences, LERs & related correspondence

7907190515 Forwards LER 79-034/03L-0  
SHALLER, D V Indiana & Michigan Power Co 79/07/13 1p

--7907190520 LER 79-034/03L-0 on 790613 several valves exhibited excessive leakage causing as-found leak rate to exceed limit caused by leakage from check valves Check valves replaced  
BELLMAN, T P Indiana & Michigan Power Co 79/07/13 2pp

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

Q Adjudicatory correspondence

7907270008 Forwards V Stello 790525 ltr & DV Shaller 790526 memo re cracking of feedwater lines at DC Cook plant  
CHRISTENBURY, E Hearings Division 79/06/20 1p

--7907270016 Recommends transmittal of V Stello 790525 ltr & DV Shaller 790526 memo to HB Robinson Board.  
STELLO, V Division of Operating Reactors 79/06/08 1p

--7907270023 Informs all PWR licensees that some circumferential throughwall cracks & inside-of-pipe indications occurred at DC Cook Requests submittal of info on PWR feedwater lines List of info requested encl  
STELLO, V Division of Operating Reactors 79/05/25 1p

J Insurance & indemnity information

7907260705 Forwards Endorsements 33 & 34 to MAELU Policy MF-79 & Endorsements 40 & 41 to ANI Policy NF-206 W/o encl  
DOLAN, J E Indiana & Michigan Power Co 79/07/20 2pp

P Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/util to discuss Westinghouse plant design per TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310588 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSB W/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p

7907260086 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22 2pp

7907130209 Requests addl info re structural analysis of spent fuel storage pool expansion Encl questions should be answered within 30 days of receipt.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/30 1p

7907110731 Notifies that application for amend to Licenses DPR-5B & DPR-74 are Classes III & I, not II & I Addl fee should be provided  
DIGGS, R M License Fee Management Branch 79/05/31 1p

7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related reevaluations of operating plants  
KANE, W F Standardization Branch 79/05/31 4pp

7907240288 Notification of 790411 meeting w/American Electric Power in Bethesda, MD to discuss results of examinations & analyses of feedwater nozzle cracking & to identify cause of failure method of repair & testing program  
JORDAN, E L Division of Reactor Operations Inspections 79/06/08 2pp

7907240547 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods. NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp

7907250009 Forwards NUREG-0560, "Staff Rpt on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907240493 Summary of 790514 meeting w/util in Bethesda, MD re status of containment purge review & related subj  
WIGGINTON, D Operating Reactors Branch 1 79/06/12 9pp

7907260177 Forwards Amends 29 & 11 to Licenses DPR-5B & DPR-74, respectively, safety evaluation & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/21 2pp

--7907260195 Amends 29 & 11 to Licenses DPR-5B & DPR-74, respectively, revising Tech Specs to require actuation of safety injection based on two of three channels of low pressurizer pressure & changing P-11 permissive setpoint  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/21 24pp

--7907260208 Safety evaluation supporting Amends 29 & 11 to Licenses DPR-5B & DPR-74, respectively  
\* Operating Reactors Branch 1 (Pre 790625) 79/06/21 2pp

--7907260230 Notice of issuance & availability of Amends 29 & 11 to Licenses DPR-5B & DPR-74, respectively.  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/21 2pp

7907030497 Forwards addl info requested during 790531 meeting w/NRC re unrestricted containment purging  
JURGENSEN, R W Indiana & Michigan Power Co 79/06/29 12pp

7907100470 Responds to A Schwencer 790530 ltr requesting addl info re spent fuel storage capacity extension program Forwards revised pages to 7B1122 ltr re refined dimension of spent fuel rack storage coils  
DOLAN, J E American Electric Power Co, Inc 79/06/29 30pp

7907250611 Notification of 790731 meeting w/util in Bethesda, MD to discuss remaining issues re radiological Tech Specs  
WIGGINTON, D Light Water Reactors Branch 1 79/07/05 2pp

7907260497 Supplements 771222 response which addressed potential sodium hydroxide flow paths to RCB Forwards revised schematic diagram of piping arrangements from spray additive tank to discharge points  
DOLAN, J E Indiana & Michigan Power Co 79/07/20 4pp

Q Inspection reports, IE Bulletins & correspondence

7907160297 Evaluates util responses to IE Bulletin 79-04A Forwards memo reviewing Westinghouse rept, "Qualification Testing of Barton Pressure & Differential Pressure Transmitters"  
WILLIAMS, F J Division of Project Management 79/04/24 1p

7907270392 Forwards IE Insp Repts 50-315/79-05 & 50-316/79-05 on 790305-09, 12-16, 19-23, 24-31 & 0401-06 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/08 2pp

--7907270399 Notice of violation from insp on 790305-09, 12-16, 19-23, 24-31 & 0401-06  
\* Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/08 1p

--7907270407 IE Insp Repts 50-315/79-05 & 50-316/79-05 on 790305-09, 12-16, 19-23, 24-31 & 0401-06 Noncompliance noted failure to implement locked & sealed valve procedure & failure to use jumper logs as directed  
MASSE, R E, BAKER, K R, WARNICK, R F Region 3, Chicago, Office of the Director 79/05/03 17pp

7907240605 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907050046 Forwards tabular response to IE Bulletin 79-10 re reactor operator training  
DOLAN, J E Indiana & Michigan Power Co 79/05/24 3pp

7907200320 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907190272 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240427 Forwards IE Info Notice 79-13, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07  
1p

7907040007 Advises that IE Info Notice 79-13, "Deficient Procedures" was forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp

7907300083 Forwards IE Insp Repts 80-315/79011 & 80-316/79-08 on 790407-0504 & notice of violation  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13 2pp

--7907300086 Notice of violation from insp on 790407-0504  
\* Region 3, Chicago, Office of the Director 79/06/13 1p

--7907300092 IE Insp Repts 80-315/79-11 & 80-316/79-08 on 790407-0504 Noncompliance noted failure to implement procedure from LER & failure to review mod of containment structure  
MABSE, R E Region 3, Chicago, Office of the Director 79/06/11  
10pp

7907020431 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20  
1p

7907120238 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907030448 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22  
1p

7907120676 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

7907300480 Forwards supplemental response to IE Bulletin 79-06A, Revision 1 Submits info re containment isolation, emergency procedures & safety-related valves  
JURGENSEN, R W American Electric Power Co, Inc 79/06/25 7pp

7907060302 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907180390 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130271 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p.

7907240097 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06  
1p

7907310305 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p.

7907310402 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260148 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907260398 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907250229 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20  
1p

#### R Periodic operating reports & related correspondence

7907200329 Forwards monthly operating rept for June 1979  
SHALLER, D V Indiana & Michigan Power Co 79/07/11 1p

--7907200333 Monthly operating rept for June 1979  
GILLET, W T Indiana & Michigan Power Co 79/07/05 7pp

#### S Reportable occurrences, LERs & related correspondence

7907190532 Forwards LER 79-020/03L-0  
SHALLER, D V Indiana & Michigan Power Co 79/07/13 1p

--7907190537 LER 79-020/03L-0 on 790615 several valves exhibited excessive leakage, causing as-found leak rate to exceed limit. Major source of leak attributed to check valves. Caused by sand deposits on seating surfaces & pitted seats  
BELLMAN, T P Indiana & Michigan Power Co 79/07/13 2pp

7907250253 Forwards LER 79-021/03L-0  
SHALLER, D V Indiana & Michigan Power Co 79/07/19 1p

--7907250268 LER 79-021/03L-0 on 790622 starting time exceeded Tech Specs during test on hydrogen skimmer recirculation fan Design change installed 781118 after repeated occurrences & 10 tests satisfactorily performed  
RISCHLING, J L Indiana & Michigan Power Co 79/07/19 2pp

7907300325 Forwards LER 79-022/03L-0  
SHALLER, D V Indiana & Michigan Power Co 79/07/25 1p

--7907300337 LER 79-022/03L-0 on 790706 bistable 2PB-934B tripped at value exceeding Tech Spec limit by 0.104 psi during surveillance test on containment pressure protection. Caused by drifting of bistable trip set point. Bistable replaced  
RISCHLING, J L Indiana & Michigan Power Co 79/07/25 2pp

#### DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

#### J Insurance & indemnity information

7907060276 Forwards Endorsements 31 & 32 to MAELU Policy MF-76 & Endorsements 36 & 37 to NELIA Policy NF-216  
SHOEMAKER, C L Baltimore Gas & Electric Co 79/06/29 5pp

#### P Operating license stage documents & correspondence

7907030144 Discusses review of 790313 reanalysis of ECCB small break LOCA. Reanalysis is acceptable. Safety evaluation encl  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/18  
2pp

--7907030147 Safety Evaluation re reanalysis of small break LOCA w/o charging pump injection  
\* Operating Reactors Branch 4 (Pre 790625) 79/05/18 3pp

7907180692 Forwards safety evaluation re postulated fuel handling accident inside containment bldg  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/18  
2pp

--7907180693 Safety evaluation re postulated fuel handling accident inside containment  
\* Office of Nuclear Reactor Regulation 79/05/18 4pp

7907260037 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional o/c will communicate operational & environ info.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp.

## DOCKETED ITEMS

7907110736 Confirms NRC 790607 site visit to observe auxiliary feedwater sys  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/03 2pp

7907250001 Forwards NUREG-0360, "Staff Rept on Generic Assessment of Feedwater Transients in PHRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 1p

7907260084 Forwards Amend 39 to License DPR-53, safety evaluation & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/14 3pp

--7907260092 Amend to License DPR-53, authorizing operation w/modified guide tubes for control element assemblies w/high burnup demonstration fuel assembly installed in core & revising Tech Specs based on analysis of Cycle 4 reload fuel  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/14 39pp

--7907260096 Safety evaluation supporting Amend 39 to License DPR-53  
\* Office of Nuclear Reactor Regulation 79/06/14 19pp

--7907260105 Notice of issuance & availability of Amend 39 to License DPR-53  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/14 2pp

7907090215 Forwards appropriate Class III & Class II fees for amend to OLS re spent fuel pool mod  
OLSON, R C Baltimore Gas & Electric Co 79/07/03 1p

7907090219 Requests amend to OLS DPR-53 & DPR-69 re physical mod to spent fuel pool Forwards proposed mod & licensing rept w/Tech Specs & licensing repts for high density spent fuel storage racks & enriched fuel storage  
ODRE, J W Baltimore Gas & Electric Co 79/07/03 2pp

--7907090222 Forwards appropriate Class I & III amend fees  
OLSON, R C Baltimore Gas & Electric Co 79/07/03 9pp

--7907090224 Proposed change to Unit 1 Tech Specs re high density spent fuel storage racks, prepared by Nuclear Energy Svc, Inc  
\* Baltimore Gas & Electric Co 79/05/24 27pp

--7907090225 Proposed change to Unit 2 Tech Specs re storage of 4 1% enriched fuel, prepared by Nuclear Svc Corp  
\* Baltimore Gas & Electric Co 79/06/11 22pp

7907170062 Discusses Unit 2, Cycle 3 reload core design. Preliminary review indicates no unreviewed safety questions & no Tech Spec changes required C-E review continues  
LUNDVALL, A E Baltimore Gas & Electric Co 79/07/11 3pp

7907190222 Forwards, per 10CFR50.59 rept of changes, tests & experiments, covering period from last rept through 781231  
LUNDVALL, A E Baltimore Gas & Electric Co 79/07/12 27pp

7907260424 Submits nonroutine radiological environ operating rept  
STOUT, J W Baltimore Gas & Electric Co 79/07/23, 2pp

7907310390 Requests amend to Licenses DPR-53 & DPR-69, changing Tech Specs re insp intervals, requirements for environ studies & organizational changes Proposed pages & amend fee encl  
LUNDVALL, A E Baltimore Gas & Electric Co 79/07/24 18pp

Q Inspection reports, IE Bulletins & correspondence

7907100033 Responds to IE Bulletin 79-06B Emergency procedure for LOCA has been revised to include specific instructions contained in bulletin  
LUNDVALL, A E Baltimore Gas & Electric Co. 79/05/08 3pp

7907060375 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/05/22. 1p

7907100021 Responds to IE Bulletin 79-10 Forwards info re examination of reactor operators.  
LUNDVALL, A E Baltimore Gas & Electric Co. 79/05/25 4pp

7907030018 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200481 Submits addl info to 790416 response to IE Bulletin 79-03 re longitudinal weld defects in ASME 8A-312 Type 304 stainless steel pipe spools Recommends radiographic review w/suppl ultrasonic examination  
LUNDVALL, A E Baltimore Gas & Electric Co 79/05/29 2pp

7907190043 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of ASCO Solenoid Valves" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060081 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907300091 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers No Westinghouse DB-50 or DB-75 breakers are in use at facility Preventive maint program includes confirmation of overcurrent time delay protection  
LUNDVALL, A E Baltimore Gas & Electric Co 79/06/08 1p

7907300124 Responds to IE Bulletin 79-02 re concrete expansion anchor bolts Discusses hanger insp program, contributing factors to communications re bulletin, intentions for Unit 1 restart & justification of continued Unit 2 operation  
LUNDVALL, A E Baltimore Gas & Electric Co 79/06/11. 4pp

7907100467 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230644 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907240131 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/06/23 1p

7907120479 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bypass Piping" Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907060174 Forwards IE Circular 79-10, "Pipe Fittings Mfg from Unacceptable Matl" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907030288 Submits addl info in response to IE Bulletin 79-01 re environ qualification of electrical equipment Thirteen ASCO solenoids are not qualified for post-accident environ & will be replaced  
LUNDVALL, A E Baltimore Gas & Electric Co 79/06/28 4pp

7907100492 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180748 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys" Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907290492 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/07/06 1p

7907270318 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/07/11. 1p.

7907310483 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/07/16. 1p.

R Periodic operating reports & related correspondence

7907230271 Forwards monthly operating rept for June 1979  
MERSON, S D Baltimore Gas & Electric Co 79/07/15 1p

--7907230274 Monthly operating rept for June 1979  
MERSON, S D Baltimore Gas & Electric Co 79/07/15 12pp

S Reportable occurrences, LERs & related correspondence

7907030390 Forwards LER 79-019/03L-0  
RUSSELL, L B Baltimore Gas & Electric Co 79/06/25 1p

--7907030393 LER 79-019/03L-0 on 790606 discovered that Number 11 control room air conditioning unit breaker had tripped. Cause by windings of compressor motor exceeding resistance acceptance criteria. Compressor replaced.  
LAQIEWSKI, J B, ROMNEY, K M Baltimore Gas & Electric Co 79/06/25 1p

7907250292 Forwards LER 79-020/03L-0  
RUSSELL, L B Baltimore Gas & Electric Co 79/07/19 1p

--7907250298 LER 79-020/03L-0 on 790706 while performing post-mod test on RCB, power relief valves RC-402-ERV failed to fully close after lifting. Cause not determined. Pilot valve stroke adjusted & relief valve stroked satisfactorily.  
DAVIS, S M, MIERNICKI, M J Baltimore Gas & Electric Co 79/07/19 2pp

U Congressional/Executive Correspondence

7907180130 Responds to 790419 request to evaluate NRC program to license power plant operators. Provides examples of operator error & suggestions for improving training & qualifications.  
STAATS, E B General Accounting Office, 79/05/15 16pp

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2J Insurance & indemnity information

7907060276 Forwards Endorsements 31 & 32 to MAELU Policy MF-76 & Endorsements 36 & 37 to NELIA Policy NF-216  
BHOEMAKER, C L Baltimore Gas & Electric Co 79/06/29 5pp

P Operating license stage documents & correspondence

7907180235 Requests info from currently operating PWRs re small break analysis, as followup to TMI-2 incident review.  
GRIHES, B K, Assistant Director for Engineers & Projects (Pre 790625), 79/05/09 8pp

7907030144 Discusses review of 790313 reanalysis of ECCS small break LOCA. Reanalysis is acceptable. Safety evaluation encl.  
REID, R W, Operating Reactors Branch 4 (Pre 790625) 79/05/18 2pp

--7907030147 Safety Evaluation re reanalysis of small break LOCA w/o charging pump injection  
\* Operating Reactors Branch 4 (Pre 790625) 79/05/18 3pp

7907180492 Forwards safety evaluation re postulated fuel handling accident inside containment bldg  
REID, R W, Operating Reactors Branch 4 (Pre 790625), 79/05/18 2pp

--7907180493 Safety evaluation re postulated fuel handling accident inside containment  
\* Office of Nuclear Reactor Regulation 79/05/18 4pp

7907260037 Discusses plans to install communication links between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info.  
GRIER, B H, Region 1, Philadelphia, Office of the Director, 79/05/22 2pp.

7907110736 Confirms NRC 790607 site visit to observe auxiliary feedwater sys  
REID, R W, Operating Reactors Branch 4 (Pre 790625) 79/06/05 2pp.

7907250001 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W." W/o encl.  
GRIHES, B K, Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 1p.

7907090215 Forwards appropriate Class III & Class II fees for amend to OLS re spent fuel pool mod  
OLSDON, R C Baltimore Gas & Electric Co 79/07/03 1p.

7907090219 Requests amend to OLS DPR-53 & DPR-69 re physical mod to spent fuel pool. Forwards proposed mod & licensing rept w/Tech Specs & licensing repts for high density spent fuel storage racks & enriched fuel storage  
GDRE, J W Baltimore Gas & Electric Co 79/07/03 2pp

--7907090222 Forwards appropriate Class I & III amend fees  
OLSDON, R C Baltimore Gas & Electric Co 79/07/03 9pp

--7907090224 Proposed change to Unit 1 Tech Specs re high density spent fuel storage racks, prepared by Nuclear Energy Svc. Inc.  
\* Baltimore Gas & Electric Co 79/05/24 27pp

--7907090225 Proposed change to Unit 2 Tech Specs re storage of 4 1% enriched fuel, prepared by Nuclear Svc Corp  
\* Baltimore Gas & Electric Co 79/06/11 22pp

7907100662 Discusses Unit 2 Cycle 3 reload core design. Preliminary review indicates no unreviewed safety questions & no Tech Spec changes required. C-E review continues  
LUNDVALL, A E Baltimore Gas & Electric Co 79/07/11 3pp

7907190222 Forwards, per 10CFR50.59 rept of changes, tests & experiments, covering period from last rept through 7B1231  
LUNDVALL, A E Baltimore Gas & Electric Co 79/07/12 27pp

7907260424 Submits nonroutine radiological environ operating rept  
STOUT, J W Baltimore Gas & Electric Co 79/07/23 2pp

7907310390 Requests amend to Licenses DPR-53 & DPR-69, changing Tech Specs re insp intervals, requirements for environ studies & organizational changes. Proposed pages & amend fee encl.  
LUNDVALL, A E Baltimore Gas & Electric Co 79/07/24 18pp.

G Inspection reports, IE Bulletins & correspondence

7907100033 Responds to IE Bulletin 79-06B Emergency procedure for LOCA has been revised to include specific instructions contained in bulletin  
LUNDVALL, A E Baltimore Gas & Electric Co, 79/05/08 3pp.

7907060375 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
GRIER, B H, Region 1, Philadelphia, Office of the Director 79/05/22, 1p.

7907100021 Responds to IE Bulletin 79-10 Forwards info re examination of reactor operators  
LUNDVALL, A E Baltimore Gas & Electric Co 79/05/25 4pp

7907030018 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor."  
GRIER, B H, Region 1, Philadelphia, Office of the Director, 79/05/29 1p

7907200481 Submits addl info to 790416 response to IE Bulletin 79-03 re longitudinal weld defects in ASME BA-312 Type 304 stainless steel pipe spools. Recommends radiographic review w/suppl ultrasonic examination.  
LUNDVALL, A E, Baltimore Gas & Electric Co 79/05/29, 2pp

7907190043 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required  
GRIER, B H, Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060081 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required.  
GRIER, B H, Region 1, Philadelphia, Office of the Director, 79/06/07, 1p

7907300091 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers. No Westinghouse DB-50 or DB-75 breakers are in use at facility. Preventive maint program includes confirmation of overcurrent time delay protection.  
LUNDVALL, A E, Baltimore Gas & Electric Co, 79/06/08, 1p

7907300124 Responds to IE Bulletin 79-02 re concrete expansion anchor bolts. Discusses hanger insp program, contributing factors to communications re bulletin, intentions for Unit 1 restart & justification of continued Unit 2 operation.  
LUNDVALL, A E Baltimore Gas & Electric Co 79/06/11, 4pp.

## DOCKETED ITEMS

7907100467 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/06/20 1p

7907230644 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"  
 Action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/06/21 1p

7907240131 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus"  
 Action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/06/23 1p

7907120479 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping," Licensee action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/06/25 1p.

7907060174 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl"  
 No action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/06/26 1p

7907030288 Submits addl info in response to IE Bulletin 79-01 re environ qualification of electrical equipment  
 Thirteen ABCD solenoids are not qualified for post-accident environ & will be replaced  
 LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/06/28 App

7907100492 Forwards IE Circular 79-12, "Potential Diesel Generator Turbcharger Problem"  
 No action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/06/28 1p

7907180748 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys"  
 Action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/07/02 1p

7907250492 Forwards IE Info Notice 79-18, "Skylab Reentry"  
 No action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/07/06 1p

7907270318 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies"  
 Action required  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/07/11 1p.

7907310483 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors."  
 No action required.  
 ORIER, B. H. Region 1, Philadelphia, Office of the Director  
 79/07/15 1p.

#### R Periodic operating reports & related correspondence

7907230271 Forwards monthly operating rpt for June 1979  
 MERSON, S. D. Baltimore Gas & Electric Co. 79/07/15 1p

--7907230274 Monthly operating rpt for June 1979  
 MERSON, S. D. Baltimore Gas & Electric Co. 79/07/15 12pp.

#### B Reportable occurrences, LERs & related correspondence

7907200403 Forwards LER 79-021/03L-0  
 RUSSELL, L. B. Baltimore Gas & Electric Co. 79/07/13 1p

--7907200409 LER 79-021/03L-0 on 790613, during normal operation, containment atmosphere particulate monitor twice failed low. Monitor corrected & returned to svc.  
 LAQIEWSKI, J. S. MIERNICKI, M. J. Baltimore Gas & Electric Co. 79/07/13 2pp

7907200410 Forwards LER 79-024/03L-0.  
 RUSSELL, L. B. Baltimore Gas & Electric Co. 79/07/16 1p

--7907200415 LER 79-024/03L-0 on 790704, during performance of surveillance testing, control element assembly 2 dropped to core bottom  
 Caused by spike in 15 volt power supply  
 Dual power supplies will be installed next refueling outage.  
 LAQIEWSKI, J. S. Baltimore Gas & Electric Co. 79/07/16 1p.

7907250300 Forwards LER 79-022/03L-0  
 RUSSELL, L. B. Baltimore Gas & Electric Co. 79/07/19 1p

--7907250304 LER 79-022/03L-0 on 790619, containment gaseous & particulate radioactivity monitoring sys failed  
 Caused by loss of sampling pump  
 Pump restarted after 45 minutes  
 No specific maint action taken to correct cause of failure  
 DAVIS, B. M. LAQIEWSKI, J. S. Baltimore Gas & Electric Co. 79/07/19 1p

7907260656 Forwards LER 79-023/03L-0  
 RUSSELL, L. B. Baltimore Gas & Electric Co. 79/07/20 1p

--7907260663 LER 79-023/03L-0 on 790621, diesel tripped repeatedly on low lube oil pressure during test  
 Caused by isolation of engine oil pressure switch  
 Following 790620 preventive maint calibr. Preventive maint procedure changed  
 DAVIS, B. M. MIERNICKI, M. J. Baltimore Gas & Electric Co. 79/07/20 2pp

#### DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

##### A Application/construction stage documents & correspondence

7907110365 "Guide for Licensing of Facility Operators Including Senior Operators"  
 COLLINS, P. F. Operator Licensing Branch HOLMAN, J. J. Office of Nuclear Reactor Regulation NUREG-0094 76/07/31 123pp.  
 Available at NTIS \$5 50

7907110404 "Improving Regulatory Effectiveness in Federal/State Biting Actions"  
 RYAN, R. O. JASKE, R. T. YOUNG, F. W. Office of State Programs. NUREG-0195. 77/05/31 175pp Available at NTIS \$7 50

7907110359 "Study of NRC QA Program," prepared by Sandia Labs.  
 MILLER, F. W. Division of Project Management NUREG-0321 77/08/31 124pp Available at NTIS \$5 50

##### C Utility Environmental Report (ER), amends & correspondence

7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation  
 Pressurizer level info request list encl  
 SHERANSKI, P. Division of Project Management 79/04/19 2pp.

##### E NRC Safety Evaluation Report (SER), suppl & correspondence

7907100095 Forwards SER & suppl re TMI incident W/O encl  
 FITZGERALD, J. A. Office of the General Counsel 79/06/13 1p

##### F Security, medical, emergency & fire protection plans

7907100370 Reg Guide 1 101, Revision 1, "Emergency Planning for Nuclear Power Plants"  
 \* Office of Standards Development 77/03/31. 14pp

##### G Adjudicatory correspondence

7907100287 Forwards draft policy statement on TMI investigations, reflecting NRC decisions at 790413 meeting  
 Portions of transcript of 790413 meeting encl  
 BICKNIT, L. Office of the General Counsel 79/04/14 20pp

--7907100294 Draft statement of policy re TMI investigation. Primary objective will be to make factual determination of events & causes & util & NRC actions before & after incident  
 \* Office of the General Counsel. 79/04/14 5pp

7907160131 Requests summary disposition of intervenors Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact  
 Certificate of Svc encl  
 BORDENICK, B. M. Branch 4. 79/05/25. 29pp.

7907090171 Notifies of typographical errors in Mat Ed joint motion for summary disposition re radon issues  
 Mistakes were in accompanying affidavits  
 BILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge 79/06/05 9pp

7907100061 Statement of policy re TMI investigation. Factual determinations will be made of events, causes & NRC & util actions before & after accident  
 Certificate of Svc encl  
 CHILK, S. J. Office of the Secretary of the Commission 79/06/13 9pp



790718019B Responds to utils motion for summary disposition re radon issues. Twenty-one alleged deficiencies in Perkins record advanced by intervenors are supported in part & opposed in part. Certificate of Bvc encl  
BORDENICK, B M ; LEWIS, B H Branch 4 79/06/14 29pp

7907100133 Responds to request re relevance of NRC 790522 protective order concerning records. Forwards JA Fitzgerald 790614 memo BICKWIT, L. Office of the General Counsel 79/06/15 1p

--7907100140 Advises that NRC 790522 protective order encompasses notes & tape recordings discussed on pages 98-99 of O Millis testimony at 790531 hearing of President's Commission  
FITZGERALD, J A Office of the General Counsel 79/06/14 2pp

790710032B Responds to 790619 telcon re sys of accounting IRS Revenue Rulings 76-265 & 76-428 & relevant pages from MI State Univ Public Util Studies encl  
LIBERMAN, J B Berlack, Israels & Liberman 79/06/19 7pp

--7907100334 Testimony of HM Dieckamp, submitted in recent hearing before PA Public Util Commission, re preliminary analysis of time sequence of TMI incident  
DIECKAMP, H M General Public Utilities 79/06/19 39pp

7907030389 Forwards suits against Met Ed, including Palmer vs Met Ed, Civil Action 79 763, US District Court, Middle District, PA  
CARRIER, W C American Nuclear Insurers 79/06/26 20pp

7907260684 Forwards three suits filed re TMI. Buchart vs Met Ed, Civil Action 70-832; Pancake House Realty Co vs Met Ed, Civil Action 79-850 & Cuts N' Stuf vs Met Ed, Civil Action 79-796  
CARRIER, W C American Nuclear Insurers 79/07/20 21pp.

#### H General correspondence

7907260493 Discusses status of previous, current & planned NRC actions re generic aspects of TMI-2 accident  
CABE, E G Office of Nuclear Reactor Regulation 79/04/04 2pp

7907120166 Submits written records of 790401-09 actions re TMI event took data in TMI-2 control room, was NRC coordinator on late shift, relayed info to control ctr  
BOYD, D C Region 3, Chicago, Office of the Director. 79/04/09 2pp.

7907260509 Discusses concept of flexible response as one lesson learned after TMI-2 incident. Recommends use of concept in operator training & instrument design to provide info under unstable conditions that may arise  
LEWIS, H W California, Univ of, Santa Barbara 79/04/13 2pp

7907100249 Submits written record of 790328-0414 actions re TMI event, conducted radiation survey & operated mobile lab  
GOBTELL, F M Region 1, Philadelphia, Office of the Director. 79/04/14 1p

7907100284 Submits written record of 790329-0409 actions re TMI event reviewed & coordinated environ data collected by NRC & licensee  
EBBIO, T. H Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/16 2pp

7907120661 Requests rept from region staff re any time spent at TMI site during 790328-0414  
SNYDER, O L Region 1, Philadelphia, Office of the Director. 79/04/17 1p

7907260494 Discusses review considerations for plants nearing OL decision in light of TMI-2.  
SHOVHOLT, D. Assistant Director for Quality Assurance & Operations 79/04/17 2pp

7907260497 Forwards memorandum by M Spangler memo on possible effects of TMI on cost-benefit issues. Suggests meeting w/RC DeYoung to discuss issue w/o encl  
ERNST, M L Assistant Director for Environmental Technology. 79/04/19 1p.

7907260500 Lists suggested supplementary review & budgetary considerations within QA Branch for plants nearing OL decisions, in light of TMI-2 event.  
HAASS, W. P. Quality Assurance Branch. 79/04/23 7pp.

7907260573 Discusses training seminar re entry into restricted radiation areas proposed for NRC personnel. Proposed seminar encl.  
GRIBBS, B Assistant Director for Engineers & Projects (Pre 790625) 79/04/23 3pp.

7907100302 Submits written record of 790329-0405 actions re TMI event directed radiation specialists providing in-plant surveillance of radiation protection & radwaste programs  
FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/24 3pp

7907100309 Submits written record of 790330-0404 actions re TMI event monitored licensee health physics program for Unit 1, conducted routine surveys of areas outside plants  
HIATT, J. W. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/24 2pp

7907120208 Submits written record of actions re TMI event notes & calculations  
GOLDSMITH, R Radiological Health Standards Branch 79/04/24 16pp.

7907100315 Submits written record of 790330-0407 actions re TMI event conducted off-island environ radiation measurements & assessments, prepared "Summary of Iodine Situation."  
DICEV, B B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/04/25 8pp

7907100325 Submits written record of 790330-0413 actions re TMI event observed handling of effluents, water balance & transfers in plant, assisted in review of procedures  
MILLER, D E Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 2pp

7907100347 Submits written record of 790330-0409 actions re TMI event shift leader of environ monitoring team  
GRANT, W. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/26 1p.

7907260503 Discusses need for greater analytical support to NRC mgt during operating plant incidents  
AUDETTE, R. F. Analysis Branch 79/04/27 5pp

7907100234 Submits written record of 790420-0428 actions re TMI event, member of Environ Mobile Survey Team, took air & vegetation samples, performed direct environ radiation surveys  
SUMMERS, R J Region 1, Philadelphia, Office of the Director 79/04/28 1p

7907100291 Submits written record of 790420-2B actions re TMI event took air & vegetation samples, performed environ radiation surveys  
SHAUB, E. T. Region 1, Philadelphia, Office of the Director. 79/04/28 1p

7907120203 Submits written record of 790328-0409 actions re TMI event collected info re chemical kinetics of water radiolysis coolant composition, possible borohydride formation  
READ, J. B. Division of Site Safety & Environmental Analysis 79/05/01 34pp

7907120240 Submits written record of 790404-05 actions re TMI event obtained info from B&W re plant sys affected by incident. Handwritten notes encl.  
CHERNY, F C Mechanical Engineering Branch 79/05/02 13pp.

7907120193 Submits written record of 790402 actions re TMI event summary of telcon w/C Frenzel, Coastal Science Associates, re structural changes in TMI concrete  
HALAPATZ, J. Division of Systems Safety 79/05/03 3pp

7907260519 Requests review of philosophy & requirements re operating procedures at nuclear power plants in light of TMI incident  
KENNEDY, R. T. Commission 79/05/03 1p

7906200417 Forwards list of NRC personnel receiving access key & cards for TMI-1. Info partially withheld. Social Security numbers (ref FOIA Exemption 6)  
BLODINIEN, M J. Region 1, Philadelphia, Office of the Director. 79/05/04 5pp

7907100249 Submits written record of 790426-0505 actions re TMI event member of environ mobile survey team, took air & vegetation samples, performed direct radiation surveys of environ  
SMITH, G. C. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/05/05 1p

7907100260 Submits written record of 790502-06 actions re TMI event, repaired & modified equipment in NRC equipment van, performed miscellaneous errands when required.  
SHAUB, E. T. Region 1, Philadelphia, Office of the Director 79/05/06 1p

## DOCKETED ITEMS

- 7907100331 Submits written record of 790411-25 actions re TMI event conducted environ direct & airborne radiation surveys & collected grass samples  
HAQUE, R.L. Region 3, Chicago, Office of the Director 79/05/10 1p
- 7907100589 Submits written record of 790419-0503 actions re TMI event obtained hourly monitor readings, collected in-plant charcoal & particulate samples, recorded sources of liquids released  
HUETER, L.J. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/10 2pp
- 7907100234 Submits written record of 790511-21 actions re TMI event assigned to environ mobile survey team, took air samples, performed direct environ radiation surveys  
MCKEOWN, L.M. Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7907100335 Submits written record of 790330-0412 actions re TMI event assigned to environ monitoring team mobile unit, performed surveys in plume, collected air, soil & water samples  
PAUL, R.A., BRENIANSKI, D.J. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/11 2pp
- 7907100278 Submits written record of 790510-14 actions re TMI event assigned to environ mobile survey team, took air & vegetation samples & performed direct radiation surveys  
SMITH, G.C. Region 1, Philadelphia, Office of the Director 79/05/14 1p
- 7907100341 Submits written record of 790419-0504 actions re TMI event communicator for in-plant health physics group & later in-plant health physics inspector  
OSBERG, C.R. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/15 2pp
- 7100355 Submits written record of 790423-0506 actions re TMI event control room inspector  
DOULES, N.C. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/16 1p
- 7100365 Submits written record of 790402-16 actions re TMI event collected & collated environ data, supported Unit 2 control room operations, represented IE on procedures committee  
JORGENSEN, B.L. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/16 2pp
- 7907100382 Submits written record of 790330-0516 actions re TMI event coordinated & directed operations inspectors, developed sequence of events, reviewed procedures  
LITTLE, W.S. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/16 1p
- 7907100390 Submits written record of 790402-11 actions re TMI event worked on sequence of events & as IE shift supervisor.  
WARNICK, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/16 1p
- 7120185 Submits written record of 790401 actions re TMI event contacted outside organizations re hydrogen concentration in containment & methods of control  
CHIERLING, W. Accident Analysis Branch 79/05/16 1p
- 7100400 Submits written record of 790419-29 actions re TMI events reviewed & approved plant procedures, provided liaison between licensee & NRC, obtained key plant parameter data.  
BOYD, D.C. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/21 2pp
- 7907100405 Submits written record of 790330-0413 actions re TMI event assigned as communicator for in-plant health physics team, reassigned to observe Unit 1 health physics operations  
AKELSON, W.L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/22 1p
- 7907100410 Submits written record of 790424-0507 actions re TMI event, worked on respiratory protection program, followed use of svc air for respiratory protection.  
FISH, R.F. Region 4, Dallas, Office of the Director. 79/05/23 2pp
- 7907100419 Submits written record of 790411-24 actions re TMI event, reviewed operating & emergency procedures, observed control room operations  
GUTTS, J.E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/23 1p
- 7907100428 Submits written record of 790412-26 actions re TMI event assigned as environ shift leader, coordinated NRC environ monitoring onsite, maintained shift log.  
TROJANOWSKI, R.E. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/23 1p
- 7907160320 Ack 790423 ltr re implications of TMI-2 event Detailed study of event has been initiated during which comments will be considered  
DENTON, H.R. Office of Nuclear Reactor Regulation 79/05/23 1p
- 7907100435 Submits written record of 790425-0509 actions re TMI event assigned to control room  
BRADFORD, W.H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/24 1p
- 7907100438 Submits written record of 790423-0506 actions re TMI event served as Unit 2 control room inspector  
CHOULES, N.C. Region 3, Chicago, Office of the Director 79/05/24 1p
- 7907120184 Forwards written records of IE Region 3 personnel on actions re TMI event W/o encl  
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/05/24 1p
- 7907190311 Ack receipt of 790514 ltr requesting comments re revised subcommittee rept on TMI-2 followup health effects research Forwards specific editorial changes W/o encl  
GOLLER, K.R. Division of Siting, Health & Safeguards Standards 79/05/24 2pp
- 7907090441 Forwards comparative listing of safety concerns before & after TMI incident Safety concerns are generic to all nuclear plants  
BASDEKAS, D.L. Office of Nuclear Regulatory Research 79/05/25 2pp
- 7907100441 Submits written record of 790408-22 & 0507-17 actions re TMI event assigned as in-plant health physics shift supervisor  
OREGER, L.R. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/25 3pp
- 7907120177 Submits written record of 790518-25 actions re TMI event assigned to environ mobile survey team, took air samples, vegetation samples, performed direct radiation surveys  
SMITH, G.C. Region 1, Philadelphia, Office of the Director 79/05/25 1p
- 7907130277 Ack assistance w/hydrogen bubble problem at TMI-2.  
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/05/25 1p.
- 7907100445 Submits written record of 790330-0413 actions re TMI event monitored licensee health physics activities in Units 1 & 2, monitored robot testing for primary sampling  
TONGUE, T.M. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/30 1p
- 7907100447 Submits written record of 790502-14 actions re TMI event assigned as in-plant health physics shift w/principal duties involving radioactive waste mgt  
TROUP, G.L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/30 4pp
- 790710646 Certifies that AR Duhl may appear before NRC on behalf of himself or Technology for Energy Corp. Appearance involves TMI incident  
GOSBICK, L.V. Office of the Executive Director for Operations 79/05/30 2pp
- 7907190301 Confirms 790608 briefing re TMI event  
BAKER, R.E. Radiological Health Standards Branch. 79/05/30 1p
- 7907100452 Submits written record of 790510-25 actions re TMI event assigned as environ shift coordinator, dispatched field monitoring teams, directed environ sampling, kept shift log  
ANDREWS, D.L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/31 1p
- 7907100454 Submits written record of 790328-0403 actions re TMI event maintained telephone communications w/Incident Response Ctrs, observed control room operations  
BAUNACH, W.H. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/31 3pp
- 7907100461 Submits written record of 790514-24 actions re TMI event assigned to Environ Survey Team  
BURGIN, R.E. Region 3, Chicago, Office of the Director. 79/05/31 1p
- 7907100464 Submits written record of 790524-25 actions re TMI event: reviewed results of electrical insp of 790508-11 & receipt of electrical van for control of decay heat removal sys  
FINKEL, A.E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/31 1p

- 7907100469 Submits written record of 790426-0511 actions re TMI event made direct reading radiation surveys & took air samples offsite, received data from in-plant personnel  
SCHULTZ, W H Region 3, Chicago, Office of the Director 79/05/31 1p.
- 7907100477 Submits written record of 790506-21 actions re TMI event assigned to in-plant health physics coverage w/responsibility for reviewing Unit 1 & 2 activities  
KRAY, J R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/31 2pp
- 7907100524 Submits written record of 790426-0511 actions re TMI event assigned to survey team, performed perimeter & area monitoring to determine meter readings from Unit 2 releases  
YOUNG, H W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/31 1p
- 7907120254 Submits written record of 790506-21 actions re TMI event was day shift section chief for operations  
MCQUAHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/05/31 2pp
- 7907100180 Forwards commission guidelines on FOIA release of documents re TMI event Decisions to withhold or release staff-level documents are to be made by staff officers  
CHILK, B J Office of the Secretary of the Commission 79/06/01 3pp.
- 7907100535 Submits written record of 790507-18 actions re TMI event observed operations such as maintaining pressurizer level stack exhaust monitoring & new sys status  
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/01 2pp
- 7907100336 Submits written record of 790430-0513 actions re TMI event served as environ monitoring shift leader  
PAOLIARD, J A Region 3, Chicago, Office of the Director 79/06/01, 2pp
- 7907100540 Submits written record of 790425-0510 actions re TMI event performed shift duty in Unit 2 control room taking specific data hourly & transmitting info via telephone to NRC  
RILEY, B W. Region 2, Atlanta, Office of the Director 79/06/01 1p
- 7907100342 Forwards investigation rept re allegations made in 1975 by former TMI-2 guards w/o encl  
THOMPSON, D. Office of I & E Executive Officer for Operations Support 79/06/01 1p
- 7907160329 Ack 790419 ltr re TMI investigation Points raised will be carefully considered during detailed investigation  
HENDRIE, J. M. Commission 79/06/01 1p
- 7907100209 Forwards two transcripts of ACRS meetings re TMI event Transcripts were omitted from 790601 mailing w/o encl  
FITZGERALD, J A Office of the General Counsel. 79/06/04 1p
- 7907030008 Describes organizational structure & plans of NRC/TMI special inquiry staff  
CORNELL, E. K. NRC Three Mile Island Task Force. 79/06/05 2pp
- 7907100194 Notifies of 790601 mailing of ACRS meeting transcripts to R Dicker of President's Commission  
FITZGERALD, J A Office of the General Counsel 79/06/05 1p
- 7907100541 Submits written record of 790508-23 actions re TMI event. assigned as operations inspector to observe conduct of operations, monitored plant sys & plant mods  
ASHENDEN, M C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/05 1p.
- 7907100346 Submits written record of 790406-19 & 0514-24 actions re TMI event; assigned to in-plant health physics surveillance  
THOMAS, R. D. Region 3, San Francisco, Office of the Director 79/06/05, 2pp
- 7907100348 Submits written record of 790413-0515 actions re TMI event; performed surveillance of const activities re plant mods  
WALTON, O A. Region 1, Philadelphia, Office of the Director. 79/06/05, 1p
- 7907100343 Forwards requested copy of WASH-1400 W/o encl  
CORNELL, E. K. NRC Three Mile Island Task Force. 79/06/05 1p
- 7907100398 Forwards NUREQ-0557, "Evaluation of Long-Term Post Accident Core Cooling of TMI-2." W/o encl.  
FITZGERALD, J. NRC Three Mile Island Task Force. 79/06/05 1p.
- 7907100351 Submits written record of 790405-07 & 18-20 actions re TMI event provided liaison between licensee & NRC, monitored control room activities, reviewed Tech Specs  
BRIGGS, L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/06 2pp
- 7907100554 Submits written record of 790426-0511 actions re TMI event assigned as environ monitoring team leader  
PERROTTI, D J Region 2, Atlanta, Office of the Director 79/06/06 2pp
- 790710684 Responds to 790503 questions re TMI Forwards answers provided to Senator Hart committee questions & NRC 790510 rept on population dose & health impact of TMI  
DENTON, H R Division of Operating Reactors 79/06/06 9pp
- 790710697 Ack receipt of 790413 ltr expressing views re nuclear power, TMI accident & waste disposal Forwards discussion of NRC role in solution of waste problem  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/06 4pp
- 790710707 Urges NRC to invest in developing technology to make nuclear plants & waste totally safe Current nuclear industry is unsafe  
NOLAN, H O Affiliation Unknown 79/04/13 1p
- 7907100358 Notifies that NUREQ-0557, "Evaluation of Long Term Post-Accident Core Cooling of TMI-2" will be sent on 790606  
FITZGERALD, J NRC Three Mile Island Task Force 79/06/06 1p
- 7907160260 Forwards info requested by EK Cornell for Presidential TMI Commission  
LARKING, J T Program Coordination Branch 79/06/06 1p
- 7907160266 Provides synopsis of assistance rendered during TMI-2 event through Apr 1979 to Branch staff by resources from outside NRC  
MCORATH, P E Probabilistic Analysis Branch 79/06/05 2pp
- 7907160271 Ack receipt of EK Cornell 790531 memo transmitting request for info from Presidential Commission Provides list of consultant personnel & work performed  
BUDNITZ, R J Office of Nuclear Regulatory Research 79/06/06 7pp
- 7907030006 Suggests procedures to be followed in obtaining info re TMI incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/07, 2pp
- 7907100358 Submits written record of 790429-0504 action re TMI event provided liaison w/licensee re radiogas effluent control & NRC notification of anticipated releases  
BECKMAN, D A Region 1, Philadelphia, Office of the Director 79/06/07 3pp
- 7907100563 Submits written record of 790511-25 actions re TMI event provided Unit 2 control room surveillance & reviewed recovery procedures  
JOHNSON, J R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/07 3pp
- 7907120173 Forwards written records of IE Region 3 personnel re actions TMI event, w/o encl  
KEPLER, J O Region 3, Chicago, Office of the Director 79/06/07 1p
- 7907100395 Responds to 790606 request for copies of NUREQ-0560 W/o encl  
FITZGERALD, J A NRC Three Mile Island Task Force 79/06/07 1p.
- 7907190059 Ack receipt of 790509 ltr to Congressman Mica re invention of disaster prevention device, TRIP-A-LARM. Requests further info  
MATTHEW, R. J Division of Systems Safety 79/06/07 1p
- 7907030001 Requests name, title & telephone of individual within HEW to be contacted by NRC during investigation of TMI-2 incident.  
CORNELL, E. K NRC Three Mile Island Task Force 79/06/08, 1p
- 7907030002 Requests name, title & telephone of individual within DOE to be contacted by NRC during investigation of TMI-2 incident.  
CORNELL, E. K NRC Three Mile Island Task Force 79/06/08, 1p
- 7907030003 Requests name, title & telephone of individual within EPA to be contacted by NRC during investigation of TMI-2 incident.  
CORNELL, E. K NRC Three Mile Island Task Force 79/06/08, 1p.

## DOCKETED ITEMS

- 7907030004 Requests name, title & telephone of individual within small Business Administration to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/08 1p
- 7907030028 Requests name, title & telephone of individual within Dept of Commerce to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/08 1p
- 79070300293 Requests name, title & telephone of individual within Interstate Regional Councils to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/08 1p
- 79070300302 Requests name, title & telephone of individual within OSA to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/08 1p
- 7907160225 Forwards RC DeYoung 790606 memo requesting info on NRC activities re TMI-2 accident Requests response by 790613  
LARKIN, B J Program Coordination Branch 79/06/08 1p
- 7907160230 Requests brief description of personnel activity in response to TMI-2 incident Distribution list encl  
DEYOUNG, R C NRC Three Mile Island Task Force 79/06/06 7pp
- 7907030035 Requests name, title & telephone of individual within Dept of Labor to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/11 1p
- 7907030040 Requests name, title & telephone of individual within DOT to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/11 1p
- 7907030024 Requests name, title & telephone of individual within HUD to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/12 1p
- 7907030048 Requests name, title & telephone of individual within Defense Civil Preparedness Agency to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/12 1p
- 7907030052 Requests name, title & telephone of individual within DOD to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/12 1p
- 7907030130 Requests name, title & telephone of individual within Dept of Agriculture to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/12 1p
- 7907030280 Requests name, title & telephone of individual within Postal Svc to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/12 1p
- 7907030285 Requests name, title & telephone of individual within Federal Regional Council to be contacted by NRC during investigation of TMI-2 incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/12 1p
- 7907100565 Submits written record of 790520-0601 actions re TMI event assigned to review Unit 1 & 2 in-plant health physics activities.  
HOBSEY, C M Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/12 2pp
- 7907100573 Submits written record of 790524-0608 actions re TMI event assigned as environ survey team leader  
MACARTHUR, T C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/12 1p
- 7907130362 Responds to 790606 R DeYoung memo. Author was not involved in TMI investigation until first week of May 1979.  
COX, T H NRC Three Mile Island Task Force 79/06/12, 1p
- 7907100576 Submits written record of 790427-0504 actions re TMI event provided clerical assistance such as typing, operating xerox & telecopy machines & answering telephones.  
DIDONATO, M J Region 1, Philadelphia, Office of the Director, 79/06/13, 1p
- 7907100579 Submits written record of 790331-0406 actions re TMI event provided clerical assistance such as typing, operating xerox & telecopy machines & answering telephones  
LAW, S K Region 1, Philadelphia, Office of the Director 79/06/13 1p
- 7907120224 Submits written record of 790416-23 actions re TMI event coordinated IE activities, represented IE at licensee senior technical meeting, supervised IE inspectors  
KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/06/13 2pp
- 7907120234 Submits written record of 790417-0526 actions re TMI event completed environ TLD run, assisted Mobile Lab in counting samples & calculating results, prepared environ rept w/EPA  
HCOINNEBB, J A Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/13 1p
- 7907130253 Supplies requested info re B&W reactors either currently in operation, under const or in planning stage  
CORNELL, E K NRC Three Mile Island Task Force 79/06/13 1p
- 7907130295 Act 790419 ltr to JM Hendrie & President Carter considering human factors in design of nuclear facilities Forwards NUREG-0560, description of NRC actions. W/o encl  
HINDQUE, R B Office of Standards Development 79/06/13 2pp
- 7907130318 Requests cooperation w/TMI-2 investigation by supplying info re agency actions as result of incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/13 1p
- 7907130346 Forwards draft interviews of TMI-2 operators W/o encl  
CORNELL, E K NRC Three Mile Island Task Force 79/06/13 1p
- 7907100585 Submits written record of 790508-11 actions re TMI event witnessed installation of diesel cables, inspected mods to circulating water & steam generator pumps  
FINKEL, A E Region 1, Philadelphia, Office of the Director 79/06/14 2pp
- 7907130350 Forwards list of potential Task Group 3 interviews to date  
MIRAGLIA, F J NRC Three Mile Island Task Force 79/06/14 3pp
- 7907130424 Forwards accession list of TMI-2 documents from 790522 through 790608  
NORRY, P NRC Three Mile Island Task Force 79/06/14 107pp
- 7907130308 Requests cooperation w/TMI-2 investigation by supplying info re company actions as result of incident  
CORNELL, E K NRC Three Mile Island Task Force 79/06/15 1p
- 7907130312 Forwards transcript of ACRS Subcommittee on TMI-2 790614 meeting held in Middletown, PA, Pp 1-192, W/o encl  
CORNELL, E K NRC Three Mile Island Task Force 79/06/15 1p
- 7907190256 Requests listing of logs re TMI-2 event before 790702 Forwards format for listing  
CRUTCHFIELD, D M Technical & Administrative Support Branch 79/06/28 2pp
- 7907190306 Submits written record of 790328-0628 actions re TMI event recommended method to calculate break flow, calculated core condition & bubble size & natural circulation.  
HOLAHAN, G M Analysis Branch 79/06/28 2pp
- 7907200449 Conveys Commissioners appreciation & commendation to employees who provided emergency communications during TMI incident  
HENDRIE, J M Commission 79/07/03 1p
- 7907200457 Conveys appreciation for assistance offer re TMI incident Accepts offer to share lessons learned from 1952 Canadian research reactor accident Interested in various areas of cooperation, including long-term info exchange  
HENDRIE, J M Commission 79/07/03 1p
- 7907200479 Conveys appreciation for info re TMI incident. Plans review of Canadian reactors engendered by TMI. Requests authoritative & interim repts. Offers to brief NRC on lessons learned from 1952 Canadian research reactor accident  
JENNEKENS, J H Canada, Atomic Energy Control Board 79/04/09 2pp
- 7907180080 Follows up 790705 transmittal of Nuclear Regulatory Research records Forwards page 3 inadvertently omitted from 790522 Denhong-Cunningham ltr re march/corral analyses of hypothetical meltdown scenarios  
SCROGGINS, R M Administrative and Resource Control Staff, 79/07/12 2pp

## J Insurance &amp; indemnity information

7907100181 Forwards ltr from resident of Lancaster, PA seeking compensation of \$200 for evacuation expenses ltr is being sent to ANI along w/draft response from BJ Chilk BICKWIT, L Office of the General Counsel 79/06/06 1p

--790710018B Draft response to 790528 ltr requesting compensation of \$200 for evacuation expenses Claim has been forwarded to ANI CHILK, B J Office of the Secretary of the Commission 79/06/06 1p

--7907100837 Requests compensation of \$200 for evacuation expenses NRC was aware of deficiencies in reactors and did not take proper action STARR, P Affiliation Unknown 79/05/25 1p

7907030489 Submits update on indemnity paid & total claim & legal expenses paid re TMI incident CARRIER, W C American Nuclear Insurers 79/06/27 1p

7907090295 Confirms 790607 conversation re request by General Public Util for meeting w/NRC & nuclear pools to discuss financial protection requirements NRC will issue no orders on protection until questions are resolved BOLLMAN, C T Marsh & McLennan, Inc 79/06/29 2pp

7907100397 Discusses consolidated class action complaint re TMI event Forwards 790702 ltr to reactor operators re possible financial involvement w/consolidated class action; Fastasky vs General Public Utils CARRIER, W C American Nuclear Insurers 79/07/05 31pp

790710232 Forwards consolidated class action complaint filed 790627 & 790625 draft of socioeconomic study re impact of TMI CARRIER, W C American Nuclear Insurers 79/07/11 1p

--790710235 Comments on socioeconomic impact of TMI incident re liability claims & reimbursements Documentation re particular claims encl CARRIER, W C American Nuclear Insurers 79/06/25 14pp

0 Advisory Committee on Reactor Safeguards reports & correspondence

790710350 Unofficial transcript of 740723 meeting of ACRS Subcommittee on TMI in Harrisburg, PA to review info re issuing OL ARNDL, J M ACRS - Advisory Committee on Reactor Safeguards 76/09/23 504PP.

7907020104 Submits interim rept on incident at TMI Circumstances of TMI reviewed at 228th ACRS meeting on 790405-07 Agreed that PWR operators have difficulty understanding & controlling incident involving small break in RCS CARBON, M W ACRS - Advisory Committee on Reactor Safeguards 79/04/07 2pp.

7907020099 Submits schedule for discussion at special ACRS meeting on 790416-17 in Washington, DC re TMI-2 incident \* ACRS - Advisory Committee on Reactor Safeguards 79/04/11 3pp

7907090477 Forwards, for review & comment, preliminary copy of C Nicholson "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR" EISENHUT, D Division of Operating Reactors 79/04/17 37pp

7907100192 Notifies that ACRS 790417 recommendations were not intended to apply to TMI. Plant has begun survey of operating procedures for achieving natural circulation CARBON, M W ACRS - Advisory Committee on Reactor Safeguards 79/04/20 3pp

7907100223 Suggests improvements in presenting info to reactor operators. Better info display would relax dependence on operator diagnostic skills BENDER, M ACRS - Advisory Committee on Reactor Safeguards 79/05/02 3pp

7907100200 Forwards Duke Power Co ltr indicating planned changes in response to TMI-2 events & IE Bulletin BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/08 1p.

7907020394 Submits recommendations from ACRS 790510-12 meeting re TMI incident Suggests that procedures be developed by all operators of PWRs for initiating natural circulation in safe manner. CARBON, M W ACRS - Advisory Committee on Reactor Safeguards 79/05/16 3pp.

--7907020404 Offers addl recommendations re TMI incident Suggests all PWR licensees submit design proposals & schedules for completing provision for instrumentation showing unambiguous indication of vessel fluid in reactor CARBON, M W ACRS - Advisory Committee on Reactor Safeguards 79/05/16 5pp

7907100067 Forwards notice of ACRS meeting for publication in 790523 Federal Register CHILK, B J Office of the Secretary of the Commission 79/05/17 1p

790710216 Forwards pages from plant operating procedures re addition of feedwater to hot dry steam generators Number of transients which are acceptable might be explored w/o encl BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/25 1p

790710225 Forwards LER re loss of pressurizer level indication Presents questions to be addressed during review of long-term implications of TMI w/o encl BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/25 1p

7907020484 Discusses 790501 meeting w/C-E re natural circulation conditions At TMI power operated relief valve did not close. Vendor should investigate open valve BHEMMON, P O ACRS - Advisory Committee on Reactor Safeguards 79/05/30 1p

7907100002 Forwards observations re civil defense aspects of TMI & OAD rept on emergency preparedness from 790516 hearing of House Committee on Armed Svc. Subcommittee on Military Installations & Facilities JOHNSON, D H ACRS - Advisory Committee on Reactor Safeguards 79/05/30 7pp

--7907100003 Transcript of opening statement of LN Nedzi & JD Peach at 790516 hearing of House Committee on Armed Svc. Subcommittee on Military Installations & Facilities DH Johnson 790530 memo encl NEDZI, L N House of Rep : Armed Services 79/05/16 21pp

7907100004 Summary of 790508 hearings before Subcommittee on Energy, Nuclear Proliferation & Federal Svc of Committee on Governmental Affairs re radiation monitoring at TMI & survivors of atomic tests. UNDERHILL, D W ACRS - Advisory Committee on Reactor Safeguards. 79/05/30 2pp.

--7907100005 Transcript of opening statement by J Glenn at 790508 hearing before Subcommittee on Energy, Nuclear Proliferation & Federal Svc of Committee on Governmental Affairs re research & regulatory issues of radiation protection w/witness list GLENN, J Senate, Governmental Affairs 79/05/08 1p.

--7907100007 Transcript of testimony of FP Libassi at 790508 hearings before Subcommittee on Energy, Nuclear Proliferation & Federal Svc of Committee on Governmental Affairs re research & regulatory issues of radiation protection LIBASSI, F P Health, Education & Welfare, Dept. of 79/05/08 18pp.

--7907100008 Transcript of testimony of DG Hawkins at 790508 hearings before Subcommittee on Energy, Nuclear Proliferation & Federal Svc of Committee on Governmental Affairs re research & regulatory issues of radiation protection HAWKINS, D G Environmental Protection Agency. 79/05/08 10pp.

--7907100009 Transcript of testimony of RC Clusen at 790508 hearings before Subcommittee on Energy, Nuclear Proliferation & Federal Svc of Committee on Governmental Affairs re research & regulatory issues of radiation protection CLUSEN, R C Energy, Dept. of. 79/05/08 12pp.

--7907100010 Transcript of testimony of RB Minogue at 790508 hearing before Subcommittee on Energy, Nuclear Proliferation & Federal Svc of Committee on Governmental Affairs re research & regulatory issues of radiation protection. MINOGUE, R B Office of Standards Development 79/05/08 13pp.

790710248 Forwards W Poe 790502 ltr to Memphis newspaper Commercial Appeal, suggesting accident was sabotage. Accident was not due to sabotage. MCKINLEY, J L ACRS - Advisory Committee on Reactor Safeguards 79/05/30 4pp.

790710324 Forwards background info from ACRS subcommittee re TMI, including transcripts of employee interviews, responses to IE bulletins, temporary mode, sequence of events, NUREG-0560, ACRS rept on incident & shutdown orders w/o encl. MAJOUR, R K ACRS - Advisory Committee on Reactor Safeguards 79/05/30 2pp.

## DOCKETED ITEMS

- 7907110011 Forwards news clip, NRC statement, NRC memo & Congressional Subcommittee transcript re date of NRC access to Michelson small break analysis at B&W reactors NRC had access to rept in Oct 1977  
MCKINLEY, J C ACRS - Advisory Committee on Reactor Safeguards 79/05/31 3pp
- 7907110014 Notifies of status of NRC knowledge as of 790523 re C Michelson Jan 1978 rept, "Decay Heat Removal During Very Small Break LOCA for B&W ROS - Fuel Assembly PWR"  
\* ACRS - Advisory Committee on Reactor Safeguards 79/05/23 6pp
- 7907110016 Transcript of MK Udall opening statement at 790524 hearing before Subcommittee on Energy & Environ. oversight hearings on TMI  
UDALL, M K House of Rep., Interior & Insular Affairs 79/05/24 2pp
- 7907110020 Notifies of discovery of deleterious sys interaction resulting from NRC-mandated fix to PWR re TMI Problem was identified by WE Electric Power Co Forwards NRC amend to DL BOEHMERT, P ACRS - Advisory Committee on Reactor Safeguards 79/06/01 1pp
- 7907110047 Notifies of 790606-07 meeting w/TMI-2 Subcommittee in Middletown, PA Location of meeting has been changed Map encl  
MULLER, R ACRS - Advisory Committee on Reactor Safeguards 79/06/01 6pp
- 7907110071 Notifies that discussion of block valves between 4-h 6 minutes & 4-h 34 minutes is on agenda of 790606 meeting Forwards util opinion on problem & operational log from plant  
MULLER, R ACRS - Advisory Committee on Reactor Safeguards 79/06/02 4pp
- 7907110076 Summary of 790521 hearings of House Committee on Interior & Insular Affairs in Washington, DC re TMI, future of commercial nuclear power & Michelson 1978 memo  
ALDERMAN, H ACRS - Advisory Committee on Reactor Safeguards 79/06/04 8pp
- 7907110079 Transcript of testimony of J Weaver at 790521 hearing of Committee on Interior & Insular Affairs re TMI  
WEAVER, J House of Rep., Interior & Insular Affairs 79/05/21 8pp
- 7907110086 Transcript of 790521 hearing of Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearings re TMI  
WEAVER, J, RUNNELS, H, CARR, R House of Rep., Interior & Insular Affairs 79/05/21, 11pp
- 7907110194 Responds to ACRS recommendations re TMI-2 accident  
DENTON, H R Office of Nuclear Reactor Regulation. 79/06/04 2pp
- 7907110330 Forwards A Weinberg testimony before Senate Committee on Governmental Affairs, Subcommittee on Energy Radiation level in Senate Ofc Bldg is higher than that received downwind of TMI, W/o encl  
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/06/04 1p
- 7907110111 Transcript of testimony of H Dieckamp at 790524 hearing of House Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearings re TMI Witness list encl  
DIECKAMP, H M General Public Utilities 79/05/24 29pp.
- 7907110122 Transcript of testimony of JO Herbein at 790524 hearing of House Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearings re TMI.  
HERBEIN, J O Metropolitan Edison Co 79/05/24 19pp.
- 7907110129 Transcript of testimony of OP Miller at 790524 hearing of House Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearings re TMI.  
MILLER, O P Metropolitan Edison Co 79/05/24, 32pp.
- 7907110135 Transcript of testimony of B Lee at 790524 hearing of House Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearings re TMI AIF 790419 & 0511 ltrs encl.  
LEE, B Atomic Industrial Forum 79/05/24 11pp.
- 7907110141 Transcript of testimony of WS Lee testifying on behalf of EEI at 790524 hearing of House Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearing re TMI.  
LEE, W B Duke Power Co 79/05/24, 9pp.
- 7907110150 Transcript of testimony on behalf of B&W at 790524 hearing of House Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearing re TMI Supporting documentation encl.  
\* Babcock & Wilcox Co 79/05/24 34pp.
- 7907110200 Recommends ACRS closely examine generic implications of normally unreviewed aspects of control sys failures & plant dynamics affecting all operating plants  
BARDEKAS, D L Experimental Fast Reactor Safety Research Branch 79/06/05 1p.
- 7907110156 Forwards Westinghouse response to NRC questions re main feedwater & auxiliary feedwater sys  
DURASWAMY, S ACRS - Advisory Committee on Reactor Safeguards 79/06/07 1p
- 7907110365 Notifies that transcript of 790521 ACRS Ad Hoc Subcommittee meeting, pp 1-350, re TMI-2 incident implications will be sent on 790607  
CORNELL, E K NRC Three Mile Island Task Force. 79/06/07 1p
- 7907110160 Forwards util computer listing of all procedures in effect at plant as of 790524  
MULLER, R ACRS - Advisory Committee on Reactor Safeguards 79/06/08 1p.
- 7907110166 Computer listing of all procedures in effect at plant as of 790524  
\* Metropolitan Edison Co 79/05/24 53pp
- 7907110170 Forwards summary of ACRS subcommittee meeting re TMI  
TAM, P ACRS - Advisory Committee on Reactor Safeguards 79/06/13 3pp
- 7907110179 Forwards TMI questions to be addressed during ACRS 790614-15 meeting  
MULLER, R ACRS - Advisory Committee on Reactor Safeguards 79/06/13, 5pp.
- 7907110236 Summary of 790611 meeting w/util to discuss proposed actions prior to TMI startup  
TAM, P ACRS - Advisory Committee on Reactor Safeguards 79/06/13 2pp
- 7907110241 Emergency plan for facility.  
\* Metropolitan Edison Co. 79/06/11 11pp
- 7907110187 Forwards EPA-520/6-74-002, "Evacuation Risks - Evaluation"  
MULLER, R ACRS - Advisory Committee on Reactor Safeguards 79/06/14 1p
- 7907110192 "Evacuation Risks - Evaluation"  
HANG, J. M., BELL, T C Environmental Protection Agency EPA-520/6-74-002, 74/06/30, 165pp
- 7907110274 Forwards transcript of ACRS Subcommittee on TMI-2 790607 meeting in Middletown, PA Pp 193-405, W/o encl  
CORNELL, E K NRC Three Mile Island Task Force 79/06/14 1p
- 7907110275 Requests publication of enclosed FR notice re 790709 meeting of ACRS Ad Hoc Subcommittee on TMI-2 Accident Bulletins & Orders  
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards 79/06/20, 1p
- 7907110284 FR notice re 790709 meeting of ACRS Ad Hoc Subcommittee on TMI-2 Accident Bulletins & Orders in Washington, DC.  
HOYLE, J C ACRS - Advisory Committee on Reactor Safeguards 79/06/20 2pp
- 7907110319 Offers suggestions re methods of avoiding situation similar to TMI event. One-line diagrams, technical data book & keeping informed of actions by other agencies would be helpful.  
BENDER, M ACRS - Advisory Committee on Reactor Safeguards 79/05/02 3pp.
- 7907110292 Forwards notice of 790711 meeting of ACRS Ad Hoc Subcommittee on TMI-2 Accident Implications re Nuclear Power Plant Design Notice to be published 790626.  
CHILK, S J Office of the Secretary of the Commission. 79/06/21, 1p.
- 7907110298 FR notice re 790711 meeting of ACRS Ad Hoc Subcommittee on TMI-2 Accident Implications re Nuclear Power Plant Design in Washington, DC.  
HOYLE, J. C ACRS - Advisory Committee on Reactor Safeguards. 79/06/21, 2pp

7907120589 Responds to NRC request for B&W positions concerning each ACRS recommendation re TMI-2  
TAYLOR, J H Babcock & Wilcox Co 79/07/03 24pp

7907110001 Forwards ACRS records to be placed in congressional TMI reading room in Washington, DC  
FELTON, J M Division of Rules and Records 79/07/06 2pp

7907110049 Notifies of dates of arrival of ACRS members attending TMI-2 Subcommittee meeting in Middletown, PA  
VANDERHOLT, M E ACRS - Advisory Committee on Reactor Safeguards 79/05/31 1p

P Operating license stage documents & correspondence

7907120643 Forwards info re unit instrumentation status  
BEARD, J T Plant Systems Branch 79/04/10 11pp

7907110340 Suggests careful execution of maint program outlined in Diamond Power control rod drive control sys vendor manual Procedures should prevent trip breaker problems  
FAUST, F R Babcock & Wilcox Co 78/06/12 1p

7907260470 "Accident Descriptions for Emergency Response Exercise Scenarios"  
ERICSSON, D M Sandia Laboratories NUREG/CR-0388 78/11/30 115pp

7901170158 Forwards rept "B&W 177 Fuel Assembly Owner's Group Asymmetric LOCA Loads Evaluation Program, Phase 2"  
PARKER, W D Duke Power Co 79/01/11 1p

7907110401 "US NRC Functional Organization Charts"  
\* Office of Management and Program Analysis NUREG-0325 79/01/31 46pp Available at NTIS \$4.50

7907020107 Discusses preliminary sequence of events for TMI incident of 790328  
LONG, R L GPU Service Corp 79/03/28 16pp

7907180072 Describes decay heat removal sys proposed by Westinghouse to back up existing sys Backup sys can be ready in 15 days  
\* Office of Nuclear Reactor Regulation. 79/03/28 5pp

7907260562 Submits graph showing estimated time required to bring water in core to saturation temp of 300, 400 & 1,000 lbs per square inch absolute from present 280 F energy level  
WEIMER, J A ; HARNE, R L Babcock & Wilcox Co. 79/04/01 2pp

7907100631 "Preliminary Test Results, Second Semiscale Relief Valve Venting Test From TMI Conditions"  
\* Affiliation Unknown 79/04/02 13pp

7907160084 Documents results of COBRA IV core thermal hydraulic calculations for post-accident conditions Results indicate cooldown & use of RHR pumps for core cooling is inadvisable  
HOLAHAN, G M Analysis Branch 79/04/02 3pp

7907020439 Discusses environ impact of TMI incident J Behn 790330 telcon advised that collected fish in fish sample at TMI be preserved by freezing so that genetic examination can be conducted Requests plan for monitoring environ info  
BERKSON, H Environmental Specialists Branch 79/04/03 2pp

7907110358 Notifies that literature review has been completed & technical discussions held re flammability limits for hydrogen & oxygen in nuclear reactor vessels Discusses safe flammable & detonable limits  
RIEHL, W A. National Aeronautics & Space Admin 79/04/03 3pp

--7907110382 Notifies of review of potential hydrogen hazards & removal measures in containment room Conditions are safe & in control.  
RIEHL, W A. National Aeronautics & Space Admin 79/04/03 2pp

--7907110411 Submits current plan & contingency plan for transfer of hydrogen from waste gas storage tanks  
RIEHL, W A. National Aeronautics & Space Admin 79/04/03 2pp.

7907120718 Submits info requested in NRC 790403 telecopy re radiological environ qualification of TMI-2 hydrogen recombiners  
MEYER, O W. Energy Systems Group. 79/04/03 2pp

--7907120800 Requests info re radiological environ qualification of TMI-2 hydrogen recombiners.  
IRELAND, R E Division of Systems Safety 79/04/03 2pp.

7907020176 Identifies potential problems at B&W facilities in wake of TMI incident, re transients for high power pressurizer level instrumentation, integrated control sys, release of coolant, lack of hydrogen recombiners & accident analysis  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 3pp

7907110022 Forwards comments re proposed meeting w/B&W to discuss stable cooling mode Present pressurized cooling mode should be maintained as long as possible  
TEDESCO, R L Assistant Director for Reactor Safety 79/04/04 14pp

7907110077 Submits assessment of remaining life of surge capacitors as result of radiation exposure  
KENNEDY, R K General Public Utilities 79/04/04 2pp

7907260564 Submits graph re min core flow & long-term cooling  
MEYER, O A Babcock & Wilcox Co 79/04/04 2pp

7907110139 Notifies of activities as combustion expert at TMI  
RIEHL, W A. National Aeronautics & Space Admin 79/04/05 3pp.

7907110154 Forwards handout used at NRC 790404 briefing re TMI Info includes B&W reactor status summary, IE actions, IE Bulletin 79-05 & establishment of task group  
MATTHEWS, P Division of Systems Safety 79/04/05 12pp

7907160092 Provides potential core melt sequence of events based on TMI conditions on 790404  
MURPHY, J Office of Nuclear Regulatory Research 79/04/05 2pp

7907160094 Data from venting test at Billings Energy Corp, Provo, UT on 790404  
LIEBENTHAL, J L Billings Energy Corp 79/04/05 8p

7907160222 Discusses radiological dose to population since 790328  
Total population dose since 790328 is 2100 man rems as of 790404 Provides dose tabulation  
BARRETT, L Office of Nuclear Reactor Regulation 79/04/05 3pp.

7907180091 Summary of 790405 meeting of Util-Industry Committee on Reactor Core Condition Working Group re pellet conditions in Lynchburg, VA  
THOMAS, G Babcock & Wilcox Co. 79/04/05 5pp

--7907180102 Summary of 790405 meeting of Util Industry Committee on Reactor Core Condition Working Group Zircaloy-water reaction & hydrogen inventory in Lynchburg, VA  
TULENKO, J B Babcock & Wilcox Co 79/04/05 5pp

7907260535 Discusses reliability & uncertainty of thermocouples following loss of feedwater transient Tests simulating transient conditions should be performed to determine temp threshold for gross failure in TMI-2 design detectors  
WILSON, T L Babcock & Wilcox Co 79/04/05 2pp

7907260546 Discusses thermocouple tracking sensitivity Thermocouples track fairly steadily when core condition is in steady state & responds to local changes w/relative accuracy W/related documentation  
WEIMER, J A Babcock & Wilcox Co. 79/04/05 9pp

7907020144 Lists concerns which require reconsideration, including environ qualification envelope, items to be qualified, Reg Guide 1.97 implementation & backfitting Changes in thinking include credibility of core damage.  
HANAUER, B H Assistant Director for Plant Systems 79/04/06, 2pp

7907110185 Forwards resistance temp detector test results, Resistance temp detector on pressurizer can be used to distinguish wet-dry condition  
\* EQ & Q, Inc 79/04/06 20pp

7907190724 FOIA request for communications between TMI personnel & NRC, between various NRC ofcs & for log books of licensing & operating project managers for TMI  
WEISS, E R Sheldon, Harmon & Reisman 79/04/06, 2pp.

7907260541 Elaborates on conclusions of B&W 790405 memo Increase in selected thermocouple readings is no cause for concern  
WILLBE, J T Babcock & Wilcox Co 79/04/06, 5pp.

7907260644 Submits current assessment of core condition based on info available as of 790407.  
DEMARR, R V. Babcock & Wilcox Co. 79/04/07, 5pp.

## DOCKETED ITEMS

- 7907160099 Provides info on RHR leak rates re 10CFR20.App 1  
BARETT,L Division of Site Safety & Environmental Analysis  
79/04/08 2pp
- 7907260566 Discusses findings of B&W 790408 memo re core bypass flow  
for core blocked at top only Core bypass flow for core  
blocked above uppermost intermediate spacer grid will be  
approx 27X  
GRIBBLE,R M Babcock & Wilcox Co. 79/04/08 2pp
- 7907120723 Discusses attempted test of concrete & coatings by TMI-2  
simulation Notes difficulties in efforts to obtain data &  
input expertise Offers to further discuss situation  
FRENZEL,C A Coastal Science Associates 79/04/09 1p
- 7907120734 Submits general outline drawings & cross-sectional details  
of valves & actuators furnished to TMI  
ZAROLIA,B M Henry Pratt Co 79/04/09 2pp
- 7907160102 Forwards "Advisory Rept-TMI Cutdown" re boration &  
criticality aspects of cooldown from points A to C  
DAVIS,D Systematic Evaluation Programs Branch (Pre 790625)  
79/04/09 5pp
- 7907260568 Discusses discrepancy between thermocouples & outlet  
resistance temp detector temp measurements Graph encl  
WILSON,T L Babcock & Wilcox Co 79/04/09 6pp
- 7907260674 Discusses addl info which confirms conclusions re core  
pressure drop for natural circulation calculation Graphs  
encl  
BARTLELL,B S Babcock & Wilcox Co 79/04/09 9pp
- 7907260685 Submits estimate of loose core debris vol W/graphs &  
charts  
Babcock & Wilcox Co 79/04/09 6pp
- 7907020127 Forwards Westinghouse statement indicating special  
instructions may need to be manually initiated for TMI type  
of events due to uncertain level indication in pressurizer  
TEDESCO,R L Division of Systems Safety 79/04/10 1p
- 7907020130 Submits 790407 telephone notification made to all  
Westinghouse operating plant customers having coincident  
pressure & pressurizer level safety injection initiation.  
ANDERSON,T M Westinghouse Electric Corp 79/04/10 2pp
- 7907060136 FOIA request for documents relating to TMI  
RUBY,R The Sun Baltimore,MD 79/04/10 1p
- 7907110197 Discusses background of boiler operation pressurizer level  
problems  
JASKE,R Office of State Programs 79/04/10 2pp
- 7907110218 Forwards diagnostic data taken during 790406 pump switch  
ACKERMANN,N J Electric, Instrumentation & Control Systems  
Branch 79/04/10 3pp
- 7907120642 Describes work needed to evaluate adequacy of Util list of  
instruments needed to bring unit to cold shutdown Notes  
telcon request to postpone action until notified  
BEARD,J T Plant Systems Branch. 79/04/10 1p
- 7907160078 Forwards "Advisory Rept.Reactor Sys Cutdown,TMI-2 "  
DAVIS,D Systematic Evaluation Programs Branch (Pre 790625)  
79/04/10 29pp
- 7907200246 Supplements 790416 FOIA request Requests copies of actual  
tests w/answers & test scores  
SCHAKNE,R CBS News, CBS, Inc 79/04/10 1p.
- 7907260530 Discusses criteria to be used during establishment of  
natural circulation.W/core decay heat vs time charts &  
other related info  
LDSH,L L, BURROW,J F Babcock & Wilcox Co. 79/04/10 8pp
- 7907260551 Submits graphs re core flow requirements.Uncertainties  
included in core flow requirements have been re-evaluated  
based on uncertainties provided in B&W 790409 memo.  
JACKSON,A B Babcock & Wilcox Co 79/04/10 7pp
- 7907260556 Discusses relative advantages of cooling at up to 1,800 &  
down to 13 lbs per square inch absolute  
GLOUDEMANS,J R Babcock & Wilcox Co 79/04/10. 3pp
- 7907260558 Submits graphs showing adiabatic heatup rate as function of  
time in days after loss of feedwater event Curve assumes  
instantaneous core uncoverage  
JONES,J H Babcock & Wilcox Co 79/04/10 4pp
- 7907260560 Discusses increased thermocouple readings due to proximity  
of fuel particulates W/graphs  
HENNINGSON,P J Babcock & Wilcox Co 79/04/10 4pp
- 7907260565 Discusses core flow distribution for one & two pump  
operation W/charts  
HIATT,R M Babcock & Wilcox Co 79/04/10 8pp
- 7907260567 Discusses incore thermocouple error evaluation Results  
indicate average + 7.94 F error at 98% & A + 5.59 F error at  
16% power,which extrapolates to A + 5.16 F error at 1%  
power  
WEIMER,J A Babcock & Wilcox Co 79/04/10 3pp
- 7907260570 Discusses development of method for analyzing local coolant  
conditions for TMI-2 during selected times of accident &  
determination of local cooling capability for blocked core  
under natural circulation  
HIATT,R M Babcock & Wilcox Co 79/04/10 3pp
- P Operating license stage documents & correspondence
- 7907260572 Discusses attempt to provide reliable explanation for  
TMI-2 through use of modeling techniques  
HENNINGSON,P J Babcock & Wilcox Co 79/04/10 4pp
- 7906200415 Provides info re activities while at TMI-2,for 790330-0440S  
Very impressed w/conduct of health physics supervisor under  
existing conditions  
JENKINS,O R Region 2, Atlanta, Fuel Facility & Materials Safety  
Branch 79/04/12 2pp
- 7907190146 FOIA request for all info re 790328 incident at TMI  
OSTI,A P Pfizer, Inc. 79/04/12 1p.
- 7904270228 Forwards tabular presentation of results of analysis for  
primary coolant sample including Bettis analysis  
MIRAGLIA,F J Office of Nuclear Reactor Regulation 79/04/13 2pp
- 7904270414 Forwards info re storage of liquid radwaste in tankcars &  
response to request of R Vollmer re transuranic  
concentrations in coolant  
MIRAGLIA,F J Program Support Branch 79/04/13 10pp
- 7907100168 Notifies of other NRC investigations,IE fact finding will  
develop description of TMI events Ofc of Std Development  
reviewing Reg Guides for necessary changes  
FITZGERALD,J A. Office of the General Counsel 79/04/13. 2pp
- 7907110306 Forwards rept on penetration availability Rept presents  
summary of NRC effort in evaluating ability to monitor  
reactor pressure & level  
MIRAGLIA,F J Office of Nuclear Reactor Regulation 79/04/13 6pp
- 7907120150 Summary of 790412 meeting w/representatives of B&W,ANL,GE,  
Westinghouse & C-E re condition of core  
JOHNSTON,W V Office of Nuclear Reactor Regulation 79/04/13 4pp
- 7907120732 List of electrical instrumentation & control schematics  
needed by headquarters  
LAINAS,O C Plant Systems Branch 79/04/13 4pp
- 7907160118 Recommends all incore thermocouple readings be read in  
continuous manner w/provisions for rapid retrieval &  
permanent storage  
MEYER,R O Core Performance Branch. 79/04/13 1p
- 7907180765 FOIA request for copies of all daily release data for  
gaseous & liquid radioactive isotopes for TMI & all  
confirmatory measurement program results for licensees.  
LITTLEJOHN,J.D. Affiliation Unknown. 79/04/13 2pp.
- 7907020152 Outlines tasks necessitated by TMI incident,Includes example  
of more detailed task description.  
BUNCH,D. Office of Nuclear Reactor Regulation. 79/04/16. 3pp.
- 7907020434 Suggests personnel directly involved w/TMI incident contact  
Coastal Science Associates & provide requested info re  
changing structure of concrete as result of incident Coastal  
Science Associates 790409 ltr to R Livingstone encl.  
HOFHAYER,C Assistant Director for Systems Engineering. 79/04/16.  
2pp



7907160098 Tabulates Met Ed & contractor doses to 790416 Total accumulated for all badged personnel between 790401-16 is 60 015  
SLBDDIEN, H J Region 1, Philadelphia, Office of the Director 79/04/16 1p

7907020148 Lists review consideration for plants hearing OL decision data including operator licensing, administrative controls, QA, initial test programs & technical qualifications  
SKOVHOLT, D Quality Assurance Branch 79/04/17 2pp

7907050023 Requests NRC repts re cause of recent TMI incident if info withheld, requests specific exemptions & appeal procedures  
HATLING, J Affiliation Unknown 79/04/17 1p

7904270421 Advises that compilation of analyses of 790322 & 0410 primary coolant samples were sent to R Mattson at site  
Forwards text revision of compilation & unchanged table  
MIRAQLIA, F J Office of Nuclear Reactor Regulation 79/04/18 5pp

7905020115 Forwards requested info re calculation of radiation dose rates due to piping in sys filled w/diluted secondary water  
MIRAQLIA, F J Technical & Administrative Support Branch 79/04/18 3pp

7905030130 Forwards info requested on 790404 re radiological consequences of placing steam generator B in operation in steaming mode  
MIRAQLIA, F J Technical & Administrative Support Branch 79/04/18 4pp.

7907100026 Forwards list of pros & cons re opening of valve DHR-DHR6 to obtain containment water level readings  
AYCQCK, M Office of Nuclear Reactor Regulation 79/04/18 2pp

7907100038 Forwards calculations of radiation dose rates resulting from piping in sys filled w/diluted secondary water, per E Adensam  
790414 request  
MIRAQLIA, F J Office of Nuclear Reactor Regulation 79/04/18 3pp

7905070092 Forwards evaluation of alternate cooling sys for steam generators  
AYCQCK, M Office of Nuclear Reactor Regulation 79/04/19 17pp

7907020158 "TMI-2 Groundwater Study"  
NICHOLSON, T Site Safety Standards Branch 79/04/19 23pp

7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation Pressurizer level info request list encl  
BHEHANSKI, P Division of Project Management 79/04/19 2pp

7907100031 Forwards general comments & questions on alternate cooling sys, prepared by NRC  
AYCQCK, M Office of Nuclear Reactor Regulation 79/04/19 20pp

7905040159 Forwards memo describing NRC actions resulting from TMI-2 incident Requests review for accuracy & info on budget needs Comments sought by 790425  
QBSICK, L V Office of the Executive Director for Operations 79/04/20, 1p

---7905040162 Describes NRC actions taken since TMI-2 incident  
Categorizes actions into site support, investigative, NRC response improvement, technical & miscellaneous activities  
QBSICK, L V Office of the Executive Director for Operations 79/04/20, 12pp.

7907020155 Submits estimated low level trajectories originating from Middletown, PA for period 790328-0404  
TELEGADAS, K Commerce, Dept of National Oceanographic & Atmospheric Administration 79/04/23 33pp

7907120710 Confirms arrangements to transport three charcoal filters from Harrisburg, PA to Columbus, OH via PA Air Natl Guard.  
QBSICK, L V Office of the Executive Director for Operations. 79/04/23, 1p.

7907250449 Forwards FOIA request from J Danielson, American Friends Svc Committee.  
MITKUS, R J Environmental Protection Agency. 79/04/23, 1p

---7907250458 FOIA request for daily briefing papers & repts re emission data on particulate matter & gamma radiation at TMI for 790328-29  
DANIELSON, J American Friends Service Committee. 79/04/06, 1p

7907050406 Provides notes & comments re effects of TMI incident on local population Discusses study of incident info partially withheld home phone numbers (ref FOIA Exemption 6)  
QOLDSMITH, R Office of Standards Development 79/04/24 16pp

7907100281 Forwards info re dose rate at top of containment dome, per Q Chipman request  
MIRAQLIA, F J Office of Nuclear Reactor Regulation 79/04/28 3pp

7907190112 FOIA request for records & documents relating to TMI meetings between util representatives & NRC  
KRANISH, A Trends Publishing, Inc 79/04/24 1p

7906200428 Provides info re activities while at TMI-2, for 790330-0411  
Critical of duplication of effort between IE & Ofc of Nuclear Reactor Regulation  
DYER, J A Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/26 2pp

7907190259 FOIA request for documents transmitted to NSC re nuclear reactor incident at TMI  
WEISS, E R Sheldon, Harman & Roisman 79/04/26 1p

7905230310 Forwards listing of ongoing & planned NRC actions re TMI incident  
QBSICK, L V Office of the Executive Director for Operations 79/04/27 20pp

7907090430 Forwards procedure for badging of NRC personnel  
SMITH, Q H Region 1, Philadelphia, Office of the Director 79/04/28, 4pp

7907100045 Forwards summaries & plots of thermocouple temp & time at time of reactor core performance 2A trip info covers period from 49 minutes before to 170 minutes after 2A trip  
WEIBER, J L General Public Utilities 79/04/28 54pp

7907110390 "Improving Regulatory Effectiveness in Federal/State Siting Actions State Regulatory Activity Involved in Need for Power," prepared by Cox, Langford & Brown  
NASSIKAS, T N Office of State Programs NUREG-0197 79/04/30 58pp Available at NTIS \$4.50

7907050030 FOIA request for info re dosimeter readings taken at sampling sites in vicinity of TMI from 790325 to present  
WOLFSON, J L Washington Univ 79/05/01 1p

7905230296 Discusses TMI-2 startup range counts from D(gamma, n) reactions in downcomer region rather than from normal source multiplication in core  
RICHINOS, H Core Performance Branch 79/05/02 2pp

7906200393 Provides info re activities while at TMI-2, for 790412-27  
Procedures & calculations should be examined before using sample results for health physics activities  
BROWN, R A Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/03 1p

7907260483 Responds to requests re status of hydrogen instrumentation for typical OL applications W/tables & illustrating data  
BUTLER, W R Containment Systems Branch 79/05/03, 5pp

7907190097 FOIA request for documents & other records produced by IE re TMI accident  
WEISS, E R Sheldon, Harman & Roisman 79/05/04 4pp.

7907190125 FOIA request for all info re TMI accident  
ELKINS, B T Affiliation Unknown 79/05/08, 1p.

7906290383 Provides summary of activities while assigned to TMI-2 site.  
RUHLMAN, W A Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/09, 1p

7907020137 FOIA request for transcripts of interviews w/util personnel on 7906328-31  
TAYLOR, R E The Evening & Sunday Bulletin, Philadelphia, PA 79/05/09 1p.

7907090458 Forwards rept of Subcommittee on Long-Term Effects of TMI, presented on 790310 by D Okrent, ACRB W/o encl.  
MCRELESS, T O ACRB - Advisory Committee on Reactor Safeguards 79/05/10 2pp

7906250325 Forwards Amends 38 & 43 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability.  
SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/11, 2pp

## DOCKETED ITEMS

- 7906250326 Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively, requiring actuation of safety injection, revising opening logic for pressurizer power operated relief valves & modifying power supplies  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625)  
79/05/11 14pp
- 7906250327 Safety evaluation supporting Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625)  
79/05/11 5pp
- 7906250328 Notice of issuance & availability of Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625)  
79/05/11 2pp
- 7907090456 Summary of 790510 meeting w/NRC Commissioners re TMI activities Forwards summary of NRC mgt activities re TMI  
BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/05/11 6pp
- 7906290389 Provides requested summary of activities while assigned to TMI-2 site  
MONTGOMERY, D M Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/14 1p
- 7907200243 Renews FOIA request for identities of operators at TMI & specifically for test scores of C Faust, E Frederick, K Bryan & BQ Smith  
SCHAYNE, R CBS News, CBS, Inc 79/05/14 1p
- 7906290386 Provides summary of activities while assigned to TMI-2 site  
Comments on licenses & NRC operations  
PEERY, W W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/15 2pp
- 7906290401 Provides summary of activities while assigned to TMI-2 site  
Comments on licenses & NRC operations  
MILLSAP, W J Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/15 2pp
- 7906290406 Provides summary of activities while assigned to TMI-2 site  
Comments on NRC operations  
JAPE, F Region 2, Atlanta, Office of the Director 79/05/16 2pp
- 7906220115 Responds to request to arrange Nuclear Reactor Regulation participation in briefing of foreign govt visitors on TMI-2 incident Lists pertinent agenda items  
HELYMES, C J Standardization Branch 79/05/17 2pp
- 7907090455 Notifies that special press facilities will not be necessary for Harrisburg, PA 790606-07 subcommittee meeting  
MULLER, R ACRS - Advisory Committee on Reactor Safeguards 79/05/18 1p
- 7906200512 Submits item for possible use in daily rept re death of livestock on farm near TMI-2 NRC is investigating  
MCQUAGHY, R W Region 1, Philadelphia, Office of the Director 79/05/21 1p
- 7907260053 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp
- 7907030135 Responds to 790430 ltr re improving design of pressurized water reactors  
MATTSON, R J Division of Systems Safety 79/05/25 1p
- 7907030137 Forwards 790430 ltr from WP Brown for reply  
REINHUTH, C W Division of Reactor Construction Inspection 79/05/21 1p
- 7907030141 Suggests mode for design improvement of PWRs  
BROWN, W P Affiliation Unknown 79/04/30 5pp
- 7907100165 Summary of meeting w/Presidential Commission re hearings All testimony will be under oath Witnesses will be given more advance notice & can be questioned on any topic re TMI  
FITZGERALD, J A Office of the General Counsel 79/05/29 2pp
- 7907200218 Supplements FOIA 790514 request Requests test score info score info for addl TMI operators & senior operators B Zewe, F Scheinmann & Q Miller  
SCHAKNE, R CBS News, CBS, Inc 79/05/29 1p
- 7907060025 Ack receipt of 790514 ltr requesting info on TMI incident Forwards NUREG-0557, NUREG-0560 & Interim Sequence of Operating Events w/o encl  
MATTSON, R J Division of Systems Safety 79/05/30 1p
- 7907060026 Requests info re accident at TMI  
CHIRASANTA, K Thailand 79/05/14 3pp
- 7907090465 Forwards monthly rept for Apr 1979 prepared by Ichthyological Assoc. Inc. re nonradiological aquatic & water quality for Susquehanna River  
HICKEY, C R Environmental Specialists Branch 79/05/30 2pp
- 7907090469 Aquatic study monthly rept for Apr 1979  
NARDACCI, G A Ichthyological Associates, Inc 79/04/30 21pp
- 7907100154 Notifies that transcripts of President's Commission hearings can be purchased from Daily Verbatim Reporters  
FITZGERALD, J A Office of the General Counsel 79/05/30 1p
- 7907100270 Forwards visual aids for meeting re licensee performance & Commission 79/05/30 22pp
- 7907100277 Notifies that AR Power & Light Co has performed immediate actions re NRC 790517 order Operating restrictions may be removed  
DENTON, H R Office of Nuclear Reactor Regulation, 79/05/30, 1p
- 7907100288 Draft ltr notifying of satisfactory completion of immediate actions required by NRC 790517 order Operating restrictions may be removed Modified Tech Specs must be submitted.  
DENTON, H R Office of Nuclear Reactor Regulation, 79/05/30 4pp
- 7907100292 Draft SER AR Power & Light Co has performed immediate actions required by NRC 790517 order  
\* Office of Nuclear Reactor Regulation 79/05/30 14pp
- 7907100304 Draft notice announcing that AR Power & Light Co has satisfactorily completed actions required by NRC 790517 order Operating restrictions may be removed  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/30 2pp
- 7907090472 Forwards staff actions re TMI incident, including summary listing of resources for individual tasks & listing sorting tasks by ofc  
GOSBICK, L V Office of the Executive Director for Operations 79/05/31 38pp
- 790710258 Summary of meeting w/B&W, C-E & Westinghouse in Bethesda, MD re Lessons Learned Task Force on TMI-2  
MATTSON, R J Division of Systems Safety 79/05/31 9pp.
- 7907190325 Summary of 790521 meeting w/Exxon re role in TMI-related reevaluations of operating plants  
KANE, W F Standardization Branch, 79/05/31 4pp
- 7907020420 Forwards EPA Region 3 790515 ltr to Met Ed re disposal of radioactive water accumulated during TMI-2 incident w/o encl  
HICKEY, C R Division of Site Safety & Environmental Analysis 79/06/01 3pp
- 7907130190 Forwards DL amends, orders & ltrs in effect on 790328 & documents tracing evolution of license from issuance of license on 780208.  
DEVOUNG, R C Division of Site Safety & Environmental Analysis, 79/06/01 1p
- 7907130284 Requests that two copies of TMI-2 incident data collected to date be sent to NRC w/updated indexes sent every two weeks.  
LONG, R L GPU Service Corp 79/06/01, 1p
- 7907160204 Forwards "Unexpected I-131 in English Sheep" by L Van Middlesworth, dtd 790515 Rept contains findings re TMI incident  
REED, P R Environmental Effects Research Branch 79/06/04 2pp
- 7907160208 "Unexpected I-131 in English Sheep."  
VANMIDDLESWORTH Tennessee, Univ. of 79/05/15 6pp.
- 7907160214 Summarizes 790514 telcon w/L Van Middlesworth on recent research results re I-131 levels in cow, sheep & human thyroids & relation of results to TMI incident.  
REED, P R Environmental Effects Research Branch 79/06/04, 3pp

7907160219 Describes status of radioiodine air sampler at TMI as of 790518 One sampler is currently in use  
REED, P R Environmental Effects Research Branch 79/06/04 1p

7907110101 Summary of 790524 hearing of House Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. oversight hearings re TMI  
ALDERMAN, H ACRB - Advisory Committee on Reactor Safeguards 79/06/05 2pp

7907160316 Expresses pleasure for meeting w/PF Gustafson & IL Ad Hoc Committee Will be placed on mailing list re TMI documents  
HENDRIE, J. M Commission 79/06/05 1p

--7907160325 Forwards IL Commission on Atomic Energy 790529 list of questions & topics re nuclear safety under consideration by Ad Hoc Committee on Nuclear Reactor Safety Review  
GUSTAFSON, P F Illinois, State of 79/05/30 3pp

7907050040 FOIA request for all info re radioactive releases into Susquehanna River as result of TMI incident  
THURSH, J. E Affiliation Unknown 79/06/06 1p

7907130269 Discusses role of reactor operators & technical qualifications included in J Olshinski 790605 memo re need of qualified safety monitor  
KRUG, H E TMI-2 Lessons Learned Task Force 79/06/06 2pp

7907130402 Forwards memo re scope of NRC TMI-2 investigation, professional staff assignments for NRC investigation & draft NRC policy statement by L Bickwit  
CORNELL, E K NRC Three Mile Island Task Force 79/06/06 1p

--7907130405 Draft memo re scope of NRC TMI-2 investigation  
ORNSTEIN, H NRC Three Mile Island Task Force 79/05/21 3pp

--7907130414 Lists task force assignments for NRC TMI-2 investigation  
CORNELL, E K, DEYOUNG, R NRC Three Mile Island Task Force 79/06/01 2pp

7907250429 FOIA request for reg guides re reactor safety: "Statutory Rept to Congress on Abnormal Occurrences," transcript of NRC investigation of TMI incident & any relevant addl info re incident  
FILCOCK, N. I Waters, McPherson, Hudzin & McNeill 79/06/06 2pp

7907060131 Responds to FOIA request for documents & communications re TMI. Forwards "Title List - Publicly Available Documents - TMI Unit 2 - Docket 50-320" & printout w/o encl.  
FELTON, J. M Division of Rules and Records 79/06/07 1p

7907130243 Ack receipt of suggestions concerning improvement of conditions at TMI-2.  
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/06/07 5pp

7907160194 Describes contact w/R Ritmann re H2 & O2 generation in TMI vessel & w/J Proctor on effect of H2 explosion on vessel integrity  
LEVINE, S. Office of Nuclear Regulatory Research 79/06/07 1p.

7907120492 Forwards IE 790531 memo soliciting questions & topics for IE investigation of TMI-2 incident.  
SCROOGINS, R. M Administrative and Resource Control Staff. 79/06/08 1p

--7907120698 Forwards 790420 memo describing IE TMI investigation & requests questions & info needs within its scope which should be pursued.  
DAVIS, J. Q Office of Inspection & Enforcement. 79/05/31 2pp

7907030057 Responds to 790522 request for NRC plan for response to TMI-type emergency & summary of NRC actions re TMI incident. w/o encl  
QOBSICK, L. V NRC Three Mile Island Task Force 79/06/11 2pp

7907120743 Submits rept of activities, observations & opinions re TMI-2 accident. Rept to President's Commission encl  
BRODSKY, A. Occupational Health Standards Branch. 79/06/11 7pp.

7907130261 Notifies that ABT Associates, Inc proposal, "Theories of Action at TMI," does not meet criteria outlined in HE Coleman 790611 memo Funding should be rejected  
CORNELL, E. K. NRC Three Mile Island Task Force 79/06/12 1p

7907130303 Summary of 790604 TMI-2 Task Force meeting in Washington, DC to discuss present & future role of Div of Reactor Research in wake of incident  
MATTBON, R. J Division of Systems Safety. 79/06/12 6pp.

7907020216 Notifies that interim requests for TMI-2 data should be made on encl Data Request Form  
OLSHINSKI, J. A TMI-2 Lessons Learned Task Force 79/06/13 2pp

7907160345 Forwards chronological summary of significant precursor events re TMI-2 incident  
HEBDON, F NRC Three Mile Island Task Force 79/06/13 6pp

7907100057 Notifies of lesson learned from TMI event NRC action updated FSAR should be implemented as soon as possible  
GRIMES, B. K Assistant Director for Engineers & Projects (Pre 790625) 79/06/14 1p

7907100051 Forwards info re monitoring for radioiodine releases under emergency conditions & lack of readout capability by util, prepared by Lessons Learned Task Force  
MATIN, J. A Accident Analysis Branch 79/06/15 2pp

7907020163 Summary of 790615 meeting w/DOE in Germantown, MD re DOE involvement in TMI-2 accident response  
LYNCH, D. D NRC Three Mile Island Task Force 79/06/18 2pp

7907020064 Requests IE participation at 790625 meeting w/full TMI-2 Lessons Learned Task Force to discuss possible coordination & encl draft paper on NRC incident response program  
MATTBON, R. J TMI-2 Lessons Learned Task Force 79/06/19 6pp

7907160335 Discusses R Pollack 790619 request for list of personnel detailed to TMI special inquiry. JG Davis 790420 memo & NRC Press Release 79-104 announcing special inquiry director  
CORNELL, E. K NRC Three Mile Island Task Force 79/06/19 5pp

7907160348 Requests cooperation & designation of liaison re special inquiry into TMI-2 event  
CORNELL, E. K NRC Three Mile Island Task Force 79/06/19 1p

7907020136 Responds to 790509 request for transcripts of interviews w/ util personnel on 790328-31 Transcripts are available in NRC FDR  
FELTON, J. M Division of Rules and Records 79/06/21 1p

7907090435 Forwards request from Shizuoka Public Health Lab of Japan for info re TMI incident  
LEVINE, S. Office of Nuclear Regulatory Research 79/06/21 1p

--7907090437 Request by Shizuoka Public Health Lab for info re TMI incident  
ISHIHATA, T Japan 79/06/21 2pp

7907020185 IE Info Notice 79-16; "Nuclear Incident at TMI"  
\* Office of Inspection & Enforcement 79/06/22 1p

7907160176 Responds to 790502 ltr proposing cooperation between agencies at TMI NRC will participate if EPA schedules & conducts periodic briefing sessions for involved organizations  
HENDRIE, J. M. Commission 79/06/26 1p

--7907160182 Discusses importance of cooperation of agencies to collect environ radiation data. Proposes weekly briefing in Harrisburg, PA where each agency would rept environ findings & hear rept on reactors.  
COSTLE, D. M. Environmental Protection Agency. 79/05/02 2pp.

7907100123 Forwards requested rept "NRC Incident Response," Draft 2, dtd 790723  
GRIMES, B. K Assistant Director for Engineers & Projects (Pre 790625) 79/06/27 44pp.

7907100148 Notifies that briefing on Lessons Learned status rept was held on 790625. Task force made recommendations for short term pending OL & CP that are near conclusions  
CHILK, S. J Office of the Secretary of the Commission 79/06/27 1p.

7907050019 Responds to 790417 FOIA request for info re cause of TMI incident. Forwards printout & list of available documents pertinent to request.  
FELTON, J. M. Division of Rules and Records 79/06/28 1p.

7907050027 Responds to 790501 FOIA request for info re radiation dosage rates at TMI Forwards "Title List - Publicly Available Documents - TMI Unit 2 - Docket 50-320" & printouts identifying records pertinent to request  
FELTON, J. M Division of Rules and Records 79/06/28 1p.

## DOCKETED ITEMS

- 7907050035 Responds to 790606 FOIA request for info re radioactive releases into Susquehanna River as result of TMI incident. Forwards printouts & list of available documents pertinent to request.  
FELTON, J. M. Division of Rules and Records. 79/06/28 1p
- 7907050045 Responds to 790415 FOIA request re public statements & testimony by NRC officials & transcripts relating to NRC response to TMI incident. Forwards list of documents available in PDR.  
FELTON, J. M. Division of Rules and Records. 79/06/28 1p
- 7907050379 Submits short-term mods/actions to be taken prior to startup Recertification of TMI-1 operators requested from NRC. Long-term mods & accomplishment of add'l items will be undertaken. Description of mods encl.  
HERBEIN, J. O. Metropolitan Edison Co. 79/06/28 5pp
- 7907120737 Submits rept on penetration availability for monitoring reactor pressure & level w/instruments outside containment.  
MIRAGLIA, F. J. NRC Three Mile Island Task Force. 79/06/28. 7pp
- 7907190260 Recommends relative reliability evaluation of B&W plant auxiliary feedwater sys. Requests notification of intention to adopt recommendation.  
MATTSON, R. J. Division of Systems Safety. 79/06/28 1p
- 7907230324 Summary of 790621 meeting w/util in Bethesda, MD re emergency feedwater sys reliability.  
CAPRA, R. A. Division of Project Management. 79/06/28 7pp
- 79060321 Responds to 790331 request. Submits schedule for completion of long-term mods to feedwater sys described in Section II of 790517 order.  
HIMBLE, D. C. Arkansas Power & Light Co. 79/06/29 2pp
- 79070784 Responds to 790413 request for daily release data for all gaseous & liquid radioactive isotopes for TMI. Forwards Title List, Publicly Available Documents, TMI-2, Docket 50-320 & printout indicating relevant documents. W/o encl.  
FELTON, J. M. Division of Rules and Records. 79/06/29 1p
- 7907190249 Responds to FOIA request for safety insps made just prior to 790328. Forwards IE Insp Repts 50-289/79-08 & 50-320/79-07 W/o encl.  
FELTON, J. M. Division of Rules and Records. 79/06/29. 12pp
- 7907250438 Responds to 790406 FOIA request for emission data on particulate matter & gamma radiation at TMI for 790328-29. Forwards "Title List, Publicly Available Documents, TMI-2, Docket 50-320" & printouts indicating relevant documents.  
FELTON, J. M. Division of Rules and Records. 79/06/29 1p
- 79060469 Forwards benchmark calculations B&W computer model for benchmarking has several deficiencies. All calculations point to leakage in addition to that through stuck power operated relief valve. Add'l benchmark analysis is necessary.  
HILLIPS, L. Analysis Branch. 79/06/29 15pp
- 79090291 Describes evolution of TMI-2 OL.  
FELTON, J. M. Office of Nuclear Reactor Regulation. 79/07/02 7pp.
- 79090304 Proposes plans re containment entry & subsequent cleanup suggests observation of containment debris, insulation matls, containment liner, water level on floor & paint peeling.  
HENSE, R. P. Assistant Director for Reactor Safety. 79/07/02. 1p
- 7907190107 Responds to 790424 request for records re TMI meetings between util & NRC. Forwards "Title List, Publicly Available Documents, TMI-2, Docket 50-320" & printouts indicating relevant documents. W/o encl.  
FELTON, J. M. Division of Rules and Records. 79/07/03 1p
- 7907190115 Responds to 790308 request for all info re TMI accident. Forwards "Title List, Publicly Available Documents, TMI-2, Docket 50-320" & printouts identifying records subj to request & available in PDR. W/o encl.  
FELTON, J. M. Division of Rules and Records. 79/07/03 1p
- 7907190141 Responds to 790412 request for all info re TMI incident. Forwards "Title List, Publicly Available Documents, TMI-2, Docket 50-320" & printouts identifying records subj to request & available in PDR. W/o encl.  
FELTON, J. M. Division of Rules and Records. 79/07/03 1p
- 7907300464 Forwards TMI Run 106, analysis of first 2,550-s of transient. Calculations to be continued after reactor coolant pumps tripped off & heatup phase of accident started.  
BEHLING, B. R. EG & O, Inc. 79/07/03 7pp
- 7907230170 Forwards 790425 memo re production of hydrogen & oxygen in RCS after accident at TMI-2.  
HENDRIE, J. M. Commission. 79/07/05 1p
- 7907230174 Discusses results of analyses & evaluations performed by Containment Sys Branch for several containment-related issues in support of incident response team. Primary concern potential sources & rates of hydrogen & oxygen production.  
BUTLER, W. R. Containment Systems Branch. 79/04/25 39pp
- 7907190669 Responds to FOIA 790404 request for documents & communications re TMI. Forwards "Title List, Publicly Available Documents, TMI-2, Docket 50-320" & printout of records subj to request. W/o encl.  
FELTON, J. M. Division of Rules and Records. 79/07/06 1p
- 7907190731 Responds to FOIA request for communications between TMI personnel & NRC, between various NRC ofcs & for log books of licensing & operating project managers for TMI.  
FELTON, J. M. Division of Rules and Records. 79/07/06 2pp
- 7907190803 Responds to FOIA request for NRC Annual Rept 1978, recent NRC studies of TMI rept indicating methods to cool down TMI core & environ impact studies of Indian Point Facility & Brookhaven Nat'l Lab. Forwards 1978 NRC Annual Rept, W/o encl.  
FELTON, J. M. Division of Rules and Records. 79/07/06 1p
- 7907190264 Responds to FOIA request for documents transmitted to NSC re TMI incident. None located.  
FELTON, J. M. Division of Rules and Records. 79/07/10 1p
- 7907200226 Supplements 790424 response to FOIA request for test scores of reactor operators licensed for TMI. Request of 790410 sought inclusion of exam questions & responses. Records placed in PDR. Names withheld (ref FOIA Exemption 6).  
FELTON, J. M. Division of Rules and Records. 79/07/11 2pp
- 7907260700 Forwards 790522 ltr summarizing work done re contingency planning of TMI-2 using MARCH & CORRAL codes.  
MATTSON, R. J. Division of Systems Safety. 79/07/11 1p
- 7907260711 Forwards "MARCH/CORRAL Analysis of Hypothetical Meltdown Scenarios for Contingency Planning." Performed on quick response basis for NRC re TMI accident.  
DENNING, R. S. Battelle Memorial Institute, Columbus Laboratories. 79/05/22 1p
- 7907260716 "MARCH/CORRAL Analysis of Hypothetical Meltdown Scenarios for Contingency Planning."  
WOODSON, R. O., KURTH, R. E., CYBULSKI, P. Battelle Memorial Institute, Columbus Laboratories. 79/05/22 7pp
- 7907260721 Requests Battelle memo dtd between 790328-0427 re steam explosion potential in event of core or fuel meltdown during TMI-2 accident.  
WEBB, R. E. Affiliation Unknown. 79/06/12 1p
- 7907300377 Responds to 790627 request. Forwards preliminary evaluation of 790306 turbine overspeed trip Sys behavior is predictable up to 5.5 minutes into event.  
SHERON, B. W. Analysis Branch. 79/07/11. 5pp.
- 7907250448 Responds to 790606 FOIA request for reg guides, NRC abnormal occurrence rept to Congress re TMI, transcripts of proceeding & other records. Forwards reg guides. Rept to Congress not finalized. Forwards printout lists of disclosed TMI info.  
FELTON, J. M. Division of Rules and Records. 79/07/13 2pp
- 7907100107 Diagrams of parts of TMI electrical sys, including condensate booster pump, reactor coolant & control switch development.  
REBBAPAGODA, R. Jersey Central Power & Light Co. 79/07/14. 5pp
- 7907230626 Forwards third interim rept re TMI-2 incident on 790328.  
HERBEIN, J. O. Metropolitan Edison Co. 79/07/16. 1p
- 7907230633 Third interim rept on TMI-2 incident, w/expanded version of sequence of events submitted 790515.  
\* Metropolitan Edison Co. 79/07/16 204pp.
- 7907310064 Forwards NUREG-057B, "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations." Recommends immediate implementation through issuance of licensing position.  
MATTSON, R. J. TMI-2 Lessons Learned Task Force. 79/07/18. 3pp
- 7907310071 "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations."  
\* TMI-2 Lessons Learned Task Force. NUREG-057B. 79/07/31. 98pp.

7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
OEISSLER, G D, Babcock & Wilcox Co 79/07/20 2pp

7907270269 Forwards "Preliminary Annotated Sequence of Events, 790329-0430" for TMI-2 incident.  
HERBEIN, J G Metropolitan Edison Co 79/07/20 1p

--7907270275 "Preliminary 19nonated Sequence of Events, 790329-0430" for TMI-2 incident  
\* Metropolitan Edison Co 79/07/20 9pp

7907280442 Submits comments on environ qualification, instrumentation to monitor course of accident & emergency response NRC should evaluate ability to predict conditions inside containment  
SCHOLL, R F Electric, Instrumentation & Control Systems Branch 79/07/25 9pp

--7907280449 Requests that NRC consider instituting network of teletype facilities between each plant & regional NRC ofc  
LASHER, D R Electric, Instrumentation & Control Systems Branch 79/08/01 1p

--7907280453 Submits page from IAEA Safety Guide DB re Class 2E principles & requirements  
HANAUER, B H, Assistant Director for Plant Systems 79/04/10 2pp

--7907280458 Summarizes IAEA 790122-0202 meetings in London & Vienna to complete review of Technical Review Committee comments on Safety Guide DB & prepare revision to DB  
WENZINGER, E C Plant Systems Branch, 79/04/04 7pp

--7907280466 Discusses "organ pipe" method for monitoring of pressure vessel water level  
ROSENTHAL, J E Plant Systems Branch 79/08/02 1p

#### G Inspection reports, IE Bulletins & correspondence

7907020337 IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI " Draft Transmittal ltrs encl  
\* Office of Inspection & Enforcement 79/04/11 10pp

7907120746 "Form NRC-766 Statistical Data Audit Rept, Apr 1973-May 1979 "  
\* Office of I&E, Executive Officer for Management & Analysis 79/04/11 300pp

7907020279 Summary of 790411 meeting w/Westinghouse in Bethesda, MD to discuss corrective actions for Westinghouse NBSB plants, as result of TMI incident Forwards IE Bulletin 79-05A  
ROBS, D F Division of Project Management, 79/04/12 6pp.

7904270123 Forwards IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident" & draft ltrs to licensees  
MOSELEY, N C Division of Reactor Operations Inspections 79/04/14 4pp.

7906290493 Responds to IE Bulletin 79-08 Forwards info re review of TMI incident Existing line isolation not important to ECCS injection  
REED, C Commonwealth Edison Co 79/04/27 22pp.

7907190237 FOIA request for records of two preincident federal safety insps & findings after incident  
REINEMA, R M, Affiliation Unknown 79/05/04. 1p

7907100322 Submits summary of discussion w/JS Creswell re safety concerns influenced by TMI incident. Requests review of concerns by Ofc of Nuclear Reactor Regulation & update of status or resolution  
BRYAN, S-E Division of Reactor Operations Inspections 79/05/17 2pp.

7907030037 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907100312 Forwards Bryan 790517 memo re potential safety concerns. Requests evaluation & response  
MOSELEY, N C, Division of Reactor Operations Inspections 79/05/29 1p.

--7907100322 Submits summary of discussion w/JS Creswell re safety concerns in light of TMI incident. Requests review by Ofc of Nuclear Reactor Regulation & update of status.  
BRYAN, S.E Division of Reactor Operations Inspections. 79/05/17 2pp.

7907200108 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190062 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060103 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907130396 Forwards list of IE insp rept items for Aug 1977-Feb 1979 Requests identification of items relevant to inquiry group tasks Response requested by 790615  
PARLER, W NRC Three Mile Island Task Force 79/06/07 7pp

7907110510 Ack receipt of 790208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/78-25 & 50-320/78-38  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/08 1p

--7907110521 Responds to NRC 790117 ltr re violations noted in IE Insp Repts 50-289/78-25 & 50-320/79-38 Corrective actions soldering iron was unplugged & cardboard boxes were removed from cable spreading room  
HERBEIN, J G Metropolitan Edison Co 79/02/08 4pp

--7907110529 Forwards IE Insp Repts 50-289/78-25 & 50-320/78-38 on 781212-15 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/01/17 2pp

--7907110538 Notice of violation from insp on 781212-15  
\* Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/01/15 2pp

--7907110542 IE Insp Repts 50-289/78-25 & 50-320/78-38 on 791212-15. Noncompliance noted failure to control combustibles, failure to fully implement procedures & failure to implement SER commitment  
GAGE, L.W., EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/01/15 9pp

7907130352 Lists IE insp repts relevant to TMI-2 Task Force investigation  
MIRAGLIA, F J NRC Three Mile Island Task Force 79/06/13. 1p

7907180854 Notifies that response to IE Bulletin 79-01A will be forwarded 790712 More time is needed for preparation of response  
HERBEIN, J G Metropolitan Edison Co 79/06/13 1p

7907020119 Summarizes 790410 discussion of IE Bulletin 79-05A w/R Woodruff Action should be taken for other PWRs Operating procedures for transients listed. Discusses override of engineered safety feature Forwards Bulletin.  
ROBS, D F, Division of Project Management 79/06/16. 4pp.

--7907020124 IE Bulletin 79-05A, "Nuclear Accident at TMI - Suppl "  
\* Office of Inspection & Enforcement. 79/04/05 11pp

7907110370 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
GRIER, B.H Region 1, Philadelphia, Office of the Director. 79/06/20 1p

7907230677 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907240154 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required.  
GRIER, B.H Region 1, Philadelphia, Office of the Director. 79/06/23 1p.

7907180365 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required.  
GRIER, B H, Region 1, Philadelphia, Office of the Director 79/06/25. 1p.

## DOCKETED ITEMS

7907040190 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907180615 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907190088 Responds to 790504 request for documents & other records produced by IE re TMI Forwards "Title List, Publicly Available Documents, TMI-2, Docket 50-320" & printout indicating relevant documents w/o encl  
FELTON, J M Division of Rules and Records 79/06/29 1p

7907310505 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R. Periodic operating reports & related correspondence

7907100228 Forwards aquatic study monthly repts for Jan, Feb & Mar 1979 in response to 790418 telcon  
NARDACCI, G A Ichthyological Associates, Inc 79/05/01, 1p

--7907100236 Aquatic study monthly rept for Jan 1979  
\* Metropolitan Edison Co. 79/01/31 13pp.

--7907100244 Aquatic study monthly rept for Feb 1979  
\* Metropolitan Edison Co 79/02/28 14pp

--7907100235 Aquatic study monthly rept for Mar 1979.  
\* Metropolitan Edison Co 79/03/31 21pp

#### B. Reportable occurrences, LERs & related correspondence

7904130346 Forwards PNO-79-67P.  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/04/09, 1p

7904160043 Forwards PNO-79-67Q  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/04/10 1p

7905020227 Forwards PNO-79-67AF  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/04/28 1p

7905020256 Forwards PNO-79-67A0.  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/04/26, 1p

7907260641 Discusses LER trends. Study of high failure rates shown by LERs is under way. Methods exist for automatic detection & alarming of incorrect valve positions. Requirements for safety sys status monitoring sys is being reconsidered.  
BENTON, H R. Office of Nuclear Reactor Regulation 79/05/15 3pp

7907130328 Forward PNOs re TMI-2 incident, w/daily repts submitted by Region 1 since 790328 w/o encl.  
THOMPSON, D. Office of I & E Executive Officer for Operations Support 79/06/01 1p.

7907120637 Drafts of PNO 79-67 & suppls through 790604 (suppl AR)  
\* Office of Inspection & Enforcement. 79/06/04, 84pp

7907030118 PNO-79-67AV summary of info re nuclear incident as of 790626 Describes operational & environ status. Highest incore thermocouple temp indication 267 F.  
PAULUS, R C Office of Inspection & Enforcement 79/06/26 2pp.

7907180189 Notification of 790703 meeting w/NBSS vendors & A/E's in Bethesda, MD to discuss impact of TMI on review schedules for standardized designs undergoing review & planned for review  
KANE, W. F. Standardization Branch 79/06/28, 1p.

7907120162 PNO-79-67AV summary of info re nuclear incident as of 790702. Describes plant status & environ status. Highest incore thermocouple temp indication is 270 F.  
PAULUS, R. C.; THOMPSON, D. Office of Inspection & Enforcement 79/07/02, 2pp

7907170153 PNO-79-67AW summary of info re nuclear incident as of 790709 Describes operational & environ status. Highest incore thermocouple temp indication was 270 F.  
THOMPSON, D., PAULUS, R Office of Inspection & Enforcement  
79/07/09 2pp

7907240340 PNO-79-67AX summary of info re nuclear incident as of 790717 Describes operational & environ status. Highest incore thermocouple temp indication 269 F. Environ radiation levels consistent w/background  
PAULUS, R C., QDWER, G. C Office of Inspection & Enforcement  
79/07/17 2pp

#### T. Hearing transcripts on non-antitrust matters

7907120729 Transcript of 790410 press conference in Middletown, PA Pp 1-23  
QDCHY, R Division of Site Safety & Environmental Analysis  
79/04/10 23pp

7907180085 Transcript of 790425 meeting of President's Commission on Accident at TMI in Washington, DC Pp 1-56  
KEMENY, J., BABBITT, B., HAQOERTY, P President's Commission on the Accident at Three Mile Island 79/04/25 58pp

7907180077 Transcript of 790426 meeting of President's Commission on Accident at TMI in Washington, DC Pp 1-253  
KEMENY, J., BABBITT, B., HAQOERTY, P President's Commission on the Accident at Three Mile Island 79/04/26 254pp

7907180092 Transcript of 790427 meeting of President's Commission on Accident at TMI in Washington, DC Pp 1-73  
KEMENY, J., BABBITT, B., HAQOERTY, P President's Commission on the Accident at Three Mile Island 79/04/27 74pp

7907180099 Cover sheet of transcript of 790517 second meeting of President's Commission on Accident at TMI in Middletown, PA Pp 1-42  
\* President's Commission on the Accident at Three Mile Island  
79/05/17 1p

7907180106 Transcript of 790519 morning session, second meeting of President's Commission on Accident at TMI in Middletown, PA Pp 1-152  
KEMENY, J. Q., BABBITT, B., HAQOERTY, P E President's Commission on the Accident at Three Mile Island 79/05/19 152pp

--7907180109 Transcript of 790519 afternoon session, second meeting of President's Commission on Accident at TMI in Middletown, PA Pp 152a-346  
KEMENY, J. Q., BABBITT, B., HAQOERTY, P President's Commission on the Accident at Three Mile Island. 79/05/19, 351pp.

7907180022 Transcript of 790530 third meeting of President's Commission on Accident at TMI in Washington, DC Pp 1-210  
KEMENY, J. Q., BABBITT, B., HAQOERTY, P E President's Commission on the Accident at Three Mile Island 79/05/30, 210pp

--7907180030 Transcript of H Dieckamp 790518 testimony before President's Commission on Accident at TMI Pp 1-11.  
DIECKAMP, H M GPU Service Corp 79/05/18, 11pp

--7907180034 Transcript of WM Greitz 790518 testimony before President's Commission on Accident at TMI Pp 1-6  
GREITZ, W. M Metropolitan Edison Co 79/05/18 6pp.

--7907180037 Transcript of JQ Herbein 790518 testimony before President's Commission on Accident at TMI Pp 1-4.  
HERBEIN, J Q, Metropolitan Edison Co 79/05/18, 5pp.

--7907180041 Transcript of RC Arnold 790530 testimony before President's Commission on Accident at TMI Pp 1-4  
ARNOLD, R C. GPU Service Corp. 79/05/30, 6pp.

--7907180046 Transcript of GP Miller 790518 testimony before President's Commission on Accident at TMI Pp 1-5.  
MILLER, G P. Metropolitan Edison Co 79/05/18 6pp

--7907180055 Transcript of H Dieckamp 790423 testimony before Senate Subcommittee on Nuclear Regulation. Pp 1-21.  
DIECKAMP, H. M GPU Service Corp 79/04/23 22pp.

7907180013 Transcript of 790531 afternoon session, third meeting of President's Commission on Accident at TMI in Washington, DC. Pp 145-374.  
KEMENY, J. Q., BABBITT, B., HAQOERTY, P E President's Commission on the Accident at Three Mile Island 79/05/31, 23pp.

7907180017 Transcript of 790531 press conference of President's Commission on Accident at TMI Pp 1-350  
KEMENY, J Q President's Commission on the Accident at Three Mile Island 79/05/31 350pp

7907180073 Transcript of 790531 morning session, third meeting of President's Commission on Accident at TMI in Washington, DC Pp 1-143  
KEMENY, J Q, DABBITT, B, HAGGERTY, P E President's Commission on the Accident at Three Mile Island 79/05/31 143pp

7907180003 Transcript of 790601 morning session, third meeting of President's Commission on Accident at TMI in Washington, DC Pp 1-177  
KEMENY, J Q, DABBITT, B, HAGGERTY, P E President's Commission on the Accident at Three Mile Island 79/06/01 177pp

7907180010 Transcript of 790601 press conference w/President's Commission on Accident at TMI Pp 1-19  
KEMENY, J Q President's Commission on the Accident at Three Mile Island 79/06/01 20pp

7907030043 Follows up 790607 transmittal Forwards transcript of ACRS 790601 meeting of TMI Ad Hoc Subcommittee W/o encl  
CORNELL, E K NRC Three Mile Island Task Force 79/06/12 1p

7907100082 Forwards transcript of 790601 testimony of JM Hendrie Proposed corrections made by JM Hendrie are marked on transcript & listed on correction sheets Transcript not encl  
FITZGERALD, J A Office of the General Counsel 79/06/15 1p

--7907100087 Errata to transcript of 790601 testimony of JM Hendrie before President's Commission Corrections made by JM Hendrie  
HENDRIE, J M Commission 79/06/15 3pp

--7907100092 Forwards transcript of 790601 testimony of JM Hendrie before President's Commission re TMI Corrections may be submitted W/o encl  
JORGENSEN, B President of UB & Executive Offices 79/06/07 1p

7907100122 Transcript of 790620 meeting in Washington, DC to discuss NRC response to emergency requirements  
HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commission 79/06/20 68pp

--7907100130 Discusses NRC response to emergency requirements Commission would meet quickly to make necessary assignments Submits fixed agenda as starting point for discussion  
BRADFORD, P A Commission 79/06/30 2pp

7907100124 Transcript of 790621 NRC meeting re TMI radiological sequence Forwards operational log Visual aid & briefing outline encl  
HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commission 79/06/21 100pp

--7907100132 Forwards interim radiological sequence of events as of 790614 Sequence does not include all environ sampling data, only that illustrating conditions at time reported  
BTLELO, V Office of Inspection & Enforcement 79/06/19 1p

7907100121 Transcript of 790625 meeting in Washington, DC re lessons learned at TMI Visual Aid "TMI-2 Lessons Learned Task Force" encl  
HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commission 79/06/25 136pp

790726072B Transcript of subcommittee 790711 meeting in Washington, DC re implications of TMI-2 accident, Pp 1-194  
OKRENT, D, CARBON, M W, KERR, W. ACRS - Advisory Committee on Reactor Safeguards 79/07/11 194pp

#### U Congressional/Executive Correspondence

7906060054 Requests info re whether downgrading of H&W plants to 50% capacity would help ensure safe shutdown in case of TMI type emergency Requests info re state emergency plans, Document withheld (ref FOIA Exemption 5)  
HART, O Congress (Joint & Rotating Committees, etc.) 79/04/03 2pp.

790726047B Reviews comments made by Senator Simpson in 790430 meeting of Subcommittee on Nuclear Regulation.  
BROVHOLT, D Assistant Director for Quality Assurance & Operations 79/05/01 3pp.

7907260489 Requests info re NRC policy toward evacuation plans  
UDALL, M K House of Rep. 79/05/02. 3pp

7907050564 Advises of error in NY Times 790508 article re subcommittee site visit Clarifies chain of events re pressure spike in containment bldg  
DIECKAMP, H M OPU Service Corp 79/05/09 1p

7907180130 Responds to 790419 request to evaluate NRC program to license power plant operators Provides examples of operator error & suggestions for improving training & qualifications  
STAATB, E B General Accounting Office 79/05/15 16pp

7906110416 Ack receipt of 790403 ltr re matters of immediate health & safety in connection w/TMI incident Discusses steps taken as result of incident Forwards orders to plants constructed by B&W  
HENDRIE, J M Commission 79/05/18 4pp

7907260520 Responds to T Franz 790401 ltr re health & safety of airline passengers who flew over site during accident Concerned w/release of radioactivity to atmosphere  
GOSSICK, L V Office of the Executive Director for Operations 79/06/05 2pp

7907030071 Responds to Representative Stratton 790504 ltr suggesting involving Admiral Rickover in corrective actions re TMI Forwards draft ltrs supporting involvement  
GOSSICK, L V NRC Three Mile Island Task Force 79/06/11 1p

7907180721 Informs that review of TMI accident impact is completed & addl reprogramming actions in FY79 are necessary Forwards list of proposed actions & requests early approval W/o encl  
HENDRIE, J M Commission 79/06/27 1p

--7907180736 Informs that review of TMI accident impact is completed & addl reprogramming actions in FY79 are necessary Forwards list of proposed actions & requests early approval W/o encl  
HENDRIE, J M Commission 79/06/27 1p

--7907180751 Informs that review of TMI accident impact is completed & addl reprogramming actions in FY79 are necessary Forwards list of proposed actions & requests early approval W/o encl  
HENDRIE, J M Commission 79/06/27 1p

--7907180766 Informs that review of TMI accident impact is completed & addl reprogramming actions in FY79 are necessary Forwards list of proposed actions & requests early approval W/o encl  
HENDRIE, J M Commission 79/06/27 1p

--7907180785 Informs that review of TMI accident impact is completed & addl reprogramming actions in FY79 are necessary Forwards list of proposed actions & requests early approval  
HENDRIE, J M Commission 79/06/27 9pp

7907160050 Responds to 790523 ltr re health hazards to travelers in central PA as result of TMI-2 accident No danger exists  
HENDRIE, J M Commission 79/06/28 1p

7907180651 Responds to 790330 request for investigation into accident at TMI & comparison of facility designs Investigations are under way Forwards IE bulletin relevant to facility & public announcement re TMI task force  
HENDRIE, J M Commission 79/06/28 2pp

--7907180673 Requests full & immediate investigation into TMI accident & analysis of comparative structural & operational design of facilities  
PANETTA, L E. House of Rep 79/03/30 1p

#### DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

D. NRC Draft/Final Environmental Statements, suppl & correspondence

7907230318 Summary of 790613 meeting w/util in Bethesda, MD re proposed instrumentation on changes to be completed prior to Cycle 4 operation  
VERRELLI, D M Operating Reactors Branch 3 (Pre 790625) 79/06/19 3pp

#### F. Security, medical, emergency & fire protection plans

7907250605 Notifies that refund of Class III amend fee is in process Waiver for amend to Tech Specs re fire protection is warranted.  
MILLER, W O. License Fee Management Branch. 79/06/15. 1p

7907230280 Forwards appropriate amend fee for review & approval of safeguards contingency plan.  
EHRENBERGER, W Georgia Power Co 79/07/12 1p

## DOCKETED ITEMS

## I Financial information

7907050357 Forwards Annual Financial Repts 1978 for GA Power Co & Southern Co  
WHITHER, C F Georgia Power Co 79/07/02 1p

--7907050384 Annual Financial Rept 1978  
\* The Southern Co 79/02/28 39pp

--7907050394 Annual Financial Rept 1978  
\* Georgia Power Co 79/01/31 34pp

## P Operating license stage documents &amp; correspondence

7907106492 Notification of 790613 meeting w/GA Power Co re reload application for Facility  
VERRELLI, D M Operating Reactors Branch 3 (Pre 790625)  
79/05/06 2pp

7907180632 Forwards NUREG-0560. "Staff Rept on Generic Assessment of Feedwater Transients in PHRS Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907310224 Forwards Amend 66 to License DPR-57, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/06/12 2pp

--7907310232 Amend 66 to License DPR-57, revising Tech Specs to allow count rate on source range monitor channels to drop below three counts per second when entire core is removed or reloaded  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/06/12 7pp

--7907310236 Safety evaluation supporting Amend 66 to License DPR-57  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/12 4pp

--7907310239 Notice of issuance & availability of Amend 66 to License DPR-57  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625)  
79/06/12 2pp

7907100545 Summarizes actions taken re alternate power supply to reactor protection sys. in light of NRC 790613 meeting  
Installation of protective breakers on alternate power supply cannot be assured by end of refueling outage  
WHITHER, C F Georgia Power Co 79/06/25 2pp

7907170066 Forwards proposed Tech Spec changes re spent fuel pool storage expansion & proposed determination of amend fee & design rept & safety evaluation  
WHITHER, C F Georgia Power Co 79/07/09 3pp

--7907170069 Proposed Tech Spec changes re spent fuel pool storage expansion  
\* Georgia Power Co 79/07/09 8pp

--7907170073 "Spent Fuel Pool Mod." design rept & safety evaluation  
\* Georgia Power Co 79/07/09 69pp

7907240339 Forwards proposed amends to Tech Specs of App B to Licenses DPR-57 & NPF-5 Changes will allow 90-day extension for annual environ surveillance rept when radiological & nonradiological data results not available  
EHRENSPERGER, W Georgia Power Co 79/07/12 4pp

7907200337 Forwards proposed changes to Tech Specs re safety relief valve tail pipe monitoring sys  
EHRENSPERGER, W Georgia Power Co 79/07/13 2pp

--7907200341 Proposed changes to Tech Specs re safety relief valve tail pipe monitoring sys  
\* Georgia Power Co 79/07/13 4pp

7907240691 Ack receipt of 790629 request for info required by NRC to review corporate capabilities before 790730. Seeks extension to 790831 because of extant of request  
WHITHER, C F Georgia Power Co 79/07/19 1p

## G Inspection reports, IE Bulletins &amp; correspondence

907180087 Forwards list of Region 2 personnel for whom permanent nonemployee badges are requested.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/03/19 4pp

7907020342 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl 1"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

790710329 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907190243 Responds to IE Bulletin 79-09 Several Type AKL-2-15, AK-2-25 & AK-2-50 circuit breakers are currently in use None have undervoltage trip device incorporated.  
WIDNER, W A Georgia Power Co 79/05/16 2pp

7907100196 Forwards IE Circular 79-0B, "Attempted Extortion ~ Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060399 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907100160 Responds to IE Bulletin 79-10 Forwards operator & senior operator examination results & statistics  
STAFFA, R W Georgia Power Co 79/05/24 3pp

7907030098 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907180058 Requests extension until 790629 for responding to IE Bulletin 78-12, 78-12A & 78-12B  
STAFFA, R W Georgia Power Co 79/05/29 1p

7907200194 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907120426 Forwards list of Region 2 personnel for whom permanent non-employee badges are requested  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/04 3pp

7907190175 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060059 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907190085 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-07 & 50-366/79-08  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/06/08 1p

--7907190095 Responds to NRC 790402 ltr re violations noted in IE Insp Repts 50-321/79-07 & 50-366/79-08 Corrective actions importance of corrective action verification emphasized during regular training sessions  
STAFFA, R W Georgia Power Co 79/04/25 2pp.

--7907190103 Forwards IE Insp Repts 50-321/79-07 & 50-366/79-08 on 790220-22, 28 & 0302 & notice of violation.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

--7907190110 Notice of violation from insp on 790220-22, 28 & 0302  
\* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 1p

--7907190121 IE Insp Repts 50-321/79-07 & 50-366/79-08 on 790220-22, 28 & 0302 Noncompliance noted failure to take corrective action on nonconforming concrete expansion anchors & failure to rept significant const deficiency  
BRYANT, J C, MOENOB, L, COMPTON, R M Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 4pp



7907250163 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp

7907190355 Responds to IE Bulletins 79-01 & 79-01A Engineering review of environ qualification is being performed Incomplete results indicate that reactor water sample isolation valve solenoids & MSIV limit switches are not in compliance  
STAFFA, R W Georgia Power Co 79/06/13 1p

7907190518 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 2pp

7907120079 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907110228 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

7907310020 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180436 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310254 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907100437 Forwards addl info to 790613 response to IE Bulletins 79-01 & 79-01A Class IE equipment has been found capable of functioning under postulated accident conditions, except for items identified in util 790613 response  
STAFFA, R W Georgia Power Co 79/07/03 10pp

7907310383 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### R. Periodic operating reports & related correspondence

7907060234 Forwards Suppl 1, "Discharges to Ground," to Annual Environ Surveillance Rept 1978  
MANRY, M Georgia Power Co 79/06/27 1p

--7907060236 Suppl 1, "Discharges to Ground," to Annual Environ Surveillance Rept 1978  
\* Georgia Power Co 79/06/30 39pp

7907100350 Forwards Suppl 2 to Annual Environ Surveillance Rept, 1978  
MANRY, M Georgia Power Co 79/07/02 1p

--7907100360 Suppl 2 to Annual Environ Surveillance Rept, 1978  
\* Georgia Power Co 78/12/31 52pp

7907170220 Forwards monthly operating rept for June 1979  
MANRY, M Georgia Power Co 79/07/09 1p

--7907170222 Monthly operating rept for June 1979  
ALLEN, P. B Georgia Power Co 79/07/05 7pp

#### B Reportable occurrences, LERs & related correspondence

7907110478 Corrects 780224 ltr LER 50-321/1977-08 should be designated 50-321/1978-08  
MANRY, M Georgia Power Co 78/03/02 1p

--7907110482 Forwards LER 78-008/01T-0  
MANRY, M Georgia Power Co. 78/02/24, 1p

--7907110485 LER 78-008/01T-0 on 780209 during steady state power operation, test valve found to be broken off Cause unknown  
Valve repaired Investigation under way  
GREENE, T V Georgia Power Co 78/02/24 2pp

--7907110491 Notifies that LER 78-085 has been voided  
MANRY, M Georgia Power Co 78/11/16 1p

7907060346 Forwards LER 79-021/03L-3  
MANRY, M Georgia Power Co 79/06/27 1p

--7907060348 LER 79-021/03L-3 on 790320 small amount of water bubbled from ground Caused by open valve on temporary half-inch line which was not removed after const Line broken & capped  
ROGERS, W H Georgia Power Co 79/06/27 4Bpp

7907090373 Forwards LER 79-038/03L-0  
MANRY, M Georgia Power Co 79/07/02 1p

--7907090376 LER 79-038/03L-0 on 790613 scram discharge vol hi-level switches inoperable Caused by bent float & binding against float chamber Float rods straightened Similar switches to be inspected  
NIX, R T Georgia Power Co 79/07/02 1p

7907100369 LER 79-040 has been voided  
MANRY, M Georgia Power Co 79/07/02 1p

7907170133 LER 50-321/79-40 has been voided  
MANRY, M Georgia Power Co 79/07/03 1p

7907170214 Forwards LER 79-043/01T-0  
MANRY, M Georgia Power Co 79/07/03 1p

--7907170218 LER 79-043/01T-0 on 790628 radwaste sump discharge piping not supported per Class 1 requirements Caused by design error Piping supports will be redesigned & installed during current refueling outage  
GREENE, T V Georgia Power Co 79/07/03 3pp

7907180498 Forwards LER 79-039/03L-0  
MANRY, M Georgia Power Co 79/07/06 1p

--7907180499 LER 79-039/03L-0 on 790618 while installing conduit in flooding sys, worker started timing relay which initiated alarms & carbon dioxide deluge Caused by employee working near timer initiation relay  
GREENE, T V Georgia Power Co NRC 79/07/06 1p

7907170206 Forwards LER 79-042/03L-0  
MANRY, M Georgia Power Co 79/07/10 1p

--7907170209 LER 79-042/03L-0 on 790625 during local leak rate testing, standby liquid control inboard containment isolation valve C41-F007 was leaking excessively Caused by scratch on valve seat Seat lapped & successfully tested  
GREENE, T V Georgia Power Co 79/07/10 2pp

7907170056 Forwards LER 79-041/03L-0  
MANRY, M Georgia Power Co 79/07/11 1p

7907170060 LER 79-041/03L-0 on 790624 diesel generator tripped while performing procedure HNP-1-3801 Cause not yet determined Procedure performed again successfully Investigation is in progress  
NIX, R T Georgia Power Co 79/07/11 1p

7907170087 Forwards LER 78-093/03L-1  
MANRY, M Georgia Power Co 79/07/11 1p

--7907170091 LER 78-093/03L-1 on 781109, during normal operation, core drills were made through diesel generator room walls Caused by drills made to allow conduit through walls Conduit installed & holes grouted on 781112  
NIX, R T Georgia Power Co 79/07/11 1p

7907230535 Forwards LER 79-045/03L-0,  
MANRY, M. Georgia Power Co. 79/07/12 1p.

--7907230541 LER 79-045/03L-0 on 790624 during test, relief valve lifted at 1200 psig Caused by valve corrosion Valve disassembled, cleaned & reset to relieve at 1380 psig  
\* Georgia Power Co 79/07/12 1p

7907260840 Forwards LER 79-046/03L-0  
MANRY, M Georgia Power Co 79/07/18 1p

## DOCKETED ITEMS

--7907260847 LER 79-046/03L-0 on 790710 technician failed to check down scale alarm & red out block alarms during weekly surveillance test HNP-1-3052 on intermediate range monitors Caused by confusion over procedures Procedure revised  
NIX,R T Georgia Power Co 79/07/18 1p

## DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

## A Application/construction stage documents &amp; correspondence

7907120209 Forwards order extending const completion date  
VARONA, S A Light Water Reactors Branch 4 79/05/14 3pp

--7907120226 Order extending const completion date  
DOYD, R S Division of Project Management 79/05/14 2pp

--7907120241 Evaluates request for extension of provisional const permit CFP-95 Issuance of order is reasonable & should be authorized  
VARONA, S A, WILSON, J N Light Water Reactors Branch 4 79/05/14 4pp

--7907120253 Negative declaration supporting extension of const permit CFP-95 expiration date  
REGAN, W H Environmental Projects Branch 2 79/05/04 2pp

--7907120261 EIA supporting extension of const permit CFP-95  
a Division of Site Safety & Environmental Analysis 79/05/14 2pp

7907250385 FOIA request for 17,000 to 18,000 licensee engineering & design coordination repts describing inadequacies in facility const  
GROSBMAN, K Island Closeup News Service 79/05/22 2pp

7907110276 Notification of 790608 meeting w/util in Bethesda, MD to discuss facility licensing schedule  
WILSON, J N Light Water Reactors Branch 4 79/05/31 2pp

7907310472 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W," per 790523 request, w/o encl  
HOEFLING, R K Office of the General Counsel 79/06/04 1p

7907130018 Notification of 790615 meeting w/Mark II owners & OE in Bethesda, MD re closure of Mark II lead plant program  
ANDERSON, C J Assistant Director for Reactor Safety 79/06/05 6pp

7907180415 Notification of postponement of 790615 meeting w/Mark II owners & OE to discuss closure of Mark II lead plant program Meeting will be rescheduled.  
ANDERSON, C J Containment Systems Branch 79/06/05 2pp

7907090251 Notification of 790724-25 meeting w/representatives from lead Mark II plants to discuss long-term program  
ANDERSON, C J Containment Systems Branch 79/06/11 2pp

7907250603 Notification of 790726 meeting w/O.E.C. Economus & Mark II owners in Bethesda, MD to discuss closure of Mark II lead plant program  
ANDERSON, C J Containment Systems Branch 79/06/25 6pp.

907300171 Notification of 790717-18 meeting w/Mark II owners group & OE in Lebanon, NH to discuss Mark II pool dynamic programs  
ANDERSON, C J Containment Systems Branch 79/07/03 12pp

907190803 Responds to FOIA request for NRC Annual Rept 1978, recent NRC Studies of TMI rept indicating methods to cool down TMI core & environ impact studies of Indian Point facility & Brookhaven Natl Lab. Forwards 1978 NRC Annual Rept w/o encl.  
FELTON, J M Division of Rules and Records 79/07/06 1p

07180547 Advises of decision to delay scheduled fuel load date to Nov 1980 Delay caused by plant mods & current slippage of project schedule Change in date will be included in normal monthly schedule rept  
WOLFORD, A H Long Island Lighting Co 79/07/12 2pp

07180561 Notifies that util has invoked Code Cases N-122, N-192, N-225 & 1644-S to ASME Section III Affected parts include flexible metal hose & Class I, II & III pipe support assemblies  
WOLFORD, J P Long Island Lighting Co 79/07/12 3pp

7907250396 Ack receipt of 790522 FOIA request for B&W design coordination repts FOIA applies only to documents in possession of NRC; access to specified documents is impossible  
FELTON, J M Division of Rules and Records 79/07/13 1p

## F Security, medical, emergency &amp; fire protection plans

7907110524 Summary of 790516-17 meeting w/util re util security plan & contingency plan for facility Details withheld (ref 10CFR9.12)  
WILSON, J N Light Water Reactors Branch 4 79/05/29 4pp

## G Adjudicatory correspondence

7907190182 Submits discovery request re inclusion by applicant of offshore winds in analyses of relative concentrations  
LIKE, I Reilly, Like & Schneider 79/05/07 2pp

7907090401 Forwards to counsel for Suffolk County, NY, NEDE-21021-P "Test Program for Collet Retainer Tube," list of safety-related items discussed in Reel Rept & summary status rept of items  
W/o encl  
WHITTEMORE, F C Hunton & Williams 79/05/15 2pp

--7907090409 Agreement re confidentiality of NEDE-21021-P "Test Program for Collet Retainer Tube," list of safety-related items discussed in Reel rept & summary status rept of items  
HARD, R C Reilly, Like & Schneider GOLDSMITH, M W Suffolk County, NY DANNEYER, J R General Electric Co 79/03/26 4pp

7907050524 Forwards responses to questions raised during 790502 meeting of NRC, util, B&W & OE re narrowing of util contentions addressed in NRC interrogatories Next meeting will be held  
790606  
NOVARRO, J P Long Island Lighting Co 79/05/16 10pp

7907120139 Forwards matl to assist in developing Suffolk County, NY position on contentions re component reliability, merit computer code & seismic qualification programs for Westinghouse equipment, w/o encl  
HOEFLING, R K Branch 4 79/05/16 2pp

7907170244 Forwards ALAB-455, ALAB-527, 10CFR19 & 10CFR21 w/o encl  
HOEFLING, R K Branch 4 79/05/18 1p

7907180603 Answer submitted by util to I Like 790517 ltr requesting NRC to begin insp of plant Request is improperly directed & unnecessary Affidavit of JP Navarro & Certificate of Svc encl  
REVELEY, W T Hunton & Williams 79/05/29 8pp

7907060519 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" in response to 790523 request w/o encl  
HOEFLING, R K Branch 4 79/06/04 1p

7907130400 Second set of interrogatories & document requests for util & NRC, submitted by County of Suffolk NY Questions are derived from NRC evaluation of engineering documents describing safety-related problems at plant  
LIKE, I Suffolk County, NY 79/06/06 7pp

7907180741 Notifies of series of meetings between NRC, util & Suffolk County, NY to facilitate discovery & particularize contentions of Suffolk County, NY Forwards 790605 stipulations requesting ABLD to accept parties agreements, stipulations requesting ABLD to accept parties agreements.  
WHITTEMORE, E C Hunton & Williams 79/06/07 1p

--7907180755 Requests ABLD to accept parties agreements re meetings to facilitate informal discovery. Twelve contentions of Suffolk County, NY will be dropped Util agrees to certain insps & leakage rate re spent fuel pool.  
LIKE, I Suffolk County, NY REVELEY, W T Long Island Lighting Co HOEFLING, R K Branch 4 79/06/05 2pp.

7907180752 Request for extension until 790706 to respond to County of Suffolk 790606 second set of interrogatories & document requests to util & NRC Suffolk County has no objection to request Certificate of Svc encl  
HOEFLING, R K Branch 4 79/06/14 3pp.

7907180645 Order granting NRC 790614 request for extension until 790706 to respond to Suffolk County 790606 discovery request.  
BOWERS, E. B. Atomic Safety and Licensing Board Panel 79/06/20 1p.

7907180718 Responds to I Like 790606 ltr requesting NRC require util to study feasibility of converting to conventional or alternative fuel. Request was improperly formed & addressed. Certificate of Svc encl.  
REVELEY, W T Long Island Lighting Co 79/06/21 3pp.

7907180761 Answer submitted by util to Suffolk County 790604 second set of interrogatories & document requests Forwards info requested in Apps A & B Affidavit of WJ Museler & Certificate of Svc encl  
WHITTEMORE, F C Hunton & Williams 79/06/22 2pp

#### G Inspection reports, IE Bulletins & correspondence

7907110395 Responds to IE Bulletin 79-09 OE Type AK circuit breakers not in use in safety-related sys  
NOVARRO, J P Long Island Lighting Co 79/05/04 2pp

7907110308 Responds to IE Bulletin 79-03 Three spool pieces contain welded stainless steel pipe SA312, TP304 mfg by Youngstown Welding & Engineering Co for use in safety-related piping sys  
NOVARRO, J P Long Island Lighting Co 79/05/16 2pp

7907060387 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907030033 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200107 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/05/31 1p

7907190057 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060101 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020046 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/06/11 1p

7907100471 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230674 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120300 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100308 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100418 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p.

7907100502 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180775 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270337 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310802 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

#### B Reportable occurrences, LERs & related correspondence

7907120623 Submits 30-day deficiency rept re welding of integral attachments to Class 1 piping by sys Caused by lack of penetration of weld at root & most matl used not being Class 1 matl  
NOVARRO, J P Long Island Lighting Co 79/06/29 2pp

#### DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

#### A Application/construction stage documents & correspondence

7907100691 Responds to 790317 ltr re earthquake potential & existence of Hosgr fault CP could be issued based on current seismic criteria Some parts of plant do not provide degree of safety currently required Discusses waste disposal & exposures  
BOYD, R B Division of Project Management 79/05/18 6pp

7907090206 Submits addl info requested in NRC 790516 ltr re high voltage penetration, thermal cycling, fault current protection for containment penetrations, fire protection program & inservice testing OE 790605 ltr to util  
FURUBUH, M H Pacific Gas & Electric Co 79/07/02 9pp.

7907230242 Notifies that requested info for review of corporate capabilities will be submitted by 790730 Info requested in Sections I & II B of NRC 790629 ltr will be submitted upon completion  
CRANE, P A Pacific Gas & Electric Co 79/07/16 1p

#### F Security, medical, emergency & fire protection plans

7907240234 Clarifies statement in 790702 ltr re item 6 fire protection program Intends to comply w/Section 5 c 2 of Branch Tech Position ASB 9 5-1, Revision 1 re surveillance of control & sectionalizing valves in firewater sys  
CRANE, P A Pacific Gas & Electric Co 79/07/18 1p

7907260643 Forwards summaries of recent plant mods, including mod identified in BER Suppl B, fire protection mod according to fire zones, other commitments not in BER Suppl B & mods different from those listed in BER Suppl B  
CRANE, P A Pacific Gas & Electric Co, 79/07/20 19pp

#### Q Adjudicatory correspondence

7907130496 Submits addl correction to proposed findings of fact & conclusions of law  
CRANE, P. A. Pacific Gas & Electric Co 79/05/07 1p.

7907160075 Responds to Joint Intervenor's 790509 request to ABLB Motion to reopen should be deferred pending completion of NRC rept on TMI Seeks denial of request for certification of certain legal issues re Class 2 accidents, Certificate of Svc encl  
DAVIS, L D Anti-Trust Division 79/05/24 6pp

7907060144 Responds to 790504 ltr to JM Hendrie which requested moratorium on licensing of facility NRC is evaluating TMI accident extensively No new reactor licenses will be issued until evaluation is complete.  
GOBBACK, L. V. Office of the Executive Director for Operations 79/05/30 2pp.

--7907060149 Urges suspension of OL proceeding until TMI accident is investigated, emergency preparedness completed & seismic design bolstered  
BROWN, E Q California, State of 79/05/04 3pp

7907130110 Util request for denial of Joint Intervenor's 790509 motion for ABLB to reopen record re emergency plans & for directed certification. Both requests require regulation & mods through inappropriate procedures Certificate of Svc encl.  
NORTON, B Bruce Norton, MORRISSEY, J. C. Pacific Gas & Electric Co  
QEHR, A. C. Snell & Wilmer 79/06/01 13pp.

--7907130118 Comments on EO Brown, Governor of CA, 790511 ltr requesting suspension of licensing proceedings No indication of need for substantial changes in design or operating procedures  
BONNER, J F, Pacific Gas & Electric Co 79/05/11 2pp

## DOCKETED ITEMS

7907130347 Motion by San Luis Obispo Mothers for Peace for copy of security plan, discovery schedule for examination of plan & for hearings to determine adequacy of plan Certificate of Svc encl  
BALDWIN, W A San Luis Obispo Mothers for Peace 79/06/08 Bpp

7907200255 Opposes intervenors San Luis Obispo Mothers for Peace 790608 request that ASLB reopen record re security plan intervenors waived right to participate in security hearings & have not shown good cause to reopen issue W/Certificate of Svc  
DAVIS, L D Branch 4 79/06/28 10pp

#### H General correspondence

7907120333 Responds to 740511 ltr to JM Hendrie expressing concern re Governor Brown request for moratorium on issuing DL New safety requirements arising from TMI investigation will be applied to all plants where applicable  
BOVD, R B Division of Project Management 79/06/14 2pp

--7907120349 Responds to 790504 ltr to JM Hendrie re moratorium on licensing plants Until TMI evaluation is complete, no new licenses will be issued ASLB will consider testimony re adequacy of plant to withstand earthquakes  
GOBSICK, L V Office of the Executive Director for Operations 79/05/30 2pp

#### Q Inspection reports, IE Bulletins & correspondence

7907160243 Review Westinghouse rept, "Qualification Testing of Barton Pressure & Differential Pressure Transmitters."  
SATTERFIELD, R Electric, Instrumentation & Control Systems Branch 79/04/17 1p

7907190381 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breaker not used or planned for use  
CRANE, P A Pacific Gas & Electric Co 79/05/15 1p.

7907270140 Forwards IE Insp Repts 50-275/79-11 & 50-323/79-06 on 790401-20 No noncompliance noted  
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/15 2pp

--7907270141 IE Insp Repts 50-275/79-11 & 50-323/79-06 on 790401-20 No noncompliance noted Major areas inspected: preoperational testing, emergency procedures & fire prevention & protection  
YOUNG, T Region 5, San Francisco, Office of the Director  
STEINBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/14 4pp

7907090398 Forwards response to IE Bulletins 79-04 & 79-06A, Revision 1 Info & training sessions scheduled. Revising emergency operating procedures to include possibility of void formation in vessel  
CRANE, P A Pacific Gas & Electric Co 79/05/24 12pp

7907020452 Submits unsolicited response to IE Bulletin 79-06A, re sys transients, plant equipment features & operating procedures as result of TMI incident  
GORMLEY, H J Pacific Gas & Electric Co 79/05/25 13pp

7906200052 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/29 1p.

7907190423 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves)" No action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p.

7907060029 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07 1p

7907020265 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys."  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907020448 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate."  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p

7907120006 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/21 1p

7907120621 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/25 1p

7907060216 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907050492 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/27 1p

7907100529 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/28 1p

7907130205 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p

7907180700 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/11 1p

7907310396 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260270 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

#### B Reportable occurrences, LERs & related correspondence

7907020282 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/05 1p

7907030191 Forwards PNO-79-67AB  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/13 1p

7907030232 Forwards PNO-79-67AT, "Nuclear Incident at TMI"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/19 1p

7907050531 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907130384 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/03 1p.

#### U Congressional/Executive Correspondence

7907180631 Responds to 790330 request for investigation info accident at TMI & comparison of facilities designs. Investigations are underway. Forwards IE Bulletins relevant to Diablo Canyon & public announcement re TMI task force  
HENDRIE, J M. Commission. 79/06/28. 2pp

--7907180673 Requests full & immediate investigation into TMI accident & analysis of comparative structural & operational design of facilities  
PANETTA, L E House of Rep. 79/03/30. 1p

7907310145 Responds to 790601 ltr re constituent concerns over facilities Discusses measures taken to prevent Class 9 accident, seismic problems & emergency response procedures  
GOBSICK, L V Office of the Executive Director for Operations 79/06/29 2pp

--7907310164 Urges NRC to review Class 9 accidents & seismic problems & to re-evaluate emergency response procedures at facilities  
LAGOMARSINO, R J House of Rep 79/06/01 1p

# DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

## J Insurance & indemnity information

7907050336 Forwards Endorsements 34 & 35 to NELIA Policy NF-21B  
GRAHAM, W E Carolina Power & Light Co 79/06/26 3pp

7907240321 Forwards Endorsements 31 & 32 to MAELU Policy MF-80  
GRAHAM, W E Carolina Power & Light Co 79/07/16 3pp

## P Operating license stage documents & correspondence

7907030051 Summary of 790516 meeting w/util, GE & United Engineers & Constructors in Bethesda, MD re results of seismic piping stress reanalysis performed per IE Bulletin 79-07  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/05/21 12pp.

7907130054 Notification of 790530 meeting w/util in Bethesda, MD to discuss reanalysis of pipes & supports & proposed fixes for identified deficiencies  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625) 79/05/30 2pp

7907190297 Notification of 790604 meeting w/util in Bethesda, MD to discuss pipe & support reanalyses, current status of identified deficiencies & provide verification of items discussed at last meeting  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/06/01 1p

7907180624 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907310243 Notifies that refund of Class 1 & 2 amend fees is being processed  
Waiver for Tech Specs re fire protection is warranted  
MILLER, W O License Fee Management Branch 79/06/13 1p

7907230335 Summary of 790604 meeting w/util, GE & United Engineers & Const in Bethesda, MD re current status of reanalyses of pipes & supports, mod to be completed & procedures to address deviations from as-built conditions  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/06/19 4pp

7907090323 RD on 790625 noted that Tech Specs could cause reactor to operate in less conservative manner than assumed in safety analyses. Plant operating manual provides safety backup  
STARKEY, R B, ROBINSON, H B Carolina Power & Light Co 79/06/26 1p

7907110406 Submits technical description of proposed mods for offgas hydrogen recombiner sys, as requested in NRC 780912 ltr.  
UTLEY, E E Carolina Power & Light Co 79/06/29 6pp

7907130379 Submits status of seismic analysis of safety-related piping  
UTLEY, E E Carolina Power & Light Co 79/07/03 7pp

## Q Inspection reports, IE Bulletins & correspondence

7907050150 Forwards IE Insp Repts 50-325/79-14 & 50-324/79-14 on 790327-30 Notice of violation withheld (ref 10CFR2 790)  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/17 2pp

--7907050155 IE Insp Repts 50-325/79-14 & 50-324/79-14 on 790327-30 Noncompliance noted physical barrier, security plan, lighting & access control Details withheld (ref 10CFR2 790)  
MOORE, D E Region 2, Atlanta, Office of the Director  
TOBIN, W J Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/16, 1p

7907020352 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/21 2pp.

7907120558 Forwards IE Insp Repts 50-324/79-16 & 50-325/79-16 on 790410-13 No noncompliance noted  
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 79/05/01 2pp

--7907120560 IE Insp Repts 50-324/79-16 & 50-325/79-16 on 790410-13 No noncompliance noted Major areas inspected preparation for refueling, start-up after refueling & review of refueling associated procedures  
JULIAN, C A, GRAHAM, M J, BURNETT, P T Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/27 5pp

7907110314 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907190566 Responds to IE Insp Rept 79-14 Details of response withheld (ref 10CFR2 790)  
FURR, B J Carolina Power & Light Co 79/05/10 1p

7907100150 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110084 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907030090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907190608 Responds to IE Bulletin 78-12, 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds" Submits info confirming that Chicago Bridge & Iron Co has provided NRC w/data requested  
UTLEY, E E Carolina Power & Light Co 79/05/27 5pp

7907130091 Ack receipt of 790510 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-14 & 50-325/79-14  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/05/31 1p

7907200167 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907110745 Summary of 790521 meeting w/util, GE & United Engineers & Constructors in Bethesda, MD re results of seismic stress reanalysis in response to IE Bulletin 79-07  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625), 79/06/06 5pp

7907190148 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASD Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 1p

7907120058 Review of piping reanalysis per IE Bulletin 79-07  
\* Operating Reactors Branch 3 (Pre 790625) 79/06/07 3pp

7907060043 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907120052 Responds to util ltrs dtd 790424, 0521, 0522, 0529 & 0604, documenting results of seismic piping stress reanalysis for facility per IE Bulletin 79-07 Finds response satisfactory  
Forwards safety evaluation.  
IPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/07 2pp

7907250150 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp

7907190368 Responds to IE Bulletin 79-01 No stem mounted limit switches in use on safety-related equipment  
UTLEY, E E Carolina Power & Light Co 79/06/12 2pp

7907310218 Summary of 790530 meeting w/util & contractors in Bethesda, MD re status of seismic pipe stress reanalysis per IE Bulletin 79-07 & review of licensee program of identifying & modifying overloaded pipe supports & hangers  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625), 79/06/12 13pp

## DOCKETED ITEMS

7907240400 Act receipt of 790606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-17 & 50-325/79-17  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/15 1p

--7907240413 Responds to NRC 790514 ltr re violations noted in IE Insp Repts 50-324/79-17 & 50-325/79-17 Corrective actions doors made functional, valves opened on sprinkler sys & oil retainer sys being installed  
BANKS, H R Carolina Power & Light Co 79/06/06 8pp

--7907240420 Forwards IE Insp Repts 50-324/79-17 & 50-325/79-17 on 790416-20, notice of violation & notice of deviation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907240429 Notice of violation from insp on 790416-20  
\* Region 2, Atlanta, Office of the Director 79/05/08 1p

--7907240437 Notice of deviation from insp on 790416-20  
\* Region 2, Atlanta, Office of the Director 79/05/08 2pp

--7907240452 IE Insp Repts 50-324/79-17 & 50-325/79-17 on 790416-20 Noncompliance noted nonfunctional fire barriers, sprinkler sys out of svc & fire protection mod not met  
\* Region 2, Atlanta, Office of the Director 79/05/08 12pp

79072020375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120036 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110213 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907310004 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/25 2pp

7907180427 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907310229 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 1p

7907310362 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 1p

907190376 Forwards response to IE Bulletin 79-01, originally omitted as encl to 790612 ltr Response Available in Central Files only  
UTLEY, E E Carolina Power & Light Co 79/07/16 1p

790720230 Discusses completed seismic reanalysis of safety-related piping & supports using acceptable computer code, in response to IE Bulletin 79-07, Pipes discovered to have discrepancies are being modified  
UTLEY, E E Carolina Power & Light Co 79/07/23 23pp

Periodic operating reports & related correspondence

7907170025 Forwards monthly operating rept for June 1979.  
WILLIS, B J Carolina Power & Light Co 79/07/10 1p

907170031 Monthly operating rept for June 1979  
WILLIS, B J Carolina Power & Light Co 79/07/02 9pp.

Reportable occurrences, LERs & related correspondence

79060403 Forwards LER 79-044/03L-0.  
BANKS, H R Carolina Power & Light Co 79/07/03 1p

--7907060409 LER 79-044/03L-0 on 790612 sample pump for drywell atmosphere sampler 2-CAC-ATH-1259 stopped Caused by broken pump drive belt Belt replaced & sys returned to normal  
TOLLISON, A C Carolina Power & Light Co 79/07/03 1p

7907060405 Forwards LER 79-042/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/03 1p

--7907060413 LER 79-042/03L-0 on 790606 standby liquid control concentration discovered at 10% w/3,000 gallons Leakage observed on both 2A & 2B pump suction drain lines Caused by missing endcap on 2A Lines capped & checked for leakage  
TOLLISON, A C Carolina Power & Light Co 79/07/03 2pp

7907090229 Forwards LER 79-029/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/05 1p

--7907090233 LER 79-029/03L-0 on 790627 during insp of pipe supports & hangers, four snubbers found inoperable Two had low fluid levels due to seal leakage, one had loose pump clamp & one snubber missing entirely  
TOLLISON, A C Carolina Power & Light Co 79/07/05 2pp

7907160360 Forwards LER 79-040/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/12 1p

--7907160364 LER 79-040/03L-0 on 790614 chloride intrusion monitor 2-CO-CR24 point 4 would not calibr at high end of scale Caused by defective conductivity cell Cell replaced, monitor tested & returned to svc  
TOLLISON, A C Carolina Power & Light Co 79/07/12 1p

7907160392 Forwards LER 79-050/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/12 1p

--7907160400 LER 79-050/03L-0 on 790619 2A RHR svc water pump uncoupled by mistake after clearance of 2B pump for uncoupling Caused by personnel error Pump recoupled & tested when mistake was discovered Clearance procedure changed  
TOLLISON, A C Carolina Power & Light Co 79/07/12 2pp

7907160371 Forwards LER 79-043/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/13 1p

--7907160381 LER 79-045/03L-0 on 790613 unexplained shift noted in 2-CAC-ATH-1259-2 monitor indicating drywell oxygen concentration Caused by corroded contacts on range switch Switch replaced, monitor calibr & returned to svc  
TOLLISON, A C Carolina Power & Light Co 79/07/13 1p

7907190373 Forwards LER 79-052/01T-0  
BANKS, H R Carolina Power & Light Co 79/07/16 1p

--7907190382 LER 79-052/01T-0 on 790702 support beams for snubbers 2E11-4768326 & 2E11-4968334 were found incapable of carrying calculated loads under worst seismic condition Support beams were reinforced  
TOLLISON, A C Carolina Power & Light Co 79/07/16 2pp

7907190331 Forwards LER 79-051/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/16 1p

--7907190534 LER 79-051/03L-0 on 790620 during normal surveillance of reactor bldg, sample pump for CAC-ATH-1259 drywell atmospheric monitor made loud noises Caused by bad bearings Pump replaced w/new one from stock  
TOLLISON, A C Carolina Power & Light Co 79/07/16 1p

7907230551 Forwards LER 79-049/03L-0.  
BANKS, H R Carolina Power & Light Co 79/07/18 1p

--7907230563 LER 79-049/03L-0 on 790619 drywell oxygen concentration exceeded 4% for approx 4 5-h while containment inerting line was under clearance for repair, Caused by rupture of nitrogen inerting line to reactor bldg  
TOLLISON, A C Carolina Power & Light Co 79/07/18 1p

7907230588 Forwards LER 79-029/03X-1  
BANKS, H R Carolina Power & Light Co 79/07/18 1p

--7907230618 LER 79-029/03X-1 on 790602 during insp per IE Bulletin 79-07, snubbers in core to spray vessel, recirculation pump suction & main steam line discovered inoperable Caused by low fluid level, snubbers aligned & clamps tightened  
TOLLISON, A C Carolina Power & Light Co 79/07/18 2pp.

7907240366 Forwards LER 79-046/03L-0.  
BANKS, H R Carolina Power & Light Co 79/07/19 1p

--7907240371 LER 79-046/03L-0 on 790627 during normal operator surveillance of control panel, noted that conductivity recorder CO-CR2A not printing correctly. Caused by slipping of paint head on drive string. Drive string adjusted. TOLLISON, A C Carolina Power & Light Co 79/07/19 1p

7907300423 Forwards LER 79-056/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/27 4pp

--7907300428 LER 79-056/03L-0 on 790628 large increase in steam jet air injector rod levels & turbine bldg monitor rod levels noticed. Probable cause due to offgas release. Faulty rod replaced & tested satisfactorily. TOLLISON, A C Carolina Power & Light Co 79/07/27 3pp

#### DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

##### J Insurance & indemnity information

7907050336 Forwards Endorsements 34 & 35 to NELIA Policy NF-218  
GRAHAM, W E Carolina Power & Light Co 79/06/26 3pp

7907240321 Forwards Endorsements 31 & 32 to MAELU Policy MF-80  
GRAHAM, W E Carolina Power & Light Co 79/07/16 3pp

##### P Operating license stage documents & correspondence

7907030051 Summary of 790516 meeting w/util, OE & United Engineers & Constructors in Bethesda, MD re results of seismic piping stress reanalysis performed per IE Bulletin 79-07  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/05/21 12pp

7907130054 Notification of 790530 meeting w/util in Bethesda, MD to discuss reanalyses of pipes & supports & proposed fixes for identified deficiencies.  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625) 79/05/30 2pp

7907190297 Notification of 790604 meeting w/util in Bethesda, MD to discuss pipe & support reanalyses, current status of identified deficiencies & provide verification of items discussed at last meeting.  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/06/01 1p

7907180624 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PHRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907310243 Notifies that refund of Class 1 & 2 amend fees is being processed. Waiver for Tech Specs re fire protection is warranted.  
MILLER, W D License Fee Management Branch 79/06/15 1p

7907230335 Summary of 790604 meeting w/util, OE & United Engineers & Const in Bethesda, MD re current status of reanalyses of pipes & supports, mod to be completed & procedures to address deviations from as-built conditions.  
HANNON, J N Operating Reactors Branch 3 (Pre 790625) 79/06/19 4pp.

7907090323 RO on 790625 noted that Tech Specs could cause reactor to operate in less conservative manner than assumed in safety analyses. Plant operating manual provides safety backup.  
STARKEY, R B, ROBINSON, H B. Carolina Power & Light Co 79/06/26 1p.

7907110406 Submits technical description of proposed mods for offgas hydrogen recombiner sys, as requested in NRC 780912 ltr.  
UTLEY, E E Carolina Power & Light Co 79/06/29 6pp

7907060284 Submits Cycle 2 summary startup test rept  
BANKS, H R Carolina Power & Light Co 79/07/03 3pp

7907130379 Submits status of seismic analysis of safety-related piping  
UTLEY, E E Carolina Power & Light Co, 79/07/03 7pp

##### Q Inspection reports, IE Bulletins & correspondence

7907050130 Forwards IE Insp Repts 50-325/79-14 & 50-324/79-14 on 790327-30 Notice of violation withheld (ref 10CFR2 790)  
KENNA, W B. Region 2, Atlanta, Safeguards Branch 79/04/17. 2pp

--7907050155 IE Insp Repts 50-325/79-14 & 50-324/79-14 on 790327-30 Noncompliance noted physical barrier, security plan, lighting & access control Details withheld (ref 10CFR2 790)  
MOORE, D E Region 2, Atlanta, Office of the Director  
TOBIN, W J Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/16 1p

7907020352 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907120598 Forwards IE Insp Repts 50-324/79-16 & 50-325/79-16 on 790410-13 No noncompliance noted.  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp

--7907120560 IE Insp Repts 50-324/79-16 & 50-325/79-16 on 790410-13 No noncompliance noted. Major areas inspected preparation for refueling, start-up after refueling & review of refueling associated procedures.  
JULIAN, C A, GRAHAM, M J, BURNETT, P T Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/27 5pp

7907110314 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907190566 Responds to IE Insp Rept 79-14 Details of response withheld (ref 10CFR2 790)  
FURR, B J Carolina Power & Light Co 79/05/10 1p

7907100150 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110084 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907030090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907190608 Responds to IE Bulletins 78-12, 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds" Submits info confirming that Chicago Bridge & Iron Co has provided NRC w/data requested.  
UTLEY, E E. Carolina Power & Light Co 79/05/29. 5pp

7907130091 Ack receipt of 790510 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-14 & 50-325/79-14  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/05/31 1p

7907200167 Forwards IE Bulletin 79-12, "Short Period Screens at BWR Facilities" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907110745 Summary of 790521 meeting w/util, OE & United Engineers & Constructors in Bethesda, MD re results of seismic stress reanalysis in response to IE Bulletin 79-07.  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625) 79/06/06 5pp.

7907190148 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class 1E Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves)" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 1p.

7907120058 Review of piping reanalysis per IE Bulletin 79-07  
\* Operating Reactors Branch 3 (Pre 790625). 79/06/07. 3pp

7907060043 Forwards IE Info Notice 79-13, "Deficient Procedures" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907120052 Responds to util ltrs dtd 790424, 0521, 0522, 0529 & 0604, documenting results of seismic piping stress reanalysis for facility per IE Bulletin 79-07. Finds response satisfactory. Forwards safety evaluation.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/07 2pp

## DOCKETED ITEMS

7907250150 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp

7907190368 Responds to IE Bulletin 79-01 No stem mounted limit switches in use on safety-related equipment  
UTLEY, E E Carolina Power & Light Co 79/06/12 2pp

7907310218 Summary of 790530 meeting w/util & contractors in Bethesda. MD re status of seismic pipe stress reanalysis per IE Bulletin 79-07 & review of licensee program of identifying & modifying overloaded pipe supports & hangers  
BEVAN, R B Operating Reactors Branch 3 (Pre 790625) 79/06/12 13pp

7907240400 Ack receipt of 790606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-17 & 50-325/79-17  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/15 1p

--7907240413 Responds to NRC 790514 ltr re violations noted in IE Insp Repts 50-324/79-17 & 50-325/79-17. Corrective actions doors made functional, valves opened on sprinkler sys & oil retainer sys being installed  
BANKS, H R Carolina Power & Light Co 79/06/06 8pp

--7907240420 Forwards IE Insp Repts 50-324/79-17 & 50-325/79-17 on 790416-20, notice of violation & notice of deviation.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907240429 Notice of violation from insp on 790416-20  
\* Region 2, Atlanta, Office of the Director. 79/05/08 1p.

--7907240437 Notice of deviation from insp on 790416-20  
\* Region 2, Atlanta, Office of the Director 79/05/08 2pp

--7907240452 IE Insp Repts 50-324/79-17 & 50-325/79-17 on 790416-20 Noncompliance noted nonfunctional fire barriers, sprinkler sys out of svc & fire protection mod not met  
\* Region 2, Atlanta, Office of the Director 79/05/08 12pp

7907020375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120036 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907110213 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

7907310004 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/23 2pp

7907180427 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/28 2pp.

7907310229 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 1p

7907310362 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

7907190576 Forwards response to IE Bulletin 79-01, originally omitted as encl to 790612 ltr Response available in Central Files only  
UTLEY, E E Carolina Power & Light Co 79/07/16 1p

790720230 Discusses completed seismic reanalysis of safety-related piping & supports using acceptable computer code, in response to IE Bulletin 79-07. Pipes discovered to have discrepancies & being modified  
UTLEY, E E Carolina Power & Light Co. 79/07/23 23pp

R Periodic operating reports & related correspondence

7907170025 Forwards monthly operating rept for June 1979  
FURR, B J Carolina Power & Light Co 79/07/10 1p

--7907170031 Monthly operating rept for June 1979  
WILLIS, E Carolina Power & Light Co 79/07/02 9pp

S Reportable occurrences, LERs & related correspondence

7907110543 Forwards LER 78-015/03L-0  
BANKS, H R Carolina Power & Light Co 78/02/23 1p

--7907110549 LER 78-015/03L-0 on 780205 during reactor recirculation pump discharge valve cycle test, valve B32-F031A failed in closed position requiring pump A to be secured Caused by stuck 42 auxiliary contactor Contractor realigned  
\* Carolina Power & Light Co 78/02/23 2pp

7907110470 Forwards LER 78-039/03L-0  
BANKS, H R Carolina Power & Light Co 78/05/12 1p

--7907110477 LER 78-039/03L-0 on 780412 during quarterly HPCI pump flow test, HPCI turbine control valve was inoperable Caused by corrosion inside electro/mechanical/hydraulic actuator preventing pilot valve plunger from operating  
\* Carolina Power & Light Co 78/05/12 3pp

7907050310 Forwards LER 79-036/03L-0  
BANKS, H R Carolina Power & Light Co 79/06/28 1p

--7907050329 LER-79-036/03L-0 on 790602 while performing pipe support insp, snubbers in RHR discharge-to-fuel pool cooling, core spray line-to-vessel & vessel head vent found inoperable Caused by loose nut on hanger belt  
TOLLISON, A C Carolina Power & Light Co 79/06/28 1p

7907060406 Forwards LER 79-023/03X-1  
BANKS, H R Carolina Power & Light Co 79/07/03 1p

--7907060412 LER 79-023/03X-1 on 790429 control rod 10-07 had no indication at notch 47 Caused by switch grounded to prototypic inlet piping probe case Switch unwrapped in fiberglass tape & returned to svc  
TOLLISON, A C Carolina Power & Light Co 79/07/03 1p

7907060408 Forwards LER 79-008/03X-2  
BANKS, H R Carolina Power & Light Co 79/07/03 1p

--7907060416 LER 79-008/03X-2 on 790112 RHR svc water pump 17, Ingersoll-Rand Model 18x13AD, exhibited unacceptable vibration levels Caused by restrictor bushing seizing to shaft Excessive wear noted on impeller hub & shaft sleeve  
TOLLISON, A C Carolina Power & Light Co 79/07/03 2pp

7907190480 Forwards LER 79-029/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/06 1p

--7907190487 LER 79-029/03L-0 on 790609 drywell exhaust backup valve, 1-CAC-V10, would not close during testing of valves after plant mod 79-09B Caused by dirty vent line air restrictor Restrictor cleaned & limit switch lubricated.  
TOLLISON, A C Carolina Power & Light Co. 79/07/06 1p

7907130339 Forwards LER 79-028/03X-1  
BANKS, H R Carolina Power & Light Co 79/07/09 1p

--7907130345 LER 79-028/03X-1 on 790504 during normal startup, operator did not have "full in" or "full out" indication of valves after 22-47 Cause unknown Circuitry checked w/no problem found Isolated event, w/no further action required.  
TOLLISON, A C Carolina Power & Light Co 79/07/09 1p

7907130360 Forwards LER 78-093/03X-1.  
BANKS, H R Carolina Power & Light Co 79/07/09 1p

--7907130363 LER 78-093/03X-1 on 781202 while inserting control rods to decrease reactor power, operator observed that position indication for notch 1B & 2B was inoperable for rod 2-23 Caused by grounding on Switch 4B, Switch covered w/tape  
TOLLISON, A C Carolina Power & Light Co 79/07/09 1p.

7907230315 Forwards LER 79-036/03X-1.  
BANKS, H R Carolina Power & Light Co 79/07/18 1p.



--7907230320 LER 79-036/03X-1 on 790602 six snubbers found inoperable  
Caused by two had loose bolts in clamps & four had low fluid  
level due to leaking seals First two were realigned & bolts  
tightened  
TOLLISON, A C Carolina Power & Light Co 79/07/18 1p

7907240357 Forwards LER 79-045/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/18 1p

--7907240363 LER 79-045/03L-0 on 790622 during normal operator  
surveillance of control panels, CAC-ATH-1263-2 indicated  
drywell oxygen greater than 4% & was erratic Caused by  
corrosion buildup in exhaust check valve Instrument calibr  
TOLLISON, A C Carolina Power & Light Co 79/07/18 2pp

7907230325 Forwards LER 79-025/03L-0  
BANKS, H R Carolina Power & Light Co 79/07/19 1p

--7907230343 LER 79-025/03L-0 on 790622 HPCI torus suction valves for  
each unit not being timed closed in less than 80-s once per  
92 days as required Caused by omission of valves from  
original issue of penetrant test Test revised  
TOLLISON, A C Carolina Power & Light Co 79/07/19 1p

#### DOCKET 50-326 UNIV OF CALIFORNIA AT IRVINE RES REACTOR

##### G. Inspection reports, IE Bulletins & correspondence

7907230390 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI "  
No action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/06/22 1p

7907230765 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/07/06 1p

#### DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

##### A Application/construction stage documents & correspondence

7907160109 Draft memo re licensing strategy for plants w/fuel load  
dates in CV79  
BOYD, R B Division of Project Management 79/03/28 6pp

7907130015 Forwards FR notice, negative declaration & EIA supporting  
issuance of OL W/o negative declaration  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

--7907130019 Notification of issuance of EIA & negative declaration  
supporting issuance of OL  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

--7907130022 EIA supporting issuance of OL  
\* Division of Site Safety & Environmental Analysis 79/05/31  
19pp

7907180650 EIA supporting issuance of OL  
\* Office of Nuclear Reactor Regulation 79/05/31 41pp.

7907110699 Notification of 790614 meeting w/util in Bethesda, MD to  
discuss southern Appalachian region tectonic study  
STAHLER, C R Light Water Reactors Branch 4. 79/06/11 3pp

7907030492 Requests extension to 800101 for const completion. Requires  
addl time for reanalysis of piping sys penetrating steel  
containment vessel for effects of postulated LOCA  
GILLELAND, J E Tennessee Valley Authority 79/06/28 1p

7907060309 Forwards "Southern Appalachian Tectonic Study "  
GILLELAND, J E Tennessee Valley Authority 79/06/28 2pp

--7907060316 "Southern Appalachian Tectonic Study " Oversized maps encl  
SEAY, W H Tennessee Valley Authority. 79/01/31 84pp

7907170124 Forwards "Preliminary Evaluation of Sequoyah Unit 1 Flaw  
Indication" & "Analytical Evaluation of Flaw Indication  
in Unit 1 Reactor Vessel Closure Head "  
MILLS, L M Tennessee Valley Authority 79/07/10 2pp.

--7907170131 "Preliminary Evaluation of Sequoyah Unit 1 Flaw Indication,"  
supplemental rept. prepared by Southwest Research Inst.  
\* Tennessee Valley Authority. 79/02/28. 14pp.

--7907170140 "Analytical Evaluation of Flaw Indication in Unit 1 Reactor  
Vessel Closure Head "  
ROCKELLE, J K Tennessee Valley Authority CER-CGS-79-1  
79/07/10 87pp

7907250324 Forwards Offsite Dose Calculation Manual, Revision 2  
MILLS, L M Tennessee Valley Authority 79/07/17 1p

--7907250331 Offsite Dose Calculation Manual, Revision 2  
\* Tennessee Valley Authority 79/07/31 46pp

7907250306 Forwards "Reactor Bldg Containment Integrated Leak Rate  
Test" performed 790313-16  
MILLS, L M Tennessee Valley Authority 79/07/18 1p

--7907250317 "Reactor Bldg Containment Integrated Leak Rate Test,"  
conducted 790713-16  
\* Tennessee Valley Authority 79/07/18 125pp

##### G Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-058, "Nuclear Incident at  
TMI-Suppl "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 3pp

7907050095 Forwards IE Insp Repts 50-327/79-23 & 50-328/79-12 on  
790410-12 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/05/01 2pp

--7907050103 IE Insp Repts 50-327/79-23 & 50-328/79-12 on 790410-12 No  
noncompliance noted Major areas inspected routine  
safety-related structures, welding, records, followup to  
previous insp findings & licensee-identified item  
VAN DOORN, P K Region 2, Atlanta, Office of the Director  
CONLON, T E Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/01 6pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07. 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New  
Fuel Assemblies " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/10 3pp

7907130356 Forwards IE Insp Rept 50-327/79-22 on 790329-30 & 0406.  
No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support  
Branch 79/05/10 2pp

--7907130359 IE Insp Rept 50-327/79-22 on 790329-30 & 0406 No  
noncompliance noted Major areas inspected thermal expansion  
testing during hot functional testing  
WHITENER, H L, DONAT, T, MARTIN, R D Region 2, Atlanta, Office  
of the Director 79/05/09 4pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22. 3pp

7907240122 Forwards IE Insp Repts 50-327/79-29 & 50-328/79-16 on  
790508-11 No noncompliance noted.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/05/24 2pp

--7907240129 IE Insp Repts 50-327/79-29 & 50-328/79-16 on 790508-11 No  
noncompliance noted Major areas inspected areas of previous  
noncompliance, 10CFR50.55(e) items, response to IE Bulletin  
79-02 & containment penetrations  
MCFARLAND, C R Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/24. 2pp.

7907050105 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Guster Creek Reactor." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 3pp.

## DOCKETED ITEMS

7907260532 Forwards IE Insp Repts 50-327/79-27 & 50-328/79-14 on 790507-11 No noncompliance noted  
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/30 2pp

--7907260538 IE Insp Repts 50-327/79-27 & 50-328/79-14 on 790507-11 No noncompliance noted Major areas inspected liquid & gas monitoring, gaseous filtration sys, resin transfer, HEPA filter storage & tank vol verification  
HILLBAP, W J Region 2, Atlanta, Office of the Director 79/05/30 6pp

7907190207 Responds to IE Bulletin 79-04 Specified Velan swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NSSS sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190196 Responds to IE Bulletin 79-03 No ASMEBA-312 stainless steel piping mfg by Youngstown Welding & Engineering Co has been received for use in safety-related sys.  
GILLELAND, J E Tennessee Valley Authority 79/06/01 2pp.

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/06/06 3pp.

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907250167 Requests that Region 2 measurements can be granted access privileges of "license designated vehicle " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts. " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp.

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/06/28 3pp.

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/11 2pp.

7907200376 Forwards response to IE Bulletin 79-06A & to ACRS recommendations Changes planned re design testing, operation & emergency procedures will be documented in FSAR  
HILLS, L M Tennessee Valley Authority 79/07/12 37pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 3pp

#### 8. Reportable occurrences, LERs & related correspondence

7907090351 Forwards first interim deficiency rept re lack of design consideration for thermal, static & BBE deflections in variable & rigid spring pipe supports  
GILLELAND, J E Tennessee Valley Authority 79/06/21 1p

--7907090369 First interim deficiency rept re lack of design considerations of sum of static, thermal & BBE deflections for rigid & variable spring pipe supports Potentially deficient piping supports reviewed  
\* Tennessee Valley Authority 79/06/21 2pp

7907090316 Forwards final deficiency rept re pressurizer relief piping support  
GILLELAND, J E Tennessee Valley Authority 79/06/22 1p

--7907090318 Final deficiency rept pipe support 1-RCH-93 failed to slide during hot functional testing Caused by failure to lubricate sliding surfaces, resulting in plastic deformation of piping  
Pipe support redesigned  
\* Tennessee Valley Authority 79/06/22 1p

#### DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

#### A Application/construction stage documents & correspondence

7907130015 Forwards FR notice, negative declaration & EIA supporting issuance of OL W/o negative declaration  
BALLARD, R L Environmental Projects Branch 1. 79/05/31 2pp

--7907130019 Notification of issuance of EIA & negative declaration supporting issuance of OL  
BALLARD, R L Environmental Projects Branch 1. 79/05/31 2pp

--7907130022 EIA supporting issuance of OL  
\* Division of Site Safety & Environmental Analysis. 79/05/31 19pp

7907180650 EIA supporting issuance of OL  
\* Office of Nuclear Reactor Regulation 79/05/31. 41pp

7907110699 Notification of 790614 meeting U/util in Bethesda, MD to discuss southern Appalachian region tectonic study  
STAHLER, C R Light Water Reactors Branch 4 79/06/11 3pp

7907060309 Forwards "Southern Appalachian Tectonic Study "  
GILLELAND, J E Tennessee Valley Authority. 79/06/28 2pp

--7907060316 "Southern Appalachian Tectonic Study " Oversized maps encl.  
SEAY, W M Tennessee Valley Authority 79/01/31 84pp

7907250324 Forwards Offsite Dose Calculation Manual, Revision 2  
HILLS, L M Tennessee Valley Authority 79/07/17 1p

--7907250331 Offsite Dose Calculation Manual, Revision 2.  
\* Tennessee Valley Authority. 79/07/31. 46pp.

#### G Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl. "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 3pp.

7907050095 Forwards IE Insp Repts 50-327/79-23 & 50-328/79-12 on 790410-12. No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/01 2pp.

--7907050103 IE Insp Repts 50-327/79-23 & 50-328/79-12 on 790410-12. No noncompliance noted Major areas inspected: routine safety-related structures, welding, records, followup to previous insp findings & licensee-identified item  
VAN DOORN, P. K. Region 2, Atlanta, Office of the Director.  
CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/01. 6pp.

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 3pp

7907240122 Forwards IE Insp Repts 50-327/79-29 & 50-328/79-16 on 790508-11 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

--7907240129 IE Insp Repts 50-327/79-29 & 50-328/79-16 on 790508-11 No noncompliance noted Major areas inspected areas of previous noncompliance, 10CFR50.55(e) items; response to IE Bulletin 79-02 & containment penetrations  
MCFARLAND, C R Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 3pp

7907260332 Forwards IE Insp Repts 50-327/79-27 & 50-328/79-14 on 790507-11 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/30 2pp

--7907260338 IE Insp Repts 50-327/79-27 & 50-328/79-14 on 790507-11 No noncompliance noted Major areas inspected liquid & gas monitoring, gaseous filtration sys, resin transfer, HEPA filter storage & tank vol verification  
MILLBAP, W J Region 2, Atlanta, Office of the Director.  
79/05/30 6pp

7907190207 Responds to IE Bulletin 79-04 Specified Valves swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NBBS sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190196 Responds to IE Bulletin 79-03 No ASME SA-312 stainless steel piping mfg by Youngstown Welding & Engineering Co has been received for use in safety-related sys.  
GILLELAND, J E Tennessee Valley Authority 79/06/01 2pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environment Qualification of Class IE Equipment (Deficiencies in Environment Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys."   
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907250167 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "   
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "   
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 3pp

#### B Reportable occurrences, LERs & related correspondence

7907090351 Forwards first interim deficiency rept re lack of design consideration for thermal, static & SSE deflections in variable & rigid spring pipe supports  
GILLELAND, J E Tennessee Valley Authority 79/06/21 1p

--7907090369 First interim deficiency rept re lack of design considerations of sum of static, thermal & SSE deflections for rigid & variable spring pipe supports Potentially deficient piping supports reviewed  
\* Tennessee Valley Authority 79/06/21 2pp

#### DOCKET 50-329 MIDLAND PLANT, UNIT 1

#### A Application/construction stage documents & correspondence

7905230663 Summary of 790130-31 meeting w/util, Bechtel & B&W in Bethesda, MD re selected outstanding FSAR review matters Forwards list of attendees, draft responses to NRC questions & summary of applicant presentation.  
HOOD, D B Light Water Reactors Branch 4 79/04/23 44pp

7905240952 Summary of 790410-11 meeting w/util, Bechtel Associates & B&W in Bethesda, MD to discuss NRC review of FSAR, Forwards lists of attendees & meeting summaries  
HOOD, D B Light Water Reactors Branch 4 79/04/25 13pp

7907130057 Notification of 790607 site visit w/util in Midland, MI to observe test pits in fill.  
HOOD, D B Light Water Reactors Branch 4 79/06/01 3pp

7907190028 Notification of 790710 meeting w/util in Bethesda, MD to discuss abnormal settlement of fill & structures at site  
HOOD, D B Light Water Reactors Branch 4 79/06/13 2pp

7907240053 Notification of 790618 meeting in Bethesda, MD w/util re status of safety & environ reviews  
HOOD, D B Light Water Reactors Branch 4 79/06/15 2pp

## DOCKETED ITEMS

7907190039 Forwards summary of 790607 site visit to observe test pits in plant area fill  
HOOD, D S Light Water Reactors Branch 4 79/06/21 2pp

--7907190046 Summarizes 790607 site visit in Midland, MI to observe test pits in plant area fill  
GILLEN, D M Geosciences Branch 79/06/14 3pp

7907030428 Submits offer to provide NRC w/steel & concrete test specimens w/protective coating sys presently employed in nuclear facilities  
PUSCHEL, M A Consumers Power Co 79/06/27 3pp

7907300579 Notification of 790719 meeting w/util in Bethesda, MD to discuss tectonic provinces  
HOOD, D S Light Water Reactors Branch 4 79/07/05 3pp

7907110416 Forwards Revision 2 to 790424 responses to 10CFR50.54(f) request re plant fill  
HOWELL, S H Consumers Power Co 79/07/09 19pp.

7907260475 Forwards response to request for addl info re seismic qualification review team data Data concerns transmitter, pressure transmitters inside containment & delta-pressure transmitters inside containment  
HOWELL, S H Consumers Power Co 79/07/20 65pp

#### C Utility Environmental Report (ER), amends & correspondence

7907050306 Forwards Amend 67 to application for CP & DL, consisting of Revision 9 to environ rept Includes addl info requested in WH Regan 790522 & 781011 ltrs, revised matl on water usage & corrections of errors & omissions  
HOWELL, S H Consumers Power Co 79/06/29 2pp

--7907050315 Amend 67 to application for CP & DL, consisting of Revision 9 to environ rept Includes addl info requested in WH Regan 790522 & 781011 ltrs, revised matl on water usage & corrections of errors & omissions  
\* Consumers Power Co 79/06/29 98pp

7907170006 Forwards affidavit re distribution of Amend 67 to application for CP & DL, Revision 9 to environ rept  
BACON, J L Consumers Power Co 79/07/10 4pp

#### G Adjudicatory correspondence

7907180285 Forwards 790501 final deficiency rept & 790427 rept re diesel generator bldg settlement  
GIBBS, M E Isham, Lincoln & Beale 79/05/04 1p.

--7907180305 Interim Deficiency Rept 5 re diesel generator foundations & bldg settlement Caused by erroneous settlement readings. Redesignated instrumentation installed  
\* Consumers Power Co 79/04/27 10pp

7907180810 Second amended notice of deposition of J Falahes, J Bacon, AH Aymond, R Renfrow, L Nute & D Rosso, to be taken on 790530-0601, 04 & 05-07 Deposition concerns issues set forth in 790503 order Certificate of Svc encl  
OLMSTEAD, W J Branch 4 79/05/25 3pp

7907020016 Notification of evidentiary hearing to be held on 790702-27 at NRC Issues of ASLR 790503 prehearing conference order shall be discussed at hearing  
MILLER, M E Atomic Safety and Licensing Board Panel 79/06/12 2pp

7907190682 NRC opposition to Consumers Power Co 790330 motion for summary disposition re ASLR 790104 order, Part II Certificate of Svc encl  
OLMSTEAD, W J Branch 4 79/06/18 5pp

7907190504 Consumers Power Co supplemental memo clarifying facts prior to hearing scheduled to begin on 790702 Certificate of Svc encl  
REYNOLDS, W B, CHARNOFF, G, WEISSARD, A J Shaw, Pittman, Potts, & Troubridge 79/06/26 10pp

7907260131 Forwards HD Thornburg 790625 memo re Ofc of Inspector & Auditor investigation  
OLMSTEAD, W J Branch 4 79/06/26 1p.

--7907260139 Submits findings re M Cherry 781120 ltr to JO Keppler re assigned resident inspector at facility who had been co-opted by licensee inquiry indicated allegation not substantiated Parties should be informed  
THORNBURG, H D Division of Reactor Construction Inspection 79/06/25 1p.

#### H General correspondence

7907050281 Forwards summary of 790529 telex to JM Hendrie re interruption of DL review process  
DEMLOW, D J Michigan, State of 79/03/30 1p

--7907050283 Summarizes 790529 telex to JM Hendrie Requests NRC review assessment of operating schedule before taking action on interrupting review process  
DEMLOW, D J Michigan, State of 79/05/29 1p

7907050569 Opposes const delay & suspension of license application review  
SELBY, J D Consumers Power Co 79/05/29 1p

#### K Utility Final Safety Analysis Report (FSAR) & amends

7907030279 Forwards Amend 66 to CP & DL Oversized drawings of piping & instrumentation for makeup & purification on boron recovery encl Drawings available in Central Files only  
HOWELL, S H Consumers Power Co 79/06/28 2pp

--7907030445 Amend 66 to application for CP & DL, revising various FSAR sections  
HOWELL, S H Consumers Power Co 79/06/28 1p

7907030470 Forwards Amend 66 to application for CPs & DLs & Revision 22 to FSAR  
HOWELL, S H Consumers Power Co 79/06/28 1p

--7907030472 FSAR Revision 22  
\* Consumers Power Co 79/06/28 300pp

7907090366 Forwards Certificate of Svc for Amend 66, FSAR Revision 22, to CP & DL applications  
BACON, J L Consumers Power Co 79/07/02 2pp

#### I Inspection reports, IE Bulletins & correspondence

7907300088 Forwards IE Insp Repts 50-329/79-09 & 50-330/79-09 on 790201-0329. Na noncompliance noted  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/08 2pp

--7907300096 IE Insp Repts 50-329/79-09 & 50-330/79-09 on 790201-0329. Na noncompliance noted Major areas inspected site conditions, vendor supplied electrical penetrations, reactor vessel internal storage & mgt meetings  
COOK, R J, KNOP, R C Region 3, Chicago, Office of the Director. 79/08/07 6pp

7907110702 Responds to IE Bulletin 79-04, "Incorrect Weights for Bulging Check Valves Mfg by Velan Engineering Corp." No valves used at facility.  
HOWELL, S H Consumers Power Co 79/05/17 1p

7907130166 Forwards 790313 B&W rept, "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Responses to IE Bulletins 78-12 & 78-12A"  
HOWELL, S H Consumers Power Co 79/05/22 1p

--7907130175 Forwards "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Responses to IE Bulletins 78-12 & 78-12A" W/o encl  
TAYLOR, J H Babcock & Wilcox Co 79/03/13 2pp

7907110215 Responds to IE Bulletin 79-07 None of methods specified used in listed computer program for seismic analysis of safety-related piping Review of modal results in piping analysis establishes specified spectral methods not used  
HOWELL, S H Consumers Power Co 79/05/24 2pp

7907200307 Forwards IE Bulletin 79-12, "Short Period Scrams at BHR Facilities." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/14 1p

7907240156 Forwards IE Insp Repts 50-329/79-11 & 50-330/79-11 on 790507-08 Na noncompliance noted.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/14 2pp

--7907240164 IE Insp Repts 50-329/79-11 & 50-330/79-11 on 790507-08 noncompliance noted Major areas inspected, damage to control room wiring.  
CREED, J R, DONAHUE, J F., NORELIUS, C E Region 3, Chicago, Office of the Director 79/05/29 6pp.

# DOCKETED ITEMS

151

7907190244 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of AGCO Bolenoid Valves) " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240251 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/07  
1p

7907260102 Forwards IE Insp Repts 50-329/79-07 & 50-330/79-07 on 790426-27 No noncompliance noted  
DAVIS, A D Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/07 2pp

--7907260196 IE Insp Repts 50-329/79-07 & 50-330/79-07 on 790426-27 No noncompliance noted Major areas inspected environmental protection requirements, including mgt controls & GC of analytical measurements  
GEBMANN, M J, ESSIO, T H Region 3, Chicago, Office of the Director, 79/06/08 6pp

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020249 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/11  
1p.

7907300331 Responds to IE Bulletin 79-09 GC Type AK-2 circuit breakers are only used in control rod drive control sys Preventive maint procedure A has been entered in master procedure index. Procedure will be performed at 6-month intervals  
HOWELL, S H Consumers Power Co, 79/06/15 1p

7907020421 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/20  
1p

7907120221 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/21  
1p

7907090327 Responds to FOIA request for documents re IE Bulletin 79-12, 12A & 12B & info on atypical weld matl at facility  
Forwards FBAR "Weld Matl Rept, CHL Nuclear Co 1979, Vols 1-4, " & responses to NRC questions re Midland facility  
FELTON, J M Division of Rules and Records 79/06/22 36pp

7907130113 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/25  
1p.

7907060308 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/26  
1p

7907060472 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/27  
1p

7907180405 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130240 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/02  
1p.

7907310331 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310407 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260174 Notifies that written responses to IE Bulletin 79-15 Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/18  
1p

7907260351 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/18  
1p

7907250227 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/20  
1p

## R Periodic operating reports & related correspondence

7907020256 Forwards for May 1979 Bechtel nonconformance repts & rept log, quality audit findings, quality action requests, mgt corrective action repts, B&W repts of nonconformity & util nonconformance, audit & action repts  
HOWELL, S H Consumers Power Co 79/06/25 500pp

7907270248 Forwards Bechtel nonconformance repts, quality action requests, mgt corrective action repts, B&W nonconformance repts, util nonconformance repts & audit findings  
MCDOWELL, S H Consumers Power Co 79/07/25 550pp

## S Reportable occurrences, LERs & related correspondence

7907050243 Interim rept on status of component qualification test documentation re-review Initial reviews indicate discrepancies may exist similar to those found in procurements made by Bechtel Addl info will be submitted  
HOWELL, S H Consumers Power Co 79/03/04 2pp

7907100604 Forwards Interim Deficiency Rept & re settlement of diesel generator foundations & bldg due to landfill insufficient compaction in plant area fill  
HOWELL, S H Consumers Power Co 79/06/25 2pp

--7907100604 Interim Deficiency Rept & re settlement of diesel generator foundations & bldg due to insufficient compaction in plant area fill Prepared by Bechtel Associates  
\* Consumers Power Co 79/06/11 96pp

7907100527 Submits interim deficiency rept re component qualification test documentation re-review by Bechtel Further rept will be sent by 790910  
HOWELL, S H Consumers Power Co 79/07/06 2pp

--7907100538 Interim Deficiency Rept 4 re seismic & environ component qualification Forwards 790608 qualification test status rept Revision B, prepared by Bechtel  
DART, C Consumers Power Co 79/01/05 41pp

7907250325 Forwards Interim Deficiency Rept 2 re discrepancies in soldered components of J201 main control panel  
HOWELL, S D Consumers Power Co 79/07/20 1p

--7907250329 Interim Deficiency Rept 2 during field insp of engineered safety features actuation sys, status display light modules revealed discrepancies in soldered wire connections Caused by lack of insp plan in QA program  
\* Bechtel Associates Professional Corp 79/07/19 3pp

## T Hearing transcripts on non-environmental matters

7907130085 Transcript of 790514 deposition of P Oreffice Pp 1-75  
OREFFICE, P Dow Chemical Co 79/05/14 76pp

7907130093 Transcript of 790514 deposition of DA Durand Pp 1-120  
NIRAND, D A Dow Chemical Co 79/05/14 121pp

7907180247 Transcript of 790514 deposition of JF Hanes Pp 1-76  
HANES, J F Dow Chemical Co 79/05/14 77pp

7907130102 Transcript of 790522 deposition of JQ Temple Pp 1-166  
TEMPLE, J Q Dow Chemical Co 79/05/22 167pp

7907110652 Transcript of 790523 deposition of RR Renfrow in Atlanta, GA Pp 1-220.  
RENFROW, R R Affiliation Unknown 79/05/23 221pp

## DOCKETED ITEMS

7907190039 Forwards summary of 790607 site visit to observe test pits in plant area fill  
HOOD, D B Light Water Reactors Branch 4 79/06/21 2pp

--7907190046 Summarizes 790607 site visit in Midland, MI to observe test pits in plant area fill  
GILLEN, D M Geosciences Branch 79/06/14 3pp

7907030428 Submits offer to provide NRC w/steel & concrete test specimens w/protective coating sys presently employed in nuclear facilities  
PUSCHEL, M A Consumers Power Co 79/06/27 3pp

7907300579 Notification of 790719 meeting w/util in Bethesda, MD to discuss tectonic provinces  
HOOD, D B Light Water Reactors Branch 4 79/07/05 3pp

7907110416 Forwards Revision 2 to 790424 responses to 10CFR50.54(f) request re plant fill  
HOWELL, S H Consumers Power Co 79/07/09 19pp

7907260475 Forwards response to request for addl info re seismic qualification review team data Data concerns transmitter, pressure transmitters inside containment & delta-pressure transmitters inside containment  
HOWELL, S H Consumers Power Co 79/07/20 65pp

#### C Utility Environmental Report (ER), amends & correspondence

7907050306 Forwards Amend 67 to application for CP & DL, consisting of Revision 9 to environ rept Includes addl info requested in WH Regan 790522 & 791011 ltrs, revised matl on water usage & corrections of errors & omissions  
HOWELL, S H Consumers Power Co 79/06/29 2pp

--7907050315 Amend 67 to application for CP & DL, consisting of Revision 9 to environ rept Includes addl info requested in WH Regan 790522 & 791011 ltrs, revised matl on water usage & corrections of errors & omissions  
\* Consumers Power Co 79/06/29 98pp

7907170006 Forwards affidavit re distribution of Amend 67 to application for CP & DL, Revision 9 to environ rept  
BACON, J L Consumers Power Co 79/07/10 4pp.

#### G Adjudicatory correspondence

7907180285 Forwards 790501 final deficiency rept & 790427 rept re diesel generator bldg settlement  
QIBBS, M E Isham, Lincoln & Beale 79/05/04 1p

--7907180305 Interim Deficiency Rept 3 re diesel generator foundations & bldg settlement Caused by erroneous settlement readings  
Redesigned instrumentation installed  
\* Consumers Power Co 79/04/27 10pp

07180810 Second amended notice of deposition of J Falahee, J Bacon, AH Aymond, R Renfrow, L Nute & D Rosso, to be taken on 790530-0601, 04 & 05-07 Deposition concerns issues set forth in 790503 order Certificate of Svc encl.  
OLMSTEAD, W J Branch 4 79/05/25 3pp

7907020016 Notification of evidentiary hearing to be held on 790702-27 at NRC issues of ASLB 790503 prehearing conference order shall be discussed at hearing.  
HILLER, M E Atomic Safety and Licensing Board Panel 79/06/12 2pp.

7907190682 NRC opposition to Consumers Power Co 790330 motion for summary disposition re ASLB 790104 order, Part II Certificate of Svc encl  
OLMSTEAD, W J Branch 4. 79/06/15 5pp

7907190504 Consumers Power Co supplemental memo clarifying facts prior to hearing scheduled to begin on 790702 Certificate of Svc encl  
REYNOLDS, W B, CHARNOFF, G., WEISBARD, A J. Shaw, Pittman, Potts, & Trowbridge 79/06/26 10pp

7907260131 Forwards HD Thurnburg 790625 memo re Ofc of Inspector & Auditor investigation.  
OLMSTEAD, W J Branch 4 79/06/26 1p.

7907260139 Submits findings re M Cherry 791120 ltr to JO Keppler re assigned resident inspector at facility who had been co-opted by licensee inquiry indicated allegation not substantiated. Parties should be informed  
THORNBURG, H B. Division of Reactor Construction Inspection 79/06/25 1p.

#### H General correspondence

7907050281 Forwards summary of 790529 telex to JM Hendrie re interruption of OL review process  
DEMLON, D J Michigan, State of 79/03/30 1p

--7907050283 Summarizes 790529 telex to JM Hendrie Requests NRC review assessment of operating schedule before taking action on interrupting review process  
DEMLON, D J Michigan, State of 79/05/29 1p

7907050569 Opposes const delay & suspension of license application review  
SELBY, J D Consumers Power Co 79/05/29 1p

#### K Utility Final Safety Analysis Report (FSAR) & amends

7907030279 Forwards Amend 66 to CP & DL Oversized drawings of piping & instrumentation for makeup & purification on boron recovery encl Drawings available in Central Files only  
HOWELL, S H Consumers Power Co 79/06/28 2pp

--7907030445 Amend 66 to application for CP & DL, revising various FSAR sections  
HOWELL, S H Consumers Power Co 79/06/28 1p

7907030470 Forwards Amend 66 to application for CPs & DLs & Revision 22 to FSAR  
HOWELL, S H Consumers Power Co 79/06/28 1p

--7907030472 FSAR Revision 22  
\* Consumers Power Co 79/06/28 300pp

7907090366 Forwards Certificate of Svc for Amend 66, FSAR Revision 22, to CP & DL applications  
BACON, J L Consumers Power Co 79/07/02 2pp

#### Q Inspection reports, IE Bulletins & correspondence

7907300088 Forwards IE Insp Repts 50-329/79-09 & 50-330/79-09 on 790201-0329 No noncompliance noted  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/08 2pp

--7907300096 IE Insp Repts 50-329/79-09 & 50-330/79-09 on 790201-0329 No noncompliance noted Major areas inspected, site conditions, vendor supplied electrical penetrations, reactor vessel internal storage & mgt meetings  
COOK, R J, KNOP, R C Region 3, Chicago, Office of the Director 79/05/07 6pp

7907110702 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Valen Engineering Corp " No valves used at facility  
HOWELL, S H Consumers Power Co 79/05/17 1p

7907130166 Forwards 790313 B&W rept, "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Responses to IE Bulletins 78-12 & 78-12A "  
HOWELL, S H Consumers Power Co 79/05/22 1p

--7907130175 Forwards "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Responses to IE Bulletins 78-12 & 78-12A " W/o encl  
TAYLOR, J H Babcock & Wilcox Co 79/03/13 2pp

7907110215 Responds to IE Bulletin 79-07 None of methods specified are used in listed computer program for seismic analysis of safety-related piping Review of modal results in piping analysis establishes specified spectral methods not used  
HOWELL, S H Consumers Power Co 79/05/24 2pp

7907200307 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907240156 Forwards IE Insp Repts 50-329/79-11 & 50-330/79-11 on 790507-08 No noncompliance noted  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/06/01 2pp.

--7907240164 IE Insp Repts 50-329/79-11 & 50-330/79-11 on 790507-08 No noncompliance noted Major areas inspected, damage to control room wiring  
CREED, J R, DONAHUE, J F., NORELIVS, C E Region 3, Chicago, Office of the Director, 79/05/29 6pp

7907190244 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240251 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907260182 Forwards IE Insp Repts 50-329/79-07 & 50-330/79-07 on 790426-27 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/07 2pp

--7907260196 IE Insp Repts 50-329/79-07 & 50-330/79-07 on 790426-27 No noncompliance noted Major areas inspected environmental protection requirements, including mgt controls & QC of analytical measurements  
DESTMANN, M J, ESSIG, T H Region 3, Chicago, Office of the Director 79/06/05 6pp

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020249 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907000531 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers are only used in control rod drive control sys Preventive maint procedure A has been entered in master procedure index Procedure will be performed at 6-month intervals  
HOWELL, S H Consumers Power Co 79/06/15 1p

7907020421 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120221 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907090327 Responds to FOIA request for documents re IE Bulletins 78-12, 12A & 12B & info on atypical weld matl at facility  
Forwards FBAR "Weld Matl Rept, CBI Nuclear Co 1979, Vols 1-4, " & responses to NRC questions re Midland facility.  
FELTON, J M Division of Rules and Records 79/06/22 36pp

7907130113 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060308 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p.

7907050472 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p.

7907180405 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p.

7907130260 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p.

7907310331 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPLER, J G. Region 3, Chicago, Office of the Director. 79/07/11. 1p

7907310407 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260174 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260331 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250227 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### R Periodic operating reports & related correspondence

7907020256 Forwards for May 1979 Bechtel nonconformance repts & rept log, quality audit findings, quality action requests, mgt corrective action repts, B&W repts of nonconformity & util nonconformance, audit & action repts  
HOWELL, S H Consumers Power Co 79/06/25 500pp

7907270248 Forwards Bechtel nonconformance repts, quality action requests, mgt corrective action repts, B&W nonconformance repts, util nonconformance repts & audit findings  
HOWELL, S H Consumers Power Co 79/07/25 550pp

#### S Reportable occurrences, IERs & related correspondence

7907050243 Interim rept on status of component qualification test documentation re-review Initial reviews indicate discrepancies may exist similar to those found in procurements made by Bechtel Addl info will be submitted  
HOWELL, S H Consumers Power Co 79/03/04 2pp

7907100604 Forwards Interim Deficiency Rept & re settlement of diesel generator foundations & bldg due to landfill insufficient compaction in plant area fill  
HOWELL, S H Consumers Power Co 79/06/25 2pp

--7907100606 Interim Deficiency Rept & re settlement of diesel generator foundations & bldg due to insufficient compaction in plant area fill Prepared by Bechtel Associates  
\* Consumers Power Co 79/06/11 96pp

7907100527 Submits interim deficiency rept re component qualification test documentation re-review by Bechtel Further rept will be sent by 790910  
HOWELL, S H Consumers Power Co 79/07/06 2pp

--7907100538 Interim Deficiency Rept 4 re seismic & environ component qualification, Forwards 790608 qualification test status rept Revision 8, prepared by Bechtel  
DART, C Consumers Power Co 79/01/05 41pp

7907250325 Forwards Interim Deficiency Rept 2 re discrepancies in soldered components of J201 main control panel  
HOWELL, S D Consumers Power Co 79/07/20 1p

--7907250329 Interim Deficiency Rept 2 during field insp of engineered safety features actuation sys, status display light modules revealed discrepancies in soldered wire connections Caused by lack of insp plan in QA program  
\* Bechtel Associates Professional Corp 79/07/19 3pp

#### T Hearing transcripts on non-anthrust matters

7907130085 Transcript of 790514 deposition of P Orefice Pp 1-75  
OREFFICE, P. Dow Chemical Co 79/05/14 76pp

7907130093 Transcript of 790514 deposition of DA Durand Pp 1-120  
DURAND, D. A Dow Chemical Co 79/05/14 121pp

7907180247 Transcript of 790514 deposition of JF Hanes, Pp 1-76  
HANES, J. F. Dow Chemical Co. 79/05/14. 77pp

7907130102 Transcript of 790522 deposition of JB Temple Pp 1-166  
TEMPLE, J G Dow Chemical Co 79/05/22 167pp

7907110652 Transcript of 790523 deposition of RR Renfrow in Atlanta, GA Pp 1-220.  
RENFROW, R. R. Affiliation Unknown 79/05/23 221pp.

## DOCKETED ITEMS

7907110580 Deposition of RR Renfrow on 790404 in Atlanta, GA Pp 221-377  
RENFWO, R R Isham, Lincoln & Beale 79/06/04 156pp

7907130076 Transcript of 790605 deposition of LF Nute Pp 205-444  
NUTE, L F Dow Chemical Co 79/06/05 239pp

7907130069 Transcript of 790606 deposition of DJ Rosso Pp 1-189  
ROSSO, D J Dow Chemical Co 79/06/06 190pp

7907130184 Transcript of 790605 deposition of LF Nute Pp 445-546  
NUTE, L F Dow Chemical Co 79/06/06 101pp

7907180268 Transcripts of 790607 deposition of DJ Rosso Pp 190-324  
ROSSO, D J Dow Chemical Co 79/06/07 134pp

7907120412 Transcript of 790702 hearing in Bethesda, MD Pp 50, 172-  
50, 372  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing Board  
Panel 79/07/02 201pp

7907120364 Transcript of 790703 hearing in Bethesda, MD Pp 50, 373-  
50, 607  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/03 235pp

7907160138 Transcript of 790705 hearing in Bethesda, MD Pp 50, 608-  
50, 837  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/05 230pp

7907230540 Transcript of 790706 hearing in Bethesda, MD Pp 50, 838-  
51, 032  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/06 194pp

7907120380 Transcript of 790709 hearing in Bethesda, MD Pp 51, 033-  
51, 246  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/09 214pp

7907160151 Transcript of 790710 hearing in Bethesda, MD Pp 51, 247-  
51, 524 Supporting documentation encl  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/10 487pp

7907190606 Transcript of 790711 hearing in Bethesda, MD Pp 51, 535-  
51, 808  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/11 334pp

7907190594 Transcript of 790712 hearing in Bethesda, MD Pp 51, 809-  
52, 055  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/12 247pp

7907190553 Transcript of 790713 hearing in Bethesda, MD Pp 52, 056-  
52, 225  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/13 90pp

7907230592 Transcript of 790716 hearing in Bethesda, MD Pp 52, 227-  
52, 469  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/16 243pp

7907230526 Transcript of 790717 hearing in Bethesda, MD Pp 52, 470-  
52, 718  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/17 249pp

7907230574 Transcript of 790718 hearing in Bethesda, MD Pp 52, 719-  
52, 960  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/18 242pp

7907270321 Transcript of 790719 hearing in Bethesda, MD Pp 52, 961-  
53, 243  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/19 283pp

7907280174 Transcript of 790720 hearing in Bethesda, MD Pp 53, 244-  
53, 409  
MILLER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/20 166pp

7300153 Transcript of 790723 hearing in Bethesda, MD Pp 53, 408-  
501  
LER, M E, LEEDS, J V, LUEBKE, E. Atomic Safety and Licensing  
Board Panel 79/07/23 194pp

## DOCKET 50-320 MIDLAND PLANT, UNIT 2

## A Application/construction stage documents &amp; correspondence

7905230663 Summary of 790130-31 meeting w/uttl. Bechtel & B&W  
in Bethesda, MD re selected outstanding FBAR review matters  
Forwards list of attendees, draft responses to NRC  
questions & summary of applicant presentation  
HOOD, D S Light Water Reactors Branch 4 79/04/23 44pp

7905240952 Summary of 790410-11 meeting w/uttl. Bechtel  
Associates & B&W in Bethesda, MD to discuss NRC review of  
FBAR Forwards lists of attendees & meeting summaries  
HOOD, D S Light Water Reactors Branch 4 79/04/25 13pp

7907130057 Notification of 790607 site visit w/uttl in Midland, MI to  
observe test pits in fill  
HOOD, D S Light Water Reactors Branch 4 79/06/01 3pp

7907190028 Notification of 790710 meeting w/uttl in Bethesda, MD to  
discuss abnormal settlement of fill & structures at site  
HOOD, D S Light Water Reactors Branch 4 79/06/13 2pp

7907240053 Notification of 790618 meeting in Bethesda, MD w/uttl re  
status of safety & environ reviews  
HOOD, D S Light Water Reactors Branch 4 79/06/15 2pp

7907190039 Forwards summary of 790607 site visit to observe test pits  
in plant area fill  
HOOD, D S Light Water Reactors Branch 4 79/06/21 2pp

--7907190046 Summarizes 790607 site visit in Midland, MI to observe test  
pits in plant area fill  
GILLEN, D M Geosciences Branch 79/06/14 3pp

7907300579 Notification of 790719 meeting w/uttl in Bethesda, MD to  
discuss tectonic provinces  
HOOD, D S Light Water Reactors Branch 4 79/07/05 3pp

7907110416 Forwards Revision 2 to 790424 responses to 10CFR50.54(f)  
request re plant fill.  
HOWELL, S H Consumers Power Co 79/07/09 19pp

7907260475 Forwards response to request for addl info re seismic  
qualification review team data. Data concerns transmitter,  
pressure transmitters inside containment & delta-pressure  
transmitters inside containment  
HOWELL, S H Consumers Power Co 79/07/20 65pp

## C Utility Environmental Report (ER), amends &amp; correspondence

7907050306 Forwards Amend 67 to application for CP & DL, consisting of  
Revision 9 to environ rept. Includes addl info requested in  
WH Regan 790522 & 781011 ltrs, revised matl on water usage  
& corrections of errors & omissions  
HOWELL, S H Consumers Power Co 79/06/29 2pp

--7907050315 Amend 67 to application for CP & DL, consisting of Revision  
9 to environ rept. Includes addl info requested in WH Regan  
790522 & 781011 ltrs, revised matl on water usage &  
corrections of errors & omissions.  
\* Consumers Power Co 79/06/29 98pp

7907170006 Forwards affidavit re distribution of Amend 67 to  
application for CP & DL, Revision 9 to environ rept.  
BACON, J L Consumers Power Co 79/07/10 4pp

## G Adjudicatory correspondence

7907180285 Forwards 790501 final deficiency rept & 790427 rept re  
diesel generator bldg settlement  
GIBBS, M E Isham, Lincoln & Beale, 79/05/04 1p.

--7907180305 Interim Deficiency Rept 5 re diesel generator foundations  
& bldg settlement. Caused by erroneous settlement readings.  
Redesigned instrumentation installed  
\* Consumers Power Co 79/04/27 10pp.

7907180810 Second amended notice of deposition of J Falahee, J Bacon, AH  
Aymond, R Renfrow, L Nute & D Rosso, to be taken on  
790530-0601, 04 & 05-07. Deposition concerns issues set  
forth in 790503 order. Certificate of Svc encl  
OLMSTEAD, W J Branch 4, 79/05/25 3pp

7907020016 Notification of evidentiary hearing to be held on 790702-27  
at NRC. Issues of ASLB 790503 prehearing conference order  
shall be discussed at hearing.  
MILLER, M E. Atomic Safety and Licensing Board Panel, 79/06/12  
2pp.



7907190482 NRC opposition to Consumers Power Co 790330 motion for summary disposition re ASLB 790104 order, Part II Certificate of Svc encl  
OLMSTEAD, W J Branch 4 79/06/15 5pp

7907190504 Consumers Power Co supplemental memo clarifying facts prior to hearing scheduled to begin on 790702 Certificate of Svc encl  
REYNOLDS, W B, CHARNOFF, G, WEISBARD, A J Shaw, Pittman, Potts, & Troubridge 79/06/26 10pp

7907260131 Forwards HD Thornburg 790625 memo re Ofc of Inspector & Auditor investigation  
OLMSTEAD, W J Branch 4 79/06/26 1p

--7907260139 Submits findings re M Cherry 781120 ltr to JO Keppler re assigned resident inspector at facility who had been co-opted by licensee Inquiry indicated allegation not substantiated Parties should be informed  
THORNBURG, H D Division of Reactor Construction Inspection 79/06/25 1p

#### H General correspondence

7907050281 Forwards summary of 790529 telex to JM Hendrie re interruption of OL review process  
DEMLOW, D J Michigan, State of 79/03/30 1p.

--7907050283 Summarizes 790529 telex to JM Hendrie Requests NRC review assessment of operating schedule before taking action on interrupting review process  
DEMLOW, D J Michigan, State of 79/05/29 1p

7907050569 Opposes const delay & suspension of license application review.  
SELBY, J D Consumers Power Co. 79/05/29 1p

#### K Utility Final Safety Analysis Report (FSAR) & amends

7907030279 Forwards Amend 66 to CP & DL Oversized drawings of piping & instrumentation for makeup & purification on boron recovery encl Drawings available in Central Files only  
HOWELL, S H Consumers Power Co 79/06/28 2pp.

--7907030445 Amend 66 to application for CP & DL, revising various FSAR sections  
HOWELL, S H Consumers Power Co 79/06/28 1p

7907030470 Forwards Amend 66 to application for CPs & DLs & Revision 22 to FSAR  
HOWELL, S H Consumers Power Co 79/06/28 1p.

--7907030472 FSAR Revision 22  
\* Consumers Power Co 79/06/28 300pp.

7907090366 Forwards Certificate of Svc for Amend 66, FSAR Revision 22, to CP & DL applications  
BACON, J L Consumers Power Co 79/07/02 2pp.

#### P Operating license stage documents & correspondence

7907030428 Submits offer to provide NRC w/steel & concrete test specimens coated w/protective coating sys presently employed in nuclear facilities.  
PUSCHEL, H A Consumers Power Co 79/06/27 3pp.

#### Q Inspection reports, IE Bulletins & correspondence

7907300088 Forwards IE Insp Repts 50-329/79-09 & 50-330/79-09 on 790201-0329 No noncompliance noted.  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/08 2pp

--7907300096 IE Insp Repts 50-329/79-09 & 50-330/79-09 on 790201-0329 No noncompliance noted Major areas inspected, site conditions, vendor supplied electrical penetrations, reactor vessel internal storage & mgt meetings  
COOK, R. J., KNOP, R C Region 3, Chicago, Office of the Director 79/05/07 6pp.

7907110702 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." No valves used at Facility.  
HOWELL, S H Consumers Power Co. 79/05/17 1p

7907130166 Forwards 790313 B&W rept, "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Responses to IE Bulletins 78-12 & 78-12A"  
HOWELL, S H Consumers Power Co 79/05/22 1p

--7907130175 Forwards "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Responses to IE Bulletins 78-12 & 78-12A" W/o encl  
TAYLOR, J H Babcock & Wilcox Co 79/03/13 2pp

7907110215 Responds to IE Bulletin 79-07 None of methods specified are used in listed computer program for seismic analysis of safety-related piping Review of modal results in piping analysis establishes specified spectral methods not used  
HOWELL, S H Consumers Power Co 79/05/24 2pp

7907200307 Forwards IE Bulletin 79-12, "Short Period Seisms at BWR Facilities" No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907240156 Forwards IE Insp Repts 50-329/79-11 & 50-330/79-11 on 790507-08 No noncompliance noted.  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/01 2pp

--7907240164 IE Insp Repts 50-329/79-11 & 50-330/79-11 on 790507-08 No noncompliance noted Major areas inspected damage to control room wiring  
CREED, J. R., DONAHUE, J F, NORELIUS, C E Region 3, Chicago, Office of the Director 79/05/29 6pp

7907190244 Forwards suppl IE Bulletin 79-01A, "Environment Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/06 1p.

7907240251 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/07 1p

7907260182 Forwards IE Insp Repts 50-329/79-07 & 50-330/79-07 on 790426-27 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/07 2pp

--7907260196 IE Insp Repts 50-329/79-07 & 50-330/79-07 on 790426-27 No noncompliance noted Major areas inspected environmental protection requirements, including mgt controls & QC of analytical measurements  
OESTMANN, H J, EBBIG, T H Region 3, Chicago, Office of the Director 79/06/05 6pp

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils.  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020249 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/11 1p

7907300531 Responds to IE Bulletin 79-09, OE Type AK-2 circuit breakers are only used in control rod drive control sys Preventive maint procedure A has been entered in master procedure index. Procedure will be performed at 6-month intervals.  
HOWELL, S H Consumers Power Co 79/06/13 1p.

7907020421 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/20 1p.

7907120221 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/21 1p.

7907090327 Responds to FOIA request for documents re IE Bulletins 78-12, 12A & 12B & info re atypical weld matl at facility Forwards FSAR "Weld Matl Rept, CB1 Nuclear Co 1979, Vols 1-4," & responses to NRC questions re Midland facility.  
FELTON, J. M. Division of Rules and Records 79/06/22 36pp.

## DOCKETED ITEMS

7907130113 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060308 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050472 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907180405 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130260 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907310331 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310407 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260174 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260351 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250227 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### R Periodic operating reports & related correspondence

7907020256 Forwards for May 1979, Bechtel nonconformance repts & rept log, quality audit findings, quality action requests, mgt corrective action repts, B&W repts of nonconformity & util nonconformance, audit & action repts  
HOWELL, B H Consumers Power Co 79/06/25 500pp

7907270248 Forwards Bechtel nonconformance repts, quality action requests, mgt corrective action repts, B&W nonconformance repts, util nonconformance repts & audit findings  
MCADOWELL, S H Consumers Power Co 79/07/23 550pp

#### B Reportable occurrences, LERS & related correspondence

7907050243 Interim rept on status of component qualification test documentation re-review. Initial reviews indicate discrepancies may exist similar to those found in procurements made by Bechtel. Addl info will be submitted  
HOWELL, B H Consumers Power Co 79/03/04 2pp

7907100604 Forwards Interim Deficiency Rept & re settlement of diesel generator foundations & bldg due to landfill insufficient compaction in plant area fill  
HOWELL, B H Consumers Power Co. 79/06/25 2pp

--7907100606 Interim Deficiency Rept & re settlement of diesel generator foundations & bldg due to insufficient compaction in plant area fill Prepared by Bechtel Associates  
\* Consumers Power Co. 79/06/11 96pp

7907100527 Submits interim deficiency rept re component qualification test documentation re-review by Bechtel. Further rept will be sent by 790910  
HOWELL, B H Consumers Power Co. 79/07/06 2pp

--7907100538 Interim Deficiency Rept 4 re seismic & environ component qualification Forwards 790606 qualification test status rept Revision B, prepared by Bechtel  
DART, C. Consumers Power Co 79/01/05 41pp

7907250325 Forwards Interim Deficiency Rept 2 re discrepancies in soldered components of J201 main control panel  
HOWELL, B H Consumers Power Co 79/07/20 1p

--7907250327 Interim Deficiency Rept 2 during field insp of engineered safety features actuation sys, status display light modules revealed discrepancies in soldered wire connections Caused by lack of insp plan in QA program  
\* Bechtel Associates Professional Corp 79/07/19 3pp

#### T Hearing transcripts on non-antitrust matters

7907130085 Transcript of 790514 deposition of P Greffice Pp 1-75  
GREFFICE, P Dow Chemical Co 79/05/14 76pp

7907130093 Transcript of 790514 deposition of DA Durand Pp 1-120  
DURAND, D A Dow Chemical Co 79/05/14 121pp

7907180247 Transcript of 790514 deposition of JF Hanes Pp 1-76  
HANES, J F Dow Chemical Co 79/05/14 77pp

7907130102 Transcript of 790522 deposition of JO Temple Pp 1-166  
TEMPLE, J O Dow Chemical Co 79/05/22 167pp

7907110692 Transcript of 790523 deposition of RR Renfrow in Atlanta, GA Pp 1-220  
RENFROW, R R Affiliation Unknown 79/05/23 221pp

7907110580 Deposition of RR Renfrow on 790604 in Atlanta, GA Pp 221-377  
RENFROW, R R Isham, Lincoln & Seale 79/06/04 156pp.

7907130076 Transcript of 790605 deposition of LF Nute Pp 205-444  
NUTE, L F Dow Chemical Co 79/06/05 239pp

7907130069 Transcript of 790606 deposition of DJ Rosso Pp 1-189  
ROSSO, D J Dow Chemical Co 79/06/06 190pp

7907130184 Transcript of 790605 deposition of LF Nute Pp 445-546.  
NUTE, L F Dow Chemical Co 79/06/06 101pp

7907180248 Transcripts of 790607 deposition of DJ Rosso Pp 190-324  
ROSSO, D J Dow Chemical Co 79/06/07 134pp

7907120412 Transcript of 790702 hearing in Bethesda, MD Pp 50,172-50,372  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel. 79/07/02 201pp

7907120364 Transcript of 790703 hearing in Bethesda, MD Pp 50,373-50,607  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/03 235pp

7907160138 Transcript of 790705 hearing in Bethesda, MD Pp 50,608-50,837  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/05 230pp

7907230540 Transcript of 790706 hearing in Bethesda, MD Pp 50,838-51,032  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/06 194pp

7907120380 Transcript of 790709 hearing in Bethesda, MD Pp 51,033-51,246  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/09 214pp

7907160151 Transcript of 790710 hearing in Bethesda, MD Pp 51,247-51,534 Supporting documentation encl  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/10 487pp

7907190606 Transcript of 790711 hearing in Bethesda, MD Pp 51,535-51,808  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/11 334pp.

7907190594 Transcript of 790712 hearing in Bethesda, MD Pp 51,809-52,055  
MILLER, M E, LEEDS, J V, LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/12 247pp

7907190853 Transcript of 790713 hearing in Bethesda, MD Pp 52, 056-52, 225  
MILLER, M E , LEEDS, J V , LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/13 90pp

7907230592 Transcript of 790716 hearing in Bethesda, MD Pp 52, 227-52, 449  
MILLER, M E , LEEDS, E A , LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/16 243pp

7907230526 Transcript of 790717 hearing in Bethesda, MD Pp 52, 470-52, 718  
MILLER, M E , LEEDS, J V , LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/17 249pp

7907230574 Transcript of 790718 hearing in Bethesda, MD Pp 52, 719-52, 760  
MILLER, M E , LEEDS, J V , LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/18 242pp

7907270321 Transcript of 790719 hearing in Bethesda, MD Pp 52, 961-53, 243  
MILLER, M E , LEEDS, J V , LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/19 283pp

7907250174 Transcript of 790720 hearing in Bethesda, MD Pp 53, 244-53, 409  
MILLER, M E , LEEDS, J V , LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/20 166pp

7907300153 Transcript of 790723 hearing in Bethesda, MD Pp 53, 408-53, 601  
MILLER, M E , LEEDS, J V , LUEBKE, E A Atomic Safety and Licensing Board Panel 79/07/23 194pp

#### DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

##### O Adjudicatory correspondence

7907240370 Notice of receipt of Citizens United for Responsible Energy, Community Action Research Group & IA PIRG 790601 request for suspension of Amend 46 to DPR-49  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/26 1p

##### P. Operating license stage documents & correspondence

7907260098 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22 2pp

7907090242 Notifies that restart physics test program was performed at end of safe-end repair outage Program necessitated by off-loading of core & leaking of fuel assembly replacement that occurred during outage  
HAMMOND, E L Iowa Electric Light & Power Co 79/06/04 1p

7907180636 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625). 79/06/11 2pp

7907180887 Notification of 790613 meeting w/util to discuss licensing actions, both pending & forthcoming  
KEVERN, T A Operating Reactors Branch 3 (Pre 790625). 79/06/11 2pp.

7907180462 Confirms 790611 telcon re upcoming meeting between NRC & util to discuss progress of security program  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/13 1p.

7907250112 Forwards Amend 51 to License DPR-49, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625). 79/06/15 2pp

--7907250117 Amend 51 to License DPR-49, changing Tech Specs to clarify requirements for permanent retention of records & adding two snubbers to list of snubbers for recirculation sys in drywell  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/15 7pp.

--7907250118 Safety evaluation supporting Amend 51 to License DPR-49 \* Office of Nuclear Reactor Regulation 79/06/15 4pp.

--7907250122 Notice of issuance & availability of Amend 51 to License DPR-49  
CLARK, R J Operating Reactors Branch 3 (Pre 790625) 79/06/15 2pp

7907050220 Notifies NRC of delay in implementing security mod project due to strike by local electrician union  
RODT, L D Iowa Electric Light & Power Co 79/05/20 1p

7907100560 Notifies that App I to Tech Specs will be submitted no later than 790831  
RODT, L D Iowa Electric Light & Power Co 79/07/02 1p

7907270355 Forwards Amend 52 to License DPR-49, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 79/07/05 2pp

--7907270360 Amend 52 to License DPR-49, requiring all inservice insp & testing to be performed in accordance w/ASME Boiler & Pressure Vessel Code  
IPPOLITO, T A Operating Reactors Branch 3 79/07/05 17pp

--7907270364 Safety evaluation supporting Amend 52 to License DPR-49 \* Office of Nuclear Reactor Regulation 79/07/05 10pp

--7907270369 Notice of issuance & availability of Amend 52 to License DPR-49  
IPPOLITO, T A Operating Reactors Branch 3 79/07/05 2pp

7907230067 Summary of 790613 meeting w/util in Bethesda, MD re pending licensing actions  
KEVERN, T A Operating Reactors Branch 3 (Pre 790625) 79/07/16 4pp

##### O Inspection reports, IE Bulletins & correspondence

7907180416 Forwards IE Insp Rept 50-331/79-13 on 790417-19 & 23-25 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/10 2pp

--7907180425 IE Insp Rept 50-331/79-13 on 790417-19 & 23-25 No noncompliance noted Major areas inspected plant operations, licensee action on previous insp findings, LER followup, cleanup sys crack repair & IE bulletin & circular followup  
JACKLIN, I N , SPEGBARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/09 9pp

7907100686 Forwards IE final rept IE-116, "Metallurgical Examination & Stress Evaluation of Recirculation Inlet Nozzle Safe-End Cracking " W/o encl  
JORDAN, E L Office of Inspection & Enforcement 79/05/15 2pp

7907110261 Responds to IE Bulletin 79-10 Submits info re requalification training of reactor operators & senior operators  
WALLACE, J A Iowa Electric Light & Power Co 79/05/25 3pp

7907200316 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907190267 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Bolanoid Valves) " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/06 1p.

7907240422 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures " forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907300474 IE Insp Rept 50-331/79-15 on 790501-03, 07-11 & 16-18 Noncompliance noted failure to adhere to procedures for engineering safety  
JACKLIN, I N Region 3, Chicago, Office of the Director 79/06/11 13pp.

7907310015 Forwards IE Insp Rept 50-331/79-15 on 790501-03, 07-11 & 16-18 & notice of violation.  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/13. 2pp.

## DOCKETED ITEMS

--7907310028 Notice of violation from insp on 790501-03, 07-11 & 16-18  
\* Region 3, Chicago, Office of the Director 79/06/11 1p

7907300017 Ack receipt of 790424 & 0329 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept  
50-331/79-03  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/19 1p

--7907300094 Responds to NRC ltr re violations noted in IE Insp Rept 50-331/79-03 Corrective actions investigation not complete. Response to be ready by 790718  
TUTHILL, S J Iowa Electric Light & Power Co 79/04/24 1p

--7907300095 Responds to NRC ltr re violations noted in IE Insp Rept 50-331/79-03 Corrective actions contract maint personnel for future activities will be instructed to follow all written procedures & will be closely monitored for adherence  
TUTHILL, S J Iowa Electric Light & Power Co 79/05/29 2pp

7907020428 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120231 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907050522 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907130122 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/23 1p

7907060313 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907180412 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130268 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240094 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310335 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310410 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260184 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260391 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borehole Water Sys at PWR Plants." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

#### 2. Periodic operating reports & related correspondence

7907190571 Forwards monthly operating rept for June 1979  
HAMMOND, E L Iowa Electric Light & Power Co. 79/07/14 1p.

--7907190574 Monthly operating rept for June 1979  
VAN SICKEL, J Iowa Electric Light & Power Co 79/07/13 5pp

#### 3 Reportable occurrences, LERs & related correspondence

7907100562 Submits prompt notification of RO re potential generic problem in pipe support base plate concrete expansion anchor bolts investigation re affect on plant operability continues  
HAMMOND, E L Iowa Electric Light & Power Co 79/07/03 1p

7907200366 Forwards LER 79-013/03L-0  
HAMMOND, E L Iowa Electric Light & Power Co 79/07/13 1p

--7907200373 LER 79-013/03L-0 on 790614 during daily surveillance tests, drywell gaseous radiation monitors RR 4379A & RR 4379B indicated downscale Caused by defective amplifier card in RR 4379B RR 4379A awaiting test  
VAN SICKEL, J Iowa Electric Light & Power Co 79/07/13 1p

7907230555 Forwards LER 79-014/01T-0  
HAMMOND, E L Iowa Electric Light & Power Co 79/07/17 1p

--7907230559 LER 79-014/01T-0 on 790703 test program indicated faulty Phillips anchor bolts Caused by improper installation & inadequate design Replacement program underway using improved design anchor bolts mfg by Hilli  
VAN SICKEL, J Iowa Electric Light & Power Co 79/07/17 2pp

#### DOCKET 50-332 BARNWELL REPROCESSING PLANT

##### Q Inspection reports, IE Bulletins & correspondence

7907100030 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907240481 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

#### 3 Reportable occurrences, LERs & related correspondence

7907120308 Submits rept re Flowline Corp stainless steel elbows which failed to meet acceptance criteria & for which results of test for detecting susceptibility of intergranular attack were erroneously recorded Elbows returned to distributor.  
BUCKHAM, J A Allied - General Nuclear Services 79/06/08 3pp.

#### DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

##### F Security, medical, emergency & fire protection plans

7907180245 Requests clarification re fire protection sys design verification per NEPA-13 & commitment to implementation dates for mod  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625). 79/05/23 2pp

7907100601 Submits addl responses to draft SER re fire protection program, in reply to 790523 ltr Forwards revised table re implementation dates for proposed mods & staff requirements  
EARLY, P J Power Authority State of New York 79/07/02 4pp

7907200301 Forwards Class III application fee for review of safeguard contingency plans under protest pending final determination of legality of fee schedule  
EARLY, P J Power Authority State of New York 79/07/13 2pp

#### H General correspondence

7907120332 Comments on closing of five nuclear plants due to seismic testing inconsistencies NRC unjustly criticized for doing right thing  
WABBERBACH, A E Affiliation Unknown 79/03/26 1p

7907040343 Responds to 790314 ltr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord w/accepted engineering practice Failed piping could cause LOCA Plant review is being expedited  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/09 3pp.

--7907060356 Comments on incidence of seismic activity in Northeast.  
SMITH, E T Affiliation Unknown 79/03/14 3pp.

7907090460 Responds to 790316 telegram re orders closing five power plants in eastern US Analysis techniques used in seismic design of safety-related piping not in accord w/proven & generally accepted engineering practice  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 3pp

7907050542 Responds to 790315 ltr re shutdown of five nuclear plants Plants shut down due to inadequacy of seismic analysis techniques w/map showing previous earthquakes in area  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907050348 Expresses outrage at closing five nuclear power plants due to possible consequences resulting from earthquakes  
DRUM, D E Peter Bent Brigham Hosp BQ, Massachusetts 79/03/15 1p

7907060293 Responds to 790315 telegram opposing plant shutdown due to seismic design concerns Forwards earthquake maps  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3PP

--7907060299 Opposes shutdown of plants Plants should be allowed to continue to operate while seismic improvements are developed  
KUS, C M Affiliation Unknown 79/03/15 1p

#### P Operating license stage documents & correspondence

7907130437 Forwards Cycle III startup test rept  
LEONARD, J D Power Authority State of New York 79/04/18 1p

--7907130439 Cycle III startup test rept  
\* Power Authority State of New York 79/04/18 7pp

7907060481 Summary of 790410 meeting w/util in Boston MA re safety-related piping reanalysis  
POLK, P J Operating Reactors Branch 3 (Pre 790625) 79/05/09 9pp

7907060407 Summary of 790504 meeting w/util in Bethesda, MD re safety-related piping reanalysis  
POLK, P J Operating Reactors Branch 3 (Pre 790625) 79/05/18 15pp

7907060179 Responds to 790126, 0202 & 0316 ltrs re proposed license amend to improve communications between organizations. meeting has been tentatively scheduled for early May to discuss proposed changes No hearings planned  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/18 4pp

7907260064 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22, 2pp

7907190277 Notification of 790605 meeting w/util in New York, NY to review piping seismic reanalysis, pipe supports, nozzles & containment penetration associated w/specific piping sys  
POLK, P J Operating Reactors Branch 3 (Pre 790625) 79/06/01 1p

7907180655 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/d encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 2pp

7907300518 Ack receipt of 790316 request for NRC approval of planned course of action Defines cold shutdown as specified in NRC 790313 order Plant operating review committee should effect conformance w/10CFR50.59  
IPPOLITO, T A Operating Reactors Branch 3 79/06/12 2pp.

7907310459 Requests submittal of Offsite Dose Calculation Manual & process control program Guidance encl.  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/06/12 11pp

7907240041 Notification of 790619 meeting in Bethesda, MD w/util & B&W to review 790608 startup request & piping seismic reanalysis  
POLK, P J Operating Reactors Branch 3 (Pre 790625), 79/06/13 1p.

7907030463 Requests NRC approval of safety of reactor protection sys power supplies Forwards OE 790223 ltr documenting results of analysis on typical OE reactor protection sys motor generator set protective circuit  
EARLY, P J Power Authority State of New York 79/06/28 19pp

7907020270 Submits supplemental info re piping stress reevaluation Request for plant startup was contingent upon completion of rept & necessary mods to constraints Expected date now 790715  
EARLY, P J Power Authority State of New York 79/06/29 49pp

7907090363 Notifies that major mods needed to conform to long-term program acceptance criteria consisting of installation of vent header deflators & anchoring support columns will be installed by end of Dec 1982  
EARLY, P J Power Authority State of New York 79/06/29 2pp

7907230494 Forwards draft Offsite Dose Calculation Manual  
EARLY, P J Power Authority State of New York 79/07/20 2pp

--7907230497 Draft Offsite Dose Calculation Manual  
\* Power Authority State of New York 79/07/20 61pp

#### G Inspection reports, IE Bulletins & correspondence

7907110421 Forwards IE Insp Rept 50-333/79-03 on 790320-23 No noncompliance noted  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/08 2pp

--7907110424 IE Insp Rept 50-333/79-03 on 790320-23 No noncompliance noted Major areas inspected backshift operations containment leak rate testing, inservice testing of pumps & valves & previous insp findings  
HIGGINS, J C, CAPHTON, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/03 10pp

7907120066 Responds to IE Bulletin 79-04 Suing check valves mfg by Velan Engineering Corp not installed in Category 1 piping sys  
LEONARD, J D Power Authority State of New York 79/05/09 1p

7907190278 Responds to IE Bulletin 79-08 re several minor problems concerning BHRs identified during TMI incident  
EARLY, P J Power Authority State of New York 79/05/18 2pp

7907030054 Ack receipt of 790223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/78-28  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/21 2pp

--7907030058 Responds to NRC 790131 ltr re violations noted in IE Insp Rept 50-333/78-28 Corrective actions signs posted in radiation area Requests status of several noncompliance items be reviewed  
LEONARD, J D Power Authority State of New York 79/02/23 7pp

--7907030062 Forwards IE Insp Rept 50-333/78-28 on 781204-07 & notice of violation.  
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/01/31 3pp

--7907030065 Notice of violation from insp on 781204-07  
\* Region 1, Philadelphia, Office of the Director 79/01/04 4pp

--7907030068 IE Insp Rept 50-333/78-28 on 781204 Noncompliance noted Failure to maintain adequate respiratory protection procedures, exceeded quarterly limit on gaseous release & deficient labeling of radioactive matl containers  
PLUMLEE, K E, NIMITZ, R L Region 1, Philadelphia, Office of the Director CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/01/04 16pp.

7907060399 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/05/22, 1p

7907060117 Forwards request for addl info re inservice testing program  
IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/05/23, 4pp

7907050133 Notifies requested response to IE Bulletin 79-12 will not be submitted by 790529 info will be supplied within two weeks of receipt of required info from reactor vendor  
LEONARD, J D Power Authority State of New York 79/05/24, 1p.

7907030049 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29, 1p

## DOCKETED ITEMS

7907200124 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190069 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060115 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907090421 Responds to IE Bulletin 79-02 Extensive work conducted at plant to verify adequacy of hangers Physical insp of anchor bolts underway  
LEONARD, J D Power Authority State of New York 79/06/08 2pp

7907110378 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230691 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240194 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907120516 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907100351 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100506 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907310094 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/79-02  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

--7907310107 Responds to NRC 790504 ltr re violations noted in IE Insp Rept 50-333/79-02 Corrective actions procedures to document temporary changes in valve lineups were initiated & surveillance tests for suppression pool were revised  
LEONARD, J D Power Authority State of New York 79/05/23 3pp

--7907310115 Forwards IE Insp Rept 50-333/79-02 on 790313-16 & notice of violation  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/04 2pp

--7907310121 Notice of violation from insp on 790313-16  
\* Region 1, Philadelphia, Office of the Director 79/05/03 2pp.

--7907310130 IE Insp Rept 50-333/79-02 on 790313-16 Noncompliance noted failure to complete valve lineup rept & failure to monitor & log suppression pool temp during addition of heat  
CONTE, R J, KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/05/03. 16pp

7907180793 Forwards IE Bulletin 79-14, "Seismic Analysis Per As-Built Safety-Related Piping Sys." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907250513 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director.  
79/07/06. 1p

7907270352 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310521 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### R Periodic operating reports & related correspondence

7907100607 Forwards monthly operating rept for June 1979  
LEONARD, J D Power Authority State of New York 79/07/05 1p

--7907100609 Monthly operating rept for June 1979  
ZUFELT, E Power Authority State of New York 79/06/30 12pp

#### S Reportable occurrences, LERs & related correspondence

7907130460 Forwards LER 79-036/03L-0  
LEONARD, J D Power Authority State of New York 79/07/09 1p

--7907130467 LER 79-036/03L-0 on 790611 failure to perform scheduled surveillance tests Caused by failure of computer to generate test schedule printout Tests immediately conducted satisfactorily  
CHILDS, W V Power Authority State of New York 79/07/09 2pp

7907170030 Forwards LER 79-038/03L-0  
LEONARD, J D Power Authority State of New York 79/07/11 1p

--7907170039 LER 79-038/03L-0 on 790611 main steam line tunnel high temp detectors 02-TS-121A through 02-TS-124D could not be demonstrated as fully operable due to calibr failure of instrument 02-TIC-200  
CHILDS, W V Power Authority State of New York 79/07/11 2pp

7907230287 Forwards LER 79-037/03L-0  
LEONARD, J D Power Authority State of New York 79/07/20 1p

--7907230292 LER 79-037/03L-0 on 790621 while conducting operational surveillance test F-ST-1B, inboard MBIV 29-ADV-80B required 3 B-s to reach full closed position Caused by failure of seals on hydraulic speed controls associated w/valve  
CHILDS, W V Power Authority State of New York 79/07/20 2pp

7907260646 Forwards LER 79-039/03L-0  
LEONARD, J D Power Authority State of New York 79/07/23 1p

--7907260652 LER 79-039/03L-0 on 790627 while in shutdown condition B loop LPCI injection valve did not open in response to automatic signal Caused by failure of torque switch in valve motor operator. Torque switch was replaced  
CHILDS, W V Power Authority State of New York 79/07/23 2pp

7907260741 Forwards LER 79-040/03L-0.  
LEONARD, J D Power Authority State of New York 79/07/23 1p

--7907260747 LER 79-040/03L-0 on 790630 during cold shutdown, RHR sys not fully operable due to existence of leak flow path through discharge check valve for pump A Caused by valve disc detaching from disc holder Repairs are continuing  
CHILDS, W V Power Authority State of New York 79/07/23 2pp

#### U Congressional/Executive Correspondence

7907230752 Notice describing reasons for shutdown of five plants  
CHILK, B J Office of the Secretary of the Commission 79/05/14 8pp

7907180389 Responds to 790323 ltr re shutdown of facilities None of proposed alternatives would have adequately dealt w/situation Forwards summary of code verification program, IE Bulletin 79-07 & chronology table of pipe stress issue  
HENDRIE, J M Commission 79/06/27. 17pp

--7907180633 Requests info re evaluation of feasibility & effectiveness of safe alternative responses to error in seismic codes rather than shutdown of facilities Requests info re possibility of similar errors at other plants  
DINOELL, J D House of Rep. Interstate & Foreign Commerce 79/03/23. 2pp.

## DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

## F Security, medical, emergency &amp; fire protection plans

7907190552 Ack receipt of 790703 ltr Forwards Class III fee for  
safeguards contingency plan  
MOORE, G W Duquesne Light Co 79/07/12 2pp

## G Adjudicatory correspondence

7907260438 Requests termination of 790313 order to show cause re  
safety-related piping sys  
DUNN, C N Duquesne Light Co 79/07/23 3pp

## H. General correspondence

7907120332 Comments on closing of five nuclear plants due to seismic  
testing inconsistencies NRC unjustly criticized for doing  
right thing  
WASSERBACH, A E Affiliation Unknown 79/03/26 1p

7907060343 Responds to 790314 ltr re shutdown of five nuclear power  
plants because of seismic concerns Seismic design was not in  
accord w/accepted engineering practice Failed piping could  
cause LOCA Plant review is being expedited  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/09 3pp

--7907060356 Comments on incidence of seismic activity in Northeast  
SMITH, E T Affiliation Unknown 79/03/14 3pp

7907090460 Responds to 790316 telegram re orders closing five  
power plants in eastern US Analysis techniques used in  
seismic design of safety-related piping not in accord  
w/proven & generally accepted engineering practice  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 3pp

7907030542 Responds to 790315 ltr re shutdown of five nuclear plants  
Plants shut down due to inadequacy of seismic analysis  
techniques W/map showing previous earthquakes in area  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907050548 Expresses outrage at closing five nuclear power plants due  
to possible consequences resulting from earthquakes  
DRUM, D E Peter Bent Brigham Hosp BG, Massachusetts 79/03/15  
1p

7907060293 Responds to 790315 telegram opposing plant shutdown due to  
seismic design concerns Forwards earthquake maps  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907060299 Opposes shutdown of plants Plants should be allowed to  
continue to operate while seismic improvements are  
developed  
KUB, C M Affiliation Unknown 79/03/15 1p

## P Operating license stage documents &amp; correspondence

7907190117 Forwards Kinemetrics, Inc rept re time-history accelerograph  
recording sys Sys determined operable  
WERLING, J A Duquesne Light Co 79/03/05 1p

--7907190133 "Installation Test Rept for Kinemetrics BMA, S/N 170  
Recording Sys W/Three Teledyne FB-103B Accelerometers, One  
Teledyne 361BD Trigger & Kinemetrics SMP-1, B/N 181  
(Playback Unit) "  
\* Duquesne Light Co 79/02/26 9pp

7907090410 Submits appeal of partial denial of request re Task Action  
Plans A-40 & A-41 & denial of request re seismic stress  
repts UCS seeks matl to evaluate potential danger to people  
residing near plant  
WEISS, E R Sheldon, Harmon & Roisman 79/04/26 2pp

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse  
plant design per TH1-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310583 Forwards NRC 790515 ltr to licensees of Westinghouse  
two-loop plants re rod bank exchange method for verifying  
shutdown margin of two-loop NSSB W/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15  
1p

7907060477 Requests addl info in order for NRC to review proposed  
amplified response spectra using soil structure interaction.  
STELLO, V Division of Operating Reactors. 79/05/18 3pp

7907260049 Discusses plans to install communication links between NRC &  
nuclear facilities for emergency use Direct lines from each  
facility to NRC headquarters & regional ofc will communicate  
operational & environ info  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 2pp

7907300045 Summary of 790522 meeting w/utills & B&W in Boston, MA  
re review of soil structure interaction methodology  
NEIGHBORS, J D Operating Reactors Branch 1 (Pre 790625)  
79/05/25 3pp

7907060270 Submits identified areas to be addressed during seismic  
pipestress reanalysis  
EISENHUT, D G Division of Operating Reactors 79/05/25 4pp

7907130123 Discusses areas to be covered in interim or final rept on  
seismic pipestress reanalysis, including stresses due to  
seismic anchor movements, support stiffness accountability &  
criteria for pipe support & design  
EISENHUT, D G Assistant Director for Systems Engineering 79/05/25  
3pp

7907180710 Notification of 790605-07 meeting w/utill & B&W in Boston, MA  
to discuss & review pipe stress reanalysis, examination of  
results & proposed conditions for return to power  
WIGGINTON, D L Operating Reactors Branch 1 (Pre 790625)  
79/06/04 1p

7907130311 Forwards Amend 18 to License DPR-66, safety evaluation &  
notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/06  
4pp

--7907130316 Amend 18 to License DPR-66, revising Tech Specs re  
safety-related snubbers, fire protection, chemical releases &  
environ considerations  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625)  
79/06/06 15pp

--7907130323 Safety evaluation supporting Amend 18 to License DPR-66  
\* Office of Nuclear Reactor Regulation 79/06/06 79pp

--7907130329 Notice of issuance & availability of Amend 18 to License  
DPR-66  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625)  
79/06/06 3pp

7907180626 Forwards NUREG-0560, "Staff Rept on Generic Assessment of  
Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre  
790625) 79/06/11 2pp

7907250037 Summary of 790524 meeting w/B&W & util in  
Bethesda, MD re amplified response spectra developed  
w/consideration of soil structure interactions  
WIGGINTON, D Operating Reactors Branch 1 (Pre 790625) 79/06/14  
7pp

7907020148 Forwards Proposed Change Request 29 to App A of Tech Specs,  
reducing time constant of neutron flux rate reactor trips  
from 2-s to 1-s & reducing setpoint of high negative rate  
from 5% to 3%.  
DUNN, C N Duquesne Light Co 79/06/26 3pp

7907020172 Forwards proposed change to App A of Tech Specs, changing  
safety injection sys initiation logic so two-out-of-three  
low pressurizer signals would result in safety injection  
DUNN, C N Duquesne Light Co 79/06/26 8pp

7907180194 Notification of 790709 meeting w/utill in Bethesda, MD to  
discuss examination results of cracked feedwater lines,  
stress & piping analyses, repair & mod designs & procedures  
WIGGINTON, D Operating Reactors Branch 1 (Pre 790625) 79/07/02  
2pp

7907130410 Forwards Revision 1 to "Rept on Reanalysis of Safety-Related  
Piping Sys " Seven piping supports will be modified & two  
new supports will be installed Requests authorization to  
begin interim operation until refueling  
WODLEVER, E J Duquesne Light Co 79/07/11 104pp

--7907130413 "Rept on Reanalysis of Safety-Related Piping Sys, Revision  
1," by B&W  
\* Duquesne Light Co 79/07/11 100pp

7907200472 Forwards Revision 2 to "Rept on Reanalysis of Safety-  
Related Piping Sys."  
DUNN, C N Duquesne Light Co 79/07/18 3pp

## DOCKETED ITEMS

- 7907100476 Revision 2 to "Rept on Reanalysis of Safety-Related Piping Sys." prepared by S&W  
Duquesne Light Co 79/07/17 13pp

#### Q Inspection reports, IE Bulletins & correspondence

7907020033 Submits responses to IE Bulletin 79-06A Program initiated to assure that all licensed operators, plant mgt & supervisors w/operational responsibilities will be familiar w/THI incident  
DUNN, C N Duquesne Light Co 79/05/14 11pp

7907110650 Responds to IE Bulletin 79-09 re OE Type AK-2 circuit breakers installed in safety-related sys. Breakers used in 125-volt DC control sys. Required preventive maint program will be implemented by 790930  
DUNN, C N Duquesne Light Co 79/05/17 2pp

7907060380 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907240600 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790930 in Bethesda, MD  
SCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907240609 Forwards IE Insp Rept 50-334/79-10 on 790418-20 No noncompliance noted  
CARLSON, R Y Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/25 2pp

--7907240615 IE Insp Rept 50-334/79-10 on 790418-20 No noncompliance noted Major areas inspected as-built accuracy of safety-related pipe supports & pipe sys drawings  
DUNN, J P Region 1, Philadelphia, Office of the Director  
TRIPP, L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/25 4pp

7907030025 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200095 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190031 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060090 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907110364 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230663 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907240147 Forwards IE Circular 79-09, "Occurrences of Split or Functioned Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/23 1p

7907120491 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907060182 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907110026 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180764 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907250301 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/06 1p

7907270329 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907230625 Forwards Class III fee for inservice review as requested by NRC 790705 ltr  
MODRE, Q W Duquesne Light Co 79/07/16 2pp

7907310490 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

7907270164 Supplements info to IE Bulletin 79-13 re small cracks identified in feedwater line elbows. Radiographs revealed cracks present in three inlet pipes. Instrumentation program to be developed for feedwater lines  
DUNN, C N Duquesne Light Co 79/07/17 21pp

#### R Periodic operating reports & related correspondence

7907030418 Forwards portions of 1978 Annual Environ Rept, Vol 1 nonradiological, re infrared photography performed in 1978. Photographs transmitted under separate cover  
BISSERT, F J Duquesne Light Co 79/06/27 8pp

7907100547 Forwards NPDES repts for May 1979, submitted to PA Dept of Environ Resources  
MODRE, Q W Duquesne Light Co 79/06/28 14pp

7907170047 Forwards monthly operating rept for June 1979  
DUNN, C N Duquesne Light Co 79/07/10 5pp

--7907170052 Monthly operating rept for June 1979  
SPITZNUGLE, A E Duquesne Light Co 79/07/02 4pp

#### S Reportable occurrences, LERs & related correspondence

7907090263 Forwards LER 79-014/01T-0.  
WERLING, J A Duquesne Light Co 79/07/02 2pp

--7907090265 LER 79-014/01T-0 on 790618 special radiographic insp of three steam generator nozzle-to-feedwater piping welds showed cracking in three inlet elbows. Caused by fatigue failure assisted by corrosion. Elbows replaced  
WERLING, J A Duquesne Light Co 79/07/02 2pp

7907110446 Forwards LER 79-015/01T-0.  
WERLING, J A Duquesne Light Co 79/07/06 2pp

--7907110447 LER 79-015/01T-0 on 790621, received vendor notification that high energy break inside containment could cause potential steam generator level bias leading to delayed protection signals. Caused by calculation error  
WERLING, J A Duquesne Light Co 79/07/06 4pp

7907170108 Forwards LERs 79-016/03L-0 & 79-017/03L-0  
WERLING, J A Duquesne Light Co 79/07/08 2pp

--7907170111 LER 79-016/03L-0 on 790608, cables discovered incorrectly routed. Caused by personnel error during const. Cables will be rerouted & verified correct. Investigation underway to check other cables  
WERLING, J A Duquesne Light Co 79/07/08 1p

--7907170114 LER 79-017/03L-0 on 790609 during insp, 1B LHBI pump suction valve from refueling water storage tank found inoperable. Caused by failure of motor operator torque switch. Switch assembly replaced, tested & returned to svc.  
WERLING, J A Duquesne Light Co 79/07/08 1p



7907270229 Submits special rept re groundwater leakage discovered 30 ft south of intake structure Caused by expansion joint in fire line Area around leak will be excavated & necessary repairs completed  
WERLING, J A Duquesne Light Co 79/07/18 2pp

T Hearing transcripts on non-antitrust matters

7907090015 Transcript of 790530 briefing in Washington, DC re shutdown pipe stress issue at facility Pp 1-20  
HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commission 79/05/30 22pp

U Congressional/Executive Correspondence

7907230752 Notice describing reasons for shutdown of five plants  
CHILK, B J Office of the Secretary of the Commission 79/05/14 8pp

7907180588 Responds to 790323 ltr re shutdown of facilities None of proposed alternatives would have adequately dealt w/situation Forwards summary of code verification program, IE Bulletin 79-07 & chronology table of pipe stress issue  
HENDRIE, J M Commission 79/06/27 17pp

--7907180633 Requests info re evaluation of feasibility & effectiveness of safe alternative responses to error in seismic codes rather than shutdown of facilities Requests info re possibility of similar errors at other plants  
DINGELL, J D House of Rep, Interstate & Foreign Commerce 79/03/23 2pp

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

7907260661 Forwards appropriate Class III fee for Safeguards Contingency Plans, in response to RM Diggs 790703 ltr w/o encl  
UHRIG, R E Florida Power & Light Co 79/07/19 1p

P. Operating license stage documents & correspondence

7907180235 Requests info from currently operating PWRs re small break analysis, as followup to TMI-2 incident review  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/05/09 8pp

7907090177 Forwards Amend 32 to License DPR-67, safety evaluation & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/27 3pp

--7907090184 Amend 32 to License DPR-67, incorporating changes resulting from Cycle 3 fuel reloading & deleting license requirement for neutron shielding  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/27 34pp

--7907090196 Safety evaluation supporting Amend 32 to License DPR-67  
\* Operating Reactors Branch 4 (Pre 790625) 79/05/27 50pp

--7907090200 Notice of issuance & availability of Amend 32 to License DPR-67  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/27 2pp

7907180631 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" w/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 2pp.

7907260035 Requests registration as user of Model NLI-1/2  
UHRIG, R E Florida Power & Light Co. 79/06/11 1p.

7907020188 Indicates personnel problems shortage exists re restart from refueling on 790528; pass rate for new operator qualification exams less than 50% Due to shortage of licensed operators, overtime being implemented  
ROBB, D F Division of Project Management 79/06/16 2pp.

7907090220 Forwards revised pages correcting typographical errors in 780908 pump & valve test program  
UHRIG, R E. Florida Power & Light Co. 79/07/02 8pp,

G Inspection reports, IE Bulletins & correspondence

7907020366 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907090126 Forwards IE Insp Rept 50-335/79-10 on 790414-17 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp

--7907090130 IE Insp Rept 50-335/79-10 on 790414-17 No noncompliance noted Major areas inspected preparation for refueling & fuel handling activities  
VOGT-LOWELL, R J, MARTIN, R D Region 2, Atlanta, Office of the Director 79/04/30 5pp

7907190392 Submits info as followup to initial response to IE Bulletin 79-04 Velan check valves were used Valve weights used were from Velan drawings in case of computer analyzed lines, or catalogue estimates in case of chart analyzed lines  
UHRIG, R E Florida Power & Light Co 79/05/03 3pp

7907110325 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907050121 Responds to IE Bulletin 79-06B, Item 12 No Tech Spec mods are required to implement responses to Items 1-11  
UHRIG, R E, Florida Power & Light Co 79/05/15 1p

7907100184 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110103 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907120280 Responds to IE Bulletin 79-10, Forwards operator & senior operator examination results & related statistics.  
UHRIG, R E, Florida Power & Light Co 79/05/24 5pp

7907180180 Supplements response to IE Bulletin 79-07 Uses ADLPIPE to perform seismic analyses of safety-related piping changes & mods None of methods specified in bulletin are used  
UHRIG, R E Florida Power & Light Co 79/05/24 2pp.

7907250143 Forwards IE Insp Rept 50-335/79-11 on 790417-20 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/24 2pp

--7907250147 IE Insp Rept 50-335/79-11 on 790417-20, No noncompliance noted. Major areas inspected plant procedures, refueling outage maint & operations, LERs, IE bulletins, circulars & notices & previously identified items.  
WEBSTER, E. M. Region 2, Atlanta, Office of the Director.  
CANTRELL, F B. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/24 7pp

7907100094 Responds to IE Bulletins 79-06 & 06B, Responsibility for initiation & verification of auxiliary feedwater flow to steam generators is primary duty of designated operator during transients & accidents.  
UHRIG, R E Florida Power & Light Co 79/05/25 1p.

7907030096 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907130321 Forwards status rept describing progress in responding to IE Bulletin 78-12B Plans to respond by 790629  
UHRIG, R E Florida Power & Light Co 79/05/29 2pp.

7907130415 Forwards addl response to IE Bulletin 79-06  
UHRIG, R E, Florida Power & Light Co. 79/05/29 2pp

7907200192 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required  
O'REILLY, J P. Region 2, Atlanta, Office of the Director 79/05/31 2pp

## DOCKETED ITEMS

7907190401 Responds to IE Bulletin 79-03 ASME SA-312 Type 304 stainless steel pipe spools mfg by Youngstown Welding & Engineering Co not used  
UHRIO,R E Florida Power & Light Co 79/06/05 1p

7907190172 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060056 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907250160 Requests that Region 2 measurements van be granted access privileges of "licensee designated vehicle "  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp

7907190142 Responds to IE Bulletin 79-01 Unable to submit requested rept re environ qualification of Class IE equipment until 790702  
UHRIO,R E Florida Power & Light Co 79/06/12 1p

7907020386 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120075 Forwards IE Bulletin 79-02,Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907110226 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

7907310019 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys Piping " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907110269 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/26 2pp

7907180435 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310240 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310379 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

#### S Reportable occurrences, LERs & related correspondence

7907090280 Confirms telcon re RD 335-79-21 Emergency diesel generator turbocharger thrust bearing is susceptible to damage under certain repeat starting modes which could result in turbocharger failure. Will develop mod package  
WETHY,C H Florida Power & Light Co 79/06/28 2pp

7907120634 Forwards LER 79-019/03L-0  
SCHMIDT,A D Florida Power & Light Co 79/07/03 1p.

--7907120641 LER 79-019/03L-0 on 790603 control element assembly dropped four times within 2-h period Caused by failure of coil power programmer timing module. Module replaced  
SCHOPPMAN,M A Florida Power & Light Co 79/07/03 2pp.

7907180312 Forwards LER 79-021/01T-0  
SCHMIDT,A D Florida Power & Light Co 79/07/09 1p

--7907180328 LER 79-021/01T-0 on 790625 General Motors notified util that turbocharger thrust bearing could be damaged by hot starts w/lube oil over 160 F Vendor recommends eliminating nonemergency hot starts while new design is developed  
SCHOPPMAN,M A Florida Power & Light Co 79/07/09 2pp

7907250335 Forwards LER 79-020/02L-0  
SCHMIDT,A D Florida Power & Light Co 79/07/13 1p

--7907250341 LER 79-020/03L-0 on 790614 auxiliary feedwater pump 1c failed to start due to failure of steam inlet valve Caused by unknown factor Valve operated normally after being manually cycled  
SCHOPPMAN,M A Florida Power & Light Co 79/07/13 1p

#### U Congressional/Executive Correspondence

7906260590 Forwards D Browning 790404 questions re FL nuclear power situation Requests necessary info for reply  
MICA,D A House of Rep 79/04/05 2pp

--7906260593 Ack receipt of 790405 ltr re D Browning info request re FL nuclear power situation Forwards instructions to operators re steps to prevent occurrence like TMI & JM Hendris 790410 testimony to Subcommittee on Nuclear Regulation W/o encl  
KAMMERER,C Office of Congressional Affairs 79/04/18 1p

#### DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

#### F Security, medical, emergency & fire protection plans

7907230378 Documents info provided verbally re delay in schedule of submittals for fire protection mods Delay until 790731 due to TMI event & IE Bulletin requirements  
COUNSIL,W O Northeast Utilities 79/07/19 2pp

#### D Advisory Committee on Reactor Safeguards reports & correspondence

7907100226 Forwards LER 79-008/03L-0 re loss of shutdown cooling Installation of refueling level instrumentation to provide better indication of draindown levels begun  
QUITTECHREIDER ACRS - Advisory Committee on Reactor Safeguards  
79/04/24 1p

7907310474 Submits slides to be inserted into 790613 transcript for ACRS Subcommittee on Reactor Operations meeting re power increase  
BIMPSDON,M A ACE Federal Reporters, Inc 79/06/14 34pp

#### P. Operating license stage documents & correspondence

7907050556 Advises of intention to apply requirements of GA topical rept NU-GA-1,Revision 3A, to meet criteria of 10CFR71 51  
COUNSIL,W O Northeast Utilities 79/05/15 1p

7907260060 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will communicate operational & environ info  
ORIER,B H Region 1, Philadelphia, Office of the Director  
79/05/22 2pp

7907060141 Forwards Suppl 1 to safety evaluation supporting Amend 52 to License DPR-65  
REID,R W Operating Reactors Branch 4 (Pre 790625) 79/05/25 2pp

--7907060145 Suppl 1 to safety evaluation supporting Amend 52 to License DPR-65 re control element assembly guide tube integrity  
\* Office of Nuclear Reactor Regulation 79/05/25 2pp

7907020397 Submits 790530 daily digest for Westinghouse reactors  
ROSS,D.F. Division of Project Management 79/05/30 1p

7907180642 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl.  
QRINES,B K Assistant Director for Engineers & Projects (Pre 790625), 79/06/11 1p.

7907240093 Forwards Amend 53 to License DPR-65,notice of issuance & availability & EIA.  
REID,R.W Operating Reactors Branch 4 (Pre 790625) 79/06/25 3pp

# DOCKETED ITEMS

--7907240100 Amend 53 to License DPR-65 revising App B Tech Specs to authorize operation at increased max steady-state power level of 2700 MWt  
EISENHUT, D G Division of Operating Reactors 79/06/25 4pp

--7907240101 EIA supporting Amend 53 to License DPR-65  
\* Office of Nuclear Reactor Regulation 79/06/25 3pp

--7907240105 Notice of issuance & availability of Amend 53 to License DPR-65  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/25 2pp

7907050257 Forwards Offsite Dose Calculation Manual  
COUNSIL, W G Northeast Utilities 79/06/29 1p

--7907050261 Offsite Dose Calculation Manual  
\* Northeast Utilities 79/06/30 88pp

7907120638 Forwards proposed amend to Licenses DPR-21 & DPR-65 revising ETS MIT rept, "Analysis of Exposure Panel Data Collected at Millstone Point" encl  
COUNSIL, W G Northeast Utilities 79/07/02 2pp

--7907120647 Proposed amend to ETS  
\* Northeast Utilities 79/07/02 68pp

--7907120657 "Analysis of Exposure Panel Data Collected at Millstone Point," prepared by MIT  
\* Northeast Utilities 77/07/31 126pp

7907260737 Requests extension until 790813 to respond to NRC 790629 request for PWR license capabilities to anticipate & respond to unusual incidents  
COUNSIL, W G Northeast Utilities 79/07/16 1p

7907310339 Revises util 790618 response to 790525 ltr re fabrication history of feedwater piping  
COUNSIL, W G, FEE, W F Northeast Utilities 79/07/24 2pp

## G Inspection reports, IE Bulletins & correspondence

7907160177 Evaluates responses by utils to IE Bulletin 79-06B  
WILLIAMS, F J Division of Project Management 79/04/27 3pp

7907110493 Forwards IE Insp Repts 50-245/79-07 & 50-336/79-07, on 790319-23 No noncompliance noted  
SHITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/09 2pp

--7907110460 IE Insp Repts 50-245/79-07 & 50-336/79-07 on 790319-23 No noncompliance noted Major areas inspected radiation program refueling outage conditions, solid radwaste mgt & followup on previous insp findings  
VUHAS, G P Region 1, Philadelphia, Office of the Director  
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/08 10pp

7907060240 Discusses preliminary review of 790126 & 15 submittals re proposed inservice insp & testing Tech Specs & request for relief from selected ASME code requirements Notice of relief encl  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/11 3pp

--7907060241 Notice granting relief from ASME Section XI inservice insp & testing requirements  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/11, 2pp

7907110640 Responds to IE Bulletin 79-09 re failures of OE Type AK-2 circuit breakers in safety-related sys Breakers in use at facility. Undervoltage trip device used in control element assembly power control  
COUNSIL, W G Northeast Utilities 79/05/14 1p.

7907180441 Forwards IE Insp Rept 50-336/79-11 on 790410-13 No noncompliance noted.  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/17 2pp

--7907180445 IE Insp Rept 50-336/79-11 on 790410-13 No noncompliance noted Major areas inspected: previous insp items, refueling operations, pipe supports & restraints, outage-related maint & backshift operations  
HIOGINS, J C., FOLEY, T Region 1, Philadelphia, Office of the Director  
CAPTON, D. L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/16 7pp

7907090233 Responds to IE Bulletin 79-10, "Requalification Training Program Statistics " Forwards util requalification training program statistics  
COUNSIL, W G Northeast Utilities 79/05/22 5pp

7907060392 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907020458 Submits addl info in response to IE Bulletin 79-06B Guiden provided to emergency procedures re natural circulation operation  
COUNSIL, W G Northeast Utilities 79/05/24 4pp

7907100018 Forwards addl info in response to IE Bulletin 79-06B Discusses procedural guidance for monitoring of core & for interpreting control room indications, emergency procedures & positions of safety-related valves  
COUNSIL, W G Northeast Nuclear Energy Co (Northeast Utilities) 79/05/24 4pp

7907050160 Responds to IE Bulletin 78-12B re atypical weld matl in reactor pressure vessel C-E is performing requested search & will submit rept to NRC by 790608  
COUNSIL, W G Northeast Nuclear Energy Co (Northeast Utilities) 79/05/24 1p

7907030041 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907020461 Comments on util response to IE Bulletin 79-06B Training h been conducted by NRC & plant staff Expresses concern as to whether 50 F difference between pressurizer temp & reactor coolant temp is sufficient  
SHEDLOSKEY, T Commission 79/05/30 5pp

7907200114 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190069 Forwards suppl IE Bulletin 79-01A, "Environ Qualification Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060106 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907190789 Requests addl info on inservice insp program re hydraulic snubbers, closure head welds, thread roots & nozzle-to-vessel welds of shutdown heat exchangers  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/07 3pp

7907100473 Forwards IE Info Notice 79-17, "Bounce Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/06/20 1p

7907230681 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21, 1p

7907240174 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/06/23, 1p

7907050316 Forwards "Inservice Insp & Test Program for Pumps, Valves & Pressure Tests," for 790426-801226.  
COUNSIL, W G Northeast Utilities 79/06/25, 2pp

--7907050318 "Inservice Insp & Test Program for Pumps, Valves & Pressure Tests," for 790426-801226  
\* Northeast Utilities 79/06/25, 73pp

7907120509 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Licensee action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/06/25, 1p

## DOCKETED ITEMS

7907060193 Forwards IE Circular 79-10, "Pipe Fittings Mfg from Unacceptable Matl " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/26 1p

7907110027 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/06/28 1p

7907060282 Submits addl responses to IE Bulletin 79-06B Addl necessary actions required to ensure timely initiation of auxiliary feedwater operator have been completed  
 COUNSILL, W O Northeast Utilities 79/06/29 2pp

7907180779 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/02 1p

7907250909 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/06 1p

7907270342 Forwards IE Bulletin 79-15 "Deep Draft Pump Deficiencies " Action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/11 1p

7907310509 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
 GRIER, B H Region 1, Philadelphia, Office of the Director  
 79/07/16 1p

#### R Periodic operating reports & related correspondence

7907180466 Forwards monthly operating rept for June 1979  
 OPEKA, J F Northeast Utilities 79/07/13 1p

--7907180470 Monthly operating rept for June 1979  
 HOWLETT, O H Northeast Utilities 79/07/09 7pp

#### S Reportable occurrences, LERs & related correspondence

7907100129 Forwards LER 79-012/001-P W/o encl  
 OPEKA, J F Northeast Utilities 79/05/22 1p.

7907100388 Forwards LER 79-014/03L-0  
 OPEKA, J F Northeast Utilities 79/07/03 1p

--7907100406 LER 79-014/03L-0 on 790604 small leak noted from crack in "C" charging pump body Cause of crack was stress or fatigue  
 Failure in valve block around valve cylinder shoulder  
 Valve block to be replaced  
 \* Northeast Utilities. 79/06/26 2pp

7907130333 Forwards LER 79-016/03L-0  
 OPEKA, J F Northeast Nuclear Energy Co. (Northeast Utilities).  
 79/07/09 1p

--7907130373 LER 79-016/03L-0 on 790611 one of two power-operated pressurizer relief valves reading approximately 250 psi lower than actual pressurizer pressure Caused by shift of zero point of transmitter  
 \* Northeast Nuclear Energy Co (Northeast Utilities) 79/07/09 1p

7907170088 Forwards LER 79-015/03L-0  
 OPEKA, J F Northeast Utilities 79/07/09 1p

--7907170092 LER 79-015/03L-0 on 790610 leak identified in RGB & traced to isolation valve. Cause unknown Isolation valve repaired & power-operated relief valve declared operable  
 \* Northeast Utilities. 79/07/09 1p.

7907170112 Forwards LER 79-016/03L-0  
 OPEKA, J F Northeast Utilities 79/07/09 1p

79-016/03L-0 on 790611 pressurizer pressure channel for power-operated pressurizer relief valves found 150 PSI lower than actual pressure. Caused by float. Zero point readjusted.  
 Northeast Utilities 79/07/10 1p

LER 79-017/03L-0,  
 st Utilities 79/07/13. 1p.

--7907170229 LER 79-017/03L-0 on 790614 auxiliary feedwater pump rendered inoperable by inboard pump bearing failure Caused by contamination of bearing oil w/ water Pump bearings & shaft replaced & pump restored to svc  
 STRATMAN, R A Northeast Utilities 79/07/13 2pp

7907230474 Forwards LER 79-018/03L-0  
 OPEKA, J F Northeast Nuclear Energy Co (Northeast Utilities)  
 79/07/18 1p

--7907230487 LER 79-018/03L-0 on 790619 surveillance testing during reactor startup revealed control element assembly motion inhibit interlock did not function properly Caused by drift of out-of-sequence scanner power supply voltage  
 BATES, R W Northeast Nuclear Energy Co (Northeast Utilities)  
 79/07/18 1p

7907260589 Forwards LER 79-018/03L-0  
 OPEKA, J F Northeast Utilities 79/07/18 1p

--7907260592 LER 79-018/03L-0 on 790619 surveillance testing revealed malfunction of control element assembly motion inhibit interlock. Caused by shifting of group deviation setpoint voltages Setpoint potentiometers readjusted  
 BATES, R W Northeast Utilities 79/07/18 1p

#### DOCKET 80-338 NORTH ANNA POWER STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907090071 Forwards errata to 790402 EIA  
 GOLDBERG, S C Branch 2 79/06/08 1p

7907250581 Notice of issuance & availability of Amend 11 to License NPF-4,  
 PARR, O D Light Water Reactors Branch 3 79/06/14 2pp

##### F Security, medical, emergency & fire protection plans

7907050183 Forwards security plan evaluation rept page changes Mods do not effect 10CFR73 SS review Encl withheld (ref 10CFR2 790)  
 PARR, O D Light Water Reactors Branch 3 79/05/21 3pp

7907260406 Notifies that target date for completion of sprinkler sys will be 790815  
 BROWN, S C Virginia Electric & Power Co 79/07/23 1p.

##### G Adjudicatory correspondence

7905150023 Forwards NRC testimony re turbine missiles & pumphouse settlement, & professional qualifications of K Campe, M Boyle, J D'Brien, J Burns, A Dromerick, L Heller, R Kiesel & J Leshan Certificate of Bvc encl  
 SHANBON, D T Branch 1. 79/04/27 128pp

7907120019 Motion by util for summary disposition of all matters in proceeding No genuine issues to be heard on any contention raised by Potomac Alliance & Citizens Energy Forum Affidavit of H Brehmer & Certificate of P Bvc encl  
 CHRISTMAN, J. N. Hutton & Williams. 79/05/11. 29pp.

--7907120021 Statement of matl facts as to which there is no genuine issue to be heard, re contentions by Potomac Alliance & Citizens Energy Forum stated in ASLB 790521 order.  
 \* Virginia Electric & Power Co. 79/05/11 30pp.

--7907120027 "Summary of Proposed Mods to Spent Fuel Storage Pool Associated W/Increasing Storage Capacity " Affidavits of RW Calder & JB McKay encl.  
 \* Virginia Electric & Power Co. 78/04/30 76pp

7907110618 Responds to Arnold discovery requests re pumphouse settlement. Current info indicates pumphouse elevation has undergone slow settlement since drain was installed  
 Supervising documentation encl  
 SHANBON, D T. Branch 1 79/05/14 5pp.

--7907110624 Forwards supplemental info to 751219 ltr re pumphouse settlement  
 SHAPER, H K Office of the Executive Legal Director 76/04/14 14pp

--7907110638 Summary of 750430 meeting in Bethesda, MD re pumphouse settlement for svc water reservoir. Recommended issuance of show cause order re suspension of reservoir const  
 FERROBON, R L. Light Water Reactors Branch 2 78/05/01 3pp.

- 7907110645 Discusses recommended actions against util re svc water reservoir pumphouse settlement Civil penalty package will be prepared for failure to rept per 10CFR50 55(e)  
BERATAN, L L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/05/05 1p
- 7907110654 Submits addl info re stress in svc water lines resulting from pumphouse settlement Preliminary investigation indicates stresses are above code allowables Util considered problems reportable per 10CFR50 55(e)  
BERATAN, L L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/07/29 2pp
- 7907110665 Forwards IE Insp Repts 50-338/75-05 & 50-339/75-05 on 750427 Enforcement action will be addressed at later date  
MOBELEY, N C Region 2, Atlanta, Office of the Director 75/05/20 1p
- 7907110678 IE Insp Repts 50-338/75-05 & 50-339/75-05 on 750429 Noncompliance noted failure to rept settlement of svc water reservoir pumphouse per 10CFR 50 55(e)  
COCHRAN, B J, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/05/20 Bpp
- 7907110687 Summary of 740614 meeting w/util & consultants re foundation of svc water reservoir & svc water pumphouse  
PIKE, W J Division of Project Management 76/07/21 2pp
- 7907130082 Answer by util to ASLB 790504 notice of hearing No public hearing is necessary in proceeding, since all contentions are subg to summary disposition Opposes any delay in hearing schedule Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams 79/05/14 Bpp
- 7907110726 Interrogatories & document requests for intervenor Citizens Energy Forum submitted by util Contentions were stated in ASLB 790421 order Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams 79/05/17 10pp
- 7907110746 Util answer to Potomac Alliance 790509 motion to amend petition to intervene Agrees to introduction of contention re svc water cooling sys. Submits improved statement of contention Renews 790511 motion for summary disposition.  
CHRISTMAN, J N Hunton & Williams 79/05/17 4pp.
- 7907130294 Interrogatories & document request submitted to intervenor Potomac Alliance by util Contentions were stated in ASLB 790421 order Certificate of Svc encl.  
CHRISTMAN, J N Hunton & Williams 79/05/17 11pp
- 7907180330 Answers by util to Potomac Alliance 790502 objections & Citizens Energy Forum 790503 objections to ASLB 790421 order granting intervention Seeks denial of intervenor requests for mod of order Certificate of Svc encl  
CHRISTMAN, S N Hunton & Williams 79/05/17 10pp
- 7907180337 Motion by util for interim Tech Spec change Allowable pump house settlement limits should be increased or, in the alternative, raised to level in 10CFR2 717(b). Affidavit of EA Baum & Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams. 79/05/17 10pp
- 7907310566 Forwards Board notification matl re analysis of single rod drop event in Westinghouse three-loop plants Single rod drop could create increase in overall power level of reactor  
SWANSON, D. T. Branch 1. 79/05/18 2pp.
- 7907310572 Forwards memo discussing Westinghouse Part 21 notification re analysis of single rod drop accident Recommends memo be provided to North Anna Board  
VABBALL, D B Assistant Director for Light Water Reactors. 79/05/14. 1p
- 7907310581 Discusses Board notification re analysis of single rod drop event at Westinghouse facilities Concludes that appropriate Boards should be notified Provides item of notification & considerations re relevancy & materiality  
TEDESCO, R L Assistant Director for Reactor Safety. 79/04/23. 3pp.
- 7907170242 Interrogatories & document requests submitted to intervenor Arnold. Requests info re witnesses, documents relied upon in preparing direct case & documents related to turbine missile issue. Certificate of Svc encl  
SWANSON, D. J. Branch 1. 79/05/24 4pp
- 7907160131 Requests summary disposition of intervenors Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of matl fact. Certificate of Svc encl.  
BORDENICK, B. M. Branch 4. 79/05/25. 29pp.
- 7907180438 Motion submitted by Citizens Energy Forum requesting ASLB to allow consolidation w/Potomac Alliance Consolidation will avoid delay in proceeding Certificate of Svc encl  
KRODT, I B Citizens Energy Forum 79/05/25. 3pp
- 7907060478 No objection to Potomac Alliance 790509 motion to amend petition to intervene Petition adds contention re svc water cooling sys Certificate of Svc encl  
GOLDBERG, B C Branch 2 79/05/29 3pp
- 7907130331 Responds to NRC 790502 interrogatories & document requests, submitted by Citizens Energy Forum Forwards info re Contentions 1, 2 & 5, thermal effects, radioactive emissions & corrosion Certificate of Svc encl  
BOULTON, D A Citizens Energy Forum 79/05/29 11pp
- 7907060501 Responses to NRC interrogatories & document requests Answers Contentions 3, 4, 6 & 7, re missile accidents, matl integrity, occupational exposure & alternatives Certificate of Svc encl  
DOUGHERTY, J B Potomac Alliance 79/05/30 25pp
- 7907130189 Opposition by util to postponement of 790626 prehearing conference & evidentiary hearing in alternative, requests ASLB to commence hearings by 790609. Affidavit of EA Baum & Certificate of Svc encl  
RINACA, J M Hunton & Williams 79/05/30 16pp
- 7907060370 Forwards util supplementary testimony in response to NRC testimony re svc water pumphouse settlement RB Beck 760116 ltr to B Ragone & prof qualifications of WR Cartwright encl  
RINACA, J M Hunton & Williams 79/05/31 3pp
- 7907160156 Interrogatories & document requests submitted to NRC by Citizens Energy Forum Requests info re Contentions 1, 2 & 5, radioactive emissions & corrosion & thermal effects Certificates of Svc encl  
KRODT, I B Citizens Energy Forum 79/05/31 5pp
- 7907110081 Extends date for submission of RD Pollard testimony re turbine missile issue until 790611  
SKRUTSKI, R M Atomic Safety and Licensing Appeal Panel 79/06/01 1p
- 7907170254 Interrogatories & document requests submitted to VEPCO by Citizens Energy Forum Requests info re thermal effects, radioactive emissions & corrosion Certificate of Svc encl  
KRODT, I B Citizens Energy Forum 79/06/01 7pp
- 7907180256 Potomac Alliance motion to obtain answers to interrogatories to NRC  
DOUGHERTY, J B Potomac Alliance 79/06/01 1p.
- 7907180265 Interrogatories & document requests for NRC submitted by Potomac Alliance Requests info on spent fuel pool re alternatives, tornado damage, turbine missile damage, defective fuel rods & changes in NRC requirements  
DOUGHERTY, J B. Potomac Alliance 79/06/01 10pp
- 7907180271 Request for documents identified by NRC in response to Potomac Alliance 790601 interrogatory Includes request for util FSAR & Tech Specs applicable to operations of plant  
DOUGHERTY, J. B Potomac Alliance. 79/06/01. 4pp
- 7907180279 Interrogatories & document requests to util submitted by Potomac Alliance. Requests info on spent fuel pool re diagram, const progress, transfer of fuel, alternatives to proposed mod & logistics of handling spent fuel  
DOUGHERTY, J. B Potomac Alliance 79/06/01 22pp
- 7907060438 Requests denial of util 790511 motion for summary disposition Citizens Energy Forum states motion is premature & ignores unresolved issues re proposed mod  
KRODT, I. B. Citizens Energy Forum. 79/06/05 5pp
- 7907060444 Statement of matl facts as to which there is genuine issue to be heard, submitted by Citizens Energy Forum Discusses issues re thermal effects, emissions & corrosion Certificate of Svc encl  
BOULTON, D. A. Citizens Energy Forum 79/06/05 5pp
- 7907060457 Responds to util 790505 motion for summary disposition Requests that ASLB refuse application for order continuance to reply in alternative, seeks denial of motion Affidavits cannot present facts essential to opposition to motion  
DOUGHERTY, J B Potomac Alliance. 79/06/05 5pp.
- 7907060464 Statement of matl facts to which there is genuine issue to be heard in response to util 790505 motion for summary disposition. Affidavit of JB Dougherty & Certificate of Svc encl.  
DOUGHERTY, J. B Potomac Alliance 79/06/05 4pp.

## DOCKETED ITEMS

- 790713012B Supports util 790511 motion for summary disposition re Contentions 1,2 (in part) & 4-7 Affidavits of AW Drometick, PH Leach, FC Kornegay, JS Hermiel, HE Krug, QB Georgier, MD Houston & TD Murphy & Certificate of Svc encl  
GOLDBERG, S C Branch 2 79/06/05 5pp
- 7907130130 Requests denial of util 790517 motion for ASLB to grant interim Tech Specs change re allowable svc water pumphouse settlement limits Request is unnecessary & w/o legal authority Certificate of Svc encl  
SWANSON, D T Branch 1 79/06/06 8pp
- 790713036B Answers submitted by Potomac Alliance to util interrogatories & document requests re contentions on radioactive emissions missile accidents & matl integrity Notice of appearance of LS Lempert on behalf of intervenors  
DOUGHERTY, J B , LEMPERT, L S Potomac Alliance 79/06/06 14pp
- 7907130371 Errata to Potomac Alliance answer to util motion for summary disposition Certificate of Svc encl  
DOUGHERTY, J B Potomac Alliance 79/06/07 2pp
- 7907170240 Reschedules prehearing conference in Charlottesville, VA from 790626 to 0709 Parties w/o intervenor status may make limited appearance on matters within scope of hearing  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/06 4pp
- 790718025B Amends 790421 order to add Potomac Alliance contention re adequacy of svc water cooling sys  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/06 2pp.
- 7907310083 Grants Citizens Energy Forum 790525 motion for consolidation w/Potomac Alliance for purposes of proceeding  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/06 1p
- 7907180774 No opposition by util to Citizens Energy Forum & Potomac Alliance motion for consolidation Util reserves right to oppose future motion necessitated by consolidation, if motions appear to delay proceedings Certificate of Svc encl  
RINACA, J M Hunton & Williams 79/06/07 4pp
- 7907270372 Requests to make limited appearance statement at licensing prehearing  
STONE, S T Affiliation Unknown 79/06/07 1p
- 7907130302 Order overruling Potomac Alliance 790502 objections & Citizens Energy Forum 790503 objections to ASLB 790421 order designating contentions ASLB reaffirms 790421 order  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/08 4pp
- 7907230339 Requests to make limited appearance statement at licensing prehearing  
\* Affiliation Unknown 79/06/09 1p
- 7907240357 Requests to make limited appearance statement at licensing prehearing  
MAHLER, H R Affiliation Unknown 79/06/09 1p
- 7907180606 Answers submitted by Citizens Energy Forum to util 790517 interrogatories & document requests Submits info on contentions re thermal effects, radioactive emissions, spent fuel pool & corrosion Certificate of Svc encl  
KROOT, I B Citizens Energy Forum 79/06/11 15pp
- 7907230362 Requests to make limited appearance statement at licensing prehearing  
MILLER, J Affiliation Unknown 79/06/11 1p
- 7907230529 Comments on proposed storage of spent fuel & sinking of pump house Concerned about safety  
ROVERB, J H Affiliation Unknown 79/06/11 1p
- 7907250085 Requests to make limited appearance statement at licensing prehearing  
MILLAR, F Potomac Alliance 79/06/11 1p
- 7907360377 Requests to make limited appearance statement at licensing prehearing  
BLAIRD, N Affiliation Unknown 79/06/11 1p
- 7907180589 Answer by util to NRC 790511 brief re ALAB-338 Reasonable nexus does not exist between nonsafety-grade equipment issue & issue in North Anna processing ASLB does not have jurisdiction over equipment issue Certificate of Svc encl  
CHRISTIAN, J N Hunton & Williams 79/06/13 6pp
- 7907180744 Requests to amend petition to intervene submitted by Potomac Alliance & Citizens Energy Forum Seeks addition of contention re ability of spent fuel pool to withstand seismic events Certificate of Svc encl  
DOUGHERTY, J B Potomac Alliance 79/06/13 7pp
- 7907230548 Requests to make limited appearance statement at licensing prehearing  
HUGH, S Affiliation Unknown 79/06/15 1p
- 7907180591 Request by util that ASLB authorize immediate installation of high-density spent fuel storage racks for use in storage of up to 243 spent fuel assemblies Interim relief is requested until issues are resolved Certificate of Svc encl  
RINACA, J M Hunton & Williams 79/06/18 27pp
- 7907300270 Order partially granting util 790511 motion for summary disposition Grants contentions re thermal effects, matl integrity, corrosion, occupational exposure & alternatives Grants contention on radioactive emissions  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/18 4pp
- 790718052B Supplemental response to util motion for summary disposition re ASLB 790618 order Supports motion re Contentions 2 & 3 & svc water cooling sys Affidavits of Wernick, Chan, Ferrell & Campe & Certificate of Svc encl  
GOLDBERG, S C Branch 2 79/06/25 30pp
- 7907180787 Notice of denial of request by North Anna Environ Coalition for revocation of util DL  
STELLO, V Office of Nuclear Reactor Regulation 79/06/25 2pp
- 7907180794 Denies request for revocation of util DL  
STELLO, V Division of Operating Reactors 79/06/25 1p
- 7907180803 Denies North Anna Environ Coalition 781101 request for revocation of util DL Util complied w/Tech Specs in reporting pumphouse settlement  
STELLO, V Division of Operating Reactors 79/06/25 8pp.
- 7907180809 Notifies of decision re J Allen 781101 ltr Denies request for revocation of util DL  
GOSBICK, L V Office of the Executive Director for Operations 79/06/25 1p
- 7907180816 Forwards J Allen 781101 ltr  
BYRD, H F Senate 78/12/07 1p
- 7907180827 Requests assistance in obtaining responses to 780902 ltr to JW Moorman & 781101 ltr to NRC re false statements dealing w/abnormal settlement of plant  
ALLEN, J North Anna Environmental Coalition 78/11/01 1p
- 7907180714 Orders deferral of action of 790402 Board notification re nonsafety-grade equipment ASLB jurisdiction to entertain new matters is dependent upon existence of reasonable nexus between issues Careful consideration is necessary  
BISHOP, C J Atomic Safety and Licensing Appeal Panel 79/06/26 11pp
- J Insurance & indemnity information  
-----
- 7907130315 Forwards Endorsements 17-19 to MAELU Policy HF-96.  
KELLY, P J Johnson & Higgins Insurance. 79/07/09 4PP
- P Operating license stage documents & correspondence  
-----
- 7907140109 Draft memo re licensing strategy for plants w/fuel load dates in CV79  
BOYD, R B Division of Project Management 79/03/28 6pp.
- 7907120207 Summary of 790426 meeting w/util to discuss Westinghouse plant design re TH1-2 event.  
THADANI, A Reactor Systems Branch 79/08/02 39pp
- 7907020243 Summary of 790508 meeting w/VEPCO re auxiliary feedwater sys & related areas  
GRIENHUIS, M Operating Reactors Branch 1 (Pre 790625) 79/05/09 5pp
- 7907310394 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NBSB W/o encl  
BCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p

# DOCKETED ITEMS

7907310587 Summarizes 790412 meeting w/Westinghouse in Bethesda, MD re Part 21 notification by Westinghouse re single rod drop event  
FIENO, D B Core Performance Branch 79/04/16 4pp

7907110679 Requests schedule for submittal of addl justification to demonstrate that Barton pressure & differential transmitters will meet performance requirements during hypothesized cooling period  
PARR, O D Light Water Reactors Branch 3 79/06/01 3pp

7907060169 FOIA request for NRC records re nuclear power plant at North Anna, VA  
GLASBERG, V M Hirschkop & Grad P C 79/06/08 1p

7907060173 Responds to FOIA request for documents re North Anna, VA nuclear power plants Documents available in NRC PDR  
FELTON, J M Division of Rules and Records 79/06/13 1p

7907250564 Forwards Amend 11 to License NPF-4, safety evaluation & notice of issuance & availability  
PARR, O D Light Water Reactors Branch 3 79/06/14 3pp

--7907250571 Amend 11 to License NPF-4, incorporating new condition re surveillance requirements of emergency diesel generator batteries  
PARR, O D Light Water Reactors Branch 3 79/06/14 19pp

--7907250578 Safety evaluation supporting Amend 11 to License NPF-4  
\* Light Water Reactors Branch 3 79/06/14 2pp

7907200248 Notice of issuance of Amend 12 to License NPF-4 & revision of Tech Specs re max allowable settlement values of Class 1 structures & allowable groundwater conditions of pumphouse & svc water reservoir  
PARR, O D Light Water Reactors Branch 3 79/06/28 2pp

7907270001 Amend 12 to License NPF-4, changing max allowable settlement values of Class 1 structures & allowable groundwater conditions  
VASSALLO, D B Assistant Director for Light Water Reactors 79/06/28 11pp

7907030300 Notifies that spacing between fuel assemblies in adjacent high density spent fuel racks is 14.5 inches, assuming racks are as close as possible  
STALLINGS, C M Virginia Electric & Power Co 79/06/29 1p

7907310451 Notifies that center-to-center distance between fuel assemblies in adjacent high density spent fuel racks is 14.5 inches  
STALLINGS, C M Virginia Electric & Power Co 79/06/29 1p

7907050291 Forwards Offsite Dose Calculation Manual incorporating guidance of NUREG-0133  
STALLINGS, C M Virginia Electric & Power Co 79/07/03 2pp

--7907050292 Offsite Dose Calculation Manual  
\* Virginia Electric & Power Co 79/06/28 74pp

7907090307 Forwards "Offsite Dose Calculation Manual," for review Submission of process control program not appropriate at this time  
STALLINGS, C M Virginia Electric & Power Co 79/07/03 2pp

--7907090310 "Offsite Dose Calculation Manual"  
HOPPER, D, KELLAND, J Virginia Electric & Power Co 79/06/28 74pp

7907090338 Responds to 790502 ltr re station electrical distribution sys voltages Mods & analyses in progress to verify capability of electrical power sys Results will be forwarded by 790731  
STALLINGS, C M Virginia Electric & Power Co 79/07/05 1p.

7907100581 Requests proposed Tech Spec Change 21 as amend to License NPF-4, changing power range neutron flux negative rate trip Forwards appropriate amend fee  
STALLINGS, C M Virginia Electric & Power Co 79/07/06 6pp

7907170019 Submits supplemental info to util 790619 ltr re addl instrument qualification & justification for use of Barton transmitters  
STALLINGS, C M Virginia Electric & Power Co 79/07/13 2pp

7907260804 Updates status of Type B & C leak tests completed to date Uncompleted tests include safety equipment actuation & response time testing Requests that testing be deferred until next refueling outage  
STALLINGS, C M Virginia Electric & Power Co 79/07/23 3pp.

7907270185 States that addl info re contingency plan requested in NRC 790710 ltr, will be provided by 790831 Amends & comments will apply to both North Anna & Surry stations, since contingency plans are identical  
STALLINGS, C M Virginia Electric & Power Co 79/07/28 1p

7907270191 Submits addl info re environ qualification of instruments, in response to 790822 telcons & 790622 ltrs  
STALLINGS, C M Virginia Electric & Power Co 79/07/25 2pp

7907310255 Forwards supplemental response to NRC 790525 request for info re PWR feedwater lines Describes design, fabrication history & insp & operating history  
STALLINGS, C M Virginia Electric & Power Co 79/07/27 3pp

## Q Inspection reports, IE Bulletins & correspondence

7907020336 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907160237 Evaluates util responses to IE Bulletin 79-06A Forwards mem reviewing Westinghouse rept, "Qualification Testing of Barton Pressure & Differential Pressure Transmitters"  
WILLIAMS, F J Division of Project Management 79/04/24 1p

7907050067 Forwards IE Insp Repts 50-338/79-16 & 50-339/79-22 on 790402-05 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/03 2pp

--7907050071 IE Insp Repts 50-338/79-16 & 50-339/79-22 on 790402-05 No noncompliance noted Major areas inspected LERs, hydraulic snubber & review of startup physics  
WEBSTER, E H, CANTRELL, F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch WHITENER, H L Region 2, Atlanta, Office of the Director 79/05/02 7pp

7907020032 Notification of failure to meet environ qualification for IE-class equipment stipulated in IE Bulletin 79-01  
\* Virginia Electric & Power Co 79/05/07 1p

7907110344 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907240119 Forwards IE Insp Repts 50-338/79-07 & 50-339/79-09 on 790205-09 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/14 2pp

--7907240123 IE Insp Repts 50-338/79-07 & 50-339/79-09 on 790205-09 No noncompliance noted Major areas inspected operating, abnormal, emergency, maint, administrative & temporary procedures  
FORD, E J, MOON, B T, KELL000, P J Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 13pp

7907230734 Forwards IE Insp Repts 50-338/79-18 & 50-339/79-26 on 790424-29 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/16 2pp

--7907230740 IE Insp Repts 50-338/79-18 & 50-339/79-26 on 790424-29 No noncompliance noted Major areas inspected containment integrated leakage rate testing & pipe support & restraint sys  
BROOKS, E H Region 2, Atlanta, Office of the Director MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 3pp

7907100222 Forwards IE Circular 79-0B, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P, Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907060366 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 1p

7907100131 Submits addl response to IE Bulletin 79-04 Util has determined existing design of piping containing 12.5-inch valves is acceptable.  
STALLINGS, C M Virginia Electric & Power Co 79/05/23 2pp.

## DOCKETED ITEMS

7907100042 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
STALLINGS, C M Virginia Electric & Power Co 79/05/24 5pp

7907300008 Forwards IE Insp Rept 50-338/79-08 on 790129-0202 & notice of violation  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/23 2pp

--7907300010 Notice of violation from insp on 790129-0202  
\* Region 2, Atlanta, Office of the Director 79/03/23 5pp

--7907300018 IE Insp Rept 50-338/79-08 on 790129-0208 Noncompliance noted failure to initiate prompt corrective action, inadequate or nonexistent auditing procedures & failure to perform safety analysis  
KELLOGG, P J, ABEHENDEN, M C, JENKINS, H D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 28pp

7907030114 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyster Creek Reactor,"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907180145 Responds to IE Bulletins 78-12, 78-12A & 78-12D, "Atypical Weld Matl in Reactor Pressure Vessel Welds " Info requested will be forwarded to NRC by 790901.  
STALLINGS, C M Virginia Electric & Power Co 79/05/29 1p

7907200223 Forwards IE Bulletin 79-12, "Short Period Scrams at SWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/05/31 2pp

7907190209 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060069 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907250148 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 3pp.

7907130455 Ack receipt of 790606 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-338/79-21  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/14 1p

--7907130478 Responds to NRC 790519 ltr re violation noted in IE Insp Rept 50-338/79-21 Corrective action written procedures for valve checkoff for associated lube oil & cooling water sys established & maintained  
STALLINGS, C M Virginia Electric & Power Co 79/06/06 2pp

--7907130483 Forwards IE Insp Rept 50-338/79-21 on 790430-0503 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/19 2pp

--7907130485 Notice of violation from insp on 790430-0503  
\* Region 2, Atlanta, Reactor Operations Nuclear Support Branch.  
79/05/15 1p

--7907130490 IE Insp Rept 50-338/79-21 on 790430-0503 Noncompliance noted: written procedures for emergency diesel lube oil & cooling water sys not established & maintained.  
DYER, J A, MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/15 6pp

7907020401 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/20 1p

7907230012 Ack receipt of 790606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-19 & 50-339/79-25  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/06/20 1p

--7907230014 Responds to NRC 790514 ltr re violations noted in IE Insp Repts 50-338/79-19 & 50-339/79-25 Corrective actions completed procedures will be reviewed by engineer prior to review by supervisor.  
STALLINGS, C M Virginia Electric & Power Co 79/06/06 3pp

--7907230018 Forwards IE Insp Repts 50-338/79-19 & 50-339/79-25 on 790417-20 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/14 2pp

--7907230024 Notice of violation from insp on 790417-20  
\* Region 2, Atlanta, Reactor Operations Nuclear Support Branch  
79/05/10 1p

--7907230039 IE Insp Repts 50-338/79-19 & 50-339/79-25 on 790417-20 Noncompliance noted failure to follow approved test procedure  
MARTIN, R D, SAVER, R C, WAGNER, A G Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 5pp

7907310181 Ack receipt of 790604 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-13 & 50-339/79-21  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/20 1p

--7907310190 Responds to NRC 790511 ltr re violations noted in IE Insp Repts 50-338/79-15 & 50-339/79-21 Corrective actions' restructured commitment tracking program to include specific statement of commitment.  
STALLINGS, C M Virginia Electric & Power Co 79/06/04 2pp

--7907310194 Forwards IE Insp Repts 50-338/79-15 & 50-339/79-21 on 790305-30 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/11 2pp

--7907310198 Notice of violation from insp on 790305-30  
\* Region 2, Atlanta, Office of the Director 79/05/10 1p

--7907310203 IE Insp Repts 50-338/79-15 & 50-339/79-21 on 790305-30 Noncompliance noted failure to approve past change procedures to controlled drawings by commitment date  
KIDW, M S, CANTRELL, F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 14pp

7907120142 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p.

7907102234 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p.

7907310043 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bypass Piping " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180446 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907050298 Responds to IE Bulletin 79-01, "Environ Qualification of Class IE Equipment " Two potential qualification problems have been identified re chiller equipment & safeguards bldg ventilation fans.  
STALLINGS, C M Virginia Electric & Power Co 79/07/02 36pp

7907310003 Ack receipt of 790619 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-338/79-08  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/03 2pp

--7907310010 Responds to NRC 790525 ltr re violations noted in IE Insp Rept 50-338/79-08. Corrective actions: open audit items shall be closed in manner consistent w/ANSI N45.2.12, Draft 3, Revision 4, 1974.  
STALLINGS, C M Virginia Electric & Power Co 79/06/19 21pp.

7907310389 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 1p



7907250260 Amends Section 5 of 790614 ltr to NRC re IE Bulletin 79-01  
Replacement solenoid operated valves will be installed  
during first appropriate outage following receipt of  
replacements  
STALLINGS, C M Virginia Electric & Power Co 79/07/19 1p

#### R Periodic operating reports & related correspondence

7907130266 Forwards monthly operating rept for June 1979  
STALLINGS, C M Virginia Electric & Power Co 79/07/10 1p

--7907130272 Monthly operating rept for June 1979  
MADISON, W R Virginia Electric & Power Co 79/07/03 3pp

#### B Reportable occurrences, LERs & related correspondence

7907190816 Submits rept of deficiency in safety injection sys piping  
Supports do not meet seismic stress criteria Caused by  
improper input criteria used for bldg displacement  
STALLINGS, C M Virginia Electric & Power Co 79/04/27 2pp

7907250447 Submits info re 790424 Part 21 notification of hazard  
determined on 790424 component cooling heat exchangers  
joints deflected greater than tolerances defined in Tech  
Specs B&W piping installation joints are being realigned  
STALLINGS, C M Virginia Electric & Power Co 79/04/27 2pp

7907090329 Discusses significant deficiency on 790425 security access  
computer program would not operate sys, thereby permitting  
unauthorized personnel access to area Deployed security  
personnel & revised computer program  
STALLINGS, C M Virginia Electric & Power Co 79/05/01 3pp

7907090329 Followup rept to LER 79-083/01T-O high energy line breaks  
inside containment could cause heatup of steam generator  
ref leg, causing level indications higher than actually  
exist Caused by incomplete Westinghouse analysis  
\* Virginia Electric & Power Co 79/06/22 1p

7907030421 Forwards LERs 79-076/03L-O & 79-078/02L-O  
STALLINGS, C M Virginia Electric & Power Co 79/06/29 1p

--7907030425 LER 79-076/03L-O on 790530 quadrant power tilt ratio in  
upper core in excess of Tech Spec limit Cause unknown  
Possibly due to dropped rod cluster control assembly  
rodlets  
CARTWRIGHT, W R Virginia Electric & Power Co 79/06/29 2pp

--7907030429 LER 79-078/03L-O on 790606 leak detected in casing cooling  
pump 1-RB-P-3A, making casing cooling subsystem inoperable  
Caused by unevenly cast facing adjoining "O" ring Corrective  
action "O" ring cleaned & overhauled  
CARTWRIGHT, W R Virginia Electric & Power Co. 79/06/29 2pp

7907060331 Forwards LERs 78-090/03X-1, 79-030/03X-1 & 79-040/03X-1  
STALLINGS, C M Virginia Electric & Power Co. 79/07/02 1p

--7907060332 LER 78-090/03X-1 on 780919 during critical steady state  
operation, axial flux difference deviated more than -5% from  
target Caused by rapid load reduction necessitated by  
clogging strainer Pumps shifted  
CARTWRIGHT, W R. Virginia Electric & Power Co. 79/07/02 3pp.

--7907060333 LER 79-030/03X-1 on 790308, nonconservative gain setting on  
delta-flux signal feeding overpower delta T protection  
circuitry observed Caused by improper setting of delta-flux  
gain Signal recalibr.  
CARTWRIGHT, W R Virginia Electric & Power Co 79/02/07 2pp

--7907060334 LER 79-040/03X-1 on 790326 discovered nonconservative  
output of upper/lower flux signal summing amplifier in  
overpower delta T protection circuitry. Caused by instrument  
drift. Summing amplifier card replaced & delta T recalibr  
CARTWRIGHT, W R Virginia Electric & Power Co 79/03/26 2pp.

7907090269 Forwards LER 79-083/01T-O  
STALLINGS, C. M Virginia Electric & Power Co 79/07/03 1p.

--7907090265 LER 79-083/01T-O on 790621: station personnel informed by  
Westinghouse that main feedline rupture can cause delay in  
protection signals initiated by low-low steam generator  
level Caused by incomplete previous Westinghouse analysis  
CARTWRIGHT, W R. Virginia Electric & Power Co 79/07/03. 2pp

7907110531 Forwards LER 79-079/03L-O.  
STALLINGS, C M. Virginia Electric & Power Co. 79/07/09 1p

--7907110541 LER 79-079/03L-O on 790608 quadrant power tilt ratio of  
1 0292 in upper core & 1 0285 in lower core obtained from  
ex-core detector current calculations Figures exceed Tech  
Spec limits Cause unknown Investigation initiated  
CARTWRIGHT, W R Virginia Electric & Power Co 79/07/06 2pp

7907170215 Forwards LER 79-032/03X-1  
STALLINGS, C M Virginia Electric & Power Co 79/07/12 1p

--7907170221 LER 79-032/03X-1 on 790312 containment vacuum pump suction  
valve TV-CV150A would not remain in closed position when  
operated from control room Caused by Relay & sticking in  
energized position Relay repaired.  
CARTWRIGHT, W R Virginia Electric & Power Co 79/07/09 2pp

7907230571 Forwards LERs 79-082/03L-O & 79-084/03L-O  
STALLINGS, C M Virginia Electric & Power Co 79/07/20 1p.

-7907230576 LER 79-084/03L-O on 790620 pressurizer level channel LT-1460  
declared inoperable & placed in trip condition Caused by  
energizing of welding machines in penetration area Problem  
cleared when welding machines turned off  
CARTWRIGHT, W R Virginia Electric & Power Co 79/07/18 2pp.

--7907230580 LER 79-082/03L-O on 790620 during Mode 1 operation steam  
observed leaking from lagging of trip valve TV-HB111A  
Caused by steam cuts on seat ring gasket surface Surface  
lapped & gasket set replaced  
CARTWRIGHT, W R Virginia Electric & Power Co 79/07/18 2pp.

7907300309 Forwards info requested in 790713 telcon re incore flux map  
analysis results Confirms 790701 meeting to discuss matters  
STALLINGS, C M Virginia Electric & Power Co 79/07/27. 9pp

7907310430 Forwards LER 79-086/03L-O  
STALLINGS, C M Virginia Electric & Power Co 79/07/27. 1p

--7907310436 LER 79-086/03L-O on 790628 weekly surveillance of diesel  
generator batteries exceeded surveillance interval +25%  
Caused by late receipt of NRC addition of surveillance  
requirement to Tech Specs Test 1-PT-B5 revised to add amend  
CARTWRIGHT, W R Virginia Electric & Power Co 79/07/26 2pp

#### U Congressional/Executive Correspondence

7907310261 Informs that investigation into merits of J Allen request  
to revoke OL for facilities has been completed & rept  
issued. Request should be denied Forwards decision, supporting  
rept & ltr to J Allen  
GOBBICK, L. V. Office of the Executive Director for Operations  
79/06/29 1p

--7907310271 Denies 781101 request for revocation of OL Forwards decision  
by Director of IE  
STELLO, V. Office of Inspection & Enforcement. 79/06/25 1p

--7907310277 Decision by Director of IE, per 10CFR2 206, denying J Allen  
781101 request for enforcement action  
STELLO, V. Office of Inspection & Enforcement 79/06/25 8pp

#### DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

##### A. Application/construction stage documents & correspondence

7907110667 Requests schedule for submittal of addl justification to  
demonstrate that Barton pressure & differential transmitters  
will meet performance requirements during hypothesized  
post-accident cooling period  
PARR, O D Light Water Reactors Branch 3. 79/06/01 3pp.

7907090071 Forwards errata to 790402 EIA  
OLDBERG, S. C. Branch 2 79/06/05 1p.

7907060167 FOIA request for NRC records re nuclear power plant at  
North Anna, VA  
GLASSBERG, V M Hirschkop & Orad P C. 79/06/08. 1p.

7907060173 Responds to FOIA request for documents re North Anna, VA  
nuclear power plants Documents available in NRC PDR  
FELTON, J. M. Division of Rules and Records 79/06/13 1p

7907250564 Forwards Amend 11 to License NPF-A, safety evaluation &  
notice of issuance & availability  
PARR, O D, Light Water Reactors Branch 3 79/06/14. 3pp

## DOCKETED ITEMS

--7907250571 Amend 11 to License NPF-4, incorporating new condition re surveillance requirements of emergency diesel generator batteries  
PARR, D D Light Water Reactors Branch 3 79/06/14 19pp

--7907250578 Safety evaluation supporting Amend 11 to License NPF-4  
\* Light Water Reactors Branch 3 79/06/14 2pp

--7907250581 Notice of issuance & availability of Amend 11 to License NPF-4  
PARR, D D Light Water Reactors Branch 3 79/06/14 2pp.

7907310005 Forwards HR Denton 790613 ltr to S Ragone re issuance of OL for facility  
VASSALLO, D Assistant Director for Light Water Reactors  
79/06/15 3pp

--7907310039 Responds to 790522 ltr Issuance of OL will be delayed pending results of investigation of TH1 incident  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/13 2pp

7907303000 Notifies that spacing between fuel assemblies in adjacent high density spent fuel racks is 14.5 inches, assuming racks are as close as possible  
STALLINGS, C M Virginia Electric & Power Co 79/06/29 1p

7907310451 Notifies that center-to-center distance between fuel assemblies in adjacent high density spent fuel racks is 14.5 inches  
STALLINGS, C M Virginia Electric & Power Co 79/06/29 1p

7907050291 Forwards Offsite Dose Calculation Manual incorporating guidance of NUREG-0133  
STALLINGS, C M Virginia Electric & Power Co 79/07/03 2pp

--7907050292 Offsite Dose Calculation Manual  
\* Virginia Electric & Power Co 79/06/28 74pp

7907090307 Forwards "Offsite Dose Calculation Manual," for review  
Submission of process control program not appropriate at this time  
STALLINGS, C M Virginia Electric & Power Co 79/07/03 2pp

--7907090310 "Offsite Dose Calculation Manual"  
HOPPER, D, KELLAND, J Virginia Electric & Power Co 79/06/28 74pp.

7907190432 Defers submittal of rept re implementation of recommendations resulting from TH1 incident Responses will be prepared addressing specific task force recommendations  
PROFFITT, N L Virginia Electric & Power Co 79/07/12 1p

7907190556 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Type A, B & C"  
STALLINGS, C M Virginia Electric & Power Co 79/07/17 1p

--7907190558 "Reactor Containment Bldg Integrated Leak Rate Test, Type A, B & C"  
\* Virginia Electric & Power Co 79/07/17 60pp

7907270185 States that addl info re contingency plan, requested in NRC 790710 ltr, will be provided by 790831 Amends & comments will apply to both North Anna & Surry stations, since contingency plans are identical  
STALLINGS, C M Virginia Electric & Power Co 79/07/25 1p

7907270191 Submits addl info re environ qualification of instruments.  
In response to 780822 telcons & 790622 ltr  
STALLINGS, C M Virginia Electric & Power Co 79/07/25 2pp

7907310255 Forwards supplemental response to NRC 790525 request for info re PHR feedwater lines Describes design, fabrication history & insp & operating history.  
STALLINGS, C M Virginia Electric & Power Co 79/07/27 3pp

7907310446 Notifies that insp of all safety-related sys has been completed & all safety-related sys conform to descriptions in FSAR  
STALLINGS, C M Virginia Electric & Power Co 79/07/27 1p

#### F. Security, medical, emergency & fire protection plans

7907050183 Forwards security plan evaluation rept page changes Mods do not affect 10CFR73.55 review Encl withheld (ref 10CFR2790).  
ARR, D D Light Water Reactors Branch 3. 79/05/21 3pp

7907260406 Notifies that target date for completion of sprinkler sys will be 790815  
BROWN, B C Virginia Electric & Power Co 79/07/23 1p

#### G. Adjudicatory correspondence

7905150023 Forwards NRC testimony re turbine missiles & pumphouse settlement, & professional qualifications of K Campe, M Boyle, J O'Brien, J Burns, A Dromerick, L Heller, R Kiessel & J Lenehan Certificate of Svc encl  
SWANSON, D T Branch 1 79/04/27 125pp

7907120019 Motion by util for summary disposition of all matters in proceeding No genuine issues to be heard on any contention raised by Potomac Alliance & Citizens Energy Forum Affidavit of M Brehmer & Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams 79/05/11 29pp

--7907120021 Statement of matl facts as to which there is no genuine issue to be heard, re contentions by Potomac Alliance & Citizens Energy Forum stated in ASLB 790521 order  
\* Virginia Electric & Power Co 79/05/11 30pp

--7907120027 "Summary of Proposed Mods to Spent Fuel Storage Pool Associated W/Increasing Storage Capacity" Affidavits of RW Calder & HS McKay encl  
\* Virginia Electric & Power Co 78/04/30 76pp

7907110618 Responds to Arnold discovery requests re pumphouse settlement Current info indicates pumphouse elevation has undergone slow settlement since drain was installed  
Supporting documentation encl  
SWANSON, D T Branch 1 79/05/14 5pp

--7907110624 Forwards supplemental info to 751219 ltr re pumphouse settlement  
SHAPER, H K Office of the Executive Legal Director 76/04/14 14pp

--7907110638 Summary of 750430 meeting in Bethesda, MD re pumphouse settlement for svc water reservoir Recommended issuance of show cause order re suspension of reservoir const  
FERGUSON, R L Light Water Reactors Branch 2 75/05/01 3pp

--7907110645 Discusses recommended actions against util re svc water reservoir pumphouse settlement Civil penalty package will be prepared for failure to rept per 10CFR50.55(e)  
BERATAN, L L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/05/05 1p

--7907110654 Submits addl info re stress in svc water lines resulting from pumphouse settlement Preliminary investigation indicates stresses are above code allowables, Util considered problems reportable per 10CFR50.55(e)  
BERATAN, L L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/07/29 2pp

--7907110665 Forwards IE Insp Repts 50-338/75-05 & 50-339/75-05 on 750429 Enforcement action will be addressed at later date  
MOSELEY, N C Region 2, Atlanta, Office of the Director 75/05/20 1p

--7907110678 IE Insp Repts 50-338/75-05 & 50-339/75-05 on 750429 Noncompliance noted failure to rept settlement of svc water reservoir pumphouse per 10CFR 50.55(e)  
COCHRAN, B J, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/05/20 8pp

--7907110687 Summary of 760614 meeting w/util & consultants re foundation of svc water reservoir & svc water pumphouse  
PIKE, W J Division of Project Management 76/07/21 2pp

7907130082 Answer by util to ASLB 790504 notice of hearing No public hearing is necessary in proceeding, since all contentions are subg to summary disposition Opposes any delay in hearing schedule Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams 79/05/14 8pp

7907110726 Interrogatories & document requests for intervenor Citizens Energy Forum submitted by util Contentions were stated in ASLB 790421 order Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams 79/05/17 10pp

7907110746 Util answer to Potomac Alliance 790509 motion to amend petition to intervene. Agrees to introduction of contention re svc water cooling sys Submits improved statement of contention Renews 790511 motion for summary disposition  
CHRISTMAN, J N Hunton & Williams 79/05/17 4pp

- 7907130294 Interrogatories & document request submitted to intervenor Potomac Alliance by util Contentions were stated in ASLB 790421 order Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams 79/05/17 11pp
- 7907180330 Answers by util to Potomac Alliance 790502 objections & Citizens Energy Forum 790503 objections to ASLB 790421 order granting intervention Seeks denial of intervenor requests for mod of order Certificate of Svc encl.  
CHRISTMAN, S N Hunton & Williams 79/05/17 10pp
- 7907180339 Motion by util for interim Tech Spec change Allowable pump house settlement limits should be increased or, in the alternative, raised to level in 10CFR2 717(b) Affidavit of EA Baum & Certificate of Svc encl  
CHRISTMAN, J N Hunton & Williams 79/05/17 10pp
- 7907310566 Forwards Board notification matl re analysis of single rod drop event in Westinghouse three-loop plants Single rod drop could create increase in overall power level of reactor  
SWANSON, D T Branch 1 79/05/18 2pp
- 7907310572 Forwards memo discussing Westinghouse Part 21 notification re analysis of single rod drop accident Recommends memo be provided to North Anna Board  
VASSALLO, D B Assistant Director for Light Water Reactors 79/05/14 1p
- 7907310581 Discusses Board notification re analysis of single rod drop event at Westinghouse facilities Concludes that appropriate Boards should be notified Provides item of notification & considerations re relevancy & materiality  
TEDESCO, R L Assistant Director for Reactor Safety 79/04/23 3pp
- 7907170242 Interrogatories & document requests submitted to intervenor Arnold Requests info re witnesses, documents relied upon in preparing direct case & documents related to turbine missile issue Certificate of Svc encl  
SWANSON, D J Branch 1 79/05/24 4pp
- 7907160131 Requests summary disposition of intervenors Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 27pp
- 7907180638 Motion submitted by Citizens Energy Forum requesting ASLB to allow consolidation w/Potomac Alliance Consolidation will avoid delay in proceeding Certificate of Svc encl  
KRODT, I B Citizens Energy Forum 79/05/25 3pp
- 7907060478 No objection to Potomac Alliance 790509 motion to amend petition to intervene Petition adds contention re svc water cooling sys Certificate of Svc encl  
GOLDBERG, B C Branch 2 79/05/29 3pp
- 7907130331 Responds to NRC 790502 interrogatories & document requests, submitted by Citizens Energy Forum Forwards info re Contentions 1,2 & 5, thermal effects, radioactive emissions & corrosion Certificate of Svc encl  
BOULTON, D A Citizens Energy Forum 79/05/29 11pp
- 7907060501 Responses to NRC interrogatories & document requests Answers Contentions 3,4,6 & 7, re missile accidents, matl integrity, occupational exposure & alternatives Certificate of Svc encl  
DOUGHERTY, J B Potomac Alliance 79/05/30 25pp
- 7907130189 Opposition by util to postponement of 790626 prehearing conference & evidentiary hearing in alternative, requests ASLB to commence hearings by 790609 Affidavit of EA Baum & Certificate of Svc encl  
RINACA, J M Hunton & Williams 79/05/30 16pp
- 7907060390 Forwards util supplementary testimony in response to NRC testimony re svc water pump house settlement RB Beck 760116 ltr to B Ragone & prof qualifications of WR Cartwright encl  
RINACA, J M Hunton & Williams 79/05/31 3pp
- 7907160156 Interrogatories & document requests submitted to NRC by Citizens Energy Forum Requests info re Contentions 1,2 & 5, radioactive emissions & corrosion & thermal effects Certificates of Svc encl  
KRODT, I B Citizens Energy Forum 79/05/31 5pp.
- 7907110081 Extends date for submission of RD Pollard testimony re turbine missile issue until 790611  
SKRUTSKI, R M Atomic Safety and Licensing Appeal Panel 79/06/01 1p.
- 7907170254 Interrogatories & document requests submitted to VEPCO by Citizens Energy Forum Requests info re thermal effects, radioactive emissions & corrosion Certificate of Svc encl  
KRODT, I B Citizens Energy Forum 79/06/01 7pp
- 7907180256 Potomac Alliance motion to obtain answers to interrogatories to NRC  
DOUGHERTY, J B Potomac Alliance 79/06/01 1p
- 7907180265 Interrogatories & document requests for NRC submitted by Potomac Alliance Requests info on spent fuel pool re alternatives, tornado damage, turbine missile damage, defective fuel rods & changes in NRC requirements  
DOUGHERTY, J B Potomac Alliance 79/06/01 10pp
- 7907180271 Request for documents identified by NRC in response to Potomac Alliance 790601 interrogatory Includes request for util FBAR & Tech Specs applicable to operations of plant  
DOUGHERTY, J B Potomac Alliance 79/06/01 4pp
- 7907180279 Interrogatories & document requests to util submitted by Potomac Alliance Requests info on spent fuel pool re diagram, const progress, transfer of fuel, alternatives to proposed mod & logistics of handling spent fuel  
DOUGHERTY, J B Potomac Alliance 79/06/01 22pp
- 7907060438 Requests denial of util 790511 motion for summary disposition Citizens Energy Forum states motion is premature & ignores unresolved issues re proposed mod  
KRODT, I B Citizens Energy Forum 79/06/05 5pp
- 7907060444 Statement of matl facts as to which there is genuine issue to be heard, submitted by Citizens Energy Forum Discusses issues re thermal effects, emissions & corrosion Certificate of Svc encl  
BOULTON, D A Citizens Energy Forum 79/06/05 5pp
- 7907060457 Responds to util 790505 motion for summary disposition Requests that ASLB refuse application or order continuance to reply in alternative, seeks denial of motion Affidavits cannot present facts essential to opposition to motion  
DOUGHERTY, J B Potomac Alliance 79/06/05 5pp
- 7907060464 Statement of matl facts to which there is genuine issue to be heard in response to util 790505 motion for summary disposition Affidavit of JB Dougherty & Certificate of Svc encl  
DOUGHERTY, J B Potomac Alliance 79/06/05 4pp
- 7907130128 Supports util 790511 motion for summary disposition re Contentions 1,2 (in part) & 4-7 Affidavits of AM Drometick, PH Leach, FC Kornegay, JB Werniel, HE Krug, QB Georgier, MD Houston & TD Murphy & Certificate of Svc encl  
GOLDBERG, B C Branch 2 79/06/05 59pp
- 7907130130 Requests denial of util 790517 motion for ASLB to grant interim Tech Specs change re allowable svc water pump house settlement limits Request is unnecessary & w/o legal authority Certificate of Svc encl  
SWANSON, D T Branch 1 79/06/06 8pp
- 7907130368 Answers submitted by Potomac Alliance to util interrogatories & document requests re contentions on radioactive emissions missile accidents & matl integrity Notice of appearance of LB Lampert on behalf of intervenors  
DOUGHERTY, J B, LEMPERT, L B Potomac Alliance 79/06/06 14pp.
- 7907130371 Errata to Potomac Alliance answer to util motion for summary disposition, Certificate of Svc encl  
DOUGHERTY, J B Potomac Alliance 79/06/07 2pp
- 7907170240 Reschedules prehearing conference in Charlottesville, VA from 790626 to 0709 Parties w/o intervenor status may make limited appearance on matters within scope of hearing.  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/06 4pp
- 7907180258 Amends 790421 order to add Potomac Alliance contention re adequacy of svc water cooling sys  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/06 2pp
- 7907310083 Grants Citizens Energy Forum 790525 motion for consolidation w/Potomac Alliance for purposes of proceeding  
DEALE, V B Atomic Safety and Licensing Board Panel 79/06/06 1p
- 7907180774 No opposition by util to Citizens Energy Forum & Potomac Alliance motion for consolidation Util reserves right to oppose future motion necessitated by consolidation, if motions appear to delay proceedings, Certificate of Svc encl.  
RINACA, J M Hunton & Williams 79/06/07 4pp.

## DOCKETED ITEMS

907270372 Requests to make limited appearance statement at licensing prehearing  
STONE, S. T. Affiliation Unknown 79/06/07 1p

907130302 Order overruling Potomac Alliance 790302 objections & Citizens Energy Forum 790503 objections to ASLB 790421 order designating contentions ASLB reaffirms 790421 order  
DEALE, V. B. Atomic Safety and Licensing Board Panel 79/06/08 6pp

907230539 Requests to make limited appearance statement at licensing prehearing  
\* Affiliation Unknown 79/06/09 1p

907260357 Requests to make limited appearance statement at licensing prehearing  
MAHLER, H. R. Affiliation Unknown 79/06/09 1p

907180606 Answers submitted by Citizens Energy Forum to util 790517 interrogatories & document requests. Submits info on contentions re thermal effects, radioactive emissions, spent fuel pool & corrosion Certificate of Svc encl  
KRODT, I. B. Citizens Energy Forum 79/06/11 15pp

907230362 Requests to make limited appearance statement at licensing prehearing  
MILLER, J. Affiliation Unknown 79/06/11 1p

907230529 Comments on proposed storage of spent fuel & sinking of pump house. Concerned about safety  
ROGERS, J. H. Affiliation Unknown. 79/06/11 1p

907250085 Requests to make limited appearance statement at licensing prehearing  
MILLAR, F. Potomac Alliance 79/06/11 1p

907300577 Requests to make limited appearance statement at licensing prehearing  
BLAUGROVE, N. Affiliation Unknown 79/06/11 1p

907180589 Answer by util to NRC 790511 brief re ALAB-538 Reasonable nexus does not exist between nonsafety-grade equipment issue & issues in North Anna proceeding ASLB does not have jurisdiction over equipment issue Certificate of Svc encl  
CHRISTMAN, J. N. Hunton & Williams 79/06/13 6pp

907180744 Requests to amend petition to intervene submitted by Potomac Alliance & Citizens Energy Forum. Seeks addition of contention re ability of spent fuel pool to withstand seismic events. Certificate of Svc encl.  
DOUGHERTY, J. B. Potomac Alliance 79/06/15 7pp.

907230548 Requests to make limited appearance statement at licensing prehearing  
HUGH, S. Affiliation Unknown 79/06/15 1p

907180591 Request by util that ASLB authorize immediate installation of high-density spent fuel storage racks for use in storage of up to 243 spent fuel assemblies. Interim relief is requested until issues are resolved Certificate of Svc encl.  
RINACA, J. M. Hunton & Williams 79/06/18 27pp

907300270 Order partially granting util 790511 motion for summary disposition. Grants contentions re thermal effects, matl integrity, corrosion, occupational exposure & alternatives. Grants contention on radioactive emissions  
DEALE, V. B. Atomic Safety and Licensing Board Panel 79/06/18 4pp

907180528 Supplemental response to util motion for summary disposition re ASLB 790618 order. Supports motion re Contentions 2 & 3 & svc water cooling sys. Affidavits of Hermal, Chan, Ferrell & Campe & Certificate of Svc encl  
GOLDBERG, S. C. Branch 2 79/06/25 30pp

907180787 Notice of denial of request by North Anna Environ Coalition for revocation of util DL  
STELLO, V. Office of Nuclear Reactor Regulation 79/06/25 2pp

-7907180794 Denies request for revocation of util DL  
STELLO, V. Division of Operating Reactors 79/06/25 1p

-7907180803 Denies North Anna Environ Coalition 781101 request for revocation of util DL. Util complied w/Tech Specs in reporting pumphouse settlement  
STELLO, V. Division of Operating Reactors 79/06/25 8pp

-7907180809 Notifies of decision re J Allen 781101 ltr. Denies request for revocation of util DL  
GOBBICK, L. V. Office of the Executive Director for Operations. 79/06/25. 1p

--7907180816 Forwards J Allen 781101 ltr  
BYRD, H. F. Senate 78/12/07 1p

--7907180827 Requests assistance in obtaining responses to 780902 ltr to JW Moorman & 781101 ltr to NRC re false statements dealing w/abnormal settlement of plant  
ALLEN, J. North Anna Environmental Coalition 78/11/01 1p

7907180714 Orders deferral of action of 790402 Board notification re nonsafety-grade equipment ASLB jurisdiction to entertain new matters is dependent upon existence of reasonable nexus between issues. Careful consideration is necessary  
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 79/06/26 11pp

#### J Insurance & indemnity information

7907130315 Forwards Endorsements 17-19 to MAELU Policy MF-96  
KELLY, P. J. Johnson & Higgins Insurance 79/07/09. 4PP

#### Q Inspection reports, IE Bulletins & correspondence

7907020336 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl."  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907050067 Forwards IE Insp Repts 50-33B/79-16 & 50-339/79-22 on 790402-05 No noncompliance noted  
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/03 2pp

--7907050071 IE Insp Repts 50-33B/79-16 & 50-339/79-22 on 790402-05 No noncompliance noted. Major areas inspected LERs, hydraulic snubber & review of startup physics  
WEBSTER, E. H., CANTRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch WHITENER, H. L. Region 2, Atlanta, Office of the Director 79/05/02 7pp

7907110344 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/05/07 2pp.

7907110721 Forwards IE Insp Repts 50-339/79-24, 50-404/79-02 & 50-405/79-02 on 790417-19 No noncompliance noted  
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/08 2pp

--7907110743 IE Insp Repts 50-339/79-24, 50-404/79-02 & 50-405/79-02 on 790417-19 No noncompliance noted. Major areas inspected QA procedures, work activities & records for extended const delay & hydraulic snubber installation  
ANO, W. P., BRYANT, J. C. Region 2, Atlanta, Office of the Director 79/05/07 5pp

7907230483 Forwards IE Insp Rept 50-339/79-27 on 790425-27 No noncompliance noted  
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 79/05/11 2pp

--7907230488 IE Insp Rept 50-339/79-27 on 790425-27. No noncompliance noted. Major areas inspected matl control & accounting  
HODGES, J. W. Region 2, Atlanta, Office of the Director. GILLESPIE, F. P. Region 2, Atlanta, Safeguards Branch 79/05/11 4pp.

7907240119 Forwards IE Insp Repts 50-33B/79-07 & 50-339/79-09 on 790205-09 No noncompliance noted  
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/14 2pp

--7907240123 IE Insp Repts 50-33B/79-07 & 50-339/79-09 on 790205-09 No noncompliance noted. Major areas inspected: operating, abnormal, emergency, maint, administrative & temporary procedures  
FORD, E. J., MOON, D. T., KELLOGG, P. J. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09. 13pp.

7907240337 Forwards IE Insp Rept 50-339/79-31 on 790423-27. No noncompliance noted  
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/14. 2pp.

--7907240347 IE Insp Rept 50-339/79-31 on 790423-27. No noncompliance noted. Major areas inspected: startup test records, preoperational testing QA, preoperational test records, operating staff training & safety committee mgt.  
BROWNLEE, V. L. Region 2, Atlanta, Office of the Director. KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/11. 7pp.

# DOCKETED ITEMS

7907230734 Forwards IE Insp Repts 50-338/79-18 & 50-339/79-26 on 790424-29 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/15 2pp

--7907230740 IE Insp Repts 50-338/79-18 & 50-339/79-26 on 790424-29 No noncompliance noted Major areas inspected containment integrated leakage rate testing & pipe support & restraint sys  
BROOKS, E H Region 2, Atlanta, Office of the Director  
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 5pp

7907100222 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907240189 Forwards IE Insp Rept 50-339/79-29 on 790515 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/21 2pp

--7907240192 IE Insp Rept 50-339/79-29 on 790515 No noncompliance noted Major areas inspected licensee action on previous insp findings  
JENKINS, H D, RUHLMAN, W A, KELLOGG, P J Region 2, Atlanta, Office of the Director 79/05/18 6pp

7907110127 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907100186 Responds to IE Bulletin 79-02 Discusses Items 1-4 re installed pipe support base plates w/concrete anchor bolts Procedures meet criteria  
BROWN, B C Virginia Electric & Power Co 79/05/24 3pp

7907030114 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907180145 Responds to IE Bulletins 78-12, 78-12A & 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds" Info requested will be forwarded to NRC by 790901  
STALLINGS, C M Virginia Electric & Power Co 79/05/29 1p

7907190511 Responds to IE Bulletin 79-04 All necessary mods have been made & actual valve weights have been incorporated into piping analysis, where required  
BROWN, B C Virginia Electric & Power Co 79/05/30 4pp

7907200223 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907190209 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Bolonoid Valves)." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp

7907060069 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907190347 Responds to IE Bulletin 79-03 Interim rept reveals that only one single fitting was made by Yongstown Welding & Engineering Co Final rept expected 790711.  
BROWN, B C Virginia Electric & Power Co 79/06/11 3pp

7907230148 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp

7907020401 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907230012 Ack receipt of 790606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-19 & 50-339/79-25.  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/20 1p

--7907230014 Responds to NRC 790514 ltr re violations noted in IE Insp Repts 50-338/79-19 & 50-339/79-25 Corrective actions completed procedures will be reviewed by engineer prior to review by supervisor  
STALLINGS, C M Virginia Electric & Power Co 79/06/06 3pp

--7907230018 Forwards IE Insp Repts 50-338/79-19 & 50-339/79-25 on 790417-20 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/14 2pp

--7907230024 Notice of violation from insp on 790417-20  
\* Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 1p

--7907230039 IE Insp Repts 50-338/79-19 & 50-339/79-25 on 790417-20 Noncompliance noted failure to follow approved test procedure  
MARTIN, R D, SAVER, R C, WAGNER, A G Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 5pp

7907310181 Ack receipt of 790604 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-15 & 50-339/79-21  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/06/20 1p

--7907310190 Responds to NRC 790511 ltr re violations noted in IE Insp Repts 50-338/79-15 & 50-339/79-21 Corrective actions restructured commitment tracking program to include specific statement of commitment  
STALLINGS, C M Virginia Electric & Power Co 79/06/04 2pp

--7907310194 Forwards IE Insp Repts 50-338/79-15 & 50-339/79-21 on 790305-30 & notice of violation  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/11 2pp

--7907310198 Notice of violation from insp on 790305-30  
\* Region 2, Atlanta, Office of the Director 79/05/10 1p

--7907310203 IE Insp Repts 50-338/79-15 & 50-339/79-21 on 790305-30 Noncompliance noted failure to approve past change procedures to controlled drawings by commitment date  
KIDD, M S, CANTRELL, F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 14pp

7907120142 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110234 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907310043 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/23 2pp

7907180340 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180446 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 3pp

7907310389 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 1p

B. Reportable occurrences, LERs & related correspondence

7907090359 Advises that rept submitted 790606 re electrical fault on Class IE 480-volt motor control ctr was intended to constitute 5-day rept per 10CFR21 Ltr should also be considered final rept per 10CFR50.55(e).  
BROWN, B C Virginia Electric & Power Co 79/06/14 1p

# DOCKETED ITEMS

120382 Follows up 790627 deficiency rept Heating of steam generator  
level ref legs after high energy line break inside  
containment not considered in original Westinghouse  
analysis Problem being reanalyzed Results expected soon  
OWN, S C Virginia Electric & Power Co 79/07/02 3pp

250326 Final deficiency rept re failure of inside recirculation  
ray pump motors Motors tested satisfactorily Qualification  
will be verified GE topical rept to be submitted by 790727  
OWN, S C Virginia Electric & Power Co 79/07/19 2pp

## Congressional/Executive Correspondence

310261 Informs that investigation into merits of J Allen request  
revoke QL for facilities has been completed & rept  
sued Request should be denied Forwards decision, supporting  
pt & ltr to J Allen  
SBICK, L V Office of the Executive Director for Operations  
7/06/29 1p.

07310271 Denies 7B1101 request for revocation of QL Forwards decision  
by Director of IE  
STELLD, V Office of Inspection & Enforcement 79/06/25 1p

07310277 Decision by Director of IE, per 10CFR2 206, denying J Allen  
7B1101 request for enforcement action  
STELLD, V Office of Inspection & Enforcement 79/06/25 8pp

## ET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

### Application/construction stage documents & correspondence

170072 Forwards Certificate of Svc for Amend 24 to amended &  
stituted application for licenses  
TERB, B R Detroit Edison Co 79/07/11 3pp.

### Security, medical, emergency & fire protection plans

240583 Notification of 790717-19 meeting w/Detroit Edison Co &  
Libert Associates to tour facility as part of fire  
protection review  
NTNER, L L Light Water Reactors Branch I 79/06/25 4pp

130417 Forwards Amend 1 to physical security plan Plan withheld  
(# 10CFR2 790)  
NS, W H Detroit Edison Co 79/07/11 2pp

### Judiciary correspondence

050450 Advises of change of address for counsel as of 790521.  
IGHT, H H LeBoeuf, Lamb, Leiby & MacRae 79/05/22 2pp

020479 Citizens for Employment & Energy Interrogatories addressed  
Detroit Edison, per 790321 order Certificate of Svc encl  
GFRIED, K A Citizens for Energy & Employment 79/05/25 5pp

07020480 Notice of appearance on behalf of Citizens for Employment  
& Energy  
IEGFRIED, K A Citizens for Energy & Employment 79/05/25 1p

190485 Detroit Edison objections to Citizens for Employment &  
ergy interrogatories & requests for production of  
documents served on 790525 Certificate of Svc encl.  
OT, H H LeBoeuf, Lamb, Leiby & MacRae 79/06/25 14pp

000214 Detroit Edison responses to intervenor Citizens for  
Employment & Energy 790525 interrogatories  
OT, H H LeBoeuf, Lamb, Leiby & MacRae 79/06/29 23pp

### ility Final Safety Analysis Report (FSAR) & amends

050123 Forwards Amend 24 to FSAR, BL-3647, "Structural Design  
Assessment for Safe-End Break," & drawings  
IGHT, H H LeBoeuf, Lamb, Leiby & MacRae 79/06/29 3pp

07050127 Amend 24 to FSAR.  
Detroit Edison Co 79/06/30 100pp

07050129 "Structural Design Assessment for Safe-End Break," prepared  
by Bargent & Lundy Engineers  
Detroit Edison Co 79/03/22 55pp.

110326 Submits updated Amend 24 instruction sheets.  
FTB, J NUS Corp. 79/07/10 4pp.

## G Inspection reports, IE Bulletins & correspondence

7907130310 Forwards IE Insp Rept 50-341/79-11 on 790417-18 No  
noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety  
Branch 79/05/04 2pp

--7907130320 IE Insp Rept 50-341/79-11 on 790417-18 No noncompliance  
noted Major areas inspected radiological preoperational  
monitoring program & results for 1978 & terrestrial  
monitoring program  
GREER, R J, ESSIG, T H Region 3, Chicago, Office of the  
Director. 79/05/03 6pp

7907200314 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/05/31  
1p

7907190258 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240287 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/07  
1p

7907260160 Forwards IE Insp Rept 50-341/79-12 on 790801-04 No  
noncompliance noted.  
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering  
Support Branch 79/06/07 2pp

--7907260169 IE Insp Rept 50-341/79-12 on 790801-04 No noncompliance  
noted Major areas inspected followup of previously  
identified noncompliances & unresolved items, 10CFR50 55(a)  
repts, torus mod & safety-related piping records  
WESCOTT, H M, HUGHES, J, KNOP, R C Region 3, Chicago, Office of the  
Director 79/06/04 15pp

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures"  
forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp

7907020252 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys "  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/11  
1p

7907190086 Ack receipt of 790322 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Rept 50-341/79-09  
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering  
Support Branch 79/06/14 1p

--7907190092 Responds to NRC ltr re violations noted in IE Insp Rept  
50-341/79-09 Corrective actions will develop updated welding  
insp certification for personnel required to submit results  
of eye exams.  
HINES, E. Detroit Edison Co 79/05/22 6pp

7907020426 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/20.  
1p

7907120229 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts," Action  
required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907130119 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
KEPLER, J. G. Region 3, Chicago, Office of the Director 79/06/25  
1p

7907060312 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl." No action required  
KEPLER, J. G. Region 3, Chicago, Office of the Director. 79/06/26.  
1p.

7907050473 Forwards IE Circular 79-11, "Design/Const Interface  
Problem." No action required  
KEPLER, J. G. Region 3, Chicago, Office of the Director 79/06/27.  
1p

7907180410 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/28 1p

7907130267 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/02 1p

7907310334 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/11 1p

7907310409 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/13 1p

7907260181 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/18 1p

7907260389 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/18 1p

#### 9 Reportable occurrences, LERs & related correspondence

7907090078 Ack receipt of 790525 ltr re core spray impeller vane cracks Review of matter will be completed during future insp  
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/14 1p

7907200498 Ack receipt of 790525 ltr re variation in properties of Class IE cable jacketing Review will be completed during future insp  
FIORELLI, O Region 3, Chicago, Office of the Director 79/06/14 1p

#### DOCKET 50-344 TROJAN NUCLEAR PLANT, UNIT 1

##### F Security, medical, emergency & fire protection plans

7907190590 Forwards Amend B to radiological emergency response plan  
GOODWIN, C Portland General Electric Co 79/07/17 1p

--7907190400 Amend B to radiological emergency response plan  
\* Portland General Electric Co 79/05/31 190pp

7907300366 Forwards replacement pages for Amend B to PGE-1012, fire protection review  
GOODWIN, C Portland General Electric Co 79/07/27 1p

--7907300373 Amend B to PGE-1012, fire protection review  
LIPPINCOTT, S M Portland General Electric Co PGE-1012 79/07/27 88pp

##### Q Adjudicatory correspondence

7907030207 Based on review of all applications for amend to facility license, determined that none have any bearing on Phase II issues  
GRAY, J R Branch 1 79/05/04, 1p

7907190366 Second set of interrogatories & document requests to E Rosolie, pro se & Coalition for Safe Power, & N Bell & Consolidated Intervenor  
JOHNSON, R W Portland General Electric Co 79/05/08 18pp.

--7907190370 Forwards list of requests for design changes per mod program described in rept on mod for control bldg Changes & additions to piping sys will qualify sys for response spectra, per PGE-1020, App B  
JOHNSON, R W Portland General Electric Co. 79/05/09 2pp.

--7907190375 Forwards answer to Question 3 re fire test data. Util has supplied info to NRC re Question 4, number of workers & type of work. W/o encl  
ERICKSON, L W, Portland General Electric Co. 79/05/08 1p

7907030179 Forwards copies of 790329-30 prehearing conference transcripts W/o encl  
GRAY, J R Branch 1 79/05/10 1p

7907130517 Forwards BAND 77-1927, "Transport of Radionuclides in Urban Environs Working Draft Assessment & Commission Info Rept," 780614 BECY-78-311 & 781109 BECY-78-311A W/o encl  
ULMAN, M B Operations & Administrative Division 79/05/15 2pp

7907260171 Response by Coalition for Safe Power to second set of interrogatories submitted by util Forwards until 790307 memo & article from 790310 "OR Statesman " Certificate of Svc encl  
ROBDLIE, E Coalition for Safe Power 79/05/30 8pp

7907060521 Forwards DC Circuit Court of Appeals 790523 decision in MN v NRC & New England Coalition on Nuclear Pollution v NRC NRC must clarify "reasonable assurance" of available disposal methods for radwastes  
GRAY, J R Branch 1 79/06/01 19pp

7907130081 Requests that ASLB grant order to compel intervenor N Bell & Consolidated Intervenor to respond to util 790508 second set of interrogatories Questions were directed to contentions admitted as issues Certificate of Svc encl  
JOHNSON, R W Portland General Electric Co AXELROD, M, CARR, A V Lowenstein, Newman, Reis, Axelrad & Toll 79/06/04 4pp

7907030453 Grants limited continuance to hearing schedule established in ASLB 790412 order Definite date for commencement of hearings will be set when NRC has completed SER All parties will continue discovery on matters not related to SER  
MILLER, M E Atomic Safety and Licensing Board Panel 79/06/05 3pp

7907060520 Takes no position re util 790304 motion to compel N Bell & Consolidated Intervenor to respond to util second set of interrogatories Motion involves discovery between util & intervenor; NRC does not intend to file further response  
GRAY, J R Branch 1 79/06/06 1p

7907130051 Interrogatories & document requests for State of OR NRC asks for witnesses, testimony, publications & evaluations proposed by state in preparation for proceedings Certificate of Svc encl  
GRAY, J R Branch 1 79/06/11 7pp

7907180739 Requests ASLB to compel intervenor E Rosolie & Coalition for Safe Power to respond fully to util 790508 second set of interrogatories 14, 15c & d & 16-18 Certificate of Svc encl  
JOHNSON, R W Portland General Electric Co AXELROD, M, CARR, A V Lowenstein, Newman, Reis, Axelrad & Toll 79/06/11 16pp

7907180716 Requests that ASLB compel Coalition for Safe Power to respond to NRC 790515 second set of interrogatories  
GRAY, J R Branch 1 79/06/14, 1p

--7907180719 Requests that ASLB compel Consolidated Intervenor to respond to NRC 790515 second set of interrogatories Certificate of Svc encl  
GRAY, J R Branch 1 79/06/14 3pp

7907180772 Order directing Consolidated Intervenor & Coalition for Safe Power to respond promptly to NRC 790515 second set of interrogatories. Order relates to NRC 790614 request  
MILLER, M E Atomic Safety and Licensing Board Panel 79/06/15, 1p

7907180712 Forwards list of requests for design changes associated w/mod program described in rept on design mods (PGE-1020) Util will continue to inform ASLB re 790330 prehearing conference. Certificate of Svc encl  
JOHNSON, R W Portland General Electric Co 79/06/20 4pp

7907240275 Response to NRC interrogatories submitted by E Rosolie, & Coalition for Safe Power. Certificate of Svc encl  
ROBDLIE, E Coalition for Safe Power. 79/06/23 2pp.

7907240310 Response submitted by State of OR to NRC interrogatories Questions concern hearing witnesses, testimony, documents supporting testimony & scheduling of proposed mod Affidavit of PW Ostrander & Certificate of Svc encl.  
REDDEN, J A, OSTRANDER, F W Oregon, State of. 79/06/25 9pp

7907190662 Orders extension of NRC review of ALAB-531, pending further notice, while NRC considers response to remand of ALAB-435  
CHILK, S J, Office of the Secretary of the Commission. 79/06/29 1p

# M General correspondence

7907110737 Forwards info in response to 790502 request for USGS seismic studies pertaining directly to design & const  
BALSLEY, J R Interior, Dept of 79/05/01 22pp

# J Insurance & indemnity information

7907120635 Forwards Endorsements 31 & 32 to MAELU Policy HF-86  
WILSON, F R Portland General Electric Co 79/07/05 3pp

# P. Operating license stage documents & correspondence

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design re TH1-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907030187 FOIA request for detailed listing of 1978-79 releases of transuranium series particles from facility  
NEPOM, D L Nepom & Ross. 79/05/07 1p

7907310593 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSS W/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/15 1p

7907020236 Summary of 790512 meeting w/Portland General Electric re auxiliary feedwater sys  
TRAMMELL, C Operating Reactors Branch 1 (Pre 790625) 79/05/18 5pp

7907060239 Forwards request for addl info re review of PGE-1020, "Rept on Design Mod for Control Bldg," dtd 790114  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/18 8pp

7907300568 Notification of 790613-14 site visit to review proposed mods to restore seismic capacity  
TRAMMELL, C M Operating Reactors Branch 1 79/05/31 4pp

7907110082 Notification of 790608 meeting w/util in Bethesda, MD to discuss environ qualification of existing transmitters inside containment & qualification of replacements  
TRAMMELL, C M Operating Reactors Branch 1 (Pre 790625) 79/06/04 1p

7907030184 Responds to 790507 request for records relating to releases of transuranium series particles from facility Lists documents where info may be found  
FELTON, J M Division of Rules and Records 79/06/03 2pp

7907110156 Forwards Westinghouse response to NRC questions re main feedwater & auxiliary feedwater sys  
DURAISHAWY, S ACRS - Advisory Committee on Reactor Safeguards 79/06/07 1p

7907180230 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W " W/o encl  
GRIMES, S K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907240538 Forwards NRC 790604 ltr to Westinghouse requesting addl info re small break LOCA analyses & analysis methods NRC will eventually require documentation re applicability of Westinghouse results to analyses at facility  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/11 2pp.

7907300121 Responds to OR DOE 790301 ltr re generic safety issues & seismic, environ & radiation qualification of plant electrical equipment Response by Westinghouse to OR DOE Question 1 3 encl  
STELLG, V. Division of Operating Reactors 79/06/11 11pp

7907300024 Summarizes 790613-14 site visit & 790615 meeting w/Bechtel in San Francisco, CA to review proposed seismic mod to control bldg. Attendance list & request for addl info encl.  
TRAMMELL, C M Operating Reactors Branch 1 (Pre 790625) 79/06/20 14pp.

7907250071 Summary of 790608 meeting w/util in Bethesda, MD re environ qualification of pressure & differential pressure transmitters inside containment  
TRAMMELL, C M Operating Reactors Branch 1 (Pre 790625) 79/06/22 13pp

7907260068 Forwards Amend 41 to License NPF-1, safety evaluation & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/22 3pp

--7907260088 Amend 41 to License NPF-1, deleting pressurizer level as input to safety injection actuation & requiring safety injection actuation based on two-out-of-three channels of low pressurizer pressure  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/22 11pp

--7907260094 Safety evaluation supporting Amend 41 to License NPF-1  
\* Operating Reactors Branch 1 (Pre 790625) 79/06/22 2pp

--7907260102 Notice of issuance & availability of Amend 41 to License NPF-1  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/06/22 2pp

7907100462 Notifies that DOE 790612 meeting of Energy Facility Biting Council authorized DOE to request info re auxiliary feedwater sys, environ qualification of equipment & control/protective interactions altering safety.  
FRANK, L Energy, Dept of 79/06/27 5pp

7907030462 Forwards responses to 14 of 50 questions submitted in NRC 790518 ltr Will submit remaining responses by 790706  
JOHNSON, R W Portland General Electric Co 79/06/29 59pp

7907110474 Forwards Bechtel responses to NRC informal questions raised during 790613-14 site visit Questions concern const details re structural mod of control-fuel-auxiliary bldg complex  
JOHNSON, R W Portland General Electric Co 79/07/05 1p

7907110479 Forwards Bechtel responses to NRC 790518 ltr re bolt assembly dead loads & block & beam to column connection capacities Balance of responses will be submitted 790710.  
Certificate of Bvc encl  
JOHNSON, R W Portland General Electric Co 79/07/06 55pp

7907170175 Forwards responses to remaining questions from 790518 ltr, re effects of creep & shrinkage on strength & stiffness of complex walls Responses prepared by Bechtel Corp  
Certificate of Bvc encl  
BROEHL, D J Portland General Electric Co. 79/07/10 57pp

7907240330 Forwards revised pages for Revision 2 to "Rept on Design Mods for Trojan Control Bldg" (PGE-1020) prepared by Bechtel Revision 2 supersedes encls to 790117 & 790402 ltrs & amends 790117 request Certificate of Bvc encl  
BROEHL, D J. Portland General Electric Co 79/07/20. 44pp

# Q Inspection reports, IE Bulletins & correspondence

7907050407 Responds to IE Bulletin 79-03 No ASME SA-312 Type 304 piping mfg by Youngstown Welding & Engineering Co used or planned for use in safety-related sys.  
GOODWIN, C Portland General Electric Co 79/04/20 1p

7907050400 Responds to IE Bulletin 79-04 re incorrect weights for Velan check valves in piping analyses Definitive info unavailable on six Velan check valves installed at facility Final rept will be submitted when outstanding info is available.  
BROEHL, D J Portland General Electric Co 79/05/01. 2pp.

7907300119 Forwards IE Insp Rept 50-344/79-08 on 790402-30 & notice of violation  
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/16. 2pp

--7907300125 Notice of violation from insp on 790402-30  
\* Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/05/16 1p

--7907300135 IE Insp Rept 50-344/79-08 on 790402-30, Noncompliance noted failure to perform Tech Spec surveillance, Paragraph 2.  
MALHROS, M H Region 5, San Francisco, Office of the Director  
STERNBERG, D. M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/16 7pp

7907090183 Responds to IE Bulletin 79-10 by forwarding statistical data re requalification training program  
GOODWIN, C Portland General Electric Co. 79/05/18. 3pp.

7907270270 Forwards IE Insp Rept 50-344/79-09 on 790327-30 No noncompliance noted  
CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/21 2pp.



--7907270276 IE Insp Rept 50-344/79-09 on 790327-30 No noncompliance noted Major areas inspected responses to IE bulletins & circulars, LERs, document control, mgt controls & followup on previous insp items  
JOHNSON, P H, JOHNSON, A D, STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/21 5pp

7907240610 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790530 in Bethesda, MD  
SCHWENKER, A Operating Reactors Branch 1 (Pre 790625) 79/05/22 4pp

7907090146 Responds to IE Bulletins 79-12, 12A & 12B Reactor vessel weld matl requested is contained in Chicago Bridge & Iron Co generic rept as Part 2  
BROEHL, D J Portland General Electric Co 79/05/29 1p

7907200370 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/31 1p

7907190425 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p

7907060030 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07 1p

7907300219 Forwards IE Insp Rept 50-344/79-10 on 790501-31 No noncompliance noted  
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/19 2pp

7907300233 IE Insp Rept 50-344/79-10 on 790501-31 No noncompliance noted Major areas inspected plant operations, maint, physical security surveillance testing calibr review & audit & radiological protection operations.  
STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/19 8pp

7907020449 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p.

7907120010 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/06/21 1p

7907110201 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p.

7907030432 Requests prompt review & issuance of requested License Change Application 26. Revised inservice insp program will be submitted in 30-60 days No insp will be performed until 1980 refueling outage  
GOODWIN, C Portland General Electric Co 79/06/25 2pp

7907120622 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bypass Piping " Licensee action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/25 1p.

7907060218 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p.

7907100530 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/06/28 1p.

7907130208 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys." Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p.

7907230780 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

7907300462 IE Insp Rept 50-344/79-10 No noncompliance noted Major areas inspected plant operations, physical protection, followup to IE Bulletins 79-02 & 79-06A, maint, surveillance testing & calibr  
Region 5, San Francisco, Office of the Director 79/07/06 8pp

7907180703 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/11 1p

7907310397 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260274 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

#### R Periodic operating reports & related correspondence

7907120608 Forwards monthly operating rept for June 1979  
WITHERS, B D Portland General Electric Co 79/07/05 1p

--7907120613 Monthly operating rept for June 1979  
BAIR, G O Portland General Electric Co 79/07/05 4pp

#### S Reportable occurrences, LERs & related correspondence

7907090245 Discusses deficiency re impeller locknut design for containment spray pumps mfg by Ingersoll-Rand Co Locking action modified to include use of set screw & locking tabs  
Pump mod to be completed by 790615  
GOODWIN, C Portland General Electric Co 79/04/15 4pp

7907020284 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/06/05 1p

7907030193 Forwards PNO-79-67AB  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907030235 Forwards PNO-79-67AT, "Nuclear Incident at TMI "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/06/19 1p

7907050370 Followup rept re high energy line breaks inside containment which may result in heatup of steam generator (S/O) level measurement ref leg will change S/O Low-Low level trip point from 5-13% prior to startup.  
WITHERS, B D Portland General Electric Co 79/06/26 7pp.

7907050833 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/06/26 1p.

7907130386 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/07/03 1p

7907110422 Forwards LER 79-011/01T-0.  
WITHERS, B D Portland General Electric Co 79/07/05 1p

--7907110425 LER 79-011/01T-0 on 790421 Westinghouse reported that after feedwater line break in containment, primary protection signal could be delayed Caused by deficient design &/or safety analysis of steam generator water level sys  
PERRY, J C Portland General Electric Co 79/07/05 3pp.

#### DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 F. Security, medical, emergency & fire protection plans

7907170075 Notifies that fire protection sys w/svc water back-up not dependent on offsite power will be operative Jul 1984. Capability is discussed in Revision 4 of Fire Hazards Analysis.  
ROE, L E Toledo Edison Co 79/07/09 1p.

## DOCKETED ITEMS

## Q Adjudicatory correspondence

7907110648 Requests addl info in order to evaluate adequacy & acceptability of response to order issued 790516  
 REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/18 3pp

7907060513 Notice of receipt of Toledo Coalition for Safe Power 790424 petition requesting order to maintain plant in shutdown condition until certain emergency actions have been taken  
 DENTON, H R Office of Nuclear Reactor Regulation 79/06/01 1p

--7907060514 Requests that plant remain in shutdown condition until certain actions are taken re emergency & evacuation proceeding & public hearings have been held  
 LODGE, T J Toledo Coalition for Safe Energy 79/04/24 2pp

7907110330 Ack receipt of petition requesting order to prevent plant restart until emergency & evacuation procedures are initiated & public hearings are held Forwards notice filed w/Ofc of Federal Register  
 DENTON, H R Office of Nuclear Reactor Regulation 79/06/01 1p

7907240304 Response to T McCormack 790503 request for hearing re NRC 790516 order on shutdown Intervenor must prove personal interests are affected & issues must be delineated Plant can resume operations before hearings completed  
 MULKEY, M E Branch 2 79/06/27 7pp

7907300391 Orders ASLAB to decide standing of OH State Senator T McCormack & determine topics to be considered at requested hearing Resumed operation of unit is not stayed by pendency of proceeding  
 HOYLE, J C Office of the Secretary of the Commission 79/07/05 3pp

7907300400 Responds to 790618 request for plant shutdown Licensee has satisfactorily completed requirements of NRC 790516 order Licensee will promptly implement long-term mod ASLB is deciding OH State Senator T McCormack request for training  
 ROSS, D Division of Project Management 79/07/06 2pp

--7907300405 Evaluation of licensee compliance w/NRC 790516 order Requirements of order were fulfilled Plant may resume operations  
 \* Office of Nuclear Reactor Regulation 79/07/06 3Bpp

7907130513 Forwards motion seeking preliminary injunction w/complaint & memo of particulars in support of motion & w/supporting documentation  
 LODGE, T J Toledo Coalition for Safe Energy 79/07/09 1p

--7907130515 Motion for preliminary injunction to suspend power-generating operations  
 LODGE, T J Toledo Coalition for Safe Energy 79/07/09 2pp

--7907130521 Complaint & memo of particulars supporting motion for preliminary injunction Plant is immediate threat to persons living within 50 mile radius Supporting documentation encl  
 LODGE, T J Toledo Coalition for Safe Energy 79/07/09 32pp

--7907130528 Draft Ottawa County, OH radiological emergency plan  
 \* Ottawa County, OH 79/07/09 19pp

--7907130535 "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants"  
 COLLINS, H E Office of State Programs GRIMES, B K Office of Nuclear Reactor Regulation GALPIN, F Environmental Protection Agency NUREG-0396 78/12/31 130pp

7907300416 Forwards J Delujak 790608 ltr to JM Hendrie & JM Hendrie 790706 response J Delujak ltr not considered as request for hearing, per NRC 790516 order  
 MULKEY, M E Branch 2 79/07/11 1p.

--7907300488 Responds to 790618 request for plant shutdown Licensee has satisfactorily completed requirements of NRC 790516 order & will promptly implement long-term mod ASLB is considering OH State Senator McCormack request for hearing  
 ROSS, D F Division of Project Management, 79/07/06 2pp

--7907300494 Requests plant remain in shutdown condition until safety evaluation via hearing  
 BELULJAK, J Affiliation Unknown, 79/06/18 1p

7907300425 Forwards HR Denton ltr to L Rowe Plant has completed requirements of NRC 790516 order & operations may resume Safety evaluation & FR notice encl.  
 MULKEY, M E Branch 2 79/07/11 1p

--7907300431 Discusses NRC 790516 order requiring increase in capacity & reliability of plant to respond to various transient events Plant may resume operations Schedule for long-term mod will be forwarded within 30 days  
 DENTON, H R Office of Nuclear Reactor Regulation 79/07/06 4pp

## H General correspondence

7907300420 Forwards transcript of NRC 790705 meeting re plant operations w/o encl  
 MULKEY, M E Branch 2 79/07/10 1p

7907300429 Forwards transcript of NRC 790705 meeting re plant operations w/o encl  
 MULKEY, M E Branch 2 79/07/10 1p

## P Operating license stage documents &amp; correspondence

7907110340 Suggests careful execution of maint program outlined in Diamond Power control rod drive control sys vendor manual Procedures should prevent trip breaker problems  
 FAIST, F R Babcock & Wilcox Co 78/06/12 1p

7907020442 Submits list of B&W licensees who have provided info on pressurizer level instrumentation Pressurizer level info request list encl  
 SHEHANSKI, P Division of Project Management 79/04/19 2pp

7907100238 Forwards extracts from chronology of 770942 event & sequence of events re 790613 incident  
 WRIGHT, R L ACRB - Advisory Committee on Reactor Safeguards 79/05/03 1p

7907260106 Discusses plans to install communication links between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional OFC will communicate operational & environ info  
 KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907020263 Requests review of acceptability of Item IV re RCB makeup pumps Requests written safety evaluation upon approval of proposed change to Tech Specs governing isolation of RCB makeup.  
 REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/23 2pp

7907130465 Expresses satisfaction that 790501 meeting provided info requested re operation of nuclear power plants in OH  
 DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907130474 Requests briefing be arranged on 790501 or 02 re safe operation of nuclear power plants in OH  
 MCAVDY, J F Ohio, State of 79/04/16 1p

--7907130479 Requests comments, in view of TMI incident, re adequacy of facility staff training, safety & emergency procedures & plant design Also seeks info re sys & safety reviews planned for facilities in OH  
 MCAVDY, J F Ohio, State of 79/04/12 1p

7907020397 Submits 790530 daily digest for Westinghouse reactors  
 ROSS, D F Division of Project Management 79/05/30 1p

7907110017 Forwards 790601 petition filed per Toledo Coalition for Safe Energy 790424 request to prevent plant restart until emergency & evacuation procedures are initiated & public hearings are held  
 DENTON, H R Office of Nuclear Reactor Regulation 79/06/01 2pp

--7907110021 Requests order to prevent plant restart until emergency & evacuation procedures are initiated & public hearings are held.  
 LODGE, T J Affiliation Unknown 79/04/24 2pp

--7907110025 Request for action under 10CFR12.06 per Toledo Coalition for Safe Energy 790424 petition re order to prevent plant restart until emergency & evacuation procedures are initiated & public hearings are held  
 DENTON, H R Office of Nuclear Reactor Regulation, 79/06/01 1p

7907230464 Responds to 790503 ltr addressed to JM Hendrie Commission, issued order requiring facility to remain shut until NRC determines suitability & acceptability of proposed short-term corrective actions  
 DENTON, H R Office of Nuclear Reactor Regulation, 79/06/01 2pp

# DOCKETED ITEMS

179

- 7907180876 Forwards Amend 15 to License NPF-3, safety evaluation & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/05 2pp
- 7907180884 Amend 15 to License NPF-3, deleting Paragraph 2 C (3)(1)  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/03 1p
- 7907180889 Safety evaluation supporting Amend 15 to License NPF-3  
REID, R W Office of Nuclear Reactor Regulation 79/06/05 2pp
- 7907180893 Notice of issuance & availability of Amend 15 to License NPF-3  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/05 2pp
- 7907180661 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PWRs Designed by B&W" W/o encl  
GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 1p
- 7907300142 Forwards Amend 17 to License NPF-3, safety evaluation & notice of issuance & availability  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/18 2pp
- 7907300147 Amend 17 to License NPF-3 re schedule for performing noise & isolation testing  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/18 2pp
- 7907300152 Safety evaluation supporting Amend 17 to License NPF-3  
\* Operating Reactors Branch 4 (Pre 790625) 79/06/18 2pp
- 7907300157 Notice of issuance & availability of Amend 17 to License NPF-3  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/06/18 2pp
- 7907240196 Forwards drawings re proposed mod of makeup & purification sys Drawings & drawing change notices available in Central Files only  
RDE, L E Toledo Edison Co 79/06/19 3pp
- 7907170203 Submits test results to indicate satisfactory manual operator control of auxiliary feedwater sys in maintaining steam generator levels.  
MURRAY, T D Toledo Edison Co 79/06/21 2pp
- 7907170201 Forwards info re applicability of B&W 790613 rept on reactor vessel brittle failure during LOCA & HPI Also forwards revised procedure & test results re auxiliary feedwater sys mod  
RDE, L E Toledo Edison Co 79/06/25 2pp.
- 7907310525 Determines that 790316 application for amend to License NPF-3 requires Class III fee  
MILLER, W O License Fee Management Branch 79/06/25 2pp
- 7907170005 Notification of violation of Tech Spec 3.4.1 on 790628 During surveillance testing on reactor protection sys Channel 4, instrument & control technician shorted several terminals w/allegator clip  
MURRAY, T D Toledo Edison Co 79/06/29 1p
- 7907130380 Submits requested info re testing of AFW pumps NPBH/DB-1 & HPI line break analysis.  
RDE, L E Toledo Edison Co 79/07/03 6pp
- 7907100584 Forwards seismic re-evaluation indicating that facility can be shutdown safely in event of earthquake  
RDE, L E Toledo Edison Co 79/07/09 1p
- 7907100587 "Seismic Re-evaluation."  
\* Toledo Edison Co 79/07/09 150pp
- 7907300437 Forwards list of followup activities needed on plant  
MAZETIS, G R Division of Systems Safety 79/07/09 1p
- 7907240351 Forwards application for amend to License NPF-3 revising Tech Specs to reflect changes re interim anticipatory reactor trip sys & auxiliary feedwater flow indications Class IV Amend fee encl.  
RDE, L E Toledo Edison Co 79/07/13 31pp
- 7907270182 Forwards form ltr to B&W operating plants re revised operating guidelines in event of engineered safety features sys actuation caused by low reactor coolant pressure  
GEISLER, G O Babcock & Wilcox Co 79/07/20 2pp
- G Inspection reports, IE Bulletins & correspondence  
-----
- 7907020076 B&W site inspector daily rept on 790419 Plant status reactor in Mode 5 cold shutdown for maint General plant activities inspected  
TAMBLING, T, REYES, L, DANIELS, T Region 3, Chicago, Office of the Director 79/04/19 2pp
- 7907020115 B&W site inspector daily rept on 790416 Plant status reactor in Mode 5 cold shutdown for maint outage Auxiliary feedwater motor operators will not be modified due to matl problems  
BAKER, K R, SMITH, J D Region 3, Chicago, Office of the Director 79/04/16 2pp
- 7907020149 B&W site inspector daily rept on 790418 Plant status reactor in Mode 5 cold shutdown for maint outage Insp plant procedures inspected & licensee training program observed  
TAMBLING, T, REYES, L, DANIELS, T Region 3, Chicago, Office of the Director 79/04/18 2pp
- 7907160059 Responds to IE Bulletin 79-05 & suppl  
\* Region 3, Chicago, Office of the Director 79/04/20 4p
- 7907160365 Draft ltr forwarding draft NRC evaluation of 790411 & 16 licensee responses to IE Bulletin 79-05A Request for addl info encl Response required within 30 days  
\* Division of Project Management 79/04/25 22pp
- 7907050015 Responds to IE Bulletin 79-05B Forwards design mods & new procedures to assure reduction of automatic actuations of pressurizer power operated relief valves  
GRANT, J B Toledo Edison Co 79/05/18 2pp
- 7907090085 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
GRANT, J B Toledo Edison Co 79/05/23 3pp
- 7907200332 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p
- 7907050159 Forwards IE Insp Rept 50-346/79-10 on 790507-11 Notice of violation withheld (ref 10CFR2 790)  
HIND, J A Region 3, Chicago, Safeguards Branch 79/06/01 2pp
- 7907050163 IE Insp Rept 50-346/79-10, Noncompliance noted nonconformance in areas of physical barriers, protected areas, access control, alarm stations & detection aids Details withheld (ref 10CFR2 90)  
MADEBA, T J, SCHAEFFER, J C, HIND, J A Region 3, Chicago, Office of the Director 79/06/01 2pp
- 7907190290 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Bolensold Valves)." Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/06 1p
- 7907240441 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/07 1p
- 7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp
- 7907180287 Forwards IE Insp Rept 50-346/79-12 on 790531 No noncompliance noted  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/15 2pp
- 7907180296 IE Insp Rept 50-346/79-12 on 790531 No noncompliance noted Major areas inspected action taken to address Region 3 concerns re organization & plant procedures  
TAMBLING, T N, SPESSARD, R L Region 3, Chicago, Office of the Director HEISHMAN, R F. Region 3, Chicago, Reactor Operations w Nuclear Support Branch 79/06/13 7pp
- 7907020437 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/20 1p

## DOCKETED ITEMS

7907120257 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907050434 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907130150 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/23 1p

7907060320 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907100523 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130291 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907180263 Ack receipt of 790622 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/79-10  
HIND, J A Region 3, Chicago, Safeguards Branch 79/07/02 1p

--7907180270 Responds to NRC 790601 ltr re violations noted in IE Insp Rept 50-346/79-10 Corrective actions withheld (ref 10CFR2 790)  
GRANT, J S Toledo Edison Co 79/06/22 1p

7907240108 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310348 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310417 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260214 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260416 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p.

#### R Periodic operating reports & related correspondence

7907110513 Forwards monthly operating rept for June 1979.  
MURRAY, T D Toledo Edison Co 79/07/06 1p

--7907110520 Monthly operating rept for June 1979  
CABA, E C Toledo Edison Co 79/07/06 6pp

correspondence

1p

open.

7907110417 Provides info re util handling of RD 79-062, in response to NRC 790629 request Established procedures were followed & proper evaluation & dispositions were made in reporting failure of auxiliary feedwater suction switches  
ROE, L E Toledo Edison Co 79/06/29 2pp

7907090258 Summarizes actions taken to increase surveillance program to determine failure mode associated w/pressure switches as reported in LER 79-062 Calbr checks of pressure switches will be run weekly  
ROE, L E Toledo Edison Co 79/07/02 1p

7907100439 Forwards LER 79-064/01T-0  
MURRAY, T D Toledo Edison Co 79/07/03 1p

--7907100444 LER 79-064/01T-0 on 790621 impact points of eight main steam line seismic restraint locations may deform if sufficient seismic event occurs Caused by design deficiency Web reinforcing plates installed at impact points  
BATCH, G N Toledo Edison Co 79/07/03 3pp

7907100448 Forwards LER 79-065/03L-0  
MURRAY, T D Toledo Edison Co 79/07/05 1p

--7907100458 LER 79-065/03L-0 on 790609 contact data logger failed, rendering fire & radiation remote monitoring sys inoperable Caused by intermittent equipment problem of undetermined nature, Computer program reloaded, equipment to be phased out  
BORYSIAK, M Toledo Edison Co 79/07/05 2pp

7907100463 Forwards LER 79-066/03L-0  
MURRAY, T D Toledo Edison Co 79/07/05 1pp

--7907100472 LER 79-066/03L-0 on 790609 fire alarm point alarmed, although investigation revealed no fire Cause suspected to be dust or dirt on detector Detector removed, tested & reinstalled  
CHESKID, R C Toledo Edison Co 79/07/05 2pp

7907300407 Comments on 790706 telcon w/T Novak IE will pursue licensee evaluation of 790704 auxiliary feedwater valve failure Attention should be given to failed valve motor & associated circuitry  
ROBB, D F Division of Project Management 79/07/08 1p

7907100029 Forwards LER 79-067/01T-0  
MURRAY, T D Toledo Edison Co 79/07/10 1p

--7907100034 LER 79-067/01T-0 on 790628 short circuit caused loss of essential bus Y4 supplying power to safety feature actuation sys Blown inverter fuse was replaced & Y4 bus returned to normal supply  
BEELE, T Toledo Edison Co 79/07/10 3pp

7907300411 Summary of 790629 meeting w/util in Bethesda, MD to discuss LER 79-062 concerning inoperability of pressure switches associated w/DB-1 auxiliary feedwater sys  
CAPRA, R A Division of Project Management 79/07/11 4pp

--7907300417 Discusses commitment resulting from 790629 meeting w/NRC in Bethesda, MD Util committed to increased surveillance program to aid in determining failure mode associated w/pressure switches  
ROE, L E Toledo Edison Co 79/07/02 1p.

7907230303 Forwards suppl info re LER 79-030 On 790220, during surveillance testing, auxiliary feedwater sys valve could not be closed Caused by faulty torque switch, New torque switch of heavier duty design was installed  
MURRAY, T D Toledo Edison Co 79/07/13 2pp

7907310359 Forwards LER 79-068/03L-0  
MURRAY, T D Toledo Edison Co 79/07/19 1p

--7907310373 LER 79-068/03L-0 on 790623, during performance of svc water sys monthly test ST 5075 Ol, component cooling water heat exchanger 1-3 outlet valve failed to close fully Caused by vibrational loosening of retaining nut.  
DEAKYNE, K Toledo Edison Co 79/07/19 3pp.

7907310422 Forwards LER 79-069/03L-0.  
MURRAY, T D Toledo Edison Co. 79/07/19 1p

--7907310473 LER 79-069/03L-0 on 790623, during performance of surveillance testing, containment post-accident radiation monitor RE 5029 had low flow alarm & was declared inoperable Caused by loose sheave set screws.  
ADAMS, J. Toledo Edison Co 79/07/19 2pp

# DOCKETED ITEMS

181

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

## A. Application/construction stage documents & correspondence

7907090364 Confirms 790622 telcon re Westinghouse 790621 notification of possible heatup of steam generator level transmitter ref legs if high energy line break occurs inside containment  
HAIRSTON, W O Alabama Power Co 79/06/22 1p

## J. Insurance & indemnity information

7907030459 Forwards Endorsements 18, 19 & 20 to MAELU Policy MF-93  
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div  
79/06/26 4pp

## P. Operating license stage documents & correspondence

7907190063 FOIA request for info re proposed Westinghouse nuclear fuel assembly plant in Prattville, AL & correspondence from Southern Interstate Energy Board to NRC concerning Southern Co & subsidiaries  
OAKES, D L Affiliation Unknown 79/04/23 2pp

7907120207 Summary of 790426 meeting w/utills to discuss Westinghouse plant design, per TMI-2 event  
THADANI, A Reactor Systems Branch 79/05/02 39pp

7907310568 Forwards NRC 790515 ltr to licensees of Westinghouse two-loop plants re rod bank exchange method for verifying shutdown margin of two-loop NSSS W/o encl  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790623) 79/05/15 1p

7907180604 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Reactor Transients in PWRs Designed by B&W" W/o encl  
GRIMES, D K Assistant Director for Engineers & Projects (Pre 790623) 79/06/11 2pp

7907190647 Forwards Amend 12 to License NPF-2, safety evaluation & notice of issuance & availability  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790623) 79/06/11 2pp

--7907190652 Amend 12 to License NPF-2, revising Tech Specs to require actuation of safety injection on two of three channels of low pressurizer pressure  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790623) 79/06/11 13pp

--7907190656 Safety evaluation supporting Amend 12 to License NPF-2  
\* Office of Nuclear Reactor Regulation 79/06/11 4pp

--7907190661 Notice of issuance & availability of Amend 12 to License NPF-2  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790623) 79/06/11 2pp.

7907030435 Submits responses to 790619 questions re reactor vessel supports  
CLAYTON, F L Alabama Power Co 79/06/26 2pp

7907300362 Summary of 790606 meeting w/utill & Southern Co Svc re App I radiological Tech Specs, proposed by 790415 ltr  
REEVES, E A Operating Reactors Branch 1 79/06/27 5pp

7907190056 Responds to FOIA request for documents re proposed Westinghouse nuclear fuel assembly plant in Prattville, AL & certain Southern Interstate Energy Board correspondence  
Forwards Westinghouse 790515 ltr. W/o encl  
FELTON, J. M. Division of Rules and Records 79/06/29. 2pp

7907180576 Discusses info to be included in Offsite Dose Calculation Manual. Forwards 790126 draft Offsite Dose Calculation Manual  
CLAYTON, F. L. Alabama Power Co. 79/07/11 2pp

--7907180582 Draft Offsite Dose Calculation Manual  
\* Alabama Power Co 79/01/26 47pp

7907170183 Forwards until 790712 NPDES noncompliance rept submitted to EPA re turbine bldg sump effluent.  
CLAYTON, F. L. Alabama Power Co 79/07/13 2pp

7907250340 Requests that Westinghouse rept WCAP-9600, "Rept on Small Break Accident for Westinghouse NSSS Sys," be placed in docket.  
CLAYTON, F L Alabama Power Co. 79/07/18. 1p

7907300321 Forwards revised nonroutine environ operating rept on 790525  
CLAYTON, F L Alabama Power Co 79/07/20 1p

--7907300323 Revised nonroutine environ operating rept on 790514 room sinks connected to floor drain sys of wrong unit due to inadequate design change control Contaminated water possibly escaped to river Surveys taken & personnel monitored  
\* Alabama Power Co 79/07/10 3pp

## Q. Inspection reports, IE Bulletins & correspondence

7907020333 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110312 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907200244 Forwards IE Insp Rept 50-348/79-16 on 790424-26 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 2pp

--7907200250 IE Insp Rept 50-348/79-16 on 790424-26 No noncompliance noted Major areas inspected concrete expansion anchor testing program  
MODENOS, L, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/08 3pp

7907180634 Forwards IE Insp Rept 50-348/79-18 on 790424-27 No noncompliance noted  
LEWIS, R. C Region 2, Atlanta, Office of the Director 79/05/10 2pp

--7907180658 IE Insp Rept 50-348/79-18 on 790424-27 No noncompliance noted Major areas inspected LERs, IE bulletins & circulars, Followup on allegations & plant operations  
HARDIN, A K, CANTRELL, F S Region 2, Atlanta, Office of the Director 79/05/09 5pp

7907100143 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp.

7907110080 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907240392 Forwards results of preliminary review of licensee responses to IE Bulletins 79-06, 06A & 06, Amend 1 Meeting w/owners of operating plants having Westinghouse-designed sys scheduled for 790930 in Bethesda, MD  
SCHWENCER, A Operating Reactors Branch 1 (Pre 790623). 79/05/22 4pp.

7907030086 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 1p

7907180172 Responds to IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Westinghouse Types DB-50 & DB-73 circuit breakers are not used at facility  
CLAYTON, F L Alabama Power Co 79/05/29 1p

7907200162 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/05/31 2pp.

7907190144 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Bolonoid Valves)" Action required  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/06/06. 2pp.

7907310315 Forwards safety evaluation of mods to safety injection actuation sys, proposed in response to IE Bulletin 79-06A. Mods to Tech Specs meet requirements of IEEE 279-1971  
LAINAS, G. Plant Systems Branch. 79/06/06 2pp.

## DOCKETED ITEMS

---7907310323 Safety evaluation of mods to safety injection actuation sys proposed in response to IE Bulletin 79-06A  
 Mods meet IEEE 279-1971 requirements & associated Tech Spec stds  
 \* Plant Systems Branch 79/06/06 3pp

7907060040 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/07 2pp

7907250148 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/11 3pp

7907310326 Provides detailed response to IE Bulletin 79-01, "Environ Qualification of Class IE Equipment "  
 CLAYTON, F L Alabama Power Co 79/06/13 22pp

7907020374 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/20 1p

7907120033 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/21 1p

7907110211 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/22 1p

7907250100 Ack receipt of IE Insp Rept 50-348/79-20 on 790516-18 No proprietary info  
 CLAYTON, F L Alabama Power Co 79/06/22 1p

---7907250103 Forwards IE Insp Rept 50-348/79-20 on 790516-18 No noncompliance noted  
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/04 2pp

---7907250106 IE Insp Rept 50-348/79-20 on 790516-18 No noncompliance noted Major areas inspected concrete expansion anchor testing procedures, work activities & records  
 ANQ, W P, COMPTON, R M Region 2, Atlanta, Office of the Director  
 BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/30 3pp

7907310001 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys Piping " Action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/25 2pp

7907110259 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/26 2pp.

7907180426 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/06/28 2pp

7907310223 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys. " Action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director.  
 79/07/02 2pp

7907260499 Confirms 790628 & 29 telcons re 790625 ltr requesting that certain items in IE Repts 50-348/79-17 & 50-364/79-07 be withheld as proprietary Per advice of util, repts can now be released w/o objection  
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/03 2pp.

---7907260506 Requests that info re unresolved allegations be withheld as proprietary until resolution  
 CLAYTON, F L Alabama Power Co 79/06/25 1p

---7907260517 Forwards IE Insp Repts 50-348/79-17 & 50-364/79-07 on 790424-26 & 0316-19. No noncompliance noted  
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/12, 2pp.

---7907260542 IE Insp Repts 50-348/79-17 & 50-364/79-07 on 790424-26 & 0316-18 No noncompliance noted Major areas inspected flow-splitters in Unit 1 main loop elbows & allegations re const problems  
 BLAKE, J J, KLEINBORGE, W P, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/11 11pp

7907310360 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
 O'REILLY, J P Region 2, Atlanta, Office of the Director  
 79/07/11 1p

R Periodic operating reports & related correspondence

7907180469 Forwards monthly operating rept for June 1979  
 CLAYTON, F L Alabama Power Co 79/07/11 1p

---7907180473 Monthly operating rept for June 1979  
 HAIRSTON, W G Alabama Power Co 79/07/01 4pp

S Reportable occurrences, LERs & related correspondence

7907110409 Forwards LER 78-043/03L-0  
 CLAYTON, F L Alabama Power Co 78/07/17 1p

---7907110415 LER 78-043/03L-0 on 780624 FNP-0-BTP-12 0 had not been performed between 780611-24 Caused by incorrect scheduling Personnel notified & surveillance schedule reviewed  
 \* Alabama Power Co 78/07/14 1p

7907110455 Forwards LERs 78-059/03L-0 & 78-060/03L-0  
 CLAYTON, F L Alabama Power Co 78/09/26 1p

---7907110461 LER 78-059/03L-0 on 780830 during rapid load reduction from 100% power, Tavg exceeded Tech Spec limits Caused by attempt to maintain axial flux differential within target band Control rods driven in  
 \* Alabama Power Co 78/09/26 1p

---7907110465 LER 78-060/03L-0 on 780827 diesel generator 2c would not respond to governor motor switch or voltage regulator switch Caused by instrument noise & failure of motor pot Pot & fuses replaced  
 \* Alabama Power Co 78/09/26 1p

7907100286 Forwards LER 79-023/01T-0  
 CLAYTON, F L Alabama Power Co, 79/07/06 2pp

---7907100295 LER 79-023/01T-0 on 790622 notified by Westinghouse that high energy line break inside containment could cause heatup of steam generator level transmitter ref legs LER will be issued upon completion of investigation  
 HAIRSTON, W G Alabama Power Co 79/07/06 1p

7907170049 Forwards LERs 79-025/03L-0 & 78-088/03L-1  
 CLAYTON, F L Alabama Power Co 79/07/09 1p

---7907170059 LER 79-025/03L-0 on 790623 during surveillance test FNP-1-BTP-256 11 both source range channels inadvertently were deenergized Caused by procedure deficiency. Power restored & procedure changed  
 HAIRSTON, W G Alabama Power Co 79/07/09 1p

---7907170071 LER 78-088/03L-1 on 791125 train A river water pumps found tripped & could not be restarted from control room Caused by moisture in switch box Condulst sealing fittings installed on switch box to prevent water accumulation Design changed  
 HAIRSTON, W G Alabama Power Co 79/07/09 3pp.

7907240359 Forwards LERs 79-022/03L-0, 79-024/03L-0 & 79-027/03L-0  
 CLAYTON, F L Alabama Power Co 79/07/19 1p

---7907240367 LER 79-022/03L-0 on 790620 surveillance test procedure FNP-1-BTP-29 2 not performed on 790620. Caused by inadequate surveillance test schedule review by shift foreman on 790620 importance of accurate daily review stressed  
 HAIRSTON, W G, Alabama Power Co 79/07/19 1p

---7907240376 LER 79-024/03L-0 on 790622 during review of surveillance tests FNP-1-BTP-40 1 & 40 2, noted that certain components were not included in test procedures. Caused by procedural deficiencies Procedure change has been made.  
 HAIRSTON, W G Alabama Power Co 79/07/19 1p

--7907240379 LER 79-027/03L-0 on 790607 radiation monitor declared inoperable Caused by pump malfunction Pump repaired & declared operable 790615  
HAIRSTON, W G Alabama Power Co 79/07/19 1p

#### DOCKET 90-052 LIMERICK GENERATING STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907250483 Forwards FOIA request re facility  
SNYDER, Q L Region 1, Philadelphia, Office of the Director  
79/04/10 1p

--7907250489 FOIA request for info re facility  
SHNIPER, J Mayerson, H 79/04/09 1p

7907190154 Forwards FOIA request re environ impact of facility  
SNYDER, Q L Region 1, Philadelphia, Office of the Director  
79/05/09 1p

--7907190160 FOIA request for info re environ impact of plant on  
Pottstown, PA vicinity  
BOGOS, R Affiliation Unknown 79/05/09 1p

7907300171 Notification of 790717-18 meeting w/Mark II owners group &  
QE in Lebanon, NH to discuss Mark II pool dynamic programs  
ANDERSON, C J Containment Systems Branch 79/07/03 12pp

7907190150 Responds to FOIA request for info re environ impact of  
facility Info requested can be found in DES, FES & BER, on  
file in LPDR, Pottstown Public Library, Pottstown, PA  
FELTON, J M Division of Rules and Records 79/07/10 1p

7907250476 Responds to 790409 FOIA request for info re facility Info  
requested is available from LPDR & found in facility SER, DES  
& FES Projected opening date info can be found in Yellow  
Book  
FELTON, J M Division of Rules and Records 79/07/10 1p

##### 0 Adjudicatory correspondence

7907130002 Notice of receipt of F Romano 790412 ltr requesting NRC  
investigate seismic effects of blasting at quarry near  
plants Ltr being treated as request for action per  
10CFR2 206  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/31 1p

--7907130007 Notifies of concern that seismic stresses could cause  
accident resulting in reactor meltdown Investigation is  
needed of vibratory motion & deleterious effects of ongoing  
blasting  
ROMANO, F Affiliation Unknown 79/04/12 8pp

--7907130010 Forwards activities for NRC investigation of seismic  
stresses around plants in response to F Romano 790412 ltr  
DENTON, H R Assistant Director for Rits Technology 79/05/30  
2pp

--7907130014 Notifies of receipt of 790412 ltr requesting investigation  
of seismic stresses near plants Ltr will be treated as  
request for action per 10CFR2 206 Forwards FR notice W/o  
encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/05 2pp

--7907130020 Forwards F. Romano 790412 ltr requesting investigation of  
seismic stresses at plants Ltr will be treated as request  
for action per 10CFR2 206. Forwards FR notice W/o encl.  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/05 2pp

##### H General correspondence

7907190229 Responds to 790412 request for investigation of blasting at  
quarry near facility site FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/05 2pp.

##### 0 Inspection reports, IE Bulletins & correspondence

7907050446 Supplements response to IE Bulletin 79-08 Review under way  
No Tech Spec changes anticipated  
DALTROFF, S L Philadelphia Electric Co 79/05/14, 1p

7907060422 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys." Licensee  
action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907050446 Responds to IE Bulletin 79-07 re computer codes used for  
seismic analysis of safety-related piping  
BOYER, V S Philadelphia Electric Co 79/05/25 2pp

7907060244 Supplements response to IE Bulletin 78-12 Manufacturer has  
verified that no deviations in weld matl in reactor pressure  
vessel welds  
BOYER, V S Philadelphia Electric Co 79/05/25 1p

7907130516 Responds to IE Bulletin 79-04 Submits info re swing check  
valves supplied by Velan Engineering Corp & in use at  
facility  
BOYER, V S Philadelphia Electric Co 79/05/25 2pp

7907030055 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200134 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190074 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit  
breakers used or planned for use in safety-related sys  
BOYER, V S Philadelphia Electric Co 79/06/06 1p

7907190098 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060118 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907020050 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Bys "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/11 1p

7907230342 Ack receipt of 790503 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Repts 50-352/79-02 &  
50-353/79-02  
CARLBON, R T Region 1, Philadelphia, Reactor Construction &  
Engineering Support Branch 79/06/18 1p

--7907230348 Responds to NRC 790406 ltr re violations noted in IE Insp  
Repts 50-352/79-02 & 50-353/79-02 Corrective actions  
abandoned & replacement holes filled w/dry mortar & replaced  
by another hole  
BOYER, V S Philadelphia Electric Co 79/05/13 3pp

--7907230440 Forwards IE Insp Repts 50-352/79-02 & 50-353/79-02 on  
790220-23 & notice of violation  
CARLBON, R T Region 1, Philadelphia, Reactor Construction &  
Engineering Support Branch 79/07/06 2pp

--7907230442 Notice of violation from insp on 790220-23  
\* Region 1, Philadelphia, Office of the Director 79/04/06  
2pp

--7907230444 IE Insp Repts 50-352/79-02 & 50-353/79-02 on 790220-23  
Noncompliance noted failure to follow procedure for drilling  
anchor bolt holes & for storage of stainless steel pipe in  
laydown area  
MATTIA, J, DURR, J P, MCGAUGHY, R. Region 1, Philadelphia,  
Reactor Construction & Engineering Support Branch 79/04/05  
21pp

7907110379 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230695 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p.

7907120522 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping." No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

## DOCKETED ITEMS

7907100393 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100424 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/27 1p

7907100507 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180802 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907270353 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310930 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

## DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

## A Application/construction stage documents &amp; correspondence

7907250483 Forwards FOIA request re facility  
BOYDER, G L Region 1, Philadelphia, Office of the Director  
79/04/10 1p

--7907250487 FOIA request for info re facility  
SHNIFER, J Mayerson, H 79/04/09 1p

7907190154 Forwards FOIA request re environ impact of facility  
BOYDER, G L Region 1, Philadelphia, Office of the Director  
79/03/09 1p

--7907190160 FOIA request for info re environ impact of plant on Pottstown, PA vicinity  
BOGGB, R Affiliation Unknown 79/05/09 1p

7907300171 Notification of 790717-18 meeting w/Mark II owners group & GE in Lebanon, NH to discuss Mark II pool dynamic programs  
ANDERSON, C J Containment Systems Branch 79/07/03 12pp

7907190150 Responds to FOIA request for info re environ impact of facility. Info requested can be found in DES, FEB & SER, on file in LPDR, Pottstown Public Library, Pottstown, PA  
FELTON, J M Division of Rules and Records 79/07/10 1p

7907250476 Responds to 790409 FOIA request for info re facility Info requested is available from LPDR & found in facility SER, DES & FEB Projected opening date info can be found in Yellow Book  
FELTON, J M Division of Rules and Records 79/07/10 1p

## Q Adjudicatory correspondence

7907130002 Notice of receipt of F Romano 790412 ltr requesting NRC investigate seismic effects of blasting at quarry near plants Ltr being treated as request for action per 10CFR2 206  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/31 1p

--7907130007 Notifies of concern that seismic stresses could cause accident resulting in reactor meltdown Investigation is needed of vibratory motion & deleterious effects of ongoing blasting  
ROMANO, F Affiliation Unknown 79/04/12 8pp

--7907130010 Forwards activities for NRC investigation of seismic stresses around plants in response to F Romano 790412 ltr.  
DENISE, R. P. Assistant Director for Site Technology, 79/05/30 2pp.

--7907130014 Notifies of receipt of 790412 ltr requesting investigation of seismic stresses near plants Ltr will be treated as request for action per 10CFR2 206. Forwards FR notice W/o encl.  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/05 2pp.

--7907130020 Forwards F Romano 790412 ltr requesting investigation of seismic stresses at plants Ltr will be treated as request for action per 10CFR2 206 Forwards FR notice W/o encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/05 2pp

## H General correspondence

7907190229 Responds to 790412 request for investigation of blasting at quarry near facility site FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/05 2pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907050446 Supplements response to IE Bulletin 79-08 Review under way No Tech Spec changes anticipated  
DALTROFF, B L Philadelphia Electric Co 79/05/14 1p

7907060422 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907050468 Responds to IE Bulletin 79-07 re computer codes used for seismic analysis of safety-related piping  
BOYER, V S Philadelphia Electric Co 79/05/25 2pp

7907060244 Supplements response to IE Bulletin 79-12 Manufacturer has verified that no deviations in weld matl in reactor pressure vessel welds  
BOYER, V S Philadelphia Electric Co 79/05/25 1p

7907130516 Responds to IE Bulletin 79-04 Submits info re swing check valves supplied by Velan Engineering Corp & in use at facility  
BOYER, V S Philadelphia Electric Co. 79/05/25 2pp

7907030055 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor."  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200134 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190074 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers used or planned for use in safety-related sys  
BOYER, V S Philadelphia Electric Co 79/06/06 1p

7907190098 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907060118 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907020050 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/11 1p

7907230342 Ack receipt of 790503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-02 & 50-353/79-02  
CARLBON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/18 1p

--7907230348 Responds to NRC 790406 ltr re violations noted in IE Insp Repts 50-352/79-02 & 50-353/79-02 Corrective actions abandoned & replacement holes filled w/dry mortar & replaced by another hole  
BOYER, V S Philadelphia Electric Co 79/05/13 3pp

--7907230440 Forwards IE Insp Repts 50-352/79-02 & 50-353/79-02 on 790220-23 & notice of violation  
CARLBON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/07/06 2pp.

--7907230442 Notice of violation from insp on 790220-23  
\* Region 1, Philadelphia, Office of the Director, 79/04/06 2pp.



--7907230444 IE Insp Repts 50-352/79-02 & 50-353/79-02 on 790220-23  
Noncompliance noted failure to follow procedure for drilling  
anchor bolt holes & for storage of stainless steel pipe in  
laydown area  
MATTIA, J., DURR, J. P., MCQUAGHY, R. Region 1, Philadelphia,  
Reactor Construction & Engineering Support Branch 79/04/05  
21pp

7907110379 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230695 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907120522 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907100353 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100424 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/27 1p

7907100507 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180802 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907270353 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310530 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

##### G. Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action  
of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re  
Perkins record Deficiencies do not raise genuine issue of  
matl fact. Certificate of Svc encl  
BORDENICK, B. H. Branch 4 79/05/25 29pp

7907090171 Notifies of typographical errors in licensees joint  
motion for summary disposition re radon issues. Mistakes  
were in accompanying affidavits  
SILBERG, J. E. Shaw, Pittman, Potts, & Trowbridge 79/06/05 9pp

7907180188 Responds to utils motion for summary disposition re radon  
issues. Twenty-one alleged deficiencies in Perkins record  
advanced by intervenors are supported in part & opposed in  
part. Certificate of Svc encl  
BORDENICK, B. H. Branch 4 79/06/14 29pp.

##### G. Inspection reports, IE Bulletins & correspondence

7907050443 Responds to IE Bulletin 79-03 Pipe mfg by Youngstown Welding  
& Engineering Co is not being supplied for use in any  
safety-related sys  
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey  
79/05/11, 1p.

7907060425 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys." Licensee  
action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907180114 Responds to IE Bulletin 79-04 Valves 3, 4 or 6-inch diameter  
swing check valves will be used in Seismic Category I  
piping sys  
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey  
79/05/22 1p

7907160144 Notifies that response to IE Bulletin 79-07 re seismic  
analysis of safety-related piping will be made by 790815  
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey  
79/05/23 1p

7907030061 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor "  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200142 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/05/31 1p

7907190102 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/04 1p

7907060128 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907020052 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys "  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/11 1p

7907110389 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230700 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907120536 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required.  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907100363 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100429 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/27 1p

7907110035 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180811 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907270361 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/07/11 1p

7907310536 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

##### G. Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action  
of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re  
Perkins record Deficiencies do not raise genuine issue of  
matl fact. Certificate of Svc encl  
BORDENICK, B. H. Branch 4 79/05/25, 29pp

## DOCKETED ITEMS

7907090171 Notifies of typographical errors in licensee's joint motion for summary disposition re radon issues Mistakes were in accompanying affidavits  
SILBERG, J E Shaw, Pittman, Potts, & Troubridge 79/06/05 9pp

7907180188 Responds to utility motion for summary disposition re radon issues. Twenty-one alleged deficiencies in Perkins record advanced by intervenors are supported in part & opposed in part Certificate of Svc encl  
BORDENICK, B M Branch 4 79/06/14 29pp

G Inspection reports, IE Bulletins & correspondence

7907050443 Responds to IE Bulletin 79-03 Pipe mfg by Youngstown Welding & Engineering Co is not being supplied for use in any safety-related sys  
MARTIN, T J Public Service Electric & Gas Co of New Jersey 79/05/11 1p

7907060425 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907180114 Responds to IE Bulletin 79-04 Velan 3.4 or 6-inch diameter swing check valves will be used in Seismic Category I piping sys  
MARTIN, T J Public Service Electric & Gas Co of New Jersey 79/05/22 1p

7907160144 Notifies that response to IE Bulletin 79-07 re seismic analysis of safety-related piping will be made by 790815  
MARTIN, T J Public Service Electric & Gas Co of New Jersey 79/05/22 1p

7907030061 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907280142 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190102 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060128 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020092 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907110389 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230700 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120536 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100363 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100429 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p.

7907110035 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180811 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270361 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310536 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

DOCKET 90-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR

P Operating license stage documents & correspondence

7907190840 Forwards license renewal review items License will expire 791101 Renewal requires demonstration that reactor can continue to be operated safely & withstand prolonged use  
REID, R W Operating Reactors Branch 4 (Pre 790625) 79/05/30 8pp

G Inspection reports, IE Bulletins & correspondence

7907230432 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907240030 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/09 1p

DOCKET 90-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7907160109 Draft memo re licensing strategy for plants w/fuel load dates in CY79  
BOYD, R B Division of Project Management 79/03/28 6pp

7907130465 Expresses satisfaction that 790501 meeting provided info requested re operation of nuclear power plants in OH  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907130474 Requests briefing be arranged on 790501 or 02 re safe operation of nuclear power plants in OH  
MCAVOY, J F Ohio, State of 79/04/16 1p

---7907130474 Requests comments, in view of TMI incident, re adequacy of facility staff training, safety & emergency procedures & plant design Also seeks info re sys & safety reviews planned for facilities in OH  
MCAVOY, J F Ohio, State of 79/04/12 1p

7907130018 Notification of 790615 meeting w/Mark II owners & GE in Bethesda, MD re closure of Mark II lead plant program  
ANDERSON, C J Assistant Director for Reactor Safety 79/06/05 6pp.

7907180415 Notification of postponement of 790615 meeting w/Mark II owners & GE to discuss closure of Mark II lead plant program Meeting will be rescheduled  
ANDERSON, C J Containment Systems Branch 79/06/05 2pp.

7907090231 Notification of 790724-25 meeting w/representatives from lead Mark II plants to discuss long-term program  
ANDERSON, C J Containment Systems Branch 79/06/11 2pp

7907300535 Confirms planned 790626 meeting in Cincinnati, OH to discuss the const status & preoperational testing programs.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/18 1p

7907250063 Notification of 790726 meeting w/GE, C Economus & Mark II owners in Bethesda, MD to discuss closure of Mark II lead plant program.  
ANDERSON, C J Containment Systems Branch 79/06/25 6pp

7907300171 Notification of 790717-18 meeting w/Mark II owners group & GE in Lebanon, NH to discuss Mark II pool dynamic programs  
ANDERSON, C J Containment Systems Branch 79/07/03 12pp

7907310429 Forwards Amend 12 to containment design assessment rept  
Amend consists of App F, "Containment Structure Assessment for LOCA Jet Impingement & Pool Swell Loads"  
BORGMANN, E A Cincinnati Gas & Electric Co 79/07/30 1p

--7907310431 Amend 12 to containment design assessment rept Amend consists of App F, "Containment Structure Assessment for LOCA Jet Impingement & Pool Swell Loads"  
\* Cincinnati Gas & Electric Co 79/07/30 41pp

#### D NRC Draft/Final Environmental Statements, suppl's & correspondence

7907060427 Notifies that revisions to draft ETS have been forwarded under separate cover. Requirements re monitoring impact on water quality & fish impingement are not included in ETS. NRC agrees w/stds set by OH EPA  
BALLARD, R L Environmental Projects Branch 1 79/06/08 3pp

#### F Security, medical, emergency & fire protection plans

790730038/ Forwards Revision 13 to fire protection evaluation rept, consisting of three revised pages & supplemental rept, "Fire Protective Cable Tray Fire Test"  
BORGMANN, E A Cincinnati Gas & Electric Co 79/07/13 6pp

--7907300395 "Fire Protective Cable Tray Fire Test," submitted on behalf of util  
ABRAMS, M S Portland Cement Association 79/07/13 143pp

#### G Adjudicatory correspondence

7907110432 Cincinnati Gas & Electric opposition to intervenor Miami Valley Power Project motion to amend petition to intervene Certificate of Bvc encl  
CONNER, T B, RADER, R M Conner, Moore & Corber 79/05/09 9pp

--7907110437 Rept on "Cable Raceway Protection Sys Fire Test Investigation" for B&W Project 7BNK5345  
PRZYBYLA, L J, HOWELL, K W, PARKS, R L obsolete code 78/09/06 45pp

7907110449 Miami Valley Power Project objections to certain of NRC 790420 interrogatories. Protective order should be granted as Interrogatories 14, 25 & 42, re summary request of expert testimony, have effect of moving deadline ahead  
KOSIK, L S Kosik, L S 79/05/09 1p.

--7907110456 Intervenor Miami Valley Power Project answers to NRC 790420 interrogatories  
KOSIK, L S Kosik, L S 79/05/09 7pp

--7907110463 Miami Valley Power Project objections to certain of Cincinnati Gas & Electric 790420 fifth set of interrogatories. Protective order should be granted re Interrogatories 17 & 29 as being irrelevant & burdensome  
KOSIK, L S Kosik, L S 79/05/09 1p.

--7907110468 Intervenor Miami Valley Power Project answer to Cincinnati Gas & Electric 790420 fifth set of interrogatories  
KOSIK, L S Kosik, L S 79/05/09 3pp

--7907110475 Comments on consequences of in-depth investigation in response to JO Keppler 781204 ltr re allegations concerning cable trays Affidavit & Certificate of Bvc encl.  
HOFSTADTER, E P Miami Valley Power Project 78/12/11 5pp

7907050844 Motion by intervenor City of Cincinnati for continuation of hearing until TMI investigation completed. Accident at TMI challenges current safety concepts. Certificate of Bvc encl  
LUEBBERG, T A Cincinnati, OH 79/05/10 7pp

7907120274 Requests limited appearance at hearing scheduled for 790522 re licensing of facility.  
RUTHEMEYER, T J Clermont County, OH 79/05/10 2pp

7907110483 Forwards Cincinnati Gas & Electric objections to certain of intervenor Miami Valley Power Project 790420 third set of interrogatories & Cincinnati Gas motion for protective order. Responses to remaining questions will be forwarded.  
WATTERHAHN, M J Conner, Moore & Corber 79/05/14 1p

--7907110428 Cincinnati Gas & Electric objections to certain of intervenor Miami Valley Power Project 790420 third set of interrogatories, & Cincinnati Gas & Electric motion for protective order Certificate of Bvc encl  
WATTERHAHN, M J Conner, Moore & Corber 79/05/14 6pp

7907170237 Forwards affidavits of PR Anderson, AM Hill, WR Kelley, WH Zimmer & RP Wiwi, copies of which were included w/applicant 790423 suppl motion for summary disposition. Typographical errors corrected  
WATTERHAHN, M J Conner, Moore & Corber 79/05/15 18pp

7907110413 Miami Valley Power Project motion to allow non-atty members of Miami Valley Power Project to appear & participate in hearings  
KOSIK, L S Kosik, L S 79/05/16 2pp

--7907110505 Notice of appearance on behalf of intervenor Miami Valley Power Project  
FELDMAN, J H Feldman, J H, Jr 79/05/15 1p

--7907110515 Notice of appearance on behalf of intervenor Miami Valley Power Project Certificate of Bvc encl  
SHANE, S C Shane & Rebel 79/05/15 2pp

7907100656 Requests hearing appearance  
ALDAKER, V Affiliation Unknown 79/05/18 1p

7907100660 Requests to make limited appearance statement at 790523 hearing  
DIEHL, S E Affiliation Unknown 79/05/18 1p

7907100681 Intervenor Valley Power Project opposition to Cincinnati Gas & Electric supplemental motion for summary disposition re financial competence of util to operate facility Certificate of Bvc encl  
KOSIK, L Kosik, L S 79/05/21 7pp

7907100720 Opposes issuance of OL  
\* Affiliation Unknown 79/05/30 7pp

7907110131 Miami Valley Power Project answers to certain of NRC interrogatories Affidavit & Certificate of Bvc encl  
RIOBERG, S A Miami Valley Power Project 79/05/30 4pp

7907310097 Notification of appearance on behalf of Cincinnati Gas & Electric Co Certificate of Bvc encl  
RADER, R M Conner, Moore & Corber 79/05/30 3pp

7907190748 Summary of intervenor Fankhauser-prepared testimony for June 1979 hearing re Contention 6 relating to spent fuel pool at facility  
FANKHAUSER, D B Affiliation Unknown 79/06/01 7pp

7907060006 Forwards applicant testimony re Contentions 14, 15 & 16 concerning cable trays, mfg of control rods & control rod seals, Prof qualifications of WM Schwiers, FL Banta & VW Pence encl  
CONNER, T B Conner, Moore & Corber 79/06/08 13pp

7907190127 Miami Valley Power Project motion to reschedule licensing hearings during evening hours  
KOSIK, L S Kosik, L S 79/06/08 1p

--7907190134 Miami Valley Power Project memo in support of motion to allow hearing participation by parties other than attys  
SHANE, S C Shane & Rebel 79/06/08 4pp.

--7907190136 Testimony concerning Contention 14 re cable trays welding  
HOFSTADTER, E P Miami Valley Power Project 79/06/08 3pp

--7907190152 Testimony concerning Contentions 15 & 16 re procedures involving control rods & control blades.  
MARTIN, T D Miami Valley Power Project 79/06/08 4pp

--7907190158 Testimony re presence of design matter in control rods Certificate of Bvc encl  
REYNOLDS, Q L Miami Valley Power Project 79/06/08 3pp

/7907100708 Cincinnati Gas & Electric motion to strike intervenor DB Fankhauser 790601 testimony for June hearing Fankhauser comments & conclusions are argumentative & unsupported by law or facts Certificate of Bvc encl.  
CONNER, T B Conner, Moore & Corber 79/06/09 6pp

7907190067 Order granting intervenor Miami Valley Power Project 790516 motion & intervenor D Fankhauser 790521 request for non-atty representation re issues raised by other parties or by ASLB.  
BECHHOEFER, C Atomic Safety and Licensing Board Panel 79/06/13 6pp

## DOCKETED ITEMS

7907190687 Cincinnati Gas & Electric further responses to Miami Valley Power Project third set of interrogatories Affidavit & Certificate of Svc encl  
BORGMANN, E A Cincinnati Gas & Electric Co 79/06/15 13pp

K Utility Final Safety Analysis Report (FSAR) & amends

7907170084 Forwards Revision 59 to FSAR, consisting of responses to second round questions, submitted as Amend 94 to GL application  
BORGMANN, E A Cincinnati Gas & Electric Co 79/07/13 2pp

--7907170086 Revision 59 to FSAR  
\* Cincinnati Gas & Electric Co 79/07/13 70pp

7907230491 Forwards Certificate of Svc of FSAR Revision 59  
BORGMANN, E A Cincinnati Gas & Electric Co 79/07/19 2pp

G Inspection reports, IE Bulletins & correspondence

7907180598 Forwards IE Insp Rept 50-358/79-06 on 790227-28, 0301-02, 19-23 & 0409-11 & notice of violation  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/16 2pp

--7907180608 Notice of violation from insp on 790227-28, 0301-02, 19-23 & 0409-11  
\* Region 3, Chicago, Office of the Director 79/05/07 3pp

--7907180627 IE Insp Rept 50-358/79-06 on 790227-28 & 0301-02, 19-23 & 0409-11 Noncompliance noted failure to follow procedures, inadequate procedures & inadequate records  
MAURA, F A, DETTENMEIER, R W, STREETER, J F Region 3, Chicago, Office of the Director 79/05/07 14pp

7907130153 Forwards documentation & info in response to IE Bulletins 78-12, 12A & 12B re atypical weld matl in reactor pressure vessel welds OE investigation concludes identified weld deposits unlikely  
BORGMANN, E A Cincinnati Gas & Electric Co 79/05/25 3pp

--7907130158 Forwards rept re IE Bulletins 79-12 & 12A w/o encl  
KELLEY, R E Chicago Bridge & Iron Co 79/04/24 1p

7907190151 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping Forwards Sargent & Lundy 790518 ltr re bulletin Facility seismic analysis programs do not employ algebraic techniques described in bulletin  
BORGMANN, E A Cincinnati Gas & Electric Co 79/05/25 6pp

7907200300 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907090425 Responds to IE Bulletin 79-07 identified computer codes not used for seismic analysis of OE piping sys  
BORGMANN, E A Cincinnati Gas & Electric Co 79/06/06 3pp

7907190236 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240246 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures " was forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020242 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys. "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

310213 Forwards IE Insp Rept 50-358/79-16 on 790502-04 & 29-30. No noncompliance noted  
\* BHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Port Branch 79/06/14 2pp

--7907310222 IE Insp Rept 50-358/79-16 on 790502-04, 29-30 No noncompliance noted Major areas inspected operating & surveillance procedures Documents 790504 meeting w/ licensee mgt to discuss proposed assignment of resident inspector  
MENNING, J E, WARNICK, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/12 5pp

7907020416 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120215 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907120693 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060306 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050469 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907180400 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130258 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907310319 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310405 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260164 Notifies that written responses to IE Bulletin 79-13, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260348 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Boreated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18, 1p

7907250224 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys. " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

T Hearing transcripts on non-antitrust matters

7907090099 Transcript of 790619 hearing in Cincinnati, OH Pp 533-696 Exhibits encl  
BECHHOEFER, C., HOOPER, R F, BRIGHT, G O Atomic Safety and Licensing Board Panel 79/06/19 189pp

7907030265 Transcript of 790620 hearing in Cincinnati, OH, Pp 697-888 FD Fankhauser testimony encl  
BECHHOEFER, C., HOOPER, R F, BRIGHT, G O Atomic Safety and Licensing Board Panel 79/06/20 198pp

7907030388 Transcript of 790620 hearing in Cincinnati, OH, Pp 889-975 BECHHOEFER, C., HOOPER, R F, BRIGHT, G O Atomic Safety and Licensing Board Panel 79/06/20, 87pp

7907120294 Transcript of 790621 hearing in Cincinnati, OH Pp 976-1, 155 Testimony of applicant & EP Hofstadter encl  
BECHHOEFER, C., HOOPER, R F, BRIGHT, G O Atomic Safety and Licensing Board Panel 79/06/21 187pp

7907120170 Transcript of 790622 hearing in Cincinnati, OH Pp 1,156-1,339  
BECHHOEFER, C , HOOPER, F F , BRIGHT, G D Atomic Safety and Licensing Board Panel 79/06/22 183pp

7907120303 Transcript of 790626 hearing in Cincinnati, OH Pp 1,340-1,532  
BECHHOEFER, C , HOOPER, F F , BRIGHT, G D Atomic Safety and Licensing Board Panel 79/06/26 193pp

7907120400 Transcript of 790626 hearing in Cincinnati, OH Pp 1,533-1,605  
BECHHOEFER, C , HOOPER, F F , BRIGHT, G D Atomic Safety and Licensing Board Panel 79/06/26 63pp

7907120158 Transcript of 790627 hearing in Cincinnati, OH Pp 1,606-1,817 Testimony of T Vandell, R Anderson, H Westcott & FA Maura & other exhibits encl  
BECHHOEFER, C , HOOPER, F F , BRIGHT, G D Atomic Safety and Licensing Board Panel 79/06/27 292pp

7907120446 Transcript of 790628 hearing in Cincinnati, OH Pp 1,817-2,034  
BECHHOEFER, C , HOOPER, F F , BRIGHT, G D Atomic Safety and Licensing Board Panel 79/06/28 218pp

7907120469 Transcript of 790629 hearing in Cincinnati, OH Pp 2,035-2,221 Testimony of applicant & VW Pence encl  
BECHHOEFER, C , HOOPER, F F , BRIGHT, G D Atomic Safety and Licensing Board Panel 79/06/29 193pp

#### DOCKET 50-360 BATTELLE MEMORIAL INST CRITICAL FACILITY

Q Inspection reports, IE Bulletins & correspondence

7907230520 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907230744 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENDELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

#### DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7907050131 Summary of 790427 meeting w/util & C-E in Bethesda, MD re core protection computer review  
RODD, H Light Water Reactors Branch 2 79/05/18 24pp

7907050378 Forwards addendum to "Cultural Resources & High Voltage Transmission Line From San Onofre to Santiago Substation & Black Star Canyon "  
BASKIN, K P Southern California Edison Co 79/06/27. 1p

--7907050382 Addendum to "Cultural Resources & High Voltage Transmission Line From San Onofre to Santiago Substation & Black Star Canyon," by Cultural Sys Research, Inc  
\* Southern California Edison Co. 79/04/15 20pp

7907130459 Responds to structural audit info requests Forwards nonproprietary responses to action items, proprietary & nonproprietary versions of structural design calculation packages & affidavit of LO Hinkelman  
HAYNEB, J. G Southern California Edison Co 79/07/06 56pp

7907260666 Forwards "Rept on Exploration/Demobilization of Wells 4 & 5" by Woodward Clyde & "Rept on Deep Exploration Drilling Program/Dewatering Well 7" & "Rept on Exploration/Grouting Program/Dewatering Well 7"(2 vols), by Bechtel  
BASKIN, K P Southern California Edison Co 79/07/11 18pp

--7907260671 "Rept on Exploration/Demobilization of Wells 4 & 5,"  
\* Woodward-Clyde Consultants 79/07/31 313pp.

--7907260677 "Rept on Deep Exploration Drilling Program/Dewatering Well 7"  
\* Bechtel Power Corp. (subs of Bechtel Corp.). 79/06/30 250pp

--7907260683 "Rept on Exploration/Grouting Program Dewatering Well 7," Vol 1.  
\* Bechtel Power Corp. (subs of Bechtel Corp.). 79/06/30 200pp

--7907260687 "Rept on Exploration/Grouting Program/Dewatering Well 7," Vol 2  
\* Bechtel Power Corp (subs of Bechtel Corp.) 79/06/30 200pp

7907310274 Forwards "Application for Permission to Transfer Ownership Interest to Cities of Anaheim & Riverside, CA & for Amend to CPs CPPR-97 & CPPR-98 "  
DRAKE, J H Southern California Edison Co 79/07/17 1p

--7907310280 Ack receipt of antitrust info on 790719 Info acceptable for docketing & distribution  
TOLSTON, A Antitrust & Indemnity Group 79/07/19 2pp

--7907310286 "Application for Permission to Transfer Ownership Interest to Cities of Anaheim & Riverside, CA & for Amend to CP CPPR-97 & CPPR-98," Vols 1-3  
DRAKE, J H Southern California Edison Co 79/07/17 100pp

7907310377 Forwards Jul 1979 "Final Environ Impact Rept" re proposed San Onofre-to-Mission 230 kV transmission line Encl available in Central Files  
STEEGER, D D California, State of 79/07/27 1p

F Security, medical, emergency & fire protection plans

7907120475 Summary of 790427 meeting w/Southern CA Edison & San Diego Gas & Electric Co in Bethesda, MD re staff fire protection criteria  
RODD, H Light Water Reactors Branch 2 79/05/27 5pp

--7907120485 Preliminary draft first round questions on fire protection  
\* Light Water Reactors Branch 2 79/05/27 13pp.

G Adjudicatory correspondence

7907310488 Corrects info submitted to Board on 790306 re issuance of SNM license for new fuel to be used at site Subsequently informed that License SNM-1844 was already issued  
CHANDLER, L J Branch 1 79/05/16 1p

--7907310526 License authorizing receipt, possession & storage of up to 20 g U-235 contained in fission chambers for eventual use in reactors  
CROW, W T Division of Fuel Cycle & Material Safety 79/01/02. 1p.

7907170253 Requests for documents submitted to util by Friends of the Earth Seeks info re effects of dewatering of well cavities, various geologic studies of land area & substratum & siting studies Certificate of Svc encl  
WHARTON, R J Wharton, R J 79/05/22 6pp

7907190198 Petitions NRC to deny DLs Plant is dangerously sited near active earthquake fault  
RUSSELL, A F , GREENGAUD, S , SILVERMAN, L Affiliation Unknown 79/06/05 1p

7907130392 Objection by util to Friends of the Earth 790522 document request Rules of Practice demand that documents be made available for insp & copying Certificate of Svc encl  
PIGOTT, D R Chickering & Gregory 79/06/19 App

H General correspondence

7907050551 Requests time & distance parameters for emergency planning  
HICKS, L. H California, State of, 79/05/13. 1p

--7907050554 Requests info re evacuation & emergency planning.  
HICKS, L. H California, State of 75/12/31 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

7907090252 Submits affidavit of svc & distribution list for Amend 15 to FSAR.  
HAYNEB, J. G Southern California Edison Co 79/06/26. 3pp.

G. Inspection reports, IE Bulletins & correspondence

7907110705 Forwards IE Insp Repts 50-361/79-07 & 50-362/79-07 on 790201-28 & notice of violation.  
BENCER, G B Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/27. 2pp

--7907110712 Notice of violation from insp on 790201-28  
\* Region 5, San Francisco, Office of the Director. 79/04/27 2pp

## DOCKETED ITEMS

- 7907110725 IE Insp Repts 50-361/79-07 & 50-362/79-362 on 790201-2B Noncompliance noted improper storage of Fin-Fan radiator fan motor & nonavailability of procedure qualification records for post weld heat-treatment  
PATE,R J , HAIST,D P Region 5, San Francisco, Office of the Director  
HAYNES,R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/04/26 8pp
- 7907130531 Responds to IE Bulletin 79-03 re piping mfg by Youngstown Welding & Engineering Co Rept submitted 781201 discussed matter in detail & should adequately address issue.  
BASKIN,K P Southern California Edison Co 79/05/04 1p
- 7907260518 Forwards IE Insp Repts 50-361/79-11 & 50-362/79-11 on 790409-12 No noncompliance noted  
SPENCER,Q S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/21 2pp
- 7907260649 IE Insp Rept 50-361/79-11 & 50-362/79-11 on 790409-12 No noncompliance noted Major areas inspected const activities, installation of reactor vessel internals & safety-related equipment & preservice insp.  
ALBERT,W G , HAIST,D P Region 5, San Francisco, Office of the Director  
HAYNES,R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/21 9pp
- 7907090238 Responds to IE Bulletin 79-07 No identified methods utilized for seismic analyses of safety-related piping  
BASKIN,K P Southern California Edison Co 79/05/23 2pp
- 7907090235 Responds to IE Bulletin 79-04 Valen has not supplied, nor scheduled to supply, valves for plant use  
BASKIN,K P Southern California Edison Co 79/05/24 1p
- 7907180694 Summary of 790504 meeting w/utills in Bethesda, MD re interpretation of seismic profiles Forwards consultant  
790707 ltr re evaluation of offshore fault  
RODD,H Light Water Reactors Branch 2 79/05/30 6pp
- 7907200374 Forwards IE Bulletin 79-12, "Short Period Sgrams at BWR Facilities " No action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/31 1p.
- 7907260965 Forwards IE Insp Repts 50-361/79-12 & 50-362/79-12 on 790401-30 No noncompliance noted  
SPENCER,Q S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/01 2pp
- 7907260978 IE Insp Repts 50-361/79-12 & 50-362/79-12 on 790401-30 No noncompliance noted Major areas inspected const activities including piping storage, fit-up, welding & nondestructive testing & protection of reactor pressure vessel & internals  
PATE,R J Region 5, San Francisco, Office of the Director  
DODDS,R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/05/31 4pp
- 7907180380 Notification of 790612 meeting w/util in Bethesda, MD to discuss probability analysis of offsite hazards gas pipelines & hazardous transportation  
RODD,H Light Water Reactors Branch 2 79/06/05 3pp
- 7907190428 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " No action required.  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/06 1p
- 7907060032 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79/06/07 1p
- 7907020267 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys."  
ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79/06/11 1p
- 7907190101 Ack receipt of 790530 ltr informing NRC of steps taken to correct violations noted in IE 790201-26 insp.  
ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79/06/11. 1p
- 7907190108 Responds to NRC 790427 ltr re violations noted in IE 790201-26 insp. Corrective actions evaluation of post-weld heat treatment procedure & evaluation of pressure setting for hydraulic pump EC-206.  
MOORE,J B Southern California Edison Co. 79/05/30. 40pp.
- 7907300442 Forwards IE Insp Repts 50-361/79-13 & 50/362/79-13 on 790507-10 No noncompliance noted  
SPENCER,Q S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/14 2pp
- 7907300451 IE Insp Rept 50-361/79-13 & 50-362/79-13 on 790507-10 No noncompliance noted Major areas inspected const activities, including pipe installation & welding & containment post-tensioning sys  
ECKHARDT,J H , DODDS,R T , NARBUT,P P Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/14 4pp
- 7907020450 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/20 1p
- 7907120014 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/21 1p
- 7907120625 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys Piping " No action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/25 1p
- 7907060219 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/26 1p
- 7907050495 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/27 1p
- 7907100531 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/28 1p
- 7907130216 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/07/02. 1p
- 7907180704 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/07/11. 1p
- 7907310399 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required.  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/07/13 1p
- 7907260277 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79/07/18 1p
- 9 Reportable occurrences, LERs & related correspondence
- 7907020287 Forwards PNO-79-67AR  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/05 1p
- 7907030195 Forwards PNO-79-67AB  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/11. 1p
- 7907180738 Ack receipt of 790604 ltr re interim rpt on Taylor Forge pipe defects  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/11. 1p
- 7907030238 Forwards PNO-79-67AT, "Nuclear Incident at TMI "  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/19. 1p.
- 7907050538 Forwards PNO-79-67AU.  
ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/06/26. 1p

7907100651 Ack receipt of 790605 ltr providing addl info re 79051B deficiency rept concerning undersized safety-related high voltage alternating current damper actuators Util 790615 & 051B ltr & deficiency rept encl  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/27 1p

--7907100659 Notifies that suppl info re deficiency rept on undersized safety-related high voltage alternating current damper actuators will be provided by 790727  
NUNN, D E Southern California Edison Co 79/06/15 1p

7907100673 Ack receipt of 790622 ltr forwarding final deficiency rept on Taylor Forge pipe defects Rept will be reviewed & evaluated Final rept & 790622 ltr encl  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/29 1p

--7907100676 Forwards final deficiency rept on Taylor Forge pipe defects  
MOORE, J B Southern California Edison Co 79/06/22 1p

--7907100680 Final deficiency rept on Taylor Forge pipe defects Linear indications identified at surface adjacent to longitudinal seam welds  
\* Southern California Edison Co 79/06/22 8pp

7907100592 Ack receipt of 790622 ltr forwarding final deficiency rept re containment polar crane support girder/bracket connections  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/02 1p

7907100387 Forwards PNO-79-47AV.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/03 1p.

7907102607 Forwards final deficiency report re pipe support design calculation deficiencies  
MOORE, J B Southern California Edison Co 79/07/06 1p

--7907102610 Final deficiency rept re pipe support design calculation deficiencies Design verification & documentation required to support safety-related pipe support designs have been upgraded  
\* Southern California Edison Co 79/07/06 3pp

#### DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

##### A Application/construction stage documents & correspondence

7907050131 Summary of 790427 meeting w/util & C-E in Bethesda, MD re core protection computer review  
RODD, H Light Water Reactors Branch 2. 79/05/18 24pp

7907050378 Forwards addendum to "Cultural Resources & High Voltage Transmission Line From San Onofre to Santiago Substation & Black Star Canyon"  
BASKIN, K P Southern California Edison Co 79/06/27 1p

--7907050382 Addendum to "Cultural Resources & High Voltage Transmission Line From San Onofre to Santiago Substation & Black Star Canyon," by Cultural Sys Research, Inc  
\* Southern California Edison Co 79/04/15 20pp.

7907130459 Responds to structural audit info requests Forwards nonproprietary responses to action items, proprietary & nonproprietary versions of structural design calculation packages & affidavit of LO Hinkelmann  
HAYNES, J O Southern California Edison Co 79/07/06 56pp

7907260666 Forwards "Rept on Exploration/Demobilization of Wells 4 & 5" by Woodward Clyde & "Rept on Deep Exploration Drilling Program, Dewatering Well 7" & "Rept on Exploration/Grouting Program, Dewatering Well 7" (2 vols), by Bechtel  
BASKIN, K P Southern California Edison Co 79/07/11 18pp

--7907260671 "Rept on Exploration/Demobilization of Wells 4 & 5."  
\* Woodward-Clyde Consultants. 79/07/31 313pp

--7907260677 "Rept on Deep Exploration Drilling Program, Dewatering Well 7"  
\* Bechtel Power Corp. (subs of Bechtel Corp.) 79/06/30 230pp.

--7907260683 "Rept on Exploration/Grouting Program Dewatering Well 7," Vol 1.  
\* Bechtel Power Corp (subs. of Bechtel Corp ). 79/06/30 200pp

--7907260685 "Rept on Exploration/Grouting Program, Dewatering Well 7," Vol 2  
\* Bechtel Power Corp (subs of Bechtel Corp ) 79/06/30 200pp.

7907310274 Forwards "Application for Permission to Transfer Ownership Interest to Cities of Anaheim & Riverside, CA & for Amend to CPs CPPR-97 & CPPR-98"  
DRAKE, J H Southern California Edison Co 79/07/17 1p

--7907310280 Ack receipt of antitrust info on 790719 Info acceptable for docketing & distribution  
TOALSTON, A Antitrust & Indemnity Group 79/07/19 2pp

--7907310286 "Application for Permission to Transfer Ownership Interest to Cities of Anaheim & Riverside, CA & for Amend to CP CPPR-97 & CPPR-98," Vols 1-3  
DRAKE, J H Southern California Edison Co 79/07/17 180pp

7907310377 Forwards Jul 1979 "Final Environ Impact Rept" re proposed San Onofre-to-Mission 230 kV transmission line Encl available in Central Files  
BTEGER, D B California, State of 79/07/27 1p

##### F Security, medical, emergency & fire protection plans

7907120475 Summary of 790427 meeting w/Southern CA Edison & San Diego Gas & Electric Co in Bethesda, MD re staff fire protection criteria  
RODD, H Light Water Reactors Branch 2 79/05/29 5pp

--7907120485 Preliminary draft first round questions on fire protection  
\* Light Water Reactors Branch 2 79/05/29 13pp

##### G Adjudicatory correspondence

7907310488 Corrects info submitted to Board on 790306 re issuance of BNH license for new fuel to be used at site Subsequently informed that License BNH-1844 was already issued  
CHANDLER, L J Branch 1 79/08/16 1p

--7907310526 License authorizing receipt, possession & storage of up to 20 g U-235 contained in fission chambers for eventual use in reactors.  
CROW, H T Division of Fuel Cycle & Material Safety. 79/01/02 1p

7907170253 Requests for documents submitted to util by Friends of the Earth Reeks info re effects of dewatering of well cavities, various geologic studies of land area & substratum & siting studies Certificate of Svc encl  
WHARTON, R J Wharton, R J 79/05/22 6pp

7907190198 Petitions NRC to deny GLs. Plant is dangerously sited near active earthquake fault  
RUSSELL, A F, GREENGAUD, B, SILVERMAN, L Affiliation Unknown  
79/06/05 1p.

7907130392 Objection by util to Friends of the Earth 790522 document request Rules of Practice demand that documents be made available for insp & copying Certificate of Svc encl.  
PIGOTT, D R Chickering & Gregory. 79/06/19 4pp

##### H General correspondence

7907050551 Requests time & distance parameters for emergency planning  
HICKS, L H California, State of 79/05/13 1p

--7907050554 Requests info re evacuation & emergency planning  
HICKS, L H California, State of 78/12/31 2pp

##### K Utility Final Safety Analysis Report (FSAR) & amends

7907090252 Submits affidavit of svc & distribution list for Amend 15 to FSAR.  
HAYNES, J O Southern California Edison Co. 79/06/26 3pp.

##### G. Inspection reports, IE Bulletins & correspondence

7907110705 Forwards IE Insp Repts 50-361/79-07 & 50-362/79-07 on 790201-28 & notice of violation.  
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/27 2pp.

## DOCKETED ITEMS

--7907110712 Notice of violation from insp on 790201-28  
\* Region 5, San Francisco, Office of the Director 79/04/27  
2pp

--7907110725 IE Insp Repts 50-361/79-07 & 50-362/79-362 on 790201-28  
Noncompliance noted improper storage of Fin-Fan radiator  
fan motor & nonavailability of procedure qualification  
records for post weld heat-treatment  
PATE, R J, HAIST, D P Region 5, San Francisco, Office of the  
Director HAYNES, R C Region 5, San Francisco, Reactor  
Construction & Engineering Support Branch 79/04/26 8pp

7907130531 Responds to IE Bulletin 79-03 re piping mfg by Youngstown  
Welding & Engineering Co Rept submitted 781201 discussed  
matter in detail & should adequately address issue  
BASKIN, K P Southern California Edison Co 79/05/04 1p

7907260518 Forwards IE Insp Repts 50-361/79-11 & 50-362/79-11 on  
790409-12 No noncompliance noted  
SPENCER, O S Region 5, San Francisco, Reactor Construction &  
Engineering Support Branch 79/05/21 2pp

--7907260649 IE Insp Rept 50-361/79-11 & 50-362/79-11 on 790409-12 No  
noncompliance noted Major areas inspected const activities,  
installation of reactor vessel internals & safety-related  
equipment & preservice insp  
ALBERT, W O, HAIST, D P Region 5, San Francisco, Office of the  
Director HAYNES, R C Region 5, San Francisco, Reactor  
Construction & Engineering Support Branch 79/05/21 9pp

7907090238 Responds to IE Bulletin 79-07 No identified methods  
utilized for seismic analyses of safety-related piping  
BASKIN, K P Southern California Edison Co 79/05/23 2pp

7907090235 Responds to IE Bulletin 79-04 Velan has not supplied, nor  
scheduled to supply, valves for plant use  
BASKIN, K P Southern California Edison Co 79/05/24 1p

7907180694 Summary of 790504 meeting w/utls in Bethesda, MD re  
interpretation of seismic profiles Forwards consultant  
790707 ltr re evaluation of offshore fault  
RODD, H Light Water Reactors Branch 2 79/05/30 6pp

7907280374 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/05/31 1p

7907260965 Forwards IE Insp Repts 50-361/79-12 & 50-362/79-12 on  
790401-30 No noncompliance noted  
SPENCER, O S Region 5, San Francisco, Reactor Construction &  
Engineering Support Branch 79/06/01 2pp

--7907260978 IE Insp Repts 50-361/79-12 & 50-362/79-12 on 790401-30 No  
noncompliance noted Major areas inspected const activities  
including piping storage, fit-up, welding & nondestructive  
testing & protection of reactor pressure vessel & internals  
PATE, R J Region 5, San Francisco, Office of the Director  
DODDS, R T Region 5, San Francisco, Reactor Construction &  
Engineering Support Branch 79/05/31 4pp

7907180580 Notification of 790612 meeting w/utls in Bethesda, MD to  
discuss probability analysis of offsite hazards gas  
pipelines & hazardous transportation  
RODD, H Light Water Reactors Branch 2 79/06/05 3pp

7907190428 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " No action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/06/06 1p

7907060032 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/06/07 1p

7907020267 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys." ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p.

7907190101 Ack receipt of 790530 ltr informing NRC of steps taken to  
correct violations noted in IE 790201-26 insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11. 1p.

--7907190108 Responds to NRC 790427 ltr re violations noted in IE  
790201-26 insp Corrective actions: evaluation of post-weld  
heat treatment procedure & evaluation of pressure setting  
for hydraulic pump EC-206  
MOORE, J B Southern California Edison Co. 79/05/30, 40pp.

7907300442 Forwards IE Insp Repts 50-361/79-13 & 50-362/79-13 on  
790507-10 No noncompliance noted  
SPENCER, O S Region 5, San Francisco, Reactor Construction &  
Engineering Support Branch 79/06/14 2pp

--7907300451 IE Insp Rept 50-361/79-13 & 50-362/79-13 on 790507-10 No  
noncompliance noted Major areas inspected const activities,  
including pipe installation & welding & containment  
post-tensioning sys  
ECKHARDT, J H, DODDS, R T, NARBUT, P P Region 5, San Francisco,  
Reactor Construction & Engineering Support Branch 79/06/14 4pp

7907020450 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate " ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/20 1p

7907120014 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/21 1p

7907120625 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/25 1p

7907060219 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907050495 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/27 1p

7907100531 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/28 1p

7907130216 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/02 1p

7907180704 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/11 1p

7907310399 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/13 1p

7907260277 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/18 1p

8 Reportable occurrences, LERs & related correspondence  
-----

7907020287 Forwards PNO-79-67AR.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/05. 1p

7907030195 Forwards PNO-79-67AS  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11. 1p

7907180738 Ack receipt of 790604 ltr re interim rept on Taylor Forge  
pipe defects.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907030238 Forwards PNO-79-67AT, "Nuclear Incident at TMI." ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/19. 1p.

7907050538 Forwards PNO-79-67AU.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p.



7907100631 Ack receipt of 790605 ltr providing addl info re 790518 deficiency rept concerning undersized safety-related high voltage alternating current damper actuators Util 790615 & OS18 ltrs & deficiency rept encl  
ENQELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/29 1p

--7907100659 Notifies that suppl info re deficiency rept on undersized safety-related high voltage alternating current damper actuators will be provided by 790727  
NUNN, D E Southern California Edison Co 79/06/15 1p

7907100673 Ack receipt of 790622 ltr forwarding final deficiency rept on Taylor Forge pipe defects Rept will be reviewed & evaluated Final rept & 790622 ltr encl  
ENQELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/29 1p

--7907100676 Forwards final deficiency rept on Taylor Forge pipe defects  
MOORE, J B Southern California Edison Co 79/06/22 1p

--7907100680 Final deficiency rept on Taylor Forge pipe defects Linear indications identified at surface adjacent to longitudinal seam welds  
\* Southern California Edison Co 79/06/22 8pp

7907100592 Ack receipt of 790622 ltr forwarding final deficiency rept re containment polar crane support girder/bracket connections  
ENQELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/02 1p

7907130387 Forwards PND-79-67AV  
ENQELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/03 1p

7907120607 Forwards final deficiency report re pipe support design calculation deficiencies  
MOORE, J B Southern California Edison Co 79/07/06 1p

--7907120610 Final deficiency rept re pipe support design calculation deficiencies Design verification & documentation required to support safety-related pipe support designs have been upgraded  
\* Southern California Edison Co 79/07/06 3pp

#### DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907240424 Notification of 790620 meeting w/JCP&L to discuss financial, environ & radiological safety considerations of 760831 application to extend CPPR-96 completion date  
BENEDICT, R A Light Water Reactors Branch 2 79/06/05 2pp.

7907200465 Confirms 790713 telcon requesting summary of NRC meeting w/util re renewal of facility CP  
DNBDORFF, K A New Jersey, State of 79/07/13 1p.

##### Q Inspection reports, IE Bulletins & correspondence

7907050494 Forwards IE Insp Rept 50-363/79-04 on 790403 No noncompliance noted  
CARLBON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/24 2pp

--7907050498 IE Insp Rept 50-363/79-04 on 790403. No noncompliance noted  
Major areas inspected: QA program for containment concrete & linear const  
NARRON, L Region 1, Philadelphia, Office of the Director.  
MCQUAY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/23 3pp

7907060384 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/22 1p

7907030030 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/29 1p

7907200104 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities." No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/05/31 1p.

7907090390 Responds to IE Bulletin 79-07 Version of ADLPIPE Computer Program which includes algebraic summation technique has been used for final design of support for containment spray sys  
FINROCK, I R Jersey Central Power & Light Co 79/06/06 5pp

7907190034 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/06 1p

7907190223 Partially responds to IE Bulletin 78-12B re atypical weld matl C-E will submit generic rept to NRC by 790608 Final response will be provided by 790629  
FINROCK, I R Jersey Central Power & Light Co 79/06/06 1p

7907060096 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/07 1p

7907020045 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/11 1p

7907100468 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230672 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907120497 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907060185 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required.  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100416 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/27 1p

7907100501 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p

7907180767 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p

7907270335 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director.  
79/07/11 1p.

7907310495 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director  
79/07/16 1p

#### DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

##### A. Application/construction stage documents & correspondence

7907090364 Confirms 790622 telcon re Westinghouse 790621 notification of possible startup of steam generator level transmitter ref lags if high energy line break occurs inside containment  
HAIRSTON, W O Alabama Power Co, 79/06/22 1p.

7907180576 Discusses info to be included in Offsite Dose Calculation Manual. Forwards 790126 draft Offsite Dose Calculation Manual  
GLAYTON, F. L. Alabama Power Co 79/07/11 2pp.

## DOCKETED ITEMS

--7907180582 Draft Offsite Dose Calculation Manual  
\* Alabama Power Co 79/01/26 47pp

7907170183 Forwards util 790712 NPDES noncompliance rept submitted to  
EPA re turbine bldg sump effluent  
CLAYTON, F. L. Alabama Power Co 79/07/13 2pp

#### J Insurance & indemnity information

7907030459 Forwards Endorsements 18, 19 & 20 to MAELU Policy NF-93.  
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div  
79/06/26 4pp

#### Q Inspection reports, IE Bulletins & correspondence

7907020333 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
THI - Suppl 1"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110312 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907270036 Forwards IE Insp Rept 50-364/79-08 on 790303-04. No  
noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/05/15 2pp

--7907270043 IE Insp Rept 50-364/79-08 on 790303-04 No noncompliance  
noted Major areas inspected, pre-operational test procedures.  
WAGNER, A Q, MARTIN, R D Region 2, Atlanta, Office of the  
Director 79/05/15 3pp

7907100143 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/03/18 2pp

7907060352 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Licensee  
action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22, 1p.

7907030086 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 1p

7907180172 Responds to IE Bulletin 79-11, "Faulty Overcurrent Trip  
Device in Circuit Breakers for Engineered Safety Sys "  
Westinghouse Types DB-50 & DB-75 circuit breakers are not  
used at facility  
CLAYTON, F. L. Alabama Power Co 79/05/29 1p

7907190145 Responds to IE Bulletin 79-04, "Incorrect Heights for Swing  
Check Valves Mfg by Velan Engineering Corp " Lists Seismic  
Category 1 piping sys where 3/4 or 4-inch valves are  
installed Verifies valve weights  
CLAYTON, F. L. Alabama Power Co 79/05/31 1p

7907200162 Forwards IE Bulletin 79-12, "Short Period Screams at BHR  
Facilities." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp.

7907190144 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06, 2pp

7907060040 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/07 2pp.

7907020190 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11, 1p.

7907020374 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/20, 1p.

7907120033 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310002 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/23, 2pp

7907110259 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/26 2pp

7907180278 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180426 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310223 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907260495 Confirms 790628 & 29 telcons re 790625 ltr requesting that  
certain items in IE Repts 50-348/79-17 & 50-364/79-07  
be withheld as proprietary Per advice of util, repts can now  
be released w/o objection  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/07/03 2pp

--7907260506 Requests that info re unresolved allegations be withheld as  
proprietary until resolution  
CLAYTON, F. L. Alabama Power Co 79/06/25 1p.

--7907260517 Forwards IE Insp Repts 50-348/79-17 & 50-364/79-07 on  
790424-26 & 0514-19 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/06/12 2pp

--7907260542 IE Insp Repts 50-348/79-17 & 50-364/79-07 on 790424-26 &  
0514-19 No noncompliance noted Major areas inspected  
flow-splitters in Unit 1 main loop elbows & allegations re  
const problems  
BLAKE, J J, KLEINSORGE, W P, HERDT, A R Region 2, Atlanta,  
Reactor Construction & Engineering Support Branch 79/06/11  
11pp

7907310360 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/11 1p

#### DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

#### F Security, medical, emergency & fire protection plans

7907250605 Notifies that refund of Class III amend fee is in process  
Waiver for amend to Tech Specs re fire protection is  
warranted  
MILLER, W O License Fee Management Branch 79/06/15 1p

7907230280 Forwards appropriate amend fee for review & approval of  
safeguards contingency plan.  
EHRENSPERGER, W Georgia Power Co 79/07/12, 1p

#### I Financial information

7907050357 Forwards Annual Financial Repts 1978 for GA Power Co &  
Southern Co  
WHITMER, C F, Georgia Power Co. 79/07/02 1p

--7907050384 Annual Financial Rept 1978  
\* The Southern Co 79/02/28, 39PP.

--7907050394 Annual Financial Rept 1978  
\* Georgia Power Co 79/01/31 34pp

#### K Utility Final Safety Analysis Report (FSAR) & amends

7907230195 Forwards Amend 47 to FSAR including inservice insp repts.  
EHRENSPERGER, W, Georgia Power Co 79/07/11, 3pp

--7907230209 Amend 47 to FSAR  
\* Georgia Power Co 79/07/11 35pp

P Operating license stage documents & correspondence

7907180632 Forwards NUREG-0560, "Staff Rept on Generic Assessment of Feedwater Transients in PHRs Designed by B&W" W/o encl  
QRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 79/06/11 2pp

7907120301 Forwards proposed amend to License NPF-5, changing Tech Specs to temporarily delete requirement for HPCI & for reactor core isolation trips to be in effect during performance of special tests on sys Description of test program encl  
WHITMER, C F Georgia Power Co 79/07/02 9pp

7907270309 Forwards Amend B to License NPF-5, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 79/07/03 2pp

--7907270322 Amend B to License NPF-5, revising certain action statements applicable to reactor protection sys & isolation actuation instrumentation  
IPPOLITO, T A Operating Reactors Branch 3 79/07/03 17pp

--7907270328 Safety evaluation supporting Amend B to License NPF-5  
\* Operating Reactors Branch 3 79/07/03 2pp

--7907270332 Notice of issuance & availability of Amend B to License NPF-5  
IPPOLITO, T A Operating Reactors Branch 3 79/07/03 2pp

7907270336 Forwards Amend 9 to License NPF-5, safety evaluation & notice of issuance & availability  
IPPOLITO, T A Operating Reactors Branch 3 79/07/05 2pp.

--7907270341 Amend 9 to License NPF-5, modifying Tech Specs by deleting HPCI & reactor core isolation cooling sys isolation signals on indicated high steam flow supply lines.  
IPPOLITO, T A Operating Reactors Branch 3 79/07/05 5pp.

--7907270346 Safety evaluation supporting Amend 9 to License NPF-5  
\* Operating Reactors Branch 3 79/07/05 App

--7907270350 Notice of issuance & availability of Amend 9 to License NPF-5  
IPPOLITO, T A Operating Reactors Branch 3 79/07/05 2pp

7907170066 Forwards proposed Tech Spec changes re spent fuel pool storage expansion & proposed determination of amend fee & design rept & safety evaluation.  
WHITMER, C F Georgia Power Co 79/07/09 3pp

--7907170069 Proposed Tech Spec changes re spent fuel pool storage expansion  
\* Georgia Power Co 79/07/09 8pp

--7907170073 "Spent Fuel Pool Mod." design rept & safety evaluation  
\* Georgia Power Co 79/07/09 69pp

7907240339 Forwards proposed amends to Tech Specs of App B to Licenses DPR-57 & NPF-5 Changes will allow 90-day extension for annual environ surveillance rept when radiological & nonradiological data results not available  
EHRENSPERGER, W Georgia Power Co 79/07/12 4pp

7907260691 Ack receipt of 790629 request for info required by NRC to review corporate capabilities before 790730 Seeks extension to 790831 because of extent of request.  
WHITMER, C F Georgia Power Co 79/07/19 1p

7907260746 Requests amend to App A of License NPF-5, revising Tech Specs re surveillance requirements for diesel-generator & channel calibr following seismic event & correcting max permissible level numbers in Table 3.3.6 2-1  
WHITMER, C F. Georgia Power Co. 79/07/19. 3pp.

--7907260751 Revised Tech Specs re surveillance requirements for diesel generator & channel calibr following seismic event & max permissible level numbers of seismic monitoring instruments in Table 3.3.6 2-1  
\* Georgia Power Co. 79/07/19. App

7907270187 Requests amend to License NPF-5, revising Tech Specs to increase average drywell temp limit from 135 F to 145 F. Proposed Tech Spec change & amend fee encl.  
WHITMER, C F. Georgia Power Co. 79/07/23 2pp

--7907270193 Proposed Tech Spec change to License NPF-5, raising average drywell temp limit from 135 F to 145 F  
\* Georgia Power Co 79/07/23 3pp

Q Inspection reports, IE Bulletins & correspondence

7907180087 Forwards list of Region 2 personnel for whom permanent nonemployee badges are requested  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/19 4pp

7907020342 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110329 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907180233 Forwards IE Insp Rept 50-366/79-14 on 790425-27 No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 2pp

--7907180244 IE Insp Rept 50-366/79-14 on 790425-27 No noncompliance noted Major areas inspected startup testing activities  
VODOT-LOWELL, R, MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/09 4pp

7907190243 Responds to IE Bulletin 79-09 Several Type AKL-2-15, AK-2-25 & AK-2-50 circuit breakers are currently in use None have undervoltage trip device incorporated  
WIDNER, W A Georgia Power Co 79/05/16 2pp

7907100196 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907060359 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 1p

7907100160 Responds to IE Bulletin 79-10 Forwards operator & senior operator examination results & statistics.  
STAFFA, R W Georgia Power Co. 79/05/24. 3pp

7907030078 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907180058 Requests extension until 790629 for responding to IE Bulletins 78-12, 78-12A & 78-12B  
STAFFA, R W Georgia Power Co 79/05/29 1p

7907200196 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp.

7907120426 Forwards list of Region 2 personnel for whom permanent non-employee badges are requested  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/04 3pp

7907190173 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
O'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/06/06 2pp

7907060059 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
O'REILLY, J P. Region 2, Atlanta, Office of the Director 79/06/07. 2pp.

7907190085 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-07 & 50-366/79-08  
MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/08. 1p.

## DOCKETED ITEMS

- 7907190093 Responds to NRC 790402 ltr re violations noted in IE Insp Repts 50-321/79-07 & 50-366/79-08 Corrective actions importance of corrective action verification emphasized during regular training sessions  
STAFFA, R W Georgia Power Co 79/04/25 2pp
- 7907190103 Forwards IE Insp Repts 50-321/79-07 & 50-366/79-08 on 790220-22, 2B & 0302 & notice of violation.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- 7907190110 Notice of violation from Insp on 790220-22, 2B & 0302  
\* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 1p
- 7907190121 IE Insp Repts 50-321/79-07 & 50-366/79-08 on 790220-22, 2B & 0302 Noncompliance noted failure to take corrective action on nonconforming concrete expansion anchors & failure to rep significant const deficiency  
BRVANT, J C, MODENOS, L, COMPTON, R M Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 4pp
- 7907250163 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 3pp
- 7907190355 Responds to IE Bulletins 79-01 & 79-01A Engineering review of environ qualification is being performed Incomplete results indicate that reactor water sample isolation valve solenoids & MSIV limit switches are not in compliance  
STAFFA, R W Georgia Power Co 79/06/13 1p
- 7907260136 Ack receipt of IE Insp Rept 50-366/79-14 No proprietary info  
STAFFA, R W Georgia Power Co 79/06/15 1p
- 7907190518 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 2pp
- 7907120079 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p
- 7907110228 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p
- 7907250086 Ack receipt of IE Insp Rept 50-366/79-18 No proprietary info  
STAFFA, R W Georgia Power Co 79/06/22 1p
- 7907310020 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bypass Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28, 2pp
- 7907180436 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp
- 7907310254 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bypass" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp
- 7907100437 Forwards addl info to 790613 response to IE Bulletins 79-01 & 79-01A Class IE equipment has been found capable of functioning under postulated accident conditions, except for items identified in util 790613 response  
STAFFA, R W Georgia Power Co 79/07/03 10pp
- 7907310383 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 1p
- R Periodic operating reports & related correspondence
- 7907060234 Forwards Suppl 1, "Discharges to Ground," to Annual Environ Surveillance Rept 1978  
MANRY, M Georgia Power Co 79/06/27 1p.
- 7907060236 Suppl 1, "Discharges to Ground," to Annual Environ Surveillance Rept 1978  
\* Georgia Power Co 79/06/30 39pp
- 7907100350 Forwards Suppl 2 to Annual Environ Surveillance Rept, 1978  
MANRY, M Georgia Power Co 79/07/02 1p
- 7907100360 Suppl 2 to Annual Environ Surveillance Rept, 1978  
\* Georgia Power Co 78/12/31 52pp
- 7907170220 Forwards monthly operating rept for June 1979  
MANRY, M Georgia Power Co 79/07/09, 1p
- 7907170222 Monthly operating rept for June 1979  
ALLEN, P B Georgia Power Co 79/07/05 7pp
- 7907190564 Forwards monthly operating rept for June 1979  
MANRY, M Georgia Power Co 79/07/09 1p
- B Reportable occurrences, LERs & related correspondence
- 7907110506 Forwards LER 78-064/03L-0  
MANRY, M Georgia Power Co 78/11/17 1p
- 7907110517 LER 78-064/03L-0 on 781106 during run mode & attempt to perform HPCI quick start, HPCI control valves failed to operate Caused by loose wire in speed feedback signal circuit Wire secured & HPCI quick start completed  
NIX, R T Georgia Power Co 78/11/17 1p
- 7907110400 Forwards LER 78-067/03L-0  
MANRY, M Georgia Power Co 78/11/27 1p
- 7907110407 LER 78-067/03L-0 on 781112 while performing procedure HNP-2-5202 on RB21-N017B, instrument found to be out of tolerance Caused by setpoint drifting by as much as 8 inches Instrument replaced  
NIX, R T Georgia Power Co 78/11/27 1p
- 7907110588 Forwards LER 78-069/03L-0  
MANRY, M Georgia Power Co 78/11/27 1p
- 7907110594 LER 78-069/03L-0 on 781113 while performing operability test on RC diesel, 8-h time limit surveillance on other diesels ran out Since operability test on RC diesel was in progress, not necessary to test remaining diesels  
\* Georgia Power Co 78/11/27 1p
- 7907020248 Forwards LER 79-048/03L-0.  
MANRY, M Georgia Power Co 79/06/15 1p
- 7907020253 LER 79-048/03L-0 on 790603 while operating at 86% power increase, average drywell temp was 135.3 F Caused by control rod drive line being left off during drywell closeout Part replaced Investigations continue  
\* Georgia Power Co 79/06/15 2pp
- 7907020259 Forwards LER 79-047/03L-0  
MANRY, M Georgia Power Co 79/06/18 1p.
- 7907020264 LER 79-047/03L-0 on 790602 both strainers on standby pump were isolated, thereby isolating pump to B diesel generator Caused by incorrect installation of valve Operators have been reinstructed.  
BAXLEY, B X Georgia Power Co 79/06/18 2pp
- 7907020283 Forwards LER 79-049/03L-0.  
MANRY, M Georgia Power Co 79/06/21 1p.
- 7907020294 LER 79-049/03L-0 on 790608 HPCI vacuum tank condensate pump (2E41-C002-1) tripped after which vacuum pump (2E41-C002-2) also tripped Caused by burnt coil in motor shunt field Condensate motor coil replaced  
NIX, R T Georgia Power Co 79/06/21, 1p.
- 7907020302 Forwards LER 79-050/03L-0  
MANRY, M Georgia Power Co 79/06/21, 1p.
- 7907020308 LER 79-050/03L-0 on 790609 while performing HPCI valve operability test, pump suction valve failed to open within specified time. Caused by loose connection in shunt field circuit. Connection tightened & motor released.  
NIX, R T Georgia Power Co. 79/06/21 1p.

7907030194 LER 50-366/78-20 has been voided  
MANRY,M Georgia Power Co 79/06/26 1p

7907090360 Forwards LER 79-053/03L-0  
MANRY,M Georgia Power Co 79/06/26 1p

--7907090363 LER 79-053/03L-0 on 790611 high trip setpoint of monitor  
2D11-K603D was higher than Tech Spec limits Caused by  
personnel error Setpoint corrected  
NIX,R T Georgia Power Co 79/06/26 1p

7907050372 Forwards LER 79-052/03L-0  
MANRY,M Georgia Power Co 79/06/27 1p

--7907050376 LER 79-052/03L-0 on 790612 reactor cooldown max rate of  
100 F/h was exceeded Caused by manually starting HPCI  
during scram, resulting in rapid pressure Personnel  
admonished  
BAXLEY,B X Georgia Power Co 79/06/27 2pp

7907110357 LER 78-020 has been voided  
\* Georgia Power Co 79/06/27 1p

7907110362 LER 78-086 has been voided  
\* Georgia Power Co 79/06/27 1p

7907090330 RD 1979-59 on 790627 reactor scram followed MBIV closure  
test Reactor core isolation cooling & HPBI sys isolated on  
steam line high differential pressure Cause Undetermined Sys  
manually started & secured  
MANRY,M Georgia Power Co 79/06/28 2pp

7907060305 LER 79-051 has been voided  
MANRY,M Georgia Power Co 79/07/02 1p

7907090336 Forwards LER 79-055/03L-0  
MANRY,M Georgia Power Co 79/07/02 1p

--7907090344 LER 79-055/03L-0 on 790618 linear heat generation rate  
increased from 87% limiting valve to 106% w/corresponding 3%  
increase in thermal power during test Caused by rod  
withdrawal Rods inserted & rate lowered to 98%  
GREENE,T V Georgia Power Co 79/07/02 2pp

7907170100 Forwards LER 79-054/03L-0  
MANRY,M Georgia Power Co 79/07/06 1p

--7907170105 LER 79-054/03L-0 on 790619 drywell pressure exceeded Tech  
Specs limit following shutdown from load reject test Caused  
by loss of drywell cooling from tripped chillers Drywell  
venting returned pressure below limit within 15 minutes  
BAXLEY,B X Georgia Power Co 79/07/06 1p

7907180545 Forwards LER 79-059/01T-0  
MANRY,M Georgia Power Co 79/07/06 1p

--7907180551 LER 79-059/01T-0 on 790628 reactor screamed as result of  
MBIV closure During resulting transient,RCIC & HPCI  
isolated on steam line high differential pressure Cause of  
RCIC isolation unknown,HPCI switch was recalibr.  
GREENE,T V Georgia Power Co 79/07/06 3pp

7907170089 Forwards LER 79-056/03L-0  
MANRY,M Georgia Power Co 79/07/10 1p

--7907170096 LER 79-056/03L-0 on 790620 during startup test,reactor core  
isolation exhaust & RHR heat exchanger vents to torus  
increased water level to 150 7 inches,exceeding Tech Specs  
Drainage decreased water level below limit within one hour.  
BAXLEY,B X Georgia Power Co 79/07/10 1p.

7907170216 Forwards LER 79-058/03L-0  
MANRY,M Georgia Power Co 79/07/10 1p

--7907170219 LER 79-058/03L-0 on 790625 while at power level of 66%,  
control mass peaking factor discovered exceeding design  
Caused by inaccurate calculation of existing core  
conditions Computer data base updated  
GREENE,T V Georgia Power Co 79/07/10. 2pp.

7907230480 Forwards LER 79-057/03L-0  
MANRY,M Georgia Power Co 79/07/10 1p

--7907230482 LER 79-057/03L-0 on 790624:while performing test for avc  
water operability, valve closed & would not reopen  
Electrically Caused by torque switch corroding to switch  
shaft Torque switch repaired  
DAYLEY,C Georgia Power Co. 79/07/10 2pp.

7907230467 Forwards LER 79-062/03L-0  
MANRY,M Georgia Power Co 79/07/17 1p

--7907230473 LER 79-062/03L-0 on 790628 during shutdown,main steam safety  
relief valve discharge line vacuum breaker valves found in  
open position Caused by misalignment of valve when  
installed Study underway on addition of alignment device  
NIX,R T Georgia Power Co 79/07/12 2pp

7907230477 Forwards LER 79-061/03L-0  
MANRY,M Georgia Power Co 79/07/13 1p

--7907230486 LER 79-061/03L-0 on 790627 while shutting down reactor,core  
isolation cooling barometric condensate pump tripped Caused  
by personnel stepping on & damaging motor connection box  
Personnel instructed re damage repts  
NIX,R T Georgia Power Co 79/07/13 2pp

7907230546 Forwards LER 79-064/03L-0.  
MANRY,M Georgia Power Co 79/07/13 1p.

--7907230553 LER 79-064/03L-0 on 790701 on 790214 RCIC initiated on low  
water level following reactor scram & isolated before  
injecting to vessel Possibly due to failed check valve  
GREENE,T V Georgia Power Co 79/07/13 1p

7907240224 LER 79-063 has been voided  
MANRY,M Georgia Power Co 79/07/17 1p

7907230316 Forwards LER 78-030/03L-1  
MANRY,M Georgia Power Co 79/07/18 1p

--7907230319 LER 78-030/03L-1 on 780910 while fully open,RHR valves  
failed to close when given close signal Caused by valve  
gates that sagged & galled at gate guides Two separate  
wedge guides welded to inside surface of bonnet  
NIX,R T Georgia Power Co 79/07/18 3pp

7907260799 Forwards LER 79-062/01T-1  
MANRY,M Georgia Power Co 79/07/18 1p

--7907260813 LER 78-062/01T-1 on 781101,condensing pots 2B21-DO04A & B  
not installed per design,resulting in 11 2 inch error in  
calibr of 2B21-N017A-D level switches Caused by installation  
design error Detail drawings corrected  
NIX,R T Georgia Power Co 79/07/18 1p

7907260824 Forwards LER 79-065/03L-0  
MANRY,M Georgia Power Co 79/07/18 1p

--7907260833 LER 79-065/03L-0 on 790703 during surveillance procedure  
HNP-2-3055,rod block monitor A downscale setpoint found to  
be high Caused by setpoint drift Component recalibr &  
surveillance procedure completed  
NIX,R T Georgia Power Co 79/07/18 1p

#### DOCKET 50-367 BAILLY GENERATING STATION

##### A Application/construction stage documents & correspondence

7907020310 Forwards suppl info,clarifications & alternatives to  
foundation pile design Proposals developed for improving  
subsoil conditions within preconstruction areas & for  
defining criteria for pile placement,splices & load tests  
BHORB,E M Northern Indiana Public Service Co. 79/05/29 6pp

7907300171 Notification of 790717-1B meeting w/Mark II owners group &  
OE in Lebanon,NH to discuss Mark II pool dynamic programs  
ANDERSON,C J Containment Systems Branch 79/07/03. 12pp

##### O. Advisory Committee on Reactor Safeguards reports & correspondence

790719006B Requests that ACRB identify & address engineering & safety  
issues arising from use of shorter pilings,as opposed to  
longer pilings,as originally planned  
HENDRIE,J M. Commission 79/06/08 1p

##### Q. Inspection reports, IE Bulletins & correspondence

7907160242 Responds to IE Bulletin 79-07 re methods of combination of  
seismic directional responses.None of computer programs used  
for seismic analysis of safety-related piping use algebraic  
techniques described.  
BHORB,E M Northern States Power Co 79/05/21 3pp.

## DOCKETED ITEMS

7907090424 Responds to IE Bulletin 79-09 GE Type Ak-2 circuit breakers not used in safety-related sys  
SHORB, E H Northern Indiana Public Service Co 79/05/29 1p

7907200322 Forwards IE Bulletin 79-12, "Short Period Scrums at BHR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190276 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240428 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020258 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907300326 Forwards IE Insp Rept 50-367/79-02 on 790515-16 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/13 2pp

--7907300328 IE Insp Rept 50-367/79-02 on 790515-16 No noncompliance noted Major areas inspected environ protection, including administrative controls & review of ecological monitoring program  
GERTHANN, H J, ESSIG, T H Region 3, Chicago, Office of the Director 79/06/07 4pp

7907020432 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120242 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907130131 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060315 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050477 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907180420 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130279 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907310340 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310412 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260194 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260399 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

#### A Periodic operating reports & related correspondence

7907060232 Forwards well charts for 790613-20, Bailly wells w/o recorders for 790621, pond levels for 790621, pneumatic pressure transducers for 790620 & water meter readings for 790620  
BOHN, R J Northern Indiana Public Service Co 79/06/29 32pp

7907130039 Forwards "1978-1979 Annual Rept, Bailly Nuclear-1 Site," Apr 1978-Mar 1979  
PURCELL, J F Northern Indiana Public Service Co 79/07/02 1p

--7907130044 "1978-79 Annual Rept, Bailly Nuclear-1 Site," Apr 1978-Mar 1979, Prepared by TX Instruments Corp.  
\* Northern Indiana Public Service Co 79/06/30 400pp.

7907120387 Forwards 790620-27 well charts, 790627 Bailly wells w/o recorders, 790627 pond levels, 790627 pneumatic pressure transducers & 790627 water meter readings  
BOHN, R J Northern Indiana Public Service Co 79/07/06 32pp

7907230566 Submits well charts for 790627-0705, including charts for Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USOB wells for 790705  
BOHN, R J Northern Indiana Public Service Co 79/07/13 33pp

7907270245 Forwards well charts for 790705-11 & charts for Bailly wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 790711  
BOHN, R J Northern Indiana Public Service Co 79/07/20 32pp

#### DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

#### F Security, medical, emergency & fire protection plans

7907300560 Ack receipt of 790430 submission of Revision 2 to fire protection plan Forwards discussion of two points found unacceptable Plan should apply to both Unit 1 & Unit 2  
REID, R W Operating Reactors Branch 4 STOLZ, J F Light Water Reactors Branch 1 79/06/13 3pp.

7907230573 Discusses progress in completing items listed in Table 3 1 of fire protection safety evaluation Water spray shields & ventilation duct fire dampers will be installed during next refueling outage.  
TRIMBLE, D C Arkansas Power & Light Co 79/07/17 2pp

#### J Insurance & indemnity information

7907050211 Forwards Endorsements 36-39 to NELIA Policy NF-210 & Endorsements 32-35 to MACLU Policy MF-74  
TRIMBLE, D C Arkansas Power & Light Co 79/06/28 9pp

#### P Operating license stage documents & correspondence

7907120601 Forwards proprietary & nonproprietary versions of CEN-39(A), Revision 2 & both versions of Suppl 1, Revision 1, Affidavit encl.  
WILLIAMS, D H. Arkansas Power & Light Co 79/01/11 6pp

--7907120603 "CPC Protection Algorithm Software Change Procedure," Revision 2 Nonproprietary version of C-E rept.  
\* Arkansas Power & Light Co 78/12/10 56pp

--7907120605 "CPC Protection Algorithm, Software Change Procedure," Suppl 1-NP, Revision 1 Nonproprietary version of C-E rept.  
\* Arkansas Power & Light Co. 79/01/05 96pp.

7907020156 Provides info requested in 770322 ltr & Amend 1 to License NPF-6. Forwards proprietary & nonproprietary versions of "Determination of Plant Protection Sys Trip Setpoint Values " Affidavit encl.  
RUETER, D A Arkansas Power & Light Co 79/02/28 6pp

--7907020161 Nonproprietary version of "Determination of Plant Protection Sys Trip Setpoint Values "  
\* Arkansas Power & Light Co 79/07/02 45pp

7907060407 Provides status of IE Bulletin 79-01 response Projected  
 submittal date is 790714  
 TRIMBLE, D C Arkansas Power & Light Co 79/05/03 1p

7907250051 Forwards Amend 12 to License NPF-6, safety evaluation &  
 notice of issuance & availability  
 STOLZ, J F Light Water Reactors Branch 1 79/06/12 3pp

--7907250061 Amend 12 to License NPF-6, modifying App A Tech Specs to  
 include nuclear software export as member of plant safety  
 committee & deleting restrictions on making changes to core  
 protection sys  
 STOLZ, J F Light Water Reactors Branch 1 79/06/12 6pp

--7907250072 Safety evaluation supporting Amend 12 to License NPF-6  
 STOLZ, J F, ENGLE, L B Light Water Reactors Branch 1  
 79/06/12 10pp

--7907250080 Notice of issuance & availability of Amend 12 to License  
 NPF-6  
 STOLZ, J F Light Water Reactors Branch 1 79/06/12 2pp

7907170125 Forwards 790709 draft offsite dose calculation manual  
 TRIMBLE, D C Arkansas Power & Light Co 79/07/09 1p

--7907170128 Draft Offsite Dose Calculation Manual  
 \* Arkansas Power & Light Co 79/07/09 105pp

7907270182 Forwards form ltr to B&W operating plants re revised  
 operating guidelines in event of engineered safety features  
 sys activation caused by low reactor coolant pressure.  
 GEISLER, G D Babcock & Wilcox Co 79/07/20 2pp

7907310439 Proposes change to Tech Specs re response time for  
 steam-driven emergency feedwater pump Forwards revised page  
 of Tech Specs w/vertical lines showing items changed Class  
 III fee encl  
 CAVANAUGH, W Arkansas Power & Light Co 79/07/24 4pp

#### G Inspection reports, IE Bulletins & correspondence

7907160062 Comments on licensee response to IE Bulletin 79-05A  
 MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
 Branch 79/04/13 3pp

7907160009 Forwards evaluation by IE Region 4 of licensee 790416  
 responses to IE Bulletin 79-05A  
 VARGA, B A Light Water Reactors Branch 4 79/04/20 1p.

--7907160017 Evaluates licensee 790416 response to IE Bulletin 79-05A  
 MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear  
 Support Branch 79/04/14 3pp

7907120001 Forwards IE Insp Rept 50-313/79-07 & 50-368/79-07 on  
 790319-0413 & notice of violation  
 MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
 Branch 79/05/01 2pp

--7907120003 Notice of violation from insp on 790319-0413  
 \* Region 4, Dallas, Office of the Director 79/05/01 2pp

--7907120007 IE Insp Rept 50-313/79-07 & 50-368/79-07 on 790319-0413  
 Noncompliance noted. Failure to adhere to procedures.  
 JOHNSON, W D, SPANGLER, R O, WESTERMAN, T F Region 4, Dallas,  
 Reactor Operations Nuclear Support Branch 79/05/01 20pp.

7907060417 Forwards partial response to IE Bulletin 79-03 re use of  
 Youngstown longitudinal welded pipe in safety-related sys  
 Volumetric examination of longitudinal welds has begun Fully  
 developed program will be submitted by 790622.  
 TRIMBLE, D C Arkansas Power & Light Co 79/05/14 1p

7907090439 Forwards IE Insp Repts 50-313/79-08 & 50-368/79-08 on  
 790426-27 No noncompliance noted  
 MADSEN, G L Region 4, Dallas, Office of the Director 79/05/17  
 2pp

--7907090446 IE Insp Repts 50-313/79-08 & 50-368/79-08 on 790516. No  
 noncompliance noted. Major areas inspected: radiation  
 protection program, respiratory protection program, posting &  
 controls & radiological surveys  
 MURRAY, B, BROWN, G D Region 4, Dallas, Fuel Facility &  
 Materials Safety Branch, 79/05/16, 6pp

7907100283 Forwards IE Circular 79-08, "Attempted Extortion - Low  
 Enriched U " No action required.  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18  
 1p

7907060325 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
 in Circuit Breakers for Engineered Safety Sys " Licensee  
 action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/22  
 1p

7907180225 Submits info requested in IE Bulletin 79-10 re  
 requalification training program statistics  
 TRIMBLE, D C Arkansas Power & Light Co 79/05/25 5pp

7907060411 Notifies that rept on records search requested by IE  
 Bulletin 78012 is currently underway by C-E Final response  
 re reactor vessels will be submitted by 790629  
 TRIMBLE, D C Arkansas Power & Light Co 79/05/29 1p

7907200343 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
 Facilities " No action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31  
 1p

7907190390 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
 Class IE Equipment (Deficiencies in Environ Qualification of  
 ASCO Solenoid Valves) " Action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06  
 1p

7907060010 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
 action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07  
 1p

7907020443 Forwards IE Info Notice 79-17, "Source Holder Assembly  
 Damage from Misfit Between Assembly & Reactor Upper Grid  
 Plate, "   
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20  
 1p

7907120370 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
 Plate Designs Using Concrete Expansion Anchor Bolts " Action  
 required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21  
 1p.

7907020013 Forwards IE Circular 79-09, "Occurrence of Split or  
 Punctured Regulator Diaphragms in Certain Self-Contained  
 Breathing Apparatus "   
 BEYFRIT, K V Region 4, Dallas, Office of the Director, 79/06/22  
 1p

7907120590 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
 Piping, " Action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25  
 1p

7907100385 Forwards IE Circular 79-10, "Pipefittings Mfg from  
 Unacceptable Matl " No action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26,  
 1p

7907180376 Forwards IE Circular 79-12, "Potential Diesel Generator  
 Turbocharger Problem " No action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28  
 1p

7907240271 Ack receipt of 790423 & 0612 ltrs informing NRC of steps  
 taken to correct violations noted in IE Insp Repts  
 50-313/79-08 & 50-368/79-08  
 MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
 Branch 79/06/29 1p.

7907310207 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
 Safety-Related Piping Sys " Action required.  
 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02,  
 1p

7907310619 Forwards IE Info Notice 79-18, "Skylab Reentry " No action  
 required.  
 BEYFRIT, K V Region 4, Dallas, Office of the Director, 79/07/06,  
 1p.

7907190489 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "   
 Action required  
 BEYFRIT, K V Region 4, Dallas, Office of the Director, 79/07/11  
 1p

7907240279 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
 Pump Starting Contactors, " No action required.  
 BEYFRIT, K V Region 4, Dallas, Office of the Director, 79/07/13  
 1p.

## DOCKETED ITEMS

7907260325 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant  
Corrated Water Sys at PWR Plants " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/17  
1p

7907260231 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18  
1p

#### R Periodic operating reports & related correspondence

7907190541 Forwards monthly operating rept for June 1979  
TRIMBLE, D C Arkansas Power & Light Co 79/07/11 1p

--7907190544 Monthly operating rept for June 1979.  
SHIVELY, C N Arkansas Power & Light Co 79/07/11 6pp

#### S Reportable occurrences, LERs & related correspondence

7907030296 Forwards PND-79-67A0, "Nuclear Incident at TMI "  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/05/31 1p

7907020297 Forwards PND-79-67AR  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/06/05 1p

7907030175 Forwards PND-79-67AS  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/06/13 1p

7907030218 Forwards PND-79-67AT  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/06/19 1p

7907050090 Forwards LERs 79-039/03L-0 & 79-038/03L-0  
TRIMBLE, D C Arkansas Power & Light Co 79/06/26 1p

--7907050102 LER 79-039/03L-0 on 790527 during NRC audit of Category E  
valve positions, while in Mode 3 operation, low pressure  
safety injection discharge header valve 251-5091-3 was  
discovered in closed position Cause Unstated Valve opened  
SHIVELY, C N Arkansas Power & Light Co 79/06/26 1p

--7907050107 LER 79-038/03L-0 on 790527 during main steam safety valve  
testing in Mode 3 operation, steam generator A pressure  
indicator, 2PI-1041-A on Channel DPPS, failed high Caused by  
heat breakdown of some component  
SHIVELY, C N Arkansas Power & Light Co 79/06/26 1p

7907130307 Forwards PND-79-67AU  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/06/27 1p

7907090289 Forwards LERs 79-040/03L-0 & 79-043/03L-0  
TRIMBLE, D C Arkansas Power & Light Co 79/06/28 1p

--7907090292 LER 79-040/03L-0 on 790603 during Mode 3 operation,  
emergency feedwater valve from electric pump to B steam  
generator, would not stroke shut Caused by coil & tripper  
bar being out of adjustment Valve repaired  
SHIVELY, C N Arkansas Power & Light Co 79/06/27 1p

--7907090297 LER 79-043/03L-0 on 790609 during Mode 3 operation,  
emergency feedwater control valves from electric pump to A  
steam generator failed to close Caused by loose wire on  
handswitch Valve filled & vented w/oil.  
SHIVELY, C N Arkansas Power & Light Co 79/06/27 1p

7907120645 Forwards LERs 79-041/03L-0, 79-042/03L-0 & 79-037/03L-1  
TRIMBLE, D C Arkansas Power & Light Co 79/07/06 1p

--7907120650 LER 79-041/03L-0 on 790607 failure to perform surveillance  
test on containment personnel hatch within specified time  
limit Caused by irregularity of testing on weekends Testing  
rescheduled to fall on Monday, Wednesday & Friday  
SHIVELY, C N Arkansas Power & Light Co 79/07/06 1p

--7907120654 LER 79-042/03L-0 on 790607 reheat stop valve 4 would not  
open during Mode 1 operation w/main turbine latched,  
Caused by mechanical binding of reheat stop valve to seat  
Valve freed & trip tested  
SHIVELY, C N Arkansas Power & Light Co 79/07/06 1p

--7907120660 LER 79-037/03L-1 on 790614 supply valves 2CV-1039-2 &  
CV-1076-2 to steam generator 2E24B would not respond during  
Mode 3 operation Caused by blown fuse & stuck relay Repairs  
made & valves proven operable  
SHIVELY, C N Arkansas Power & Light Co 79/07/06 1p

7907160283 Forwards LERs 79-044/03L-0 & 79-045/03L-0  
TRIMBLE, D C Arkansas Power & Light Co 79/07/09 1p

--7907160296 LER 79-044/03L-0 on 790610 valve operator tripped circuit  
breaker on overload & affected containment penetration  
automatic isolation valve deactivated in closed position  
Caused by valve shaft binding in packing Valve tested  
SHIVELY, C N Arkansas Power & Light Co 79/07/09 1p

--7907160308 LER 79-045/03L-0 on 790613 channel A core protection  
calculator taken out of bypass, resulting in linear power  
density & DNBR trip Cause unknown Channel tested & returned  
to svc  
SHIVELY, C N Arkansas Power & Light Co 79/07/09 1p

7907180669 Forwards PND-79-67AV & AW  
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support  
Branch 79/07/10 1p

7907300297 Forwards LER 79-046/03L-0  
TRIMBLE, D C Arkansas Power & Light Co 79/07/18 1p

--7907300307 LER 79-046/03L-0 on 790619 leakage of seal on personnel  
escape hatch was in excess of 50,000 cubic centimeters/  
minute Cause not given Seal replaced Retest indicated  
no leakage  
SHIVELY, C N Arkansas Power & Light Co 79/07/18 1p

#### DOCKET 50-369 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907160109 Draft memo re licensing strategy for plants w/fuel load  
dates in CV79  
BOYD, R S Division of Project Management 79/03/28 6pp

7907260120 Summary of 790608 meeting w/util in Bethesda, MD re  
draft radiological effluent Tech Specs & Offsite Dose  
Calculation Manual  
BOEGLI, J S Effluent Treatment Systems Branch 79/06/18 5pp

7907250377 Informs of change in projected fuel load dates to May 1980  
for Unit 1 & Jan 1982 for Unit 2 & change in commercial  
operation dates to Aug 1980 for Unit 1 & Apr 1982 for  
Unit 2 Formal request to follow  
PARKER, W O Duke Power Co 79/07/20 1p

##### 0 Adjudicatory correspondence

7907110499 State of IL opposition to NRC 790504 motion & Comm Ed 790507  
motion for reconsideration &/or clarification & referral of  
ASLB 790419 memo & order admitting Contentions 6 & 11  
SEKULER, S N Illinois, State of 79/05/17 6pp

--7907110572 Forwards new info re analysis of sabotage & possible  
consequences, potentially relevant to McGuire proceedings  
w/o encl Certificate of Bvt encl  
CARTER, T F Division of Safeguards 79/01/22 3pp

7907170247 Confirms 790522 conversation re info requested in 790503 ltr  
on status of proposed amend to Byproduct/Matl License  
BNM-1773 issued to Duke Power Co Hearings scheduled for  
790619-19 in Charlotte, NC  
KETCHEN, E G Branch 4 79/05/23 1p

##### K Utility Final Safety Analysis Report (FSAR) & amends

7907120559 Forwards Amend 61 to application for OL, consisting of  
Revision 37 to FSAR  
PARKER, W O Duke Power Co. 79/07/09 2pp

--7907120562 Revision 37 to FSAR W/34 oversized drawings  
\* Duke Power Co 79/07/06 164pp.

##### Q Inspection reports, IE Bulletins & correspondence

7907020417 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI -  
Suppl." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/28 2pp.



7907110319 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907110091 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 2pp

7907240155 Forwards IE Insp Rept 50-369/79-23 on 790508-11 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/25 2pp

--7907240163 IE Insp Rept 50-369/79-23 on 790508-11 No noncompliance noted Major areas inspected storage installed electrical penetration assemblies & installation of & records for instrumentation components & sys  
RUFF, A B Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/25 3pp

7907030093 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907090382 Requests extension of time for responding to IE Bulletins 7B-12, 12A & 12D  
PARKER, W O Duke Power Co 79/05/29 1p

7907190565 Responds to IE Bulletin 79-04 Review of sys revealed no swing check valves mfg by Velan Engineering Corp in use  
PARKER, W O Duke Power Co 79/05/29 1p

7907190750 Responds to IE Bulletin 79-07 re use of particular computer codes PISOL & SUPERPIPE used on all piping analyses, except analyses performed by Westinghouse.  
PARKER, W O Duke Power Co 79/05/29 2pp

7907200186 Forwards IE Bulletin 79-12, "Short Period Bcrams at BNR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907160185 Ack receipt of IE Insp Rept 50-369/79-16 on 790305-09 No proprietary info  
PARKER, W O Duke Power Co 79/06/04 1p

--7907160191 Forwards IE Insp Rept 50-369/79-16 on 790305-09. No noncompliance noted  
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/10 2pp

--7907160195 IE Insp Rept 50-369/79-16 on 790305-09 No noncompliance noted Major areas inspected plant procedures  
DUZTS, J E, FORD, E J, KELLOO, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/05 15pp

7907190153 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Bolonoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907100161 Forwards IE Info Notice 79-15  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020205 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907250153 Requests that Region 2 measurements can be granted access privileges of "licensee designated vehicle "  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/11 3pp.

7907020382 Forwards IE Info Notice 79-17, "Source Holder Assembly Damaged from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120061 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310009 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180263 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/26 2pp

7907180303 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180597 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907270375 Ack receipt of 790619 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/79-22 & 50-370/79-11  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/02 1p

--7907270378 Submits addl info re IE Insp Rept 50-369/79-22 & 50-370/79-11 Repair & reassembly will be performed by maint personnel & will be inspected by both QA dept & vendor representative  
PARKER, W O Duke Power Co 79/06/19 2pp

--7907270380 Forwards revised pages to Insp Repts 50-369/79-32 & 50-370/79-11  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/04 4pp

--7907270383 Forwards IE Insp Repts 50-369/79-22 & 50-370/79-11 on 790802-04  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

--7907270387 IE Insp Repts 50-369/79-22 & 50-370/79-11 on 790502-04 No noncompliance noted  
HERDT, A R, HUNT, M D Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 4pp

7907310234 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310369 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

8. Reportable occurrences, LERs & related correspondence

7907090342 Forwards Deficiency Repts 369/79-03 & 370/79-04  
PARKER, W O Duke Power Co 79/06/22 1p

--7907090353 Deficiency Rept: present rod controller is less conservative than assumed in safety analysis & could lead to DNB reduction below min design value. Revised setpoint will be included in Tech Specs  
\* Duke Power Co 79/06/22 1p.

V. Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present.  
AHRENDT, B, Jefferson Pilot Broadcasting. 79/06/20 2pp.

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420. Forwards documents listed on App A.  
FELTON, J M Division of Rules and Records 79/07/18 3pp

## DOCKETED ITEMS

DOCKET 50-370 WILLIAM D. MCGUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7907260120 Summary of 790608 meeting w/Util in Bethesda, MD re draft radiological effluent Tech Specs & Offsite Dose Calculation Manual  
BDEGLI, J S Effluent Treatment Systems Branch 79/06/18 5pp

7907250377 Informs of change in projected fuel load dates to May 1980 for Unit 1 & Jan 1982 for Unit 2 & change in commercial operation dates to Aug 1980 for Unit 1 & Apr 1982 for Unit 2 Formal request to follow  
PARKER, W D Duke Power Co 79/07/20 1p

G Adjudicatory correspondence

7907110572 Forwards new info re analysis of sabotage & possible consequences, potentially relevant to McGuire proceedings w/o encl Certificate of Svc encl  
CARTER, T F Division of Safeguards 79/01/22 3pp

7907170247 Confirms 790522 conversation re info requested in 790503 ltr on status of proposed amend to Byproduct/Matl License SNM-1773 issued to Duke Power Co Hearings scheduled for 790619-19 in Charlotte, NC  
KETCHEN, E G Branch 4 79/05/23 1p

K Utility Final Safety Analysis Report (FSAR) & amends

7907120559 Forwards Amend 61 to application for OL, consisting of Revision 37 to FSAR  
PARKER, W D Duke Power Co 79/07/09 2pp

--7907120562 Revision 37 to FSAR w/34 oversized drawings  
\* Duke Power Co 79/07/06 144pp

O Inspection reports, IE Bulletins & correspondence

7907020417 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110319 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907110091 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp

7907030093 Forwards IE Info Notice 79-12, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/29 2pp

7907090382 Requests extension of time for responding to IE Bulletins 78-12, 12A & 12B  
PARKER, W D Duke Power Co. 79/05/29 1p

7907190565 Responds to IE Bulletin 79-04 Review of sys revealed no swing check valves mfg by Velan Engineering Corp in use  
PARKER, W D Duke Power Co 79/05/29 1p

7907190750 Responds to IE Bulletin 79-07 re use of particular computer codes PISOL & SUPERPIPE used on all piping analyses, except analyses performed by Westinghouse  
PARKER, W D Duke Power Co 79/05/29 2pp

7907200186 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907200153 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of less IE Equipment (Deficiencies in Environ Qualification of 300 Solenoid Valves)." Action required  
REILLY, J P Region 2, Atlanta, Office of the Director, 79/06/06 2pp

100161 Forwards IE Info Notice 79-15  
REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020205 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907020382 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120061 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907310009 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 2pp

7907110263 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907180303 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180597 Forwards IE Circular 79-12, "Potential Diesel Generator Turbcharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907270375 Ack receipt of 790619 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/79-22 & 50-370/79-11  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/07/02 1p

--7907270378 Submits addl info re IE Insp Rept 50-369/79-22 & 50-370/79-11 Repair & reassembly will be performed by maint personnel & will be inspected by both QA dept & vendor representative  
PARKER, W D Duke Power Co 79/06/19 2pp

--7907270380 Forwards revised pages to Insp Repts 50-369/79-32 & 50-370/79-11  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/06/04 4pp

--7907270383 Forwards IE Insp Repts 50-369/79-22 & 50-370/79-11 on 790502-04  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

--7907270387 IE Insp Repts 50-369/79-22 & 50-370/79-11 on 790502-04 No noncompliance noted  
HERDT, A R, HUNT, M D Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 4pp

7907310234 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp

7907310369 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 1p

B Reportable occurrences, LERs & related correspondence

7907090342 Forwards Deficiency Repts 369/79-03 & 370/79-04.  
PARKER, W D Duke Power Co. 79/06/22 1p

--7907090353 Deficiency Rept present rod controller is less conservative than assumed in safety analysis & could lead to DNB reduction below min design value Revised setpoint will be included in Tech Specs  
\* Duke Power Co 79/06/22 1p

V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present  
AHRENDT, B. Jefferson Pilot Broadcasting 79/06/20 2pp.

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp

#### DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907160109 Draft memo re licensing strategy for plants w/fuel load dates in CY79  
BOYD, R B Division of Project Management 79/03/28 6pp

7907130018 Notification of 790615 meeting w/Mark II owners & GE in Bethesda, MD re closure of Mark II lead plant program  
ANDERSON, C J Assistant Director for Reactor Safety 79/06/05 6pp

7907180415 Notification of postponement of 790615 meeting w/Mark II owners & GE to discuss closure of Mark II lead plant program Meeting will be rescheduled  
ANDERSON, C J Containment Systems Branch 79/06/05 2pp

7907090231 Notification of 790724-25 meeting w/representatives from lead Mark II plants to discuss long-term program  
ANDERSON, C J Containment Systems Branch 79/06/11 2pp

7907250063 Notification of 790726 meeting w/GE, C Economus & Mark II owners in Bethesda, MD to discuss closure of Mark II lead plant program  
ANDERSON, C J Containment Systems Branch 79/06/25 6pp

7907050229 Forwards seismic response spectra for LaSalle County auxiliary bldg. in response to NRC request  
DELGEORGE, L O Commonwealth Edison Co 79/06/28 23pp

7907300171 Notification of 790717-18 meeting w/Mark II owners group & GE in Lebanon, NH to discuss Mark II pool dynamic programs  
ANDERSON, C J Containment Systems Branch 79/07/03 12pp

7907240230 Submits schedule for responses to various branch questions, in response to OD Parr 790621 request for addl info  
DELGEORGE, L O Commonwealth Edison Co 79/07/17 2pp

##### E NRC Safety Evaluation Report (SER), suppl & correspondence

7907240434 Summary of 790511 & 24 meetings w/util re outstanding issues in draft SER  
BOURNIA, A Light Water Reactors Branch 3 79/06/14 19pp

##### Q Inspection reports, IE Bulletins & correspondence

7907300038 Forwards IE Insp Repts 50-373/79-13 & 50-374/79-10 on 790322-23 & 0403-06 & notice of violation  
FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/01 2pp

--7907300041 Notice of violation from insp on 790322-23 & 0403-06  
\* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/26 3pp

--7907300046 IE Insp Repts 50-373/79-13 & 50-374/79-10 on 790322-23 & 0403-06 Noncompliance noted post-accident monitoring, electrical terminations & heating, ventilation & air conditioning component design  
HAYES, D W, NAIDU, K R, HUGHES, J Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/26 19pp

7907060031 Responds to IE Bulletin 77-07 Safety-related penetrations for Unit 1 do not use epoxy seal described Safety-related penetrations for Unit 2 are mfg by Amphenol Sams Div of Bunker Ramo Corp & does use epoxy seal described  
DELGEORGE, L O Commonwealth Edison Co 79/05/23 3pp

7907200287 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/31 1p

7907240124 Forwards IE Insp Rept 50-373/79-15 on 790402-03 & 18-20 No noncompliance noted  
HEISMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/06/01 2pp

--7907240127 IE Insp Rept 50-373/79-15 on 790402-03 & 18-20 No noncompliance noted Major areas inspected responses to IE bulletins, operating procedures, IE headquarters requests & Tech Spec evaluation  
WALKER, R D, WRIGHT, G C, SPESBARD, R L Region 3, Chicago, Office of the Director 79/05/30 6pp

7907250290 Forwards IE Insp Repts 50-373/79-18 & 50-374/79-12 on 790515-16 No noncompliance noted  
FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/05 2pp

--7907250301 IE Insp Repts 50-373/79-18 & 50-374/79-12 on 790515-16 No noncompliance noted Major areas inspected work activities & QA records relative to suppression pool mods & records relative to reactor recirculation sys  
NEISLER, J H, KNOPF, R C Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/31 4pp

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020237 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/11 1p

7907190010 Responds to IE Bulletin 79-09 OE Type AK-2 circuit breakers are not used at LaSalle, but are used at Byron & Braidwood as main supply air operated circuit breakers  
REED, C Commonwealth Edison Co 79/06/18 3pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/21 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bypass Piping " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/25 1p

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/26 1p

7907050466 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/27 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/28 1p

7907240064 Ack receipt of 790601 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/79-13 & 50-374/79-10  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/29 3pp

--7907240078 Responds to NRC 790501 ltr re violations noted in IE Insp Repts 50-373/79-13 & 50-374/79-10 Corrective actions nonconformance rept written to identify where cadmium-plated bolts were used as fastening matl  
REED, C Commonwealth Edison Co 79/06/01 8pp

## DOCKETED ITEMS

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/07/02 1p

7907300077 Ack receipt of 790618 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/79-17 & 50-374/79-11  
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/10 1p

--7907300089 Responds to NRC 790518 ltr re violations noted in IE Insp Repts 50-373/79-17 & 50-374/79-11 Corrective actions grout has been analyzed & casing filler will be sampled from storage tanks.  
REED, C. Commonwealth Edison Co 79/06/18 6pp

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director. 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Rotated Water Sys at PWR Plants " No action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/07/18 1p

7907290217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director. 79/07/20 1p

#### B Reportable occurrences, LERs & related correspondence

7907110716 Ack receipt of 790521 final rept re conduit supports Review will be completed during future insp  
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/09/31. 1p

#### DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

#### A Application/construction stage documents & correspondence

7907130018 Notification of 790615 meeting w/Mark II owners & GE in Bethesda, MD re closure of Mark II lead plant program  
ANDERSON, C J. Assistant Director for Reactor Safety 79/06/05 6pp

7907180415 Notification of postponement of 790615 meeting w/Mark II owners & GE to discuss closure of Mark II lead plant program Meeting will be rescheduled  
ANDERSON, C J. Containment Systems Branch 79/06/05 2pp

7907090251 Notification of 790724-25 meeting w/representatives from lead Mark II plants to discuss long-term program  
ANDERSON, C J. Containment Systems Branch 79/06/11 2pp

7907230063 Notification of 790726 meeting w/GE, C Economus & Mark II owners in Bethesda, MD to discuss closure of Mark II lead plant program.  
ANDERSON, C J. Containment Systems Branch 79/06/25 6pp

7907050229 Forwards seismic response spectra for LaSalle County auxiliary bldg, in response to NRC request.  
DELEGORGE, L. O. Commonwealth Edison Co 79/06/28. 23pp.

7907300171 Notification of 790717-18 meeting w/Mark II owners group & GE in Lebanon, NH to discuss Mark II pool dynamic programs  
ANDERSON, C J. Containment Systems Branch. 79/07/03 12pp

7907240230 Submits schedule for responses to various branch questions, in response to OD Parr 790621 request for addl info  
DELEGORGE, L. O. Commonwealth Edison Co. 79/07/17. 2pp.

E NRC Safety Evaluation Report (SER), suppl & correspondence

7907240434 Summary of 790511 & 24 meetings w/util re outstanding issues in draft SER  
BOURNIA, A. Light Water Reactors Branch 3 79/06/14 19pp

#### G Inspection reports, IE Bulletins & correspondence

7907300038 Forwards IE Insp Repts 50-373/79-13 & 50-374/79-10 on 790322-23 & 0403-06 & notice of violation  
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/01 2pp

--7907300041 Notice of violation from insp on 790322-23 & 0403-06  
\* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/26 3pp

--7907300046 IE Insp Repts 50-373/79-13 & 50-374/79-10 on 790322-23 & 0403-06 Noncompliance noted post-accident monitoring, electrical terminations & heating, ventilation & air conditioning component design  
HAYES, D W., NAIDU, K R., HUOHEB, J. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/26 19pp

7907060031 Responds to IE Bulletin 77-07 Safety-related penetrations for Unit 1 do not use epoxy seal described Safety-related penetrations for Unit 2 are n/a by Amphenol Bams Div of Bunker Ramo Corp & does use epoxy seal described  
DELEGORGE, L. O. Commonwealth Edison Co 79/05/23 3pp

7907200287 Forwards IE Bulletin 79-12, "Short Period Scrams at BHR Facilities " No action required  
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/05/31 1p.

7907250290 Forwards IE Insp Repts 50-373/79-18 & 50-374/79-12 on 790515-16 No noncompliance noted  
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/05 2pp

--7907250301 IE Insp Repts 50-373/79-18 & 50-374/79-12 on 790515-16 No noncompliance noted Major areas inspected work activities & QA records relative to suppression pool mods & records relative to reactor recirculation sys  
NEIBLER, J. H., KNOPF, R. C. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/31 4pp

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/06/07. 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H. Region 3, Chicago, Office of the Director 79/06/08 2pp.

7907020237 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/11 1p

7907190010 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers are not used at LaSalle, but are used at Byron & Braidwood as main supply air operated circuit breakers  
REED, C. Commonwealth Edison Co 79/06/18 3pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/21 1p.

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G. Region 3, Chicago, Office of the Director. 79/06/23 1p

# DOCKETED ITEMS

7907240303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/26 1p

7907240464 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/27 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/28 1p

7907240064 Ack receipt of 790601 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/79-13 & 50-374/79-10  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/29 3pp

--7907240078 Responds to NRC 790501 ltr re violations noted in IE Insp Repts 50-373/79-13 & 50-374/79-10 Corrective actions nonconformance rept written to identify where cadmium-plated bolts were used as fastening matl  
REED, C Commonwealth Edison Co 79/06/01 8pp

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/02 1p

7907300077 Ack receipt of 790618 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/79-17 & 50-374/79-11  
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/10 1p

--7907300089 Responds to NRC 790518 ltr re violations noted in IE Insp Repts 50-373/79-17 & 50-374/79-11 Corrective actions grout has been analyzed & casing filler will be sampled from storage tanks  
REED, C Commonwealth Edison Co 79/06/18 6pp

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/13 1p

7907240153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/18 1p

7907240336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required.  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/18 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/07/20, 1p.

## B Reportable occurrences, LERs & related correspondence

7907110716 Ack receipt of 790521 final rept re conduit supports. Review will be completed during future insp  
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch, 79/05/31 1p

## DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

### J Insurance & indemnity information

7907120399 Forwards executed copy of Amend 15 to Indemnity Agreement B-13  
WHEELER, L W Rockwell International Corp, 79/06/27 2pp.

### G Inspection reports, IE Bulletins & correspondence

7907230754 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/07/06, 1p

## DOCKET 50-376 NORTH COAST NUC PLANT

### G Adjudicatory correspondence

7907050204 Forwards SER for facility w/o encl  
MCGURREN, H J Branch 1, 79/03/09 1p

## DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

### A Application/construction stage documents & correspondence

7907240420 Summary of 790523 meeting w/util & Ebasco at facility re hydrology of site & environ  
BENEDICT, R A Light Water Reactors Branch 2 79/06/08 3pp

7907230487 Notification of 790716 meeting w/util in Bethesda, MD to discuss site selection process  
COTA, P C Environmental Projects Branch 1 79/07/02 2pp

7907200249 Summarizes util evaluation of effect of TH1 incident reviewed all correspondence, evaluated sequence of events to compare designs of TH1 & Waterford & participated in C-E in C-E meetings & in post-event evaluation program  
ABWELL, D L Louisiana Power & Light Co 79/07/17, 3pp

### F Security, medical, emergency & fire protection plans

7907240214 Forwards responses to questions & comments re physical security plan & changes to plan Withheld (ref 10CFR2 790)  
ABWELL, D L Louisiana Power & Light Co 79/07/19 1p

### G Adjudicatory correspondence

7907050476 Forwards DO Eisenhower 790302 ltr to DL Aswell & NUREO-0523, "Summary of Operating Experience W/Recirculating Steam Generators "  
MCGURREN, H J Branch 1 79/03/10 1p

7907250026 Advises of motion passed re const &/or operation of nuclear plant in Taft, LA Affidavit encl  
BECNEL, R M St John the Baptist Parish Police Jury 79/05/14 1p

7907180206 Notifies that NRC has investigated defects in concrete work as requested at 790426 special prehearing conference  
Concerns expressed in 790404 New Orleans States Item newspaper article have no basis  
MCGURREN, H J Branch 1 79/03/30 1p

--7907180226 Notifies of discussion w/reporter J Amuss of New Orleans States Item newspaper re article on concrete work Matter should not be pursued any further.  
HALL, R, E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/04 2pp

7907060523 Responds to Save Our Wetlands, Inc & Oyster Shell Alliance, Inc 790411 contentions & to 790426 special prehearing conference agreement Util submits position on disputed contentions Certificate of Svc encl  
YOUNGBRIDGE, O F, YUBEN, A. R Shaw, Pittman, Potts, & Trowbridge 79/06/01 13pp

7907130114 Motion to dispense w/10CFR2 70B(d) filing requirements, submitted by Save Our Wetlands Inc & Oystershell Alliance Inc Providing large number of copies is financial burden  
Certificate of Svc encl  
JONES, L. L. Gillespie & Jones 79/06/01, 5pp

7907130195 Request for adoption of unstipulated Contentions B-14 & 22 submitted by Save Our Wetlands & Oystershell Alliance, Inc Contentions include effects of radiation emissions & health & environ effects of plant Certificate of Svc encl  
JONES, L. L. Gillespie & Jones, 79/06/01 25pp

7907180579 No objection to Oystershell Alliance, Inc & Save Our Wetlands, Inc 790601 request for exemption from requirement of filing 20 copies of each document, per 10CFR2.70B(d), Certificate of Svc encl.  
MCGURREN, H J Branch 1, 79/06/21, 2pp

### H. General correspondence

7907060012 Submits text to LA congressional delegation urging opposition to delay in issuance of DL.  
WYATT, J. M. Louisiana Power & Light Co 79/05/25, 2pp

## DOCKETED ITEMS

## K Utility Final Safety Analysis Report (FSAR) &amp; amends

7907240346 Forwards Amend 5 to FSAR  
ASWELL,D L Louisiana Power & Light Co 79/07/19 2pp

--7907240349 Amend 5 to FSAR  
ASWELL,D L Louisiana Power & Light Co 79/07/19 487pp

7907260011 Forwards drawings & documentation for Amend 5 review,  
including revised electrical drawings for FSAR, geological  
mapping rept & addl FSAR info w/o encl  
PRADOS,R Ebasco Services, Inc (subs of Enserch Corp) 79/07/23  
1p

7907300347 Certificate of Svc for Amend 5 to FSAR  
\* Louisiana Power & Light Co 79/07/24 1p

## 0 Inspection reports, IE Bulletins &amp; correspondence

7907110414 Forwards IE Insp Rept 50-382/79-05 on 790430 & 0501-03 No  
noncompliance noted  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/05/11 2pp

--7907110418 IE Insp Rept 50-382/79-05 on 790430 & 0501-03 No  
noncompliance noted Major areas inspected followup review  
of previous noncompliance re const activity & review of  
records & observations of maint activities  
MARTIN,L E, CROSSMAN,W A, HALL,R E Region 4, Dallas, Reactor  
Construction & Engineering Support Branch 79/05/11 6pp

7907110470 Forwards util 790504 response to IE Bulletin 79-03 re ASME  
SA-312 Type 304 piping  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/05/21 1p

--7907110477 Responds to IE Bulletin 79-03 ASME SA-312 Type 304 pipe  
not in use or planned for use  
ASWELL,D L Louisiana Power & Light Co 79/05/04 1p

7907260043 Responds to IE Bulletins 78-12,12A & 12B Licensee awaiting  
results of C-E records search prior to submitting final  
response  
ASWELL,D L Louisiana Power & Light Co 79/05/24 1p

7907260070 Responds to IE Bulletin 79-04 No Velan check valves larger  
than two inches in use at Facility  
ASWELL,D L Louisiana Power & Light Co 79/05/28 1p

907030126 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Dyster Creek Reactor " No action required.  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/29  
1p

7907200357 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director. 79/05/31  
1p

7907190400 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ABCO Solenoid Valves)." No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/06  
1p

07060017 Forwards IE Info Notice 79-15, "Deficient Procedures." No  
action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director. 79/06/07  
1p

7907240051 Ack receipt of 790515 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Rept 50-382/79-04  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/08 1p

7907240118 Responds to NRC ltr re violations noted in IE Insp Rept  
50-382/79-04 Corrective actions GA stop work order issued  
790409 ensuring immediate removal of scaffolding matls.  
ASWELL,D L Louisiana Power & Light Co 79/05/15 3pp.

7907050565 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys " No action required  
SEYFRIT,K V. Region 4, Dallas, Office of the Director 79/06/11  
1p

7907050514 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/20  
1p

7907050488 Forwards IE Bulletin 79-02,Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/21  
1p

7907120602 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/25  
1p

7907110252 Forwards IE Circular 79-10, "Pipe Fittings Mfg from  
Unacceptable Matl " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/26  
1p.

7907180262 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/27  
1p

7907100518 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/28  
1p

7907110296 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
SEYFRIT,K V. Region 4, Dallas, Office of the Director 79/07/02  
1p

7907190500 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/11  
1p

7907240312 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/13  
1p

7907270397 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/07/18  
1p

## 8 Reportable occurrences, LERs &amp; related correspondence

7907030267 Forwards PNO-79-67AG, "Nuclear Incident at TMI "  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/05/31 1p

7907020307 Forwards PNO-79-67AR  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/05 1p

7907050574 Forwards PNO-79-67AG, "Nuclear Incident at TMI "  
SEIDLE,W C Region 4, Dallas, Office of the Director 79/06/13  
1p

7907030212 Forwards PNO-79-67AT  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch. 79/06/19 1p

7907130340 Forwards PNO-79-67AU  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/27 1p

7907090227 Summarizes current status of corrective actions taken re  
matl failures of 4-inch 45-degree & 4-inch 90-degree ells  
Six ells on hold in warehouse awaiting return to vendor.  
Site Nonconformance Rept W3-1354 issued  
ASWELL,D L Louisiana Power & Light Co 79/06/29 2pp

7907180689 Forwards PNO-79-67AV  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/07/06 1p

7907260621 Confirms 790624 telcon. Util continues to evaluate  
reportability of problem w/Rosemount 1153 Series A pressure  
transmitters Rept will be completed by 790731  
ASWELL,D L. Louisiana Power & Light Co 79/07/06 1p

7907240519 Forwards PNG-79-47AW  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/07/13 1p

# U Congressional/Executive Correspondence

7907310122 Responds to 790605 ltr re delays in processing & issuance of  
OL for facilities As result of TMI accident, NRC resources  
have been diverted from previous work OL reviews suspended,  
since subj facilities do not qualify for priority treatment  
GOSSICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310136 Urges consideration of socio-economic impact of moratorium  
on issuance of OLs for facilities  
LIVINOSTON, R L House of Rep 79/05/29 1p

7907310202 Responds to 790605 ltr re delays in processing & issuance of  
OL for facilities As result of TMI accident, NRC resources  
have been diverted from previous work OL reviews suspended,  
since subj facilities do not qualify for priority treatment  
GOSSICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310211 Forwards D Lutken, of MI Power & Light Co, 790524 telegram re  
impact of delay & subsequent issuance of OL for facilities &  
statement outlining safety of proposed plant Requests  
comments & info on subj  
GOCHRAN, T B Senate 79/06/05 7pp

7907310244 Responds to 790606 ltr re delays in processing & issuance of  
OL for facilities As result of TMI accident, NRC resources  
have been diverted from previous work OL reviews suspended,  
since subj facilities do not qualify for priority treatment  
GOSSICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310253 Forwards JM Wyatt, of LA Power & Light Co, 790525 ltr re  
impact of delay & subsequent issuance of OL for facilities  
Requests comments & info on subj  
BREAUX, J House of Rep 79/06/06 3pp

# DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

## A Application/construction stage documents & correspondence

7907090055 Requests consultation w/DOI re possible endangered species  
near reservoir to be operated in conjunction w/proposed  
facility Drawing encl  
REGAN, W H Environmental Projects Branch 2 79/05/23 2pp

7907190799 Requests addl mechanical engineering info re mathematical  
basis for seismic design methods & procedures for combining  
modal responses  
PARR, D D Light Water Reactors Branch 3 79/06/06 3pp

7907110704 Forwards Round 2 questions re QA operations  
PARR, D D Light Water Reactors Branch 3 79/06/11 2pp

--7907110711 Round 2 questions re QA operations  
\* Light Water Reactors Branch 3 79/06/11 4pp

7907300504 Responds to 790606 correspondence re NRC response to first  
round discovery requests for proceeding Requests that Board  
grant NRC relief from current schedule P Leach to complete  
questions by Sept w/draft environ statement questions  
SELLS, D E Environmental Projects Branch 2 79/06/13 1p

7907310483 Approves request for withholding from public disclosure two  
figures re fuel enrichment & gadolinia distribution within  
fuel assemblies  
PARR, D D Light Water Reactors Branch 3 79/06/19 3pp

7907300171 Notification of 790717-18 meeting w/Mark II owners group &  
QE in Lebanon, NH to discuss Mark II Pool Dynamic Programs  
ANDERSON, C J Containment Systems Branch 79/07/03 12pp.

7907250097 Notification of 790716 meeting w/Mark II owners & QE re  
WPP8-2 chugging improvement program & Susquehanna test  
programs  
ANDERSON, C J Containment Systems Branch 79/07/05 3pp

7907170045 Forwards in-depth archaeological survey of transmission  
corridor  
CURTIS, N W Pennsylvania Power & Light Co 79/07/11 1p.

--7907170051 "Knouse Site, Historical Site in Luzerne County, PA"  
Prepared by Dayton Museum of Natural History  
\* Pennsylvania Power & Light Co 79/03/31 134pp

7907180478 Provides requested info re federally-proposed or listed  
endangered species in PA  
LARGEN, H N Interior, Dept of, Fish & Wildlife Service 79/07/11  
3pp

7907260457 Forwards Affidavit of Svc for Amend 13 to DL application  
CURTIS, N W Pennsylvania Power & Light Co 79/07/20 2pp

## D NRC Draft/Final Environmental Statements, supp's & correspondence

7907200242 Notice of availability of DES & environ rept  
SELLS, D E Environmental Projects Branch 2 79/05/27 2pp

## G Adjudicatory correspondence

7907260761 Forwards J Perkins 790424 request for responses to questions  
posed at 790130 prehearing conference  
BECHHOEFER, C Atomic Safety and Licensing Board Panel 79/09/02  
1p

--7907260859 Requests responses to question posed at 790130  
prehearing conference  
PERKINS, J Affiliation Unknown 79/04/24 1p

7907080186 Responds to 790418 ltr expressing concern re nuclear safety  
Forwards info summary re nuclear siting W/o encl  
SNYDER, G L Region 1, Philadelphia, Office of the Director  
79/05/15 1p

--7907080425 Expresses concern re nuclear safety, Forwards paid public  
announcement from 790417 Berwick Enterprise  
SHRADER, D Affiliation Unknown 79/04/18 4pp

7907130501 Explains NRC process for handling questions raised by  
individuals making limited appearance statements  
CUTCHIN, J M Branch 3 79/05/17 2pp

7907240298 Forwards request for documents per ASLB 790306 order Items  
1-18 are directed to util Items 19-22 are directed to PA  
Bureau of Radiological Health, Dept of Environ Resources  
LEMANOWICZ, T Citizens Against Nuclear Dangers 79/05/22 1p

--7907240303 Document requests submitted per ASLB 790306 order Items 1-18  
are directed to util Items 19-22 are directed to PA Bureau  
of Radiological Health, Dept of Environ Resources  
\* Citizens Against Nuclear Dangers 79/05/22 6pp

7907090393 First set of interrogatories & document requests submitted  
by util to intervenor Susquehanna Environ Advocates  
Interrogatories covering all contentions served on each  
intervenor  
BILBERG, J E, YUSPEH, A R Shaw, Pittman, Potts, & Troubridge  
79/05/25 28pp

7907060452 First round document request submitted by Environ Coalition  
on Nuclear Power to NRC, util & Commonwealth of PA Requests  
info re contentions of intervenors Certificate of Svc encl  
JOHNSRUD, J, KEPPORD, C Environmental Coalition on Nuclear Power  
79/05/28 8pp

7907130157 Opposition by util to Citizens Against Nuclear Dangers  
790512 request that ASLB restrain util from obtaining govt  
permits Completion of administrative procedures before state  
agencies does not prejudice intervenors  
BILBERG, J E, YUSPEH, A R Shaw, Pittman, Potts, & Troubridge  
79/06/04 3pp

7907060487 Notice of deposition of MK Cressy on 790711 in Wilkes-Barre,  
PA re allegations made at 790129-31 prehearing conference  
Certificate of Svc encl  
CUTCHIN, J M Branch 3 79/06/11 3pp

7907180664 Responds to NRC interrogatories & document request Citizens  
Against Nuclear Dangers categorically objects to each  
question Independent re-evaluation of application is  
necessary Certificate of Svc encl  
LEMANOWICZ, I. Citizens Against Nuclear Dangers 79/06/16 7pp

7907180596 Order requesting submission of contentions by 790709 re NRC  
790612 interim final rule on protection of spent fuel in  
transit, Contentions previously rejected may now be  
submitted  
BECHHOEFER, C Atomic Safety and Licensing Board Panel 79/06/18  
2pp

## DOCKETED ITEMS

7907240335 Request on behalf of util that ASLB compel Citizens Against Nuclear Dangers respond to util 790525 interrogatories & document request Intervenor 790416 objections are unsupportable Certificate of Svc encl  
SILBERG, J E, YUSPEH, A R Shaw, Pittman, Potts, & Trowbridge  
79/06/27, 7pp

# K Utility Final Safety Analysis Report (FSAR) & amends

7907030349 Forwards Amend 13 to DL application, consisting of Revision 10  
CURTIS, N W Pennsylvania Power & Light Co 79/06/29 2pp

--7907030353 FSAR Revision 10  
CURTIS, N W Pennsylvania Power & Light Co 79/06/25 152pp

# Q Inspection reports, IE Bulletins & correspondence

7907130226 Forwards IE Insp Rept 50-387/79-13 on 790313-16 No noncompliance noted  
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/16 2pp

--7907130238 IE Insp Rept 50-387/79-13 on 790313-16 No noncompliance noted Major areas inspected procedures documenting QA program to be implemented during pre-operational testing  
MARKOWSKI, R S, MAPUDA, O, KISTER, H B Region 1, Philadelphia, Office of the Director 79/04/12, 8pp

7907060423 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907030059 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200139 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

79050254 Responds to IE Bulletin 79-07 re computer codes used in seismic stress analysis in safety-related piping Lists computer codes in use & codes which are verified  
CURTIS, N W Pennsylvania Power & Light Co 79/06/01 2pp.

79050653 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-01 & 50-388/79-01  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/05 1p

--7907110672 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-387/79-01 & 50-388/79-01 Corrective actions, field procedures revised  
SABOL, A R Pennsylvania Power & Light Co. 79/05/23, 3pp

--7907110680 Forwards IE Insp Repts 50-387/79-01 & 50-388/79-01 on 790306-08 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/14 2pp

7907110689 Notice of violation from insp on 790306-08  
\* Region 1, Philadelphia, Office of the Director. 79/03/09 1p

7907110696 IE Insp Repts 50-387/79-01 & 50-388/79-01 on 790306-08 Noncompliance noted: Failure to remove arc strike per established procedures  
GALLO, R M Region 1, Philadelphia, Office of the Director  
MCQUAHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/09 12pp

79090099 Forwards suppl IE Bulletin 79-01A, "Environment Qualification of Class IE Equipment (Deficiencies in Environment Qualification of ASCO Solenoid Valves)." Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/06/06 1p

7907060123 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/06/07, 1p.

7907020051 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907260087 Responds to IE Bulletin 79-03 One ASME-SA-312 Type 304 fusion-welded pipe spool installed in Class I sys Completion of radiography of exposed position expected by 790716  
CURTIS, N W Pennsylvania Power & Light Co 79/06/12 2pp

7907260192 Responds to IE Bulletin 79-09 GE Type AK-2 breakers utilized but w/o undervoltage trip device New measures will be incorporated into preventive maint program to be implemented prior to fuel load  
CURTIS, N W Pennsylvania Power & Light Co 79/06/12 1p

7907260156 Responds to IE Bulletin 79-04 No Velan swing check valves installed at facility  
CURTIS, N W Pennsylvania Power & Light Co 79/06/13 1p

7907190006 Ack receipt of 790604 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-14 & 50-388/79-08  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/14 1p

--7907190011 Responds to NRC 790426 ltr re violations noted in IE Insp Repts 50-387/79-14 & 50-388/79-08 Corrective actions welding procedure revised to include supplementary essential variable GW-410-24  
SABOL, A R Pennsylvania Power & Light Co 79/06/04 4pp

--7907190016 Forwards IE Insp Repts 50-387/79-14 & 50-388/79-08 on 790319-23 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/26 2pp.

--7907190019 Notice of violation from insp on 790319-23  
\* Region 1, Philadelphia, Office of the Director 79/04/19 2pp

--7907190029 IE Insp Repts 50-387/79-14 & 50-388/79-08 on 790319-23, Noncompliance noted: Failure to specify supplementary essential variables in welding procedure specs & failure to assure piping cleanliness before closure  
DURR, J P, FINKEL, A E Region 1, Philadelphia, Office of the Director  
TRIPP, L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/19 7pp

7907230558 Ack receipt of 790516 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-387/79-11 & 50-388/79-07  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/14 1p

--7907230572 Responds to NRC 790417 ltr re violation noted in IE Insp Repts 50-387/79-11 & 50-388/79-07 Corrective actions, new terminations properly installed Memo issued to insure wire brushing of connectors  
SABOL, A R Pennsylvania Power & Light Co 79/05/16 2pp

--7907230579 Forwards IE Insp Repts 50-387/79-11 & 50-388/79-07 on 790306-08 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/17, 2pp

--7907230585 Notice of violation from insp on 790306-08  
\* Region 1, Philadelphia, Office of the Director. 79/04/06 1p

--7907230598 IE Insp Repts 50-387/79-11 & 50-388/79-07 on 790306-08 Noncompliance noted: Failure to properly prepare electrical cable termination prior to installation.  
FINKEL, A E Region 1, Philadelphia, Office of the Director  
EBNETER, B D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/06, 8pp.

7907200477 Ack receipt of 790611 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-387/79-10 & 50-388/79-06  
CARLSON, R T Region 1, Philadelphia, Office of the Director 79/06/18, 1p.

--7907200484 Responds to NRC 790510 Ltr re violation noted in IE Insp Repts 50-387/79-10 & 50-388/79-06, Corrective actions, noncompliance repts processed per procedural requirements of Field Insp Procedure 0-3  
SABOL, A R Pennsylvania Power & Light Co. 79/06/11, 3pp.



--7907200491 Forwards IE Insp Rept 50-387/79-10 & 50-388/79-06 on 790305-30 & notice of violation  
CARLBON, R T Region 1, Philadelphia, Office of the Director  
79/05/10 2pp

--7907200496 Notice of violation from insp on 790305-30  
\* Region 1, Philadelphia, Office of the Director 79/05/05  
1p

--7907200503 IE Insp Rept 50-387/79-10 & 50-388/79-06 on 790305-30  
Noncompliance noted failure to follow documented procedures  
for control of nonconfirming items  
GALLO, R M Region 1, Philadelphia, Office of the Director  
MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction &  
Engineering Support Branch 79/05/05 10pp

7907110386 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/20 1p

7907230697 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/21 1p

7907120528 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/25 1p

7907230003 Forwards IE Insp Rept 50-387/79-12 on 790313 No  
noncompliance noted  
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials  
Safety Branch 79/06/25 2pp

--7907230006 IE Insp Rept 50-387/79-12 on 790313 No noncompliance noted  
Major areas inspected routine meeting held w/portion of  
license & mgt associated w/implementation of licensee  
emergency planning provisions  
SDTR, J. P., SMITH, G H Region 1, Philadelphia, Fuel Facility &  
Materials Safety Branch TERC, N Region 1, Philadelphia, Office  
of the Director 79/06/22 2pp

7907100361 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/26 1p

7907100426 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/27, 1p.

7907100033 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/28 1p.

7907180805 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/07/02 1p.

7907270359 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director.  
79/07/11, 1p.

7907310532 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors, " No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director.  
79/07/16, 1p.

#### B. Reportable occurrences, LERs & related correspondence

7907030327 Notifies that Region 1 granted extension until 790815 for  
submittal of final rept re deficiency in solenoid valves in  
response to util 790522 request  
CURTIS, N W. Pennsylvania Power & Light Co 79/06/28, 2pp.

7907260631 Confirms 790614 verbal rept re damage sustained by  
safety-related cables during cable pulling activities.  
Problem deemed reportable. Util final rept will be submitted  
by 791201  
CURTIS, N W Pennsylvania Power & Light Co 79/07/17, 2pp.

7907270258 Updates 780623 deficiency rept re unsatisfactory field  
welding & insp of shear studs Required shear stud repairs  
completed  
CURTIS, N W Pennsylvania Power & Light Co 79/07/23 1p

#### DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

##### A Application/construction stage documents & correspondence

7907050055 Requests consultation w/DDI re possible endangered species  
near reservoir to be operated in conjunction w/proposed  
facility Drawing encl  
REGAN, W H Environmental Projects Branch 2 79/05/23 2pp

7907190799 Requests addl mechanical engineering info re mathematical  
basis for seismic design methods & procedures for combining  
modal responses  
PARR, O D Light Water Reactors Branch 3 79/06/06 3pp

7907110704 Forwards Round 2 questions re GA operations  
PARR, O D Light Water Reactors Branch 3 79/06/11 2pp.

--7907110711 Round 2 questions re GA operations  
\* Light Water Reactors Branch 3 79/06/11 4pp

7907300504 Responds to 790606 correspondence re NRC response to first  
round discovery requests for proceeding Requests that Board  
grant NRC relief from current schedule P Leach to complete  
questions by Sept w/draft environ statement questions  
BELL, D E Environmental Projects Branch 2 79/06/13 1p

7907310463 Approves request for withholding from public disclosure two  
figures re fuel enrichment & gadolinia distribution within  
fuel assemblies  
PARR, O D Light Water Reactors Branch 3 79/06/19 3pp

7907300171 Notification of 790717-18 meeting w/Mark II owners group &  
OE in Lebanon, NH to discuss Mark II Pool Dynamic Programs  
ANDERSON, C J Containment Systems Branch, 79/07/03 12pp.

7907250097 Notification of 790716 meeting w/Mark II owners & OE re  
WPPS-2 chugging improvement program & Susquehanna test  
programs  
ANDERSON, C J Containment Systems Branch 79/07/05 5pp

7907170045 Forwards in-depth archaeological survey of transmission  
corridor  
CURTIS, N W Pennsylvania Power & Light Co 79/07/11, 1p

--7907170091 "Knouse Site, Historical Site in Luzerne County, PA "  
Prepared by Dayton Museum of Natural History  
\* Pennsylvania Power & Light Co 79/03/31, 134pp

7907180478 Provides requested info re federally-proposed or listed  
endangered species in PA  
LARGEN, H M Interior, Dept of, Fish & Wildlife Service 79/07/11  
3pp

7907260457 Forwards Affidavit of Svc for Amend 13 to GL application  
CURTIS, N W. Pennsylvania Power & Light Co 79/07/20 2pp.

#### D NRC Draft/Final Environmental Statements, supplis & correspondence

7907200242 Notice of availability of DES & environ rept  
BELL, D E. Environmental Projects Branch 2 79/05/27 2pp.

#### G Adjudicatory correspondence

7907260761 Forwards J Perkins 790424 request for responses to questions  
posed at 790130 prehearing conference  
BECHHOEFER, C Atomic Safety and Licensing Board Panel 79/05/02  
1p

--7907260859 Requests responses to question posed at 790130  
prehearing conference  
PERKINS, J Affiliation Unknown 79/04/24 1p

7907050186 Responds to 790418 ltr expressing concern re nuclear safety  
Forwards info summary re nuclear siting, w/o encl  
BNYDER, G. L. Region 1, Philadelphia, Office of the Director.  
79/05/15 1p

--7907050425 Expresses concern re nuclear safety. Forwards paid public  
announcement from 790417 Barwick Enterprise  
BHRADER, D. Affiliation Unknown. 79/04/18 4pp.

## DOCKETED ITEMS

7907130501 Explains NRC process for handling questions raised by individuals making limited appearance statements  
CUTCHIN, J M Branch 3 79/05/17 2pp

7907240298 Forwards request for documents per ASLB 790306 order Items 1-18 are directed to util Items 19-22 are directed to PA Bureau of Radiological Health, Dept of Environ Resources  
LEMANOWICZ, I Citizens Against Nuclear Dangers 79/05/22 1p

--7907240303 Document requests submitted per ASLB 790306 order Items 1-18 are directed to util Items 19-22 are directed to PA Bureau of Radiological Health, Dept of Environ Resources  
\* Citizens Against Nuclear Dangers 79/05/22 6pp

7907090393 First set of interrogatories & document requests submitted by util to intervenor Susquehanna Environ Advocates  
Interrogatories covering all contentions served on each intervenor  
SILBERG, J E, YUSPEH, A R Shaw, Pittman, Potts, & Trowbridge 79/05/29 28pp

7907060452 First round document request submitted by Environ Coalition on Nuclear Power to NRC, util & Commonwealth of PA Requests info re contentions of intervenors Certificate of Svc encl  
JOHNSBRUD, J, KEFFORD, C Environmental Coalition on Nuclear Power 79/06/28 8pp

7907130157 Opposition by util to Citizens Against Nuclear Dangers 790512 request that ASLB restrain util from obtaining govt permits Completion of administrative procedures before state agencies does not prejudice intervenors  
SILBERG, J E, YUSPEH, A R Shaw, Pittman, Potts, & Trowbridge 79/06/04 5pp

7907060487 Notice of deposition of MK Creasy on 790711 in Wilkes-Barre, PA re allegations made at 790129-31 prehearing conference  
Certificate of Svc encl  
CUTCHIN, J M Branch 3 79/06/11 3pp.

7907180664 Responds to NRC interrogatories & document request Citizens Against Nuclear Dangers categorically objects to each question Independent re-evaluation of application is necessary Certificate of Svc encl  
EMANOWICZ, I Citizens Against Nuclear Dangers 79/06/16 7pp

80596 Order requesting submission of contentions by 790709 re NRC 512 interim final rule on protection of spent fuel in sit  
Contentions previously rejected may now be submitted  
HHOEFER, C Atomic Safety and Licensing Board Panel 79/06/18

240335 Request on behalf of util that ASLB compel Citizens Against Nuclear Dangers respond to util 790525 interrogatories & document request Intervenor 790616 objections are unsupported Certificate of Svc encl  
SILBERG, J E, YUSPEH, A R Shaw, Pittman, Potts, & Trowbridge 79/06/27 7pp

K Utility Final Safety Analysis Report (FSAR) & amends

7907030349 Forwards Amend 13 to OL application, consisting of Revision 10  
CURTIS, N W Pennsylvania Power & Light Co 79/06/29 2pp

7907030353 FSAR Revision 10  
CURTIS, N W Pennsylvania Power & Light Co 79/06/25 152pp

Inspection reports, IE Bulletins & correspondence

07060423 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers For Engineered Safety Sys " Licensee action required  
RIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7030039 Forwards IE Info Notice 79-13, "Indication of Low Water level in Oyster Creek Reactor " No action required  
RIER, B H Region 1, Philadelphia, Office of the Director, 79/05/29 1p

07200137 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
RIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907030284 Responds to IE Bulletin 79-07 re computer codes used in seismic stress analysis in safety-related piping, Lists computer codes in use & codes which are verified  
CURTIS, N W Pennsylvania Power & Light Co. 79/06/01. 2pp.

7907110663 Ack receipt of 790523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-01 & 50-388/79-01  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/05 1p

--7907110672 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-387/79-01 & 50-388/79-01 Corrective actions field procedures revised  
SABOL, A R Pennsylvania Power & Light Co 79/05/23 3pp

--7907110680 Forwards IE Insp Repts 50-387/79-01 & 50-388/79-01 on 790102-0202 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/14 2pp

--7907110689 Notice of violation from insp on 790102-0202  
\* Region 1, Philadelphia, Office of the Director 79/03/09 1p

--7907110696 IE Insp Repts 50-387/79-01 & 50-388/79-01 on 790102-0202 Noncompliance noted failure to remove arc strike per established procedures  
GALLO, R M Region 1, Philadelphia, Office of the Director  
MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/09 12pp

7907190099 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060123 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020051 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907260087 Responds to IE Bulletin 79-03 One ASME-SA-312 Type 304 fusion-welded pipe spool installed in Class 1 sys Completion of radiography of exposed position expected by 790716  
CURTIS, N W Pennsylvania Power & Light Co 79/06/12 2pp

7907260192 Responds to IE Bulletin 79-09 OE Type AK-2 breakers utilized but w/o undervoltage trip device New measures will be incorporated into preventive maint program to be implemented prior to fuel load  
CURTIS, N W Pennsylvania Power & Light Co 79/06/12. 1p

7907260156 Responds to IE Bulletin 79-04 No Valen swing check valves installed at facility  
CURTIS, N W Pennsylvania Power & Light Co 79/06/13 1p.

7907190006 Ack receipt of 790604 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-14 & 50-388/79-08.  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/14. 1p

--7907190011 Responds to NRC 790426 ltr re violations noted in IE Insp Repts 50-387/79-14 & 50-388/79-08 Corrective actions welding procedure revised to include supplementary essential variable GW-410-24  
SABOL, A R Pennsylvania Power & Light Co. 79/06/04 4pp.

--7907190016 Forwards IE Insp Repts 50-387/79-14 & 50-388/79-08 on 790319-23 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/26 2pp

--7907190019 Notice of violation from insp on 790319-23  
\* Region 1, Philadelphia, Office of the Director. 79/04/19 2pp

--7907190029 IE Insp Repts 50-387/79-14 & 50-388/79-08 on 790319-23 Noncompliance noted failure to specify supplementary essential variables in welding procedure specs & failure to assure piping cleanliness before closure  
DURR, J P, FINKEL, A E Region 1, Philadelphia, Office of the Director. TRIPP, L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/19. 7pp

7907230558 Ack receipt of 790516 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-387/79-11 & 50-388/79-07  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/14 1p

--7907230572 Responds to NRC 790417 ltr re violation noted in IE Insp Repts 50-387/79-11 & 50-388/79-07 Corrective actions new terminations properly installed Memo issued to insure wire brushing of connectors  
SABOL, A R Pennsylvania Power & Light Co 79/05/16 2pp

--7907230579 Forwards IE Insp Repts 50-387/79-11 & 50-388/79-07 on 790306-08 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/17 2pp

--7907230585 Notice of violation from insp on 790306-08  
+ Region 1, Philadelphia, Office of the Director 79/04/06 1p

--7907230598 IE Insp Repts 50-387/79-11 & 50-388/79-07 on 790306-08 Noncompliance noted failure to properly prepare electrical cable termination prior to installation  
FINKEL, A E Region 1, Philadelphia, Office of the Director  
EDNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/06 8pp

7907200477 Ack receipt of 790611 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-387/79-106 & 50-388/79-06  
CARLSON, R T Region 1, Philadelphia, Office of the Director 79/06/18 1p

--7907200484 Responds to NRC 790510 Ltr re violation noted in IE Insp Repts 50-387/79-10 & 50-388/79-06 Corrective actions noncompliance repts processed per procedural requirements of Field Insp Procedure G-3  
SABOL, A R Pennsylvania Power & Light Co 79/06/11 3pp

--7907200491 Forwards IE Insp Rept 50-387/79-10 & 50-388/79-06 on 790308-30 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Office of the Director 79/05/10 2pp

--7907200496 Notice of violation from insp on 790305-30  
+ Region 1, Philadelphia, Office of the Director 79/05/05 1p

--7907200503 IE Insp Rept 50-387/79-10 & 50-388/79-06 on 790305-30 Noncompliance noted failure to follow documented procedures for control of nonconfirming items  
GALLO, R M Region 1, Philadelphia, Office of the Director  
MCOAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/05 10pp.

7907110386 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230697 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"  
Action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120528 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director, 79/06/23 1p

7907100361 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100426 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907110033 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180805 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required.  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270359 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310532 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/07/16 1p

#### S Reportable occurrences, LERs & related correspondence

7907030327 Notifies that Region 1 granted extension until 790815 for submittal of final rept re deficiency in solenoid valves in response to util 790522 request  
CURTIS, N W Pennsylvania Power & Light Co 79/06/28 2pp

7907260651 Confirms 790614 verbal rept re damage sustained by safety-related cables during cable pulling activities  
Problem deemed reportable Util final rept will be submitted by 791201  
CURTIS, N W Pennsylvania Power & Light Co 79/07/17 2pp

7907270298 Updates 780623 deficiency rept re unsatisfactory field welding & insp of shear studs Required shear stud repairs completed  
CURTIS, N W Pennsylvania Power & Light Co 79/07/23 1p

#### DOCKET 50-389 ST LUCIE PLANT, UNIT 2

#### A Application/construction stage documents & correspondence

7907060247 Summary of 790516 meeting w/util re failure of offsite power w/simultaneous onsite ac power failure & other ALAB-537 matters Attendance list, agenda & info provided by util encl  
BIRKEL, R A Light Water Reactors Branch 2 79/05/22 78pp

7907020188 Indicates personnel problems shortage exists re restart from refueling on 790528, pass rate for new operator qualification exams less than 50% Due to shortage of licensed operators, overtime being implemented  
ROSS, D F Division of Project Management 79/06/16 2pp

7907120599 Forwards info re const & loading schedule Provides updated listing of major activities by node number & logic network. Corrects several errors in NRC May 1979 const status rept Oversized drawing encl  
UHRIG, R E Florida Power & Light Co 79/06/26 3pp

#### G Adjudicatory correspondence

7907190206 Submits Certified Resolution 79-4 1 adopted by Martin County FL Board of County Commissioners on 790403 NRC should review plant safety precautions to alleviate possibility of incident similar to TMI  
CARMODY, J T Martin County, FL 79/05/01 3pp

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of matl fact Certificate of Bvc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907160027 Forwards MP Amend. EL Bivans, WE Coe & OE Liebier prepared written testimonies per 790516 meeting & ALAB-537 Advises of util suggestion to make changes in summary of 790516 meeting Certificate of Bvc encl  
COLL, N A Steel, Hector & Davis 79/06/01 4pp

--7907160034 Joint testimony re Questions A1 & D of 790405 memo & order ALAB-537 re general design criterion "Electric Power Sys," & ongoing improvement of sys reliability. Supporting documentation encl  
ARMAND, M P, BIVANS, E L, COE, W E Florida Power & Light Co 79/06/01 71pp

--7907160044 Testimony on Question C of ALAB-537 re requirement to place power distribution sys in alert status  
LIEBLER, O E Florida Power & Light Co 79/06/01 3pp

7907190398 NRC motion for extension until 790921 to respond to ALAB-537 questions re Florida Power & Light electrical grid & emergency power sys Certificate of Bvc encl.  
PATON, W D Branch 4 79/06/21 4pp

7907230071 Forwards FQ Flusser 790405 testimony re ALAB-537 Questions A2 & B1-4 & technical info re Midway substation Certificate of Bvc encl  
COLL, N A Steel, Hector & Davis 79/06/22 5pp

## DOCKETED ITEMS

--7907230080 Testimony re ALAB-537 memo & order, Questions A2 & B1-4, relating to electrical grid stability & emergency power sys Affidavit & supporting documentation encl  
FLUGGER, F G Florida Power & Light Co 79/04/05 46pp

G Inspection reports, IE Bulletins & correspondence

7907020366 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl 1" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110325 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907100184 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110097 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/22 2pp

7907100094 Responds to IE Bulletins 79-06 & 06B Responsibility for initiation & verification of auxiliary feedwater flow to steam generators is primary duty of designated operator during transients & accidents. UHRIO, R E Florida Power & Light Co 79/05/25 1p

7907030096 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907200192 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required. O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907190172 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class 1E Equipment (Deficiencies in Environ Qualification of TCO Solenoid Valves)." Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 06/06 2pp.

60056 Forwards IE Info Notice 79-15, "Deficient Procedures." No ion required EILLY, J P Region 2, Atlanta, Office of the Director 06/07 2pp

090105 Responds to IE Bulletin 79-09, Procedures similar to those described in 790522 response will be developed prior to initial fuel loading, providing OE AX-2 circuit breakers are used JHRIQ, R E Florida Power Corp 79/06/07. 1p.

907020208 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

190060 Advises that C-E intends to submit generic rept requested Item 1 of IE Bulletin 78-12B re atypical weld matl. Final ponsse will be submitted by 790629. 10, R E Florida Power & Light Co. 79/06/11 1p

90383 Responds to IE Bulletin 79-09 No ASME SA-312 Type 304 or er welded pipe mfg by Youngstown Welding & Engineering Co nmed for or used in safety-related sys 10, R E Florida Power & Light Co. 79/06/11. 1p.

50160 Requests that Region 2 measurements van be granted access villages of "licensee designated vehicle " EILLY, J P Region 2, Atlanta, Office of the Director, 06/11. 3pp

71 Responds to IE Bulletin 79-07, None of methods specified A/E or NBBB ADL PIPE used to perform seismic s of safety-related piping plant changes & mods. E, Florida Power & Light Co. 79/06/14. 2pp.

10184 Supplements 780626 response to IE Bulletin 78-05, OE CR150X ilary contact mechanisms not in use or planned for in safety-related sys. 18, R E Florida Power & Light Co. 79/06/15 1p

7907310199 Supplements 780801 response to IE Bulletin 78-06 No Cutler-Hammer Type M relays w/coils are in use or planned for use in safety-related sys at facility UHRIO, R E Florida Power & Light Co 79/06/15 1p

7907020386 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120075 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110269 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907180306 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180435 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907310240 Forwards IE Bulletin 79-14, "Eismic Analysis for As-Built Safety-Related Piping Sys " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp

7907310379 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 2pp

U Congressional/Executive Correspondence

7906260590 Forwards D Browning 790404 questions re FL nuclear power situation Requests necessary info for reply MICA, D A House of Rep 79/04/05 2pp

--7906260593 Ack receipt of 790405 ltr re D Browning info request re FL nuclear power situation Forwards instructions to operators re steps to prevent occurrence like TH1 & JM Hendrie 790410 testimony to Subcommittee on Nuclear Regulation W/s encl. KAMMERER, C Office of Congressional Affairs. 79/04/18 1p

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7907160109 Draft memo re licensing strategy for plants w/fuel load dates in CV79. BOYD, R B Division of Project Management 79/03/28 6pp.

7907110699 Notification of 790614 meeting w/util in Bethesda, MD to discuss southern Appalachian region tectonic study. STAHL, C R Light Water Reactors Branch 4. 79/06/11 3pp

7907260048 Summary of 790501-02 meeting w/TVA at facility re status of plant const. STAHL, C. Light Water Reactors Branch 4 79/06/22 8pp

7907060309 Forwards "Southern Appalachian Tectonic Study." GILLELAND, J E Tennessee Valley Authority. 79/06/28. 2pp.

--7907060316 "Southern Appalachian Tectonic Study " Oversized maps encl. BEAY, W.M. Tennessee Valley Authority 79/01/31. 84pp

G Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl 1." O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/21. 3pp.

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required. O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/05/07. 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/10 3pp

7907230755 Forwards IE Insp Repts 50-390/79-21 & 50-391/79-17 on 790424-27 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907230768 IE Insp Repts 50-390/79-21 & 50-391/79-17 on 790424-27 No noncompliance noted Major areas inspected in-place storage & records for electrical motors & installation of & records for instrumentation components  
RUFF, A B Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/11 4pp

7907240383 Forwards IE Insp Repts 50-390/79-19 & 50-391/79-15 on 790402-27 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907240391 IE Insp Repts 50-390/79-19 & 50-391/79-15 on 790402-27 No noncompliance noted Major areas inspected cable pulling & termination, safety injection sys piping & insulation installation on refueling water storage tank  
COCHRAN, B J, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 7pp.

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 3pp

7907240197 Forwards IE Insp Repts 50-390/79-22 & 50-391/79-18 on 790502-04 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 2pp

--7907240201 IE Insp Repts 50-390/79-22 & 50-391/79-18 on 790502-04 No noncompliance noted Major areas inspected concrete expansion anchors & safety-related components  
COMPTON, R M Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 3pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Valves swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp.

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NSSS sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components.  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/06. 3pp.

7907040064 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/07. 2pp.

7907180592 Ack receipt of 790508 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-390/79-12 & 50-391/79-10  
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/08. 2pp.

--7907180602 Responds to NRC 790417 ltr re violations noted in IE Insp Repts 50-390/79-13 & 50-391/79-10 Corrective actions none deemed necessary Affixed mark of inspector complies w/requirements  
GILLELAND, J E Tennessee Valley Authority 79/05/08 4pp

--7907180614 Forwards IE Insp Repts 50-390/79-13 & 50-391/79-10 on 790305-30 & notice of violation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 2pp

--7907180623 Notice of violation from insp on 790305-30  
\* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p

--7907180640 IE Insp Repts 50-390/79-13 & 50-391/79-10 on 790305-30 Noncompliance noted failure to properly document insp of nondestructive examinations of pipe whip restraints  
COCHRAN, B J Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 8pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem. " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02. 3pp

7907300355 Ack receipt of 790601 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-390/79-12 & 50-391/79-09.  
MURPHY, C E Operating Reactors Branch 2 79/07/03 2pp

--7907300360 Responds to NRC 790404 ltr re violation noted in IE Insp Repts 50-390/79-12 & 50-391/79-09 Corrective actions: all personnel involved in preparation of welder qualification records not to use corrective fluid.  
GILLELAND, J E Tennessee Valley Authority. 79/06/01 2pp.

7907100556 Forwards Revisions 6 & 7 to Preservice Baseline & Inservice Insp Program SI-4 4 10 1  
MILLER, L. M. Tennessee Valley Authority 79/07/06. 1p.

--7907100564 Preservice baseline insp & inservice insp program, Revision 6 to SI-4.4 10 1  
BELEM, O L. Tennessee Valley Authority 78/10/25 2pp

--7907100569 Preservice baseline insp & inservice insp program, Revision 7 to SI-4.4 10 1  
\* BELEM, O L. Tennessee Valley Authority. 78/10/25. 18pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies. " Action required.  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.  
79/07/11 2pp.

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required.  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.  
79/07/13. 3pp

## DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

7907030351 Forwards final deficiency rept re defective Phillips self drill concrete anchors, originally reported 790319 Caused by mfg defect Corrective actions testing & replacing as required Vendor improving QA insp  
GILLELAND, J E Tennessee Valley Authority 79/06/26 4pp

7907170036 Forwards final deficiency rept re vendor-supplied discharge accumulator  
MILLS, L M Tennessee Valley Authority 79/07/09 2pp

--7907170041 Final deficiency rept re failure of metal bellows in discharge accumulator Caused by abrasion of liner due to pounding or lodging between terminal Nickel-plated aluminum will be replaced w/stainless steel on lines  
\* Tennessee Valley Authority 79/07/09 1p

7907180484 Forwards deficiency rept re changing of intermediate break locations of pressurizer surge lines  
MILLS, L M Tennessee Valley Authority 79/07/10 1p

--7907180491 Final deficiency rept on 790604 changing of intermediate break locations on pressurizer surge line Initial temp distribution for process pipe determined unconservative Caused by improper analysis Devices modified  
\* Tennessee Valley Authority 79/07/10 1p

7907180533 Discusses second interim deficiency rept re QA program implementation breakdown TVA to determine if spent fuel racks are acceptable after further documentation & verification from Wachter Final rept to be sent by 790928  
MILLS, L M Tennessee Valley Authority 79/07/10 2pp

7907180477 Forwards final deficiency rept re possible unconservative pressurizer relief & safety line blowdown analysis  
MILLS, L M Tennessee Valley Authority 79/07/11 1p

--7907180501 Final deficiency rept during blowdown analysis of pressurizer relief & safety lines, discovered that sys failure would cause pressurizer line blowdown & create LOCA condition Caused by unconservative pressure relief  
\* Tennessee Valley Authority 79/07/11 1p

7907180496 Forwards deficiency rept re conduit junction boxes inside containment  
MILLS, L M Tennessee Valley Authority 79/07/12 1p

--7907180513 Final deficiency rept on 790615 conduit junction boxes in containment Field installed conduits connected to intermediate junction boxes do not provide for sealing around conduit Terminations to be replaced w/splices  
\* Tennessee Valley Authority 79/07/12 1p

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2A Application/construction stage documents & correspondence

7907110699 Notification of 790614 meeting w/util in Bethesda, MD to discuss southern Appalachian region tectonic study  
STAHL, C R Light Water Reactors Branch 4 79/06/11 3pp

7907260048 Summary of 790501-02 meeting w/TVA at facility re status of plant const  
STAHL, C R Light Water Reactors Branch 4 79/06/22 8pp

7907060309 Forwards "Southern Appalachian Tectonic Study"  
GILLELAND, J E Tennessee Valley Authority 79/06/28 2pp

--7907060316 "Southern Appalachian Tectonic Study" Oversize maps encl  
SEAY, W M Tennessee Valley Authority 79/01/31 84pp

G Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/21 3pp

7907110338 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 7/05/10 3pp

7907230755 Forwards IE Insp Repts 50-390/79-21 & 50-391/79-17 on 790424-27 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907230768 IE Insp Repts 50-390/79-21 & 50-391/79-17 on 790424-27 No noncompliance noted Major areas inspected in-place storage & records for electrical motors & installation of & records for instrumentation components  
RUFF, A B Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/11 4pp

7907240383 Forwards IE Insp Repts 50-390/79-19 & 50-391/79-15 on 790402-27 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907240391 IE Insp Repts 50-390/79-19 & 50-391/79-15 on 790402-27 No noncompliance noted Major areas inspected cable pulling & termination, safety injection sys piping & insulation installation on refueling water storage tank  
COCHRAN, B J, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 7pp

7907100207 Forwards IE Circular 79-0B, "Attempted Extortion - Low Enriched U" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 3pp

7907240197 Forwards IE Insp Repts 50-390/79-22 & 50-391/79-18 on 790502-04 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 2pp

--7907240201 IE Insp Repts 50-390/79-22 & 50-391/79-18 on 790502-04 No noncompliance noted Major areas inspected concrete expansion anchors & safety-related components  
COMPTON, R M Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 3pp

7907030108 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Valves swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NSSB sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907180592 Ack receipt of 790508 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-390/79-13 & 50-391/79-10  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/08 2pp

--7907180602 Responds to NRC 790417 ltr re violations noted in IE Insp Repts 50-390/79-13 & 50-391/79-10 Corrective actions none deemed necessary Affixed mark of inspector complies w/requirements  
GILLELAND, J E Tennessee Valley Authority 79/05/08 4pp.

# DOCKETED ITEMS

218

--7907180414 Forwards IE Insp Repts 50-390/79-13 & 50-391/79-10 on 790305-30 & notice of violation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 2pp

--7907180423 Notice of violation from insp on 790305-30  
\* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p

--7907180640 IE Insp Repts 50-390/79-13 & 50-391/79-10 on 790305-30  
Noncompliance noted failure to properly document insp of nondestructive examinations of pipe whip restraints  
COCHRAN, B J Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 8pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907250434 Ack receipt of 790529 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-391/79-04  
MURPHY, C E Region 2, Atlanta, Office of the Director 79/06/11 2pp

--7907250454 Responds to NRC 790520 ltr re violations noted in IE Insp Rept 50-391/79-04 Corrective actions load sensor repaired & placed in svc Importance of QA emphasized to employees  
GILLELAND, J E Tennessee Valley Authority 79/05/29 3pp

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

79070310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 3pp

79070310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/02 3pp

7907300355 Ack receipt of 790601 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-390/79-12 & 50-391/79-09  
MURPHY, C E. Operating Reactors Branch 2 79/07/03 2pp

--7907300360 Responds to NRC 790404 ltr re violation noted in IE Insp Repts 50-390/79-12 & 50-391/79-09. Corrective actions all personnel involved in preparation of welder qualification records not to use corrective fluid  
GILLELAND, J E Tennessee Valley Authority 79/06/01 2pp.

7907100556 Forwards Revisions 6 & 7 to Preservice Baseline & Inservice Insp Program SI-4 4 10.1  
MILLS, L M Tennessee Valley Authority 79/07/06 1p.

--7907100564 Preservice baseline insp & inservice insp program, Revision 6 to SI-4 4 10.1.  
BELEM, O L Tennessee Valley Authority 78/10/25 2pp

--7907100569 Preservice baseline insp & inservice insp program, Revision 7 to SI-4 4 10.1  
BELEM, O L Tennessee Valley Authority. 78/10/25 18pp

79070310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 3pp

S Reportable occurrences, LERs & related correspondence

7907030351 Forwards final deficiency rept re defective Phillips self drill concrete anchors, originally reported 790319 Caused by mfg defect Corrective actions testing & replacing as required Vendor improving GA insp  
GILLELAND, J E Tennessee Valley Authority 79/06/26 4pp

7907170036 Forwards final deficiency rept re vendor-supplied discharge accumulator  
MILLS, L M Tennessee Valley Authority 79/07/09 2pp

--7907170041 Final deficiency rept re failure of metal bellows in discharge accumulator Caused by abrasion of liner due to pounding or lodging between terminal Nickel-plated aluminum will be replaced w/stainless steel on lines  
\* Tennessee Valley Authority 79/07/09 1p

7907180484 Forwards deficiency rept re changing of intermediate break locations of pressurizer surge lines  
MILLS, L M Tennessee Valley Authority 79/07/10 1p

--7907180491 Final deficiency rept on 790404 changing of intermediate break locations on pressurizer surge line Initial temp distribution for process pipe determined unconservative Caused by improper analysis Devices modified  
\* Tennessee Valley Authority 79/07/10 1p

7907180533 Discusses second interim deficiency rept re QA program implementation breakdown TVA to determine if spent fuel racks are acceptable after further documentation & verification from Wachter Final rept to be sent by 790928  
MILLS, L M Tennessee Valley Authority 79/07/10 2pp

7907180497 Forwards final deficiency rept re possible unconservative pressurizer relief & safety line blowdown analysis  
MILLS, L M Tennessee Valley Authority 79/07/11 1p

--7907180501 Final deficiency rept during blowdown analysis of pressurizer relief & safety lines, discovered that sys failure would cause pressurizer line blowdown & create LOCA condition Caused by unconservative pressure relief  
\* Tennessee Valley Authority 79/07/11 1p

7907180496 Forwards deficiency rept re conduit junction boxes inside containment  
MILLS, L M Tennessee Valley Authority 79/07/12 1p

--7907180513 Final deficiency rept on 790613 conduit junction boxes in containment Field installed conduits connected to intermediate junction boxes do not provide for sealing around conduit Terminations to be replaced w/splices  
\* Tennessee Valley Authority 79/07/12 1p.

DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES REACTOR

G Inspection reports, IE Bulletins & correspondence

7907230561 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907310166 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/06 1p

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7907110268 Notification of 790622 meeting w/util in Bethesda, MD to discuss induced seismicity at facility site List of discussion items encl  
TIBBITT, D L Light Water Reactors Branch 2 79/05/31 4pp

7907050365 Notifies that schedule to conduct cold hydro has been changed from Nov to Sept 1979 Anticipates fuel load during Jul 1980. Requests aid in developing actions which will support schedule  
CREWS, E. H. South Carolina Electric & Gas Co. 79/06/29 1p

## DOCKETED ITEMS

## F Security, medical, emergency &amp; fire protection plans

7907030217 Forwards physical security plan Plan withheld  
(ref 10CFR2 790)  
CREWS, E H South Carolina Electric & Gas Co 79/06/28 2pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907020354 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
TMI - Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 1p

7907020354 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
TMI - Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907180549 Forwards IE Insp Rept 50-395/79-10 on 790320-23 & notice of  
violation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/05/04 2pp

--7907180791 Notice of violation from insp on 790320-23  
\* Region 2, Atlanta, Office of the Director 79/05/04 1p

--7907180801 IE Insp Rept 50-395/79-10 on 790320-23 Noncompliance noted  
no requirements on weld profile  
BLAKE, J J Region 2, Atlanta, Office of the Director  
CDLON, Y E Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/04 7pp

7907110332 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907110333 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 1p

7907100204 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907100100 Responds to IE Bulletin 79-07 In no instance is algebraic  
technique used to combine responses Code used by  
Westinghouse is WESTDYN, which is documented in HCAP-8252,  
Revision 1  
CREWS, E H South Carolina Electric & Gas Co 79/05/21 2pp

7907060362 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys" Licensee  
action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907060363 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys" Licensee  
action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907090404 Responds to IE Bulletins 57B-12, 12A & 12B. Weld matl data &  
other required info included in Chicago Bridge & Iron  
Co generic rept Cover ltr to rept & relevant info encl  
CREWS, E H South Carolina Electric & Gas Co 79/05/24 2pp

--7907090414 Responds to IE Bulletins 78-12 & 12A Forwards rept on  
all completed reactor vessels W/O encl  
KELLEY, R E Chicago Bridge & Iron Co 79/04/24 1p

7907030101 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor."  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 1p.

7907260145 Forwards IE Insp Rept 50-395/79-15 on 790508-11. No  
noncompliance noted.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/05/30 2pp.

--7907260151 IE Insp Rept 50-395/79-15 on 790508-11 No noncompliance  
noted. Major areas inspected: safety-related 7200-volt  
switchgear & 480-volt load ctr installations, safety-related  
wiring & wiring support installations.  
WALTERS, D K, BRYANT, J C Region 2, Atlanta, Reactor  
Construction & Engineering Support Branch. 79/05/30. 5pp.

7907200204 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907200205 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 1p

7907260316 Forwards IE Insp Rept 50-395/79-19 on 790508-11 No  
noncompliance noted  
MURPHY, C E Region 2, Atlanta, Office of the Director 79/05/31  
2pp

--7907260522 IE Insp Rept 50-395/79-19 on 790508-11 No noncompliance  
noted. Major areas inspected: welding & QA implementing  
procedures for safety-related piping.  
GIRARD, E H Region 2, Atlanta, Office of the Director  
79/05/30 4pp

7907190340 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit  
breakers are used in safety-related sys  
CREWS, E H South Carolina Electric & Gas Co 79/06/04 1p

7907190184 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 1p

7907190187 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060061 Forwards IE Info Notice 79-15, "Deficient Procedures" No  
action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907060062 Forwards IE Info Notice 79-15, "Deficient Procedures" No  
action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp.

7907020217 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907130200 Ack receipt of IE Insp Rept 50-395/79-14 on 790430-0501 No  
proprietary info  
JOHNSON, M C Public Service Electric & Gas Co of New Jersey  
79/06/12 1p

--7907130210 Forwards IE Insp Rept 50-395/79-14 on 790430-0501 No  
noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/21 2pp

--7907130225 IE Insp Rept 50-395/79-14 on 790430-0501 No noncompliance  
noted. Major areas inspected: dome tendon stressing, QA plan  
revision, cable tray hanger welding & anchor plate bolt  
torquing.  
SWAN, W B, HERDT, A R Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/18 4pp

7907020391 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p.

7907120094 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts" Action  
required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/21 1p

7907120098 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts." Action  
required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p.

7907230547 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI"  
No action required.  
ENOKLKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22 1p.



# DOCKETED ITEMS

21

7907310026 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907110277 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/26 2pp

7907180318 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180440 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310385 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

7907310386 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

## S Reportable occurrences, LERs & related correspondence

7907100662 Discusses noncompliance w/QA procedures specified on purchase orders for limit switches received from Butler & Land, Anchor Darling Valve Co & Bradner Industries Will replace switches within 45 days  
SWANSON, N E Acme-Cleveland Co., Namco Controls Div 79/06/14. 3pp

7907170067 Discusses failure to implement QA requirements re Namco limit switches Namco QA program now in effect & licensee will have all non-QA switches replaced by 790729  
JOHNSON, M C South Carolina Electric & Gas Co 79/07/10 3pp

## DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR

### G Inspection reports, IE Bulletins & correspondence

7907100081 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 1p

7907230415 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

## DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

### A Application/construction stage documents & correspondence

7907270281 Forwards request from Reactor Sys Branch for addl info re FBAR analyses indicating compliance w/requirement for overpressurization protection IE Circular 78-06 encl  
VARGA, S. A. Light Water Reactors Branch 4 79/05/29 19pp

--7907270284 IE Circular 78-06 Potential Common Mode Flooding of ECCB Equipment Rooms at BWR Facilities  
\* Office of Inspection & Enforcement 78/05/30. 2pp

7906210227 Forwards "Chugging Loads-Improved Definition & Application Methodology to Mark II Containments-Technical Rept " Rept withheld (ref 10CFR2 790)  
KENBERGER, D L Washington Public Power Supply System 79/06/01. 3pp

--7906210231 Requests that "Chugging Loads-Improved Definition & Application Methodology to Mark II Containments-Technical Rept," be withheld (ref 10CFR2 790)  
CANTER, H L Burns & Roe Co 79/06/01 2pp

--7906210234 Forwards "Chugging Loads-Improved Definition & Application Methodology to Mark II Containments-Technical Rept," Rept withheld (ref 10CFR2 790).  
BAKER, D C Burns & Roe Co. 79/06/14. 2pp

--7906210238 "Chugging Loads-Improved Definition & Application Methodology to Mark II Containments "  
ETTDUNEY, H H, PATTI, F J Washington Public Power Supply System 79/06/15 180pp

7907250097 Notification of 790716 meeting w/Mark II owners & OE re WPPSS-2 chugging improvement program & Busquehanna test programs  
ANDERSON, C J Containment Systems Branch 79/07/05 5pp

7907260511 Forwards response to first round questions, Sets 5 & 6  
RENBARGER, D L Washington Public Power Supply System 79/07/20 3pp

--7907260515 Responds to first round questions, Sets 5 & 6  
\* Washington Public Power Supply System 79/07/20 182pp

### K Utility Final Safety Analysis Report (FSAR) & amends

7907310289 Forwards Amend 4 to FSAR Includes new section, "Reactor Recirculation Sys," & other minor changes Affidavit of distribution will be forwarded within 10 days, per 10CFR2 101  
RENBARGER, D L Washington Public Power Supply System 79/07/06 2pp

--7907310294 Amend 4 to FSAR  
\* Washington Public Power Supply System 79/06/30 380pp

### G Inspection reports, IE Bulletins & correspondence

7907050388 Forwards IE Insp Rept 50-397/79-06 on 790402-05 No noncompliance noted  
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/26 2pp

--7907050392 IE Insp Rept 50-397/79-06 on 790402-05 No noncompliance noted Major areas inspected routine safety-related piping work, review of quality records, followup on IE circulars & reportable items.  
BISHOP, T W, ECKHARDT, J H Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/25 10pp

7907110624 Forwards IE Insp Rept 50-397/79-07 on 790402-04, No noncompliance noted  
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/05/09 2pp

--7907110634 IE Insp Rept 50-397/79-07 on 790402-04 No noncompliance noted Major areas inspected four allegations re situ work by Waldinger Corp, welding procedures, ventilation sys isolation valves & QA/QC program  
BISHOP, T W, ECKHARDT, J E Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/08 5pp

7907090237 Responds to IE Bulletin 79-04 No Velan swing check valves used Nine testable check valves will be provided by Velan to be used in HPCB, LPCB, reactor core isolation cooling & RHR Seismic Category 1 piping sys  
RENBARGER, D L Washington Public Power Supply System 79/05/25 2pp

7907180069 Responds to IE Bulletins 78-12, 78-12A & 78-12B, No atypical weld matl found  
RENBARGER, D L Washington Public Power Supply System 79/05/25. 2pp

7907260554 Forwards IE Insp Rept 50-397/79-08 on 790423-26 No noncompliance noted  
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/25 2pp

--7907260557 IE Insp Rept 50-397/79-08 on 790423-26 No noncompliance noted Major areas inspected safety-related piping work, quality records, reactor recirculation nozzle mod & quality implementing procedures.  
BISHOP, T W, NARBUT, P P Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/25 11pp

7907030073 Ack receipt of 790510 & 18 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/79-04.  
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/31 1p.

## DOCKETED ITEMS

--7907030084 Responds to NRC 790417 ltr re violations noted in IE Insp Rept 50-397/79-04 Corrective actions for QA program initiation of periodic reindocination programs for managers & audit of contractor QA records  
STRAND, N O Washington Public Power Supply System 79/05/18 3pp

--7907030088 Responds to NRC 790417 ltr re violations noted in IE Insp Rept 50-397/79-04 Corrective actions taped all ports, corrected color coded tags & rept filed to document battery rack deficiency  
RENNBERGER, D L Washington Public Power Supply System 79/05/10 6pp

--7907030091 Forwards IE Insp Rept 50-397/79-04 on 790227-28, 0301-02 & 14-16 & notice of violation  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/17 3pp

--7907030092 Notice of violation from insp on 790227-28, 0301-02 & 14-16  
\* Region 5, San Francisco, Office of the Director 79/04/16 4pp

--7907030094 IE Insp Rept 50-397/79-04 on 790227-28, 0301-02 & 14-16 Noncompliance noted failure to properly install batteries, perform welding insp, maintain sys cleanliness protection & identify 480 volt breakers as to quality class  
DISHOP, T W, KIRSCH, D F Region 5, San Francisco, Office of the Director  
HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/16 16pp

7907200374 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/31 1p

7907190436 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p

7907060036 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07 1p

7907020271 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907270287 Forwards IE Insp Rept 50-397/79-11 on 790529-31 No noncompliance noted  
CRENS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/14 2pp

--7907270290 IE Insp Rept 50-397/79-11 on 790529-31 No noncompliance noted Major areas inspected operational staffing, QA & resolution of comments re preoperational testing & plant const status  
BERNBERG, D M, JOHNSON, P H, CARLSON, J D Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/06/13 3pp

907020453 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p

707120017 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/21 1p

07120630 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/25 1p

07060226 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/26 1p

79080497 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/27 1p

7907100534 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/28 1p

7907130222 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p

7907180711 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/11 1p

7907310401 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260286 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

#### B Reportable occurrences, LERs & related correspondence

7907020291 Forwards PND-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/03 1p

7907030200 Forwards PND-79-67AS  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907180541 Ack receipt of 790531 ltr forwarding rept of deficiency involving defective steel plate in supporting structures for pipe whip restraints Rept will be reviewed & evaluated  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907030244 Forwards PND-79-67AT, "Nuclear Incident at TMI "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/19 1p

7907050543 Forwards PND-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907130390 Forwards PND-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/03 1p

7907250310 Forwards reportable deficiency on 790611 re emergency dc motor control ctr room cooler RRA-FC-12, powered from noncritical motor control ctr.  
RENNBERGER, D L Washington Public Power Supply System 79/07/16 1p

--7907250314 Reportable deficiency on 790621 emergency dc motor control ctr cooler RRA-FC-12 is powered from noncritical motor control ctr MC-7C-A Design directive issued & power to RRA-FC-12 is presently being provided  
\* Washington Public Power Supply System 79/06/11 3pp

7907240315 Ack receipt of 790702 ltr forwarding reportable deficiency re improper installation of concrete anchors Rept will be reviewed & evaluated  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

--7907240320 Forwards reportable deficiency re improper installation of concrete anchors  
RENNBERGER, D L Washington Public Power Supply System 79/07/02 1p

--7907240326 Reportable deficiency improper installation of concrete anchors could result in possible failure of safety-related equipment during operation Contracts reviewed & engineering change orders issued  
\* Washington Public Power Supply System 79/06/04 1p

#### DOCKET 50-400 SHEARDON HARRIS NUCLEAR POWER PLANT, UNIT 1

##### A Application/construction stage documents & correspondence

7906260325 Summary of 790502 Affirmation Session 79-10 in Washington, DC re SECY-79-16A & SECY-79-20 Motion to reopen hearings on Shearon Harris plants was denied  
CHILK, S. J. Office of the Secretary of the Commission 79/05/04 1p

7907190140 Forwards review of criteria for previously placed fill  
GC of field moisture content determinations should be  
resolved Recommends content be controlled to remain within  
spec limits  
JACKSON, R E Division of Systems Safety 79/06/06 5pp

7907030497 Forwards Tech Procedure TP-02, Revision 11, re special control  
procedures for fill supporting Category 1 pipes & electrical  
conduits  
MCDUFFIE, M A Carolina Power & Light Co 79/06/28 1p

--7907030500 Tech Procedure TP-02, Revision 11, re soil control program,  
fill & backfill for plant grade, plant bldg & reservoir  
concrete structures  
\* Carolina Power & Light Co 79/06/28 32pp

7907260460 Forwards "Rept on Rock Fill Test Sections, Main Dam"  
Requests approval of rept as soon as possible  
MCDUFFIE, M A Carolina Power & Light Co 79/07/18 1p

--7907260467 "Rept on Rock Fill Test Sections, Main Dam"  
\* Carolina Power & Light Co 79/07/18 87pp

#### G Adjudicatory correspondence

7907050320 Forwards 790508 Board notification re addl faults found in  
main dam area  
REIS, E J Branch 3 79/05/09 1p

--7907050325 Forwards 790427 memo re addl faults found in main dam site  
VASSALLO, D B Assistant Director for Light Water Reactors  
79/05/08 1p

--7907050325 Forwards 790427 memo re addl faults found in main dam site  
VASSALLO, D B Assistant Director for Light Water Reactors  
79/05/08 1p

7907130507 Submits corrections for NRC proposed findings  
REIS, E J Branch 3 79/05/17 1p

7907060052 CP & L reply to NRC 790510 proposed findings of fact &  
conclusions of law Position expressed in applicant 790417  
proposed findings of fact & conclusion of law in form of  
supplemental initial decision Certificate of Svc encl  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/05/22  
14pp

7907160131 Requests summary disposition of Intervenor's Ecology Action  
of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re  
Perkins record Deficiencies do not raise genuine issue of  
matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907160269 Forwards JA Jones 790527 affidavit marked as Applicant  
Exhibit PP, per ASLB 790525 order  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/06/12 6pp

--7907160276 CP & L revision to util 790417 proposed findings of fact &  
conclusion of law in form of supplemental initial decision  
Certificate of Svc encl  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/06/12  
7pp

7907190617 NRC revision to proposed findings of fact reflecting  
CP & L mgt changes, per applicant 790518 ltr & JA Jones  
790607 affidavit Certificate of Svc encl  
REIS, E J Branch 3 79/06/18 4pp

#### G Inspection reports, IE Bulletins & correspondence

7907020392 Forwards IE Bulletin 79-09B, "Nuclear Incident at  
THI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110314 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/08/07 2pp.

7907100150 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907050178 Ack receipt of IE Insp Repts 50-400/79-08, 50-401/79-08,  
50-402/79-07 & 50-403/79-07 on 790423-27 No proprietary  
info  
HOWE, P W Carolina Power & Light Co 79/05/22 1p

--7907050182 Forwards IE Insp Repts 50-400/79-08, 50-401/79-08,  
50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance  
noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/16 2pp

--7907050189 IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 &  
50-403/79-07 on 790423-27 No noncompliance noted Major areas  
inspected steam generator mod, concrete placement & QA manual  
procedures for nondestructive examination  
BRADLEY, R D Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/22 5pp

7907110088 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys" Action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 2pp

7907030090 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Dyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907180153 Responds to IE Bulletin 78-12B Generic rept submitted by  
Chicago Bridge & Iron Co adequately represents data for  
facility reactor pressure vessels C-E will submit generic  
rept by midsummer 1979 & request 30-day review period  
MCDUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190190 Responds to IE Bulletin 79-04 No plans for use of Velan  
Engineering Corp swing check valves in Seismic Category 1  
piping sys  
MCDUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190533 Responds to IE Bulletin 79-07 Methods employed in seismic  
analysis of safety-related piping investigated Computer  
code used, WECAN & WESTDYN, are documented in WCAP-8252,  
Revision 1  
MCDUFFIE, M A Carolina Power & Light Co 79/05/29 2pp

7907110578 Ack receipt of IE Insp Repts 50-400/79-09, 50-401/79-09,  
50-402/79-08 & 50-403/79-08 on 790425-26 No proprietary  
info  
HOWE, P W Carolina Power & Light Co 79/05/31 1p

--7907110589 Forwards IE Insp Repts 50-400/79-09, 50-401/79-09,  
50-402/79-08 & 50-403/79-08 on 790425-26 No noncompliance  
noted  
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials  
Safety Branch 79/05/22 2pp

--7907110598 IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 &  
50-403/79-08 on 790425-26 No noncompliance noted Major  
areas inspected dust abatement, erosion control & silt  
loading  
CUNNINGHAM, A L, ANDREWS, D L, HUFHAM, J W Region 2, Atlanta,  
Fuel Facility & Materials Safety Branch 79/05/21 3pp

7907200165 Forwards IE Bulletin 79-12, "Short Period Scrams at BHR  
Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190148 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 1p

7907060043 Forwards IE Info Notice 79-15, "Deficient Procedures" No  
action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020194 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p.

7907240210 Responds to NRC 790521 ltr re violations noted in IE Insp  
Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06.  
Corrective actions, procedures implemented & necessary  
repairs accomplished  
HOWE, P W Carolina Power & Light Co 79/06/12 4pp

--7907240215 Ack receipt of IE Insp Repts 50-400/79-07, 50-401/79-07,  
50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18  
No proprietary info  
HOWE, P W Carolina Power & Light Co 79/05/29 1p

--7907240219 Forwards IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 & notice of violation  
MURPHY, C E Region 2, Atlanta, Office of the Director  
79/05/21 2pp

--7907240225 Notice of violation from insp on 790410-13 & 17-18  
\* Region 2, Atlanta, Office of the Director 0 79/05/17  
2pp

--7907240227 IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 Noncompliance noted  
no accurate revolution counter found on concrete transport truck & no control of moisture found on powerblock fill  
HARRIS, J R, LENAHEAN, J J, BRYANT, J C Region 2, Atlanta, Office of the Director 79/05/17 5pp

7907310204 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers planned for use in safety-related sys at facility  
MCDUFFIE, M A Carolina Power & Light Co 79/06/14 1p

7907020375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120036 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p.

7907250090 Ack receipt of IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24 No proprietary info  
HOWE, P W Carolina Power & Light Co 79/06/21 1p

7907310004 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180281 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180427 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310229 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 1p

7907310362 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

##### A Application/construction stage documents & correspondence

7907190140 Forwards review of criteria for previously placed fill  
QC of field moisture content determinations should be resolved. Recommends content be controlled to remain within spec limits  
JACKSON, R E Division of Systems Safety 79/06/06 5pp

7907030497 Forwards Tech Procedure TP-02, Revision 11, re special control procedures for fill supporting Category 1 pipes & electrical conduits  
MCDUFFIE, M A Carolina Power & Light Co 79/06/28 1p

--7907030500 Tech Procedure TP-02, Revision 11, re soil control program, fill & backfill for plant grade, plant bldg & reservoir concrete structures  
\* Carolina Power & Light Co 79/06/28 32pp

7260460 Forwards "Rept on Rock Fill Test Sections, Main Dam."  
requests approval of rept as soon as possible  
MCDUFFIE, M A Carolina Power & Light Co. 79/07/18 1p

--7907260467 "Rept on Rock Fill Test Sections, Main Dam"  
\* Carolina Power & Light Co 79/07/18 87pp

##### G Adjudicatory correspondence

7907030320 Forwards 790508 Board notification re addl faults found in main dam area  
REIS, E J Branch 3 79/05/09 1p

--7907050325 Forwards 790427 memo re addl faults found in main dam site  
VASSALLO, P B Assistant Director for Light Water Reactors  
79/05/08 1p

7907130507 Submits corrections for NRC proposed findings  
REIS, E J Branch 3 79/05/17 1p

7907060052 CP & L reply to NRC 790510 proposed findings of fact & conclusions of law Position expressed in applicant 790417 proposed findings of fact & conclusion of law in form of supplemental initial decision Certificate of Svc encl  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/05/22 14pp

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, D M Branch 4 79/05/25 29pp

7907160269 Forwards JA Jones 790529 affidavit marked as Applicant Exhibit PP, per ASLB 790525 order  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/06/12 6pp

--7907160276 CP & L revision to util 790417 proposed findings of fact & conclusion of law in form of supplemental initial decision Certificate of Svc encl  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/06/12 7pp

7907190617 NRC revision to proposed findings of fact reflecting CP & L mgt changes, per applicant 790518 ltr & JA Jones 790607 affidavit Certificate of Svc encl  
REIS, E J Branch 3 79/06/18 4pp

##### G Inspection reports, IE Bulletins & correspondence

7907020352 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110314 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907100150 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907050175 Ack receipt of IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No proprietary info  
HOWE, P W Carolina Power & Light Co. 79/05/22 1p

--7907050182 Forwards IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance noted.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/16. 2pp

--7907050189 IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance noted. Major areas inspected: steam generator mod, concrete placement & QA manual procedures for nondestructive examination  
BRADLEY, R D Region 2, Atlanta, Office of the Director.  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/22 5pp

7907110088 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22. 2pp

7907030090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907180153 Responds to IE Bulletin 78-128 Generic rept submitted by Chicago Bridge & Iron Co adequately represents data for facility reactor pressure vessels C-E will submit generic rept by midsummer 1979 & request 30-day review period  
MCDUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190190 Responds to IE Bulletin 79-04 No plans for use of Velan Engineering Corp swing check valves in Seismic Category 1 piping sys  
MCDUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190553 Responds to IE Bulletin 79-07 Methods employed in seismic analysis of safety-related piping investigated Computer code used, WEGAN & WESDYN, are documented in WCAP-8252, Revision 1  
MCDUFFIE, M A Carolina Power & Light Co 79/05/29 2pp

7907110578 Ack receipt of IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790425-26 No proprietary info  
HOWE, P W Carolina Power & Light Co 79/05/31 1p

--7907110589 Forwards IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790425-26 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/22 2pp

--7907110598 IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790425-26 No noncompliance noted Major areas inspected dust abatement, erosion control & silt loading  
CUNNINGHAM, A L, ANDREWS, D L, HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/21 3pp

7907200165 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190148 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCD Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 1p

7907060043 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020194 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907240210 Responds to NRC 790521 ltr re violations noted in IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403 79-06 Corrective actions procedures implemented & necessary repairs accomplished  
HOWE, P W Carolina Power & Light Co 79/06/12 4pp

--7907240215 Ack receipt of IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 No proprietary info  
HOWE, P W Carolina Power & Light Co 79/05/29 1p

--7907240219 Forwards IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 & notice of violation  
MURPHY, C E Region 2, Atlanta, Office of the Director  
79/05/21 2pp

--7907240225 Notice of violation from insp on 790410-13 & 17-18  
\* Region 2, Atlanta, Office of the Director Q 79/05/17 2pp

--7907240227 IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 Noncompliance noted, no accurate revolution counter found on concrete transport truck & no control of moisture found on powerblock fill.  
HARRIS, J R, LENAHAN, J J, BRYANT, J. C. Region 2, Atlanta, Office of the Director 79/05/17 5pp

7907310204 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit breakers planned for use in safety-related sys at facility  
MCDUFFIE, M A Carolina Power & Light Co 79/06/14 1p

7907020375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120036 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907250090 Ack receipt of IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24 No proprietary info  
HOWE, P W Carolina Power & Light Co 79/06/21 1p

7907310004 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180281 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180427 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310229 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 1p

7907310362 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

A Application/construction stage documents & correspondence

7907190140 Forwards review of criteria for previously placed fill GC of field moisture content determinations should be resolved Recommends content be controlled to remain within spec limits  
JACKSON, R E Division of Systems Safety 79/06/06 5pp

7907030497 Forwards Tech Procedure TP-02, Revision 11, re special control procedures for fill supporting Category 1 pipes & electrical conduits  
MCDUFFIE, M A Carolina Power & Light Co 79/06/28 1p

--7907030500 Tech Procedure TP-02, Revision 11, re soil control program, fill & backfill for plant grade, plant bldg & reservoir concrete structures  
\* Carolina Power & Light Co 79/06/28 32pp

7907260440 Forwards "Rept on Rock Fill Test Sections, Main Dam " Requests approval of rept as soon as possible  
MCDUFFIE, M A Carolina Power & Light Co 79/07/18 1p

--7907260467 "Rept on Rock Fill Test Sections, Main Dam "  
\* Carolina Power & Light Co 79/07/18 87pp

#### Q Adjudicatory correspondence

7907050320 Forwards 790508 Board notification re addl faults found in main dam area  
REIB, E J Branch 3 79/05/09 1p

--7907050325 Forwards 790427 memo re addl faults found in main dam site  
VASSALLO, D B Assistant Director for Light Water Reactors  
79/05/08 1p

7907130507 Submits corrections for NRC proposed findings  
REIB, E J Branch 3 79/05/17 1p

## DOCKETED ITEMS

7907060052 CP & L reply to NRC 790510 proposed findings of fact & conclusions of law Position expressed in applicant 790417 proposed findings of fact & conclusion of law in form of supplemental initial decision Certificate of Svc encl  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Troubridge 79/05/22 14pp

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of material fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907160269 Forwards JA Jones 790529 affidavit marked as Applicant Exhibit PP, per ASLB 790525 order  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Troubridge 79/06/12 6pp

---7907160276 CP & L revision to util 790417 proposed findings of fact & conclusion of law in form of supplemental initial decision Certificate of Svc encl  
TROWBRIDGE, G F Shaw, Pittman, Potts, & Troubridge 79/06/12 7pp

#### G Inspection reports, IE Bulletins & correspondence

7907020352 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110314 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907100150 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907050175 Ack receipt of IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No proprietary info  
HOWE, P W Carolina Power & Light Co 79/05/22 1p

---7907050182 Forwards IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/16 2pp,

---7907050189 IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance noted Major areas inspected steam generator mod, concrete placement & QA manual procedures for nondestructive examination  
BRADLEY, R D Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/22 9pp

7907110088 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/22 2pp

7907030090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907180153 Responds to IE Bulletin 78-120 Generic rept submitted by Chicago Bridge & Iron Co adequately represents data for facility reactor pressure vessels C-E will submit generic rept by midsummer 1979 & request 30-day review period  
MC DUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190190 Responds to IE Bulletin 79-04 No plans for use of Valan Engineering Corp swing check valves in Seismic Category I piping sys  
MC DUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190553 Responds to IE Bulletin 79-07 Methods employed in seismic analysis of safety-related piping investigated Computer code used, WECAN & WESTOYN, are documented in WCAP-B252, Revision I  
MC DUFFIE, M A Carolina Power & Light Co 79/05/29 2pp

7907110578 Ack receipt of IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790425-26, No proprietary info.  
HOWE, P W Carolina Power & Light Co 79/05/31 1p

---7907110569 Forwards IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790425-26 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/22 2pp

---7907110578 IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790425-26 No noncompliance noted Major areas inspected dust abatement, erosion control & silt loading  
CUNNINGHAM, A L, ANDREWS, D L, HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/21 3pp

7907200165 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907190148 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 1p

7907060043 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020194 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907240210 Responds to NRC 790521 ltr re violations noted in IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 Corrective actions procedures implemented & necessary repairs accomplished  
HOWE, P W Carolina Power & Light Co 79/06/12 4pp

---7907240215 Ack receipt of IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 No proprietary info  
HOWE, P W Carolina Power & Light Co 79/05/29 1p

---7907240219 Forwards IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 & notice of violation  
MURPHY, C E Region 2, Atlanta, Office of the Director 79/05/21 2pp

---7907240225 Notice of violation from Insp on 790410-13 & 17-18  
" " Region 2, Atlanta, Office of the Director G 79/05/17 2pp

---7907240227 IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 Noncompliance noted no accurate revolution counter found on concrete transport truck & no control of moisture found on powerblock fill  
HARRIS, J R, LENAHAN, J J, BRYANT, J C Region 2, Atlanta, Office of the Director 79/05/17 5pp

7907310204 Responds to IE Bulletin 79-09 No OE Type AK-2 circuit breakers planned for use in safety-related sys at facility  
MC DUFFIE, M A Carolina Power & Light Co. 79/06/14 1p

7907020375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120036 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907250090 Ack receipt of IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24 No proprietary info  
HOWE, P W Carolina Power & Light Co. 79/06/21 1p

7907310004 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 2pp

7907180281 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180427 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310229 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 1p

7907310362 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### DOCKET 90-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

##### A Application/construction stage documents & correspondence

7906260325 Summary of 790502 Affirmation Session 79-10 in Washington, DC re SECY-79-16A & SECY-79-20 Motion to reopen hearings on Shearon Harris plants was denied  
CHILK, S J Office of the Secretary of the Commission 79/05/04 1p

7907190140 Forwards review of criteria for previously placed fill QC of field moisture content determinations should be resolved. Recommends content be controlled to remain within spec limits  
JACKSON, R E Division of Systems Safety 79/06/06 5pp

7907030497 Forwards Tech Procedure TP-02 Revision 11 re special control procedures for fill supporting Category 1 pipes & electrical conduits  
MCUFFIE, M A Carolina Power & Light Co 79/06/28 1p

--7907030500 Tech Procedure TP-02 re soil control program, fill & backfill for plant grade, plant bldg & reservoir concrete structures  
\* Carolina Power & Light Co 79/06/28 32pp

7907260440 Forwards "Rept on Rock Fill Test Sections, Main Dam " Requests approval of rept as soon as possible  
MCUFFIE, M A Carolina Power & Light Co 79/07/18 1p

--7907260467 "Rept on Rock Fill Test Sections, Main Dam " \* Carolina Power & Light Co 79/07/18 B7pp

##### Q Adjudicatory correspondence

7907050320 Forwards 790508 Board notification re addl faults found in main dam area  
REIS, E J Branch 3 79/05/09 1p

--7907050325 Forwards 790427 memo re addl faults found in main dam site  
VABBALLO, D B Assistant Director for Light Water Reactors  
79/05/08 1p

7907130507 Submits corrections for NRC proposed findings  
REIS, E J Branch 3 79/05/17 1p

7907060052 CP&L reply to NRC 790510 proposed findings of fact & conclusions of law Position expressed in applicant 790417 proposed findings of fact & conclusion of law in form of supplemental initial decision Certificate of Svc encl  
TROWBRIDGE, O F Shaw, Pittman, Potts, & Trowbridge 79/05/22 14pp

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907160269 Forwards Exhibit PP, JA Jones 790529 affidavit per 790525 order & revisions to Carolina Power & Light 790612 revisions to proposed findings of fact & conclusion of law in form of supplemental initial decision  
TROWBRIDGE, O F Shaw, Pittman, Potts, & Trowbridge 79/06/12 6pp

--7907160276 Carolina Power & Light revision to 790417 proposed findings of fact & conclusion of law in form of supplemental initial decision, Certificate of Svc encl  
TROWBRIDGE, O F Shaw, Pittman, Potts, & Trowbridge 79/06/12 7pp.

7907190617 NRC revision to proposed findings of fact reflecting CP & L mgt changes, per applicant 790518 ltr & JA Jones  
790607 affidavit Certificate of Svc encl  
REIS, E J Branch 3 79/06/18 4pp

##### Q Inspection reports, IE Bulletins & correspondence

7907020352 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1 " O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110314 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907100150 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907050175 Ack receipt of IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance info  
HOME, P W Carolina Power & Light Co 79/05/22 1p

--7907050182 Forwards IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/16 2pp

--7907050189 IE Insp Repts 50-400/79-08, 50-401/79-08, 50-402/79-07 & 50-403/79-07 on 790423-27 No noncompliance noted Major areas inspected steam generator mod, concrete placement & QA manual procedures for nondestructive examination  
BRADLEY, R D Region 2, Atlanta, Office of the Director  
79/05/22 5pp

7907110088 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 2pp

7907030090 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907180153 Responds to IE Bulletin 78-1PB Generic rept submitted by Chicago Bridge & Iron Co adequately represents data for facility reactor pressure vessels C-E will submit generic rept by mid summer 1979 & request 30-day review period  
MCUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190190 Responds to IE Bulletin 79-04 No plans for use of Velan Engineering Corp swing check valves in Seismic Category 1 piping sys  
MCUFFIE, M A Carolina Power & Light Co 79/05/29 1p

7907190553 Responds to IE Bulletin 79-07 Methods employed in seismic analysis of safety related piping investigated Computer coder used, MECAN & WESTOYN are documented in WCAP-B232, Revision 1  
MCUFFIE, M A Carolina Power & Light Co 79/05/29 2pp

7907110578 Ack receipt of IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790423-26 No noncompliance info  
HOME, P W Carolina Power & Light Co 79/05/31 1p

--7907110589 Forwards IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790423-26 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/22 2pp

--7907110598 IE Insp Repts 50-400/79-09, 50-401/79-09, 50-402/79-08 & 50-403/79-08 on 790423-26 No noncompliance noted Major areas inspected dust abatement, erosion control & silt loading  
CUNNINGHAM, A L Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/21 3pp

7907200165 Forwards IE Bulletin 79-12, "Short Period Scrams at BHR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190148 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASDC Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 1p

7907060043 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020194 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907240210 Responds to NRC 790521 ltr re violations noted in IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06  
Corrective actions procedures implemented & necessary repairs accomplished  
HOWE, P W Carolina Power & Light Co 79/06/12 4pp

--7907240215 Ack receipt of IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18  
No proprietary info  
HOWE, P W Carolina Power & Light Co 79/05/27 1p

--7907240219 Forwards IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 & notice of violation  
MURPHY, C E Region 2, Atlanta, Office of the Director  
79/05/21 2pp

--7907240225 Notice of violation from insp on 790410-13 & 17-18  
\* Region 2, Atlanta, Office of the Director 79/05/17 2pp

--7907240227 IE Insp Repts 50-400/79-07, 50-401/79-07, 50-402/79-06 & 50-403/79-06 on 790410-13 & 17-18 Noncompliance noted  
no accurate revolution counter found on concrete transport truck & no control of moisture found on powerblock fill  
HARRIS, J R Region 2, Atlanta, Office of the Director  
79/05/17 5pp

7907310204 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers planned for use in safety-related sys at facility  
MCDOUFFIE, M A Carolina Power & Light Co 79/06/14 1p

7907020375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p.

7907120036 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907250090 Ack receipt of IE Insp Repts 50-400/79-11, 50-401/79-11, 50-402/79-10 & 50-403/79-10 on 790523-24 No proprietary info  
HOWE, P W Carolina Power & Light Co 79/06/21 1p.

7907310004 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180281 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp.

7907180427 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310229 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 1p

7907310368 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/11 1p

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

7907310468 Responds to 790508, 17 & 30 ltrs re util positions, in response to Reg Guides 1.1, 1.1.1, 1.1.1.1 & 1.1.2.0 No further response will be forwarded until submittal of FSAR, unless design appears to be in conflict w/NRC position  
VASSALLO, D B Assistant Director for Light Water Reactors  
79/06/19 2pp

J Insurance & indemnity information

7907130315 Forwards Endorsements 17-19 to MAELU Policy MF-96  
KELLY, P J Johnson & Higgins Insurance 79/07/09 4PP

Q Inspection reports, IE Bulletins & correspondence

7907020336 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI - Suppl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110344 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907110721 Forwards IE Insp Repts 50-339/79-24, 50-404/79-02 & 50-405/79-02 on 790417-19 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/08 2pp

--7907110743 IE Insp Repts 50-339/79-24, 50-404/79-02 & 50-405/79-02 on 790417-19 No noncompliance noted Major areas inspected  
GA procedures, work activities & records for extended const delay & hydraulic snubber installation  
AND, W P, BRYANT, J C Region 2, Atlanta, Office of the Director  
79/05/07 5pp

7907020477 Responds to IE Bulletins 78-12, 78-12A & 78-12B re atypical weld matl in reactor pressure vessel welds Investigation indicates matl not in use  
BROWN, S C Virginia Electric & Power Co 79/05/17 1p

7907100222 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907110127 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 2pp

7907100183 Responds to IE Bulletin 79-04 No Valan Engineering Corp swing check valves in use  
BROWN, S C Virginia Electric & Power Co 79/05/24 1p

7907100206 Responds to IE Bulletin 79-07 Discusses computer codes & programs used by B&W & B&W in seismic analysis of safety-related piping  
BROWN, S C Virginia Electric & Power Co 79/05/24 2pp

7907030114 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907200223 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190209 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASDC Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp.

7907060069 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020233 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p



7907190347 Responds to IE Bulletin 79-03 Interim rept reveals that only one single fitting was made by Yongstown Welding & Engineering Co Final rept expected 790711  
BROWN, S C Virginia Electric & Power Co 79/06/11 3pp

7907020401 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120142 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310046 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180340 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180446 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310389 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### S Reportable occurrences, LERs & related correspondence

7907050360 Final rept re potential deficiency in east wing wall of circulating water intake structure Final design mods outlined will result in sys capable of accommodating all loading combinations required for seismic stability  
BROWN, S C Virginia Electric & Power Co 79/06/29 2pp

#### DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

#### A Application/construction stage documents & correspondence

7907310468 Responds to 790508, 17 & 30 ltrs re util positions, in response to Reg Guides 1.1.1 55, 1.1.1 & 1.1.20 No further response will be forwarded until submittal of FSAR, unless design appears to be in conflict w/NRC position  
VASSALLO, D B Assistant Director for Light Water Reactors  
79/06/19 2pp

#### J Insurance & indemnity information

7907130315 Forwards Endorsements 17, 18 & 19 to MAELU Policy MF-96  
KELLY, P J Johnson & Higgins Insurance 79/07/09 4pp

#### Q Inspection reports, IE Bulletins & correspondence

7907020336 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110344 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/03/07 2pp

7907110721 Forwards IE Insp Repts 50-339/79-24, 50-404/79-02 & 50-405/79-02 on 790417-19 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/08 2pp

--7907110743 IE Insp Repts 50-339/79-24, 50-404/79-02 & 50-405/79-02 on 790417-19 No noncompliance noted, Major areas inspected: QA procedures, work activities & records for extended const delay & hydraulic snubber installation  
ANDRUS, P C Region 2, Atlanta, Office of the Director  
79/05/07 3pp

7907020477 Responds to IE Bulletins 78-12, 78-12A & 78-12B re atypical weld matl in reactor pressure vessel welds. Investigation indicates matl not in use.  
BROWN, S C Virginia Electric & Power Co. 79/05/17 1p

7907100222 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907110127 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 2pp

7907100183 Responds to IE Bulletin 79-04 No Velan Engineering Corp swing check valves in use  
BROWN, S C Virginia Electric & Power Co 79/05/24 1p

7907100206 Responds to IE Bulletin 79-07 Discusses computer codes & programs used by B&W & S&W in seismic analysis of safety-related piping  
BROWN, S C Virginia Electric & Power Co 79/05/24 2pp

7907030114 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907200223 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190209 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASQC Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060069 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020233 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907190347 Responds to IE Bulletin 79-03 Interim rept reveals that only one single fitting was made by Yongstown Welding & Engineering Co Final rept expected 790711  
BROWN, S C Virginia Electric & Power Co 79/06/11 3pp

7907020401 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120142 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310046 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping, " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180340 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180446 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310389 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### B Reportable occurrences, LERs & related correspondence

7907050360 Final rept re potential deficiency in east wing wall of circulating water intake structure Final design mods outlined will result in sys capable of accommodating all loading combinations required for seismic stability.  
BROWN, S C Virginia Electric & Power Co 79/06/29 2pp

## DOCKETED ITEMS

## DOCKET 50-406 YUSKEGEE INST RESEARCH REACTOR

## G Inspection reports, IE Bulletins &amp; correspondence

7907100087 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 1p

7907230412 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

7907240470 Forwards IE Info Notice 79-18, "Skylab Reentry" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/06 1p

## DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

## G Inspection reports, IE Bulletins &amp; correspondence

7907100263 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/18 1p

7907020028 Forwards IE Circular 79-09, "Occurrence of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

7907230514 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/22 1p

## DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

## F Security, medical, emergency &amp; fire protection plans

7907180846 Forwards discussion of consultant rept re evaluation of fire protection program, including valve supervision, ventilation & hose testing  
LANIAB, G Plant Systems Branch 79/06/04 4pp

7907260481 Forwards emergency plans for facility  
LINDER, F Dairyland Power Cooperative 79/06/29 2pp

--7907260486 Emergency plans for facility  
\* Dairyland Power Cooperative 79/05/22 157pp

## G Adjudicatory correspondence

7907300539 Ack receipt of petition to suspend License DPR-45  
Appropriate action on petition will be taken in reasonable time Forwards FR notice re request for action under 10 CFR 206  
BENTON, H R Office of Nuclear Reactor Regulation 79/06/19 1p

--7907300545 Notice of issuance & availability of AK Morse 790521 request for order to suspend License DPR-45  
BENTON, H R Office of Nuclear Reactor Regulation 79/06/19 1p

7907120639 Discusses AK Morse 790521 petition to suspend License DPR-45 Addressee's allegations re continuous venting of containment, analysis of liquefaction, leakage, pumpage, fuel failures & spent fuel Certificate of Svc encl  
HIESTAND, G S Morgan, Lewis & Dockius 79/07/03 9pp

## I Financial information

7907260576 Forwards Annual Financial Rept 1978  
LINDER, F Dairyland Power Cooperative 79/07/17 1p

--7907260578 Annual Financial Rept 1978  
\* Dairyland Power Cooperative 78/12/31 46pp

## O Advisory Committee on Reactor Safeguards reports &amp; correspondence

7907190842 Forwards FR notice of proposed ACRS meetings, providing notice of subcommittee meeting to be held on 790630 in Washington, DC  
\* Operating Reactors Branch 2 (Pre 790625). 79/05/24. 2pp

--7907190845 Notice of ACRS subcommittee meeting on 790630 to discuss overall condition of reactor & status of systematic evaluation  
HOYLE, J C ACRS - Advisory Committee on Reactor Safeguards 79/05/21 6pp

7907190129 Forwards proposed FR notice of 790630 ACRS Subcommittee on LaCrosse Nuclear Power Plant meeting in Washington, DC  
Requests publication in 790615 issue  
MCKINLEY, J C ACRS - Advisory Committee on Reactor Safeguards 79/06/08 1p

--7907190135 Proposed notice of 790630 ACRS Subcommittee on LaCrosse Nuclear Power Plant meeting in Washington, DC  
HOYLE, J C ACRS - Advisory Committee on Reactor Safeguards 79/06/08 2pp

7907270262 Forwards notice of ACRS Subcommittee on LACBWR 790630 meeting  
\* Operating Reactors Branch 2 (Pre 790625) 79/06/13 2pp

--7907270264 Notice of ACRS Subcommittee on LACBWR 790630 meeting in Washington, DC to review overall condition of plant & status of NRC systematic evaluation  
HOYLE, J C ACRS - Advisory Committee on Reactor Safeguards 79/06/11 2pp

## P Operating license stage documents &amp; correspondence

7906190135 Summary of 790417 meeting w/SEP owner's group in Bethesda, MD re technical details of site-specific spectra project  
LEVIN, H A Systematic Evaluation Programs Branch (Pre 790625) 79/04/30 4pp

7907260097 Discusses plans to install communication lines between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will forward operational & environ info  
KEPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907190796 Forwards draft evaluation of SEP Topic VIII-3 A station battery test requirement  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/05 4pp

7907310247 Requests addl info re SEP Topic VI-1, "Organic Matls & Post-Accident Chemistry" Forwards list of info needed  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/06 3pp

7907110647 Forwards Category 2 & 3 regulatory positions to be addressed in SEP Reg Guide 1 114 encl  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/11 7pp

7907280181 Requests listing of alarms & voltage monitoring devices available to provide operability status indication to complete evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation"  
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/06/18 2pp

7907310534 Notifies that 790511 application for license amend requires Class III fee  
DIOGB, R M License Fee Management Branch 79/06/22 1p

7907020177 Forwards draft Tech Specs for amend to License DPR-45, re irradiated fuel storage & handling of heavy objects above spent fuel pool & containment isolation during cask handling, in response to NRC 790614, 21 & 22 requests  
LINDER, F Dairyland Power Cooperative 79/06/26 15pp

7907060210 Forwards current HI pollution discharge elimination sys permits written for common discharge of cooling water w/adjoining 350 MW coal-fired facility  
DELUICHE, P Dairyland Power Cooperative 79/06/28 19pp

790710608 Forwards procurement bid response & manufacturer drawings re containment ventilation dampers  
SHIMSHAK, R E Dairyland Power Cooperative 79/07/05 7pp

7907110535 Forwards 790320 "Review of Liquefaction Potential, LACBWR Near Genoa, Vernon County, WI," prepared by Dames & Moore Includes geotechnical investigations, waterways station rept & summary of 790209 meeting w/NRC  
LINDER, F Dairyland Power Cooperative 79/07/06 1p

--7907110539 "Review of Liquefaction Potential, LACBWR Near Genoa, Vernon County, WI," prepared by Dames & Moore includes geotechnical investigations, waterways station report & summary of 790209 meeting w/NRC  
\* Dairyland Power Cooperative 79/03/20 43pp

7907170043 Notifies of compliance w/Reg Guide 1.114, Revision 1, submitted in NRC 790611 ltr Operators in control area have unobstructed view of & access to operational control panels  
LINDER, F Dairyland Power Cooperative 79/07/06 1p

7907170018 Forwards complete set of calculations & results of reanalysis of spent fuel shipping cask drop accident w/pool water at 680-foot level  
LINDER, F Dairyland Power Cooperative 79/07/11 39pp

7907190580 Submits list of alarms & monitoring devices, in response to Topic VIII-3 B Forwards request for add'l info  
LINDER, F Dairyland Power Cooperative 79/07/11 2pp

7907300388 Submits complete set of detailed calculations, including summary of results of reanalysis of spent fuel shipping cask drop accident w/pool water at 680-ft elevation, as followup to util 790626 ltr  
LINDER, F Dairyland Power Cooperative 79/07/11 39pp

7907260788 Responds to request for clarification re amount of B-10 in poison mat'l to be installed in high density fuel racks  
LINDER, F Dairyland Power Cooperative 79/07/20 2pp

#### Q Inspection reports, IE Bulletins & correspondence

7907020454 Responds to Action Item 11 Determines that no mod to current Tech Specs are necessary Authorization for response to be submitted one day beyond 30-day reporting period granted to J Farlyn by K Ridgway on 790518  
LINDER, F Dairyland Power Cooperative 79/05/18 2pp

7907090473 Responds to IE Bulletin 79-10 re qualification training program statistics Lists operators attending lectures  
LINDER, F Dairyland Power Cooperative 79/05/21 4pp

7907050005 Forwards response to Question 7c of IE Bulletin 79-08  
LINDER, F Dairyland Power Cooperative 79/05/23 2pp

7907110385 Forwards supplemental info in response to IE Bulletin 79-07 re seismic analysis of safety-related piping Seismic analysis performed per Reg Guide 1.92 & all three directions of earthquakes applied simultaneously  
LINDER, F Dairyland Power Cooperative 79/05/24 3pp

7907240187 Forwards IE Insp Rept 50-409/79-11 on 790515-17 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/29 2pp

--7907240191 IE Insp Rept 50-409/79-11 on 790515-17 No noncompliance noted Major areas inspected performance of containment integrated leak rate test  
REYES, L A Region 3, Chicago, Office of the Director  
STREETER, J F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/24 5pp

7907200312 Forwards IE Bulletin 79-12, "Short Period Bcrans at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907090274 Responds to IE Bulletin 79-11 Westinghouse Type DB-30 & DB-75 circuit breakers not used in safety-related or other electrical circuits  
LINDER, F Dairyland Power Cooperative 79/06/05 1p

7907250270 Forwards IE Insp Rept 50-409/79-09 on 790511 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/06/05 2pp

--7907250282 IE Insp Rept 50-409/79-09 on 790511 No noncompliance noted Major areas inspected observation of emergency drill, including accident assessment, license response, offsite agency response & drill critique  
AKELSON, W L., EBBIO, T H Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/25, 4pp.

7907260252 Forwards IE Insp Rept 50-409/79-10 on 790501-04 No noncompliance noted  
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch, 79/06/05 2pp

--7907260264 IE Insp Rept 50-409/79-10 on 790501-04 & 21-24 No noncompliance noted Major areas inspected licensee activities in response to IE Bulletin 79-08 re operability & availability of engineering safety features  
RIDGWAY, K R., BOYD, D C Region 3, Chicago, Office of the Director 79/05/31 6pp

7907190249 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240254 Forwards IE Info Notice 79-13, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060907 Advises that IE Info Notice 79-13, "Deficient Procedures" forwarded to listed utils  
FAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020424 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120227 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907080521 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907130117 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060311 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Mat'l " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907180408 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130265 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907240091 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/06 1p

7907310332 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310408 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260178 Notifies that written responses to IE Bulletin 79-13, Suppl 1, should be directed to IE Div of Reactor Const Insp.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p.

7907240359 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Boreated Water Sys at PWR Plants." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

#### R Periodic operating reports & related correspondence

7907180519 Forwards monthly operating report for June 1979.  
LINDER, F Dairyland Power Cooperative 79/07/12 1p

## DOCKETED ITEMS

--7907180520 Monthly operating rept for June 1979  
PARKYN, J Dairyland Power Cooperative 79/07/04 9pp

S Reportable occurrences, LERs & related correspondence

7907060326 Forwards LER 79-011/03L-0  
LINDBER, F Dairyland Power Cooperative 79/06/27 2pp

--7907060330 LER 79-011/03L-0 on 790601 upscale scram setpoint on power range nuclear instrument Channel & exceeded 120% limit of rated thermal power by 1.8% caused by setpoint drift of undetermined origin Scram setpoint reset  
PAPWORTH, L G Dairyland Power Cooperative 79/06/27 1p

T Hearing transcripts on non-antitrust matters

7907120321 Transcript of 790630 meeting of ACRS Subcommittee on LaCrosse BWR in Washington, DC Pp 1-213 Documentation encl  
KERR, W, LAWROSKI, S, SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards 79/06/30 234pp

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7907100690 Summary of 790424 meeting w/Niagara Mohawk Corp, S&W, Dams & Moore, NY State Geological Survey & US Army Corps of Engineers in Bethesda, MD to provide opportunity for util to discuss results of geological investigation  
MCMULLEN, R B Geosciences Branch 79/05/15 16pp

7907060339 Forwards info re detailed plan for const of revetment-ditch, in response to 771205 request Oversized drawing encl  
RHODE, G V Niagara Mohawk Power Corp 79/06/28 8pp

7907300171 Notification of 790717-18 meeting w/Mark II owners group & OE in Lebanon, NH to discuss Mark II Pool Dynamic Programs  
ANDERSON, C J Containment Systems Branch 79/07/03 12pp

7907250351 Corrects ref in 790628 ltr re acceptance criteria for volumetric examination of longitudinal weld in drywell floor downcomers Should have been Article NC-5000 of ASME Section III, 1977 Edition through Summer 1977 Addendum  
RHODE, G K Niagara Mohawk Power Corp 79/07/16 1p

G Inspection reports, IE Bulletins & correspondence

7907060394 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907090094 Responds to IE Bulletin 79-10 Submits requalification training program statistics  
LEONARD, J D Power Authority State of New York 79/05/22 3pp

7907030046 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907020491 Responds to IE Bulletin 79-07 re seismic analysis of computer codes Computer codes used at facility do not employ methods described in bulletin  
BARTLETT, J Niagara Mohawk Power Corp 79/05/30 1p

7907200121 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190071 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060110 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p.

7907200048 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907300364 Ack receipt of 790601 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/79-02  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/18 1p

--7907300372 Responds to NRC 790426 ltr re violations noted in IE Insp Rept 50-410/79-02 Corrective actions welds will undergo ultrasonic, radiographic, liquid penetrant or magnetic testing  
RHODE, G K Niagara Mohawk Power Corp 79/06/01 2pp

--7907300374 Forwards IE Insp Rept 50-410/79-02 on 790320-23 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/26 2pp

--7907300378 Notice of violation from insp on 790320-23  
\* Region 1, Philadelphia, Office of the Director 79/03/23 1p

--7907300385 IE Insp Rept 50-410/79-02 on 790320-23 Noncompliance noted Failure to comply w/code requirements re welds  
NARROW, L, MCGAUGHY, R W, WALTON, G A Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/24 12pp

7907110375 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230683 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120515 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100316 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100422 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907050373 Responds to IE Bulletin 79-03 Abnormal indications of porosity have been discovered in Youngtown 130 drywell floor downcomers Will use criteria of ASME III, 1977 Addendum, Paragraph NC-2553 NRC approval requested by 790727  
RHODE, G K Niagara Mohawk Power Corp 79/06/28 2pp

7907100505 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180788 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270344 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310313 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

7907160252 Forwards IE Insp Rept 50-412/79-04 on 790409-10 No noncompliance noted  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/07 2pp

--7907160258 IE Insp Rept 50-412/79-04 on 790409-10 No noncompliance noted Major areas inspected const activities in progress  
FOLSON, S. A. , NARROW, L. , MCOAUGHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/03 3pp

7907050398 Responds to IE Bulletin 79-03 No welded type ASME BA-312 Type 304 pipe mfg by Youngstown Welding & Engineering Co used or planned for use in safety-related sys  
WOOLEVER, E. J. Duquesne Light Co 79/05/17 1p

7907060381 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907030027 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200098 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190047 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060092 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020044 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907230040 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/79-03  
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/18 1p

--7907230452 Responds to NRC 790417 ltr re violation noted in IE Insp Rept 50-412/79-03 Corrective actions memo issued on 790313 instructing GC supervisor, completed welds insp & videotape training course modified  
WOOLEVER, E. J. Duquesne Light Co 79/05/17 3pp

--7907230453 Forwards IE Insp Rept 50-412/79-03 on 790306-09 & notice of violation  
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/17 2pp

--7907230707 Notice of violation from insp on 790306-09  
\* Region 1, Philadelphia, Office of the Director 79/04/17 1p

--7907230727 IE Insp Rept 50-412/79-03 Noncompliance noted failure to provide proper weld slopes for piping diameter transitions  
FOLSON, S. A. Region 1, Philadelphia, Office of the Director 79/04/12 6pp

7907110367 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230665 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Belts " Action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120489 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100305 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100415 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907100497 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180760 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907170162 Notifies of action taken re deficiency reported at waste disposal concrete area during Insp 79-02 High bays dikes have been restored & waste water has been treated Will achieve compliance by 790806  
WOOLEVER, E. J. Duquesne Light Co 79/07/03 2pp

7907270331 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310494 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/07/16 1p

8 Reportable occurrences, LERs & related correspondence

7907180529 Requests extension of time to 790810 for submittal of final Significant Deficiency Rept 79-01 re stop work directive for Bingham-Willamette Co  
WOOLEVER, E. J. Duquesne Light Co 79/07/13 1p

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

0 Inspection reports, IE Bulletins & correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl "  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907020503 Discusses schedule of response to IE Bulletins 78-12, 12A, & 12B C-E to submit generic rept directly to NRC by 790629 Wastehouse submittal re Rotterdam vessel expected in July 1979  
DAIL, L. C. Duke Power Co 79/05/16 1p

7907110643 Forwards IE Insp Rept 50-413/79-08 & 50-414/79-08 on 790501-04 No noncompliance noted  
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/17 2pp

--7907110657 IE Insp Rept 50-413/79-08 & 50-414/79-08 on 790501-04 No noncompliance noted Major areas inspected containment penetrations procedures, work activities & records & containment dome concrete work activities  
ANG, W. P. Region 2, Atlanta, Office of the Director BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/16 4pp

7907050151 Ack receipt of IE Insp Repts 50-413/79-07 & 50-414/79-07 on 790423-26. No proprietary info  
DAIL, L. C. Duke Power Co 79/05/18 1p

--7907050154 Forwards IE Insp Repts 50-413/79-07 & 50-414/79-07 on 790423-26 No noncompliance noted.  
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 2pp

--7907050157 IE Insp Repts 50-413/79-07 & 50-414/79-07 on 790423-26 No noncompliance noted Major areas inspected structural concrete, concrete expansion anchors, safety-related components & pipe support & restraint sys.  
COMPTON, R. M. Region 2, Atlanta, Office of the Director BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 4pp.

## DOCKETED ITEMS

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907190667 Ack receipt of IE Insp Repts 50-413/79-08 & 50-414/79-08 No proprietary info  
DAIL, L C Duke Power Co 79/05/24 1p

7907190122 Responds to IE Bulletin 79-07 re use of particular computer programs SUPERPIPE used on all piping analyses except analysis performed by Westinghouse  
DAIL, L C Duke Power Co 79/05/29 2pp

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

790710555 Ack receipt of IE Insp Repts 50-413/79-09 & 50-414/79-09 on 790508-11 No proprietary info  
DAIL, L C Duke Power Co 79/06/04 1p

--7907110563 Forwards IE Insp Repts 50-413/79-09 & 50-414/79-09 on 790508-11 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

--7907110568 IE Insp Repts 50-413/79-09 & 50-414/79-09 on 790508-0511 No noncompliance noted Major areas inspected electrical work & work activities, quality records & instrumentation storage  
GIBBONS, T D, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 3pp

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Balenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060048 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907190120 Ack receipt of 790525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-06 & 50-414/79-06  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/07 1p

--7907190132 Responds to NRC 790502 ltr re violations noted in IE Insp Repts 50-413/79-06 & 50-414/79-06 Corrective actions exterior surface dome pour number 32 reinspected & repaired & area cleared of debris  
DAIL, L C Duke Power Co 79/05/23 2pp

--7907190137 Forwards IE Insp Repts 50-413/79-06 & 50-414/79-06 on 790403-04 & notice of violation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/02 2pp

--7907190143 Notice of violation from insp on 790403-04  
\* Region 2, Atlanta, Office of the Director 79/04/30 4pp

--7907190149 IE Insp Repts 50-413/79-06 & 50-414/79-06 on 790403-04 Noncompliance noted unacceptable exterior surface dome pour  
ANG, W P Region 2, Atlanta, Office of the Director BRYANT, J C  
Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/02 1p

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/11 1p

7907020377 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/02 2pp

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20 2pp

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp

#### DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

#### G Inspection reports, IE Bulletins & correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07, 2pp.

7907020503 Discusses schedule of response to IE Bulletins 78-12, 12A, & 12B C-E to submit generic rept directly to NRC by 790629  
Westinghouse submittal re Rotterdam vessel expected in July 1979  
DAIL, L C Duke Power Co 79/05/16 1p

7907110643 Forwards IE Insp Rept 50-413/79-08 & 50-414/79-08 on 790501-04 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/17 2pp

--7907110657 IE Insp Rept 50-413/79-08 & 50-414/79-08 on 790501-04 No noncompliance noted Major areas inspected containment penetrations procedures, work activities & records & containment dome concrete work activities  
ANG, W P Region 2, Atlanta, Office of the Director BRYANT, J C  
Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/16 4pp

7907050151 Ack receipt of IE Insp Repts 50-413/79-07 & 50-414/79-07 on 790423-26. No proprietary info  
DAIL, L C Duke Power Co 79/05/18, 1p

--7907050154 Forwards IE Insp Repts 50-413/79-07 & 50-414/79-07 on 790423-26 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 2pp

--7907080157 IE Insp Repts 50-413/79-07 & 50-414/79-07 on 790423-26 No noncompliance noted Major areas inspected structural concrete, concrete expansion anchors, safety-related components & pipe support & restraint sys  
COMPTON, R M Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 4pp

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907190667 Ack receipt of IE Insp Repts 50-413/79-08 & 50-414/79-08 No proprietary info  
DAIL, L C Duke Power Co 79/05/24 1p

7907190122 Responds to IE Bulletin 79-07 re use of particular computer programs SUPERPIPE used on all piping analyses except analysis performed by Westinghouse  
DAIL, L C Duke Power Co 79/05/29 2pp

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907110555 Ack receipt of IE Insp Repts 50-413/79-09 & 50-414/79-09 on 790508-11 No proprietary info  
DAIL, L C Duke Power Co 79/06/04 1p

--7907110563 Forwards IE Insp Repts 50-413/79-09 & 50-414/79-09 on 790508-11 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 2pp

--7907110568 IE Insp Repts 50-413/79-09 & 50-414/79-09 on 790508-0811 No noncompliance noted Major areas inspected electrical work & work activities, quality records & instrumentation storage  
GIBBONS, T D, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/24 3pp

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060048 Forwards IE Info Notice 79-18, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907190120 Ack receipt of 790525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-06 & 50-414/79-06  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/07 1p

--7907190132 Responds to NRC 790502 ltr re violations noted in IE Insp Repts 50-413/79-06 & 50-414/79-06 Corrective actions exterior surface dome pour number 32 reinspected & repaired & area cleared of debris  
DAIL, L C Duke Power Co 79/05/25 2pp

--7907190137 Forwards IE Insp Repts 50-413/79-06 & 50-414/79-06 on 790403-06 & notice of violation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/02 2pp

--7907190143 Notice of violation from insp on 790403-06.  
\* Region 2, Atlanta, Office of the Director 79/04/30 4pp

--7907190149 IE Insp Repts 50-413/79-06 & 50-414/79-06 on 790403-06 Noncompliance noted unacceptable exterior surface dome pour  
AND, W P Region 2, Atlanta, Office of the Director BRYANT, J C, Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/05/02 1p

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020379 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20 2pp

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp

#### DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907130484 Opposes licensing delay for plant Delay would be costly & could result in energy shortage in area  
STENNIS, J C Senate 79/05/25 1p

7907060186 Responds to 790302 ltr re QA requirements for Authorized Insp Agency  
HAAS, W P Quality Assurance Branch 79/06/01 2pp

7907050346 Advises that House of Representatives has provided funds for addl personnel for OL license review Expects Senate concurrence  
LUTKEN, D C Mississippi Power & Light Co 79/06/25 1p

7907060191 Forwards responses to FBAR Questions 231, 2 3 4 7 8 & 9 in support of Amend 31 to application for license Affidavit for withholding encl Responses withheld (ref 10CFR2 790)  
DALE, L F Mississippi Power & Light Co 79/06/29 1p

7907200390 Requests deletion of water stage monitoring from environ monitoring program. Analysis shows correlation between recorder stage & surface water quality measurements can be rejected within 95 % confidence  
DALE, L F Mississippi Power & Light Co 79/07/10 1p

#### Q. Adjudicatory correspondence

7907030298 Ack receipt of util 790619 ltr sent to Ofc of Nuclear Reactor Regulation Municipal Energy Agency of MS disputes many allegations contained in ltr Requests receipt of new info  
MCDIARMID, R C Spiegel & McDiarmid 79/06/21 1p

## DOCKETED ITEMS

H General correspondence

7907250256 Forwards Affidavit of Svc re distribution of Amend 31, in accordance w/Encl 1 of NRC 780527 ltr  
DALE, L F Mississippi Power & Light Co 79/07/11 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

7907050321 Forwards Amend 31 to application for OL, consisting of responses to first round questions for FSAR  
STAMPLEY, M L Mississippi Power & Light Co 79/06/29 4pp

--7907050325 Amend 31 to FSAR  
\* Mississippi Power & Light Co 79/06/29, 1050pp

M Antitrust correspondence

7907110307 Forwards petition on behalf of Municipal Energy Agency of MS requesting enforcement of antitrust conditions of facility license FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/11 1p

--7907110320 Notice of 790529 filing of petition by Municipal Energy Agency of MS requesting proceedings to enforce antitrust conditions of facility license  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/11 1p

--7907110328 Forwards petition by Municipal Energy Agency of MS requesting that NRC commence proceedings, per 10CFR2.202, to require util to comply w/antitrust conditions of facility license  
MCDIARMID, R C Spiegel & McDiarmid 79/05/29 8pp

--7907110337 Confirms inquiry re status & interpretation of antitrust license conditions in Proceeding 40-415-57  
MCDIARMID, R C Spiegel & McDiarmid 78/09/22 7pp

--7907110343 City of Clarksdale, MS protests MS Power & Light svc schedule, petitions to intervene & requests 1-day suspension & consolidation Correspondence & Certificate of Svc encl  
MCDIARMID, R C, MORRISON, J N Spiegel & McDiarmid 78/09/19 130pp

7907050299 Reiterates Municipal Energy Agency of MS opposition to allegations made by atty for MS Power & Light re util 790110 & 0312 ltrs Supporting documentation  
MCDIARMID, R C Spiegel & McDiarmid 79/06/29 3pp

G Inspection reports, IE Bulletins & correspondence

7907020368 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1 - Suppl 1"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110331 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 1p

7907100202 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907060361 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 1p

7907030102 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/05/29 1p.

7907100332 Responds to IE Bulletin 79-07 None of methods listed were used by Bechtel or GE for seismic analysis of safety-related piping.  
DALE, L F Mississippi Power & Light Co. 79/05/29, 3pp

7907100557 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg By Velan Engineering Corp " No swing check valves mfg by Velan Engineering used.  
DALE, L F Mississippi Power & Light Co 79/05/29, 1p.

7907200200 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907190180 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASGO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp

7907060060 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020214 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11, 1p

7907190287 Ack receipt of 790601 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-416/79-07 & 50-417/79-07  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/14 1p

--7907190303 Responds to NRC 790514 ltr re violation noted in IE Insp Repts 50-416/79-07 & 50-417/79-07 Corrective actions design drawing issued to reflect change & all Unit 1 field engineers re-instructed in requirement  
DALE, L F Mississippi Power & Light Co 79/06/01 1p

--7907190307 Forwards IE Insp Repts 50-416/79-07 & 50-417/79-07 on 790403-06 & notice of violation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907190313 Notice of violation from insp on 790403-06  
\* Region 2, Atlanta, Office of the Director 79/05/11 1p

--7907190319 IE Insp Repts 50-416/79-07 & 50-417/79-07 on 790403-06 Noncompliance noted failure to follow approved drawings during installation welding of safety-related structures  
BLAKE, J J Region 2, Atlanta, Office of the Director  
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/11 5pp

7907020389 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p.

7907120084 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907110024 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25, 2pp

7907110274 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/26 2pp

7907180315 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180439 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907100258 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/07/02, 1p.

7907100384 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 2pp



S Reportable occurrences, LERs & related correspondence

7907030490 Forwards Interim Rept 1 for Reportable Deficiency 79/10  
Final rept will be submitted by 791116  
DALE, L F Mississippi Power & Light Co 79/06/20 1p

--7907030493 Interim rept for Reportable Deficiency 79/10 on 790521  
problem identified as gross failure output function of  
master & slave trip units of Rosemount 510 trip calibr  
sys. Remedial action will be completed by 791116  
\* Mississippi Power & Light Co 79/06/20 2pp

7907090324 Advises of potential reportable deficiency submitted to  
JK Rausch on 790323 re circuit separation discrepancies in  
generation control complexes Final rept will be submitted by  
791020  
DALE, L F Mississippi Power & Light Co 79/06/20 1p

7907190523 Forwards Interim Deficiency Rept 1 re gross failure output  
function of trip units  
DALE, L F Mississippi Power & Light Co 79/06/20 1p

--7907190524 Interim Deficiency Rept 1 re problem w/gross failure output  
function of master & slave trip units Plans to submit final  
rept by 791116  
\* Mississippi Power & Light Co 79/06/20 2pp

U Congressional/Executive Correspondence

7907160086 Forwards 790605 telegram re status of license for facility  
Complains about rude treatment secretary received from  
NRC telephone operator  
HINSON, J House of Rep 79/06/11 1p

--7907160091 Requests action to expedite granting of license for  
facility  
HINSON, J House of Rep 79/06/05 1p

7907310122 Responds to 790605 ltr re delays in processing & issuance of  
OL for facilities As result of TMI accident, NRC resources  
have been diverted from previous work OL reviews suspended,  
since subj facilities do not qualify for priority treatment  
GOSBICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310136 Urges consideration of socio-economic impact of moratorium  
on issuance of OLs for facilities  
LIVINGSTON, R L House of Rep 79/05/29 1p

7907310202 Responds to 790605 ltr re delays in processing & issuance of  
OL for facilities As result of TMI accident, NRC resources  
have been diverted from previous work OL reviews suspended,  
since subj facilities do not qualify for priority treatment  
GOSBICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310211 Forwards D Lutken of MI Power & Light Co. 790524 telegram re  
impact of delay & subsequent issuance of OL for facilities &  
statement outlining safety of proposed plant Requests  
comments & info on subj  
COCHRAN, T B Senate 79/06/05 7pp

7907310244 Responds to 790606 ltr re delays in processing & issuance of  
OL for facilities As result of TMI accident, NRC resources  
have been diverted from previous work OL reviews suspended,  
since subj facilities do not qualify for priority treatment  
GOSBICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310253 Forwards JM Wyatt of LA Power & Light Co. 790525 ltr re  
impact of delay & subsequent issuance of OL for facilities  
Requests comments & info on subj.  
BREAUX, J House of Rep 79/06/06 3pp

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2A Application/construction stage documents & correspondence

7907130484 Opposes licensing delay for plant Delay would be costly &  
could result in energy shortage in area.  
STENNIS, J C Senate 79/05/25 1p

7907060185 Responds to 790302 ltr re QA requirements for Authorized  
Insp Agency  
HAASB, W P Quality Assurance Branch. 79/06/01 2pp

7907050346 Advises that House of Representatives has provided funds for  
addl personnel for OL license review. Expects Senate  
concurrence.  
LUTKEN, D C Mississippi Power & Light Co 79/06/25 1p

7907060191 Forwards responses to FSAR Questions 231, 234, 7, 8 & 9 in  
support of Amend 31 to application for license Affidavit  
for withholding encl Responses withheld (ref 10CFR2 790)  
DALE, L F Mississippi Power & Light Co 79/06/29 1p

7907200390 Requests deletion of water stage monitoring from environ  
monitoring program Analysis shows correlation between  
recorder stage & surface water quality measurements can be  
rejected within 95 % confidence  
DALE, L F Mississippi Power & Light Co 79/07/10 1p

O Adjudicatory correspondence

7907030298 Ack receipt of util 790619 ltr sent to Ofc of Nuclear  
Reactor Regulation Municipal Energy Agency of MS disputes  
many allegations contained in ltr Requests receipt of new  
info  
MCDIARMID, R C Spiegel & McDiarmid 79/06/21 1p

H General correspondence

7907250256 Forwards Affidavit of Svc re distribution of Amend 31,  
in accordance w/Encl 1 of NRC 780627 ltr  
DALE, L F Mississippi Power & Light Co 79/07/11 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

7907050321 Forwards Amend 31 to application for OL, consisting of  
responses to first round questions for FSAR  
BTAMPLEY, M L Mississippi Power & Light Co 79/06/29 4pp.

--7907050326 Amend 31 to FSAR  
\* Mississippi Power & Light Co 79/06/29 1050pp

M Antitrust correspondence

7907110307 Forwards petition on behalf of Municipal Energy Agency of MS  
requesting enforcement of antitrust conditions of facility  
license FR notice encl  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/11 1p

--7907110320 Notice of 790629 filing of petition by Municipal Energy  
Agency of MS requesting proceedings to enforce antitrust  
conditions of facility license  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/11 1p

--7907110328 Forwards petition by Municipal Energy Agency of MS  
requesting that NRC commence proceedings per 10CFR2 202, to  
require util to comply w/antitrust conditions of facility  
license  
MCDIARMID, R C Spiegel & McDiarmid. 79/05/29. 8pp.

--7907110337 Confirms inquiry re status & interpretation of antitrust  
license conditions in Proceeding 60-415-57  
MCDIARMID, R C Spiegel & McDiarmid 78/09/22 7pp.

--7907110343 City of Clarksdale, MS protests MS Power & Light svc  
schedule, petitions to intervene & requests 1-day  
suspension & consolidation Correspondence & Certificate of  
Svc encl.  
MCDIARMID, R C, HORWOOD, J N Spiegel & McDiarmid 78/09/15.  
130pp

7907050299 Reiterates Municipal Energy Agency of MS opposition to  
allegations made by atty for MS Power & Light re util 790110  
& 0312 ltrs Supporting documentation  
MCDIARMID, R C Spiegel & McDiarmid. 79/06/29 3pp

Q Inspection reports, IE Bulletins & correspondence

7907020368 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
TMI - Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/04/21. 2pp

7907110331 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07. 1p

7907100202 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/05/18. 2pp

## DOCKETED ITEMS

7907060361 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers For Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907030102 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 1p

7907190332 Responds to IE Bulletin 79-07 None of methods listed were used by Bechtel or GE for seismic analysis of safety-related piping  
DALE, L F Mississippi Power & Light Co 79/05/29 3pp

7907190557 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg By Velan Engineering Corp " No swing check valves mfg by Velan Engineering used  
DALE, L F Mississippi Power & Light Co 79/05/29 1p

7907200200 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190180 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060060 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020214 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907190287 Ack receipt of 790601 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-416/79-07 & 50-417/79-07  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/14 1p

--7907190303 Responds to NRC 790514 ltr re violation noted in IE Insp Repts 50-416/79-07 & 50-417/79-07 Corrective actions design drawing issued to reflect change & all Unit 1 field engineers re-instructed in requirement  
DALE, L F Mississippi Power & Light Co 79/06/01 1p

--7907190307 Forwards IE Insp Repts 50-416/79-07 & 50-417/79-07 on 790403-06 & notice of violation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907190313 Notice of violation from insp on 790403-06  
\* Region 2, Atlanta, Office of the Director 79/05/11 1p

--7907190319 IE Insp Repts 50-416/79-07 & 50-417/79-07 on 790403-06 Noncompliance noted failure to follow approved drawings during installation welding of safety-related structures  
BLAKE, J J Region 2, Atlanta, Office of the Director  
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/11 5pp

7907020389 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120084 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/21 1p.

7907310024 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp.

7907110274 Forwards IE Circular 79-10, "Pipe Fittings Mfg from Unacceptable Matl. " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/26 2pp

7907180315 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180439 Forwards IE Circular 79-12, "Potential Diesel Generator Turb charger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310258 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 1p

7907310384 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

#### S Reportable occurrences, LERs & related correspondence

7907030490 Forwards Interim Rept 1 for Reportable Deficiency 79/10 Final rept will be submitted by 791116  
DALE, L F Mississippi Power & Light Co 79/06/20 1p

--7907030493 Interim rept for Reportable Deficiency 79/10 on 790521 problem identified as gross failure output function of master & slave trip units of Rosemount 510 trip calibr sys Remedial action will be completed by 791116  
\* Mississippi Power & Light Co 79/06/20 2pp

7907090324 Advises of potential reportable deficiency submitted to JK Rausch on 790323 re circuit separation discrepancies in generation control complexes Final rept will be submitted by 791020  
DALE, L F Mississippi Power & Light Co 79/06/20 1p

7907190523 Forwards Interim Deficiency Rept 1 re gross failure output function of trip units  
DALE, L F Mississippi Power & Light Co 79/06/20 1p

--7907190524 Interim Deficiency Rept 1 re problem w/gross failure output function of master & slave trip units Plans to submit final rept by 791116  
\* Mississippi Power & Light Co 79/06/20 2pp

#### U. Congressional/Executive Correspondence

7907160086 Forwards 790605 telegram re status of license for facility  
Complains about rude treatment secretary received from NRC telephone operator  
HINSON, J House of Rep 79/06/11 1p

--7907160091 Requests action to expedite granting of license for facility  
HINSON, J House of Rep 79/06/09 1p

7907310122 Responds to 790605 ltr re delays in processing & issuance of OL for facilities As result of TMI accident, NRC resources have been diverted from previous work OL reviews suspended, since subj facilities do not qualify for priority treatment  
GOSBICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310136 Urges consideration of socio-economic impact of moratorium on issuance of OLs for facilities  
LIVINGSTON, R L House of Rep 79/05/29 1p

7907310202 Responds to 790605 ltr re delays in processing & issuance of OL for facilities As result of TMI accident, NRC resources have been diverted from previous work OL reviews suspended, since subj facilities do not qualify for priority treatment  
GOSBICK, L V Office of the Executive Director for Operations  
79/06/29 2pp

--7907310211 Forwards D Lutken, of MI Power & Light Co, 790524 telegram re impact of delay & subsequent issuance of OL for facilities & statement outlining safety of proposed plant Requests comments & info on subj  
COCHRAN, T B Senate 79/06/05 7pp

7907310244 Responds to 790605 ltr re delays in processing & issuance of OL for facilities As result of TMI accident, NRC resources have been diverted from previous work OL reviews suspended, since subj facilities do not qualify for priority treatment  
GOSBICK, L V Office of the Executive Director for Operations.  
79/06/29 2pp.

# DOCKETED ITEMS

235

--7907310253 Forwards JM Wyatt, of LA Power & Light Co, 790525 ltr re impact of delay & subsequent issuance of OL for facilities Requests comments & info on subj  
BREAUX, J House of Rep 79/06/06 3pp

## DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

### A Application/construction stage documents & correspondence

7907110223 Summary of 790515 meeting w/util & S&W in Bethesda, MD re fault in refueling water storage tank area  
JACKSON, R E Geosciences Branch 79/05/25 7pp

7907260737 Requests extension of time to 790813 to respond to NRC 790629 request for PWR licenses capabilities to anticipate, & respond to unusual incidents  
COUNSIL, W G Northeast Utilities 79/07/16 1p

### G Inspection reports, IE Bulletins & correspondence

7907050525 Forwards IE Insp Rept 50-423/79-02 on 790313-15 No noncompliance noted  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/24 2pp

--7907050527 IE Insp Rept 50-423/79-02 on 790313-15 No noncompliance noted Major areas inspected general site work activities  
TOTH, A D, CERNE, A C Region 1, Philadelphia, Office of the Director  
MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/20 10pp

7907110013 Forwards IE Insp Rept 50-423/79-03 on 790411-12 No noncompliance noted  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/15 2pp

--7907110015 IE Insp Rept 50-423/79-03 on 790411-12 No noncompliance noted Major areas inspected design bases documents re safety-related piping  
TOTH, A D Region 1, Philadelphia, Office of the Director  
MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/09 3pp

7907060392 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licenses action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907050160 Responds to IE Bulletin 78-128 re atypical weld matl in reactor pressure vessel C-E is performing requested search & will submit rept to NRC by 790608  
COUNSIL, W G Northeast Nuclear Energy Co (Northeast Utilities) 79/05/24 1p

7907030041 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907090385 Responds to IE Bulletin 79-04 No Valan swing check valves in use.  
COUNSIL, W G Northeast Nuclear Energy Co (Northeast Utilities) 79/05/30 1p

7907190090 Responds to IE Bulletin 79-07 No computer codes for S&W seismic analysis of safety-related piping use Item 1 methods Verification of NUPIPE 03/10 program version being addressed  
COUNSIL, W G Northeast Utilities 79/05/30 1p

7907190106 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers will be used in safety-related sys  
COUNSIL, W G Northeast Utilities 79/05/30 1p

7907200114 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190069 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of AECO Bolted Valves)." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/06/06, 1p.

7907060106 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020047 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907100473 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230681 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120507 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907060195 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100420 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907110027 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180779 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p.

7907270342 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310509 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

## DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

### A Application/construction stage documents & correspondence

7907030138 FOIA request for all documents relating to facility EIS & all projects covered by EIS  
FLACK, O Myer, Bowman, Stroup & Flack 79/06/01 2pp

7907030237 Responds to FOIA 790601 request for documents re facility projects covered by EIS List of available documents related to request encl  
FELTON, J M Division of Rules and Records 79/06/26 2pp

### G Adjudicatory correspondence

7907240341 Submits addl info for Georgians Against Nuclear Energy request for reconsideration of petition for revocation of CP Alleges petitioners were misrepresented, that NEPA stds were not followed & that circumstances have changed  
FLACK, O Myer, Bauman, Stroup & Flack. 79/07/17 21 pp

### H General correspondence

7907090416 Summary of 790522 meeting w/util & Region 2 personnel re insp & enforcement, enforcement history & QA/QC authority  
MURPHY, C E Region 2, Atlanta, Office of the Director. 79/05/25 3pp

### I Financial information

7907050357 Forwards Annual Financial Repts 1978 for QA Power Co & Southern Co  
WHITMER, C F Georgia Power Co 79/07/02 1p

--7907050234 Annual Financial Rep\* 1978  
\* The Southern Co 79/02/23 3pp

--7907050394 Annual Financial Rept 1978  
\* Georgia Power Co 79/01/31 34pp

u Inspection reports, IE Bulletins & correspondence  
-----

7907020242 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
THI - Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907120523 Forwards IE Insp Repts 50-424/79-06 & 50-425/79-06 on  
790418-20 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/05/02 2pp

--7907120533 IE Insp Repts 50-424/79-06 & 50-425/79-06 on 790418-20 No  
noncompliance noted Major areas inspected QC procedures,  
ultrasonic test examination of imbeds, piping contractor  
procedures & outstanding open items  
HUNT, M D, HERDT, A R Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/02 4pp

7907110329 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907100196 Forwards IE Circular 79-08, "Attempted Extortion - Lou  
Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907110105 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 2pp

7907100135 Responds to 790319 ltr re IE Bulletins 78-12, 12A & 12B  
Requests extension to 790629 for response due to C-E  
inability to file generic rept  
STAFFA, R W Georgia Power Co 79/05/24 1p

7907100173 Responds to IE Bulletin 79-07 Action Items 2 & 4 not  
applicable No methods specified in Item 1 are used in LEAP  
computer code for seismic analysis of safety-related piping  
STAFFA, R W Georgia Power Co 79/05/24 2pp

7907090411 Discusses meeting held in Atlanta, GA on 790522 Meeting was  
beneficial & has provided for better understanding of insp &  
enforcement issues  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/25 2pp

7907180163 Responds to IE Bulletin 79-04 No Velan swing check valves  
in use  
STAFFA, R W Georgia Power Co 79/05/25 1p

7907030098 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 2pp

7907090144 Responds to IE Bulletin 79-09 There are no GE Type AK-2  
circuit breakers in any safety-related sys at facility  
STAFFA, R W Georgia Power Co 79/05/29 1p

7907200198 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190173 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060059 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020211 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907240239 Ack receipt of 790607 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Repts 50-424/79-07 &  
50-425/79-07  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/06/18 1p

--7907240270 Responds to NRC 790521 ltr re violation noted in IE Insp  
Repts 50-424/79-07 & 50-425/79-07 Corrective actions OC  
inspectors given procedural instructions on motor shaft  
rotations  
STAFFA, R U Georgia Power Co 79/06/07 2pp

--7907240272 Forwards IE Insp Repts 50-424/79-07 & 50-425/79-07 on  
790425-27, notice of violation & notice of deviation  
MURPHY, C E Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/21 2pp

--7907240275 Notice of violation from insp on 790425-27  
\* Region 2, Atlanta, Office of the Director 79/05/17 1p

--7907240278 Notice of deviation from insp on 790425-27  
\* Region 2, Atlanta, Office of the Director 79/05/17 1p

--7907240285 IE Insp Repts 50-424/79-07 & 50-425/79-07 on 790425-27  
Noncompliance noted failure to follow preventive maint  
procedures for safety-related electrical components &  
failure to conform to concrete design commitments  
GOUDE, M J Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction &  
Engineering Support Branch 79/05/17 5pp

7907190518 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage  
from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 2pp

7907120079 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907300580 Ack receipt of 790607 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Repts 50-424/79-07 &  
50-425/79-07  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/06/25 1p

7907310020 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907240268 Ack receipt of 790615 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Repts 50-424/79-08 &  
50-425/79-08  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering  
Support Branch 79/06/26 1p

--7907240269 Responds to NRC 790524 ltr re violations noted in IE Insp  
Repts 50-424/79-08 & 50-425/79-08 Corrective actions  
nonconformance repts & stop action orders issued re backfill  
operations Full compliance expected by 790716  
STAFFA, R W Georgia Power Co 79/06/15 2pp

7907180311 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director,  
79/06/27 2pp

7907180436 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director,  
79/06/28 2pp

7907310254 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310383 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

DOCKET 50-425 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7907030138 FOIA request for all documents relating to facility EIS & all projects covered by EIS  
FLACK, G Myer, Bowman, Stroup & Flack 79/06/01 2pp

7907030237 Responds to FOIA 790601 request for documents re facility projects covered by EIS List of available documents related to request encl  
FELTON, J M Division of Rules and Records 79/06/26 2pp

G Adjudicatory correspondence

7907240341 Submits addl info for Georgians Against Nuclear Energy request for reconsideration of petition for revocation of CP Alleges petitioners were misrepresented, that NEPA stds were not followed & that circumstances have changed  
FLACK, G Myer, Bowman, Stroup & Flack 79/07/17 21 pp

H General correspondence

7907090416 Summary of 790522 meeting w/util & Region 2 personnel re insp & enforcement, enforcement history & GA/OC authority  
MURPHY, C E Region 2, Atlanta, Office of the Director 79/05/25 3pp

I Financial information

7907030337 Forwards Annual Financial Repts 1978 for GA Power Co & Southern Co  
WHITHER, C F Georgia Power Co 79/07/02 1p

--7907050384 Annual Financial Rept 1978  
\* The Southern Co 79/02/28 39pp

--7907050394 Annual Financial Rept 1978  
\* Georgia Power Co 79/01/31 34pp.

G Inspection reports, IE Bulletins & correspondence

7907020342 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907120523 Forwards IE Insp Repts 50-424/79-06 & 50-425/79-06 on 790418-20 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/08/02 2pp

--7907120533 IE Insp Repts 50-424/79-06 & 50-425/79-06 on 790418-20 No noncompliance noted Major areas inspected, QC procedures, ultrasonic test examination of inbeds, piping contractor procedures & outstanding open items  
HUNT, M D, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/02 4pp

7907110329 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp.

7907100196 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110105 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 2pp.

7907100135 Responds to 790319 ltr re IE Bulletins 78-12, 12A & 12B. Requests extension to 790629 for response due to C-E inability to file generic rept  
STAFFA, R W Georgia Power Co 79/05/24 1p.

7907100173 Responds to IE Bulletin 79-07, Action Items 2 & 4 not applicable No methods specified in Item 1 are used in LEAP computer code for seismic analysis of safety-related piping  
STAFFA, R W Georgia Power Co. 79/05/24 2pp.

7907090411 Discusses meeting held in Atlanta, GA on 790522 Meeting was beneficial & has provided for better understanding of insp & enforcement issues  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/25 2pp

7907180163 Responds to IE Bulletin 79-04 No Velan swing check valves in use  
STAFFA, R W Georgia Power Co 79/05/25 1p

7907030098 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 2pp

7907090144 Responds to IE Bulletin 79-09. There are no OE Type AK-2 circuit breakers in any safety-related sys at facility  
STAFFA, R W Georgia Power Co 79/05/29 1p

7907200198 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp.

7907190175 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp.

7907060059 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020211 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907240259 Ack receipt of 790607 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/79-07 & 50-425/79-07  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/18 1p

--7907240270 Responds to NRC 790521 ltr re violation noted in IE Insp Repts 50-424/79-07 & 50-425/79-07 Corrective actions QC inspectors given procedural instructions on motor shaft rotations  
STAFFA, R U Georgia Power Co 79/06/07 2pp

--7907240272 Forwards IE Insp Repts 50-424/79-07 & 50-425/79-07 on 790425-27, notice of violation & notice of deviation  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/21 2pp.

--7907240275 Notice of violation from insp on 790425-27  
\* Region 2, Atlanta, Office of the Director 79/05/17 1p

--7907240278 Notice of deviation from insp on 790425-27  
\* Region 2, Atlanta, Office of the Director 79/05/17 1p

--7907240285 IE Insp Repts 50-424/79-07 & 50-425/79-07 on 790425-27. Noncompliance noted failure to follow preventive maint procedures for safety-related electrical components & failure to conform to concrete design commitments  
ODUQE, M J Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/17 5pp

7907190518 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 2pp

7907120079 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907300580 Ack receipt of 790607 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/79-07 & 50-425/79-07  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/25 1p

## DOCKETED ITEMS

7907310020 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907240268 Ack receipt of 790615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/79-08 & 50-425/79-08  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch  
79/06/26 1p

--7907240269 Responds to NRC 790524 ltr re violations noted in IE Insp Repts 50-424/79-08 & 50-425/79-08 Corrective actions nonconformance repts & stop action orders issued re backfill operations Full compliance expected by 790716  
STAFFAR, R W Georgia Power Co 79/06/15 2pp

7907180311 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180436 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310234 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310383 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### DOCKET 50-426 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 3

##### A Application/construction stage documents & correspondence

7907030138 FOIA request for all documents relating to facility EIS & all projects covered by EIS  
FLACK, G Myer, Bowman, Stroup & Flack 79/06/01 2pp

7907030237 Responds to FOIA 790601 request for documents re facility EIS & projects covered by EIS List of available documents related to request encl  
FELTON, J M Division of Rules and Records 79/06/26 2pp

#### DOCKET 50-427 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 4

##### A Application/construction stage documents & correspondence

7907030138 FOIA request for all documents relating to facility EIS & all projects covered by EIS  
FLACK, G Myer, Bowman, Stroup & Flack 79/06/01 2pp

7907030237 Responds to FOIA 790601 request for documents re facility EIS & projects covered by EIS List of available documents related to request encl  
FELTON, J M Division of Rules and Records 79/06/26 2pp

#### DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

##### G Inspection reports, IE Bulletins & correspondence

7907230599 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
ENDELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22 1p

7907230769 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
ENDELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/06 1p

#### DOCKET STN-50-437 FLOATING NUCLEAR PLANT

##### A Application/construction stage documents & correspondence

7907190008 Forwards Sandia Lab comments on rept 34A59 "Floating Nuclear Plant Core Ladle Design & Safety Evaluation."  
BAER, R L Light Water Reactors Branch 2 79/06/05 4pp

--7907190014 "Review of Info Needs for Design of Magnesium Oxide Core Retention Device "  
\* Sandia Laboratories 79/05/23 15pp

7907310152 Requests analysis re impacts that may result from release of insoluble core debris particles into open ocean environ following a postulated core-melt accident at floating nuclear power plant  
BALLARD, R L Environmental Projects Branch 1 79/06/14 3pp

7907250380 Provides addl info for plant design rept re effect of core ladle on reactor cavity pressure analysis  
HAGA, P B Offshore Power Systems (subs of Westinghouse Electric Corp ) 79/07/11 1p

7907170180 Forwards assessment of potential impacts of releases of insoluble core debris following postulated core melt accident Transport of radioactivity as particulate matter is considered highly unlikely  
HAGA, P B Offshore Power Systems (subs of Westinghouse Electric Corp ) 79/07/13 35pp

7907270173 Discusses effect of core ladle on reactor cavity pressure analysis Supersees 790711 ltr  
HAGA, P B Offshore Power Systems (subs of Westinghouse Electric Corp ) 79/07/19 1p

##### D NRC Draft/Final Environmental Statements, supplis & correspondence

7901102468 Forwards FES, Part 3 (NUREG-0502, Dec 1978) re comparison of risks from accidental releases of radioactivity for floating & land-based nuclear plants Distribution list encl 4/5 FES  
BALLARD, R L Environmental Projects Branch 1 79/01/08 14pp

##### G Adjudicatory correspondence

7907100650 Requests determination of date for Board to visit proposed facility site  
WOLFE, S J Atomic Safety and Licensing Board Panel 79/08/25 1p

7907250421 Forwards Offshore Power Sys 790502 proposed partial findings of fact in form of proposed initial decision  
COHAN, B Z , DAUGHERTY, T M , KENDRICK, J R Eckert, Seamans, Cherin & Hellott 79/06/01 1p

--7907250428 Proposed partial findings of fact in form of proposed initial decision submitted by Offshore Power Sys to ASLB Discusses each contention admitted as issue in controversy & ASLB questions Certificate of Svc encl  
COHAN, B Z , DAUGHERTY, T M , KENDRICK, J R Eckert, Seamans, Cherin & Hellott 79/06/01 199pp

7907190208 Responds to 790508 ltr opposing floating nuclear plant design Vendor application for mfg license is in ASLB hearing process Forwards explanation of reactor licensing process  
DENTON, H R Office of Nuclear Reactor Regulation 79/06/05 9pp

--7907190215 Requests reply to 790408 ltr re approval of floating nuclear plants off FL coast  
TOOHER, J L Affiliation Unknown 79/05/08 1p

--7907190220 Opposes floating nuclear plants because of potential weather dangers  
TOOHER, J L Affiliation Unknown 79/04/08 1p

7907180731 Requests extension until 790810 to file proposed partial findings of fact Certificate of Svc encl  
SOHINKI, S M Branch 3 79/06/13 3pp

##### G Advisory Committee on Reactor Safeguards reports & correspondence

7907300290 Notification of 790627 meeting w/utill in Washington, DC to discuss proposed core ladle design using magnesium oxide bricks Distribution list & presentation schedule encl  
BIRKEL, R A Light Water Reactors Branch 2 79/06/20 6pp

##### G Inspection reports, IE Bulletins & correspondence

7907020332 Forwards IE Bulletin 79-03B, "Nuclear Incident at TMI - Suppl 1 "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 1p.

790710310 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 1p

7907100023 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 1p

7907100036 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 1p

7907060350 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907030085 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 1p

7907200257 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 1p

7907020371 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120151 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907180343 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 1p

7907180447 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 1p

7907310282 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 3pp

7907250293 Discusses problems experienced w/pipe support baseline design, as outlined in IE Bulletin 79-02 & transmitted to ASLB on 781207 Criteria for design of steel embeddings prevents problems occurring  
HARR, P B Offshore Power Systems (subs of Westinghouse Electric Corp ) 79/07/09 1p

7907310391 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### DOCKET 90-43B BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7907110699 Notification of 790614 meeting w/util in Bethesda, MD to discuss southern Appalachian region tectonic study  
STAHLE, C R Light Water Reactors Branch 4 79/06/11 3pp

7907060309 Forwards "Southern Appalachian Tectonic Study "  
OILLELAND, J E Tennessee Valley Authority 79/06/28 2pp

--7907060316 "Southern Appalachian Tectonic Study " Oversize maps encl  
SEAY, W M Tennessee Valley Authority 79/01/31 84pp

G Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Supp1 "  
O'REILLY, J P Region 2, Atlanta, Office of the Director,  
79/04/21 3pp

7907050134 Forwards IE Insp Repts 50-43B/79-08 & 50-439/79-08 on 790410-13 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/03 2pp

--7907030143 IE Insp Repts 50-43B/79-08 & 50-439/79-08 on 790410-13 No noncompliance noted Major areas inspected const status, housekeeping, slab placement, storage & preventive maint  
WRIGHT, R W Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/03 5pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp.

7907240181 Forwards IE Insp Repts 50-43B/79-09 & 50-439/79-09 on 790417-19 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/21 2pp

--7907240186 IE Insp Repts 50-43B/79-09 & 50-439/79-09 on 790417-19 No noncompliance noted Major areas inspected reactor coolant pressure boundary piping & safety-related piping records.  
VAN DOORN, P K Region 2, Atlanta, Office of the Director  
CONLON, T E Region 3, Chicago, Office of the Director  
79/05/17 5pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 3pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Valves swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
OILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp.

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-N888 sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
OILLELAND, J E Tennessee Valley Authority 79/05/31. 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures. " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director,  
79/06/07 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

## DOCKETED ITEMS

7907120104 Forwards IE Bulletin 79-02, Revision J, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 3pp

7907030348 Forwards response to IE Insp Repts 50-438/79-11 & 50-439/79-11 Infraction failure to follow procedures for control of welding mats caused by employee error. Corrective actions briefing personnel re requirements & surveillance  
GILLELAND, J E Tennessee Valley Authority 79/06/26 2pp

7907030450 Responds to 790626 ltr re Insp Repts 50-438/79-05 & 50-439/79-05 Corrective action QA training implemented  
Welds corrected by June 1980  
GILLELAND, J E Tennessee Valley Authority 79/06/26 2pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 3pp

#### B Reportable occurrences, LERs & related correspondence

7907090331 Forwards first interim deficiency rept re water found in rock anchor tendon head protective grease cans. Next rept will be submitted by 791123  
GILLELAND, J E Tennessee Valley Authority 79/06/22 1p

--7907090343 First interim deficiency rept re water found in rock anchor tendon head protective grease cans. Investigations will attempt to identify all affected anchor tendons & locate source of water  
\* Tennessee Valley Authority 79/06/22 1p

7907260779 Forwards second interim deficiency rept re blown fuses in low voltage switch gear  
MILLS, L M Tennessee Valley Authority 79/07/19 1p

--7907260795 Second interim deficiency rept on 790425 upon energizing main breaker on Westinghouse low voltage metal type DS switchgear, fuses on primary side of main bus potential transformers blew. Cause unknown  
\* Tennessee Valley Authority, 79/07/26 1p.

#### DOCKET 50-437 BELLEFONTE NUCLEAR PLANT, UNIT 2

#### A Application/construction stage documents & correspondence

7907110699 Notification of 790614 meeting w/uttl in Bethesda, MD to discuss southern Appalachian region tectonic study  
STAHL, C R Light Water Reactors Branch 4, 79/06/11 3pp

7907060309 Forwards "Southern Appalachian Tectonic Study." GILLELAND, J E Tennessee Valley Authority 79/06/28 2pp

--7907060316 "Southern Appalachian Tectonic Study." Overseas maps encl.  
BEAY, W H Tennessee Valley Authority, 79/01/31, 84pp.

#### G Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl." O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21, 3pp.

7907050134 Forwards IE Insp Repts 50-438/79-08 & 50-439/79-08 on 790410-13 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/03 2pp

--7907050143 IE Insp Repts 50-438/79-08 & 50-439/79-08 on 790410-13 No noncompliance noted. Major areas inspected: const status, housekeeping, slab placement, storage & preventive maint  
WRIGHT, R W Region 2, Atlanta, Office of the Director  
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/03 5pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907240181 Forwards IE Insp Repts 50-438/79-09 & 50-439/79-09 on 790417-19 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/21 2pp

--7907240186 IE Insp Repts 50-438/79-09 & 50-439/79-09 on 790417-19 No noncompliance noted. Major areas inspected: reactor coolant pressure boundary piping & safety-related piping records  
VAN DOORN, P K Region 2, Atlanta, Office of the Director  
CONLON, T E Region 3, Chicago, Office of the Director  
79/05/17 5pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 3pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Velan, swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Investigation of non-NB88 sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/06, 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp.

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys." O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11, 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate." O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20, 1p



7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 3pp

7907030348 Forwards response to IE Insp Repts 50-43B/79-11 & 50-439/79-11 Infraction failure to follow procedures for control of welding mats Caused by employee error Corrective actions briefing personnel re requirements & surveillance  
GILLELAND, J E Tennessee Valley Authority 79/06/26 2pp

7907030450 Responds to 790626 ltr re Insp Repts 50-43B/79-05 & 50-439/79-05 Corrective action QA training implemented  
Welds corrected by June 1980  
GILLELAND, J E Tennessee Valley Authority 79/06/26 2pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 3pp

#### S Reportable occurrences, LERs & related correspondence

7907090331 Forwards first interim deficiency rept re water found in rock anchor tendon head protective grease cans Next rept will be submitted by 791123  
GILLELAND, J E Tennessee Valley Authority 79/06/22 1p

--7907090343 First interim deficiency rept re water found in rock anchor tendon head protective grease cans Investigations will attempt to identify all affected anchor tendons & locate source of water  
\* Tennessee Valley Authority 79/06/22 1p.

7907240779 Forwards second interim deficiency rept re blown fuses in low voltage switch gear  
MILLS, L M Tennessee Valley Authority 79/07/19 1p

--7907240795 Second interim deficiency rept on 790425 upon energizing main breaker on Westinghouse low voltage metal type DB switchgear, fuses on primary side of main bus potential transformers blew Cause unknown  
\* Tennessee Valley Authority 79/07/26 1p

#### DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

#### A Application/construction stage documents & correspondence

7907130465 Expresses satisfaction that 790501 meeting provided info requested re operation of nuclear power plants in OH  
BENTON, H R. Office of Nuclear Reactor Regulation 79/05/24 1p

--7907130474 Requests briefing be arranged on 790501 or 02 re safe operation of nuclear power plants in OH  
MCARDY, J F Ohio, State of 79/04/16 1p

--7907130479 Requests comments, in view of TMI incident, re adequacy of facility staff training, safety & emergency procedures & plant design Also seeks info re sys & safety reviews planned for facilities in OH  
MCARDY, J F, Ohio, State of 79/04/12 1p.

#### G Inspection reports, IE Bulletins & correspondence

7907250436 Forwards IE Insp Repts 50-440/79-04 & 50-441/79-04 on 790418-20 & notice of violation.  
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/05/15. 2pp

--7907250443 Notice of violation from insp on 790418-20  
\* Region 3, Chicago, Office of the Director 79/05/15 1p

--7907250452 IE Insp Repts 50-440/79-04 & 50-441/79-04 on 790418-20 Noncompliance noted improper storage of pipe sleeves  
KONKLIN, J E, HUOHES, J, HNOFF, R C Region 3, Chicago, Office of the Director 79/05/15 9pp

7907110251 Responds to IE Bulletin 79-04 No Seismic Category I piping sys use Velan swing check valves Velan Engineering Corp not one of NSSS supplier subvondors  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/21 1p

7907110285 Responds to IE Bulletins 78-12, 78-12A & 78-12B No atypical weld matl was used in reactor vessel welds  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/23 1p

7907110231 Responds to IE Bulletin 79-07 Computer codes for seismic stress analysis of safety-related piping do not use algebraic summation of codirectional spatial components or intermodal responses in response spectrum analysis  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/25 2pp

7907200303 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190240 Forwards suppl IE Bulletin 79-01A, "Environment Qualification of Class IE Equipment (Deficiencies in Environment Qualification of ABCO Solenoid Valves) " Action required  
KEPLER, J G Region 3, Chicago, Office of the Director. 79/06/06 1p

7907240250 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020245 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907020419 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120218 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907120494 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p.

7907060307 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050470 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPLER, J G. Region 3, Chicago, Office of the Director 79/06/27 1p

7907250077 Ack receipt of 790615 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-440/79-04 & 50-441/79-04.  
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/06/27 1p

--7907250082 Responds to NRC 790515 ltr re violation noted in IE Insp Repts 50-440/79-04 & 50-441/79-04. Corrective actions cleanup of area completed & storage of pipe sleeves now in accordance w/Level D requirements.  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/06/15 2pp

7907180403 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130259 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907260006 Ack receipt of 790615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/79-04 & 50-441/79-04  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/06 1p

--7907260017 Responds to NRC 790515 ltr re violation noted in IE Insp Rept 50-440/79-04 & 50-441/79-04 Corrective actions cleanup completed & pipe sleeves stored properly  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/06/15 2pp

7907310325 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310404 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260167 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260349 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250225 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### S Reportable occurrences, LERs & related correspondence

7907180463 Ack receipt of 790329 ltr re fabrication of Perry intake structures  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/13 1p

#### DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

##### A Application/construction stage documents & correspondence

7907130465 Expresses satisfaction that 790501 meeting provided info requested re operation of nuclear power plants in OH  
BENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907130474 Requests briefing be arranged on 790501 or 790502 re safe operation of nuclear power plants in OH  
MCAVOY, J F Ohio, State of 79/04/16 1p

--7907130479 Requests comments, in view of TMI, re adequacy of facility staff training, safety & emergency procedures & plant design. Also seeks info re sys & produces safety reviews planned for facilities in OH  
MCAVOY, J F Ohio, State of 79/04/12 1p

##### B Inspection reports, IE Bulletins & correspondence

7907250436 Forwards IE Insp Repts 50-440/79-04 & 50-441/79-04 on 790418-20 & notice of violation  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/15 2pp

--7907250443 Notice of violation from Insp on 790418-20  
\* Region 3, Chicago, Office of the Director 79/05/15 1p

--7907250452 IE Insp Repts 50-440/79-04 & 50-441/79-04 on 790418-20 Noncompliance noted improper storage of pipe sleeves  
KONKLIN, J E, HUGHES, J, KNOP, R C Region 3, Chicago, Office of the Director 79/05/15, 9pp

7907110251 Responds to IE Bulletin 79-04 No Seismic Category I piping sys use Velan swing check valves Velan Engineering Corp not one of NSSS supplier subvendors  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/21 1p

7907110285 Responds to IE Bulletins 78-12, 78-12A & 78-12B No atypical weld matl was used in reactor vessel welds  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/23 1p

7907110231 Responds to IE Bulletin 79-07 Computer codes for seismic stress analysis of safety-related piping do not use algebraic summation of codirectional spatial components or intermodal responses in response spectrum analysis  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/05/25 2pp

7907200303 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190240 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCD Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240250 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020245 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907020419 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120218 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907120694 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060307 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050470 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907250077 Ack receipt of 790615 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-440/79-04 & 50-441/79-04  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/27 1p

--7907250082 Responds to NRC 790515 ltr re violation noted in IE Insp Repts 50-440/79-04 & 50-441/79-04 Corrective actions cleanup of area completed & storage of pipe sleeves now in accordance w/Level D requirements  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/06/15 2pp

7907180403 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130259 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907260006 Ack receipt of 790615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/79-04 & 50-441/79-04  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/07/06 1p

--7907260017 Responds to NRC 790515 ltr re violation noted in IE Insp Rept 50-440/79-04 & 50-441/79-04 Corrective actions cleanup completed & pipe sleeves stored properly  
DAVIDSON, D R Cleveland Electric Illuminating Co 79/06/15 2pp

7907310325 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310404 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260147 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260349 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Boreated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250225 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### B Reportable occurrences, LERs & related correspondence

7907180463 Ack receipt of 790329 ltr re fabrication of Perry intake structures  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/13 1p

#### DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

#### Q Adjudicatory correspondence

7907100678 Ack receipt of 790502 petition requesting Director of Nuclear Reactor Regulation issue order suspending or revoking CPPR-135 & CPPR-136 Petition being treated under 10CFR2 206  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907100689 Forwards petition requesting Director of Nuclear Regulatory Regulation issue order suspending or revoking CPPR-135 & CPPR-136 pending determination that evacuation of persons within 30 miles of site is feasible  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907100714 "Request for Action Pursuant to 10CFR2.206 "  
DENTON, H R Office of Nuclear Reactor Regulation 79/04/24, 1p

--7907100719 "Request for Order to Show Cause Why CP for Proposed Nuclear Power Plant at Seabrook Should not be Suspended or Revoked "  
BACKUS, R A O'Neil, Backus, Spielman, 79/05/02 14pp

7907130148 Notice of receipt of Seacoast Anti-Pollution League 790502 request for order suspending or revoking CPPR-135 & CPPR-136, Petition is being treated per 10CFR2 206.  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

7907190173 Notice of 790502 petition from Seacoast Antipollution League requesting order to suspend or revoke CP & DL pending determination of acceptable evacuation plans Petition being treated per 10CFR2 206  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24, 1p

7907160131 Requests summary disposition of Intervenor's Ecology Action of Owego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record, Deficiencies do not raise genuine issue of matl fact Certificate of Evc encl  
BORDENICK, B. M. Branch 4 79/05/25 29pp.

7907180878 Motion by util requesting summary disposition of issue re alternate sites, assuming plant is required to use cooling towers.  
RITSHER, J. A., DIGNAN, T. G., GAD, R. K Ropes & Gray 79/06/06 2pp

--7907180895 Matl Facts relevant to util 790606 motion for summary disposition If sunk costs may be counted, no superior alternate site exists Certificate of Evc encl  
RITSHER, J A, DIGNAN, T G, GAD, R C Ropes & Gray 79/06/06 2pp

7907180726 Util motion for summary disposition re ALAB-54B Court of Appeals has adhered to "sunk costs" rule Certificate of Evc encl  
RITSHER, J A, DIGNAN, T G, GAD, R K Ropes & Gray 79/06/11 4pp

7907180907 Denies E Weinhold petition requesting suspension of const & imposition of high seismic protection std Seismic questions re ALAB-422 are deferred until 790731, date of issuance of dissenting opinion of ASLB member MC Farrar  
CHILK, S J Office of the Secretary of the Commission 79/06/22 2pp

#### I Financial information

7907060066 Requests addl financial info to supplement 790423 response to original NRC 780321 request  
VASSALLO, D B Assistant Director for Light Water Reactors 79/05/23 11pp

7907030335 Forwards PSC of NH 790621 preliminary prospectus re two million shares of common stock Submittal supplements info forwarded 790622  
RITSHER, J A Ropes & Gray 79/06/26 54pp

7907180112 Forwards 790712 final prospectus of PSC of NH re offering of 2 million shares of common stock  
RITSHER, J A Ropes & Gray 79/07/13 54pp.

7907270197 Advises that response date of 790731 for addl financial info cannot be guaranteed  
DIGNAN, T G Ropes & Gray 79/07/23 1p

#### M Antitrust correspondence

7907240454 Requests antitrust advice per Atomic Energy Act Util has filed info re changes of ownership among entities already participating in project Forwards info for intitrust review W/o encl  
BHAPAR, H K Office of the Executive Legal Director 79/06/04 2pp

#### Q Inspection reports, IE Bulletins & correspondence

7907060429 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers For Engineered Safety Sys " Licensee action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907030069 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200147 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190109 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06, 1p

7907060130 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020054 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys." GRIER, B.H. Region 1, Philadelphia, Office of the Director, 79/06/11 1p.

7907240204 Ack receipt of 790611 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/79-05 & 50-444/79-05  
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/06/18 1p

--7907240212 Responds to NRC 790514 ltr re violations noted in IE Insp Repts 50-443/79-05 & 50-444/79-05 Corrective actions: all motors w/ space heaters were hard wired & electrical connections inspected  
SHEPARD, A M Public Service Co of New Hampshire, 79/06/11, 2pp.

## DOCKETED ITEMS

--7907240216 Forwards IE Insp Repts 50-443/79-05 & 50-444/79-05 on 790403-04 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907240220 Notice of violation from insp on 790403-04  
Region 1, Philadelphia, Office of the Director 79/05/09 1p

--7907240222 IE Insp Repts 50-443/79-05 & 50-444/79-05 on 790403-04  
Noncompliance noted failure to electrically connect stored equipment supplied w/space heaters as required in procedures  
FOLSON, S A MATTIA, J C MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/09 5pp

7907110391 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907120543 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100371 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100431 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/27 1p

790710038 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907100818 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270365 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310538 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

7907100678 Ack receipt of 790502 petition requesting Director of Nuclear Reactor Regulation issue order suspending or revoking CPPR-135 & CPPR-136 Petition being treated under 10CFR2.206  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907100689 Forwards petition requesting Director of Nuclear Regulatory Regulation issue order suspending or revoking CPPR-135 & CPPR-136 pending determination that evacuation of persons within 30 miles of site is feasible  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 3pp

--7907100714 "Request for Action Pursuant to 10CFR2.206"  
DENTON, H R Office of Nuclear Reactor Regulation 79/04/24 1p

--7907100719 "Request for Order to Show Cause Why CP for Proposed Nuclear Power Plant at Seabrook Should not be Suspended or Revoked"  
BACKUS, R A O'Neill, Backus, Spielman 79/05/02 14pp

7907130148 Notice of receipt of Seacoast Anti-Pollution League 790502 request for order suspending or revoking CPPR-135 & CPPR-136 Petition is being treated per 10CFR2.206  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

7907190173 Notice of 790502 petition from Seacoast Antipollution League requesting order to suspend or revoke CP & OL pending determination of acceptable evacuation plans Petition being treated per 10CFR2.206  
DENTON, H R Office of Nuclear Reactor Regulation. 79/05/24 1p

7907160131 Requests summary disposition of Intervenor's Ecology Action of Duquesne & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907180878 Motion by util requesting summary disposition of issue re alternate sites, assuming plant is required to use cooling towers  
RITSHER, J A, DIGMAN, T G, GAD, R K Ropes & Gray 79/06/06 2pp

--7907180895 Matl facts relevant to util 790606 motion for summary disposition if sunk costs may be counted, no superior alternate site exists Certificate of Svc encl  
RITSHER, J A, DIGMAN, T G, GAD, R C Ropes & Gray 79/06/06 2pp

7907180907 Denies E Weinhold petition requesting suspension of commit & imposition of high seismic protection std Seismic questions re AKAS-422 are deferred until 790731, date of issuance of dissenting opinion of ASLB member MC Farrar  
CHILK, S J Office of the Secretary of the Commission 79/06/22 2pp

J Financial information

7907180112 Forwards 790712 final prospectus of PSC of NH re offering of 2 million shares of common stock  
RITSHER, J A Ropes & Gray 79/07/13 54pp

7907060066 Requests addl financial info to supplement 790423 response to original NRC 780321 request  
VASSALLO, D B Assistant Director for Light Water Reactors, 79/05/23 11pp

7907030355 Forwards PSC of NH 790621 preliminary prospectus re two million shares of common stock Submittal supplements info forwarded 790622  
RITSHER, J A Ropes & Gray 79/06/26 54pp

7907270197 Advises that response date of 790731 for addl financial info cannot be guaranteed  
DIGMAN, T G Ropes & Gray 79/07/23 1p

K Antitrust correspondence

7907240454 Requests antitrust advice per Atomic Energy Act Util has filed info re changes of ownership among entities already participating in project. Forwards info for antitrust review  
W/a encl  
SHAFAR, H K Office of the Executive Legal Director 79/06/04 2pp

G Inspection reports, IE Bulletins & correspondence

7907060429 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Licensee action required  
GRIER, D H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907030069 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Quster Creek Reactor" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200147 Forwards IE Bulletin 79-12, "Short Period Scrams at BHR Facilities" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/05/31 1p

7907190109 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Bolenoid Valves)" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060130 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020054 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907240204 Ack receipt of 790611 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/79-05 & 50-444/79-05  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch, 79/06/18 1p

--7907240212 Responds to NRC 790514 ltr re violations noted in IE Insp Repts 50-443/79-05 & 50-444/79-05 Corrective actions all motors w/space heaters were hard wired & electrical connections inspected  
SHEPARD, A M Public Service Co of New Hampshire 79/06/11 2pp

--7907240216 Forwards IE Insp Repts 50-443/79-05 & 50-444/79-05 on 790403-04 & notice of violation  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907240220 Notice of violation from insp on 790403-04  
\* Region 1, Philadelphia, Office of the Director 79/05/09 1p

--7907240222 IE Insp Repts 50-443/79-05 & 50-444/79-05 on 790403-04 Noncompliance noted failure to electrically connect stored equipment supplied w/space heaters as required in procedures  
FOLSON, B A, MATTIA, J C, MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/09 3pp

7907110391 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Onsd Plate"  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907120543 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100371 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100431 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907110038 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180818 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270365 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310538 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

#### DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA UNIT 1

##### A Application/construction stage documents & correspondence

7907110112 Summary of progress of QA program review Section 9 5 1 will be submitted in future amend  
HAASS, W P Quality Assurance Branch 79/05/21 7pp

7907110164 Forwards second round request for addl info required to complete evaluation of application for OL  
BAER, R L Light Water Reactors Branch 2 79/05/31 3pp

--7907110176 Second round request for addl info required to complete evaluation of application for OL  
\* Light Water Reactors Branch 2 79/05/31 8pp

7907180892 Forwards request for addl info as result of Mechanical Engineering Branch review of FBAR Requests amend to FBAR to include requested info  
BAER, R L Light Water Reactors Branch 2 79/06/08 5pp

7907270389 Notifies that submittal of electrical, instrumentation & control drawings is delayed until 7901231 Postponement not expected to impact projected fuel loading schedule  
BAER, R L Light Water Reactors Branch 2 79/06/20 3pp

7907090247 Notifies of intention to respond to second round questions by FBAR amend in Sept 1979  
GARY, R J Texas Utilities Generating Co 79/06/29 1p

7907250318 Forwards list of Gibbs & Hill & Westinghouse drawings re dynamic asymmetric loading review of facility coolant supports, per NRC request  
BACKO, B S Texas Utilities Services, Inc 79/07/17 5pp

##### O Adjudicatory correspondence

7907090062 Notifies that depositions have been taken from RL Stader of PPG Industries & EV Sherry of Air Products & Chemicals Central Power & Light has furnished NRC-requested documents to City of Brownsville, TX  
RYAN, T G Isham, Lincoln & Beale 79/05/01 1p

7907030185 Forwards ASLB orders Arrangements made for inclusion on svc list w/o encl  
ULMAN, M B Operations & Administrative Division 79/05/09 1p

7907170243 Motion to suppl petition to intervene submitted by Citizens for Fair Util Regulation Contentions are clarified & organized in proper form Certificate of Svc encl  
JACOBSON, N H, FOUKE, R L Citizens for Fair Utility Regulation 79/05/22 4pp

7907180612 First errata to Citizens for Util Regulation suppl to petition to intervene Certificate of Svc encl  
JACOBSON, N H, FOUKE, R L Citizens for Fair Utility Regulation 79/05/22 4pp

7907180748 Certificate of Svc for revised page 21 of 790507 suppl to petition to intervene Revised page & affidavit of M Stinson encl  
ELLIS, J Citizens Association for Sound Energy 79/05/23 3pp

7907160207 Motion to amend suppl to petition to intervene submitted by Citizens for Fair Util Regulation Motion supersedes & clarifies 790522 motion to amend Restates contentions in proper form Certificate of Svc encl  
FOUKE, R L Citizens for Fair Utility Regulation 79/05/29 8pp

7907170248 Brief re applicability of ALAB-549, submitted by M & C Bishop, O & W Wood & Association of Communities for Reform Now Standing of late intervenors should be judged by fairness, not legal technicalities Certificate of Svc encl  
GAY, O M, GARRETT, W L West Texas Legal Services 79/05/30 6pp

7907130164 Memorandum confirming applicability of ALAB-549 to petitions to intervene Standing is based on interests of members living in close proximity to Facility Petitioners should be granted intervenor status Certificate of Svc encl  
ULMAN, M B Operations & Administrative Division 79/06/04 9pp

7907060447 Provides proposed corrections to 790522 prehearing conference transcript  
REYNOLDS, N B Debevoise & Lieberman 79/06/12 4pp

7907060483 Util answer to Citizens for Fair Util Regulation 790529 second motion to amend petition to intervene No contention has been raised which meets requirements of 10CFR2 714(b) Certificate of Svc encl  
REYNOLDS, N S Debevoise & Lieberman 79/06/13 4pp

7907180555 Supports Citizens for Fair Util Regulation 790529 motion to amend 790507 suppl to petition to intervene One good contention is set forth to justify admission as intervenor Good cause has been shown Certificate of svc encl  
CHANDLER, L J Branch 1, ULMAN, M B Operations & Administrative Division 79/06/18 5pp

7907180777 Notice of appearance of DJ Preister on behalf of State of TX Certificate of Svc encl  
PREISTER, D J Texas, State of 79/06/19 2pp

7907240300 Order granting intervenor status to Citizens Association for Sound Energy, Citizens for Fair Util Regulation, State of TX & Association of Community Organizations for Reform Now Intervenor status is denied to West TX Legal Svc  
COLE, R F, KORNBLITH, L, BOMER, E S Atomic Safety and Licensing Board Panel 79/06/27 12pp

##### M. Antitrust correspondence

7907080444 Submits discovery rept for Apr 1979 No discoveries initiated or received  
BALOUGH, R C Austin, TX 79/05/08 4pp

## DOCKETED ITEMS

- 7907190213 Summarizes Public Utils Board of City of Brownsville, TX discovery progress for Apr 1979 Certificate of Svc encl  
FOIRIER, M R Spiegel & McDiarmid 79/05/14 6pp
- 7907110152 Houston Lighting & Power addl answers to NRC 790115 initial interrogatories Affidavit & Certificate of Svc encl  
COPELAND, J G Baker & Butts 79/05/24 27pp
- 7907180879 TX Utils Generating Co & subsidiaries supplemental answer to NRC initial interrogatories Affidavit, Certificate of Svc & Apps A & B encl  
SAMPOLS, M D Worsham, Forsythe & Sampels KNOTTS, J B Debevoise & Lieberman SCARTH, E D Texas Utilities Co 79/05/25 18pp
- 7907180040 DOJ rept re progress made on discovery during May 1979 Rept submitted per ASLB 780621 order  
HARRIS, J L Justice, Dept of 79/06/01 6pp
- 7907170117 Public Utils Board of City of Brownsville second application for issuance of subpoena for production of documents by El Paso Electric Draft of subpoena encl  
FOIRIER, M R Spiegel & McDiarmid 79/06/12 18pp
- 7907170117 Public Utils Board of City of Brownsville second application for issuance of subpoena for production of documents by El Paso Electric Draft of subpoena encl  
FOIRIER, M R Spiegel & McDiarmid 79/06/12 18pp
- 7907170154 Public Utils Board of City of Brownsville application for issuance of subpoena for production of documents by El Paso Electric Certificate of Svc encl  
FOIRIER, M R Spiegel & McDiarmid 79/05/13 10pp
- 7907020005 TX Utils Generating Co first set of interrogatories & production of documents, directed to TEX-LA Electric Cooperative, Seventeen Member Cooperatives & any successor entities Certificate of Svc encl  
KNOTTS, J B Debevoise & Lieberman WORTHAM, J I, SAMPOLS, M D Worsham, Forsythe & Sampels 79/06/18 12pp
- 7907190435 Houston Lighting & Power & TX Utils Generating Co joint application for issuance of subpoenas calling for production of documents re util industry competition, access to plants & interstate operation Certificate of Svc & drafts encl  
COPELAND, J G Baker & Butts BDUKNIGHT, J A Lowenstein, Newman, Reis, Aselrad & Toll 79/06/18 20pp
- 7907190451 Order per 790601 conference ruling on motions & responses filed Mar-Apr 1979 by Houston Lighting & Power, TX Utils, Gulf States Util, Central Power & Light & NRC Amends 790404 order re schedule of proceedings  
WOLFE, S J Atomic Safety and Licensing Board Panel NRC. 79/04/25 4pp
- 7907190834 Forwards Public Utils Board of City of Brownsville, TX 790626 supplemental response to Houston Lighting & Power first request for production of documents & first set of interrogatories  
WHITE, S O Spiegel & McDiarmid 79/06/26 1p
- 7907190846 Public Utils Board of City of Brownsville, TX supplemental response to Houston Lighting & Power first request for production of documents & first set of interrogatories Affidavit & Certificate of Svc encl  
JABLON, R A Texas, State of 79/06/26 19pp
- 7907260038 DOJ & NRC joint application for issuance of subpoenas for testimony & production of documents re issue of competition, structure of electric util industry & plant access W/Certificate of Svc & drafts of subpoenas  
LESSY, R P Anti-Trust Division HARRIS, J L Justice, Dept. of 79/07/03 89pp.
- 7907260014 TX Utils Generating Co discovery rept for June 1979 Certificate of Svc encl  
KNOTTS, J B Debevoise & Lieberman 79/07/06 5pp.
- Inspection reports, IE Bulletins & correspondence
- 07310593 Requests extension to license rept due date until 790704  
GARV, R J Texas Utilities Generating Co. 79/05/07 1p.
- 07110471 Forwards IE Insp Repts 50-445/79-06 & 50-446/79-06 on 790301-30 & notice of violation  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/10 2pp
- 7907110681 Notice of violation from insp on 790501-30  
\* Region 4, Dallas, Office of the Director. 79/05/10 1p
- 7907110693 IE Insp Repts 50-445/79-06 & 50-446/79-06 on 790301-30 Noncompliance noted failure to follow GC insp procedures of cable tray hangers  
TAYLOR, R O, MARTIN, L E, CROSSMAN, W A Region 4, Dallas, Office of the Director 79/05/10 8pp
- 7907300242 Forwards IE Insp Repts 50-445/79-11 & 50-446/79-11 on 790402-03 & 13-23 & notice of violation  
SEIDLE, W C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/14 2pp
- 7907300250 Notice of violation from insp on 790402-03 & 13-23  
\* Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/14 1p
- 7907300256 IE Insp Repts 50-445/79-11 & 50-446/79-11 on 790402-03 & 13-23 Noncompliance noted failure to implement QA Program  
TAYLOR, R O, TOMLINSON, D P, CROSSMAN, W A Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/10 12pp
- 7907110656 Forwards 790507 response to IE Bulletin 79-03, re ASME SA-312 Type 304 piping  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/21 1p
- 7907110660 Responds to IE Bulletin 79-03 re ASME SA-312 Type 304 stainless steel pipe Pipe planned for use Complete rept to be completed 790531  
GARV, R J Texas Utilities Generating Co 79/05/07 4pp
- 7907310600 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers planned for use on any safety-related sys  
GARV, R J Texas Utilities Generating Co 79/05/22 1p
- 7907030129 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/29 1p
- 7907200365 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31 1p
- 7907250498 Forwards IE Insp Repts 50-445/79-14 & 50-446/79-14 on 790515-18 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/01 2pp
- 7907250518 IE Insp Repts 50-445/79-14 & 50-446/79-14 on 790515-18 No noncompliance noted Major areas inspected safety-related const activities pertaining to installation & insp of cable tray & conduit supports & electrical GC insp training  
MARTIN, L E, TAYLOR, R O, CROSSMAN, W A Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/30, 3pp
- 7907190411 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06 1p
- 7907060023 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/06/07 1p
- 7907260959 Forwards IE Insp Repts 50-445/79-09 & 50-446/79-09 on 790405-0507 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/08 2pp
- 7907260561 IE Insp Repts 50-445/79-09 & 50-446/79-09 on 790405-0507 No noncompliance noted Major areas inspected allegations by former RW Hunt employees re insp & testing improprieties appearing in Fort Worth Star-Telegram on 790404-06 & 08  
STEWART, R C, CROSSMAN, W A, HALL, R E Region 4, Dallas, Office of the Director 79/06/06 35pp
- 7907030365 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Bys " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p
- 7907050517 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate." No action required  
SEYFRIT, K. V Region 4, Dallas, Office of the Director 79/06/20 1p

Report of 790605 ltr informing NRC of steps taken to  
as noted in IE Insp Repts 50-445/79-06 &  
Region 4, Dallas, Reactor Construction & Engineering  
79/06/20 1p

nds to NRC 790510 ltr re violation noted in IE Insp  
79-06 & 50-446/79-06 Corrective actions  
ports inspected for welding &  
tion Instructions revised to ensure insp  
as Utilities Generating Co 79/06/05 4pp

s IE Bulletin 79-02, Revision 1, "Pipe Support Base  
ing Concrete Expansion Anchor Bolts "

Region 4, Dallas, Office of the Director 79/06/21

s IE Bulletin 79-13, "Cracking in Feedwater Sys  
on required  
Region 4, Dallas, Office of the Director 79/06/25

s IE Circular 79-10, "Pipefittings Mfg from  
1 " No action required  
Region 4, Dallas, Office of the Director 79/06/26

s IE Circular 79-11, "Design/Const Interface  
ion required  
Region 4, Dallas, Office of the Director 79/06/27

s IE Circular 79-12, "Potential Diesel Generator  
blem " No action required  
Region 4, Dallas, Office of the Director 79/06/28

s IE Bulletin 79-14, "Seismic Analysis for As-Built  
iping Sys " Action required  
Region 4, Dallas, Office of the Director 79/07/02.

Report of 790612 ltr informing NRC of steps taken to  
as noted in IE Insp Repts 50-445/79-11 &  
Region 4, Dallas, Reactor Construction & Engineering  
79/07/05 1p

nds to NRC 790514 ltr re violation noted in IE Insp  
79-11 & 50-446/79-11 Corrective actions  
lined to evaluate in place condition of portion  
w/o QA knowledge  
as Utilities Generating Co 79/06/12 3pp

s IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Region 4, Dallas, Office of the Director 79/07/11

s IE Circular 79-13, "Replacement of Diesel Fire  
ectors " No action required  
Region 4, Dallas, Office of the Director 79/07/13

s that written responses to IE Bulletin 79-15, Suppl  
ted to IE Div of Reactor Const Insp  
Region 4, Dallas, Office of the Director 79/07/18

ferences, LERs & related correspondence

s PNO-79-67AQ, "Nuclear Incident at TMI "  
Region 4, Dallas, Reactor Construction & Engineering  
79/05/31. 1p

PNO-79-67AR  
Region 4, Dallas, Reactor Construction & Engineering  
79/06/05 1p

PNO-79-67AB, "Nuclear Incident at TMI "  
Region 4, Dallas, Office of the Director 79/06/13

s 790518 verbal communication w/RD Taylor concerning  
possibility that pipe supports may not meet  
nts Investigation & evaluation continue  
Utilities Generating Co 79/06/15 1p

7907030215 Forwards PNO-79-67AT  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/19 1p

7907030382 Notifies that subsequent evaluation of problem w/two  
pressure transmitters has been determined reportable under  
10CFR50.55(e)  
OARY, R J Texas Utilities Generating Co 79/06/25 1p

7907130341 Forwards PNO-79-67AU  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/27 1p

7907110346 Advises of completion of investigation re 790126 telcon  
w/WA Crossman on apparent weld metal defects in Unit 1  
reactor vessel nozzle Matter determined not reportable  
OARY, R J Texas Utilities Generating Co 79/07/02 1p

7907180690 Forwards PNO-79-67AV  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/07/06 1p

7907180552 Confirms 790518 verbal statement that present pipe supports  
may not meet seismic requirements Evaluation is continuing  
OARY, R J Texas Utilities Generating Co 79/07/13 1p

7907190216 Notifies of continued evaluation of possible diesel  
generator cooling problem reported on 790614  
OARY, R J Texas Utilities Generating Co 79/07/13 1p

7907240521 Forwards PNO-79-67AW  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/07/13 1p

7907230298 Notifies of continuation of investigation to ensure that  
pipe wall thickness for project piping specs meets all  
ASME stress requirements Condition is considered potentially  
reportable under 10CFR50.55(e)  
OARY, R J Texas Utilities Generating Co 79/07/17 1p

7907230284 Reports that electrical cable tray hangers found to have  
light partial penetration welds where full penetration welds  
were required by designer Investigation & evaluation will  
continue  
OARY, R J Texas Utilities Generating Co 79/07/18 1p

#### U Congressional/Executive Correspondence

7907260082 Responds to 790509 ltr re power plant design to resist  
tornadoes Discusses tornado design criteria Forwards two  
repts re Apr 1979 tornadoes in TX  
ODSBICK, L V Office of the Executive Director for Operations  
79/06/04 2pp

--7907260091 "Characteristics of Red River Valley Tornadoes as of  
790415 "  
FUJITA, T Affiliation Unknown 79/04/15 3pp

--7907260127 "Tornado Damage Survey of Wichita Falls & Vernon, TX  
Tornadoes of 790410," preliminary rept  
MCDONALD, J R ; MINOR, J E Texas Tech Univ. 79/04/20 3pp

#### DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 2

#### A Application/construction stage documents & correspondence

7907110112 Summary of progress of QA program review Section 9 B 1 will  
be submitted in future amend  
HAABSB, W P Quality Assurance Branch 79/05/21 7pp

7907110164 Forwards second round request for addl info required to  
complete evaluation of application for OL  
BAER, R L Light Water Reactors Branch 2 79/05/31 3pp

--7907110176 Second round request for addl info required to complete  
evaluation of application for OL  
\* Light Water Reactors Branch 2 79/05/31. 3pp.

7907180892 Forwards request for addl info as result of Mechanical  
Engineering Branch review of FSAR Requests amend to FSAR to  
include requested info  
BAER, R L Light Water Reactors Branch 2 79/06/08 3pp

7907270389 Notifies that submittal of electrical, instrumentation &  
control drawings is delayed until 7901231 Postponement not  
expected to impact projected fuel loading schedule  
BAER, R L Light Water Reactors Branch 2 79/06/20 3pp

7907090247 Notices of intention to respond to second round questions by FSAR amend in Sept 1979  
GARY, R J Texas Utilities Generating Co 79/06/29 1p

7907250318 Forwards list of Gibbs & Hill & Westinghouse drawings re dynamic asymmetric loading review of facility coolant supports, per NRC request  
DACKO, B S Texas Utilities Services, Inc 79/07/17 5pp

#### G Adjudicatory correspondence

7907090062 Notices that depositions have been taken from RL Steder of PPO Industries & EV Sherry of Air Products & Chemicals Central Power & Light has furnished NRC-requested documents to City of Brownsville, TX  
RYAN, T O Isham, Lincoln & Deale 79/05/01 1p

7907030185 Forwards ASLB orders Arrangements made for inclusion on svc list w/o encl  
ULMAN, M B Operations & Administrative Division 79/05/09 1p

7907170243 Motion to suppl petition to intervene submitted by Citizens for Fair Util Regulation Contentions are clarified & organized in proper form Certificate of Svc encl  
JACOBSON, N H, FOUKE, R L Citizens for Fair Utility Regulation 79/05/22 4pp

7907180612 First errata to Citizens for Util Regulation suppl to petition to intervene Certificate of Svc encl  
JACOBSON, N H, FOUKE, R L Citizens for Fair Utility Regulation 79/05/22 4pp

790718076B Certificate of Svc for revised page 21 of 790507 suppl to petition to intervene Revised page & affidavit of M Stinson encl  
ELLIS, J Citizens Association for Sound Energy 79/05/23 3pp

7907160207 Motion to amend suppl to petition to intervene submitted by Citizens for Fair Util Regulation Motion supersedes & clarifies 790522 motion to amend Restates contentions in proper form Certificate of Svc encl  
FOUKE, R L Citizens for Fair Utility Regulation 79/05/29 8pp

790717024B Brief re applicability of ALAB-549, submitted by M & C Bishop, O & W Wood & Association of Communities for Reform Now Standing of late interveners should be judged by fairness, not legal technicalities Certificate of Svc encl  
GAY, O M, GARRETT, W L West Texas Legal Services 79/05/30 6pp

7907130164 Memorandum confirming applicability of ALAB-549 to petitions to intervene Standing is based on interests of members living in close proximity to Facility Petitioners should be granted intervenor status Certificate of Svc encl  
ULMAN, M B Operations & Administrative Division 79/06/04 9pp

7907060447 Provides proposed corrections to 790522 prehearing conference transcript  
REYNOLDS, N S Debevoise & Lieberman 79/06/12 4pp

7907060493 Util answer to Citizens for Fair Util Regulation 790529 second motion to amend petition to intervene No contention has been raised which meets requirements of 10CFR2 714(b) Certificate of Svc encl  
REYNOLDS, N S Debevoise & Lieberman 79/06/13 4pp

7907180555 Supports Citizens for Fair Util Regulation 790529 motion to amend 790507 suppl to petition to intervene One good contention is set forth to justify admission as intervenor Good cause has been shown Certificate of svc encl  
CHANDLER, L J Branch 1 ULMAN, M B, Operations & Administrative Division 79/06/18 8pp

7907180777 Notice of appearance of DJ Preister on behalf of State of TX Certificate of Svc encl  
PREISTER, D J Texas, State of 79/06/19 2pp

7907240300 Order granting intervenor status to Citizens Association for Sound Energy, Citizens for Fair Util Regulation, State of TX & Association of Community Organizations for Reform Now Intervenor status is denied to West TX Legal Svc  
COLE, R F, KORNBLITH, L, BOWERS, E S Atomic Safety and Licensing Board Panel 79/06/27 12pp

#### M Antitrust correspondence

7907080444 Submits discovery rept for Apr 1979 No discoveries initiated or received  
BALOUGH, R C Austin, TX 79/05/08 4pp

7907190213 Summarizes Public Utils Board of City of Brownsville, TX discovery progress for Apr 1979 Certificate of Svc encl  
POIRIER, M R Spiegel & McDiarmid 79/05/14 6pp

7907110152 Houston Lighting & Power addl answers to NRC 790115 initial interrogatories Affidavit & Certificate of Svc encl  
COPELAND, J G Baker & Botts 79/05/24 27pp

7907180879 TX Utils Generating Co & subsidiaries supplemental answer to NRC initial interrogatories Affidavit, Certificate of Svc & Apps A & B encl  
SAMPELS, M D Worsham, Forsythe & Sampels KNOTTS, J B Debevoise & Lieberman SCARTH, E D Texas Utilities Co 79/05/25 18pp

7907180040 DDJ rept re progress made on discovery during May 1979 Rept submitted per ASLB 780621 order  
HARRIS, J L Justice, Dept of 79/06/01 6pp

7907170117 Public Utils Board of City of Brownsville second application for issuance of subpoena for production of documents by El Paso Electric Draft of subpoena encl  
POIRIER, M R Spiegel & McDiarmid 79/06/12 18pp

--7907170154 Public Utils Board of City of Brownsville application for issuance of subpoena for production of documents by El Paso Electric Certificate of Svc encl  
POIRIER, M R Spiegel & McDiarmid 79/06/13 10pp

7907020005 TX Utils Generating Co first set of interrogatories & production of documents, directed to TEX-LA Electric Cooperative, Seventeen Member Cooperatives & any successor entities Certificate of Svc encl  
KNOTTS, J B Debevoise & Lieberman WORSHAM, J I, SAMPELS, M D Worsham, Forsythe & Sampels 79/06/18 12pp

7907190435 Houston Lighting & Power & TX Utils Generating Co joint application for issuance of subpoenas calling for production of documents re util industry competition, access to plants & interstate operation Certificate of Svc & drafts encl  
COPELAND, J G Baker & Botts BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 79/06/18 20pp

7907190451 Order per 790601 conference ruling on motions & responses filed Mar-Apr 1979 by Houston Lighting & Power, TX Utils, Gulf States Util, Central Power & Light & NRC. Amends 790404 order re schedule of proceedings  
WOLFE, S J Atomic Safety and Licensing Board Panel NRC 79/06/25 4pp

7907190834 Forwards Public Utils Board of City of Brownsville, TX 790626 supplemental response to Houston Lighting & Power first request for production of documents & first set of interrogatories  
WHITE, S G Spiegel & McDiarmid 79/06/26 1p

--7907190846 Public Utils Board of City of Brownsville, TX supplemental response to Houston Lighting & Power first request for production of documents & first set of interrogatories Affidavit & Certificate of Svc encl  
JABLON, R A Texas, State of 79/06/26 19pp

7907260038 DDJ & NRC joint application for issuance of subpoenas for testimony & production of documents re issue of competition, structure of electric util industry & plant access w/ certificate of Svc & drafts of subpoenas  
LESSY, R P Anti-Trust Division HARRIS, J L Justice, Dept of 79/07/03 89pp

7907260014 TX Utils Generating Co discovery rept for June 1979 Certificate of Svc encl  
KNOTTS, J B Debevoise & Lieberman 79/07/06 8pp

#### G Inspection reports, IE Bulletins & correspondence

7907310595 Requests extension to license rept due date until 790705.  
GARY, R J Texas Utilities Generating Co 79/05/07 1p

7907110671 Forwards IE Insp Repts 50-445/79-06 & 50-446/79-06 on 790301-30 & notice of violation.  
SETALE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/05/10 2pp

--7907110681 Notice of violation from insp on 790501-30  
\* Region 4, Dallas, Office of the Director 79/05/10 1p

--7907110693 IE Insp Repts 50-445/79-06 & 50-446/79-06 on 790301-30 Noncompliance noted: Failure to follow GC insp procedures of cable tray hangers  
TAYLOR, R O, MARTIN, L E, CROSSMAN, W A Region 4, Dallas, Office of the Director 79/05/10 8pp.



7907300242 Forwards IE Insp Repts 50-445/79-11 & 50-446/79-11 on 790402-03 & 13-23 & notice of violation SEIDLE, W C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/14 2pp

--7907300280 Notice of violation from insp on 790402-03 & 13-23 \* Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/14 1p

--7907300256 IE Insp Repts 50-445/79-11 & 50-446/79-11 on 790402-03 & 13-23 Noncompliance noted Failure to implement QA Program TAYLOR, R G, TOMLINSON, D P, CROSSMAN, W A Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/10 12pp

7907110656 Forwards 790907 response to IE Bulletin 79-03, re ASME SA-312 Type 304 piping SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/21 1p

--7907110660 Responds to IE Bulletin 79-03 re ASME SA-312 Type 304 stainless steel pipe planned for use Complete rept to be completed 790531 GARY, R J Texas Utilities Generating Co 79/05/07 4pp

7907310600 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers planned for use on any safety-related sys GARY, R J Texas Utilities Generating Co 79/05/22 1p

7907030129 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/29 1p

7907200365 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31 1p

7907250498 Forwards IE Insp Repts 50-445/79-14 & 50-446/79-14 on 790515-18 No noncompliance noted SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/01 2pp

--7907250518 IE Insp Repts 50-445/79-14 & 50-446/79-14 on 790515-18 No noncompliance noted Major areas inspected safety-related const activities pertaining to installation & insp of cable tray & conduit supports & electrical GC insp training MARTIN, L E, TAYLOR, R G, CROSSMAN, W A Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/30 3pp

7907190411 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06 1p

7907060023 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07 1p

7907260589 Forwards IE Insp Repts 50-445/79-09 & 50-446/79-09 on 790405-0507 No noncompliance noted SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/08 2pp

--7907260561 IE Insp Repts 50-445/79-09 & 50-446/79-09 on 790405-0507 No noncompliance noted Major areas inspected, allegations by former RW Hunt employees re insp & testing improprieties appearing in Fort Worth Star-Telegram on 790404-06 & 08 STEWART, R C, CROSSMAN, W A, HALL, R E Region 4, Dallas, Office of the Director 79/06/06 35pp

7907050566 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys. " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907050517 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20 1p

7907300229 Ack receipt of 790603 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-445/79-06 & 50-446/79-06 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/20 1p

--7907300236 Responds to NRC 790510 ltr re violation noted in IE Insp Repts 50-445/79-06 & 50-446/79-06 Corrective actions cable tray supports inspected for welding & location/elevation instructions revised to ensure insp GARY, R J Texas Utilities Generating Co 79/06/05 4pp

7907050489 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21 1p

7907120604 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25 1p

7907110256 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26 1p

7907180266 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27 1p

7907100520 Forwards IE Circular 79-12, "Potential Diesel Generator Turbcharger Problem " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28 1p

7907110300 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02 1p

7907270294 Ack receipt of 790612 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/79-11 & 50-446/79-11 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/05 1p

--7907270305 Responds to NRC 790514 ltr re violation noted in IE Insp Repts 50-445/79-11 & 50-446/79-11 Corrective actions, consultant retained to evaluate inplace condition of portion of dome altered w/o QA knowledge GARY, R J Texas Utilities Generating Co 79/06/12 3pp

7907190508 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11 1p

7907240410 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13 1p

7907270398 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18 1p

B Reportable occurrences, LERs & related correspondence

7907030262 Forwards PNO-79-67A0, "Nuclear Incident at TH1 " SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/31 1p

7907020309 Forwards PNO-79-67AR SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/05 1p

7907050575 Forwards PNO-79-67AB, "Nuclear Incident at TH1 " SEIDLE, W C Region 4, Dallas, Office of the Director 79/06/13 1p

7907260447 Confirms 790518 verbal communication w/RG Taylor concerning potential RO re possibility that pipe supports may not meet seismic requirements. Investigation & evaluation continue GARY, R J Texas Utilities Generating Co 79/06/15 1p

7907030215 Forwards PNO-79-67AT SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/19 1p

## DOCKETED ITEMS

7907030382 Notifies that subsequent evaluation of problem w/two pressure transmitters has been determined reportable under 10CFR50.55(e)  
GARY, R J Texas Utilities Generating Co 79/06/25 1p

7907130341 Forwards PNO-79-67AU  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/27 1p

7907110346 Advises of completion of investigation re 790126 telcon w/HA Crossman on apparent weld metal defects in Unit 1 reactor vessel nozzle. Matter determined not reportable  
GARY, R J Texas Utilities Generating Co 79/07/02 1p

7907180690 Forwards PNO-79-67AV  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/06 1p

7907180532 Confirms 790518 verbal statement that present pipe supports may not meet seismic requirements. Evaluation is continuing  
GARY, R J Texas Utilities Generating Co 79/07/13 1p

7907190216 Notifies of continued evaluation of possible diesel generator cooling problem reported on 790614  
GARY, R J Texas Utilities Generating Co 79/07/13 1p

7907240521 Forwards PNO-79-67AW  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/13 1p

7907230298 Notifies of continuation of investigation to ensure that pipe wall thickness for project piping specs meets all ASME stress requirements. Condition is considered potentially reportable under 10CFR50.55(e)  
GARY, R J Texas Utilities Generating Co 79/07/17 1p

7907230284 Reports that electrical cable tray hangers found to have light partial penetration welds where full penetration welds were required by designer. Investigation & evaluation will continue  
GARY, R J Texas Utilities Generating Co 79/07/18 1p

#### U Congressional/Executive Correspondence

7907260082 Responds to 790509 ltr re power plant design to resist tornadoes. Discusses tornado design criteria. Forwards two repts re Apr 1979 tornadoes in TX  
QOSBICK, L V Office of the Executive Director for Operations 79/06/04 2pp

#### DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907060289 Forwards questions re ecological monitoring site. Requests response by 790716  
BROCKSEN, R W Electric Power Research Institute 79/06/25 2pp

#### DOCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2

##### A Application/construction stage documents & correspondence

7907060289 Forwards questions re ecological monitoring site. Requests response by 790716  
BROCKSEN, R W Electric Power Research Institute 79/06/25 2pp

7907090062 Notifies that depositions have been taken from RL Steder of PPG Industries & EV Sherry of Air Products & Chemicals. Central Power & Light has furnished NRC-requested documents to City of Brownsville, TX.  
RYAN, T O Isham, Lincoln & Beale 79/05/01 1p

#### DOCKET 50-451 SUMMIT NUCLEAR POWER STATION, UNIT 2

##### Q Inspection reports, IE Bulletins & correspondence

7907180429 Forwards IE Insp Rept 50-451/79-03 on 790410-12 & notice of violation  
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/09 2pp

--7907180449 Notice of violation from insp on 790410-12  
\* Region 3, Chicago, Office of the Director 79/05/07 1p

--7907180451 IE Insp Rept 50-451/79-03 on 790410-12 Noncompliance noted failure to properly control tools used in activities affecting quality  
VANDEL, T E, WESCOTT, H M, KNOP, R C Region 3, Chicago, Office of the Director 79/05/07 10pp

#### DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2

##### A Application/construction stage documents & correspondence

7907100685 Forwards request for addl info to complete review of Sections 13.2 & 13.5 of PSAR through Amend 14  
COLLINS, P F Operator Licensing Branch 79/05/16 3pp

##### Q Adjudicatory correspondence

7907190139 Advises of change of address for counsel, as of 790521  
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 79/05/22 2pp

#### DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

##### A Application/construction stage documents & correspondence

7907100685 Forwards request for addl info to complete review of Sections 13.2 & 13.5 of PSAR through Amend 14  
COLLINS, P F Operator Licensing Branch 79/05/16 3pp

##### Q Adjudicatory correspondence

7907190139 Advises of change of address for counsel, as of 790521  
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 79/05/22 2pp

#### DOCKET 50-454 BYRON STATION, UNIT 1

##### A Application/construction stage documents & correspondence

7907110051 Forwards request for addl info re application for OL  
VAROA, S A Light Water Reactors Branch 4 79/06/01 16pp

7907050374 Advises of decision to delay fuel load dates by one year as result of NRC suspension of licensing review until Jan 1980  
REED, C Commonwealth Edison Co 79/06/27 4pp

7907170038 Notifies that ASME Code Case N-240 will be referenced in FSAR. Code exempts certain piping from hydrostatic testing  
NAUGHTON, W F Commonwealth Edison Co 79/07/09 1p

##### Q Adjudicatory correspondence

7907130037 Notice of reconstitution of ARLB ME Miller & RF Cole replaced E Luton & FC Daiber, respectively  
LAZAR, R M Atomic Safety and Licensing Board Panel 79/06/07 1p

7907180844 Comm Ed motion requesting Board to establish reasonable schedule for filing contentions & responses. Suggests 790702 for contentions & 790720 for responses. Certificate of Svc encl  
MURPHY, P M, BIELANSKI, A P Isham, Lincoln & Beale 79/06/07 6pp

7907180373 Notification of 790725 special prehearing conference. Suppls to intervenors petitions must be filed 15 days before conference. Members of public may request to make limited appearance  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/08 2pp

7907190645 Notification of inability to continue as intervention chairman. B Von Zeilen will receive future info re prehearing. Certificate of Svc encl  
SHINEPLUG, M DeKalb Area Alliance for Responsible Energy 79/06/14 2pp

##### K Utility Final Safety Analysis Report (FSAR) & amendments

7907230158 Forwards FSAR Amend 21 revising CP & OL  
REED, C Commonwealth Edison Co 79/07/20 2pp

--7907230173 FSAR Amend 21 revising CP & OL  
\* Commonwealth Edison Co 79/07/20 650pp

##### Q Inspection reports, IE Bulletins & correspondence

7907180336 Forwards IE Insp Repts 50-454/79-07 & 50-455/79-07 on 790501-03. No noncompliance noted.  
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/17 2pp

# DOCKETED ITEMS

251

--7907180357 IE Insp Repts 50-454/79-07 & 50-455/79-07 on 790501-03 No noncompliance noted Major areas inspected Pittsburgh Testing Lab nondestructive examination procedures, work activities, personnel certifications & radiographs of welds  
WARD, K D , DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/15 8pp

7907160155 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Some valves have been identified Correct weights will be used in piping analysis & addl supports will be added  
REED, C Commonwealth Edison Co 79/05/29 2pp

7907200287 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907160264 Ack receipt of 790317 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/79-06 & 50-455/79-06  
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/06 1p

--7907160273 Responds to NRC 790420 ltr re violations noted in IE Insp Repts 50-454/79-06 & 50-455/79-06 Corrective actions storage surveillance increased  
REED, C Commonwealth Edison Co 79/05/17 3pp

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020237 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907190010 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers are not used at LaSalle, but are used at Byron & Braidwood as main supply air operated circuit breakers  
REED, C Commonwealth Edison Co 79/06/18 3pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050466 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

## DOCKET 50-455 BYRON STATION, UNIT 2

### A Application/construction stage documents & correspondence

7907110051 Forwards request for addl info re application for DL  
VARGA, S A Light Water Reactors Branch 4 79/06/01 16pp

7907050374 Advises of decision to delay fuel load dates by one year as result of NRC suspension of licensing review until Jan 1980  
REED, C Commonwealth Edison Co 79/06/27 4pp

7907170038 Notifies that ASME Code Case N-240 will be referenced in FSAR Code exempts certain piping from hydrostatic testing  
NAUGHTON, W F Commonwealth Edison Co 79/07/07 1p

### O Adjudicatory correspondence

7907130037 Notice of reconstitution of ASLB ME Miller & RF Cole replace E Lutan & FC Daiber, respectively  
LAZO, R M Atomic Safety and Licensing Board Panel 79/06/07 1p

7907180844 Comm Ed motion requesting Board to establish reasonable schedule for filing contentions & responses Suggests 790702 for contentions & 790720 for responses Certificate of Svc encl  
MURPHY, P M , BIELANSKI, A P Isham, Lincoln & Beale 79/06/07 6pp

7907180373 Notification of 790725 special prehearing conference Suppl to intervenors petitions must be filed 15 days before conference Members of public may request to make limited appearance  
LUTON, E. Atomic Safety and Licensing Board Panel 79/06/08 2pp

7907190645 Notification of inability to continue as intervention chairman B Von Zellen will receive future info re proceeding Certificate of Svc encl  
SHINEFLUO, M DeKalb Area Alliance for Responsible Energy 79/06/14 2pp

### K Utility Final Safety Analysis Report (FSAR) & amends

7907230158 Forwards FSAR Amend 21 revising CP & DL  
REED, C. Commonwealth Edison Co 79/07/20 2pp

--7907230173 FSAR Amend 21 revising CP & DL.  
\* Commonwealth Edison Co 79/07/20 650pp

### G. Inspection reports, IE Bulletins & correspondence

7907180336 Forwards IE Insp Repts 50-454/79-07 & 50-455/79-07 on 790501-03, No noncompliance noted  
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/17 2pp

--7907180357 IE Insp Repts 50-454/79-07 & 50-455/79-07 on 790501-03 No noncompliance noted Major areas inspected Pittsburgh Testing Lab nondestructive examination procedures, work activities, personnel certifications & radiographs of welds  
WARD, K D , DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/15 8pp

## DOCKETED ITEMS

7907160135 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Some valves have been identified. Correct weights will be used in piping analysis & addl supports will be added.  
REED, C Commonwealth Edison Co 79/05/29 2pp

7907200287 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907160264 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-434/79-06 & 50-455/79-06  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/06 1p

--7907160273 Responds to NRC 790420 ltr re violations noted in IE Insp Repts 50-454/79-06 & 50-455/79-06. Corrective actions storage surveillance increased.  
REED, C Commonwealth Edison Co 79/05/17 3pp.

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils.  
PAPPAS, H Region 3, Chicago, Office of the Director. 79/06/08 2pp

7907020237 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys."  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

790706010 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers are not used at LaSalle, but are used at Byron & Braidwood as in supply air operated circuit breakers.  
ED, C Commonwealth Edison Co 79/06/18 3pp

7907060409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p.

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/25. 1p

060303 Forwards IE Circular 79-10, "Pipe Fittings Mfg from acceptable Matl." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907060466 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/27 1p.

180392 Forwards IE Circular 79-12, "Potential Diesel Generator Recharger Problem." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p.

130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/02 1p.

790710311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/11. 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/19 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

## DOCKET 50-496 BRAIDWOOD STATION, UNIT 1

## A Application/construction stage documents &amp; correspondence

7907110031 Forwards request for addl info re application for OL VAROAS A Light Water Reactors Branch 4 79/06/01 16pp.

7907050374 Advises of decision to delay fuel load dates by one year as result of NRC suspension of licensing review until Jan 1980.  
REED, C Commonwealth Edison Co 79/06/27 4pp

7907170038 Notifies that ASME Code Case N-240 will be referenced in FSAR. Code exempts certain piping from hydrostatic testing.  
NAUGHTON, W F Commonwealth Edison Co 79/07/09 1p

## Q Adjudicatory correspondence

7907130037 Notice of reconstitution of ASLB ME Miller & RF Cole replace E Lutton & FC Daiber, respectively.  
LAZD, R M Atomic Safety and Licensing Board Panel 79/06/07 1p

7907180828 Commonwealth Edison motion requesting Board to establish schedule for filing contentions & responses. Suggests 790702 for contentions & 790720 for responses. Certificate of Svc encl.  
MURPHY, P M, BIELAWSKI, A P Isham, Lincoln & Deale 79/06/07 6pp

7907060246 Notice of 790726 special prehearing conference in Joliet, IL. Suppls to intervenor petitions must be filed no later than 15 days prior to conference. Limited appearance may be requested at time of conference.  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/08 2pp

## K Utility Final Safety Analysis Report (FSAR) &amp; amendments

7907230158 Forwards FSAR Amend 21 revising CP & OL.  
REED, C Commonwealth Edison Co 79/07/20 2pp

--7907230173 FSAR Amend 21 revising CP & OL.  
\* Commonwealth Edison Co 79/07/20 650pp

## Q. Inspection reports, IE Bulletins &amp; correspondence

7907160135 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Some valves have been identified. Correct weights will be used in piping analysis & addl supports will be added.  
REED, C Commonwealth Edison Co 79/05/29 2pp.

7907230741 Forwards IE Insp Repts 50-436/79-05 & 50-457/79-05 on 790419-20 & 26-27. No noncompliance noted.  
FIORELLI, G Region 3, Chicago, Office of the Director 79/05/30 2pp

--7907230746 IE Insp Repts 50-436/79-05 & 50-457/79-05 on 790419-20 & 26-27. No noncompliance noted. Major areas inspected: electrical contractor QA program including organizational structure.  
JONES, C E, BARRETT, P A, MAXWELL, O F Region 3, Chicago, Office of the Director 79/05/30 14pp

7907200287 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities." No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907020237 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907180522 Requests that encl cover sheet replace current cover sheet for IE Insp Rept 50-456/79-05  
FIORELLI, G Region 3, Chicago, Office of the Director 79/06/13 2pp

7907190010 Responds to IE Bulletin 79-09 OE Type AK-2 circuit breakers are not used at LaSalle, but are used at Byron & Braidwood as main supply air operated circuit breakers  
REED, C Commonwealth Edison Co 79/06/18 3pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050466 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260193 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants, " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

#### DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

#### A Application/construction stage documents & correspondence

7907110031 Forwards request for addl info re application for OL  
VARGA, B A Light Water Reactors Branch 4 79/06/01 16pp

7907050374 Advises of decision to delay fuel load dates by one year as result of NRC suspension of licensing review until Jan 1980  
REED, C Commonwealth Edison Co 79/06/27 4pp

7907170038 Notifies that ASME Code Case N-240 will be referenced in FSAR Code exempts certain piping from hydrostatic testing  
NAUGHTON, W F Commonwealth Edison Co 79/07/09 1p

#### G Adjudicatory correspondence

7907130037 Notice of reconstitution of ASLB ME Miller & RF Cole replace E Luton & FC Daiber, respectively  
LAZD, R M Atomic Safety and Licensing Board Panel 79/06/07 1p

7907180828 Commonwealth Edison motion requesting Board to establish schedule for filing contentions & responses Suggests 790702 for contentions & 790720 for responses Certificate of Svc encl  
MURPHY, P M, BIELAWSKI, A P Isham, Lincoln & Beale 79/06/07 6pp

7907060246 Notice of 790726 special prehearing conference in Joliet, IL Suppls to intervenor petitions must be filed no later than 15 days prior to conference Limited appearance may be requested at time of conference  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/08 2pp

#### K Utility Final Safety Analysis Report (FSAR) & amends

7907230158 Forwards FSAR Amend 21 revising CP & DL  
REED, C Commonwealth Edison Co 79/07/20 2pp

--7907230173 FSAR Amend 21 revising CP & DL  
\* Commonwealth Edison Co 79/07/20 650pp

#### G Inspection reports, IE Bulletins & correspondence

7907160155 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Some valves have been identified Correct weights will be used in piping analysis & addl supports will be added  
REED, C Commonwealth Edison Co 79/05/29 2pp

7907230741 Forwards IE Insp Repts 50-456/79-05 & 50-457/79-05 on 790419-20 & 26-27 No noncompliance noted  
FIORELLI, G Region 3, Chicago, Office of the Director 79/05/30 2pp

--7907230746 IE Insp Repts 50-456/79-05 & 50-457/79-05 on 790419-20 & 16-27 No noncompliance noted Major areas inspected electrical contractor QA program, including organizational structure  
JONES, C E, BARRETT, P A, MAXWELL, G F Region 3, Chicago, Office of the Director 79/05/30 14pp

7907260287 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190224 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves), " Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240241 Forwards IE Info Notice 79-15, "Deficient Procedures, " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils.  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

## DOCKETED ITEMS

7907020237 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " KEPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907180322 Requests that encl cover sheet replace current cover sheet for IE Insp Rept 50-486/79-05 FIGURELLI, G Region 3, Chicago, Office of the Director 79/06/13 2pp

7907190010 Responds to IE Bulletin 79-09 OE Type AK-2 circuit breakers are not used at LaSalle, but are used at Byron & Braidwood as main supply air operated circuit breakers REED, C Commonwealth Edison Co 79/06/18 3pp

7907020409 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " KEPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120198 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required KEPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907120680 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required KEPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060303 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required KEPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050466 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required KEPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907180392 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required KEPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130236 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required KEPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907310311 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required KEPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310403 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required KEPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260153 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp KEPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260336 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required KEPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

07250217 Forwards IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required. KEPLER, J G Region 3, Chicago, Office of the Director 79/07/20 1p

IKET 50-486 RIVER BEND STATION, UNIT 1

Application/construction stage documents & correspondence

79090136 Responds to 790328 request for withholding of rept, Accelerated Aging Procedure (cc-323 74-3A) " Review based on 10CFR2 790 indicates insufficient justification for withholding. ARGON, B A Light Water Reactors Branch 4 79/05/17 3pp

7907030131 Forwards comments re justification for continued licensing & operation for each Category A task action plan Necessary for SER to include statement of status of resolution in each Category A generic item BRENNER, L Office of the Executive Legal Director 78/03/10 22pp

Q Inspection reports, IE Bulletins & correspondence

7907030122 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/29 1p

7907200345 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31 1p

7907190393 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06 1p

7907060013 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07 1p

7907050560 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907050506 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20 1p

7907050493 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21 1p

7907120596 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25 1p

7907110242 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26 1p

7907180249 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27 1p

7907100314 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28 1p

7907110289 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02 1p

7907190493 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11 1p

7907240302 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13 1p

7907270391 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp. SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18 1p

# DOCKETED ITEMS

2

## S Reportable occurrences, LERs & related correspondence

7907260768 Deficiency re cadsleeve welds mfg by Graver Energy Sys & produced by semiautomatic welding procedure All defective cadsleeves will be replaced using manual welding process w/increased inprocess controls  
\* Gulf States Utilities Co 79/06/27 5pp

7907030259 Forwards PNO-79-67AQ, "Nuclear Incident at TMI " SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/31 1p

7907020303 Forwards PNO-79-67AR SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/05 1p

7907050570 Forwards PNO-79-67AB, "Nuclear Incident at TMI " SEIDLE, W C Region 4, Dallas, Office of the Director 79/06/13 1p

7907030205 Forwards PNO-79-67AT SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/19 1p

7907130334 Forwards PNO-79-67AU SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/27 1p

7907260763 Forwards deficiency rept re cadsleeve welds, originally reported 790531 All cadsleeves will be rejected & replaced WEIGAND, J G Gulf States Utilities Co 79/06/27 1p

7907180683 Forwards PNO-79-67AV SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/06 1p

7907240514 Forwards PNO-79-67AW SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/13 1p

## DOCKET 50-459 RIVER BEND STATION, UNIT 2

### A Application/construction stage documents & correspondence

7907050136 Responds to 790328 request for withholding of rept, "Accelerated Aging Procedure (cc-323 74-3A) " Review based on 10CFR2 790 indicates insufficient justification for withholding  
VARGO, S A Light Water Reactors Branch 4 79/05/17 3pp

7907030131 Forwards comments re justification for continued licensing & operation for each Category A task action plan Necessary for SER to include statement of status of resolution in each Category A generic item  
BRENNER, L Office of the Executive Legal Director 78/03/10 22pp

### Q Inspection reports, IE Bulletins & correspondence

7907030122 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/29 1p

7907200345 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required.  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31 1p.

7907190393 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06 1p.

7907060013 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07 1p.

7907050560 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907050506 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate, " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20 1p.

7907050483 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21 1p

7907120596 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25 1p

7907110242 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26 1p

7907180249 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27 1p

7907100514 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28 1p

7907110289 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02 1p

7907190493 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11 1p

7907240302 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13 1p

7907270391 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18 1p

## S Reportable occurrences, LERs & related correspondence

7907030259 Forwards PNO-79-67AQ, "Nuclear Incident at TMI " SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/31 1p

7907020303 Forwards PNO-79-67AR SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/05 1p

7907050570 Forwards PNO-79-67AB, "Nuclear Incident at TMI " SEIDLE, W C Region 4, Dallas, Office of the Director 79/06/13 1p

7907030205 Forwards PNO-79-67AT SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/19 1p

7907130334 Forwards PNO-79-67AU SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/27 1p

7907180683 Forwards PNO-79-67AV SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/06 1p

7907240514 Forwards PNO-79-67AW SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/13 1p.

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

G. Inspection reports, IE Bulletins & correspondence

7907120396 Forwards IE Insp Repts 50-460/79-02 & 50-513/79-02 on 790212-16 & notice of violation  
SPENCER, O. S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/03 2pp

--7907120406 Notice of violation from insp on 790212-16  
\* Region 5, San Francisco, Office of the Director 79/03/30 2pp

DOCKETED ITEMS

--7907120419 IE Insp Repts 50-460/79-02 & 50-513/79-02 on 790212-16 Noncompliance noted failure to follow procedures re design control & document control & failure to include applicable requirements in procurement documents HAYNES, R C , KIRSCH, D F , ECKHARDT, J H Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/03 33pp

--7907120456 Responds to NRC 790403 ltr re violations noted in IE Insp Repts 50-460/79-02 & 50-513/79-02 Corrective actions field change notice 257-1-79-02B revised to reflect correct quality class GA reviewed & approved RENBERGER, D L Washington Public Power Supply System 79/05/09 6pp

--7907120471 Act 790509 ltr informing NRC of steps taken to correct items listed in NRC 790403 ltr ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/31 2pp

7907090237 Responds to IE Bulletin 79-04 No Velan swing check valves used Nine testable check valves will be provided by Velan to be used in HPCB, LPCB, reactor core isolation cooling & RHR Seismic Category 1 piping sys RENBERGER, D L Washington Public Power Supply System 79/05/25 2pp

7907090275 Responds to IE Bulletins 78-12, 12A & 12B No reason to suspect atypical weld wire was used in fabrication of reactor vessels RENBERGER, D L Washington Public Power Supply System 79/05/29 1p

7907200379 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/31 1p

7907190436 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06 1p

7907060036 Forwards IE Info Notice 79-15, "Deficient Procedures. " No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07 1p

7907020271 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907020453 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p

7907120017 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/21 1p

7907120630 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/23 1p.

7907060226 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907050497 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/27 1p

7907100534 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/28 1p

7907130222 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p

7907180711 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action Required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/11 1p

7907310401 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260286 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/18 1p

5 Reportable occurrences, LERs & related correspondence

7907020291 Forwards PNO-79-67AR ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/05 1p

7907030200 Forwards PNO-79-67AB ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907030244 Forwards PNO-79-67AT, "Nuclear Incident at TMI " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/19 1p

7907050543 Forwards PNO-79-67AU ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907130390 Forwards PNO-79-67AV ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/03 1p

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

7907030116 FOIA request for documents re plant safety, generic safety of BWRs & GE BWRs, NRC list of generic unresolved safety problems for BWRs & GE BWRs & documents re instruction of designers, engineers, builders or operators of GE BWRs PENNER, P Prairie Alliance 79/05/04 1p.

7907190166 FOIA request for documents pertaining to safety of facility & generic safety of BWRs PENNER, P Prairie Alliance 79/05/04 1p

7907050200 Responds to 790426 ltr re radioactive releases from coal-fired power plants. Forwards ORNL-5315, "Radiological Impact of Airborne Effluents of Coal-Fired & Nuclear Power Plants," & FES W/o encl REGAN, W H Environmental Projects Branch 2 79/05/31 2pp

7907240373 Notification of 790612-13 meeting w/IL Power Co at Clinton, IL to assess const status BUCKLEY, B C Light Water Reactors Branch 1, 79/06/08 4pp.

7907030117 Responds to FOIA request for documents released to public re facilities not included in docket files Forwards list of documents & sources from which they may be obtained FELTON, J M Division of Rules and Records 79/06/11 3pp.

7907180199 Notification of 790629 meeting w/util in Bethesda, MD to discuss findings of caseload forecast panel during 790612-13 site visit BUCKLEY, B C Light Water Reactors Branch 1, 79/06/26 2pp

7907190171 Responds to 790504 FOIA request for documents pertaining to facility safety & three other categories of documents Forwards list of documents re Rasmussen rept available for public insp in PDR FELTON, J M Division of Rules and Records. 79/06/30 3pp

0. Inspection reports, IE Bulletins & correspondence

7907190250 Responds to IE Bulletin 79-04 re improper weights for check valves mfg by Velan Engineering No Velan check valves are used WULLER, G E Illinois Power Co 79/05/29 1p



7907200318 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31  
1p

7907190269 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907261011 IE Insp Rept 50-461/79-05 on 790508-11 No noncompliance noted Major areas inspected review replacement nozzle inlet safe-ends & procedures for safety-related structures  
WESTCOTT, H M, ERB, C, KNOP, R C Region 3, Chicago, Office of the Director 79/06/06 9pp

7907240425 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/07.  
1p

7907260999 Forwards IE Insp Rept 50-461/79-05 on 790508-11 No noncompliance noted  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/07 2pp.

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utility  
PAPPAS, H Region 3, Chicago, Office of the Director. 79/06/08.  
2pp

7907020254 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11  
1p

7907020429 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20  
1p

7907120233 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21.  
1p

7907130125 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/25  
1p

7907060314 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/26  
1p

7907050474 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27  
1p.

7907180418 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/28  
1p

7907130270 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/02  
1p.

7907310337 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required,  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310411 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/07/13  
1p

7907260189 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p.

7907260394 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

#### DOCKET 50-462 CLINTON POWER STATION, UNIT 2

#### A Application/construction stage documents & correspondence

7907030116 FOIA request for documents re plant safety, generic safety of BWRs & GE BWRs, NRC list of generic unresolved safety problems for BWRs & GE BWRs & documents re instruction of designers, engineers, builders or operators of GE BWRs  
PENNER, P Prairie Alliance 79/05/04 1p

7907190166 FOIA request for documents pertaining to safety of facility & generic safety of BWRs  
PENNER, P Prairie Alliance 79/05/04 1p

7907030200 Responds to 790426 ltr re radioactive releases from coal-fired power plants Forwards ORNL-5315, "Radiological Impact of Airborne Effluents of Coal-Fired & Nuclear Power Plants," & FES W/b encl  
REGAN, W H Environmental Projects Branch 2 79/05/31. 2pp

7907030117 Responds to FOIA request for documents released to public re facilities not included in docket files Forwards list of documents & sources from which they may be obtained  
FELTON, J M Division of Rules and Records. 79/06/11 3pp

7907190171 Responds to 790504 FOIA request for documents pertaining to facility safety & three other categories of documents Forwards list of documents re Rasmussen rept available for public insp in PDR  
FELTON, J M Division of Rules and Records 79/06/30 3pp

#### B Inspection reports, IE Bulletins & correspondence

7907190250 Responds to IE Bulletin 79-04 re improper weights for check valves mfg by Velan Engineering No Velan check valves are used  
WULF, G E Illinois Power Co 79/05/29 1p

7907200318 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31  
1p

7907190269 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves), " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240425 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07  
1p.

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utility  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp

7907020254 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11  
1p

7907020429 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/20.  
1p

7907120233 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required,  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907130125 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping," No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25.  
1p.

7907060314 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p.

## DOCKETED ITEMS

7907050474 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27  
1p

7907180418 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130270 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p

7907310337 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310411 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260189 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907260394 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

## DOCKET 50-463 FULTON GENERATING STATION, UNIT 1

## G Adjudicatory correspondence

7907180600 Util answer to Save Solanco Environ Conservation Fund 790514 motion to terminate docket Requests response due date of 790604, due to delay in receipt of petition Certificate of Svc encl  
IRWIN, D P Hunton & Williams 79/05/25 4pp

7907130161 Response to Save Solanco Environ Conservation Fund 790514 motion to terminate docket Ruling on application for early site review should be deferred pending NRC review Seeks denial of certification Certificate of Svc encl  
GRAY, J R Branch 1 79/06/04 15pp

7907130056 Philadelphia Electric Co motion to file motion out of time in opposition to petition to terminate docket  
IRWIN, D P Hunton & Williams 79/06/05 1p

--7907130070 Opposition by util to intervenor Save Solanco Environ Conservation Fund 790524 motion to terminate docket Petition presents no legal basis for relief Arguments are outside ASLB jurisdiction & are premature  
IRWIN, D P Hunton & Williams 79/06/05 22pp

--7907130077 Responds to 780130 ltr re site info intends to file amend to CP application for adjudicatory early site review Terminating proceedings would waste applicable work already completed  
EVERETT, J L Philadelphia Electric Co 78/03/08 4pp

7907160284 Response to util 790605 motion to file out of time Since one day delay in util response will not prejudice proceedings, NRC does not oppose motion Certificate of Svc encl  
GRAY, J R Branch 1 79/06/11 3pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907050446 Supplements response to IE Bulletin 79-08 Review under way No Tech Spec changes anticipated  
DALTROFF, S L Philadelphia Electric Co 79/05/14, 1p

## U Congressional/Executive Correspondence

7907310091 Responds to 790529 ltr urging denial of early site review requests for facility End result of review will be staff position paper on site suitability, not CP Regulations require review for which proper application has been made  
GOSSICK, L V Office of the Executive Director for Operations 79/06/29 2pp

--7907310104 Urges NRC to deny any early site review requests for facility  
SCHWEIKER, R S Senate 79/05/29 1p

## DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

## G Adjudicatory correspondence

7907180600 Util answer to Save Solanco Environ Conservation Fund 790514 motion to terminate docket Requests response due date of 790604, due to delay in receipt of petition Certificate of Svc encl  
IRWIN, D P Hunton & Williams 79/05/25, 4pp

7907130161 Response to Save Solanco Environ Conservation Fund 790514 motion to terminate docket Ruling on application for early site review should be deferred pending NRC review Seeks denial of certification Certificate of Svc encl  
GRAY, J R Branch 1 79/06/04 15pp

7907130056 Philadelphia Electric Co motion to file motion out of time in opposition to petition to terminate docket  
IRWIN, D P Hunton & Williams 79/06/05 1p

--7907130070 Opposition by util to intervenor Save Solanco Environ Conservation Fund 790524 motion to terminate docket Petition presents no legal basis for relief Arguments are outside ASLB jurisdiction & are premature  
IRWIN, D P Hunton & Williams 79/06/05 22pp

--7907130077 Responds to 780130 ltr re site info intends to file amend to CP application for adjudicatory early site review Terminating proceedings would waste applicable work already completed.  
EVERETT, J L Philadelphia Electric Co 78/03/08 4pp

7907160284 Response to util 790605 motion to file out of time Since one day delay in util response will not prejudice proceedings, NRC does not oppose motion Certificate of Svc encl  
GRAY, J R Branch 1 79/06/11 3pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907050446 Supplements response to IE Bulletin 79-08 Review under way No Tech Spec changes anticipated  
DALTROFF, S L Philadelphia Electric Co 79/05/14 1p

## U Congressional/Executive Correspondence

7907310091 Responds to 790529 ltr urging denial of early site review requests for facility End result of review will be staff position paper on site suitability, not CP Regulations require review for which proper application has been made.  
GOSSICK, L V Office of the Executive Director for Operations 79/06/29 2pp

--7907310104 Urges NRC to deny any early site review requests for facility  
SCHWEIKER, R S Senate 79/05/29 1p

## DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

## G Adjudicatory correspondence

7907180363 Requests appearance at final hearing  
ATKINSON, J B Affiliation Unknown 79/04/24 1p.

7907260003 Forwards SER W/a encl  
SCHINK, S M Branch 3 79/04/24 1p

7906210417 Responds to R&M Framson 790413 addl contention based on West German Work Rept AB-290 which analyzes meltdown Rept has been revised & no longer represents agency views Certificate of Svc encl  
SCHINK, S M Branch 3, 79/05/02, 5pp

--7906210421 "Investigations on Comparison of Greatest Possible Accident Consequences in Reprocessing Plant & in Nuclear Power Plant, Critical Comments on Work Rept AB-290 "  
BACHNER, D, FARBER, Q, HOLM, D Gesellschaft fur Reaktorsicherheit ORS-A-59 77/11/30 24pp

7907050516 Answer to ASLB 790501 order Does not hold off for TX PIRQ & does not wish to be represented by TX PIRQ counsel at proceeding.  
DOHERTY, J F Texas Public Interest Research Group 79/05/10 2pp

7907090452 Forwards TX PIRQ 790428 motion for reconsideration & clarification of ALAB-535, responses to util 790412 motion & to NRC 790418 motion & memo on due process notice  
BODITT, J M Texas Public Interest Research Group 79/05/12, 1p

# DOCKETED ITEMS

2

- 7907090459 TX PIRQ motion for reconsideration & clarification, response to util 790412 motion for reconsideration, response to NRC 790418 motion for clarification & memo on due process notice, re ALAB-535  
SCOTT, J M Public Interest Research Group 79/04/28 6pp
- 7907110496 TX PIRQ addl contentions per ASLB 790412 order FEB is not sufficiently detailed & must be rejected  
SCOTT, J M Texas Public Interest Research Group 79/05/12 15pp
- 7907100640 NRC opposition to FH Potthoff motions served on 790509 re 790412 order Request for extension of time in which to file amends to contentions should be denied Certificate of Svc encl  
SOHINKI, S M Branch 3 79/05/18 4pp
- 7907020002 State of TX response in support of Houston Lighting & Power 790521 motion for supplementary notice of intervention procedures Certificate of Svc encl  
LOHERRE, R W Texas, State of 79/05/21 5pp
- 7907050366 Requests admission to proceedings as intervenor Asserts standing based on personal economic & health impact of operation  
KAMRAS, J Affiliation Unknown 79/05/22 2pp
- 7907110558 Brief by intervenor D Marrack in support of Marrack Contentions 2-4 & 6 Alternative sites not adequately discussed & secondary impacts of plant not examined Certificate of Svc encl  
MARRACK, D Marrack, D, Intervenor 79/05/24 8pp
- 7907110073 Submits addl contentions per ALAB-535, issued 790411  
DOHERTY, J F Intervenor J F Doherty 79/05/25 18pp
- 7907110342 Houston Lighting & Power request to dismiss TX PIRQ 790512 addl contentions for untimely filing Submits individual responses to contentions to be considered if ASLB rules otherwise  
COPELAND, J Q, THRASH, C Q Baker & Botts 79/05/31 37pp
- 7907110353 Notification of appearance on behalf of Houston Lighting & Power Certificate of Svc encl  
BIDDLE, C T Baker & Botts 79/05/31 3pp
- 7907240462 Responds to 790512 ltr re procedure for submissions to NRC during pendency of ALAB-535 Intervenor 790428 motion on file w/ASLB NRC will request addl submissions as NRC deems appropriate  
ENGELHARDT, T F Deputy Executive Legal Director 79/06/01 2pp
- 7907240503 Notices of uncertainty of delivery of 790428 motion to all concerned parties All NRC commissioners should have copies of entire record  
SCOTT, J M Texas Public Interest Research Group 79/05/12 1p
- 7907240512 Motion by intervenor TX PIRQ for reconsideration & clarification of ALAB-535  
SCOTT, J M Texas Public Interest Research Group 79/04/28 6pp
- 7907100679 Orders extension until 790618 for Commission to elect to review ALAB-544  
CHILK, S J Office of the Secretary of the Commission, 79/06/04 1p
- 7907130533 Response to TX PIRQ 790512 addl contentions filed per ASLB 790412 order Contentions 15, 22, 30, 32, 34 & 46-49 should be admitted ASLB should require justification of Contention 25 Other contentions should be dismissed w/Certificate of Svc  
SOHINKI, S M Branch 3 79/06/05 42pp
- 7907180836 TX PIRQ response to Houston Lighting & Power second set of interrogatories  
SCOTT, J M Texas Public Interest Research Group 79/06/06 5pp.
- 7907190638 Second set of interrogatories directed to Houston Lighting & Power Co re installation of charcoal filters in radwaste bldg.  
DOHERTY, J F Intervenor J.F Doherty 79/06/06 1p.
- 7907190664 Request for production of documents directed to NRC.  
DOHERTY, J F Intervenor J.F Doherty, 79/06/06 1p.
- 7907190671 Third set of interrogatories directed to NRC.  
DOHERTY, J F Intervenor J.F Doherty 79/06/06 1p
- 7907190736 Request for production of documents directed to Houston Lighting & Power Co  
DOHERTY, J F Intervenor J.F Doherty, 79/06/06 1p
- 7907130556 NRC motion for extension until 790627 to respond to JF Doherty 790525 addl contentions filed per ALAB-535 Consultation w/technical staff necessary Certificate of Svc encl  
SOHINKI, S M Branch 3 79/06/07 3pp
- 7907310128 NRC opposition to JR Piepmier 790601 petition to intervene in proceeding for failure to address timeliness, standing & contentions Certificate of Svc encl  
SOHINKI, S M Branch 3 79/06/07 3pp
- 7907130546 Houston Lighting & Power response to FH Potthoff 790525 contentions filed per 790411 memo & order Contentions should be denied since subject matter is inadmissible Certificate of Svc encl  
COPELAND, J Q, BIDDLE, C T Baker & Botts CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll 79/06/08 5pp
- 7907130560 Houston Lighting & Power opposition to J Kamras petition to intervene as full party in proceeding Petition is untimely & does not demonstrate standing Certificate of Svc encl  
COPELAND, J Q, BIDDLE, C T Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 79/06/08 4pp
- 7907190701 Houston Lighting & Power responses to Marrack 790524 contentions filed per ASLB 790411 order Contentions 2(b) & 2(c), 3, 4 & 6 should be dismissed Certificate of Svc encl  
COPELAND, J Q, BIDDLE, C T, THRASH, C Q Baker & Botts 79/06/08 8pp
- 7907130538 NRC opposition to FH Potthoff 790525 contentions submitted per ASLB 790412 memo & order Contentions are irrelevant or not based on scientific data Certificate of Svc encl  
SOHINKI, S M Branch 3 79/06/11 7pp
- 7907190823 Houston Lighting & Power response to JF Doherty addl contentions Certificate of Svc encl  
COPELAND, J Q, THRASH, C Q Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 79/06/11 25pp
- 7907310118 NRC response to DR Marrack 790524 amends to original Contentions 2, 3, 4 & 6, submitted per 790411 & 0501 orders Certificate of Svc encl  
SOHINKI, S M Branch 3 79/06/11 9pp
- 7907020009 Order granting NRC 790607 motion for extension until 790627 to respond to J Doherty contentions  
WOLFE, S J Atomic Safety and Licensing Board Panel 79/06/12 1p
- 7907190114 Order denying three suggested mods proposed by interested party State of TX to applicant Houston Lighting & Power 790509 motion for supplementary notice of intervention procedures  
LINENBERGER, G A, WOLFE, S J Atomic Safety and Licensing Board Panel 79/06/12 4pp
- 7907190586 Houston Lighting & Power response to JF Doherty second set of interrogatories Certificate of Svc encl  
COPELAND, J Q Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll WHITE, J G Houston Lighting & Power Co 79/06/12 9pp
- 7907190696 TX PIRQ amends & replies to NRC 790605 responses & Houston Lighting & Power 790531 responses to TX PIRQ 790516 contentions submitted per ALAB-535 Certificate of Svc encl  
SCOTT, J M Texas Public Interest Research Group 79/06/15 5pp
- 79071907251 Response in opposition to FH Potthoff 790601 addl contentions re conservation program in util svc area & assertion that biomass production is superior alternative to proposed facility Certificate of Svc encl  
SOHINKI, S M Branch 3 79/06/18 6pp.
- 7907020001 Order denying JH Kamras 790524 petition to intervene  
WOLFE, S J Atomic Safety and Licensing Board Panel 79/06/20 2pp
- 7907270073 Advises that NRC will not respond to TX PIRQ 790615 amends & replies to Houston Lighting & Power & NRC contentions submitted per ALAB-535  
SOHINKI, S M Branch 3 79/06/20 1p.
- 7907190417 Houston Lighting & Power opposition to FH Potthoff addl contentions re conservation program & biomass production alternative, Certificate of Svc encl  
COPELAND, J Q, BIDDLE, C T Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 79/06/21 5pp

7907230089 Houston Lighting & Power motion to compel further answers to certain interrogatories submitted to intervenor TX PIRG Requests that all TX PIRG answers to interrogatories be resubmitted under oath w/Certificate of Svc & documentation  
COPELAND, J O , BIDDLE, C T Baker & Botts NEWMAN, J R  
Lowenstein, Neuman, Reis, Axelrad & Toll 79/06/21 48pp

7907190490 Order requesting NRC & Houston Lighting & Power to respond to TX PIRG 790615 amend Contentions 35, 38, 40, 42 & 28 on or before 790711 Urges TX PIRG to submit other amends to 790516 contentions  
WOLFE, S J Atomic Safety and Licensing Board Panel 79/06/25 2pp

7907200497 Houston Lighting & Power response to intervenor JF Doherty third set of interrogatories Affidavit & Certificate of Svc encl  
BIDDLE, C T , COPELAND, J O Baker & Botts NEWMAN, J R  
Lowenstein, Neuman, Reis, Axelrad & Toll 79/06/25 5pp

7907250525 Requests to make limited appearance statement at licensing prehearing  
DEOREGORI, C Affiliation Unknown 79/06/26 1p

7907200240 Response to intervenor JF Doherty 790525 amended contentions Certificate of Svc encl  
WOODHEAD, C P Branch 3 79/06/27 21pp

#### H General correspondence

7907060473 Expresses concern re impact of plant const Requests EIS Asks to be made party to CP proceedings  
PITTMAN, J D Affiliation Unknown 79/05/10 1p

#### G Inspection reports, IE Bulletins & correspondence

7907310119 Forwards IE Insp Rept 50-466/79-02 on 790508-11 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/16 2pp

--7907310126 IE Insp Rept 50-466/79-02 on 790508-11 No noncompliance noted Major areas inspected procurement, vendor surveillance, audits, development of site procedures & preparation for site civil activities  
HUBACEK, W G , BEACH, A B , HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/16 4pp

7907050561 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907180255 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27 1p

#### DOCKET STN-50-470 CESSAR SYSTEM 80

#### K Utility Final Safety Analysis Report (FSAR) & amends

7907160282 Forwards nonproprietary Amend 3 to FSAR  
SCHERER, A E Combustion Engineering, Inc 79/06/29 1p

--7907160289 Amend 3 to FSAR Oversized drawings encl  
\* Combustion Engineering, Inc 79/06/29 226pp

#### DOCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2

#### A Application/construction stage documents & correspondence

7907190004 Summarizes 790601 site visit to inspect breakwater  
JOHNSON, T L Hydrology Meteorology Branch 79/06/19 2pp

7907250413 Ack receipt of 790622 & 26 FOIA requests for records of wastewater discharges from facility Info available in LPDR  
FELTON, J M Division of Rules and Records 79/07/13 4pp

#### D NRC Draft/Final Environmental Statements, supplis & correspondence

7907240431 Forwards final suppl to FES re Facility const & NRC suppl testimony on analysis of alternate sites Financial qualification issue will be heard 790524-25 Alternative site issue will be heard beginning 790529  
SMITH, B H Branch 2 79/05/14 1p

--7907240440 Final suppl to FES re facility const  
\* Office of Nuclear Reactor Regulation 79/05/15 130pp

--7907240446 NRC suppl testimony re alternative sites Professional qualifications of TL Johnson, JC Lehr, JR Levine, LM Dykoski & MT Masnik encl  
SCALETTI, D Division of Site Safety & Environmental Analysis 79/05/14 35pp

#### G Adjudicatory correspondence

7907050383 Confirms 790508 delivery of "Metropolitan Siting - Historical Perspective" (NUREG-0478, Oct 1978)  
SMITH, B H Branch 2 79/05/09 1p

7907050507 Testimony of PB Herr re population density & other site characteristics in support of State of MA Contention 12 Alternative of locating facility at more suitable site not considered by applicant Resume & Certificate of Svc encl  
HERR, P B Massachusetts, State of 79/05/14 38pp

7907090467 Motion for addl hearing dates & for 790629 deadline to file testimony re need for power issue Financial qualifications, alternate site issues & other matters will be discussed during hearing w/Certificate of Svc  
MEYER, M B Massachusetts, State of 79/05/17 4pp

7907110695 Forwards prof qualifications of O LaRoche, F Kantor, L Soffer, P Sobel & ML Karlowicz  
SMITH, B H Branch 2 79/05/18 11pp

7907110693 Intervenor's Cleetons' motion for reconsideration of emergency planning issue Requests participation in wording of contention & introduction of evidence Certificate of Svc encl  
ABBOTT, W B Intervenor's Cleeton 79/05/21 5pp

7907250144 Forwards NUREG/CR-0250 "Regional Econometric Model for Forecasting Electricity Demand by Sector & State " W/o encl  
SMITH, B H Branch 2 79/05/21 1p

7907180366 Notice of appearance on behalf of MA Dfc of Energy Resources  
SELGRADE, E L Massachusetts, State of 79/05/23 1p

--7907180374 MA Dfc of Energy Resources petition to participate as interested state agency or to make limited appearance in proceeding Certificate of Svc, JB Fitzpatrick affidavit & EJ King directive encl  
SELGRADE, E L Massachusetts, State of 79/05/23 10pp

7907020004 NRC response in support of MA Governor Dfc of Energy Resources petition to intervene as interested state agency Certificate of Svc encl  
SMITH, B H , MULKEY, M E Branch 2 79/05/29 4pp

7907110125 Commonwealth of MA response to MA Governor Dfc of Energy Resources petition to participate as interested state agency in proceeding Expresses some remarks, but does not object participation Certificate of Svc encl  
MEYER, M Illinois, State of, 79/06/01 4pp

7907110165 MA Governor Dfc of Energy Resources support of 790524 petition to participate as interested state agency or, in alternative, to make limited appearance Certificate of Svc encl  
SELGRADE, E L Illinois, State of 79/06/01 5pp

7907180324 Response of intervenor Cleetons in opposition to MA Dfc of Energy Resources 790324 petition for leave to participate as interested state agency Certificate of Svc encl  
ABBOTT, W B Abbott, W. B 79/06/01 12pp

7907180334 Boston Edison response to MA Dfc of Energy Resources 790523 petition to participate as interested state agency Petitioners participation is encouraged & appropriate as matter of policy Certificate of Svc encl  
LEWALD, Q H Repes & Gray STOODLEY, D Q Boston Edison Co 79/06/01 7pp

7907180773 Commonwealth of MA objections to admission of Boston Edison 780802 legal opinions during 790611 hearing Certificate of Svc encl  
BURT, L Massachusetts, State of 79/06/07 3pp

7907180817 Forwards Commonwealth of MA 790607 interrogatories directed to NRC re need for power issue  
MEYER, M B Massachusetts, State of 79/06/07 1p

# DOCKETED ITEMS

2

--7907180824 Commonwealth of MA interrogatories directed to NRC re need for power issue Certificate of Svc encl  
MEYER, M B Massachusetts, State of 79/06/07 7pp

7907180829 Boston Edison memo in support of admission of expert opinion evidence in proceeding  
LEWALD, G H Ropes & Gray STODDLEY, D O Boston Edison Co 79/06/08 App

7907190643 Forwards Commonwealth of MA 790608 interrogatories directed to Boston Edison re need for power issue  
MEYER, M B Massachusetts, State of 79/06/08 1p

--7907190651 Commonwealth of MA interrogatories directed to Boston Edison re need for power issue Certificate of Svc encl  
MEYER, M B Massachusetts, State of 79/06/08 14pp

7907190582 Forwards Boston Edison 790611 motion to take official notice of certain state statutes & court decisions of NH, CT, VT & RI  
STODDLEY, D O Boston Edison Co 79/06/11 1p

--7907190587 Boston Edison motion to take official notice of certain state statutes court decisions of NH, CT, VT & RI Certificate of Svc encl  
LEWALD, G H Ropes & Gray STODDLEY, D O Boston Edison Co 79/06/11 5pp

7907190650 Forwards Commonwealth of MA & intervenors Cleetons 790613 stipulation re emergency planning issue  
BURT, L Massachusetts, State of 79/06/14 1p

--7907190738 Stipulation between Commonwealth of MA & intervenors Cleetons adopting contention on emergency planning issue  
Stipulated contention is subj to ASLB approval  
LEONARD, S M Massachusetts, State of ABBOTT, W B Abbott, W B 79/06/13 2pp

7907190438 Boston Edison motion for extension until 790709 to answer Commonwealth of MA interrogatories re need for power issue  
LEWALD, G H Ropes & Gray STODDLEY, D O Boston Edison Co 79/06/22 2pp

7907190494 NRC response to Commonwealth of MA 790607 interrogatories re need for power issue Affidavit & Certificate of Svc encl  
FELD, S E Cost Benefit Analysis Branch 79/06/25 23pp

7907120009 Boston Edison motion for protective orders & objections to Commonwealth of MA interrogatories 33, 34, 35(d) & 39-41 re need for power issue  
LEWALD, G H Ropes & Gray STODDLEY, D O Boston Edison Co 79/06/26 6pp

7907190499 Order granting extension until 790709 for Boston Edison to answer Commonwealth of MA interrogatories  
GOODHOPE, A C Atomic Safety and Licensing Board Panel 79/06/26 1p

7907240314 Forwards revised supplemental testimony on need for power issue for ASLB 790716 hearing Testimony supersedes 790518 filing Certificate of Svc encl  
STODDLEY, D O Boston Edison Co. 79/06/29 3pp

--7907240317 Revised supplemental testimony on need for facility Penalist  
BH Weiner, PA Legrow, DV Bourcier, AH Barstow, FC Turner, N Godley, & D Hanna Re Commonwealth of MA Contention 4, Cleeton Contention H, & Ford Contention M Documentation encl  
WEINER, B H Boston Edison Co 79/06/29. 322pp.

7907240417 Forwards until 790629 second motion that ASLB take official notice of certain state statutes, court decisions & documents re until Exhibit 15 Motion corrects & supercedes 790611 motion  
STODDLEY, D O Boston Edison Co. 79/06/29 1p

--7907240423 Second motion submitted by util that ASLB take official notice of certain state statutes, court decisions & documents from states of VT, NH, RI & CT. Certificate of Svc encl  
LEWALD, G H Ropes & Gray STODDLEY, D O Boston Edison Co 79/06/29 6pp

## H. General correspondence

7907030471 Requests NRC deny permit to construct Unit 2 & institute more stringent safety requirements for Unit 1.  
BARLETT, R M, BARLETT, S Affiliation Unknown 79/05/31 1p.

## G Inspection reports, IE Bulletins & correspondence

7907110688 Forwards IE Insp Rept 50-471/79-01 on 790207-09 No noncompliance noted  
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/04 2pp

--7907110703 IE Insp Rept 50-471/79-01 on 790207-09 No noncompliance noted Major areas inspected QA activities re receiving, handling & storage of safety-related components & licensee action on previous insp findings  
MATTIA, J Region 1, Philadelphia, Office of the Director  
MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/19. 4pp

7907020042 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907100413 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

## T Hearing transcripts on non-antitrust matters

7907300144 Transcript of 790716 hearing in Plymouth, MA Pg 10,342-10,651 Applicant testimony encl  
GOODHOPE, A C, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 79/07/16 207pp

7907250194 Transcript of 790717 hearing in Plymouth, MA Pg 10,494-10,651 Testimony of S Feld encl  
GOODHOPE, A C, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 79/07/17 182pp

7907310044 Transcript of 790718 hearing in Plymouth, MA Pg 10,652-10,943 Testimony of JS Fitzpatrick & JO Buckley encl  
GOODHOPE, A C, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 79/07/18 331pp

7907310054 Transcript of 790719 hearing in Plymouth, MA Pg 10,948-11,224 Testimony of PL Chernick & BC Keller encl  
GOODHOPE, A C, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 79/07/19 343pp

7907300133 Transcript of 790720 hearing in Plymouth, MA Pg 11,225-11,352  
GOODHOPE, A C, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 79/07/20 128pp

## DOCKET STN-50-481 D-BAR-241

### B Reportable occurrences, LERs & related correspondence

7907050573 Forwards PNO-79-67AG, "Nuclear Incident at TMI"  
BEIDLE, W C Region 4, Dallas, Office of the Director 79/06/13 1p

## DOCKET STN-50-482 WOLF CREEK GENERATING STATION

### A Application/construction stage documents & correspondence

7907110625 Requests addl info re concrete strength evaluation  
PARR, D D Light Water Reactors Branch 3 79/05/30. App

7907130041 Notification of 790612 meeting w/BNUPPS util representatives in Bethesda, MD to discuss plans for tendering & content of OL applications & related administrative matters  
LICITRA, E A Light Water Reactors Branch 3 79/05/30 App.

7907110057 Summary of 790529 telcon w/O Koester re status of review of facility base mat matter  
LICITRA, E A Light Water Reactors Branch 3 79/06/01. 2pp.

7907030097 Summary of 790515 meeting w/applicants in Burlington, MA re concrete strength of reactor bldg base mat  
LICITRA, E A Light Water Reactors Branch 3 79/06/07. 5pp.

7907050369 Advises of new determinations re seismic character of area & renews request for partial suspension of CP.  
WARD, W H. Mid-America Coalition for Energy Alternatives 79/06/29. 6pp

## DOCKETED ITEMS

7907300582 Summary of 790612 meeting w/utills re plans for submittal of SNUPPS OL applications  
LJCITRA,E A Light Water Reactors Branch 3 79/07/10 7pp

7907310327 Forwards util application for amend of CPPR-147 to include KS Electric Power Cooperative as co-owner of facility  
SILBERQ,J E Shaw, Pittman, Potts, & Trowbridge 79/07/30 1p

--7907310337 Application for amend of CPPR-147 to include KS Electric Power Cooperative as co-owner of facility  
CADMAN,W K Kansas Gas & Electric Co 79/07/11 10pp

--7907310365 Examination rept for FY78  
\* Affiliation Unknown 78/12/31 11pp

#### Q Adjudicatory correspondence

7907100701 Opposes facility const  
DOANE,J Affiliation Unknown 79/05/18 1p

7907060008 Endorses revocation of CP  
MCDOWELL,M Affiliation Unknown 79/05/20 2pp

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK,B M Branch 4 79/05/25 27pp

7907060097 Forwards KS Bldg & Const Trades Council request for order to show cause why CP should not be revoked  
STELLD,V Division of Operating Reactors 79/06/18 1p

--7907060102 Forwards KS Bldg & Const Trades Council request for order to show cause why CP should not be revoked  
BUKATY,S A Blake & Uhlig 79/05/15 1p

--7907060107 Request by KS Bldg & Const Trades Council for order to show cause why CP should not be revoked Const work on plant is substd;operation endangers public health & safety  
BUKATY,S A Blake & Uhlig 79/06/18 2pp

--7907060112 Ack receipt of petition requesting order to show cause why CP should not be revoked Request has been consolidated  
Separate FR notice will not be made Notice of petitions from 790801 FR encl  
STELLD,V Division of Operating Reactors 79/06/18 2pp

#### H General correspondence

7907050267 Requests foundation at facility be reconstructed  
COTTON,M Affiliation Unknown 79/06/08 2pp

7907310441 Addresses comments of 790518 ltr re quality of concrete in base mat Site is acceptable w/regard to seismological considerations Safety-related structures designed to withstand wind speed of 360 miles/h  
VASSALLO,D B Assistant Director for Light Water Reactors 79/06/14 4pp

7907090321 Reaffirms 790119 request to suspend facility CP for inadequate QC of containment bldg basemat New info re seismic disturbances should also be considered  
WARD,H H Mid-America Coalition for Energy Alternatives 79/06/29 6pp

7907240334 Requests substitution of HH Voigt for AE Upton on NRC 790713 distribution list  
VOIGT,H H LeBoeuf, Lamb, Leiby & MacRae 79/07/18 1p

#### Q Inspection reports, IE Bulletins & correspondence

7907130126 Forwards IE Insp Rept 50-482/79-04 on 790305-08 & 15 & notice of violation  
SEYFRIT,K V Region 4, Dallas, Office of the Director, 79/04/11 3pp

--7907130135 Notice of violation from insp on 790305-08 & 15  
\* Region 4, Dallas, Office of the Director, 79/04/10 1p

--7907130139 IE Insp Rept 50-482/79-04 on 790305-08 & 15 Noncompliance noted; Failure to follow procedures re spectrographs of chemical & physical properties  
OBERQ,C R , ROSENBERG,A B , CROSSMAN,W A Region 4, Dallas, Office of the Director, 79/04/10, 15pp

7907050184 Forwards IE Insp Rept 50-482/79-06 on 790402-04 No noncompliance noted  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/24 2pp

--7907050187 IE Insp Rept 50-482/79-06 on 790402-04 No noncompliance noted Major areas inspected const activities, review of audits performed for concrete activities & preparation for repairs to equipment hatch  
CROSSMAN,W A , STEWART,R C Region 4, Dallas, Office of the Director HANSEN,W A Region 3, Chicago, Office of the Director 79/04/24 6pp

7907110419 Forwards IE Insp Rept 50-482/79-07 on 790409-12 No noncompliance noted  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/11 2pp

--7907110628 IE Insp Rept 50-482/79-07 on 790409-12 No noncompliance noted Major areas inspected reactor pressure vessel, safety-related concrete, polar crane supports & licensee action on previous items  
OBERQ,C R , MARTIN,L E , CERNE,A C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/11 13pp

7907110511 Confirms 790629 deadline for response to IE Bulletins 78-12, 78-12A & 78-12B  
PETRICK,N A SNUPPS-Standardized Nuclear Unit Power Plant System 79/05/17 1p

7907110732 Forwards IE Insp Rept 50-482/79-08 on 790416-19, notice of violation & notice of deviation  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/17 2pp

--7907110735 Notice of violation from insp on 790416-19  
\* Region 4, Dallas, Office of the Director 79/05/17 2pp

--7907110740 Notice of deviation from insp on 790416-19  
\* Region 4, Dallas, Office of the Director 79/05/17 1p

--7907110747 IE Insp Rept 50-482/79-08 on 790416-19 Noncompliance noted failure to follow approved concrete curing procedures & failure to establish proper document controls for blasting procedure  
BEACH,A B , ROSENBERG,A B , HALL,R E Region 4, Dallas, Office of the Director 79/05/16 10pp

7907110682 Forwards 790511 response to IE Bulletin 79-03  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/21 1p

--7907110690 Responds to IE Bulletin 79-03 re ASME BA-312 Type 304 stainless steel pipe spools Interim rept re use or potential use to be sent by 790810  
KOEESTER,K V Kansas Gas & Electric Co 79/05/11 13pp

7907030124 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/29 1p

7907260079 Responds to IE Bulletins 79-04 & 79-07 Correct Velan valve weights used in piping analyses All computer codes used in seismic stress analysis of safety-related piping verified  
KOEESTER,K L Kansas Gas & Electric Co 79/05/29 3pp

7907200356 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities" No action required  
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/31 1p

7907250479 Forwards IE Insp Rept 50-482/79-10 on 790428 No noncompliance noted  
SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/04 1p

--7907250488 IE Insp Rept 50-482/79-10 on 790428 No noncompliance noted Major areas inspected record of items of noncompliance & effectiveness of site QA program & current & projected manning level of site QA organization  
OBERQ,C R , CROSSMAN,W A Region 4, Dallas, Office of the Director 79/05/21, 3pp

7907190399 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" No action required  
BEYFRIT,K V, Region 4, Dallas, Office of the Director 79/06/06 1p

# DOCKETED ITEMS

7907060016 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07  
1p

7907250221 Forwards IE Insp Rept 50-482/79-09 on 790423-26 & notice of violation  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/07 2pp

--7907250222 Notice of violation from insp on 790423-26  
\* Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/04 2pp

--7907250226 IE Insp Rept 50-482/79-09 on 790423-26 Noncompliance noted failure to follow storage procedures for reactor vessel internals & failure to conduct QC insp  
OBERO, C R ; TOMLINSON, D P ; CROSSMAN, W A Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/04 13pp

7907230347 Ack receipt of 790323 & 0531 ltrs informing NRC of steps taken to correct violation noted in IE Insp Rept  
50-482/79-01  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/08 1p

--7907230355 Responds to NRC 790426 ltr re violation noted in IE Insp Rept 50-482/79-01 Corrective actions when only one placement being made, truck following text load will be held at point of placement  
KOEESTER, G L Kansas Gas & Electric Co 79/06/08 2pp

7907030563 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907310598 Forwards IE Insp Rept 50-482/79-12 on 790514-17 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/14 2pp

--7907310603 IE Insp Rept 50-482/79-12 on 790514-17 No noncompliance noted Major areas inspected licensee action on previous insp findings, essential svc water sys earthwork & welding program  
OBERO, C R ; CROSSMAN, W A ; HALL, R E Region 4, Dallas, Office of the Director 79/06/13 18pp

7907030512 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20 1p

7907050487 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21 1p

7907120600 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25 1p

7907110249 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26 1p

7907180257 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27 1p

7907100517 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28 1p

7907110293 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys. " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/07/02 1p

7907270288 Ack receipt of 790618 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/79-08.  
SEIDLE, W C. Region 4, Dallas, Office of the Director. 79/07/03 1p

--7907270291 Responds to NRC 790517 ltr re violations noted in IE Insp Rept 50-482/79-08 Corrective actions area supervisors directed to perform addl training of personnel  
KOEESTER, G L Kansas Gas & Electric Co 79/06/18 3pp

7907190498 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11 1p

7907240309 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13 1p

7907270395 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/18 1p

## B Reportable occurrences, LERs & related correspondence

7907300027 Revises status of deficiency rept re essential svc water pump anchor bolts Investigation revealed bolts, as presently specified, are of sufficient length to provide safe design  
KOEESTER, G L Kansas Gas & Electric Co 79/05/29 1p

7907030266 Forwards PNO-79-67AG, "Nuclear Incident at TMI " SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/31 1p

7907020306 Forwards PNO-79-67AR SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/05 1p

7907030210 Forwards PNO-79-67AT SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/19 1p

7907260607 Forwards addl info to 790425 ltr re preassembly welds Observed condition was documented in Nonconformance Rept 18N0863M Problem caused by interior diameter counter bore ridge parts were replaced  
KOEESTER, G L Kansas Gas & Electric Co 79/06/20 2pp

7907130337 Forwards PNO-79-67AU SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/27 1p

7907180688 Forwards PNO-79-67AV, SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/06 1p

7907180530 Forwards interim significant deficiency rept on flood damage.  
KOEESTER, G L Kansas Gas & Electric Co 79/07/13 1p

--7907180537 Interim significant deficiency rept on 790608 re flood damage equipment Water entered power block bldg during heavy rains causing flood damage Caused by unfinished const Will be eliminated when bldg is roofed  
\* Kansas Gas & Electric Co 79/07/13 4pp

7907240518 Forwards PNO-79-67AW, SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/13 1p

## DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

### A. Application/construction stage documents & correspondence

7907130041 Notification of 790612 meeting w/BNUPPS util representatives in Bethesda, MD to discuss plans for tendering & content of OL applications & related administrative matters.  
LICITRA, E A Light Water Reactors Branch 3, 79/05/30, 4pp

7907300582 Summary of 790612 meeting w/utills re plans for submittal of BNUPPS OL applications  
LICITRA, E A Light Water Reactors Branch 3 79/07/10, 7pp

### H General correspondence

7907120046 Ack receipt of recent ltr re careless plant const. State govt has little authority, due to pre-emptions by NRC, as mandated by Congress. Forwards ltr to MO Senators Eagleton & Danforth, Representative Volkmer & NRC.  
TEASDALE, J P Missouri, State of. 79/05/22 2pp.

## DOCKETED ITEMS

7907240354 Requests substitution of HH Voigt for AE Upton on NRC 790713 distribution list  
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 79/07/18 1p

G Inspection reports, IE Bulletins & correspondence

7907110511 Confirms 790629 deadline for response to IE Bulletins 78-12, 78-12A & 78-12B  
PETRICK, N A SNUPPS-Standardized Nuclear Unit Power Plant System 79/05/17 1p

7907250212 Forwards IE Insp Rept 50-483/79-04 on 790424-26 & notice of violation  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/30 2pp

--7907250213 Notice of violation from insp on 790424-26  
\* Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/25 1p

--7907250216 IE Insp Rept 50-483/79-04 on 790424-26 Noncompliance noted failure to use proper penetrometer for radiography of containment liner plate  
SCHWEIBINZ, E R, HANSEN, W A, KNOP, R C Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/25 7pp

7907200334 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190295 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240444 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907240238 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/06/11 1p

7907300516 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers are not used in safety-related sys  
BRYAN, J K Union Electric Co 79/06/14 1p

7907020438 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120262 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907130155 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060003 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050481 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/06/27, 1p

7907100328 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/06/28, 1p

7907130293 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p

7907310349 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310418 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260217 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

S Reportable occurrences, LERs & related correspondence

7907130187 Ack receipt of 790518 interim rept re emergency svc water pump anchor bolts  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/01 1p

DOCKET 87N-50-484 TYRONE ENERGY PARK, UNIT 1

A Application/construction stage documents & correspondence

7907130041 Notification of 790612 meeting w/SNUPPS util representatives in Bethesda, MD to discuss plans for tendering & content of DL applications & related administrative matters  
LICITRA, E A Light Water Reactors Branch 3 79/05/30 4pp.

7907300582 Summary of 790612 meeting w/utls re plans for submittal of SNUPPS DL applications  
LICITRA, E A Light Water Reactors Branch 3 79/07/10 7pp

G Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Onwego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact. Certificate of Evc encl  
BORDENICK, B M Branch 4 79/05/28 29pp.

7907090171 Notifies of typographical errors in licensee's joint motion for summary disposition re radon issues. Mistakes were in accompanying affidavits  
SILBERG, J E Shaw, Pittman, Potts, & Troubridge, 79/06/05 9pp.

7907180188 Responds to utls motion for summary disposition re radon issues. Twenty-one alleged deficiencies in Perkins record advanced by intervenors are supported in part & opposed in part. Certificate of Evc encl  
BORDENICK, B M Branch 4 79/06/14, 29pp

H. General correspondence

7907240354 Requests substitution of HH Voigt for AE Upton on NRC 790713 distribution list.  
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae, 79/07/18 1p

G Inspection reports, IE Bulletins & correspondence

7907110511 Confirms 790629 deadline for response to IE Bulletins 78-12, 78-12A & 78-12B  
PETRICK, N A SNUPPS-Standardized Nuclear Unit Power Plant System, 79/05/17 1p

7907200325 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/05/31, 1p

7907190280 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/06/06 1p.



# DOCKETED ITEMS

7907240435 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907240226 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907300549 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breaker are used or planned for use at facility  
DIENHART, A V Northern States Power Co 79/06/14 1p

7907020433 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120244 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907130142 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060317 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050478 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 1p

7907180423 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p

7907130281 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/07/02 1p

7907310341 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies, " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11 1p

7907310413 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260201 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/1E 1p

7907260407 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

## DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT 1

### A Application/construction stage documents & correspondence

7907130041 Notification of 790612 meeting w/BNUPPS util representatives in Bethesda, MD to discuss plans for tendering & content of DL applications & related administrative matters  
LICITRA, E A Light Water Reactors Branch 3 79/05/30 4pp.

7907300582 Summary of 790612 meeting w/utills re plans for submittal of BNUPPS DL applications  
LICITRA, E A Light Water Reactors Branch 3 79/07/10. 7pp.

### G Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of SVC encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907090171 Notifies of typographical errors in licensee's joint motion for summary disposition re radon issues: Mistakes were in accompanying affidavits  
SILBERG, J E Shaw, Pittman, Potts, & Troubridge 79/06/05 9pp

7907180188 Responds to utils motion for summary disposition re radon issues: Twenty-one alleged deficiencies in Perkins record advanced by intervenors are supported in part & opposed in part Certificate of SVC encl  
BORDENICK, B M Branch 4 79/06/14 29pp

7907240353 Order granting intervenor Ecology Action of Oswego request for extension until 790716 to submit affidavit of R Pohl Affidavit is part of intervenor response to Util motion for summary disposition on radon issue.  
BISHOP, C J Atomic Safety and Licensing Appeal Panel 79/07/02 1p

### H General correspondence

7907240354 Requests substitution of HH Voigt for AE Upton on NRC 790713 distribution list  
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 79/07/18 1p

### G Inspection reports, IE Bulletins & correspondence

7907110511 Confirms response by 790629 to IE Bulletins 79-12, 12A & 12B  
PETRICK, N A BNUPPS-Standardized Nuclear Unit Power Plant System 79/05/17 1p

7907110302 Responds to IE Bulletin 79-04 Component cooling & essential svc water sys, reactor coolant, auxiliary feedwater, feedwater, compressed air & auxiliary turbines sys will use 3 4 or 6-inch Velan swing check valves  
ARTHUR, J E Rochester Gas & Electric Corp 79/05/18 2pp

7907180110 Responds to IE Bulletin 79-03 Submits ref listing of Youngstown SA-312 Type 304 welded piping spools which was inadvertently omitted in 790510 response  
ARTHUR, J E Rochester Gas & Electric Corp 79/05/18 11pp

7907060432 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers For Engineered Safety Sys " Licensee action required.  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22. 1p

7907020487 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. All analyses properly performed & methods specified in bulletin not used  
ARTHUR, J E Rochester Gas & Electric Corp 79/05/29 2pp

7907030072 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyster Creek Reactor "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200150 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/05/31 1p

7907190113 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Ball-and-Valve)." Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060135 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/07. 1p

7907020056 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/06/11 1p.

## DOCKETED ITEMS

7907110392 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230709 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120581 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100373 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100434 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907110039 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180823 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270368 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310539 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

#### DOCKET STN-50-486 CALLOWAY PLANT, UNIT 2

##### A Application/construction stage documents & correspondence

7907130041 Notification of 790612 meeting w/ENUPPS util representatives in Bethesda, MD to discuss plans for tendering & content of OL applications & related administrative matters  
LICITRA, E A Light Water Reactors Branch 3 79/05/30 4pp

7907300582 Summary of 790612 meeting w/utills re plans for submittal of ENUPPS OL applications application  
LICITRA, E A Light Water Reactors Branch 3 79/07/10 7pp

##### H General correspondence

7907120046 Ack receipt of recent ltr re careless plant const State govt has little authority, due to pre-emptions by NRC, as mandated by Congress Forwards ltr to MD Senators Eagleton & Danforth, Representative Volkner & NRC  
TEASDALE, J P Missouri 1, State of 79/05/22 2pp

7907240354 Requests substitution of HH Voigt for AE Upton on NRC 790713 distribution list  
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 79/07/18 1p

##### G Inspection reports, IE Bulletins & correspondence

7907110511 Confirms response by 790629 to IE Bulletins 78-12, 12A & 12B  
PETRICK, N A ENUPPS-Standardized Nuclear Unit Power Plant System 79/05/17 1p

7907200334 Forwards IE Bulletin 79-12, "Short Period Screams at BHR Facilities " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director, 79/05/31 1p

907190295 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCD Solenoid Valves) " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director, 79/06/06 1p

7907240444 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08 2pp

7907240238 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/11 1p

7907300516 Responds to IE Bulletin 79-09 QE Type AK-2 circuit breakers are not used in safety-related sys  
BRYAN, J K Union Electric Co 79/06/14 1p

7907020438 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/20 1p

7907120262 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/21 1p

7907130155 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/25 1p

7907060003 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/26 1p

7907080481 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director, 79/06/27 1p

7907100528 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/28 1p

7907130293 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/02 1p

7907310349 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/11 1p

7907310418 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/13 1p

7907240217 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/18 1p

7907240418 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/07/18 1p

##### B Reportable occurrences, LERs & related correspondence

7907130187 Ack receipt of 790518 interim rept re emergency svc water pump anchor bolts  
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/06/01 1p

#### DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 1

##### G Adjudicatory correspondence

7907200247 Mod of 790419 opposition to intervenor 790305 motion to reopen record & defer indefinitely issuance of initial decision Deferral of initial decision is advised until TMI review is completed  
REIS, E J Branch 3 79/06/26 2pp.

--7907200253 Notice of appearance on behalf of NRC Certificate of Svc  
encl  
REIS,E J Branch 3 79/06/26 3pp

G Inspection reports, IE Bulletins & correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
TMI - Suppl 1"  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

7907110318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907050118 Discusses schedule of response to IE Bulletin 78-12, 18-12A &  
78-12B C-E reactor vessel manufacturer, is engaged in  
requested records search Final response to bulletin will be  
made by 790629  
DAIL,L C Duke Power Co 79/05/16 1p

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Licensee  
action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907190176 Responds to IE Bulletin 79-07 SUPERPIPE computer program  
used on piping analysis Primary coolant loop analysis will  
be performed by C-E Will not be used Algebraic summation  
method for combining responses  
DAIL,L C Duke Power Co 79/05/29 2pp

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060048 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys "  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020379 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required.  
O'REILLY,J P Region 2, Atlanta, Office of the Director.  
79/06/21 1p.

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping." No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director.  
79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface  
Problem." No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem." No action required.  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp.

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

U Congressional/Executive Correspondence

7907050380 Requests delay in granting CP until all safety questions  
raised by TMI incident are adequately addressed Ltr to ABLB  
encl  
NEAL,S L House of Rep 79/06/01 1p

--7907050385 Requests assurance that licensing decision will not be made  
until all facts of nuclear safety have been addressed &  
monatorium has ended  
NEAL,S L House of Rep 79/05/11 1p

V Operator Examinations

7907250394 FDIA request for summary sheet of power plant operator  
exam results presented to NRC on 790420 & license exams &  
test results for Duke Power Co employees from 750101 to  
present  
AHRENDT,B Jefferson Pilot Broadcasting 79/06/20 2pp

7907250408 Responds to FDIA request for summary sheet of power plant  
operator exam results presented to NRC on 790420. Forwards  
documents listed on App A  
FELTON,J M Division of Rules and Records 79/07/18 3pp

DOCKET STN-80-469 PERKINS NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

7907200247 Mod of 790419 opposition to intervenor 790305 motion to  
reopen record & defer indefinitely issuance of initial  
decision Deferral of initial decision is advised until TMI  
review is completed  
REIS,E J Branch 3 79/06/26 2pp

--7907200253 Notice of appearance on behalf of NRC Certificate of Svc  
encl  
REIS,E J Branch 3 79/06/26 3pp

G Inspection reports, IE Bulletins & correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at  
TMI-Suppl 1"  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp.

7907110318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head  
Insulation Support Problem " No action required.  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907050118 Discusses schedule of response to IE Bulletin 78-12, 18-12A &  
78-12B C-E reactor vessel manufacturer, is engaged in  
requested records search Final response to bulletin will be  
made by 790629  
DAIL,L C Duke Power Co 79/05/16 1p

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low  
Enriched U " No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device  
in Circuit Breakers for Engineered Safety Sys " Licensee  
action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907190176 Responds to IE Bulletin 79-07 SUPERPIPE computer program  
used on piping analysis Primary coolant loop analysis will  
be performed by C-E Will not be used Algebraic summation  
method for combining responses  
DAIL,L C Duke Power Co 79/05/29 2pp

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities." No action required  
O'REILLY,J P Region 2, Atlanta, Office of the Director.  
79/05/31 2pp

## DOCKETED ITEMS

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/06 2pp

7907060048 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020379 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

#### U Congressional/Executive Correspondence

7907050380 Requests delay in granting CP until all safety questions raised by TMI incident are adequately addressed Ltr to ASLB  
encl.  
NEAL, S L House of Rep 79/06/01 1p

--7907050385 Requests assurance that licensing decision will not be made until all facts of nuclear safety have been addressed & moratorium has ended  
NEAL, S L House of Rep 79/05/11 1p

#### V Operator Examinations

7907230394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 780101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20 2pp.

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
PELTON, J M Division of Rules and Records 79/07/18. 3pp.

#### DOCKET STN-90-490 PERKINS NUCLEAR STATION, UNIT 3

#### G. Adjudicatory correspondence

7907200247 Mod of 790419 opposition to intervenor 790305 motion to reopen record & defer indefinitely issuance of initial decision Deferral of initial decision is advised until TMI review is completed.  
REIB, E J Branch 3 79/06/26 2pp

--7907200253 Notice of appearance on behalf of NRC Certificate of Svc  
encl  
REIB, E J Branch 3 79/06/26 3pp

#### G Inspection reports, IE Bulletins & correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp

790710318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907050118 Discusses schedule of response to IE Bulletin 78-12, 18-12A & 78-12B C-E reator vessel manufacturer, is engaged in requested records search Final response to bulletin will be made by 790629  
DAIL, L C Duke Power Co 79/05/16 1p

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U, " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/05/31 2pp

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/06 2pp

7907060048 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020379 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate "  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/11 1p

# U Congressional/Executive Correspondence

7907050380 Requests delay in granting CP until all safety questions raised by TMI incident are adequately addressed Ltr to ASLB encl  
NEAL, S L House of Rep 79/06/01 1p

--7907050385 Requests assurance that licensing decision will not be made until all facts of nuclear safety have been addressed & moratorium has ended  
NEAL, S L House of Rep 79/05/11 1p

# V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20 2pp

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp

# DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

## G. Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

## G Inspection reports, IE Bulletins & correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp

7907110318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/07 2pp

7907050118 Discusses schedule of response to IE Bulletin 78-12, 78-12A & 78-12B C-E reactor vessel manufacturer is engaged in requested records search Fiant response to bulletin will be made by 790629  
DAIL, L C Duke Power Co 79/05/16 1p

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/22 1p

7907190176 Responds to IE Bulletin 79-07 SUPERPIPE computer program used on piping analysis Primary coolant loop analysis will be performed by C-E Will not be used Algebraic summation methods for combining responses  
DAIL, L C Duke Power Co, 79/05/29 2pp

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/31 2pp

7907090420 Ack receipt of IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10 No proprietary info  
DAIL, L C Duke Power Co 79/06/06 1p.

--7907090426 Forwards IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10. No noncompliance noted.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23, 2pp.

--7907090433 IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10 No noncompliance noted Major areas inspected dan const BA/BC controls, work performance, quality records & licensee actions re previous insp findings  
LENAHAN, J J Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 3pp

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 2pp

7907060048 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907020379 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface Problem, " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 2pp

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 2pp.

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 1p

# V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present  
AHRENDT, B, Jefferson Pilot Broadcasting, 79/06/20 2pp.

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J. M. Division of Rules and Records 79/07/18 3pp

# DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

## G. Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4, 79/05/25, 29pp

## G Inspection reports, IE Bulletins & correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 2pp.

## DOCKETED ITEMS

7907110318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907050118 Discusses schedule of response to IE Bulletin 78-12, 78-12A & 78-12B C-E reactor vessel manufacturer is engaged in requested records search Final response to bulletin will be made by 790629  
DAIL, L C Duke Power Co 79/05/16 1p

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p

7907190176 Responds to IE Bulletin 79-07 SUPERPIPE computer program used on piping analysis Primary coolant loop analysis will be performed by C-E who will not use algebraic summation methods for combining responses  
DAIL, L C Duke Power Co 79/05/29 2pp

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907090420 Ack receipt of IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10 No proprietary info  
DAIL, L C Duke Power Co 79/06/06 1p

--7907090426 Forwards IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 2pp

--7907090433 IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10 No noncompliance noted Major areas inspected dam const QA/QC controls, work performance, quality records & licensee actions re previous insp findings  
LENAHAN, J J Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 5pp

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

7907060048 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020379 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

## V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 790101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20 2pp

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp

## DOCKET STN-30-493 CHEROKEE NUCLEAR STATION, UNIT 3

## Q Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of matl fact. Certificate of Svc encl.  
BORDENICK, B M Branch 4 79/05/25 2pp.

## Q Inspection reports, IE Bulletins &amp; correspondence

7907020367 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 2pp.

7907110318 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 2pp

7907050118 Discusses schedule of response to IE Bulletin 78-12, 12A & 12B, C-E reactor vessel manufacturer is engaged in requested records search Final response to Bulletin will be made by 790629.  
DAIL, L C Duke Power Co 79/05/16 1p

7907100167 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907060353 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 1p.

7907190176 Responds to IE Bulletin 79-07 SUPERPIPE computer program used on piping analysis Primary coolant loop analysis will be performed by C-E who will not use algebraic summation methods for combining responses  
DAIL, L C Duke Power Co 79/05/29 2pp

7907200170 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp.

7907090420 Ack receipt of IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10 No proprietary info  
DAIL, L C Duke Power Co 79/06/06 1p

--7907090426 Forwards IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 2pp

--7907090433 IE Insp Repts 50-491/79-09, 50-492/79-09 & 50-493/79-09 on 790508-10. No noncompliance noted Major areas inspected dam const QA/QC controls, work performance, quality records & licensee actions re previous insp findings.  
LENAHAN, J J Region 2, Atlanta, Office of the Director  
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 5pp.

# DOCKETED ITEMS

7907190159 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 2pp

790706004B Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020198 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020379 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120051 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310012 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 2pp

7907180288 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180431 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 2pp

7907310245 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 2pp

7907310371 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 1p

## V Operator Examinations

7907250394 FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 & license exams & test results for Duke Power Co employees from 750101 to present  
AHRENDT, B Jefferson Pilot Broadcasting 79/06/20, 2pp

7907250408 Responds to FOIA request for summary sheet of power plant operator exam results presented to NRC on 790420 Forwards documents listed on App A  
FELTON, J M Division of Rules and Records 79/07/18 3pp.

## DOCKET STN-50-495 SNEBBAR-P1

### A Application/construction stage documents & correspondence

7907050029 Forwards Amend 3 to preliminary design approval & notice of issuance  
BOYD, R B Division of Project Management 79/06/01, 2pp

--7907050034 Amend 3 to preliminary design approval extending date from 790603 to 790818  
BOYD, R B Division of Project Management. 79/06/01, 3pp.

--7907050038 Notice of issuance of Amend 3 to preliminary design approval  
HELTEME, C J Standardization Branch 79/06/01 3pp.

### K Utility Final Safety Analysis Report (FSAR) & amends

7907230350 Forwards Amend 40 to SBAR, SNEBBAR-P1  
KENNEDY, W J L Stone & Webster, Inc. 79/07/16 2pp.

--7907230374 Amend 40 to SBAR, SNEBBAR-P1 Amend addresses extent to which design complies w/regulatory requirements review committee Category I items  
\* Stone & Webster, Inc 79/07/16 27pp

## DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

### Q Adjudicatory correspondence

7907090062 Notifies that depositions have been taken from RL Steder PPG Industries & EV Sherry of Air Products & Chemicals Central Power & Light has furnished NRC-requested documents to City of Brownsville, TX  
RYAN, T O Isham, Lincoln & Seale 79/05/01 1p

7907120002 Citizens Concerned About Nuclear Power motion for reconsideration of ASLB 790507 order in which former's motion to strike 790501 notice of appeal & preceding brief was denied Certificate of Svc encl  
SINKIN, S A Citizens Concerned About Nuclear Power, Inc. 79/05/14 3pp.

--7907120004 Citizens Concerned About Nuclear Power response to Houston Lighting & Power brief on appeal from prehearing conference ruling upon intervention petitions Certificate of Svc encl  
SINKIN, S A Citizens Concerned About Nuclear Power, Inc 79/05/14 20pp

7907110184 Supplements Citizens for Equitable Utils original petition to intervene in proceeding Certificate of Svc encl  
BUCHERN, P Affiliation Unknown. 79/05/29 9pp

7907130442 Ack by Houston Lighting & Power re receipt of NRC 790529 1 suggesting addl time for further negotiations Opposes request & urges ASLB to rule on pleadings in order to commence discovery  
NEWMAN, J R, REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll SCHWARZ, M D Baker & Botts 79/06/05 4pp

--7907130471 Houston Lighting & Power response to intervenor Citizens Concerned About Nuclear Power Reformulated Contentions 2 & 3 Urges dismissal of Reformulated Contention 2 except Paragraphs d & e & acceptance of Reformulated Contention 3  
NEWMAN, J R, REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll SCHWARZ, M D Baker & Botts 79/06/05 6pp

--7907130486 Houston Lighting & Power response to intervenor Citizens Equitable Utils 790529 suppl to original petition Urges ASLB to act on open issues & partially dismiss Contentions 1 & 5 Certificate of Svc encl  
NEWMAN, J R, REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll SCHWARZ, M D Baker & Botts 79/06/05 12pp

7907100674 Memo & order granting NRC, Citizens Concerned About Nuclear Power & Citizens for Equitable Utils 790529 request for extension until 790702 for NRC to file re status of negotiations on various contentions  
BECHHDEFER, C Atomic Safety and Licensing Board Panel 79/06/08 4pp.

### H General correspondence

7907190124 Approves 790807 request to establish second LPDR at Austin Public Library. Reproduction of records to be forwarded is in progress  
FELTON, J M Division of Rules and Records 79/06/13 1p

--7907190130 Requests LPDR for Austin Public Library.  
MCCELLEAN, C K Austin, TX 79/05/07 2pp

### K Utility Final Safety Analysis Report (FSAR) & amends

7907170147 Forwards Amend 7 to FSAR  
TURNER, E A Houston Lighting & Power Co 79/07/16 1p

--7907170151 Amend 7 to FSAR  
\* Houston Lighting & Power Co. 79/07/16, 347pp

### M Antitrust correspondence

7907050444 Submits discovery rpt for Apr 1979. No discoveries initiated or received  
BAQUOH, R C Austin, TX 79/05/08, 4pp.

7907190213 Summarizes Public Utils Board of City of Brownsville, TX discovery progress for Apr 1979 Certificate of Svc encl  
POIRIER, M R Spiegel & McDiarmid 79/05/14, 6pp.

- 7907050319 Forwards NRC 790514 documents per request w/o encl  
LESSY, R P Anti-Trust Division 79/05/17 1p
- 7907090471 Forwards US District Court for Northern District of TX  
790515 order denying plaintiffs' motion to amend judgment in  
West TX Utils vs TX Electric Svc, CA9-76-633-F  
FLYNN, P G Lowenstein, Newman, Reis, Axelrad & Toll 79/05/23 11pp
- 7907110152 Houston Lighting & Power addl answers to NRC 790115 initial  
interrogatories Affidavit & Certificate of Svc encl  
COPELAND, J G Baker & Botts 79/05/24 27pp
- 7907090056 Summarizes discovery matters per 790601 prehearing  
conference  
COPELAND, J G Baker & Botts 79/05/25 9pp
- 7907180879 TX Utils Generating Co & subsidiaries supplemental answer  
to NRC initial interrogatories Affidavit, Certificate of Svc  
& Apps A & B encl  
SAMPOLS, M D Worsham, Forsythe & Sampsels KNOTTS, J B Debevoise &  
Lieberman SCARTH, E D Texas Utilities Co 79/05/25 18pp
- 7907180040 DDJ rept re progress made on discovery during May 1979 Rept  
submitted per ASLB 780521 order  
HARRIS, J L Justice, Dept of 79/06/01 6pp
- 7907170117 Public Utils Board of City of Brownsville second application  
for issuance of subpoena for production of documents by El  
Paso Electric Draft of subpoena encl  
POIRIER, M R Spiegel & McDiarmid 79/06/12 18pp
- 7907170154 Public Utils Board of City of Brownsville application for  
issuance of subpoena for production of documents by El Paso  
Electric Certificate of Svc encl  
POIRIER, M R Spiegel & McDiarmid 79/03/13 10pp
- 7907200005 TX Utils Generating Co first set of interrogatories &  
production of documents, directed to TEX-LA Electric  
Cooperative, Seventeen Member Cooperatives & any successor  
entities Certificate of Svc encl  
KNOTTS, J B Debevoise & Lieberman WORSHAM, J I, SAMPOLS, M D  
Worsham, Forsythe & Sampsels 79/06/18 12pp
- 7907190435 Houston Lighting & Power & TX Utils Generating Co joint  
application for issuance of subpoenas calling for production  
of documents re util industry competition, access to plants &  
interstate operation Certificate of Svc & drafts encl  
COPELAND, J G Baker & Botts BDUKNIGHT, J A Lowenstein, Newman,  
Reis, Axelrad & Toll 79/06/18 20pp
- 7907190431 Order per 790601 conference ruling on motions & responses  
filed Mar-Apr 1979 by Houston Lighting & Power, TX  
Utils, Gulf States Util, Central Power & Light & NRC Amends  
790404 order re schedule of proceedings  
HOLFE, S J Atomic Safety and Licensing Board Panel NRC 79/06/25  
4pp.
- 7907190834 Forwards Public Utils Board of City of Brownsville, TX 790626  
supplemental response to Houston Lighting & Power first  
request for production of documents & first set of  
interrogatories  
WHITE, B G Spiegel & McDiarmid 79/06/26 1p
- 7907190846 Public Utility Board of City of Brownsville, TX supplemental  
response to Houston Lighting & Power first request for  
production of documents & first set of interrogatories  
Affidavit & Certificate of Svc encl  
JABLON, R A Texas, State of 79/06/26 19pp
- 7907260038 DDJ & NRC joint application for issuance of subpoenas  
for testimony & production of documents re issue of  
competition, structure of electric util industry & plant  
access w/ Certificate of Svc & drafts of subpoenas  
LESSY, R P Anti-Trust Division HARRIS, J L Justice, Dept of  
79/07/03 89pp
- 7907260014 TX Utils Generating Co discovery rept for June 1979  
Certificate of Svc encl  
KNOTTS, J B Debevoise & Lieberman 79/07/06 5pp
- 4 Inspection reports, IE Bulletins & correspondence
- 7907110603 Forwards IE Insp Repts 50-498/79-05 & 50-499/79-05 on  
790402-06 & notice of violation  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/04/30 2pp
- 7907110612 IE Insp Repts 50-498/79-05 & 50-499/79-05 on 790402-06  
Noncompliance noted failure to follow procedures for storage  
of mat'l & for preparation of nonconformance rept  
HUBACEK, W G, MARTIN, L E, CROSSMAN, W A Region 4, Dallas, 79/04/25 7pp  
Reactor Construction & Engineering Support Branch
- 7907080174 Forwards IE Insp Repts 50-498/79-06 & 50-499/79-06 on  
790417-20 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/05/01 2pp
- 7907050179 IE Insp Repts 50-498/79-06 & 50-499/79-06 on 790417-20 No  
noncompliance noted Major areas inspected const activities,  
records review, housekeeping & equipment storage  
HUBACEK, W G, CROSSMAN, W A Region 4, Dallas, Office of the  
Director 79/04/30 4pp
- 7907310618 Responds to IE Bulletin 79-04 Investigation indicates that  
no Velan swing check valves are being used No action  
necessary  
TURNER, E A Houston Lighting & Power Co 79/05/21 1p
- 7907310607 Responds to IE Bulletin 79-07 Investigation indicates  
that no methods listed in Item 1 of bulletin were used in  
seismic piping analysis  
TURNER, E A Houston Lighting & Power Co 79/05/24 2pp
- 7907030123 Forwards IE Info Notice 79-13, "Indication of Low Water  
Level in Oyster Creek Reactor"  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/29  
1p
- 7907200354 Forwards IE Bulletin 79-12, "Short Period Scrums at DHR  
Facilities" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31  
1p
- 7907260477 Forwards IE Insp Repts 50-498/79-08 & 50-499/79-08 on  
790518-1B & notice of violation  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/04 2pp
- 7907260485 Notice of violation from insp on 790518-1B,  
\* Region 4, Dallas, Reactor Construction & Engineering Support  
Branch 79/06/04 1p
- 7907260492 IE Insp Repts 50-498/79-08 & 50-499/79-08 on 790518-1B  
Noncompliance noted lack of procedure for monitoring  
welding operations  
CROSSMAN, W A, HALL, R E, GILBERT, L D Region 4, Dallas,  
Reactor Construction & Engineering Support Branch 79/06/01 4pp
- 7907190395 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves)." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06,  
1p
- 7907060015 Forwards IE Info Notice 79-15, "Deficient Procedures" No  
action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07  
1p.
- 7907240047 Ack receipt of 790525 ltr informing NRC of steps taken to  
correct violations noted in IE Insp Repts 50-498/79-05 &  
50-499/79-05  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch, 79/06/08 1p.
- 7907240125 Responds to NRC 790430 ltr re violations noted in IE Insp  
Repts 50-498/79-05 & 50-499/79-08 Corrective actions, boron  
recycle evaporator covered w/ interim structure which meets  
storage requirements  
TURNER, E A Houston Lighting & Power Co. 79/05/25 2pp.
- 7907300055 Forwards IE Insp Repts 50-498/79-09 & 50-499/79-09 on  
790518-1B & 22-23. No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/08 2pp
- 7907300058 IE Insp Repts 50-498/79-09 & 50-499/79-09 on 790518-1B &  
22-23 No noncompliance noted Major areas inspected,  
allegations of irregularities in QA program for civil const  
activities  
HUBACEK, W G, CROSSMAN, W A Region 4, Dallas, Office of the  
Director, 79/06/08 8pp
- 7907050542 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director, 79/06/11  
1p.



7907310561 Forwards IE Insp Repts 50-498/79-07 & 50-499/79-07 on  
790507-09 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/18 2pp

--7907310574 IE Insp Repts 50-498/79-07 & 50-499/79-07 on 790507-09 No  
noncompliance noted Major areas inspected const phase  
environ control program, audits, transmission line work,  
special studies & monitoring programs  
EVERETT, R J Region 4, Dallas, Office of the Director  
BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety  
Branch 79/06/14 5pp

7907030509 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20  
1p

7907030485 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts "  
Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21  
1p

7907120598 Forwards IE Bulletin 79-13, "Cracking in Feedwater Bys  
Piping." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25  
1p

7907110246 Forwards IE Circular 79-10, "Pipe Fittings Mfg from  
Unacceptable Matl " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26  
1p

7907180252 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27  
1p

7907100516 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28  
1p.

7907110292 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/02  
1p

7907190495 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/11  
1p.

7907240305 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13  
1p

7907270394 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp.  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/07/18  
1p

#### B Reportable occurrences, LERs & related correspondence

7907030268 Forwards PNO-79-67AB, "Nuclear Incident at TMI "  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/05/31 1p

7907020305 Forwards PNO-79-67AR  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch. 79/06/05 1p

7907050372 Forwards PNO-79-67AS, "Nuclear Incident at TMI "  
SEIDLE, W C Region 4, Dallas, Office of the Director 79/06/13.  
1p.

7907030209 Forwards PNO-79-67AT  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/06/19. 1p

7907130336 Forwards PNO-79-67AU  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch. 79/06/27 1p.

7907180685 Forwards PNO-79-67AV  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/07/06 1p

7907240517 Forwards PNO-79-67AW  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering  
Support Branch 79/07/13 1p

7907260657 Submits interim deficiency rept re concrete voids in eighth  
lift of Unit 1 reactor containment bldg Detailed plan for  
investigating entire eighth lift has been prepared &  
complete rept will be available 790815  
TURNER, E A Houston Lighting & Power Co 79/07/16 2pp

#### U Congressional/Executive Correspondence

7907260082 Responds to 790809 ltr re power plant design to resist  
tornadoes Discusses tornado design criteria Forwards two  
repts re Apr 1979 tornadoes in TX.  
QOSSICK, L V Office of the Executive Director for Operations  
79/06/04 2pp

#### DOCKET BTN-50-499 SOUTH TEXAS PROJECT, UNIT 2

#### Q Adjudicatory correspondence

7907120002 Citizens Concerned About Nuclear Power motion for  
reconsideration of ASLB 790507 order in which former's  
motion to strike 790501 notice of appeal & preceding brief  
was denied Certificate of Svc encl  
BINKIN, S A Citizens Concerned About Nuclear Power, Inc 79/05/14  
3pp

--7907120004 Citizens Concerned About Nuclear Power response to Houston  
Lighting & Power brief on appeal from prehearing conference  
ruling upon intervention petitions Certificate of Svc encl  
BINKIN, S A Citizens Concerned About Nuclear Power, Inc  
79/05/14 20pp

7907110186 Supplements Citizens for Equitable Utils original petition  
to intervene in proceeding Certificate of Svc encl  
BUCHORN, P Affiliation Unknown 79/05/29 9pp

7907130442 Ack by Houston Lighting & Power re receipt of NRC 790529 ltr  
suggesting addl time for further negotiations Opposes  
request & urges ASLB to rule on pleadings in order to  
commence discovery  
NEWMAN, J R, REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll.  
SCHWARZ, M D Baker & Botts 79/06/05 4pp

--7907130471 Houston Lighting & Power response to intervenor Citizens  
Concerned About Nuclear Power Reformulated Contentions  
2 & 3. Urges dismissal of Reformulated Contention 2 except  
Paragraphs d & f & acceptance of Reformulated Contention 3  
NEWMAN, J R, REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll  
SCHWARZ, M D Baker & Botts 79/06/05 4pp

--7907130486 Houston Lighting & Power response to intervenor Citizens for  
Equitable Utils 790529 suppl to original petition Urges ASLB  
to act on open issues & partially dismiss Contentions 1 & 3.  
Certificate of Svc encl  
NEWMAN, J R, REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll  
SCHWARZ, M D Baker & Botts 79/06/05 12pp

7907100674 Memo & order granting NRC/Citizens Concerned About  
Nuclear Power & Citizens for Equitable Utils 790529 request  
for extension until 790702 for NRC to file rept re status of  
negotiations on various contentions  
BECHHOEFER, C Atomic Safety and Licensing Board Panel 79/06/08  
4pp

#### H General correspondence

7907190124 Approves 790807 request to establish second LPDR at Austin  
Public Library Reproduction of records to be forwarded is  
in progress  
FELTON, J H Division of Rules and Records 79/06/13 1p

--7907190130 Requests LPDR for Austin Public Library  
MCCELLAN, C K, Austin, TX 79/05/07 2pp

#### K Utility Final Safety Analysis Report (FSAR) & amends

7907170147 Forwards Amend 7 to FSAR  
TURNER, E A Houston Lighting & Power Co 79/07/16 1p

## DOCKETED ITEMS

--7907170151 Amend 7 to F8AR  
\* Houston Lighting & Power Co 79/07/16 547pp

M Antitrust correspondence

7907050444 Discovery rept for Apr 1979 No discoveries initiated or received  
BALOUQH, R C Austin, TX 79/05/08 4pp

7907190213 Summarizes Public Utils Board of City of Brownsville, TX discovery progress for Apr 1979 Certificate of Svc encl  
FOIRIER, M R Spiegel & McDiarmid 79/05/14 6pp

7907050319 Forwards NRC 790514 documents per request W/o encl  
LESSY, R P Anti-Trust Division 79/05/17 1p

7907090471 Forwards US District Court for Northern District of TX 790515 order denying plaintiffs' motion to amend judgment in West TX Utils vs TX Electric Svc, CA3-76-633-F  
FLYNN, P G Lowenstein, Newman, Reis, Axelrad & Toll 79/05/23 11pp

7907110152 Houston Lighting & Power addl answers to NRC 790115 initial interrogatories Affidavit & Certificate of Svc encl  
COPELAND, J O Baker & Botts 79/05/24 27pp

7907090056 Summarizes discovery matters per 790601 prehearing conference  
COPELAND, J O Baker & Botts 79/05/25 9pp

7907180879 TX Utils Generating Co & subsidiaries supplemental answer to NRC initial interrogatories Affidavit, Certificate of Svc & Apps A & B encl  
SAMPELS, M D Worsham, Forsythe & Sampels KNDTTS, J B Debevoise & Lieberman SCARTH, E D Texas Utilities Co 79/05/25 18pp

7907180040 DOJ rept re progress made on discovery during May 1979 Rept submitted per AGLD 780621 order.  
HARRIS, J L Justice, Dept of 79/06/01 6pp

7907170117 Public Utils Board of City of Brownsville second application for issuance of subpoena for production of documents by El Paso Electric Draft of subpoena encl  
FOIRIER, M R Spiegel & McDiarmid 79/06/12 18pp

--7907170154 Public Utils Board of City of Brownsville application for issuance of subpoena for production of documents by El Paso Electric Certificate of Svc encl  
FOIRIER, M R Spiegel & McDiarmid 79/06/13 10pp

7907020003 TX Utils Generating Co first set of interrogatories & production of documents, directed to TEX-LA Electric Cooperative, Seventeen Member Cooperatives & any successor entities Certificate of Svc encl  
KNDTTS, J B Debevoise & Lieberman 79/06/18 12pp

7907190435 Houston Lighting & Power & TX Utils Generating Co joint application for issuance of subpoenas calling for production of documents re util industry competition, access to plants & interstate operation Certificate of Svc & drafts encl  
COPELAND, J O Baker & Botts 79/06/18 20pp

7907190431 Order reflecting 790601 conference ruling on several motions & responses filed Mar-Apr 1979 by Houston Lighting & Power, TX Utils, Gulf States, Central Power & Light & NRC Amends 790404 order re schedule of proceedings  
WOLFE, B J Atomic Safety and Licensing Board Panel NRC 79/06/25, 4pp

7907190834 Forwards Public Utils Board of City of Brownsville, TX 790626 supplemental response to Houston Lighting & Power first request for production of documents & first set of interrogatories  
WHITE, B O Spiegel & McDiarmid 79/06/26 1p

--7907190846 Public Utils Board of City of Brownsville, TX supplemental response to Houston Lighting & Power first request for production of documents & first set of interrogatories Affidavit & Certificate of Svc encl  
JABLON, R A Texas, State of 79/06/26 19pp

7907260038 DOJ & NRC joint application for issuance of subpoenas for testimony & production of documents re issue of competition, structure of electric util industry & plant access W/Certificate of Svc & drafts of subpoenas.  
LESSY, R P Anti-Trust Division 79/07/03 89pp.

7907260014 TX Utils Generating Co discovery rept for June 1979, Certificate of Svc encl  
KNDTTS, J B Debevoise & Lieberman 79/07/06 5pp

Q Inspection reports, IE Bulletins & correspondence

7907110603 Forwards IE Insp Repts 50-498/79-05 & 50-499/79-05 on 790402-06 & notice of violation  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 2pp

--7907110606 Notice of violation from insp on 790402-06  
\* Region 4, Dallas, Office of the Director 79/04/25 2pp

--7907110612 IE Insp Repts 50-498/79-05 & 50-499/79-05 on 790402-06 Noncompliance noted failure to follow procedures for storage of matl & for preparation of nonconformance rept  
HUBACEK, W G, MARTIN, L E, CROSSMAN, W A Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/25 7pp

7907050174 Forwards IE Insp Repts 50-498/79-06 & 50-499/79-06 on 790417-20 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/01 2pp

--7907050179 IE Insp Repts 50-498/79-06 & 50-499/79-06 on 790417-20 No noncompliance noted Major areas inspected const activities, records review, housekeeping & equipment storage  
HUBACEK, W G, CROSSMAN, W A Region 4, Dallas, Office of the Director 79/04/30 4pp

7907310618 Responds to IE Bulletin 79-04 Investigation indicates that no Velan swing check valves are being used No action necessary  
TURNER, E A Houston Lighting & Power Co 79/05/21 1p

7907310607 Responds to IE Bulletin 79-07 Investigation indicates that no methods listed in Item 1 of bulletin were used in seismic piping analysis  
TURNER, E A Houston Lighting & Power Co 79/05/24 2pp

7907030123 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor"  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/29 1p.

7907200354 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/31 1p.

7907260477 Forwards IE Insp Repts 50-498/79-08 & 50-499/79-08 on 790515-18 & notice of violation  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/04 2pp

--7907260485 Notice of violation from insp on 790515-18  
\* Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/04 1p

--7907260492 IE Insp Repts 50-498/79-08 & 50-499/79-08 on 790515-18 Noncompliance noted lack of procedure for monitoring welding operations  
CROSSMAN, W A, HALL, R E, GILBERT, L D Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/01 4pp

7907190395 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/06 1p

7907060015 Forwards IE Info Notice 79-15, "Deficient Procedures," No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/07 1p

7907240047 Ack receipt of 790525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-05 & 50-499/79-05  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/08 1p

--7907240125 Responds to NRC 790430 ltr re violations noted in IE Insp Repts 50-498/79-05 & 50-499/79-05 Corrective actions boron recycle evaporator covered w/interim structure which meets storage requirements  
TURNER, E A Houston Lighting & Power Co 79/05/25 2pp

7907300055 Forwards IE Insp Repts 50-498/79-09 & 50-499/79-09 on 790515-18 & 22-23 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/08 2pp.

--7907300058 IE Insp Repts 50-498/79-09 & 50-499/79-09 on 790515-18 & 22-23 No noncompliance noted Major areas inspected  
allegations of irregularities in QA program for civil const activities  
HUBACEK, W C, CROSSMAN, W A Region 4, Dallas, Office of the Director 79/06/08 8pp

7907050562 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907310561 Forwards IE Insp Repts 50-498/79-07 & 50-499/79-07 on 790507-09 No noncompliance noted  
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/18 2pp

--7907310574 IE Insp Repts 50-498/79-07 & 50-499/79-07 on 790507-09 No noncompliance noted Major areas inspected const phase  
environ control programs, audits, transmission line work, special studies & monitoring programs  
EVERETT, R J Region 4, Dallas, Office of the Director  
BROWN, O D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/06/14 3pp

7907050509 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/20 1p

7907050485 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/21 1p

7907120598 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/25 1p

7907110246 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/26 1p

7907180252 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27 1p

7907100316 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/28 1p

7907110292 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director, 79/07/02 1p.

7907190495 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
SEYFRIT, K V, Region 4, Dallas, Office of the Director 79/07/11 1p

7907240305 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/07/13 1p

7907270394 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
SEYFRIT, K V Region 4, Dallas, Office of the Director, 79/07/18, 1p.

#### B. Reportable occurrences, LERS & related correspondence

7907030248 Forwards PNO-79-67A6, "Nuclear Incident at TMI." SEIDLE, W C, Region 4, Dallas, Reactor Construction & Engineering Support Branch, 79/03/31, 1p

7907020305 Forwards PNO-79-67AR, SEIDLE, W C, Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/05, 1p.

7907050572 Forwards PNO-79-67AB, "Nuclear Incident at TMI " SEIDLE, W C, Region 4, Dallas, Office of the Director, 79/06/13 1p

7907030209 Forwards PNO-79-67AT SEIDLE, W C, Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/19 1p

7907130336 Forwards PNO-79-67AU SEIDLE, W C, Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/27 1p

7907180685 Forwards PNO-79-67AV SEIDLE, W C, Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/06 1p

7907240517 Forwards PNO-79-67AW SEIDLE, W C, Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/07/13 1p

7907260657 Submits interim deficiency rept re concrete voids in eighth lift of Unit 1 reactor containment bldg Detailed plan for investigating entire eighth lift has been prepared & complete rept will be available 790819  
TURNER, E A Houston Lighting & Power Co 79/07/16 2pp

#### U Congressional/Executive Correspondence

7907260082 Responds to 790509 ltr re power plant design to resist tornadoes Discusses tornado design criteria Forwards two repts re Apr 1979 tornadoes in TX  
OGBICK, L V Office of the Executive Director for Operations 79/06/04 2pp

#### DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

##### A Application/construction stage documents & correspondence

7907110340 Suggests careful execution of maint program outlined in Diamond Power control rod drive control sys vendor manual Procedures should prevent trip breaker problems  
FAIST, F R Babcock & Wilcox Co 78/06/12 1p.

7907130445 Expresses satisfaction that 790501 meeting provided info requested re operation of nuclear power plants in OH  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907130474 Requests briefing be arranged on 790501 or 790502 re safe operation of nuclear power plants in OH  
MCAVOY, J F Ohio, State of 79/04/16 1p

--7907130479 Requests comments, in view of TMI, re adequacy of facility staff training, safety & emergency procedures & plant design  
Also seeks info re sys & produces safety reviews planned for facilities in OH  
MCAVOY, J F Ohio, State of, 79/04/12 1p

#### G Adjudicatory correspondence

7907050395 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients  
ULMAN, M B Operations & Administrative Division, 79/05/07 1p

--7907050399 Board notification recommends Boards of Allens Creek, Davis Besse 2 & 3 & New England should be notified re nonsafety-grade equipment to mitigate transients  
VASSALLO, D B Division of Project Management 79/04/30 1p

--7907050401 Forwards 790316 memo recommending Board notification of assessment to be made re nonsafety-grade equipment to mitigate transients  
VASSALLO, D B Division of Project Management 79/03/29, 2pp

--7907050405 Recommends Board notification of assessment to be made re recent issue on nonsafety-grade equipment to mitigate transients.  
TEDESCO, R L, Assistant Director for Reactor Safety 79/03/16 3pp.

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4, 79/05/25 2pp

## DOCKETED ITEMS

## DOCKET 80-301 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

## A Application/construction stage documents &amp; correspondence

7907110340 Suggests careful execution of maint program outlined in Diamond Power control rod drive control sys vendor manual. Procedures should prevent trip breaker problems. FAIBT, F R Babcock & Wilcox Co 78/06/12 1p

7907130465 Expresses satisfaction that 790501 meeting provided info requested re operation of nuclear power plants in OH. BENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p

--7907130474 Requests briefing be arranged on 790301 or 790502 re safe operation of nuclear power plants in OH. MCAVOY, J F Ohio, State of 79/04/16 1p

--7907130479 Requests comments in view of TMI re adequacy of facility staff training, safety & emergency procedures & plant design. Also seeks info re sys & produces safety reviews planned for facilities in OH. MCAVOY, J F Ohio, State of 79/04/12 1p

## D Adjudicatory correspondence

7907050395 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients. ULMAN, H B Operations & Administrative Division 79/05/07 1p

-7907050399 Board notification recommends Boards of Athens Creek, Davis Besse 2 & 3 & New England should be notified re nonsafety-grade equipment to mitigate transients. VASSALLO, D B Division of Project Management 79/04/30 1p

-7907050401 Forwards 790316 memo recommending Board notification of assessment to be made re nonsafety-grade equipment to mitigate transients. VASSALLO, D B Division of Project Management 79/03/29 2pp

-7907050405 Recommends Board notification of assessment to be made re recent issue on nonsafety-grade equipment to mitigate transients. TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7907160131 Requests summary disposition of Intervenor's Ecology Action of Duwago & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of mat'l fact. Certificate of Svc encl. BORDENICK, B H Branch 4 79/03/25 29pp.

## Inspection reports, IE Bulletins &amp; correspondence

07100322 Submits summary of discussion w/JS Creswell re safety concerns influenced by TMI incident. Requests review of concerns by OIC of Nuclear Reactor Regulation & update of status of resolution. BRYAN, B E Division of Reactor Operations Inspections. 79/05/17 2pp

## DOCKET STN-80-502 HAVEN NUCLEAR PLANT, UNIT 1

## Utility Environmental Report (ER), amendments &amp; correspondence

79100338 Forwards add'l info re environ rept. in response to NRC 790315 request. AY, C W Wisconsin Electric Power Co. 79/06/20 135pp.

## Insurance &amp; indemnity information

79100605 Forwards monthly rept re expenditures & commitments concerning Haven nuclear plant. Enrichment prepayment data removed from Exhibit C. BURSTEIN, B Wisconsin Electric Power Co 79/06/29 5pp.

## DOCKET STN-80-503 HAVEN NUCLEAR PLANT, UNIT 2

## Insurance &amp; indemnity information

79100605 Forwards monthly rept re expenditures & commitments concerning Haven nuclear plant. Enrichment prepayment data removed from Exhibit C. BURSTEIN, B Wisconsin Electric Power Co 79/06/29 5pp.

## DOCKET STN-80-504 KOSHKONONG NUCLEAR PLANT, UNIT 1

## J Insurance &amp; indemnity information

7907100605 Forwards monthly rept re expenditures & commitments concerning Haven nuclear plant. Enrichment prepayment data removed from Exhibit C. BURSTEIN, B Wisconsin Electric Power Co 79/06/29 5pp

## DOCKET STN-80-505 KOSHKONONG NUCLEAR PLANT, UNIT 2

## J Insurance &amp; indemnity information

7907100605 Forwards monthly rept of info re expenditures & commitments concerning Haven nuclear plant. Enrichment prepayment removed from Exhibit C. BURSTEIN, B Wisconsin Electric Power Co 79/06/29 5pp

## DOCKET STN-80-506 KOSHKONONG NUCLEAR PLANT, UNIT 3

## J Insurance &amp; indemnity information

7907100605 Forwards monthly rept of info re expenditures & commitments concerning Haven nuclear plant. Enrichment prepayment removed from Exhibit C. BURSTEIN, B Wisconsin Electric Power Co 79/06/29 5pp

## DOCKET STN-80-507 KOSHKONONG NUCLEAR PLANT, UNIT 4

## J Insurance &amp; indemnity information

7907100605 Forwards monthly rept of info re expenditures & commitments concerning Haven nuclear plant. Enrichment prepayment removed from Exhibit C. BURSTEIN, B Wisconsin Electric Power Co 79/06/29 5pp

## DOCKET STN-80-508 WPPSS NUCLEAR PROJECT, UNIT 3

## A Application/construction stage documents &amp; correspondence

7907110508 Forwards, under separate cover, "Evaluation of Faults & Landslides, Grays Harbor County, WA" & "Evaluation of Joints in Astoria Formation, WPPSS Nuclear Project 3 & 5 Geologic Mapping Project" re supplemental faulting studies. TILLSON, D D Washington Public Power Supply System 79/07/03 1p.

## G Inspection reports, IE Bulletins &amp; correspondence

7907300098 Forwards IE Insp Repts 80-508/79-04 & 80-509/79-03 on 790417-20 & notice of violation. SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/22 2pp

--7907300101 Notice of violation from insp on 790417-20. w Region 5, San Francisco, Office of the Director 79/05/22 1p

--7907300107 IE Insp Repts 80-508/79-04 & 80-509/79-03 on 790417-20. Noncompliance noted. Failure to perform in-process test on grout used for structural purposes. KIRSCH, D F, HUTEON, T. W., HAYNES, R. C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/03/22 12pp.

--7907300110 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-508/79-04 & 80-509/79-03. SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/07/10 1p

--7907300114 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 80-508/79-04 & 80-509/79-03. Corrective actions grout placement w/o flow cone documented. Task force to increase surveillance of testing. STRAND, N O. Washington Public Power Supply System 79/06/19 3pp.

7907090237 Responds to IE Bulletin 79-04. No Velan swing check valves used. Nine testable check valves will be provided by Velan to be used in HPCS, LPCB, reactor core isolation cooling & RHR. Seismic Category 1 piping sys. RENBERGER, D L Washington Public Power Supply System. 79/05/25 2pp.

7907180076 Responds to IE Bulletin 78-12, 12A & 12B Reactor vessel mfg for WNP-3/5 requested to perform records search mfg plans to submit generic rept covering all reactor vessels by C-E Vendor certifies applicability of rept  
RENNBERGER, D L Washington Public Power Supply System 79/05/25  
1p

7907200379 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/05/31 1p

7907190436 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class 1E Equipment (Deficiencies in Environ Qualification of ABCO Bolanoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/06 1p

7907060036 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/07 1p

7907020271 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907020453 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/20 1p

7907120017 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/21 1p

7907270296 Forwards IE Insp Repts 50-508/79-05 & 50-509/79-04 on 790514-17 No noncompliance noted  
SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/21 2pp

--7907270306 IE Insp Repts 50-508/79-05 & 50-509/79-04 on 790514-17 No noncompliance noted Major areas inspected licensee action on IE bulletins & circulars, previous insp findings & QA procedures  
DOODS, R T, KIRSCH, D F, HUTSON, T W Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/21 12pp

7907120630 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/25 1p

7907060226 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907050497 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/27 1p

7907100334 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/28 1p

7907130222 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/02 1p

7907180711 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/11 1p

7907310401 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/13 1p

7907260285 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/18 1p

9 Reportable occurrences, LERs & related correspondence

7907020291 Forwards PND-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/05 1p

7907030200 Forwards PND-79-67AS  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907030244 Forwards PND-79-67AT, "Nuclear Incident at TMI " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/19 1p

7907050543 Forwards PND-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907130390 Forwards PND-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/03 1p

DOCKET 57N-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

A Application/construction stage documents & correspondence

7907110508 Forwards, under separate cover, "Evaluation of Faults & Landslides, Grays Harbor County, WA" & "Evaluation of Joints in Astoria Formation, WPPSS Nuclear Project 3 & 5 Geologic Mapping Project" re supplemental faulting studies  
TILLSON, D D Washington Public Power Supply System 79/07/03 1p

B Inspection reports, IE Bulletins & correspondence

7907300098 Forwards IE Insp Repts 50-508/79-04 & 50-509/79-03 on 790417-20 & notice of violation  
SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/22 2pp

--7907300101 Notice of violation from insp on 790417-20  
\* Region 5, San Francisco, Office of the Director 79/05/22 1p

--7907300107 IE Insp Repts 50-508/79-04 & 50-509/79-03 on 790417-20 Noncompliance noted failure to perform in-process test on grout used for structural purposes  
KIRSCH, D F, HUTSON, T W, HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/22 12pp

--7907300110 Ack receipt of 790619 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-508/79-04 & 50-509/79-03  
SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/07/10 1p

--7907300114 Responds to NRC 790522 ltr re violations noted in IE Insp Repts 50-508/79-04 & 50-509/79-03 Corrective actions: grout placement w/o flow cone documented Task force to increase surveillance of testing  
STRAND, N D Washington Public Power Supply System 79/06/19 3pp

7907090237 Responds to IE Bulletin 79-04 No Velan swing check valves used Nine testable check valves will be provided by Velan which will be used in HPCS, LPCB, reactor core isolation cooling & RHR Seismic Category 1 piping sys.  
RENNBERGER, D L Washington Public Power Supply System 79/05/25 2pp

7907180076 Responds to IE Bulletin 78-12, 12A & 12B Reactor vessel mfg for WNP-3/5 requested to perform records search mfg plans to submit generic rept covering all reactor vessels by C-E Vendor certifies applicability of rept  
RENNBERGER, D L Washington Public Power Supply System 79/05/25 1p

7907200379 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/05/31 1p

## DOCKETED ITEMS

7907190436 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/06 1p

7907040036 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/07 1p

7907020271 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907020453 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/20 1p

7907120017 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/21 1p

7907270296 Forwards IE Insp Repts 50-508/79-05 & 50-509/79-04 on 790514-17 No noncompliance noted  
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/21 2pp

-7907270306 IE Insp Repts 50-508/79-05 & 50-509/79-04 on 790514-17 No noncompliance noted Major areas inspected licensee action on IE bulletins & circulars, previous insp findings & QA procedures  
ODDSE, R T, KIRSCH, D F, HUTSON, T W Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/06/21, 12pp

707120630 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/25 1p

07060226 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

07050497 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/27 1p

7100534 Forwards IE Circular 79-12, "Potential Diesel Generator unboiler Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
9/06/28 1p

7130222 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
7/07/02 1p

7180711 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " tion required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
7/07/11 1p

310401 Forwards IE Circular 79-13, "Replacement of Diesel Fire mp Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
7/07/13 1p

260286 Notifies that written responses to IE Bulletin 79-15, Suppl should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
7/07/18 1p

portable occurrences, LERs & related correspondence

20291 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
06/08 1p

30200 Forwards PNO-79-67AS  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
06/11 1p

7907030244 Forwards PNO-79-67AT, "Nuclear Incident at TMI "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/19 1p

7907050543 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907130390 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/03 1p

DOCKET 50-510 BLUE HILLS STATION, UNIT 1

H General correspondence

7907180458 Submits changes to distribution list for FES (NUREG-0449) errata  
RICHARDSON, K W Gulf States Utilities Co 79/07/11 1p

DOCKET 50-511 BLUE HILLS STATION, UNIT 2

H General correspondence

7907180458 Submits changes to distribution list for FES (NUREG-0449) errata  
RICHARDSON, K W Gulf States Utilities Co 79/07/11 1p

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

7907200331 Requests approval of application of ASME Code Case N-242 to four atmospheric dump valves Valves will be made for B&H by Control Components, Inc Forwards Certificate of Conformance from mfg  
RENNBERGER, D L Washington Public Power Supply System 79/07/13 4pp

G Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

G. Inspection reports, IE Bulletins & correspondence

7907120396 Forwards IE Insp Repts 50-460/79-02 & 50-513/79-02 on 790212-16 & notice of violation  
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/03 2pp

--7907120406 Notice of violation from insp on 790212-16  
\* Region 5, San Francisco, Office of the Director 79/03/30 2pp

--7907120419 IE Insp Repts 50-460/79-02 & 50-513/79-02 on 790212-16 Noncompliance noted. Failure to follow procedures re design control & document control & failure to include applicable requirements in procurement documents  
HAYNES, R C, KIRSCH, D F, ECKHARDT, J H Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/03 33pp

--7907120456 Responds to NRC 790403 ltr re violations noted in IE Insp Repts 50-460/79-02 & 50-513/79-02 Corrective actions field change notice 257-1-79-02B revised to reflect correct quality class QA reviewed & approved  
RENNBERGER, D L Washington Public Power Supply System 79/05/09 6pp

--7907120471 Ack 790509 ltr informing NRC of steps taken to correct items listed in NRC 790403 ltr  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/31 2pp.

7907090237 Responds to IE Bulletin 79-04 No Velan swing check valves used Nine testable check valves will be provided by Velan which will be used in HPCS, LPCS, reactor core isolation cooling & RHR Seismic Category 1 piping sys  
RENNBERGER, D L Washington Public Power Supply System 79/05/25 2pp.

# DOCKETED ITEMS

7907090275 Responds to IE Bulletins 79-12, 12A & 12B No reason to suspect atypical weld wire was used in fabrication of reactor vessels  
RENNBERGER, D L Washington Public Power Supply System 79/05/29  
ip.

7907200379 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/05/31 ip

7907190436 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/06 ip

7907060036 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/07 ip

7907020271 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 ip

7907020453 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate, " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/10 ip

7907120017 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/06/21 ip

7907120630 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/25 ip

7907060226 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 ip

7907050477 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/27 ip

7907100534 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/28 ip

7907130222 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/07/02 ip

7907180711 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/11 ip

7907310401 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/13 ip

7907260286 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/07/18 ip.

## B. Reportable occurrences, LERs & related correspondence

7907020291 Forwards PNO-79-67AR.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/05 ip.

7907030200 Forwards PNO-79-67AB  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/06/11 ip.

7907030244 Forwards PNO-79-67AT, "Nuclear Incident at TMI "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/19 ip

7907050343 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director.  
79/06/26 ip

7907130390 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/03 ip

## DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

### A Application/construction stage documents & correspondence

7907020230 Forwards meteorological monitoring program annual rept.  
1974-1977 Encl available in Central Files only  
LINDBLAD, W J Portland General Electric Co 79/06/27 ip

### O Adjudicatory correspondence

7907090051 Discusses proposal to reschedule & improve flexibility of DDE enrichment svc for facility Proposes conversion from current long-term fixed commitment contract to new adjustable fixed commitment contract  
HASTINGS, W Portland General Electric Co 79/04/27 2pp

7907060370 Notifies of change of address effective 790601  
YORE, J R Atomic Safety and Licensing Board Panel 79/06/01 ip

7907060472 Cancels 790620 conference in Portland, OR Conference will be rescheduled  
RE, J R Atomic Safety and Licensing Board Panel 79/06/14 ip

7907240364 Notifies of change of counsel effective 790618 JH Durham replaces HH Phillips  
DURHAM, J W Portland General Electric Co 79/06/18 ip

### R Periodic operating reports & related correspondence

7907100408 Forwards "Preconstruction Ecological Studies for Site," suppl to May 1978 final rept  
LINLAD, W J Portland General Electric Co 79/04/12 2pp

--7907100414 "Preconstruction Ecological Studies for Site," suppl to M. 1978 final rept  
\* Portland General Electric Co 79/02/28 107pp

## DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

### A Application/construction stage documents & correspondence

7907020230 Forwards meteorological monitoring program annual rept.  
1974-1977 Encl available in Central Files only  
LINDBLAD, W J Portland General Electric Co 79/06/27 ip

### O Adjudicatory correspondence

7907090051 Discusses proposal to reschedule & improve flexibility of DDE enrichment svc for facility Proposes conversion from current long-term fixed commitment contract to new adjustable fixed commitment contract  
HASTINGS, W Portland General Electric Co. 79/04/27 2pp.

7907060370 Notifies of change of address effective 790601  
YORE, J R Atomic Safety and Licensing Board Panel 79/06/01 ip.

7907060472 Cancels 790620 conference in Portland, OR Conference will be rescheduled.  
RE, J R Atomic Safety and Licensing Board Panel. 79/06/14 ip

7907240364 Notifies of change of counsel effective 790618 JH Durham replaces HH Phillips.  
DURHAM, J W Portland General Electric Co 79/06/18 ip.

### R Periodic operating reports & related correspondence

7907100408 Forwards "Preconstruction Ecological Studies for Site," suppl to May 1978 final rept.  
LINLAD, W J Portland General Electric Co. 79/04/12 2pp

## DOCKETED ITEMS

--7907100414 "Preconstruction Ecological Studies for Site," suppl to May 1978 final rept  
\* Portland General Electric Co 79/02/28 107pp

## DOCKET STN-90-516 JAMESPORT NUCLEAR STATION, UNIT 1

## Q Adjudicatory correspondence

7907200122 Notifies that Suffolk County, NY legislature passed resolution opposing CP sought by util  
LIKE, I Reilly, Like & Schneider 79/05/10 1p

--7907200145 Unexecuted Resolution 1450-79 passed by Suffolk County, NY legislature opposing CP sought by util Nuclear Facility would represent unacceptable safety risk to population  
MRAZEK, DEVINE, FOLEY New York, State of 79/05/10 2pp

7907120119 Forwards Suffolk County, NY legislature opposing facility const  
RDQERB, W H Suffolk County, NY 79/05/28 1p

--7907120129 Resolution opposing const of facility  
\* Suffolk County, NY 79/04/26 1p

7907160196 Requests ASLAB grant extension of time to evaluate info re TMI event & relevance of info to proceeding Request granted on condition that NRC file monthly status rept  
BORDENICK, B M Branch 4 79/06/07 2pp

## Q Inspection reports, IE Bulletins &amp; correspondence

7907060387 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 1p

7907030033 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200107 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190057 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/06/06 1p

7907060101 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020046 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

79070300512 Responds to IE Bulletin 79-09 Purchase orders for circuit breakers in safety-related sys have not been placed If OE Type AK-2 circuit breakers are used, preventive maint program will be conducted  
PLASKON, R E Long Island Lighting Co 79/06/12 1p.

907100471 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p.

907230674 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/06/21 1p.

7907120500 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/23 1p.

7907100308 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100418 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907100502 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180775 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270337 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310502 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/16 1p

## DOCKET STN-90-517 JAMESPORT NUCLEAR STATION, UNIT 2

## Q Adjudicatory correspondence

7907200122 Notifies that Suffolk County, NY legislature passed resolution opposing CP sought by util  
LIKE, I Reilly, Like & Schneider 79/05/10 1p.

--7907200145 Unexecuted Resolution 1450-79 passed by Suffolk County, NY legislature opposing CP sought by util Nuclear Facility would represent unacceptable safety risk to population  
MRAZEK, DEVINE, FOLEY New York, State of 79/05/10 2pp

7907120119 Forwards Suffolk County, NY legislature opposing facility const  
RDQERB, W H Suffolk County, NY 79/05/28 1p

--7907120129 Resolution opposing const of facility  
\* Suffolk County, NY 79/04/26 1p

7907160196 Requests ASLAB grant extension of time to evaluate info re TMI event & relevance of info to proceeding Request granted on condition that NRC file monthly status rept  
BORDENICK, B M Branch 4 79/06/07 2pp.

## Q. Inspection reports, IE Bulletins &amp; correspondence

7907060387 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/05/22 1p.

7907030033 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/29 1p

7907200107 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/31 1p

7907190057 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves) " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/06 1p

7907060101 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/07 1p

7907020046 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/06/11 1p



# DOCKETED ITEMS

7907300512 Responds to IE Bulletin 79-09 Purchase orders for circuit breakers in safety-related sys have not been placed if GE Type AK-2 circuit breakers are used, preventive maint program will be conducted  
PLASKON, R E Long Island Lighting Co 79/06/12 1p

7907100471 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/20 1p

7907230674 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"  
Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/21 1p

7907120500 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/25 1p

7907100308 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/26 1p

7907100418 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

7907100502 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/28 1p

7907180775 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/02 1p

7907270337 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/07/11 1p

7907310502 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director, 79/07/16 1p

## DOCKET BTN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

0 Adjudicatory correspondence

7907180131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of matl Fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

## 0 Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/21 3pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/07 3pp.

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/10 3pp

7907130432 Forwards IE Insp Repts 50-518/79-09, 50-519/79-09, 50-520/79-09 & 50-521/79-09 on 790417-20, No noncompliance noted.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 2pp

--7907130443 IE Insp Repts 50-518/79-09, 50-519/79-09, 50-520/79-09 & 50-521/79-09 on 790417-20 No noncompliance noted Major areas inspected Category 1 concrete, spray ponds & steel structures & supports  
SWAN, W B, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 6pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907240084 Forwards IE Insp Repts 50-518/79-10, 50-519/79-10, 50-520/79-10 & 50-521/79-10 on 790507-10 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/18 2pp

--7907240099 IE Insp Repts 50-518/79-10, 50-519/79-10, 50-520/79-10 & 50-521/79-10 No noncompliance noted Major areas inspected const activities, previously identified items, 10CFR50.55(a) & 10CFR21 items, IE circulars & preventive maint program  
BURDETTE, T E, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/18 4pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 3pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Velan swing check valves have not been installed or scheduled for installation in any Beismic Category 1 piping sys.  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Bcams at BWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping investigation of non-NSSB sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp.

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/06/07 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/06/20 1p.

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p.

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp.

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
O'REILLY, J. P Region 2, Atlanta, Office of the Director  
79/07/13 Gpd

# S Reportable occurrences, LERs & related correspondence

7907120299 Submits rept re incorrect welding of structural steel used in reactor pressure vessel shield wall. Corrective action includes radiographing all joints incorrectly cut & repaired by welding.  
BERGHUIS, F C Industrial Engineering Works 79/04/30 2pp

7907090388 Forwards deficiency rept re spray pond central support earthfill moisture content being outside of acceptable limits.  
GILLELAND, J E Tennessee Valley Authority 79/04/01 1p

--7907090395 Deficiency rept during period 780705-0915, essential svc water spray pond central & support earthfill placed w/moisture content outside acceptable limits. Caused by mathematical errors in computation QC manual revised.  
\* Tennessee Valley Authority 79/04/01 18pp

## DOCKET BTN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

### 0 Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of mat'l fact. Certificate of Svc encl.  
BORDENICK, B M Branch 4 79/05/25 29pp

### 0 Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 3pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 3pp

7907130432 Forwards IE Insp Repts 50-518/79-09, 50-519/79-09, 50-520/79-09 & 50-521/79-09 on 790417-20 No noncompliance noted.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 2pp

--7907130443 IE Insp Repts 50-518/79-09, 50-519/79-09, 50-520/79-09 & 50-521/79-09 on 790417-20 No noncompliance noted. Major areas inspected Category I concrete, spray ponds & steel structures & supports.  
SWAN, W B, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 6pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907240084 Forwards IE Insp Repts 50-518/79-10, 50-519/79-10, 50-520/79-10 & 50-521/79-10 on 790507-10 No noncompliance noted.  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/18 2pp

--7907240099 IE Insp Repts 50-518/79-10, 50-519/79-10, 50-520/79-10 & 50-521/79-10 No noncompliance noted. Major areas inspected, const activities, previously identified items, 10CFR50.55(a) & 10CFR21 items, IE circulars & preventive maint program.  
BURDETTE, T E, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/18 4pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 3pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Velan swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys.  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR Facilities." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Investigation of non-NSSS sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components.  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/23 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 3pp

# S. Reportable occurrences, LERs & related correspondence

7907120299 Submits rept re incorrect welding of structural steel used in reactor pressure vessel shield wall. Corrective action includes radiographing all joints incorrectly cut & repaired by welding.  
BERGHUIS, F C Industrial Engineering Works 79/04/30 2pp

## DOCKET BTN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

### 0 Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record. Deficiencies do not raise genuine issue of mat'l fact. Certificate of Svc encl.  
BORDENICK, B M Branch 4 79/05/25 29pp

## DOCKETED ITEMS

0 Inspection reports, IE Bulletins & correspondence

---

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 3pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/10 3pp

7907130432 Forwards IE Insp Repts 50-518/79-09, 50-519/79-09, 50-520/79-09 & 50-521/79-09 on 790417-10 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 2pp

--7907130443 IE Insp Repts 50-518/79-09, 50-519/79-09, 50-520/79-09 & 50-521/79-09 on 790417-20 No noncompliance noted Major areas inspected Category I concrete, spray ponds & steel structures & supports  
SWAN, W B Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 6pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp

7907240084 Forwards IE Insp Repts 50-518/79-10, 50-519/79-10, 50-520/79-10 & 50-521/79-10 on 790507-10 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/18 2pp

--7907240099 IE Insp Repts 50-518/79-10, 50-519/79-10, 50-520/79-10 & 50-521/79-10 No noncompliance noted Major areas inspected const activities previously identified items, 10CFR50.55(e) & 10CFR21 items, IE circulars & preventive maint program  
BURDETTE, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/18 4pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 3pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Valves swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys.  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907000210 Forwards IE Bulletin 79-12, "Short Period Grams at BWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NSSB sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures," No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp.

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310243 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp.

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 3pp

B Reportable occurrences, LERs & related correspondence

---

7907120299 Submits rept re incorrect welding of structural steel used in reactor pressure vessel shield wall Corrective action includes radiographing all joints incorrectly cut & repaired by welding by util  
BERGHUIS, F C Industrial Engineering Works 79/04/30 2pp

DOCKET BTN-50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

---

A. Application/construction stage documents & correspondence

---

7907040196 Forwards Amend 4 to application for CP & QL Affidavit & Certificate of Svc encl  
ELLIS, J W Puget Sound Power & Light Co 79/07/02 5pp

--7907060201 Amend 4 to application for CP & QL Forwards Annual Rept 1978 for Pacific Power Co, WA Water Power Co, Puget Sound Power & Light Co & Portland General Electric Co encl.  
ELLIS, J W Puget Sound Power & Light Co 79/06/30 75pp.

--7907060205 Annual Financial Rept 1978, suppl  
\* Washington Water Power Co 78/12/31 22pp

7907120632 Forwards draft case study re protection of wild & scenic rivers, to be used in factbook being prepared under contract w/DOE  
WEINSTEIN, S. Urban Systems Research & Engineering, Inc 79/07/02 3pp.

7907170042 Affidavit of svc for Amend 14 to application.  
LAFLEUR, J. Puget Sound Power & Light Co. 79/07/02. 2pp

0 Adjudicatory correspondence

---

7907110733 Forwards Apr 1979 "Interpretation Rept on Aeromagnetic Coverage of Skagit Nuclear Power Project" Rept constitutes interpretation of aeromagnetic data, in response to June 1978 request, w/o encl, Certificate of Svc encl  
LITTLE, D. S. Perkins, Coie, Stone, Olsen & Williams 79/05/03 3pp

7907060518 Motion by Upper Skagit Indian Tribe, Sauk-Suiattle Indian Tribe & Swinomish Tribal Community that ASLB expedite issuance of written decision denying intervention Delay may prejudice position on appeal  
BUSCH, R. W. Evergreen Legal Services, MEANS, D. S. Means, Donald S 79/05/15, 3pp.

- 7906260334 Opposes Skagitians Concerned About Nuclear Power 790427 motion re meeting procedures regarding contentions Meetings between NRC & applicants are to facilitate exchange of add info Certificate of Svc encl  
BLACK, R L Branch 1 79/05/17 7pp
- 7906260336 Responds to Skagitians Concerned About Nuclear Power 790427 motion re Class 9 accidents Requests denial of suppl to FES & deferral of proposed mod of issues pending further NRC submission Certificate of Svc encl  
BLACK, R L Branch 1 79/05/17 7pp
- 7907060489 Interrogatories & document requests for Puget Sound Power & Light Co submitted by Skagitians Concerned About Nuclear Power Questions concern Bechtel reinvestigation of site area & evacuation plans  
LEED, R M Skagitians Concerned About Nuclear Plants 79/05/29 9pp
- 7907130038 Interrogatories & document requests to WA Power Co. submitted by intervenors Skagitians Concerned About Nuclear Power Requests include info re const costs, operation costs & estimated cost of power Certificate of Svc encl  
LEED, R M Leed, Roger M 79/05/29 5pp
- 7907130045 Interrogatories & document requests to NRC, submitted by intervenors Skagitians Concerned About Nuclear Power Requests include info re thermal pollution & salmonids, earthquakes & generic safety issues raised by TMI  
LEED, R M Leed, Roger M 79/05/29 6pp
- 7907130024 Interrogatories & document requests to Pacific Power & Light, submitted by Skagitians Concerned About Nuclear Power Requests include info re Form IO-K for 1978, environ effects of plant & activities of employees & consultants  
LEED, R M Leed, Roger M 79/05/30 7pp
- 7907130029 Interrogatories & document requests to Portland General Electric, submitted by Skagitians Concerned About Nuclear Power Requests include info re 790227 prospectus, coal contracts, bank credit & activities of employees  
LEED, R M Leed, Roger M 79/05/30 8pp
- 7907090007 Interrogatories & document requests, submitted for intervenor Skagitians Concerned About Nuclear Power by util Questions concern geological features, design & const of plant, names of witnesses & emergency plans Certificate of Svc encl  
THOMSEN, F T, LITTLE, D S Perkins, Cole, Stone, Olsen & Williams 79/05/31 14pp
- 7907090001 Forwards suppl testimony of DL Schreiber & affidavits of WS Bivens & BM Goldstein re impacts of delivery of reactor pressure vessels Impact is insignificant & unchanged from evaluation in FES & Final Suppl  
BLACK, R L Branch 1 79/06/01 2pp
- 7907090002 Testimony re Ranney Collector Sys Sys is sufficient to provide plant water needs under varying conditions w/minimal impact on water resources  
SCHREIBER, D L Puget Sound Power & Light Co 79/06/01 12pp
- 7907090003 Assessment of impacts re delivery of reactor pressure vessel submitted in response to SM Jensch, Chairman of ASLB, 790608 ltr Delivery will affect aquatic sys in Skagit River & have minor terrestrial impacts  
BIVENS, W S Hydrology Meteorology Branch QDLSTEIN, R M Argonne National Laboratory 79/06/01 19pp
- 7907250204 Submits joint testimony of RE Olson, ME Coberley, LB Pack & JM Coombs. Util does not have reasonable assurance of obtaining funds for const & fuel cycle costs Prof qualifications & Certificate of Svc encl  
OLSON, R E Puget Sound Power & Light Co COBERLEY, M E Portland General Electric Co PACK, L S Pacific Gas & Electric Co 79/06/01 54pp
- 7907060516 Request by Skagit County, WA that ASLB grant intervenor status Local govt should be fully represented  
MCMULLEN, P R Skagit County, WA 79/06/05 2pp
- 7907130344 Puget Sound Power & Light does not object to Skagit County, WA 790605 petition to intervene before ASLB. Participation must not delay completion of hearing & issuance of initial decision. Certificate of Svc encl  
THOMSEN, F T, Perkins, Cole, Stone, Olsen & Williams 79/06/07 6pp
- 7907060125 Answers to Skagitians Concerned About Nuclear Power 790524 & 30 discovery requests, submitted by WA Water Power Co. Responds to questions re cash flow forecast & proposed coal-fired plants  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams O'KELLY, A P Paine, Lowe, Coffin, Herman & O'Kelly 79/06/13 10pp
- 7907180368 Answer to Skagitians Concerned About Nuclear Power 790530 interrogatories & document requests Util has no documents containing info on min capacity for spent fuel for 1978  
SMITH, R M Pacific Power & Light Co 79/06/14 2pp
- 7907190318 Notice of appeal of ASLB 790601 order not to entertain nontimely petition to intervene Forwards brief of Swinomish Tribal Community, Upper Skagit Indian Tribe & Sauk-Suiattle Indian Tribe in support of appeal  
BUSCH, R W Evergreen Legal Services MEANS, D S Means, Donald S 79/06/14 2pp
- 7907190324 Brief of Swinomish Tribal Community, Upper Skagit Indian Tribe & Sauk-Suiattle Indian Tribe in support of appeal of ASLB 790601 order denying intervention ASLB failed to examine reasons advanced by Tribes under 10CFR2 7.4 (a)(1)  
BUSCH, R W Evergreen Legal Services MEANS, D S Means, Donald S 79/06/14 26pp
- 7907180539 Answer to Skagitians Concerned About Nuclear Power 790530 interrogatories & document requests Responds to questions re financial matters. Certificate of Svc encl  
HASTINGS, W Portland General Electric Co 79/06/18 10pp
- 7907180619 Answers submitted by Puget Sound Power & Light Co to Skagitians Concerned About Nuclear Power 790524 document requests & interrogatories Submits info re Bechtel site investigation, financial matters & geological surveys  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 79/06/19 13pp
- 7907180629 Answers submitted by Puget Sound Power & Light Co to Skagitians Concerned About Nuclear Power 790530 document requests & interrogatories for Pacific Power & Light Co Certificate of Svc encl  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 79/06/19 13pp
- 7907180611 No objection to Skagit County 790605 petition to intervene ASLB must require intervenors to indicate, prior to hearings, sub matters on which they will participate Certificate of Svc encl  
BLACK, R L Branch 1 79/06/25 4pp
- 7907260490 Responds to 790530 ltr requesting updated accident rates for aircraft operating at Whidbey Island Naval Air Station  
Accident rate increased in recent years  
BLACK, R L Branch 1 79/06/29 2pp
- H General correspondence  
-----
- 7907170138 Forwards affidavit of svc for Amend 4 to application W/o encl  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 79/07/10 1p
- T Hearing transcripts on non-antitrust matters  
-----
- 7907020494 Forwards page 536 of 760818 transcript in joint proceeding re WL Hallmark 760818 application for subpoena duces tecum Subpoena granted orally on 760818 but never confirmed by written order  
BLACK, R L Branch 1 79/05/02 3pp
- 7907300113 Transcript of 790717 hearing in Seattle, WA Pp 11, 954-12, 146  
DEALE, V B, LINENBERGER, O A, HOOPER, F F Atomic Safety and Licensing Board Panel 79/07/17 193pp
- 7907270285 Transcript of 790718 hearing in Seattle, WA Pp 12, 147-12, 354  
Testimony & exhibits encl.  
DEALE, V B, LINENBERGER, O A, HOOPER, F F Atomic Safety and Licensing Board Panel 79/07/18 225pp
- 7907270265 Transcript of 790719 hearing in Seattle, WA Pp 12, 355-12, 543  
Testimony & exhibits encl.  
DEALE, V B, LINENBERGER, O A, HOOPER, F F Atomic Safety and Licensing Board Panel 79/07/19 400pp
- DOCKET STN-90-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2  
-----
- A Application/construction stage documents & correspondence  
-----
- 7907060196 Forwards Amend 4 to application for CP & OL Affidavit & Certificate of Svc encl  
ELLIS, J W Puget Sound Power & Light Co 79/07/02 5pp
- 7907060201 Amend 4 to application for CP & OL Forwards Annual Rept 1978 for Pacific Power Co, WA Water Power Co, Puget Sound Power & Light Co & Portland General Electric Co encl.  
ELLIS, J W Puget Sound Power & Light Co 79/06/30 75pp

## DOCKETED ITEMS

--7907060205 Annual Financial Rept 1978, suppl  
\* Washington Water Power Co 78/12/31 22pp

7907120632 Forwards draft case study re protection of wild & scenic rivers, to be used in factbook being prepared under contract w/DOE  
WEINSTEIN, S Urban Systems Research & Engineering, Inc 79/07/02 3pp

7907170042 Affidavit of svc for Amend 14 to application  
LAFLEUR, J Puget Sound Power & Light Co 79/07/02 2pp

G Adjudicatory correspondence

7907110733 Forwards Apr 1979 "Interpretation Rept on Aeromagnetic Coverage of Skagit Nuclear Power Project" Rept constitutes interpretation of aeromagnetic data, in response to June 1978 request W/o encl Certificate of Svc encl  
LITTLE, D S Perkins, Cole, Stone, Olsen & Williams 79/05/03 3pp

7907060518 Motion by Upper Skagit Indian Tribe, Sauk-Suiattle Indian Tribe & Swinomish Tribal Community that ASLB expedite issuance of written decision denying intervention Delay may prejudice position on appeal  
BUSCH, R W Evergreen Legal Services MEANS, D S Means, Donald S 79/05/15 3pp

7906260534 Opposes Skagitians Concerned About Nuclear Power 790427 motion re meeting procedures regarding contentions Meetings between NRC & applicants are to facilitate exchange of addl info Certificate of Svc encl  
BLACK, R L Branch 1 79/05/17 7pp

7906260536 Responds to Skagitians Concerned About Nuclear Power 790427 motion re Class 9 accidents Requests denial of suppl to FEB & deferral of proposed mod of issues pending further NRC submission Certificate of Svc encl  
BLACK, R L Branch 1 79/05/17 7pp

7907060489 Interrogatories & document requests for Puget Sound Power & Light Co submitted by Skagitians Concerned About Nuclear Power Questions concern Bechtel reinvestigation of site area & evacuation plans  
LEED, R M Skagitians Concerned About Nuclear Plants 79/05/29 9pp

7907130038 Interrogatories & document requests to WA Power Co, submitted by intervenors Skagitians Concerned About Nuclear Power Requests include info re const costs, operation costs & estimated cost of power Certificate of Svc encl  
LEED, R M Leed, Roger M 79/05/29 5pp

7907130045 Interrogatories & document requests to NRC, submitted by intervenors Skagitians Concerned About Nuclear Power Requests include info re thermal pollution & salmonids, earthquakes & generic safety issues raised by THI  
LEED, R M Leed, Roger M 79/05/29, 6pp.

7907130024 Interrogatories & document requests to Pacific Power & Light, submitted by Skagitians Concerned About Nuclear Power Requests include info re Form IO-K for 1978, environ effects of plant & activities of employees & consultants  
LEED, R M Leed, Roger M 79/05/30 9pp

7907130029 Interrogatories & document requests to Portland General Electric, submitted by Skagitians Concerned About Nuclear Power Requests include info re 790227 prospectus, coal contracts, bank credit & activities of employees  
LEED, R M Leed, Roger M 79/05/30, 8pp

7907090009 Interrogatories & document requests, submitted for intervenor Skagitians Concerned About Nuclear Power by util Questions concern geological features, design & const of plant, names of witnesses & emergency plans, Certificate of Svc encl  
THOMSEN, F T, LITTLE, D S Perkins, Cole, Stone, Olsen & Williams. 79/05/31 14pp

7907090001 Forwards suppl testimony of DL Schreiber & affidavits of HS Bivens & BM Goldstein re impacts of delivery of reactor pressure vessels Impact is insignificant & unchanged from evaluation in FEB & Final Suppl  
BLACK, R L Branch 1 79/06/01. 2pp.

--7907090002 Testimony re Ranney Collector Sys Bys Bys is sufficient to provide plant water needs under varying conditions w/minimal impact on water resources  
SCHREIBER, D L Puget Sound Power & Light Co 79/06/01. 12pp

--7907090003 Assessment of impacts re delivery of reactor pressure vessel submitted in response to BW Jensch, Chairman of ASLB, 790608 1tr Delivery will affect aquatic sys in Skagit River & have minor terrestrial impacts  
BIVENS, W S Hydrology Meteorology Branch GOLDSTEIN, R M Argonne National Laboratory 79/06/01 19pp

7907230204 Submits joint testimony of RE Olson, ME Coberley, LB Pack & JM Coombs Util does not have reasonable assurance of obtaining funds for const & fuel cycle costs Prof qualifications & Certificate of Svc encl  
OLSON, R E Puget Sound Power & Light Co COBERLEY, M E Portland General Electric Co PACK, L S Pacific Gas & Electric Co 79/06/01 54pp

7907060516 Request by Skagit County, WA that ASLB grant intervenor status Local govt should be fully represented  
MCMULLEN, P R Skagit County, WA 79/06/05 2pp

7907130344 Puget Sound Power & Light does not object to Skagit County, WA 790605 petition to intervene before ASLB Participation must not delay completion of hearing & issuance of initial decision Certificate of Svc encl  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 79/06/07 6pp

7907060125 Answers to Skagitians Concerned About Nuclear Power 790524 & 30 discovery requests, submitted by WA Water Power Co Responds to questions re cash flow forecast & proposed coal-fired plants  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams O'KELLY, A P Paine, Lowe, Coffin, Herman & O'Kelly 79/06/13 10pp

790718036B Answer to Skagitians Concerned About Nuclear Power 790530 interrogatories & document requests Util has no documents containing info on min capacity for spent fuel for 1978  
SMITH, R M Pacific Power & Light Co 79/06/14. 2pp

7907190318 Notice of appeal of ASLB 790601 order not to entertain nontimely petition to intervene Forwards brief of Swinomish Tribal Community, Upper Skagit Indian Tribe & Sauk-Suiattle Indian Tribe in support of appeal  
BUSCH, R W Evergreen Legal Services MEANS, D S Means, Donald S 79/06/14 2pp

--7907190324 Brief of Swinomish Tribal Community, Upper Skagit Indian Tribe & Sauk-Suiattle Indian Tribe in support of appeal of ASLB 790601 order denying intervention ASLB failed to examine reasons advanced by Tribes under 10CFR2 7 4 (a)(1)  
BUSCH, R W Evergreen Legal Services MEANS, D S Means, Donald S 79/06/14 26pp

7907180539 Answer to Skagitians Concerned About Nuclear Power 790530 interrogatories & document requests Responds to questions re financial matters Certificate of Svc encl  
HASTINGS, W Portland General Electric Co 79/06/18 10pp

7907180619 Answers submitted by Puget Sound Power & Light Co to Skagitians Concerned About Nuclear Power 790524 document requests & interrogatories Submits info re Bechtel site investigation, financial matters & geological surveys  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 79/06/19 13pp

7907180629 Answers submitted by Puget Sound Power & Light Co to Skagitians Concerned About Nuclear Power 790530 document requests & interrogatories for Pacific Power & Light Co Certificate of Svc encl  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 79/06/19 13pp

7907180611 No objection to Skagit County 790605 petition to intervene ASLB must require intervenors to indicate, prior to hearings, subj matters on which they will participate Certificate of Svc encl  
BLACK, R L Branch 1 79/06/25 4pp

7907260490 Responds to 790530 1tr requesting updated accident rates for aircraft operating at Whidbey Island Naval Air Station Accident rate increased in recent years  
BLACK, R L Branch 1. 79/06/29 2pp

H General correspondence

7907170138 Forwards affidavit of svc for Amend 4 to application W/o encl  
THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 79/07/10. 1p

T Hearing transcripts on non-antitrust matters

7907020494 Forwards page 536 of 760818 transcript in joint proceeding re WL Hallmark 760818 application for subpoena duces tecum Subpoena granted orally on 760818 but never confirmed by written order  
BLACK, R L Branch 1 79/05/02 3pp

7907300113 Transcript of 790717 hearing in Seattle, WA Pp 11, 954-12, 146  
DEALE, V B, LINENBERGER, Q A, HOOPER, F F Atomic Safety and Licensing Board Panel 79/07/17 193pp

7907270285 Transcript of 790718 hearing in Seattle, WA Pp 12, 147-12, 354  
Testimony & exhibits encl  
DEALE, V B, LINENBERGER, Q A, HOOPER, F F Atomic Safety and Licensing Board Panel 79/07/18 225pp

7907270265 Transcript of 790719 hearing in Seattle, WA Pp 12, 395-12, 543  
Testimony & exhibits encl  
DEALE, V B, LINENBERGER, Q A, HOOPER, F F Atomic Safety and Licensing Board Panel 79/07/19 400pp

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7907110724 Ack receipt of 790418 ltr transmitting design groundwater levels for facility Finds levels acceptable Const of water storage reservoir & evaporation ponds can proceed  
BOYD, R S Division of Project Management 79/06/11 3pp

B Utility Preliminary Safety Analysis Report, amends

7907120561 Forwards errata pages to list of effective pages to Amend 20 to PSAR  
VANBRUNT, E E Arizona Public Service Co ANPP-13345-JMA 79/06/27 2pp

--7907120564 Errata pages for list of effective pages to Amend 20 to PSAR  
\* Arizona Public Service Co 79/06/27 25pp

G Inspection reports, IE Bulletins & correspondence

7907270405 Responds to IE Bulletin 79-04 Swing check valves mfg by Vellan Engineering Corp are not in use in safety-related sys  
VANBRUNT, E E Arizona Public Service Co 79/05/21 1p

7907090239 Responds to IE Bulletin 79-07 No methods specified in bulletin used for seismic analysis of safety-related piping Piping computer programs for seismic stress analysis verified by NBSB  
VAN BRUNT, E E Arizona Public Service Co 79/05/25 2pp

7907200367 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/31, 1p

7907190416 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves) " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/06, 1p

7907060027 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/07, 1p.

7907020262 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/11, 1p.

7907020447 Forwards IE Info Notice 79-17, "Bounce Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/20 1p

7907120005 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/21 1p

7907120615 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/25 1p

7907060213 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/26 1p

7907030491 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/27 1p

7907110019 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/28 1p

7907130198 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/02 1p

7907180699 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/11 1p

7907130395 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/07/13 1p

7907260267 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/07/18 1p

S Reportable occurrences, LERs & related correspondence

7907020280 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/05 1p

7907030186 Forwards PNO-79-67AB  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/11 1p

7907030229 Forwards PNO-79-67AT, "Nuclear Incident at TMI " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/19, 1p.

7907050528 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/06/26, 1p

7907130383 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 79/07/03 1p

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7907110724 Ack receipt of 790418 ltr transmitting design groundwater levels for facility Finds levels acceptable Const of water storage reservoir & evaporation ponds can proceed  
BOYD, R S Division of Project Management 79/06/11 3pp

B Utility Preliminary Safety Analysis Report, amends

7907120561 Forwards errata pages to list of effective pages to Amend 20 to PSAR  
VANBRUNT, E E Arizona Public Service Co ANPP-13345-JMA 79/06/27 2pp

--7907120564 Errata pages for list of effective pages to Amend 20 to PSAR  
\* Arizona Public Service Co. 79/06/27 25pp

G Inspection reports, IE Bulletins & correspondence

7907270405 Responds to IE Bulletin 79-04 Swing check valves mfg by Vellan Engineering Corp are not in use in safety-related sys  
VANBRUNT, E E Arizona Public Service Co 79/05/21, 1p.

## DOCKETED ITEMS

7907090239 Responds to IE Bulletin 79-07 No methods specified in bulletin used for seismic analysis of safety-related piping Piping computer programs for seismic stress analysis verified by NSSS  
VAN BRUNT, E E Arizona Public Service Co 79/05/25 2pp

7907200367 Forwards IE Bulletin 79-12, "Short Period Seisms at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/05/31 1p

7907190416 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/06 1p

7907060027 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/07 1p

7907020262 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907020447 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/20 1p

7907120005 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/21 1p

7907120615 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/25 1p

7907060213 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907050491 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/27 1p

7907110019 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/28 1p

7907130198 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/02 1p

7907180699 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/11 1p

7907310395 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/13 1p

7907260267 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/18 1p

#### B Reportable occurrences, LERs & related correspondence

7907020280 Forwards PNO-79-67AR  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/08 1p

7907030186 Forwards PNO-79-67AB  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907030229 Forwards PNO-79-67AT, "Nuclear Incident at TH1 "  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/19 1p

7907050528 Forwards PNO-79-67AU  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p

7907130383 Forwards PNO-79-67AV  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/07/03 1p

#### DOCKET 87N-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

##### A Application/construction stage documents & correspondence

7907110724 Ack receipt of 790418 ltr transmitting design groundwater levels for facility Finds levels acceptable Const of water storage reservoir & evaporation ponds can proceed  
BOYD, R B Division of Project Management 79/06/11 3pp

##### B Utility Preliminary Safety Analysis Report, amends

7907120361 Forwards errata pages to list of effective pages to Amend 20 to PSAR  
VANBRUNT, E E Arizona Public Service Co ANPP-13345-JMA 79/06/27 2pp

--7907120564 Errata pages for list of effective pages to Amend 20 to PSAR  
\* Arizona Public Service Co 79/06/27 25pp

##### C Inspection reports, IE Bulletins & correspondence

7907270405 Responds to IE Bulletin 79-04 Bwing check valves mfg by Velan Engineering Corp are not in use in safety-related sys  
VANBRUNT, E E Arizona Public Service Co 79/05/21 1p

7907090239 Responds to IE Bulletin 79-07 No methods specified in bulletin used for seismic analysis of safety-related piping Piping computer programs for seismic stress analysis verified by NSSS  
VAN BRUNT, E E Arizona Public Service Co 79/05/25 2pp

7907200367 Forwards IE Bulletin 79-12, "Short Period Seisms at BWR Facilities " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/05/31 1p

7907190416 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/06 1p

7907060027 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/07 1p

7907020262 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys,"  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/11 1p

7907020447 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/20 1p

7907120005 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/21 1p

7907120615 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/25 1p

7907060213 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl." No action required.  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/26 1p.



# DOCKETED ITEMS

21

7907080491 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/06/27 1p

790710019 Forwards IE Circular 79-12, "Potential Diesel Generator Turb charger Problem " No action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director.  
79/06/28 1p

7907130198 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/07/02 1p

7907180699 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/07/11 1p

7907310395 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/07/13 1p

7907260267 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/07/18 1p

## S Reportable occurrences, LERs & related correspondence

7907020280 Forwards PNO-79-67AR  
ENGELKEN, R H Region 3, San Francisco, Office of the Director.  
79/06/08 1p

7907030186 Forwards PNO-79-67AS  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/06/11 1p

7907030229 Forwards PNO-79-67AT, "Nuclear Incident at TMI "  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/06/19 1p

7907050328 Forwards PNO-79-67AU  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/06/26 1p

7907130383 Forwards PNO-79-67AV  
ENGELKEN, R H Region 3, San Francisco, Office of the Director  
79/07/03 1p

## DOCKET STN-50-535 GASSAR-4

### J Insurance & indemnity information

7907180493 Forwards Endorsement 110 to NELIA Policy NF-34  
CDREA, C Marsh & McLennan, M & M Nuclear Consultants, Inc Div  
79/07/11 2pp

## DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

### B. Utility Preliminary Safety Analysis Report, amends

7907020191 Forwards Amend 50 to PSAR  
COPELAND, R L Energy, Dept of 79/06/29 4pp.

--7907020198 Amend 50 to PSAR.  
COPELAND, R L Energy, Dept. of 79/06/29 230pp

### G. Inspection reports, IE Bulletins & correspondence

7907100025 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 2pp.

## DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR

### G. Inspection reports, IE Bulletins & correspondence

7907100076 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required.  
O'REILLY, J P. Region 2, Atlanta, Office of the Director  
79/05/18 1p

7907230409 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p

7907240466 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/06 1p

## DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

### A Application/construction stage documents & correspondence

7907250464 FOIA request for all submitted info re const or operation of plant  
LAUDIG, S Laudig, S 79/06/22 1p

7907280484 Responds to 790622 FOIA request for all submitted info re const or operation of plant Lists relative documents on file in LPDR in Madison, IN  
FELTON, J M Division of Rules and Records 79/07/09 5pp

### G Adjudicatory correspondence

7907050359 Notifies re change of address  
VOIOT, H H LeBoeuf, Lamb, Leiby & MacRae 79/05/25 2pp.

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of mat'l fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907100559 Requests suspension & revocation of facility CP & reopening of safety hearings  
EYED, J A Sassafras Audubon Society 79/06/29 13pp

### H General correspondence

7907050190 Responds to 790420 ltr questioning facility const & concerns re composition & mission of NRC  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/30 3pp

--7907050193 Expresses concern re nuclear safety of proposed plants Suggests halting const, reassessment of NRC composition, more money for alternative energy research & greater citizen participation in nuclear decisionmaking  
WATSON, B. Jefferson County, KY, 79/04/20 2pp

### G Inspection reports, IE Bulletins & correspondence

7907180456 Forwards IE Insp Repts 50-546/79-03 & 50-547/79-03 on 790403-06 notice of violation & notice of deviation  
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/04 2pp

--7907180460 Notice of violation from insp on 790403-06  
\* Region 3, Chicago, Office of the Director 79/05/03 3pp

--7907180464 Notice of deviation from insp on 790403-06  
\* Region 3, Chicago, Office of the Director 79/05/03 1p.

--7907180474 IE Insp Rept 50-546/79-03 & 50-547/79-03 on 790403-06 Noncompliance noted: failure to properly control deviations to design documents; failure to adequately insp concrete work; failure to properly train post-tensioning QC personnel  
SCHWEIBINZ, E R Region 3, Chicago, Office of the Director  
79/05/03 18pp

7907110267 Ack unofficial granting of extension requested in 790503 ltr Response to IE Bulletin 79-03 is now due 120 days after 790511.  
COUGHLIN, J. Public Service Co of Indiana, Inc 79/05/24 1p.

7907100111 Responds to IE Bulletins 78-12, 12A & 12B Assumes response date will be moved to 790713 in order to provide pressure vessel vendor time to submit generic rept  
COUGHLIN, J. Public Service Co of Indiana, Inc 79/05/25 1p

7907100214 Responds to IE Bulletin 79-04. No 1500 psi pressure-rated Velan swing check valves installed or scheduled to be installed.  
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/05/25 1p

DOCKETED ITEMS

7907240169 Forwards IE Insp Repts 50-546/79-05 & 50-547/79-05 on 790515 No noncompliance noted  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/30. 2pp

--7907240172 IE Insp Repts 50-546/79-05 & 50-547/79-05 on 790515 No noncompliance noted Major areas inspected concrete work activities, const deficiency reporting requirements & document control  
HAWKINS, F C ; HAYES, D W ; FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/29 5pp

7907240330 Forwards IE Bulletin 79-12, "Short Period Scrums at BWR Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31 1p

7907190288 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06 1p

7907240438 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/07 1p

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures" forwarded to listed utils  
PAPPAS, M Region 3, Chicago, Office of the Director 79/06/08 2pp

7907240233 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11 1p

7907300533 Responds to IE Bulletin 79-09 OE AK-2-50 circuit breakers are planned for use in safety-related sys as battery disconnect circuit breakers Potential failure mode in IE Bulletin 79-09 does not apply to planned use  
SHIELDS, B W Public Service Co of Indiana, Inc 79/06/15 1p

7907060436 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20 1p

7907120252 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21 1p

7907130147 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping, " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25 1p

7907060319 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26 1p

7907050480 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/27. 1p.

7907100525 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28 1p.

7907130289 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02 1p.

7907310345 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies, " Action required.  
KEPPLER, J G. Region 3, Chicago, Office of the Director 79/07/11 1p

7907310416 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
KEPPLER, J. G Region 3, Chicago, Office of the Director 79/07/13 1p

7907260211 Notifies that written responses to IE Bulletin 79-19, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260413 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18. 1p.

B Reportable occurrences, LERs & related correspondence

7907100568 Notifies of RO on 790601 possible damage to Unit 1 containment liner Visual insp indicates deformation in liner at bottom of pour Dimension measurements taken by Chicago Bridge & Iron  
COUGHLIN, J Public Service Co of Indiana, Inc 79/06/29 1p

7907120618 Interim deficiency rept re concrete void discovered on 790604 in auxiliary bldg slab New repair procedures have been approved but not yet performed Final rept will follow  
COUGHLIN, J Public Service Co of Indiana, Inc 79/07/05 2pp

7907120633 Updates status of 790608 RO 1 & RO 2, in response to NRC 790626 ltr RO 2 is voided Further info re RO 1 welding qualifications to be sent 790801  
COUGHLIN, J Public Service Co of Indiana, Inc 79/07/06 2pp

7907190561 Final deficiency rept re socket welded fittings in Unit 1 RCS Caused by lack of procedural controls over fabrication & installation of pipe lines Lines removed & refabricated  
COUGHLIN, J Public Service Co of Indiana, Inc 79/07/06 2pp.

U Congressional/Executive Correspondence

7907310172 Responds to 790614 ltr re const quality problems at facilities Discusses corrective steps being taken & NRC & PB of IN investigations into matter Forwards JO Keppler 790627 immediate action ltr.  
GOSBICK, L V Office of the Executive Director for Operations 79/06/29 2pp

--7907310185 Directs util to take specific steps re quality of concrete const activities at facilities, including cessation of safety-related concrete activities until cause & conditions are fully rectified  
KEPPLER, J G Office of Inspection & Enforcement 79/06/27 2pp

--7907310193 Expresses concern over potentially serious const deficiencies at facilities Requests NRC intervention to stop const & initiate thorough & comprehensive investigation  
FORD, W Senate 79/06/14 2pp

DOCKET 81N-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7907250464 FOIA request for all submitted info re const or operation of plant  
LAUDIG, B Laudig, B 79/06/22 1p

7907250484 Responds to 790622 FOIA request for all submitted info re const or operation of plant Lists relative documents on file in LPDR in Madison, IN  
FELTON, J M Division of Rules and Records 79/07/09 5pp

G. Adjudicatory correspondence

7907050559 Notifies re change of address  
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 79/05/25 2pp

7907160131 Requests summary disposition of Interveners Ecology Action of Duwae & Northern Thunder, Inc Deficiencies 7 & 20 re Perkins record Deficiencies do not raise genuine issue of matl fact Certificate of Evc encl  
BORDENICK, B M Branch 4 79/05/25 29pp

7907100559 Requests suspension & revocation of facility CP & reopening of safety hearings  
EYED, J. A Bassafras Audubon Society. 79/06/29 13pp.

H. General correspondence

7907050190 Responds to 790420 ltr questioning facility const & concerns re composition & mission of NRC  
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/30 3pp.

# DOCKETED ITEMS

--7907030193 Expresses concern re nuclear safety of proposed plants  
Suggests halting const; reassessment of NRC composition; more  
money for alternative energy research & greater citizen  
participation in nuclear decisionmaking  
WATSON, B Jefferson County, KY 79/04/20 2pp

## G Inspection reports, IE Bulletins & correspondence

7907180456 Forwards IE Insp Repts 50-546/79-03 & 50-547/79-03 on  
790403-06; notice of violation & notice of deviation  
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering  
Support Branch 79/05/04 2pp

--7907180460 Notice of violation from insp on 790403-06  
\* Region 3, Chicago, Office of the Director 79/05/03 3pp

--7907180464 Notice of deviation from insp on 790403-06  
\* Region 3, Chicago, Office of the Director 79/05/03 1p

--7907180474 IE Insp Rept 50-546/79-03 & 50-547/79-03 on 790403-06  
Noncompliance noted failure to properly control deviations  
to design documents; failure to adequately insp concrete  
work; failure to properly train post-tensioning GC personnel  
SCHMEIBINZ, E R Region 3, Chicago, Office of the Director  
79/05/03 18pp

7907110267 Ack unofficial granting of extension requested in 790503  
ltr Response to IE Bulletin 79-03 is now due 120 days after  
790511  
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/24 1p

7907100111 Responds to IE Bulletins 78-12, 12A & 12B Assumes response  
date will be moved to 790913 in order to provide pressure  
vessel vendor time to submit generic rept  
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/25 1p

7907100214 Responds to IE Bulletin 79-04 No 1500 psi pressure-rated  
Velan swing check valves installed or scheduled to be  
installed  
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/25 1p

7907240169 Forwards IE Insp Repts 50-546/79-03 & 50-547/79-03 on  
790515 No noncompliance noted  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/30  
2pp

--7907240172 IE Insp Repts 50-546/79-03 & 50-547/79-03 on 790515 No  
noncompliance noted Major areas inspected concrete work  
activities; const deficiency reporting requirements &  
document control  
HAWKINS, F C, HAYES, D W., FIORELLI, G Region 3, Chicago,  
Reactor Construction & Engineering Support Branch 79/05/29 5pp

7907200330 Forwards IE Bulletin 79-12, "Short Period Scrams at BWR  
Facilities " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/31  
1p.

7907190288 Forwards suppl IE Bulletin 79-01A, "Environ Qualificat. on of  
Class IE Equipment (Deficiencies in Environ Qualification of  
ASCO Solenoid Valves) " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/06  
1p

7907240438 Forwards IE Info Notice 79-15, "Deficient Procedures " No  
action required  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/06/07  
1p.

7907060007 Advises that IE Info Notice 79-15, "Deficient Procedures"  
forwarded to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/08  
2pp.

7907240233 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/11  
1p.

7907300553 Responds to IE Bulletin 79-09 OE AK-2-50 circuit breakers  
are planned for use in safety-related sys as battery  
disconnect circuit breakers Potential failure mode in IE  
Bulletin 79-09 does not apply to planned use  
SHIELDS, B. W. Public Service Co of Indiana, Inc 79/06/15 1p

7907020436 Forwards IE Info Notice 79-17, "Source Holder Assembly  
Damage from Misfit Between Assembly & Reactor Upper Grid  
Plate "  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/20  
1p.

7907120252 Forwards IE Bulletin 79-02; Revision 1, "Pipe Support Base  
Plate Designs Using Concrete Expansion Anchor Bolts " Action  
required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/21  
1p

7907130147 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

7907060319 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907050480 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27  
1p

7907100525 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130289 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys " Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p

7907310345 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies "  
Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310416 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260211 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907260413 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant  
Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

## S Reportable occurrences, LERs & related correspondence

7907100368 Notifies of RO on 790601 possible damage to Unit 1  
containment liner Visual insp indicates deformation in liner  
at bottom of pour Dimension measurements taken by Chicago  
Bridge & Iron  
COUGHLIN, J Public Service Co of Indiana, Inc 79/06/29 1p

7907120618 Interim deficiency rept re concrete void discovered on  
790604 in auxiliary bldg slab. New repair procedures have  
been approved but not yet performed Final rept will follow  
COUGHLIN, J Public Service Co of Indiana, Inc. 79/07/03. 2pp

7907120633 Updates status of 790608 RO 1 & RO 2 in response to NRC  
790626 ltr. RO 2 is voided. Further infor re RO 1 welding  
qualifications to be sent 790801.  
COUGHLIN, J Public Service Co of Indiana, Inc 79/07/06 2pp

7907190561 Final deficiency rept re socket welded fittings in Unit 1  
RCS Caused by lack of procedural controls over fabrication  
& installation of pipe lines. Lines removed & refabricated  
COUGHLIN, J. Public Service Co of Indiana, Inc 79/07/06 2pp

## U Congressional/Executive Correspondence

7907310172 Responds to 790614 ltr re const quality problems at  
facilities Discusses corrective steps being taken & NRC &  
PS of IN investigations into matter Forwards JO Keppler  
790627 Immediate action ltr  
GOSBICK, L V Office of the Executive Director for Operations,  
79/06/29 2pp

--7907310185 Directs util to take specific steps re quality of concrete  
const activities at facilities, including cessation of  
safety-related concrete activities until cause & conditions  
are fully rectified  
KEPPLER, J. G Office of Inspection & Enforcement, 79/06/27 2pp.

## DOCKETED ITEMS

--7907310193 Expresses concern over potentially serious const deficiencies at Facilities Requests NRC intervention to stop const & initiate thorough & comprehensive investigation  
FORD, H Senate 79/06/14 2pp

## DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

## A Adjudicatory correspondence

7907030203 Responds to PASNY cross motion re NY Dept Public Svc 790405 dismissal of Greene County Article VIII application  
FLYNN, M New York, State of 79/05/02 4pp

7907060459 Responds to util 790507 request for suspension of proceeding until 800501 No objection is presented New application must undergo de novo review & safety matters must be updated  
LEWIS, B H, MOORE, J E Branch 2 79/05/29 2pp

--7907060466 Notifies that ASLB must be informed of necessity of reopening review of several safety matters if Greene County, NY hearings are suspended until 800501 Certificate of Svc encl  
VASSALLO, D B Assistant Director for Light Water Reactors 79/05/10 4pp

7907160116 Forwards Greene County, NY, 790605 joinder to appeal termination of proceeding by presiding examiner.  
BUTZEL, A K Butzel & Kass 79/06/05 1p

-7907160125 Green County, NY joins & supports NY Dept of Public Svc 790514 appeal of ruling of Presiding Examiner Cohen Ruling denied motion to dismiss application to terminate proceeding Requests dismissal of util license application  
BUTZEL, A K Butzel & Kass 79/06/05 3pp

## DOCKET STN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1

## A Adjudicatory correspondence

07160101 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of mat'l fact Certificate of Svc encl  
HORDENICK, B M Branch 4 79/05/25 2pp

## Inspection reports, IE Bulletins &amp; correspondence

79020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at MH-Buppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 3pp

79100335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head insulation Support Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 3pp

79030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Jet Assemblies." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 3pp

79100207 Forwards IE Circular 79-08, "Attempted Extortion - Low enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 2pp

7910108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device Circuit Breakers for Engineered Safety Sys " Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/20 3pp

240132 Forwards IE Insp Repts 50-553/79-04 & 50-554/79-04 on 0501-03 No noncompliance noted  
THRELAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 79/05/25 2pp

240140 IE Insp Repts 50-553/79-04 & 50-554/79-04 on 790501-03. No compliance noted Major areas inspected, mgt controls, solid waste, erosion, water quality, aquatic impacts & dust control.  
MINOGHAN, A L Region 2, Atlanta, Office of the Director  
HAM, J. W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/24 4pp

790105 Forwards IE Info Notice 79-13, "Indication of Low Water level in Oyster Creek Reactor." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/29 3pp

7907260133 Forwards IE Insp Repts 50-553/79-06 & 50-554/79-06 on 790508-11 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/30 2pp

--7907260142 IE Insp Repts 50-553/79-06 & 50-554/79-06 on 790508-11 No noncompliance noted Major areas inspected licensee action on previous insp findings, const engineering personnel changes & handling of licensee-identified items  
WRIGHT, R W, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/30 6pp

7907190207 Responds to IE Bulletin 79-04 Specified Valves swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
GILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrams at BHR Facilities " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NBSS sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Bolonoid Valves) " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage From Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 3pp

## DOCKET STN-90-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

## G Adjudicatory correspondence

7907160131 Requests summary disposition of Intervenor's Ecology Action of Oswego & Northern Thunder, Inc. Deficiencies 9 & 20 re Perkins record Deficiencies do not raise genuine issue of mat'l fact Certificate of Svc encl  
BORDENICK, B M Branch 4 79/05/28 29pp

## G Inspection reports, IE Bulletins &amp; correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl 1"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/21 3pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/22 3pp

7907240132 Forwards IE Insp Repts 50-553/79-04 & 50-554/79-04 on 790501-03 No noncompliance noted  
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/25 2pp

--7907240148 IE Insp Repts 50-553/79-04 & 50-554/79-04 on 790501-03 No noncompliance noted Major areas inspected: mgt controls, solid waste, erosion, water quality, aquatic impacts & dust control  
CUNNINGHAM, A L Region 2, Atlanta, Office of the Director  
HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/24 4pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/29 3pp

7907260133 Forwards IE Insp Repts 50-553/79-06 & 50-554/79-06 on 790508-11 No noncompliance noted  
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/30 2pp

--7907260142 IE Insp Repts 50-553/79-06 & 50-554/79-06 on 790508-11, No noncompliance noted Major areas inspected: licensee action on previous insp findings, const engineering personnel changes & handling of licensee-identified items  
WRIGHT, R W, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/30 6pp

7907190207 Responds to IE Bulletin 79-04 Specified Valves swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
OTLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Screens at BWR Facilities" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NSSB sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
OTLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/07 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies" Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/13 3pp

## DOCKET STN-90-556 BLACK FOX STATION, UNIT 1

## A Application/construction stage documents &amp; correspondence

7907050053 Responds to FOIA request for disclosure of Reqd rept Forwards documents supporting decision to withhold rept. Rept withheld (ref FOIA Exemption 4)  
WOLFE, B J Atomic Safety and Licensing Board Panel 79/06/18 2pp

--7907050057 Certification to NRC re return of Reqd rept to OE  
WOLFE, B J Atomic Safety and Licensing Board Panel 79/05/30 8pp

7907020199 Forwards two oversized engineering drawings showing coordinates & elevations of water transport sys.  
CONRAD, V L Public Service Co of Oklahoma 79/06/22 2pp

7907060890 Notification of 790720 meeting w/PSC of OK in Bethesda, Md to discuss priorities & facility schedule.  
THOMAS, C O Light Water Reactors Branch 1 79/07/06 2pp

## G Adjudicatory correspondence

7907110087 Errata to Citizens for Safe Energy proposed findings of fact & conclusions of law  
FARRIS, J R, Feldman & Feldman 79/05/09 5pp

7907060506 Forwards & adopts contentions of Concerned Citizens for Safe Energy Contentions supplement petition to intervene  
BROWN, P D, Mid-Hudson Nuclear Opponents, Inc. 79/05/10 1p

--7907060509 Contentions of Concerned Citizens for Safe Energy, Inc & Town of Stuyvesant, NY, in response to NRC 790205 notice Submits contentions re choice of Stuyvesant as alternate site & cost & benefit of facility. Reserves right to amend contentions  
KAPIN, R J, Miller, Mannix, Lemery & Kabin 79/05/10 7pp

## DOCKETED ITEMS

--7907060510 Notifies ASLB of participation of County of Columbia, NY & Town of Stuyvesant, NY, per 10CFR2 715(c) Contentions of Concerned Citizens for Safe Energy, Inc will be adopted if necessary  
KAFIN, R J Miller, Mannix, Lemery & Kafin 79/05/10 2pp

7907090453 Submits results of analysis contained in VL Conrad ltr re whether previously estimated const costs & scheduled commercial operation dates could be maintained  
MURPHY, P M Isham, Lincoln & Beale 79/05/11 12pp

7907060515 Answer by util to NRC 790509 finding of facts re ECCS Requests that ASLB treat findings as final & make record ready for decisions NRC is not following Rules of Practice Certificate of Svc encl  
GALLQ, J Isham, Lincoln & Beale 79/05/17 8pp

7907060367 Request by util re intervenors 790427 motion to reopen record Seeks denial of request re financial qualification, TMI, Class 9 accidents & emergency planning & post-accident monitoring Certificate of Svc encl  
GALLQ, J, QIBBS, M E Isham, Lincoln & Beale 79/05/18 21pp

7907060379 Answer to State of OK 790419 motion & intervenors 790427 motion to stay initial decision & reopen record Seeks denial w/prejudice re financial matter, denial re Class 9 assertions & deferral re TMI Certificate of Svc encl  
DAVIS, L D Branch 4 79/05/18 12pp

7907160120 Requests that ASLB allow PS of OK to responds to NRC 790518 answer to State of OK motion for indefinite stay Parties request various forms of relief Parties have no objection to motion Certificate of Svc encl  
QIBBS, M E Isham, Lincoln & Beale 79/05/21 3pp

7907180593 Certificate of Svc re util 790521 motion to file reply  
QIBBS, M E Isham, Lincoln & Beale 79/05/21 2pp

7907120024 Protests against nuclear power because of health danger from radwaste or accidents Plant is being built against wishes of Oklahomans  
HUFFERD, C Affiliation Unknown 79/05/24 1p

7907020010 NRC response to ASLB 790522 order questioning propriety of NRC 790509 ltr to ASLB & findings of fact on ECCS matters Certificate of Svc encl  
DAVIS, L D Branch 4 79/05/29 5pp

7907060503 Seeks denial of NRC 790518 request for deferral of decision on question of opening record If any pending motion is decided adversely to util, ruling should be referred to ASLB Certificate of Svc encl  
GALLQ, J, QIBBS, M E Isham, Lincoln & Beale 79/05/31 16pp

907060495 Defers ruling on undecided portions of motion to stay or reopen, pending receipt of NRC rept on TMI Initial decision will be written on existing record Resolution of CP application awaits evaluation of NRC recommendations  
SHON, P J, WOLFE, B J Atomic Safety and Licensing Board Panel 79/06/13 4pp

707130425 Forwards ME Fate 790615 ltr, responding to ACRS suggestion for assessment of TMI incident in connection w/PS of OK CP application Lessons re TMI are pertinent to past CP & PSAR status,  
GALLQ, J Isham, Lincoln & Beale 79/06/22 2pp

#### General correspondence

07020493 Ack receipt of 790313 ltr forwarding geologic info for area surrounding proposed site Info forwarded to ASLB  
DAVIS, L D Branch 4 79/05/02 1p.

7907020497 Objects to proposed site since seismicity was insufficiently considered  
WEBSTER, A Affiliation Unknown, 78/06/26 7pp

7907020502 Forwards objections to proposed project  
WEBSTER, A Affiliation Unknown 79/03/15 11pp

#### Limited work authorization & related correspondence

17170193 Requests authorization for certain const activities not usually permitted under LWA in order to take up slack caused by licensing delay after TMI-2 accident Forwards list of requested const activities  
VAND, T. N. Public Service Co of Oklahoma 79/07/10. 4pp

#### Q Inspection reports, IE Bulletins & correspondence

7907050357 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys." No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907180269 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/27 1p

7907200274 Discusses two items of concern in connection w/780925 & 26 IE insp of station environ impact control procedures Describes method of compliance re hydrological monitoring program & transmission of ecological review  
CONRAD, V L Public Service Co of Oklahoma 79/07/11 16pp

#### U Congressional/Executive Correspondence

7907050534 Requests expeditious & thorough proceeding re stay of CP JONES, J R House of Rep, 79/05/17 1p

#### DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

#### A Application/construction stage documents & correspondence

7907050053 Responds to FOIA request for disclosure of Reed rept Forwards documents supporting decision to withhold rept Rept withheld (ref FOIA Exemption 4)  
WOLFE, B J Atomic Safety and Licensing Board Panel 79/06/18 2pp

--7907050057 Certification to NRC re return of Reed rept to GE  
WOLFE, B J Atomic Safety and Licensing Board Panel 79/05/30 8pp

7907020199 Forwards two oversized engineering drawings showing coordinates & elevations of water transport sys  
CONRAD, V L Public Service Co of Oklahoma 79/06/22 2pp

7907260890 Notification of 790720 meeting w/PS of OK in Bethesda, Md to discuss priorities & facility schedule  
THOMAS, C O Light Water Reactors Branch 1 79/07/06 2pp

#### G Adjudicatory correspondence

7907110089 Errata to Citizens for Safe Energy proposed findings of fact & conclusions of law  
FARRIS, J R Feldman & Feldman 79/05/09 5pp

7907060506 Forwards & adopts contentions of Concerned Citizens for Safe Energy Contentions supplement petition to intervene  
BROWN, P D Mid-Hudson Nuclear Opponents, Inc 79/05/10 1p

--7907060509 Contentions of Concerned Citizens for Safe Energy, Inc & Town of Stuyvesant, NY, in response to NRC 790208 notice Submits contentions re choice of Stuyvesant as alternate site & cost & benefit of facility. Reserves right to amend contentions  
KAFIN, R J Miller, Mannix, Lemery & Kafin 79/05/10 7pp.

--7907060510 Notifies ASLB of participation of County of Columbia, NY & Town of Stuyvesant, NY, per 10CFR2 715(c) Contentions of Concerned Citizens for Safe Energy, Inc will be adopted if necessary  
KAFIN, R J Miller, Mannix, Lemery & Kafin 79/05/10 2pp

7907090453 Submits results of analysis contained in VL Conrad ltr re whether previously estimated const costs & scheduled commercial operation dates could be maintained  
MURPHY, P M Isham, Lincoln & Beale 79/05/11 12pp

7907060515 Answer by util to NRC 790509 finding of facts re ECCS Requests that ASLB treat findings as final & make record ready for decisions NRC is not following Rules of Practice. Certificate of Svc encl.  
GALLQ, J Isham, Lincoln & Beale. 79/05/17 8pp

7907060367 Request by util re intervenors 790427 motion to reopen record Seeks denial of request re financial qualification, TMI, Class 9 accidents & emergency planning & post-accident monitoring. Certificate of Svc encl  
GALLQ, J, QIBBS, M E Isham, Lincoln & Beale 79/05/18 21pp

7907060379 Answer to State of OK 790419 motion & intervenors 790427 motion to stay initial decision & reopen record Seeks denial w/prejudice re financial matter, denial re Class 9 assertions & deferral re TMI Certificate of Svc encl  
DAVIS, L D Branch 4. 79/05/18 12pp

# DOCKETED ITEMS

295

7907160120 Requests that ASLB allow PS of OK to responds to NRC 790518 answer to State of OK motion for indefinite stay Parties request various forms of relief Parties have no objection to motion Certificate of Svc encl  
GIBBS,M E Isham, Lincoln & Beale 79/05/21 3pp

7907180595 Certificate of Svc re util 790521 motion to file reply  
GIBBS,M E Isham, Lincoln & Beale 79/05/21 2pp

7907120024 Protests against nuclear power because of health danger from radwaste or accidents Plant is being built against wishes of Oklahomans  
HUFFERD,C Affiliation Unknown 79/05/24 1p

7907020010 NRC response to ASLB 790522 order questioning propriety of NRC 790509 ltr to ASLB & findings of fact on ECCB matters Certificate of Svc encl  
DAVIS,L D Branch 4 79/05/29 5pp

7907060503 Seeks denial of NRC 790518 request for deferral of decision on question of opening record If any pending motion is decided adversely to util,ruling should be referred to ASLB Certificate of Svc encl  
GALLO,J , GIBBS,M E Isham, Lincoln & Beale 79/05/31 16pp

7907060495 Defers ruling on undecided portions of motion to stay or reopen,pending receipt of NRC rept on TMI Initial decision will be written on existing record Resolution of CP application awaits evaluation of NRC recommendations  
SHON,F J , WOLFE,S J Atomic Safety and Licensing Board Panel 79/06/13 4pp

7907130425 Forwards ME Fate 790615 ltr,responding to ACRS suggestion for assessment of TMI incident in connection w/PS of OK CP application Lessons re TMI are pertinent to past CP & FSAR status  
GALLO,J Isham, Lincoln & Beale 79/06/22 2pp

## H General correspondence

7907020493 Ack receipt of 790313 ltr forwarding geologic info for area surrounding proposed site info forwarded to ASLB  
DAVIS,L D Branch 4 79/05/02 1p

--7907020497 Objects to proposed site since seismicity was insufficiently considered  
WEBSTER,A Affiliation Unknown 78/06/26 7pp

--7907020502 Forwards objections to proposed project  
WEBSTER,A Affiliation Unknown 79/03/13. 11pp

## L Limited work authorization & related correspondence

7907170193 Requests authorization for certain const activities not usually permitted under LWA,in order to take up slack caused by licensing delay after TMI-2 accident Forwards list of requested const activities  
EWING,T N. Public Service Co of Oklahoma 79/07/10 4pp

## G. Inspection reports, IE Bulletins & correspondence

7907050957 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Bys " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director 79/06/11 1p

7907180269 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
SEYFRIT,K V Region 4, Dallas, Office of the Director. 79/06/27 1p

7907200274 Discusses two items of concern in connection w/780925 & 26 IE insp of station environ impact control procedures. Describes method of compliance re hydrological monitoring program & transmission of ecological review  
CONRAD,V L Public Service Co of Oklahoma 79/07/11 16pp.

## U. Congressional/Executive Correspondence

7907050534 Requests expeditious & thorough proceeding re stay of CP.  
JONEB,J R House of Rep. 79/05/17 1p

## DOCKET 50-564 NUCLEAR FUELS RECOVERY & RECYCLE CENTER

### J Insurance & indemnity information

7907180590 Forwards Endorsements 15,16 & 17 to MAELU Policy MF-94 & Endorsements 40,41 & 42 to NELIA Policy NF-193 W/draft  
790710 forwarding ltr  
NILSDN,R Exxon Nuclear Co , Inc (subs of Exxon Corp ) 79/07/13 7pp

## DOCKET BTN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

### A Application/construction stage documents & correspondence

7907030246 Forwards 790524 memo summarizing 790511 geology field trip  
ROOD,M Light Water Reactors Branch 2 79/05/29 2pp

--7907030253 Summary of 790511 site visit & meeting w/MS & AL Geological Surveys,Army Corp of Engineers & TVA re foundation conditions & continuity of geologic strata exposed in excavations  
LEFEVRE,H E Geosciences Branch 79/05/24. 6pp

### Q Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl "  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/04/21. 3pp

790710335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/05/07 3pp.

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/05/10 3pp

7907100207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/05/18 2pp

790711010B Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Bys " Action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/05/22 3pp

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " No action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Velan swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
GILLELAND,J E. Tennessee Valley Authority. 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Screams at BWR Facilities " No action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/05/31 2pp.

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Investigation of non-NBBS sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
GILLELAND,J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCO Bolenoid Valves)." Action required.  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/06/06. 3pp

7907060044 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director. 79/06/07. 2pp

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Bys." No action required  
O'REILLY,J P. Region 2, Atlanta, Office of the Director 79/06/11. 1p

## DOCKETED ITEMS

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp.

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 3pp

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/07/13 3pp

#### DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

##### A Application/construction stage documents & correspondence

7907030246 Forwards 790524 memo summarizing 790511 geology field trip  
RODD, H Light Water Reactors Branch 2 79/05/29 2pp

--7907030253 Summary of 790511 site visit & meeting w/MS & AL Geological Surveys, Army Corp of Engineers & TVA re foundation conditions & continuity of geologic strata exposed in excavations  
LEFEVRE, H E Geosciences Branch, 79/05/24 6pp

##### G Inspection reports, IE Bulletins & correspondence

7907020343 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/04/21 3pp

7907110335 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/07 3pp

7907030140 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/05/10 3pp

790710207 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/05/18 2pp.

7907110108 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/22 3pp.

7907030105 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/05/29 3pp

7907190207 Responds to IE Bulletin 79-04 Specified Velan swing check valves have not been installed or scheduled for installation in any Seismic Category I piping sys  
OILLELAND, J E Tennessee Valley Authority 79/05/31 3pp

7907200210 Forwards IE Bulletin 79-12, "Short Period Scrums at DWR Facilities." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/31 2pp

7907310170 Forwards response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping investigation of non-NSSB sys revealed no dynamic seismic piping analysis was performed utilizing algebraic summation of components  
OILLELAND, J E Tennessee Valley Authority 79/05/31 11pp

7907190191 Forwards suppl IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ABCD Bolenoid Valves)." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/06 3pp

7907060064 Forwards IE Info Notice 79-15, "Deficient Procedures." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/07 2pp

7907020057 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys."  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/11 1p

7907020220 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys."  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/11 1p

7907020393 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate."  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/20 1p

7907120104 Forwards IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/21 1p

7907310029 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys Piping." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director.  
79/06/25 3pp

7907180321 Forwards IE Circular 79-11, "Design/Const Interface Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/27 2pp

7907180443 Forwards IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/28 3pp

7907310263 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/02 3pp.

7907310387 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/11 2pp

7907240281 Forwards IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/13 3pp.

#### DOCKET STN-50-568 NEP NUCLEAR, UNIT 1

##### A Application/construction stage documents & correspondence

7907020495 Responds to 790320 ltr forwarding request for site studies & proposals Moonstone Beach not regarded as probable nuclear site.  
BALLARD, R L Environmental Projects Branch 1. 79/05/25 1p



7907120565 "Decision Paper re Disposal of Naval Auxiliary Landing Field at Charlestown, RI "  
GOULDING, P E General Services Administration 79/06/20 26pp

7907100380 Forwards corrected version of Section 4 to "Biological Modeling of Effect of Entrainment on Four Selected Fish Species at New England Power 1 & 2 Site, Charlestown, RI "  
W/o encl  
HARRINGTON, J New England Power Co 79/07/02 22pp

D NRC Draft/Final Environmental Statements, suppl's & correspondence

7907130086 Forwards FR notice of availability of DES W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 1p

7907250193 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250198 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250199 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250201 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250202 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250203 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250208 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250207 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp.

7907250208 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250210 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp.

7907120563 Forwards "Decision Paper re Disposed of Naval Auxiliary Landing Field at Charlestown, RI "  
BRETTE, L F General Services Administration 79/06/27 1p

7907100645 Comments on DES. More detailed analysis of transmission facilities & corridors should have been conducted. Analysis re slurry walls seems contradictory. Further analysis of sediment grain profile within trench site must be included.  
CROWLEY, C T Agriculture, Dept. of 79/07/03 2pp

7907250042 Util response to OBA 790620 decision re disposition of site Requests that ASLB review decision & continue proceedings generally. Certificate of BVC encl  
RITTSHER, J A Rittsher, J A DIGNAN, T O Dignan, T O GAD, R K Gad, R K 79/06/29 4pp

7907190542 Forwards request from Concerned Citizens of RI, Point Judith Fishermen's Cooperative & TL Arnold Trust for show cause order re dismissal of CPs  
JORDAN, W B Sheldon, Harmon & Roisman 79/07/13 1p

---7907190547 Request on behalf of Concerned Citizens of RI, Point Judith Fishermen's Cooperative & TL Arnold Trust for show cause order re dismissal of CPs  
JORDAN, W B Sheldon, Harmon & Roisman 79/07/13 5pp

H General correspondence

7907180870 Comments on AEC rept: "Site Visit to Naval Facility," dtd 740103. Town officials had no basis for giving assurances regarding support for nuclear plant const within township  
SEELY, B Concerned Citizens of Rhode Island 79/05/25 2pp

G Inspection reports, IE Bulletins & correspondence

7907020059 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys "  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/11 1p

7907100412 Forwards IE Circular 79-11, "Design/Const Interface Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

DOCKET BTN-50-569 NEP NUCLEAR, UNIT 2

A Application/construction stage documents & correspondence

7907020495 Responds to 790320 ltr forwarding request for site studies & proposals Moonstone Beach not regarded as probable nuclear site  
BALLARD, R L Environmental Projects Branch 1 79/05/25 1p

7907120565 "Decision Paper re Disposal of Naval Auxiliary Landing Field at Charlestown, RI "  
GOULDING, P E General Services Administration 79/06/20 26pp

7907100380 Forwards corrected version of Section 4 to "Biological Modeling of Effect of Entrainment on Four Selected Fish Species at New England Power 1 & 2 Site, Charlestown, RI "  
W/o encl  
HARRINGTON, J New England Power Co 79/07/02 22pp

D NRC Draft/Final Environmental Statements, suppl's & correspondence

7907130086 Forwards FR notice of availability of DES W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 1p.

7907250193 Forwards DES for comment Requests response by 790807 W/o encl.  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250198 Forwards DES for comment Requests response by 790807 W/o encl.  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250199 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250201 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250202 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250203 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250205 Forwards DES for comment Requests response by 790807 W/o encl.  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250207 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1. 79/05/31 2pp.

7907250208 Forwards DES for comment Requests response by 790807 W/o encl.  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907250210 Forwards DES for comment Requests response by 790807 W/o encl  
BALLARD, R L Environmental Projects Branch 1 79/05/31 2pp

7907120563 Forwards "Decision Paper re Disposed of Naval Auxiliary Landing Field at Charlestown, RI."  
BRETTE, L F General Services Administration. 79/06/27 1p

7907100645 Comments on DES. More detailed analysis of transmission facilities & corridors should have been conducted. Analysis re slurry walls seems contradictory. Further analysis of sediment grain profile within trench site must be included.  
CROWLEY, C T Agriculture, Dept. of 79/07/03 2pp.

## DOCKETED ITEMS

G Adjudicatory correspondence

7907230042 Util response to GSA 790620 decision re disposition of site  
Requests that ASLB review decision & continue proceedings  
generally Certificate of Svc encl  
RITISHER, J A Ritsher, J A DIGNAN, T G Dignan, T G QAD, R K  
Qad, R K 79/06/29 App

7907190542 Forwards request from Concerned Citizens of RI, Point Judith  
Fishermen's Cooperative & TL Arnold Trust for show cause  
order re dismissal of CPs  
JORDAN, W S Sheldon, Harmon & Roisman 79/07/13 1p

--7907190547 Request on behalf of Concerned Citizens of RI, Point Judith  
Fishermen's Cooperative & TL Arnold Trust for show cause  
order re dismissal of CPs  
JORDAN, W S Sheldon, Harmon & Roisman 79/07/13 5pp

H General correspondence

7907180870 Comments on AEC rept, "Site Visit to Naval Facility,"  
dtd 740103 Town officials had no basis for giving  
assurances regarding support for nuclear plant const within  
township  
SEELY, S Concerned Citizens of Rhode Island 79/05/25 2pp

G Inspection reports, IE Bulletins & correspondence

7907020059 Forwards IE Info Notice 79-14, "Safety Classification of  
Electrical Cable Support Sys"  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/11 1p

7907100412 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director  
79/06/27 1p

DOCKET STN-50-574 BAOAC NUCLEAR POWER PROJECTA Application/construction stage documents & correspondence

7907310573 FOIA request for all documents re facility & applications  
XR-120, XCDM-13 & XSNM-1471  
ASHER, T R ; BOGIN, M B Asher, T R PC 79/05/14 5pp

7907180901 Submits addl info to support position of 790427 ltr re  
export of equipment to Philippines  
RODI, J P Westinghouse Electric Corp 79/05/18 1p

7907310565 Responds to FOIA request for documents re facility &  
applications XR-120, XCDM-13 & XSNM-1471  
FELTON, J M Division of Rules and Records 79/07/06 3pp

7907170199 Confirms 790702 telcon re ASME code classifications of spent  
resin storage tank, boron injection tank, floor drain tank,  
waste holder tank & laundry & hot water tanks  
BRADY, W J Westinghouse Electric Corp 79/07/10 1p

G Adjudicatory correspondence

7907100709 Opposes plant proposed by Westinghouse in Philippines  
MCENRY, M Affiliation Unknown 79/05/17 1p

H General correspondence

7907050343 Expresses concern re nuclear dangers Opposes Westinghouse  
export of reactor to Philippines  
DUNKLEY, K Affiliation Unknown 79/05/24 1p

DOCKET STN-50-580 ERIE NUCLEAR PLANT, UNIT 1G Adjudicatory correspondence

7907060383 Requests return of transcript of 770728 prehearing  
conference  
BARTH, C A Branch 3 79/06/05 1p

G Inspection reports, IE Bulletins & correspondence

7907130172 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

7907060002 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907050463 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27  
1p

7907100522 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p

7907130286 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys." Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p

7907310344 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies"  
Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p

7907310415 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p

7907260206 Notifies that written responses to IE Bulletin 79-15, Suppl  
1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

7907260410 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant  
Borated Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18  
1p

DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2G Adjudicatory correspondence

7907060383 Requests return of transcript of 770728 prehearing  
conference  
BARTH, C A Branch 3 79/06/05 1p

G Inspection reports, IE Bulletins & correspondence

7907130172 Forwards IE Bulletin 79-13, "Cracking in Feedwater Sys  
Piping." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/25  
1p

7907060002 Forwards IE Circular 79-10, "Pipefittings Mfg from  
Unacceptable Matl " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/26  
1p

7907050463 Forwards IE Circular 79-11, "Design/Const Interface  
Problem " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27  
1p

7907100522 Forwards IE Circular 79-12, "Potential Diesel Generator  
Turbocharger Problem " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/28  
1p.

7907130286 Forwards IE Bulletin 79-14, "Seismic Analysis for As-Built  
Safety-Related Piping Sys." Action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/02  
1p.

7907310344 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies."  
Action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/11  
1p.

7907310415 Forwards IE Circular 79-13, "Replacement of Diesel Fire  
Pump Starting Contactors." No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/13  
1p.

7907260206 Notifies that written responses to IE Bulletin 79-15, Suppl 1, should be directed to IE Div of Reactor Const Insp  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

7907260410 Forwards IE Info Notice 79-19, "Pipe Cracks in Stagnant Buried Water Sys at PWR Plants " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/18 1p

#### DOCKET 50-582 SUNDEBERT, UNIT 1

##### G Adjudicatory correspondence

7907060522 Notifies of issuance of NUREG-0568, "Title List of Publicly Available Documents on TMI, Docket 50-380 " Suppl will be published All new entries will be in NUREG-0540, Title List Journal, issued monthly  
BORDENICK, B M Branch 4 79/06/07 3pp

#### DOCKET 50-583 SUNDEBERT, UNIT 2

##### G Adjudicatory correspondence

7907060522 Notifies of issuance of NUREG-0568, "Title List of Publicly Available Documents on TMI, Docket 50-380 " Suppl will be published All new entries will be in NUREG-0540, Title List Journal, issued monthly  
BORDENICK, B M Branch 4 79/06/07 3pp.

#### DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

##### A Application/construction stage documents & correspondence

7907130065 Summary of 790523 meeting w/applicants in Bethesda, MD re submittal of nonproprietary financial info  
LICITRA, E A Light Water Reactors Branch 3 79/06/01 4pp

7907030240 Comments on DES re const of generating station  
KIRSHNER, D, WILLEY, W R, ROE, D. B. Environmental Defense Fund 79/06/12 19pp

7907030369 Forwards CA Energy Commission comments on DES Discusses only need & alternatives sections, since proposed plant location is outside CA  
URBAN, M. J California, State of. 79/06/26 28pp

##### B Utility Preliminary Safety Analysis Report, amends

7907130426 Forwards errata pages for List of Effective Pages, Amend 3 to PBAR for Units 4 & 5 & Amend 20 to PBAR for Units 1-3.  
VAN BRUNT, E E Arizona Public Service Co 79/06/27 40pp

##### D NRC Draft/Final Environmental Statements, suppls & correspondence

7907030370 Forwards addl comments by Applicants & consultants re DES  
VAN BRUNT, E E Arizona Public Service Co 79/06/25 3pp

7907100616 Certificate of Svc verifying that CA Energy Commission comments on NRC DES were mailed on 790628  
FRAGA, C. D California, State of. 79/06/28 2pp.

7907090326 Comments by AZ state agencies re DES, NUREG-0522 & issuance of CPs to AZ Public Svc Co  
OILBERT, R. A Division of Site Safety & Environmental Analysis. 79/06/29 13pp.

7907100633 Forwards comments on draft environ impact statement, ref concerns in emergency response operations, reactor operational experience & availability of cooling water  
FALCO, P. D Environmental Protection Agency. 79/07/03 10pp

7907130404 Comments on DES Rept does not adequately consider cumulative environ impacts, burial of radwaste, accident analysis & impacts of mitigative measures.  
MEIEROTTO, L. E Interior, Dept of. 79/07/06 5pp.

##### G Adjudicatory correspondence

7907030371 Advises of applicant opposition to L Bard 790327 request for financial assistance. Filing took place in wrong forum Request is inappropriate per 4NRC494(1976) decision.  
BISCHOFF, C. A Snell & Wilmer 79/05/14 4pp.

7907050504 Expresses desire to attend public hearing re facility Opposes further const Requests ASLB order setting date, time & place of hearing  
PEEPLES, M Affiliation Unknown 79/05/15 1p

7907060038 Response of AZ Public Svc, Southern CA Edison, El Paso Electric, San Diego Gas & Electric, NV Power, Dept of Water & Power of LA, et al, to Environ Defense Fund 790503 petition to intervene Certificate of Svc encl  
GEHR, A. C., BISCHOFF, C. A Snell & Wilmer 79/05/18 17pp.

7907020007 Arizona Public Svc first set of interrogatories & request for production of documents, directed to L Bard Certificate of Svc encl  
GEHR, A. C Snell & Wilmer 79/05/21 20pp

7907020003 Reply by State of CA & CA Public Utils Commission to AZ Public Svc 790518 response to Environ Defense Fund 790507 petition to intervene Certificate of Svc encl  
KERR, J. E California, State of 79/05/24 8pp

7907180358 Response to CA Public Utils Commission 790516 motion for extension of time to file comments to DES Extension granted until 790626, Certificate of Svc encl  
BOHINKI, B M Branch 3 79/05/25 4pp

7907030294 Opposes plant const due to increased const costs, impact on electric rates & problem of waste disposal  
MIKUS, P. J Affiliation Unknown 79/05/26 2pp

7907180119 AZ Public Svc et al, opposition to Morongo Band of Mission Indians 790511 petition to intervene IF petition is denied, petitioner limited appearance will not be opposed by applicants Certificate of Svc encl  
GEHR, A. C., BISCHOFF, C. A Snell & Wilmer 79/05/29 12pp

7907180313 Joint applicants response to CA Public Utils Commission motion for extension until 790701 to file comments on DES Date suggested is excessive Time should not be extended beyond 790531 Certificate of Svc encl  
GEHR, A. C., BISCHOFF, C. A Snell & Wilmer 79/05/31 5pp

7907190722 NRC opposition to Morongo Band of Mission Indians 790511 petition to intervene Petitioner demonstrated standing but failed to justify untimely filing & to base contention on reasonable specificity Certificate of Svc encl  
CUTCHIN, J M Branch 3 79/05/31 11pp.

7907180297 Motion to file reply to NRC & joint applicants 790518 responses to Environ Defense Fund petition to intervene Responses contain factual inaccuracies which must be corrected, Certificate of Svc encl.  
MASTBAUM, D., ROE, D. B Environmental Defense Fund. 79/06/01 4pp

7907180078 AZ Public Svc et al, opposition to CA Public Utils Commission 790524 reply to applicants response to Environ Defense Fund petition to intervene Urges rejection of reply for being defective on merits Certificate of Svc encl  
GEHR, A. C., BISCHOFF, C. A Snell & Wilmer 79/06/08 12pp.

7907130526 Response in opposition to Environ Defense Fund 790601 motion to file reply to joint applicants & NRC 790518 responses to Environ Defense Fund 790503 petition to intervene Granting of motion would be counterproductive W/Certificate of Svc  
BOHINKI, B M. Branch 3 79/06/11 5pp

7907020006 Arizona Public Svc answer in opposition to intervenor L Bard motion for extension until 790701 to answer first discovery requests Certificate of Svc encl  
GEHR, A. C., BISCHOFF, C. A Snell & Wilmer 79/06/15 6pp

7907190706 Joint applicants AZ Public Svc, et al answer to intervenor L Bard motion seeking extension until 790701 for answering first round discovery request Certificate of Svc encl.  
GEHR, A. C., BISCHOFF, C. A Snell & Wilmer 79/06/15 6pp

7907190453 Joint applicants AZ Public Svc, et al response to Environ Defense Fund 790601 petition to file reply in answer to NRC & joint applicants responses to 790503 petition to intervene Certificate of Svc encl  
GEHR, A. C., BISCHOFF, C. A Snell & Wilmer 79/06/18 4pp

7907190379 People of State of CA & Public Utils Commission of State of CA statement of issues per 790306 special prehearing conference order Certificate of Svc encl  
KERR, J. E., BIMPSON, J. C., MACKENZIE, V. V California, State of 79/06/20 36pp.

- 7907190479 CA Energy Resources Conservation & Development Commission Statement of issues, per ASLB 790306 order, indicating that Commission is entitled to participate in hearing as interested state Certificate of Bvc encl  
URBAN, M J, GRUENEICH, D M California, State of 79/06/20 10pp
- 7907090328 Comments by intervenor L Bard re DES Formal presentation of comments will be submitted at later date DES has major deficiencies which need attention before CP can be granted  
BARD, L Affiliation Unknown 79/06/26 13pp
- 7907090301 Errata to comments by State of CA & CA Public Util Commission of re adequacy of NRC DES  
WEISSMAN, B A, KERR, J E, SIMPSON, J C California, State of 79/06/29 2pp
- 7907260580 Forwards CA Public Util Commission decision on Southern CA Edison Co proposed 300 kV transmission line, Application 57251  
STEGER, D B California, State of 79/07/23 1p
- 7907260583 CA Public Util Commission decision on Southern CA Edison Co proposed 300 kV transmission line, Application 57251.  
BRYSO, J E, STURGEON, V L, GRAVELLE, R D California, State of 79/07/17 41pp
- DOCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 7907130065 Summary of 790523 meeting w/applicants in Bethesda, MD re submittal of nonproprietary financial info  
LICITRA, E A Light Water Reactors Branch 3 79/06/01 App
- 7907030240 Comments on DES re const of generating station  
KIRSHNER, D, WILLEY, W R, ROE, D B Environmental Defense Fund 79/06/12 19pp
- 7907030269 Forwards CA Energy Commission comments on DES  
Discusses only need & alternatives sections, since proposed plant location is outside CA  
URBAN, M J California, State of 79/06/26 28pp
- B Utility Preliminary Safety Analysis Report, addends
- 7907130426 Forwards errata pages for List of Effective Pages, Amend 3 to PSAR for Units 4 & 5 & Amend 20 to PSAR for Units 1-3  
VAN BRUNT, E E Arizona Public Service Co 79/06/27 40pp
- D NRC Draft/Final Environmental Statements, supp's & correspondence
- 7907030370 Forwards add'l comments by applicants & consultants re DES  
VAN BRUNT, E E Arizona Public Service Co 79/06/25 3pp
- 7907100616 Certificate of Bvc verifying that CA Energy Commission comments on NRC DES were mailed on 790628  
FRAGA, C D California, State of 79/06/28 2pp
- 7907090326 Comments by AZ state agencies re DES, NUREG-0522 & issuance of CPs to AZ Public Bvc Co  
GILBERT, R A Division of Site Safety & Environmental Analysis 79/06/29 13pp
- 7907100633 Forwards comments on draft environ impact statement, re concerns in emergency response operations, reactor operational experience & availability of cooling water  
FALCO, P D Environmental Protection Agency 79/07/03 10pp
- 7907130404 Comments on DES Rept does not adequately consider cumulative environ impacts, burial of radwaste, accident analysis & impacts of mitigative measures  
MEIEROTTO, L E Interior, Dept of 79/07/06 5pp
- Q Adjudicatory correspondence
- 7907050371 Advises of applicant opposition to L Bard 790327 request for financial assistance Filing took place in wrong forum  
Request is inappropriate per 4NRC494(1976) decision  
Certificate of Bvc encl  
BISCHOFF, C A Snell & Wilmer 79/05/14 4pp
- 7907050356 Expresses desire to attend public hearing re facility Opposes further const. Requests ASLB order setting date, time & place of hearing  
EPPLEB, M Affiliation Unknown 79/05/15 1p
- 7907060038 Response of AZ Public Bvc, Southern CA Edison, FI Paso Electric, San Diego Gas & Electric, NV Power, Dept of Water & Power of LA, et al, to Environ Defense Fund 790503 petition to intervene Certificate of Bvc encl  
GEHR, A C, BISCHOFF, C A Snell & Wilmer 79/05/18 17pp
- 7907020007 Arizona Public Bvc first set of interrogatories & request for production of documents, directed to L Bard Certificate of Bvc encl  
GEHR, A C Snell & Wilmer 79/05/21 20pp
- 7907020003 Reply by State of CA & CA Public Util Commission to AZ Public Bvc 790518 response to Environ Defense Fund 790503 petition to intervene Certificate of Bvc encl  
KERR, J E California, State of 79/05/24 8pp
- 7907180358 Response to CA Public Util Commission 790516 motion for extension of time to file comments to DES Extension granted until 790626 Certificate of Bvc encl  
BDHINKI, S M Branch 3 79/05/25 4pp
- 7907030294 Opposes plant const due to increased const costs, impact on electric rates & problem of waste disposal  
MIKUB, P J Affiliation Unknown 79/05/26 2pp
- 7907180119 AZ Public Bvc et al, opposition to Morongo Band of Mission Indians 790511 petition to intervene If petition is denied, petitioner limited appearance will not be opposed by applicants Certificate of Bvc encl  
GEHR, A C, BISCHOFF, C A Snell & Wilmer 79/05/29 12pp.
- 7907180313 Joint applicants response to CA Public Util Commission motion for extension until 790701 to file comments on DES Date suggested is excessive. Time should not be extended beyond 790531 Certificate of Bvc encl  
GEHR, A C, BISCHOFF, C A Snell & Wilmer 79/05/31 5pp
- 7907190722 NRC opposition to Morongo Band of Mission Indians 790511 petition to intervene Petitioner demonstrated standing but failed to justify untimely filing & to base contention on reasonable specificity Certificate of Bvc encl  
CUTCHIN, J M Branch 3 79/05/31 11pp
- 7907180297 Motion to file reply to NRC & joint applicants 790518 responses to Environ Defense Fund petition to intervene. Responses contain factual inaccuracies which must be corrected Certificate of Bvc encl.  
MASTBAUM, D, ROE, D B Environmental Defense Fund 79/06/01 App
- 7907180078 AZ Public Bvc et al, opposition to CA Public Util Commission 790524 reply to applicants response to Environ Defense Fund petition to intervene Urges rejection of reply for being defective on merits Certificate of Bvc encl  
GEHR, A C, BISCHOFF, C A Snell & Wilmer, 79/06/03 12pp
- 7907130526 Response in opposition to Environ Defense Fund 790601 motion to file reply to joint applicants & NRC 790518 responses to Environ Defense Fund 790503 petition to intervene Granting of motion would be counterproductive w/Certificate of Bvc  
BDHINKI, S M Branch 3 79/06/11, 5pp
- 7907020006 Arizona Public Bvc answer in opposition to intervenor L Bard motion for extension until 790701 to answer first discovery requests Certificate of Bvc encl  
GEHR, A C, BISCHOFF, C A Snell & Wilmer, 79/06/15 6pp
- 7907190706 Joint applicants AZ Public Bvc, et al answer to intervenor L Bard motion seeking extension until 790701 for answering first round discovery request. Certificate of Bvc encl  
GEHR, A C, BISCHOFF, C A Snell & Wilmer, 79/06/15 6pp.
- 7907190453 Joint applicants AZ Public Bvc, et al response to Environ Defense Fund 790601 petition to file reply in answer to NRC & joint applicants responses to 790503 petition to intervene Certificate of Bvc encl.  
GEHR, A C, BISCHOFF, C A Snell & Wilmer, 79/06/18 App.
- 7907190379 People of State of CA & Public Util Commission of State of CA statement of issues per 790306 special prehearing conference order Certificate of Bvc encl.  
KERR, J E, SIMPSON, J C, MACKENZIE, V V California, State of 79/06/20, 36pp
- 7907190479 CA Energy Resources Conservation & Development Commission Statement of issues, per ASLB 790306 order, indicating that Commission is entitled to participate in hearing as interested state Certificate of Bvc encl.  
URBAN, M J, GRUENEICH, D M California, State of 79/06/20, 10pp
- 7907090328 Comments by intervenor L Bard re DES Formal presentation of comments will be submitted at later date, DES has major deficiencies which need attention before CP can be granted  
BARD, L. Affiliation Unknown, 79/06/26, 13pp

7907090301 Errata to comments by State of CA & CA Public Util  
Commission of re adequacy of NRC DES  
WEISBMAN, S A , KERR, J E , SIMPSON, J C California, State of  
79/06/29 2pp

7907260580 Forwards CA Public Utils Commission decision on Southern CA  
Edison Co proposed 500 kV transmission line, Application  
57251  
STOGER, D B California, State of 79/07/23 1p

--7907260583 CA Public Utils Commission decision on Southern CA Edison  
Co proposed 500 kV transmission line, Application 57251  
BRYSON, J E , STURGEON, V L , GRAVELLE, R D California, State of  
79/07/17 41pp

#### DOCKET BTN-50-596 NEW HAVEN, UNIT 1

##### A Application/construction stage documents & correspondence

7907110700 Forwards info requests re aesthetics, geology, seismology, air  
quality & meteorology  
INDYKE, C M Albany, NY 79/05/04 14pp

7907130084 Forwards info re emergency planning 10CFR50 App E, Reg Guide  
1.101, NRC SRP Section 13.3, NUREG-75/111, w/Suppl 1, "NY State  
Emergency Plan for Radiation Accidents," & related matl w/o  
encl  
CAPRA, R A Light Water Reactors Branch 3 79/06/04 2pp

7907290069 Notification of 790712 meeting w/NY State Electric & Gas  
Co & B&W in Bethesda, MD to discuss site drainage & ultimate  
heat sink  
DROMERICK, A Light Water Reactors Branch 3 79/06/28 2pp

7907300550 Notices of cancellation of 790712 meeting w/util in  
Bethesda, MD to discuss site drainage & ultimate heat  
sink  
DROMERICK, A Light Water Reactors Branch 3 79/06/28 1p

7907310241 Forwards photograph showing dragged strata, Rock Pit II, in  
response to Question 361.15 of PSAR Amend 4 w/o encl  
KINTIGH, A E New York State Electric & Gas Corp 79/07/27 1p

##### B Utility Preliminary Safety Analysis Report, amends

7907310266 Forwards Amend 4 to PSAR Affidavit encl.  
KINTIGH, A E New York State Electric & Gas Corp 79/07/27 2pp

--7907310269 Amend 4 to PSAR  
\* New York State Electric & Gas Corp 79/07/27, 250pp

##### C Utility Environmental Report (ER), amends & correspondence

7907170012 Forwards Amend 4 to environ rept Affidavit encl  
KINTIGH, A E New York State Electric & Gas Corp 79/07/12 2pp

--7907170016 Amend 4 to environ rept  
\* New York State Electric & Gas Corp 79/07/01 67pp

##### D NRC Draft/Final Environmental Statements, suppl & correspondence

7907110601 Discusses NRC approval schedule for DES & FEB  
BELLS, D E Environmental Projects Branch 2 79/05/16 4pp

##### G Adjudicatory correspondence

7907260694 Forwards notices of appearance for BH Lewis & ME Mulkey as  
counsel for NRC & petitions to intervene filed by  
Gardiner, NY & Ulster County Environmental Mgt Council  
Certificate of Svc encl  
LEWIS, B. H. Office of the General Counsel 79/04/19 6pp.

--7907260701 Submits petition to intervene Intervention justified by  
environ impact of facilities Petition delayed due to late  
notification  
BOEMIER, B. J. Kingston, NY 79/03/15 1p.

--7907260712 ts petition to intervene Forwards 790312 press release in  
explanation of late submittal.  
KEEPING, W. Gardiner, NY 79/03/13 4pp

7907180240 Proposes schedule for conducting joint hearings before NRC &  
NY State Board on Electric Generation Siting Environ re  
application for units at New Haven, NY, Certificate of Svc  
encl.  
OREY, R., INDYKE, C , ENGEL, D. New York, State of. 79/04/27. 11pp.

7907110708 Initial util answer to intervenor contentions Identifies  
contentions which can be presented unopposed at 790523  
prehearing conference Seeks ABLG extension for filing  
supplemental answers Certificate of Svc encl  
SCHUTT, R , ZEBRAK, I L Huber, Magill, Lawrence & Farrell 79/05/18  
8pp

7907160106 Contentions re site selection Util has underestimated  
multiple generation units, has not considered proximity to  
schools & has discriminated against rural populace  
\* Safe Energy for New Haven 79/05/29 2pp

--7907160113 Contentions of Safe Energy for New Haven re environ matters  
Util inadequately determined energy needs, has not performed  
sufficient research on alternative sources of energy & has  
not assessed impact of accident on KV lines  
\* Safe Energy for New Haven 79/05/29 3pp

7907160169 Certification that 790319 petition to intervene & 790310  
contentions truly set forth position of Mid-Hudson Nuclear  
Opponents, Inc.  
BROWN, P. D. Mid-Hudson Nuclear Opponents, Inc 79/05/31 1p

7907190083 Support for NRC & State of NY 790427 proposed protocol for  
joint hearings submitted by Ecology Action of Oswego.  
Suggests mod for joint hearings discovery process, memo  
of understanding, schedule & procedure for joint mailings  
DALY, H., CAPLAN, B Ecology Action of Oswego 79/06/11 9pp

7907260476 NY Dept of Public Svc reply to comments offered by various  
parties at 790523 prehearing conference on proposed joint  
protocol in Case 80008  
GREY, R New York, State of 79/06/11 5pp

7907260121 Forwards E Mead 790614 intervention statement Proposes to  
respond to statement & other pleadings by 790713  
LEWIS, B H Branch 2 NRC 79/06/19 1p

--7907260128 Intervention statement offered at 790614 public comment  
session  
MEAD, E Affiliation Unknown 79/06/14 3pp

7907190495 Requests extension until 790703 to respond to util & Ecology  
Action of Oswego 790611 comments on discovery rules  
Certificate of Svc encl.  
MULKEY, M E Branch 2. 79/06/25 5pp

7907240235 Reaffirms 790611 comments Application is summary of util  
findings & conclusions NRC & intervenors must develop record  
on which Siting Board will make final decision  
DALY, H Ecology Action of Oswego 79/06/26 5pp

##### G Inspection reports, IE Bulletins & correspondence

7907100409 Forwards IE Circular 79-11, "Design/Const Interface  
Problem." No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director  
79/06/27 1p

##### T. Hearing transcripts on non-antitrust matters

7907120083 Transcript of 790614 joint public hearing before ABLP, NY  
State Dept of Public Svc & NY State Board on Electric  
Generation, Siting & Environ in Albany, NY. Pp 627-898  
WENNER, B., JORDAN, W H , PARIB, D Atomic Safety and Licensing Board  
Panel 79/06/14. 271pp

#### DOCKET BTN-50-597 NEW HAVEN, UNIT 2

##### A. Application/construction stage documents & correspondence

7907110700 Forwards info requests re aesthetics, geology, seismology, air  
quality & meteorology.  
INDYKE, C. M. Albany, NY. 79/05/04. 14pp

7907130084 Forwards info re emergency planning: 10CFR50 App E, Reg Guide  
1.101, NRC SRP Section 13.3, NUREG-75/111, w/Suppl 1, "NY State  
Emergency Plan for Radiation Accidents," & related matl. w/o  
encl.  
CAPRA, R A Light Water Reactors Branch 3. 79/06/04. 2pp.

7907250069 Notification of 790712 meeting w/NY State Electric & Gas  
Co & B&W in Bethesda, MD to discuss site drainage & ultimate  
heat sink  
DROMERICK, A Light Water Reactors Branch 3 79/06/28 2pp

## DOCKETED ITEMS

7907300550 Notifies of cancellation of 790712 meeting w/util in Bethesda, MD to discuss site drainage & ultimate heat sink  
DOMERICK, A Light Water Reactors Branch 3 79/06/28 1p

7907310241 Forwards photograph showing dragged strata, Rock Pit II, in response to Question 361 15 of PSAR Amend 4 W/o encl  
KINTIGH, A E New York State Electric & Gas Corp 79/07/27 1p

**B Utility Preliminary Safety Analysis Report: amends**

7907310266 Forwards Amend 4 to PSAR Affidavit encl  
KINTIGH, A E New York State Electric & Gas Corp 79/07/27 2pp

--7907310269 Amend 4 to PSAR  
\* New York State Electric & Gas Corp 79/07/27 250pp

**C Utility Environmental Report (ER), amends & correspondence**

7907170012 Forwards Amend 4 to environ rept Affidavit encl  
KINTIGH, A E New York State Electric & Gas Corp 79/07/12 2pp

--7907170016 Amend 4 to environ rept  
\* New York State Electric & Gas Corp 79/07/01 67pp

**D NRC Draft/Final Environmental Statements, suppl & correspondence**

7907110601 Discusses NRC approval schedule for DES & FES  
BELLIS, D E Environmental Projects Branch 2 79/03/16 4pp

**G Adjudicatory correspondence**

7907260694 Forwards notices of appearance for SH Lewis & ME Mulkey as counsel for NRC & petitions to intervene filed by Gardiner, NY & Ulster County Environmental Mgt Council  
Certificate of Svc encl  
LEWIS, S H Office of the General Counsel 79/04/19 6pp

--7907260701 Submits petition to intervene Intervention justified by environ impact of facilities Petition delayed due to late notification  
EGEMEIER, S J Kingston, NY 79/03/15 1p

--7907260712 ts petition to intervene Forwards 790312 press release in explanation of late submittal  
KEEPING, W Gardiner, NY 79/03/13 4pp

7907180240 Proposes schedule for conducting joint hearings before NRC & NY State Board on Electric Generation Siting Environ re application for units at New Haven, NY Certificate of Svc encl  
GREY, R, INDYKE, C, ENGEL, D New York, State of 79/04/27 11pp

7907110708 Initial util answer to intervenor contentions Identifies contentions which can be presented unopposed at 790523 prehearing conference Seeks ASLB extension for filing supplemental answers Certificate of Svc encl  
SCHUTT, R, ZEBRAK, I L Huber, Magill, Laurence & Farrell 79/05/18 8pp

7907160106 Contentions re site selection Util has underestimated multiple generation units, has not considered proximity to schools & has discriminated against rural populace  
\* Safe Energy for New Haven 79/05/29 2pp

--7907160113 Contentions of Safe Energy for New Haven re environ matters Util inadequately determined energy needs, has not performed sufficient research on alternative sources of energy & has not assessed impact of accident or KV lines  
\* Safe Energy for New Haven 79/05/29 3pp

7907160167 Certification that 790319 petition to intervene & 790510 contentions truly set forth position of Mid-Hudson Nuclear Opponents, Inc  
BROWN, P D. Mid-Hudson Nuclear Opponents, Inc 79/03/31 1p

7907190083 Support for NRC & State of NY 790427 proposed protocol for joint hearings submitted by Ecology Action of Oswego Suggests mod for joint hearings discovery process, memo of understanding, schedule & procedure for joint mailings  
DALY, H, CAPLAN, B Ecology Action of Oswego 79/06/11 9pp

7907260478 NY Dept of Public Svc reply to comments offered by various parties at 790523 prehearing conference on proposed joint protocol in Case 80008  
REY, R New York, State of 79/06/11 5pp

7907260121 Forwards E Mead 790614 intervention statement Proposes to respond to statement & other pleadings by 790713  
LEWIS, S H Branch 2 NRC 79/06/19 1p

--7907260128 Intervention statement offered at 790614 public comment session  
MEAD, E Affiliation Unknown 79/06/14 3pp

7907190695 Requests extension until 790703 to respond to util & Ecology Action of Oswego 790611 comments on discovery rules  
Certificate of Svc encl  
MULKEY, M E Branch 2 79/06/25 5pp

7907240235 Reaffirms 790611 comments Application is summary of util findings & conclusions NRC & intervenors must develop record on which Siting Board will make final decision  
DALY, H Ecology Action of Oswego 79/06/26 5pp

**Q Inspection reports, IE Dulletins & correspondence**

7907100409 Forwards IE Circular 79-11, "Design/Const Interface Problem" No action required  
ORIER, B H Region 1, Philadelphia, Office of the Director 79/06/27 1p

**T Hearing transcripts on non-antitrust matters**

7907120083 Transcript of 790614 joint public hearing before ASLP, NY State Dept of Public Svc & NY State Board on Electric Generation, Siting & Environ in Albany, NY Pp 627-698  
WENNER, S, JORDAN, W H, PARIB, D Atomic Safety and Licensing Board Panel 79/06/14 271pp

**DOCKET 50-399 CARROLL FACILITY I**

**A Application/construction stage documents & correspondence**

7907110023 Forwards copy of map depicting location of proposed alternative sites for facility, pamphlet describing NRC licensing process & NUREG-0180 which describes NRC approach to conducting early site reviews W/o encl  
BALLARD, R L Environmental Projects Branch 1. 79/06/11 1p

7907110686 Summary of 790430-0504 trip & meeting w/representatives of State of IL & util re CP application  
HAUPT, C A Environmental Projects Branch 1. 79/06/11. 6pp

7907050330 Submits revised schedule for fuel loading dates due to impact of TMI incident  
REED, C Commonwealth Edison Co 79/06/27. 3pp

7907060278 Requests opportunity to review & comment on application for CP & early site review  
WALLACE, A Iowa, State of 79/06/27 1p.

**G Adjudicatory correspondence**

7907130495 Notice of filing of State of IL opposition to early site review  
BENNETT, N J, SCOTT, W J Illinois, State of 79/06/04 1p.

--7907130505 State of IL opposition to early site review Necessity of present & future const is being investigated by IL Commerce Commission Affidavit & Certificate of Svc encl  
BENNETT, N J, SCOTT, W J Illinois, State of 79/06/04 4pp

7907190339 Notification of appearance on behalf of State of IL  
BENNETT, N J, SCOTT, W J Illinois, State of 79/06/04. 4pp

7907110610 Petition to intervene in hearings re CP application & request for early site review, Plant would have negative land use effort on area & would harm local economy.  
DUBERT, J Iowa Socialist Party. 79/06/05. 1p.

7907160015 NRC answer in support of State of IA 790530 notice of participation in hearing, Notice of appearance of RO Goddard & SC Goldberg & Certificate of Svc encl.  
GODDARD, R J Branch 2 79/06/07 4pp.

7907190595 NRC answer to IA PIRO, Catholic Worker, Dubuque Fellowship of Reconciliation, Environ Coordinating Organization & Carroll County Environ Coalition 790601 joint petition to intervene  
Certificate of Svc encl  
GODDARD, R J. Branch 2 79/06/12 5pp

7907190602 NRC answer to State of IL 790604 petition to intervene  
Certificate of Svc encl  
GODDARD, R J Branch 4 79/06/12 6pp

7907190618 NRC answer to J Davies County Ad Hoc Committee on Nuclear  
Energy Info 790601 petition to intervene Certificate of Svc  
encl  
GODDARD, R J Branch 4 79/06/12 5pp

7907190716 Notification of filing of State of IL 790615 brief in  
support of IL opposition to early site review  
SCOTT, W J, BENNETT, N J Illinois, State of 79/06/15 1p

--7907190784 State of IL brief in support of IL opposition to early site  
review Review is unnecessary, untimely & unwarranted  
Affidavit & Certificate of Svc encl  
BENNETT, N J Illinois, State of 79/06/15 7pp

7907190387 NRC answer to IA Socialist Party undated petition to  
intervene Certificate of Svc encl  
GODDARD, R J Branch 2 79/06/20 5pp

7907190446 Comm Ed answers to petitions to intervene filed by People  
of IL, State of IA, J Davies County Ad Hoc Committee on  
Nuclear Energy Info, IA PIRG, et al & IA Socialist Party  
Certificate of Svc encl  
STEPTOE, P P Isham, Lincoln & Beale 79/06/20 8pp

#### H General correspondence

7907100443 Forwards affidavit certifying that Site Suitability -  
Environ Rept, Suppl 1 was distributed on 790702  
NAUGHTON, W F Commonwealth Edison Co 79/07/02 2pp

#### DOCKET 80-600 CARROLL FACILITY II

##### A Application/construction stage documents & correspondence

7907110023 Forwards copy of map depicting location of proposed  
alternative sites for facility, pamphlet describing NRC  
licensing process & NUREG-0180 which describes NRC approach  
to conducting early site reviews w/o encl.  
BALLARD, R L Environmental Projects Branch 1 79/06/11 1p

7907110486 Summary of 790430-0504 trip & meeting w/representatives  
of State of IL & util re CP application  
HAUPT, C A Environmental Projects Branch 1 79/06/11 6pp

7907050330 Submits revised schedule for fuel loading dates due to  
impact of TH1 incident  
REED, C Commonwealth Edison Co 79/06/27 3pp

7907060278 Requests opportunity to review & comment on application for  
CP & early site review  
WALLACE, A Iowa, State of 79/06/27 1p

##### O Adjudicatory correspondence

7907130495 Notice of filing of State of IL opposition to early site  
review  
BENNETT, N J, SCOTT, W J Illinois, State of 79/06/04 1p

--7907130505 State of IL opposition to early site review Necessity of  
present & future const is being investigated by IL Commerce  
Commission Affidavit & Certificate of Svc encl  
BENNETT, N J, SCOTT, W J, Illinois, State of 79/06/04, 4pp.

7907190339 Notification of appearance on behalf of State of IL  
BENNETT, N J, SCOTT, W J Illinois, State of 79/06/04 4pp

7907110610 Petition to intervene in hearings re CP application &  
request for early site review Plant would have negative land  
use effect on area & would harm local economy  
DUBERT, J. Iowa Socialist Party, 79/06/05 1p.

7907160015 NRC answer in support of State of IA 790530 notice of  
participation in hearing Notice of appearance of RQ Goddard  
& BG Goldberg & Certificate of Svc encl.  
GODDARD, R J Branch 2, 79/06/07, 4pp.

7907190895 NRC answer to IA PIRG, Catholic Worker, Dubuque Fellowship of  
Reconciliation, Environ Coordinating Organization & Carroll  
County Environ Coalition 790601 joint petition to intervene.  
Certificate of Svc encl  
GODDARD, R J Branch 2 79/06/12 8pp.

7907190602 NRC answer to State of IL 790604 petition to intervene  
Certificate of Svc encl  
GODDARD, R J Branch 4 79/06/12 6pp

7907190618 NRC answer to J Davies County Ad Hoc Committee on Nuclear  
Energy Info 790601 petition to intervene Certificate of Svc  
encl  
GODDARD, R J Branch 4 79/06/12 5pp

7907190716 Notification of filing of State of IL 790615 brief in  
support of IL opposition to early site review  
SCOTT, W J, BENNETT, N J Illinois, State of 79/06/15 1p

--7907190784 State of IL brief in support of IL opposition to early site  
review Review is unnecessary, untimely & unwarranted  
Affidavit & Certificate of Svc encl  
BENNETT, N J Illinois, State of. 79/06/15 7pp

7907190387 NRC answer to IA Socialist Party undated petition to  
intervene Certificate of Svc encl  
GODDARD, R J Branch 2 79/06/20 5pp

7907190446 Comm Ed answers to petitions to intervene filed by People  
of IL, State of IA, J Davies County Ad Hoc Committee on  
Nuclear Energy Info, IA PIRG, et al & IA Socialist Party  
Certificate of Svc encl  
STEPTOE, P P Isham, Lincoln & Beale 79/06/20 8pp

#### H General correspondence

7907100443 Forwards affidavit certifying that Site Suitability -  
Environ Rept, Suppl 1 was distributed on 790702  
NAUGHTON, W F Commonwealth Edison Co 79/07/02 2pp

#### DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

##### DOCKET 70-0008 BATELLE COLUMBUS LABORATORIES

7907050428 Forwards IE Circular 79-09, "Occurrences of Split or  
Punctured Regulator Diaphragms in Certain Self-Contained  
Breathing Apparatus." No action required  
KEPPLER, J. O Region 3, Chicago, Office of the Director 79/06/22  
1p

##### DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

7907110616 Requests amend to License BMN-21 to conduct series of  
operational performance tests w/units of MO & MI fuel plates  
w/x-ray fluoroscope  
REMLEY, M E Rockwell International Energy Systems Group 79/05/10.  
4pp

7907300245 Forwards IE Insp Rept 70-0025/79-03 on 790326-30 No  
noncompliance noted  
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials  
Safety Branch 79/05/14 2pp

7907100453 Forwards IE Circular 79-09, "Occurrences of Split or  
Punctured Regulator Diaphragms in Certain Self-Contained  
Apparatus." No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director  
79/06/22 1p

7907300260 IE Insp Rept 70-0025/79-03 on 790326-30 No noncompliance  
noted. Major areas inspected, facilities & sys mods, internal  
review & audits safety committee, procedure control,  
criticality & environ safety  
CODLEY, W J, FONG, F F., BOOK, H E Region 5, San Francisco, Fuel  
Facility & Materials Safety Branch 79/05/11 17pp

##### DOCKET 70-0027 BABCOCK & WILCOX CO

7907160227 Amends License BMN-0042 to authorize reorganization &  
administration of radiation control program & emergency plan  
mod Review of amend application encl  
CROW, W. T Fuel Process. & Fab. Branch 79/04/23, 10pp

7907100705 Forwards air effluent monitoring program conducted by  
applicant over past 18 months Applicant seeks amend to  
export license to allow reduction in monitoring program  
Approves amend. Recommends permanent location of station  
SHUM, E Y. Fuel Process & Fab. Branch 79/04/26 7pp

7907200233 Forwards IE Insp Rept 70-0027/79-04 on 790327-29 No  
noncompliance noted.  
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials  
Safety Branch 79/05/10 2pp.

## DOCKETED ITEMS

- 7907200234 IE Insp Rept 70-0027/79-04 on 790327-29 No noncompliance noted Major areas inspected radiological environ monitoring program including ngt controls, QC measures & monitoring stations  
PEERY, W W , MACARTHUR, T C , WUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/10 4pp
- 7907050177 Discusses amend fee for 780915 application for Amend B to License SNM-42 Amend reclassified from minor to major Addl fee required  
MILLER, W O License Fee Management Branch 79/05/15 1p
- 7907100063 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p
- 7907060193 Responds to 790412 ltr Forwards amended Section 9 O of Amend MPP-1 to License SNM-42, adding Condition 9 4 5 re physical protection plan isolation zone  
MCCORKLE, Q W Physical Security Licensing Branch 79/05/23 2pp
- 7907060396 Requests exception to 10CFR20 51(e)(4)(i), Completion of calculation of associated limit of error of MUF for each element & fissile isotope for U contained in matl in process will be delayed from 790506 to 0601  
MCCLANAHAN, H H Babcock & Wilcox Co 79/05/25 2pp
- 7907110431 Grants 790525 request for 6-day extension to complete requirement for Mar/Apr 1979 physical inventory period re License SNM-27  
PARTLOW, J G Material Control Licensing Branch 79/05/31 1p
- 7907230498 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/79-06  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/06/14 1p
- 7907230505 Responds to NRC 790509 ltr re violations noted in IE Insp Rept 70-0027/79-06 Corrective actions info withheld (ref 10CFR2 790)  
EWING, J F Babcock & Wilcox Co 79/05/17 1p
- 7907230513 Forwards IE Insp Rept 70-0027/79-06 on 790409-13 Notice of violation withheld (ref 10CFR2 790)  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/05/02 2pp
- 7907230523 IE Insp Rept 70-0027/79-06 on 790409-13 Noncompliance noted failure to calibr two accountability scales over range of operation Details withheld (ref 10CFR2 790)  
ROBERTSON, J S , JONES, D W , GILLESPIE, F P Region 2, Atlanta, Safeguards Branch 79/05/01 1p
- 7907180724 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p
- 7907240489 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC**
- 7907060039 Requests meeting in Silver Spring, MD to discuss 790215 license renewal application re lack of allowance for internal review & approvals of operation mode Renewal application for License SNM-23 tentatively accepted  
CROW, W T Fuel Process & Fab Branch 79/04/16 1p
- 7907240296 Forwards IE Insp Rept 70-0033/79-05 on 790319-22 No noncompliance noted  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/05/16 2pp
- 7907240297 IE Insp Rept 70-0033/79-05 on 790319-22 No noncompliance noted Major areas inspected: nuclear matl control & accounting including records, repts & physical inventory operational & environ info  
COHEN, I , HOLTNER, E , JOYNER, J H Region 1, Philadelphia, Safeguards Branch 79/05/10 3pp
- 7907260013 Discusses plans to install communication lines between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional otc will forward operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp
- 7907030464 Requests description of all actions taken re comprehensive evaluation reft IE intends to confirm satisfactory resolution of all items requiring action  
BURNETT, R F Division of Safeguards 79/05/29 1p
- 7907240160 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p
- DOCKET 70-0036 COMBUSTION ENGINEERING, INC**
- 7907230725 Submits Amend 3 to 790112 application Condition 22 amend license to include decommissioning plan & financial commitment  
CROW, W T Fuel Process & Fab Branch 79/06/04 1p
- 7907030432 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPLER, J O Region 3, Chicago, Office of the Director 79/06/22 1p
- 7907240143 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p
- DOCKET 70-0049 FLORIDA, UNIV OF**
- 7907100083 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p
- DOCKET 70-0135 BABCOCK & WILCOX CO**
- 7907030473 Forwards revised proposed apollo site safeguards contingency plan, Revision D Plan withheld (ref 10CFR2 790)  
AUSTIN, M A Babcock & Wilcox Co 79/04/26 2pp
- 7907110427 Grants 790509 request to delay starting time to conduct low enriched U physical inventory by adding condition to License SNM-145, Also approves proposed changes to Fundamental nuclear matl control plan  
BURNETT, R F Division of Safeguards 79/05/31 2pp
- 7907110393 Requests that changes be made before operations security training, in order for qualification plan to be considered acceptable  
MCCORKLE, Q W Physical Security Licensing Branch 79/05/31 4pp
- 7907240139 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC,**
- 7907180743 Requests renewal of Certificate of Compliance 4949 Forwards current certificate, W/O encl.  
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co ) 79/03/01 1p
- 7907030091 Accepts Revision 14 to physical protection plan & Amends Section 9 of matl & plant protection amend, MPP-1 to License SNM-124 Enclosures to 781229 & 790322 ltrs are withheld (ref 10CFR2 790)  
MCCORKLE, Q W Physical Security Licensing Branch 79/04/10 1p
- 7907060437 Requests amend to License SNM-124 Amend withheld (ref 10CFR2, 790).  
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co ), 79/04/23 1p
- 7907120195 Submits action taken per 790417 meeting following violent NFS strike on 790416 Discussion w/IE revealed no danger to individuals or environ re clean-out operations & surveillance plans prior to start-up.  
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 79/04/24 2pp.



- 7907060134 Requests 30-day extension until 790617 for submittal of complete revision of Section 7 of fundamental nuclear matl control plan  
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/04/25 1p
- 7907090368 Requests extension of implementation date for License Conditions 9.3.10.1 through 9.3.10.3 due to labor problems  
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/04 1p
- 7907190384 Ack receipt of 790316 transmittal of License SNM-124 Discusses incorrect ref to Condition 29 requirement for quarterly emergency evacuation drill Condition 29 actually requires drills  
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/07 1p
- 7907020472 Requests extension until 790731 in which to respond to annual audit of contract labs performing matl control & accounting measurement svc  
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/10 2pp
- 7907020473 Responds to 790510 request for amend to License SNM-124, extending time limits for review of contractor matl control & accounting measurement svc Requests submittal of administrative amend fee  
WEISS, D License Fee Management Branch 79/05/18 2pp.
- 7907060386 Forwards financial statements as of 781231, including comparative data for 1977 Statements withheld (ref 10CFR2 790)  
CONTI, P L Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/14 2pp
- 7907090361 Forwards "Planning Guidelines " Requests prompt completion of NRC review & termination of 790423 license condition Encl withheld (ref 10CFR2 790)  
TAYLOR, C W Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/17 2pp
- 7907180786 Forwards addl info requested 790329 Encl withheld (ref 10CFR2 790)  
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/17 2pp
- 7907100070 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/05/18 1p
- 7907230738 Recommends termination of 790423 license condition in response to 790517 application Prior written approval from NRC is not necessary before introduction of SNM into process sys or startup of operations using mgt personnel  
DELANEY, J C Fuel Process & Fab Branch 79/05/18 3pp
- 7907160247 Ack receipt of IE Insp Rept 70-0143/79-12 on 790321 No proprietary info  
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/23 1p
- 7907160259 Forwards IE Insp Rept 70-0143/79-12 on 790321 No noncompliance noted  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/10 2pp
- 7907160268 IE Insp Rept 70-0143/79-12 on 790321 No noncompliance noted Major areas inspected nonradiological liquid effluents, underground tank monitoring program & stock fluoride monitoring program  
CUNNINGHAM, A L, ANDREWS, D L, HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/09 3pp.
- 7907060209 Conveys concern over certification & use of "KAPL Std" in measurement control program.  
PARTLOW, J O Material Control Licensing Branch. 79/05/25 1p
- 7907130111 Ack receipt of 790530 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-14  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/06/13 1p
- 7907130121 Responds to NRC 790411 ltr re violations noted in IE Insp Rept 70-0143/79-14 Corrective actions withheld (ref 10CFR2 790).  
MANBER, W C Nuclear Fuel Services, Inc. (subs of Getty Oil Co ).  
79/05/30. 1p
- 7907130132 Requests 30-day extension to respond to violation noted in IE Insp Rept 70-0143/79-14  
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/05/01 1p
- 7907130145 Forwards IE Insp Rept 70-0143/79-14 on 790312-30 & notice of violation info withheld (ref 10CFR2 790)  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/11 2pp
- 7907190828 Discusses inventory differences in highly enriched U which exceeded associated limits of error Review should include specific effect of new solid separation equipment in scrap plant  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/14 1p
- 7907230607 Ack receipt of 790605 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-17  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/19 1p
- 7907230615 Responds to NRC 790518 ltr re violations noted in IE Insp Rept 70-0143/79-17 Corrective actions required weekly testing of critical alarm sys reinstated Employees instructed  
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co )  
79/06/05 2pp
- 7907230623 Forwards IE Insp Rept 70-0143/79-17 on 790508-10 & notice of violation  
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/18 2pp
- 7907230640 Notice of violation from insp on 790508-10  
\* Region 2, Atlanta, Office of the Director 79/05/17 1p
- 7907230652 IE Insp Rept 70-0143/79-17 on 790508-10 Noncompliance noted failure to perform weekly tests of criticality monitoring sys  
CORVELL, G P, LEE, T D Region 2, Atlanta, Office of the Director  
POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/17 4pp
- 7907110207 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/06/22 1p
- 7907160070 Responds to 781212 ltr Delinates steps NRC has taken to ensure high level of safeguards assurance Facility was inspected to verify actions taken in response to guidelines of comprehensive evaluation program  
HENDRIE, J M Commission 79/06/29 6pp
- 7907160122 Responds to proposed mod to License Conditions 2.10 & 3.3 re 790109 meeting in Silver Spring, MD Mods are acceptable & do not decrease safeguards effectiveness License amend encl  
BURNETT, R F Division of Safeguards 79/01/23 3pp
- 7907160134 Comments on 780718 ltr BECY-78-425A should be amended to include thefts of license-exempt & strategic SNM Requests current status of physical security & matl accounting at plant.  
COCHRAN, T B Natural Resources Defense Council 78/12/12 3pp
- 7907160150 Comments on adequacy of physical security & matl accounting at plant Present safeguards approach is insufficient & statistical approach is sound Safeguards review of facility should be open to public  
COCHRAN, T B Natural Resources Defense Council 78/03/03 5pp
- 7907160159 Notifies that comprehensive evaluation of facility not yet available Facility will be held to high level of safeguards assurance Show cause proceeding is not indicated under circumstances.  
OILINSKY, V Commission. 78/05/17 2pp
- 7907160166 Comprehensive Evaluation Rept on Nuclear Safeguards dtd 780407.  
\* Commission 78/04/07 5pp
- 7907240495 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director  
79/07/06 1p

## DOCKET 70-0152 PURDUE UNIV

7907050421 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director 79/06/22 1p

## DOCKET 70-0267 NUCLEAR SCIENCE &amp; TECHNOLOGY FACILITY AT SUNY

7907020485 Forwards Matl Status Rept NRC/ERDA-742 for 780930-790331 for License R-77 & SNM-273  
HAAS, M N New York, State Univ of, Buffalo 79/05/18 8pp

## DOCKET 70-0297 GEORGIA INST OF TECH

7907100114 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

## DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK &amp; WILCOX CO

7907050072 Incorporates activities authorizing License 37-04456-03 into revised License SNM-414 issued 790202 Forwards Amends 33 to License 37-04456-03, terminating license  
ROUSE, L C Fuel Reprocess & Recycle Branch 79/02/05 1p

--7907050074 License 37-04456-03 is terminated by incorporation into License SNM-414  
BASSIN, N Licensing Management Branch 79/02/05 1p

7907110232 Summary of 790302 meeting w/B&W re schedule for ventilation revisions  
BURHARDT, W Fuel Reprocess & Recycle Branch 79/05/07 1p

7907060504 Requests amend of Condition 37 of License SNM-414 re Pu ventilation upgrading program  
AUSTIN, M A Babcock & Wilcox Co 79/05/14 3pp

7907260008 Discusses plans to install communication lines between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will forward operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907110224 Forwards "Environ Consequences of Postulated Pu Releases," Mar 1979  
ROUSE, L C Fuel Reprocess & Recycle Branch 79/05/25 1p

--7907110235 "Environ Consequences of Postulated Pu Releases," Mar 1979  
MCIPHERSON, R B, WATSON, E C Battelle Memorial Institute, Pacific Northwest Laboratory PNL-2833 79/03/31 65pp Available at NTIS

7907110237 Forwards "Risk Analysis of Postulated Pu Releases from B&W Plant as Result of High Winds & Earthquakes "  
ROUSE, L C Fuel Process & Fab Branch 79/05/30 1p

--7907110272 "Risk Analysis of Postulated Pu Releases from B&W Plant as Result of High Winds & Earthquakes "  
\* Fuel Process & Fab Branch 79/05/30 38pp

7907090121 Forwards increment of analysis of effects of natural phenomena relative to plutonium fabrication operations  
ROUSE, L C Fuel Reprocess & Recycle Branch 79/05/31 1p

--7907090123 "Flooding Risk Analysis "  
\* Fuel Reprocess & Recycle Branch. 79/05/31 10pp

7907240139 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

## DOCKET 70-0368 GEORGIA INSTITUTE OF TECHNOLOGY

7907100657 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 2pp.

## DOCKET 70-0371 UNITED NUCLEAR CORP

7907110611 Responds to 780610 ltr re change in spec for isotopes of U, other than U-235, in diffusion plant product Ltr classified w/o clear need  
CROW, W T Fuel Process & Fab Branch 79/04/04 1p

7907060500 Forwards revised safeguards contingency plan in response to 790228 ltr Plan withheld (ref 10CFR2.790)  
KIRK, W F United Nuclear Corp 79/05/18 2pp

7907260019 Discusses plans to install communication lines between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will forward operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907060206 Notification of 790606 meeting in Silver Spring, MD to discuss SNM accounting programs at Naval Products Div & Recovery Sys Div  
PARTLOW, J O Material Control Licensing Branch 79/05/25 2pp

7907180228 Conveys concern over certification & use of KAPL std in measurement control program  
PARTLOW, J O Material Control Licensing Branch 79/05/25 1p

7907190156 Expresses concern over certification & use of KAPL std in measurement control program Prior to performing analyses, appropriate tests must be conducted to demonstrate that biases are not introduced  
PARTLOW, J O Material Control & Accountability Development Branch. 79/05/25 1p

7907100664 Responds to 781011 ltr re amend fee for review of safeguards contingency plan Fee specified in 10CFR170 is due  
MILLER, W O License Fee Management Branch 79/05/29 2pp

7907240161 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

## DOCKET 70-0432 VIRGINIA, UNIV OF

7907100081 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/05/18 1p

## DOCKET 70-0462 FLORIDA, UNIV OF

7907100085 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/05/18 1p

## DOCKET 70-0572 MONSANTO RESEARCH CORP

7907050422 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/06/22 1p

## DOCKET 70-0698 WALTZ MILL SITE, WESTINGHOUSE ELECTRIC CORP.

7907240171 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director. 79/06/22 1p

## DOCKET 70-0734 GENERAL ATOMIC CO

7907110600 Forwards draft comprehensive evaluation rept consolidating observations of four teams that visited facility during Jul 1978. Draft withheld (ref 10CFR2.790).  
MCCORRLE, O W Physical Security Licensing Branch. 79/05/31 2pp.

# DOCKETED ITEMS

7907230597 Notifies of error in 790529 ltr which transmitted revision to Sections 1 O to 8 O of Amend MPP-1 to license Correct versions of Conditions 2 1 & 6 1 encl  
PARTLOW, J G Material Control & Accountability Development Branch 79/06/06 2pp

7907100454 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Apparatus." No action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/06/22 1p

7907050308 Forwards five revised pages to modified physical security plan for guard training & qualification plan Pages withheld (ref 10CFR2 790)  
MOWRY, W R General Atomic Co (subs of Gulf Oil Corp) 79/06/28 1p

7907180273 Forwards IE Insp Rept 70-0734/79-06 on 790416-20 & 0521-22 & notice of violation Insp rept & notice of violation withheld (ref 10CFR2 790)  
NORDERHAUO, L R Region 5, San Francisco, Safeguards Branch 79/07/06 2pp

## DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO.

7907090378 Submits revised pages to physical security plan reflecting changes previously submitted in ltr form includes several other minor changes Info withheld (ref 10CFR2 790)  
CUNNINGHAM, G E General Electric Co, Nuclear Energy Products Div 79/04/13 3pp

7907180771 Informs that GE will have resources required to decommission SNM-960 facilities at Vallecitos Nuclear Ctr  
BEATON, R H General Electric Co 79/05/14 1p

7907100661 Forwards comments re Security Guard Training & Qualification Plan Requests plan be revised to reflect comments Plan withheld (ref 10CFR2 790)  
MCCORKLE, G W Physical Security Licensing Branch 79/05/30 3pp

7907090134 Review of Revision 1 to safeguard contingency plan transmitted on 790405 Submission acceptable after minor mods incorporated Encl withheld (ref 10CFR2 790)  
MCCORKLE, G W Physical Security Licensing Branch 79/06/01 2pp

7907180243 Forwards IE Insp Rept 70-0754/79-06 on 790424-30 No noncompliance noted  
BODK, H E Region 3, San Francisco, Fuel Facility & Materials Safety Branch 79/06/01 2pp

--7907180261 IE Insp Rept 70-0754/79-06 on 790424-30 No noncompliance noted Major areas inspected organization, mods to facilities & sys, records control & storage & internal review & audit  
COBLEY, W J, BODK, H E Region 3, San Francisco, Fuel Facility & Materials Safety Branch 79/05/31 8pp

7907090093 Responds to 780616 & 790427 ltrs & forwards Revision 3 for Sections 1 O - 8 O of Amend MPP-2 to License SNM-960  
Revision withheld (ref 10CFR2 790)  
PARTLOW, J G Licensing Management Branch 79/06/06 2pp

7907130287 Orders each party to address ABLB in written memorandum re intervenor R Dellums Directs parties to discuss status of intervenor & whether case should be referred to DOJ  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/18 3pp

7907190631 Orders parties to respond to questions re intervention of Congressman Dellums & representation by Halterman & Snow  
Focus of questions standing & possible violation of federal criminal law  
LUTON, E Atomic Safety and Licensing Board Panel 79/06/18 3pp

7907100457 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Apparatus." No action required  
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/06/22 1p.

## DOCKET 70-0820 UNITED NUCLEAR CORP

7907200485 Forwards IE Insp Rept 70-0820/79-09 on 790402-04 No noncompliance noted  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/05/17 2pp

--7907200490 Summary IE Insp Rept 70-0828/79-09 on 790402-04 No noncompliance noted Major areas inspected nuclear matl control accounting in area of export verification Rept withheld (ref 10CFR2 790)  
BISSET, P, JOYNER, J H Region 1, Philadelphia, Safeguards Branch 79/05/16 3pp

7907060493 Forwards "Decommissioning Plan for United Nuclear Corp Recovery Sys, License SNM-777"  
BOWERS, C E United Nuclear Corp 79/05/18 1p

--7907060494 "Decommissioning Plan for United Nuclear Corp Recovery Sys License SNM-777"  
\* United Nuclear Corp 79/05/16 7pp

7907260315 Discusses plans to install communication lines between NRC & nuclear facilities for emergency use Direct lines from each facility to NRC headquarters & regional ofc will forward operational & environ info  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/22 2pp

7907060206 Notification of 790606 meeting in Silver Spring, MD to discuss SNM accounting programs at Naval Products Div & Recovery Sys Div  
PARTLOW, J G Material Control Licensing Branch 79/05/25 2pp

7907090045 Requests amend fee as specified in 10CFR170 31(1A), for amend to License SNM-777  
WEISS, D License Fee Management Branch 79/05/31 1p

7907180684 Ack receipt of 790521 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-07  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/06/12 1p

--7907180698 Responds to NRC 790510 ltr re violations noted in IE Insp Rept 70-0820/79-07 Corrective actions change line painted on loading dock, signs posted & personnel retrained in procedures for area  
BOWERS, C E United Nuclear Corp 79/05/21 2pp

--7907180709 Forwards IE Insp Rept 70-0820/79-07 on 790305-23 & notice of violation  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/05/10 2pp

--7907180720 Notice of violation from Insp on 790305-23  
\* Region 1, Philadelphia, Safeguards Branch 79/05/09 1p

--7907180734 IE Insp Rept 70-0820/79-07 on 790305-23 Noncompliance note failure to define contamination control & clean areas.  
SHAUB, E T, BISSETT, P H, JOYNER, J H Region 1, Philadelphia, Safeguards Branch 79/05/09 6pp

7907240165 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

## DOCKET 70-0824 BABCOCK & WILCOX CO

7907100071 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907020478 Ack receipt of 790521 ltr notifying NRC of organization change Requests payment of administrative amend fee  
WEISS, D License Fee Management Branch 79/06/20 1p

7907230405 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI." No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907240486 Forwards IE Info Notice 79-18, "Skylab Reentry." No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

## DOCKET 70-0893 FLORIDA INSTITUTE OF TECHNOLOGY

7907100110 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p.

## DOCKETED ITEMS

DOCKET 70-0925 CIMHARDON FACILITY, KERR-MCGEE CORP

7907110434 Forwards IE Insp Repts 70-0925/79-02 & 79-1193/79-02 on 790417-20 No noncompliance noted  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/10 2pp

--7907110439 IE Insp Repts 70-0925/79-02 & 70-1193/79-02 on 790417-20 No noncompliance noted Major areas inspected organization, facility changes & mods, internal audits & safety meetings, conduct of operations & emergency planning  
DUBRY, N E, HUETER, L J Region 3, Chicago, Office of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/09 9pp

7907050479 Notifies of NRC intent to install special telephones at all operating nuclear power plants & selected fuel facilities  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/22 2pp

7907050437 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/06/22 1p

DOCKET 70-0938 MASSACHUSETTS INSY OF TECHNOLOGY

7907230128 IE Insp Rept 70-0938/79-01 on 790313-15 Noncompliance noted failure to include SNM byproduct in 10CFR21 procedures & failure to post caution sign & failure to maintain records per 10CFR71.54  
ROTH, J Region 1, Philadelphia, Office of the Director CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/04/13 12pp

7907230089 Ack receipt of 790515 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0938/79-01  
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/18 1p

--7907230107 Responds to NRC 790420 ltr re violations noted in IE Insp Rept 70-0938/79-01 Corrective actions revised written procedure drafted re shipment of fissile matl  
CLARK, L Massachusetts Institute of Technology 79/05/15 2pp

--7907230113 Forwards IE Insp Rept 70-0938/79-01 on 790313-15 & notice of violation  
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/04/20 2pp

--7907230118 Notice of violation from insp on 790313-15  
\* Region 1, Philadelphia, Office of the Director 79/04/13 2pp

DOCKET 70-0959 NUCLEAR FUEL SERVICES, INC. (SUBS OF GETTY OIL CO.)

7907100233 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/18 2pp

DOCKET 70-0984 PACIFIC NORTHWEST LAB

7907100450 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Apparatus " No action required  
EMMELKEN, R H Region 3, San Francisco, Office of the Director 79/06/22 1p

DOCKET 70-0992 DAVID WITHERSPOON, INC

7907120118 Notifies that 790307 application for renewal of License SNM-952 has been accepted  
CROW, W T Fuel Process & Fab Branch 79/05/01 1p

DOCKET 70-1007 GENERAL ELECTRIC CO

7907100457 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Apparatus " No action required  
EMMELKEN, R H Region 3, San Francisco, Office of the Director 79/06/22 1p

DOCKET 70-1068 FLORIDA, UNIV OF

7907100085 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

7907020466 Ack receipt of 790423 amend application Expects to meet requested approval date of 790801  
CROW, W T Fuel Process & Fab Branch 79/05/22 1p

7907130005 Ack receipt of 790530 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1100/79-02  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/05/07 1p

--7907130026 Responds to NRC 790508 ltr re violations noted in IE Insp Rept 70-1100/79-02 Corrective actions operating personnel to schedule fuel arrivals so that matls will be dormant after arrival  
LICHTENBERGER, H C-E Power Systems 79/05/30 1p

--7907130031 Forwards IE Insp Rept 70-1100/79-02 on 790320-23 & notice of violation  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/05/08 2pp

--7907130035 Notice of violation from insp on 790320-23  
\* Region 1, Philadelphia, Safeguards Branch 79/05/07 1p

--7907130050 IE Insp Rept 70-1100/79-02 on 790320-23 Noncompliance noted Failure to follow written instructions for completing form  
NRC-741  
COHEN, I, WOLTER, E, JOYNER, J H Region 1, Philadelphia, Safeguards Branch 79/05/07 4pp

7907240142 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
GRIER, B H Region 1, Philadelphia, Office of the Director 79/06/22 1p

DOCKET 70-1113 GENERAL ELECTRIC CO

7907180797 Forwards latest revision of fundamental nuclear matl control plan & accompanying revisions to index pages NRC approval not required except for mod to Section 7, page C-15 info withheld (ref 10CFR2 790)  
KAPLAN, A L General Electric Co, Nuclear Energy Products Div 79/04/11 2pp

7907060463 Forwards Mine Safety Appliances 790412 ltr stating that full face masks & accompanying cannisters have been approved by NIOSH  
KAPLAN, A L General Electric Co 79/04/20 2pp

7907090365 Notice that License SNM-1097 is amended to include emergency plan by addition of Condition 13  
CROW, W T Fuel Process & Fab Branch 79/04/23 2pp

7907100735 Discusses 790228 review by GE of GE emergency plan, revised per 790404 & 19 ltrs Present GE review in response to 790228 telcon, includes possible accident effects described in GE 790131 environ rept NEDO-20197, Amend to license recommended.  
STEVENSON, R L Fuel Process, & Fab Branch 79/04/30 5pp

7907060211 Informs that resources necessary to satisfy obligation will be available at time of decommissioning of nuclear fuel mfg plant  
BEATON, R H General Electric Co 79/05/14 1p.

7907060404 Notifies of plan to transfer liquid hydrogen fluoride solutions containing U to GE, JT Baker Co, Conservation Chemicals Co & Allied Chemical Co  
KAPLAN, A L General Electric Co, Nuclear Energy Products Div 79/05/18 2pp.

7907100068 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907230718 Forwards Amend 9 to 780714 application Condition 19 amends license to include decommissioning plan & financial commitment Addl details of decommissioning plan are requested from util by 800701  
CROW, W T Fuel Process & Fab Branch 79/06/04 1p

7907100696 Discusses review of GE 790402 "Application Amend B-B for Physical Inventory of U Dioxide Pellets & Certain Containers of SNM " Physical inventory criteria are deficient; application is denied  
PARTLOW, J G Material Control Licensing Branch 79/06/05 1p

7907180723 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907200039 Ack receipt of 790618 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/79-12  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/06/27 1p

--7907200046 Responds to NRC 790514 ltr re violations noted in IE Insp Rept 70-1113/79-12 Corrective actions withheld (ref 10CFR2 790)  
KAPLAN, A L General Electric Co 79/06/18 1p

--7907200049 Forwards IE Insp Rept 70-1113/79-12 on 790409-12 Notice of violation withheld (ref 10CFR2 790)  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/06/14 2pp

--7907200054 IE Insp Rept 70-1113/79-12 on 790409-12 Noncompliance noted failure to calibr facility nitrate sys differential pressure transmitter within prescribed frequency Details withheld (ref 10CFR2 790)  
CLAY, E L, OILLESPIE, F P Region 2, Atlanta, Safeguards Branch  
BATES, J W Region 2, Atlanta, Office of the Director 79/06/11 1p

7907200059 Ack receipt of 790619 ltr informing NRC of steps taken to correct violations noted in IE Insp 70-1113/79-13  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/06/28 1p

--7907200064 Responds to NRC 790514 ltr re violations noted in IE Insp Rept 70-1113/79-13 Corrective actions withheld (ref 10CFR2 790).  
KAPLAN, A L General Electric Co 79/06/19 1p.

--7907200070 Forwards IE Insp Rept 70-1113/79-13 on 790423-25 Notice of violation withheld (ref 10CFR2 790)  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/06/14 2pp

--7907200074 Summary of IE Insp Rept 70-1113/79-13 on 790423-25 Noncompliance noted failure to make measurements of std twice weekly & failure to properly document scale & balance calibr Rept withheld (ref 10CFR2 790)  
BATES, J W, OILLESPIE, F P Region 2, Atlanta, Safeguards Branch  
CLAY, E L Region 2, Atlanta, Office of the Director. 79/06/11 1p

7907240492 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

#### DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

7907050068 Amend 16 to License SNM-1120 authorizing waiver of requirement that Pu fuels development lab manager have science or engineering degree.  
ROUSE, L C Fuel Reprocess & Recycle Branch 79/04/12 1p

7907060482 Requests amend to License SNM-1120 authorizing exemption from time period requirements of 10CFR70 58(1)(2) Payment encl  
DIPIAZZA, R P Westinghouse Electric Corp 79/05/07 8pp.

7907100702 Forwards info indicating locations & typical quantities of SNM which might be present in unencapsulated forms at plutonium fuels development lab info previously submitted on 780427 as proprietary  
DIPIAZZA, R P Westinghouse Electric Corp. 79/05/21 4pp

7907260021 Discusses plans to install communication lines between NRC & nuclear facilities for emergency use. Direct lines from each facility to NRC headquarters & regional ofc will forward operational & environ info  
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/05/22 2pp

7907240171 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/06/22 1p

#### DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

7907110605 Ack receipt of 790322 & 23 ltrs re lagoon waste fixation & disposal Agrees that proposed onsite activities are authorized by License SNM-1107  
CROW, W T Fuel Process & Fab Branch 79/04/04 1p

7907060393 Submits review plan re LEMUF model for approval  
FOSTER, H. Westinghouse Electric Corp 79/04/24 1p

7907060152 Submits addl info re Westinghouse request for delay in initiating certain portions of measurement control plan  
VOGEL, C E Westinghouse Electric Corp 79/05/01 2pp

7907100040 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907060199 Requests for interim relief from requirement of 10CFR70 58 (1)(2) limiting accumulation of scrap measured w/uncertainty greater than 10% Adds new License Condition 7 B to Amend 50-4 to License SNM-1107  
PARTLOW, J G Material Control Licensing Branch 79/05/25 2pp

7907090231 Ack request to withdraw revised fundamental nuclear matl control plan & combine plan w/other matl required by 10CFR79.51(g) & 10CFR70 58(1) at later date  
PARTLOW, J G Material Control Licensing Branch 79/06/08 1p

7907180515 Forwards check that was submitted w/o ltr for amend to License SNM-1107 Requests submittal of ltr w/fee  
WEISS, D License Fee Management Branch 79/06/14 1p

7907300060 Ack receipt of 790607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/79-06  
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/06/15 1p

--7907300062 Responds to NRC 790514 ltr re violations noted in IE Insp Rept 70-1151/79-06 Corrective actions withheld (ref 10CFR2 790)  
GOODWIN, W L, D'AMORE, M Westinghouse Electric Corp 79/06/07 1p

--7907300064 Forwards IE Insp Rept 70-1151/79-06 on 790424-27 Notice of violation withheld (ref 10CFR2 790)  
KENNA, W B Region 2, Atlanta, Safeguards Branch. 79/05/10 2pp

--7907300070 IE Insp Rept 70-1151/79-06 on 790424-27 Noncompliance noted failure to complete NRC-741 forms; reconcile statistically significant shipper-receiver differences & use 19 strand wire Details withheld (ref 10CFR2 790)  
JONES, D. W, TODD, Q A Region 2, Atlanta, Office of the Director  
OILLESPIE, F P. Region 2, Atlanta, Safeguards Branch 79/05/11 1p

7907240171 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22 1p

#### DOCKET 70-1193 CIMARRON FACILITY, HERR-MCGEE CORP

7907050042 Amends License SNM-1174 to authorize exception to License Conditions 21a & 21b allowing decontamination & dismantling of obsolete solvent extraction equipment  
ROUSE, L C Fuel Reprocess & Recycle Branch 79/03/09 2pp

7907060157 FOIA request for all documents re radiation levels in & surrounding plant  
ALLEE, S. United Press International 79/04/12 1p.

7907110434 Forwards IE Insp Repts 70-0925/79-02 & 79-1193/79-02 on 790417-20. No noncompliance noted.  
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/05/10 2pp.

--7907110438 IE Insp Repts 70-0925/79-02 & 70-1193/79-02 on 790417-20 No noncompliance noted. Major areas inspected organization, facility changes & mods, internal audits & safety meetings, conduct of operations & emergency planning  
DUBRY, N E, HUETER, L J Region 3, Chicago, Office of the Director  
Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/09 9pp

7907050479 Notifies of NRC intent to install special telephones at all operating nuclear power plants & selected fuel facilities  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 2pp

7907050437 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

7907060162 Responds to 790412 FOIA request for documents re radiation levels in & surrounding plant Forwards DES for mixed oxide fabricating plant, Logan County, OK  
FELTON, J M Division of Rules and Records 79/06/25 1p

--7907060165 DES for mixed oxide Fabrication plant in Logan County, OK  
Office of Nuclear Material Safety & Safeguards 79/01/16 125pp

#### DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO

7907060120 Forwards measurement control plan w/ revised Chapters 3 & 4 Plan withheld (ref 10CFR2 790)  
ZEFF, D W Babcock & Wilcox Co 79/04/27 2pp

7907100066 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907060410 Submits revised Amend Request 7B-4 & changes that would result upon approval  
ZEFF, D W Babcock & Wilcox Co 79/05/25 8pp

7907300243 Act receipt of NRC 790508 ltr re Shipping Container OA Manual Requests extension of due date to 790801  
ZEFF, D W Babcock & Wilcox Co 79/06/07 1p

7907180725 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/06/22 1p

7907240487 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required.  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/05 1p

#### DOCKET 70-1207 NAVY, DEPT OF

7907050077 Amend 2 to License BNM-1147 to change Item 2 re license name & address of facility  
GROW, W T Division of Fuel Cycle & Material Safety 79/04/13 1p

#### DOCKET 70-1220 GENERAL ELECTRIC CO

7907050436 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p

#### DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO., INC.

7907250044 Applies for license amend to increase possession limit to 4.4 kg U & change handling limit & work location.  
ESTEV, H. P. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 79/05/18 3pp.

60499 Forwards "Mixed Oxide & Specialty Fuels Plant Contingency XN-NP-488 " Plan withheld (ref 10CFR2 790).  
ON, R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 79/05/25

7907180894 Recommends endorsement of structural condition documentation & structural capacity evaluation of Exxon mixed oxide fuel fabrication plant in Richland, WA  
AYER, J E, BURKHARDT, W Fuel Reprocess & Recycle Branch 79/06/11 2pp

7907100460 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Apparatus " No action required  
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/06/22 1p

7907180282 Forwards IE Insp Rpt 70-1257/79-05 on 790430-0504 & notice of violation Insp rpt & notice of violation withheld (ref 10CFR 2 790)  
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 79/07/06 2pp

#### DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO

7907060160 Forwards revised pages of physical security plan Pages withheld (ref 10CFR2 790)  
DAWSON, D M General Electric Co, Nuclear Energy Products Div 79/04/16 1p

7907190670 Forwards 44FR24354, dtd 790425, re notice of GE application for renewal of License BNM-1267  
ROUSE, L C Fuel Reprocess & Recycle Branch 79/05/02 4pp

7907060223 Informs that resources necessary to satisfy obligation will be available at time of decommissioning of facility used for interim storage of spent fuel  
BEATON, R H General Electric Co 79/05/14 1p

7907190091 Completes response to 790404 ltr re decommissioning plan Forwards RH Beaton ltr re availability of funds for decommissioning  
DAWSON, D M General Electric Co, Nuclear Energy Products Div 79/05/16 1p

7907120449 Notice of appearance on behalf of GE  
SZWAJKOWSKI, R W Mayer, Brown & Platt 79/06/05 1p

--7907120458 Notice of appearance on behalf of GE  
ROONEY, M A Mayer, Brown & Platt 79/06/05 1p

--7907120465 Notice of appearance on behalf of GE Certificate of Evc  
encl  
HOFF, W B Mayer, Brown & Platt 79/06/05 2pp

7907020025 NRC answer in support of State of IL 790521 petition to intervene as interested state Urges denial of other portions of petition re participation of other individuals & demand for EIS  
BLACK, R L Branch 1 79/06/11 6pp

--7907020029 Notice of appearance on behalf of NRC Certificate of Evc  
encl  
BLACK, R L Branch 1 79/06/11 2pp.

7907190660 Response to BL & R Rorem, K Storey, E Quingley & Applesseed joint petition to intervene. Pertinent interest requirements satisfied except for Applesseed Specific aspects of proceeding reasonably identified  
BLACK, R L Branch 1 79/06/15 7pp

--7907190666 Notice of appearance on behalf of NRC Certificate of Evc  
encl.  
TREBY, S A Branch 2. 79/06/14 2pp

7907050436 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/22 1p.

#### DOCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL

7907050436 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus, " No action required.  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/22 1p.

## DOCKET 70-1319 U S NUCLEAR, INC

7907060203 Requests that records re defunct company not be destroyed prior to end of "discovery" period of policy which expires 881231  
WAITE, R T American Nuclear Insurers 79/05/14 1p

7907310157 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

## DOCKET 70-1375 TRANSNUCLEAR, INC

7907120316 Submits transportation security plan, per 10CFR70 20a During course of security shipment, vendor does not have physical possession of matl but is in position to control transport of formula quantities of strategic matl  
MANGUSI, J Transnuclear, Inc 79/08/21 1p

7907120112 Confirms conversation w/C Hillman re submittal of training programs for personnel utilized for 10CFR73-type shipments Training programs are in process of being written & will be submitted by 790702  
MANGUSI, J Transnuclear, Inc 79/05/24 1p

## DOCKET 70-1379 PARKWELL LABORATORIES, INC

7907110056 Forwards results of radiation measurements taken 790501-04 Results show facility requires addl decontamination  
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/06/05 10pp

## DOCKET 70-1401 VET ADMIN HOSP DA, TEXAS

7906130217 Forwards IE Circular 79-06, "Failure to Use Syringe & Bottle Shields in Nuclear Medicine "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/19 1p

## DOCKET 70-1406 VET ADMIN HOSP NO, LOUISIANA

7906130213 Forwards IE Circular 79-06, "Failure to Use Syringe & Bottle Shields in Nuclear Medicine "  
SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/19, 1p

## DOCKET 70-1432 RECYCLE FUELS PLANT, WESTINGHOUSE ELECTRIC CORP

7907100032 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/05/18 1p

7907240498 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/07/06 1p

## DOCKET 70-1489 GOODYEAR AEROSPACE CORP

7907050438 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus " No action required.  
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/06/22 1p

## DOCKET 70-1503 WESTINGHOUSE R&amp;D CENTER, WESTINGHOUSE ELECTRIC CORP

7907240171 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus." No action required  
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/06/22. 1p.

## DOCKET 70-1710 ST MARY'S HOSP. WA, CONNECTICUT

7906290180 Notice of violation from insp on 790215. Noncompliance noted: licensed matls not under surveillance & were stored in unlocked radioactive waste storage room. Failure to survey for contamination of objects before disposal of objects.  
\* Region 1, Philadelphia, Office of the Director. 79/03/19. 2pp

## DOCKET 70-1738 PACIFIC GAS &amp; ELECTRIC CO

7907270376 Forwards application for renewal of Licenses SNM-1503 & SNM-1667 No fee required  
CRANE, P A Pacific Gas & Electric Co 79/05/23 1p

--7907270382 Requests renewal of Licenses SNM-1503 & SNM-1667, extending expiration dates to 791031 & 800229 respectively  
SHACKELFORD, B W Pacific Gas & Electric Co 79/05/23 1p

## DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO

7907120112 Confirms conversation w/C Hillman re submittal of training programs for personnel utilized for 10CFR73-type shipments Training programs are in process of being written & will be submitted by 790702  
MANGUSI, J Transnuclear, Inc 79/05/24 1p

## DOCKET 70-2185 HILLCREST MEDICAL CENTER TU, OKLAHOMA

7906130219 Forwards IE Circular 79-06, "Failure to Use Syringe & Bottle Shields in Nuclear Medicine "  
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/19 1p

## DOCKET 70-2219 EXXON NUCLEAR CO, INC

7907100726 Discusses facts culminating w/790226 revised application, submitted in light of revised environ conditions Application reviewed & Exxon advised of NRC acquiescence to 790701 issuance of license per applicants request  
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 79/04/24 2pp

## DOCKET 70-2375 PACIFIC GAS &amp; ELECTRIC CO

7907270376 Forwards application for renewal of Licenses SNM-1503 & SNM-1667 No fee required  
CRANE, P A Pacific Gas & Electric Co 79/05/23 1p

--7907270382 Requests renewal of Licenses SNM-1503 & SNM-1667, extending expiration dates to 791031 & 800229 respectively  
SHACKELFORD, B W Pacific Gas & Electric Co 79/05/23 1p

## DOCKET 70-2443 TENNESSEE VALLEY AUTHORITY

7907050490 Grants Amend 5 to License SNM-1716 authorizing removal of 580 of 800 storage racks in spent fuel storage pool per util 790315 & 23 ltrs  
CROW, W T Division of Fuel Cycle & Material Safety 79/04/02 1p

--7907050493 Discusses 790315 & 23 applications to amend License SNM-1716 authorizing removal of 580 of 800 storage racks in spent fuel pool Recommends approval of amends requested by TVA  
DELANEY, J C Division of Fuel Cycle & Material Safety 79/04/02 2pp.

7907180480 Returns check which was submitted for 790529 application for renewal of License SNM-1476 License is exempt from fees  
WEISS, D License Fee Management Branch 79/06/13. 1p

## DOCKET 70-2560 OKLAHOMA OSTEOPATHIC HOSP TU, OKLAHOMA

7906130210 Forwards IE Circular 79-06, "Failure to Use Syringe & Bottle Shields in Nuclear Medicine "  
SEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/19 1p.

## DOCKET 70-2584 TRANSNUCLEAR, INC

7907050047 Forwards IE Insp Repts 70-2622/79-01 & 70-2584/79-01 on 790226-27. No noncompliance noted  
MARTIN, W Q Region 1, Philadelphia, Safeguards Branch 79/04/03 2pp

--7907050054 IE Insp Repts 70-2622/79-01 & 70-2584/79-01 on 790226-27. No noncompliance noted Major areas inspected, security measures re export shipment of SNM  
ROGERS, M, SMITH, Q Region 1, Philadelphia, Office of the Director  
DEVLIN, J Region 1, Philadelphia, Safeguards Branch. 79/04/03 App.

## DOCKET 70-2622 TRANSNUCLEAR, INC

7907050047 Forwards IE Insp Repts 70-2622/79-01 & 70-2584/79-01 on  
790226-27 No noncompliance noted  
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/04/03  
2pp

## DOCKET 70-2623 MCQUIRE SPENT FUEL POOL, DUKE POWER CO

7907250070 Transcript of 790619 hearing in Charlotte, NC Pp 167-381  
MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
Board Panel 79/06/19 215pp

7907250105 Transcript of 790623 hearing in Charlotte, NC Pp 1,212-1,401  
Testimonies of SB Hager, RH Jones, RH Carlson, JD Rollins & BJ  
Garrick encl  
MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
Board Panel 79/06/23 236pp

7907250146 Transcript of 790625 hearing in Charlotte, NC Pp 1,402-1,631  
Affidavits of CV Hodge & RD Glenn encl  
MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
Board Panel 79/06/25 372pp Available at NTIS

7907250081 Transcript of 790626 hearing in Charlotte, NC Pp 1,623-1,979  
Testimonies of CV Hodge, WH Lake, RD Glenn & L Lewis encl  
MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
Board Panel 79/06/26 372pp

7907250092 Transcript of 790627 hearing in Charlotte, NC Pp 1,980-2,371  
MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
Board Panel 79/06/27 392pp

7907250135 Transcript of 790628 hearing in Charlotte, NC Pp 2,372-2,729  
MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
Board Panel 79/06/28 358pp

7907250162 Transcript of 790629 hearing in Charlotte, NC Pp 2,730-2,886  
Testimony of LD Hamilton encl  
MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
Board Panel 79/06/29 170pp

7907060042 Requests complete physical protection plan, in support of  
790312 request for amend to License SNM-1773 re storage of  
spent fuel in plant "vital areas" Requests submittal  
within 30 days  
MCCORMACK, O W Physical Security Licensing Branch 79/04/20 1p

7907190058 Carolina Environ Study Group motion & memo for summary  
judgment Urges issuance of order requiring Duke Power to  
prepare EIS Requests postponement of hearing until  
submittal of statement Certificate of Svc encl  
BLUM, S Blum & Shelley 79/06/03 3pp

7907060222 Reply to applicant opposition to NRDC motion to compel  
response to admissions. Affidavit of RW Bastian never  
received by NRDC Applicant misread certain terms in NRDC  
petition for rulemaking  
ROISMAN, A Z Natural Resources Defense Council 79/05/08 1p

--7907060228 Motion to file reply in response to applicant opposition  
to NRDC motion to compel response to admissions Certificate  
of Svc encl  
ROISMAN, A Z Natural Resources Defense Council 79/05/08 4pp

7907190526 Forwards 790807 ltr re amend to License SNM-1773 for  
spent fuel transportation & storage.  
PORTER, W L Duke Power Co 79/05/08 1p

--7907190533 Submits pertinent output pages of probabilistic simulation  
production costing model used to determine change in  
production costs caused by operating plant at half capacity.  
Also requests note of explanation  
PARKER, W D Duke Power Co 79/05/07 17pp.

7907300090 Forwards util 790503 ltr objecting to Discovery Request 120  
MCGARRY, J M Debevoise & Lieberman 79/05/11 1p

--7907300109 Objects to Question 120 of 790416 discovery request. Question  
is beyond scope of interrogatories. Forwards most recent  
annual rept & FERC Form 1 W/o encl  
PORTER, W L Duke Power Co. 79/05/03 1p.

7907100684 Affidavit discussing preparation of NRC Dec 1978 "EIA  
Related to Spent Fuel Storage of Oconee Spent Fuel at  
McQuire Unit 1 Spent Fuel Pool," & affidavit supporting NRC  
790511 motions for summary disposition  
GLENN, R. D. Battelle Memorial Institute, Pacific Northwest  
Laboratory. 79/05/14 2pp

7907310259 Forwards supplemental affidavit of RD Glenn, referenced in  
NRC 790511 ltr to ASLB  
HOEFLING, R K Branch 4 79/05/18 1p

7907060019 Forwards NRDC 790521 motion for summary disposition  
W/supporting memo, statement of fact, affidavits of AR  
Templin, TB Cochran & D Rotow & 790518 statement re  
safeguards for spent fuel shipment  
ROISMAN, A Z Natural Resources Defense Council 79/05/21 1p

--7907060024 Motion for summary disposition, requesting postponement of  
evidentiary proceedings until analysis of proposed action  
is completed re full environ, health & safety consequences  
Past analysis does not cover all aspects  
ROISMAN, A Z Natural Resources Defense Council 79/05/21 1p

--7907060028 Memo in support of 790521 motion for summary disposition NRDC  
should be required to prepare analysis of cascade plan &  
alternatives per NEPA & 10CFR20.1c Supporting documentation  
& affidavits of AR Templin, TB Cochran & D Rotow encl  
ROISMAN, A Z Natural Resources Defense Council 79/05/21 110pp

--7907060033 NRDC statement of facts as to which there is no dispute  
ROISMAN, A Z Natural Resources Defense Council 79/05/21 2pp

--7907060037 Statement on behalf of NRDC re safeguards for spent fuel  
shipments Certificate of Svc encl  
COCHRAN, T B Natural Resources Defense Council 79/05/18 3pp

7907060058 Duke Power motion for summary disposition re Carolina  
Environ Study Group Forwards supporting statement of matl  
facts as to which there is no genuine issue to be heard &  
memo in support of motion  
MCGARRY, J M Duke Power Co 79/05/21 1p

--7907060063 Duke Power statement of matl facts as to which there is no  
genuine issue to be heard re intervenor Carolina Environ  
Study Group contentions relating to Oconee storage &  
shipment of spent fuel  
MCGARRY, J M Duke Power Co 79/05/21 5pp

--7907060065 Duke Power memo in support of 790521 motion for summary  
disposition re intervenor Carolina Environ Study Group  
contentions which should be dismissed for absence of issue  
of law or matl fact W/Certificate of Svc  
MCGARRY, J M Duke Power Co. 79/05/21 20pp

7907130088 Motion for summary disposition re matters set forth in util  
statement of matl facts as to which there is no genuine  
issue to be heard  
MCGARRY, J. M Duke Power Co 79/05/21 1p

--7907130094 Statement of matl facts as to which there is no genuine  
issue to be heard re intervenor NRDC 790520 request for  
deferral of all actions involving handling of spent fuel,  
until generic reviews completed  
MCGARRY, J M. Duke Power Co 79/05/21 8pp

--7907130098 Memo in support of motion for summary disposition Requests  
dismissal of all contentions of intervenor NRDC Intervenor  
does not present genuine issues or matl fact suitable for  
resolution Certificate of Svc encl  
MCGARRY, J M. Duke Power Co. 79/05/21 37pp

7907160216 Motion for summary disposition of matters set forth in util  
statement of matl facts as to which there is no genuine  
issue to be heard & memo in support of motion  
MCGARRY, J M Duke Power Co 79/05/01 1p

--7907160220 Statement of matl facts as to which there is no genuine  
issue to be heard, re intervenor Davidson College Chapter of  
NC PIRO.  
MCGARRY, J. M Duke Power Co 79/05/21 2pp.

--7907160223 Memorandum in support of util motion for summary disposition  
re Davidson College Chapter of NC PIRO contention.  
Certificate of Svc encl  
MCGARRY, J M Duke Power Co 79/05/21. 11pp

7907160232 Motion for summary disposition as set forth in util  
statement of matl facts as to which there is no genuine  
issue to be heard, re intervenor Carolina Action  
MCGARRY, J M Duke Power Co 79/05/21 1p

--7907160235 Statement of matl facts as to which there is no  
genuine issue to be heard, re intervenor Carolina Action  
Contention 4.  
MCGARRY, J. M Duke Power Co 79/05/21 4pp



- 7907160238 Memorandum in support of util motion for summary disposition re status of intervenor Carolina Action Intervenor should be dismissed from proceeding due to Failure to present justiciable issues  
MCGARRY, J M Duke Power Co 79/05/21 25pp
- 7907020008 NRC opposition to NRDC 790502 motion for summary disposition re NRDC Contention 4 Urges denial of NRDC request to delay proceeding until radiation exposure test is completed Certificate of Svc encl  
KETCHEN, E Q Branch 4 79/05/29 10pp
- 7907130023 Forwards SECY-79-27BA dtd 790507 & SECY-79-27B dtd 790418; in response to RP Wilson telcon W/o encl  
KETCHEN, E Q Branch 4 79/05/29 1p
- 7907130042 Util opposition to NRDC 790521 motion for summary disposition of Contention 4 addressing ALARA concept Contention should be dismissed for Failure to present issue of law or matl fact Certificate of Svc encl  
MCGARRY, J M Duke Power Co 79/05/29 17pp
- 7907110109 Forwards corrected pages 6,8 & 11 of NRDC 790521 motion for summary disposition Requests parties to insert pages in proper places  
ROISHMAN, A Z Natural Resources Defense Council 79/05/31 4pp
- 7907110119 NRDC discovery request addressed to NRC re affidavits filed in support of NRC motion for summary disposition  
ROISHMAN, A Z Natural Resources Defense Council 79/05/31 1p
- 7907110134 NRDC motion requesting NRC to answer attached discovery request Certificate of Svc & affidavits encl  
ROISHMAN, A Z Natural Resources Defense Council 79/05/31 56pp
- 7907110243 Forwards NRDC 790601 motion for suspension of hearing schedule  
ROISHMAN, A Z Natural Resources Defense Council 79/06/01 1p
- 7907110265 NRDC motion for suspension of hearing schedule for absence of sound analysis on key issues  
ROISHMAN, A Z Natural Resources Defense Council 79/06/01 8pp
- 7907110297 Advises of near future intention to publish EIS on interim storage of spent nuclear fuel Urges NRC to take necessary action in order to produce final generic environ statement on same matter Certificate of Svc encl  
ROISHMAN, A Z Natural Resources Defense Council 79/06/01 4pp
- 7907130223 Testimony of RH Jones No technical or institutional reasons exist re viewing of spent fuel shipping as acceptable activity  
JONES, R H Duke Power Co 79/06/04 15pp
- 7907130237 Testimony of LD Hamilton Overall health effects from any of options are very small, both in terms of total risk & risk to individuals  
HAMILTON, L D Brookhaven National Laboratory 79/06/04 13pp
- 7907130242 Testimony of BJ Garrick Risk to public from shipment of spent nuclear fuel is extremely small, both in terms of likelihood of release of radioactive matl  
GARRICK, B J Affiliation Unknown 79/06/04 11pp
- 7907130244 Testimony of JM Elliott Transfer of spent fuel can be executed w/negligible risk to public health & safety  
ELLIOTT, J M Affiliation Unknown 79/06/06 19pp
- 7907130252 Testimony of L Lewis Shipping & storage of spent fuel is best alternative in terms of economic value & radiation dose rates  
LEWIS, L Duke Power Co 79/06/04 7pp
- 7907130257 Testimony of BB Hager Shipping & storage of spent fuel is best alternative in terms of economic & scheduling data  
HAGER, B B Duke Power Co 79/06/04 5pp
- 7907130264 Testimony of DH Sterrett Cost of increased purchases of power due to shutdown is speculative Cost of transporting fuel to maintain full core discharge capability is insignificant when compared w/alternative of shutdown.  
STERRETT, D H Duke Power Co 79/06/04 5pp.
- 7907130273 Testimony of RW Bostian Economic comparison of alternatives indicates that mod of existing pools is not preferable to proposed shipment  
BOSTIAN, R W Duke Power Co 79/06/04 14pp.
- 7907250475 Submits info re affiliations w/prof organisations  
ROTOW, D Natural Resources Defense Council 79/06/04 1p
- 7907250480 Deposition in form of affidavit re spent fuel storage Forwards NRDC Jul 1978 study re analysis of space available for spent fuel storage at existing operating reactor sites  
COCHRAN, T B Natural Resources Defense Council 79/05/25 24pp
- 7907250485 Deposition in form of affidavit re storage capacity, trans-shipment schedule, fuel assembly discharge & other related matters  
TAMPLIN, A R Natural Resources Defense Council 79/05/25 8pp
- 7907250491 Deposition in form of affidavit Attests to accuracy of conversation w/MS Fairtile on page 5 of NRDC response to NRC motion for summary disposition Adds statement re harm of small doses of radiation  
TAMPLIN, A R Natural Resources Defense Council 79/06/04 1p
- 7907250497 Deposition in form of affidavit re absence of definite strategy for nuclear waste mgt in US Prof qualifications encl  
TAMPLIN, A R, COCHRAN, T B. Natural Resources Defense Council 79/05/25 19pp
- 7907250507 Deposition in form of affidavit re Carter administration 1977 policy of accepting private utils spent fuel storage & other related matters Prof qualifications & supporting documentation encl  
TOTOW, D Natural Resources Defense Council 79/05/21 46pp
- 7907250519 Forwards depositions in form of affidavits re prefled direct testimony relating to NRDC 790501 & 21 motions for summary disposition  
ROISHMAN, A Z Natural Resources Defense Council 79/06/04 2pp
- 7907160280 Requests denial of NRC motion for summary dismissal Presents arguments for retention of Contentions 1-5 Party is not obliged to present evidentiary case in advance of hearing Supporting documentation encl  
ROISHMAN, A Z Natural Resources Defense Council 79/06/03 17pp
- 7907160287 Disputes data presented by NRC as facts in NRC motion for summary disposition Affidavit of AR Tamplin & documentation encl  
ROISHMAN, A Z Natural Resources Defense Council 79/06/04 57pp
- 7907160301 Notifies of change in potential hazards from release of spent fuel after 5-year delay Potential hazard is 1/3 to 1/2 of hazard from 120-day old spent fuel  
MATTSSEN, C R Fuel Process Systems Standards Branch 78/12/06 9pp
- 7907190065 Requests extension of time until 790607 & 11 to file responses to NRC 790511 summary disposition & to applicant motion for summary disposition re Carolina Environ Study Group Contentions 1,2 & 3  
RILEY, L L Carolina Environmental Study Group 79/06/03 1p
- 7907180762 Carolina Environ Study Group response to NRC 790511 motion for summary disposition Response presented in form of testimony, Supporting documentation encl  
RILEY, J L Carolina Environmental Study Group 79/06/07 17pp
- 7907020019 Duke Power opposition to NRDC 790521 motion for summary disposition & to NRDC 790601 motion for suspension of hearing schedule Affidavits & Certificate of Svc encl  
MCGARRY, J M Duke Power Co 79/06/08 27pp
- 7907190593 Carolina Environ Study Group response in form of testimony to Duke Power 790521 motion for summary disposition  
RILEY, J L Carolina Environmental Study Group 79/06/11 8pp
- 7907190622 Forwards RW Bostian 790612 signed affidavit per Duke Power 790611 response to NRDC motion for suspension of hearing schedule & per Duke Power 790611 response to NRDC 790521 motion for summary disposition.  
PORTER, W L Duke Power Co 79/06/12 1p
- 7907190673 Notice of appearance on behalf of NRC Certificate of Svc encl  
TOURTELLOTTE, J Branch 4 79/06/13 3pp
- 7907190625 NRDC opposition to Duke Power motion for summary disposition re intervenor NRDC  
ROISHMAN, A Z Natural Resources Defense Council 79/06/15 11pp
- 7907190638 NRDC statement of dispute w/Duke Power 790521 statement of facts, Certificate of Svc encl.  
ROISHMAN, A Z Natural Resources Defense Council 79/06/15 5pp

7907190723 NRC opposition to NRDC motion for suspension of hearing  
 schedule Certificate of SVC encl  
 KETCHEN, E G Branch 4 79/06/15 17pp

7907130217 Submits prefiled testimony of RW Bostian, PH Sterrett, LD  
 Hamilton, RH Jones, SB Hager, L Lewis, DJ Gerrick, JD Rollins &  
 JM Elliott  
 MCQARRY, J M Debevoise & Lieberman 79/06/04 1p

--7907130232 Testimony of JD Rollins Previous operations w/casks have not  
 resulted in overexposure to radiation to workers or public  
 ROLLINS, J D Nuclear Assurance Corp 79/06/04 12pp

7907030251 Transcript of 790620 hearing in Charlotte, NC Pp 382-692  
 Testimony of L Lewis, SB Hager, RW Bostian & DH Sterrett encl  
 MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
 Board Panel 79/06/20 341pp

7907030189 Transcript of 790621 hearing in Charlotte, NC Pp 693-949  
 MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
 Board Panel 79/06/21 257pp

7907120121 Transcript of 790622 hearing in Charlotte, NC Pp 950-1,211  
 MILLER, M E, LUEBKE, E A, HAND, C H Atomic Safety and Licensing  
 Board Panel 79/06/22 261pp

#### DOCKET 70-2662 MONBANTO CO

7907050054 IE Insp Repts 70-2622/79-01 & 70-2584/79-01 on 790226-27. No  
 noncompliance noted Major Areas inspected security measures  
 re export shipment of ENM  
 ROEBIG, M, SMITH, G Region 1, Philadelphia, Office of the  
 Director DEVLIN, J Region 1, Philadelphia, Safeguards Branch  
 79/04/03 4pp

#### DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO

7907100692 Amends License SNM-1823, per 780308 application, Amend  
 authorizes receipt, possession, insp & storage of enriched U  
 CROW, W T Radioisotopes Licensing Branch (Pre 790501) 79/05/03  
 1p

--7907100717 Discusses 790412 license amend application requesting  
 revision re types & capacities of fuel handling cranes to  
 be used re receipt & storage of fuel assemblies Recommends  
 approval  
 CROW, W T Fuel Process & Fab. Branch. 79/05/03 1p

#### DOCKET 70-2882 SOUTHERN CALIFORNIA EDISON CO

7907310488 Corrects info submitted to Board on 790306 re issuance of  
 SNM license for new fuel to be used at site Subsequently  
 informed that License SNM-1844 was already issued.  
 CHANDLER, L J Branch 1 79/05/16 1p

--7907310526 License authorizing receipt, possession & storage of up to  
 20 g U-235 contained in fission chambers for eventual use in  
 reactors  
 CROW, W T Division of Fuel Cycle & Material Safety 79/01/02  
 1p

#### DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP. POWER SYSTEMS

7907190063 FOIA request for info re proposed Westinghouse nuclear fuel  
 assembly plant in Prattville, AL & correspondence from  
 Southern Interstate Energy Board to NRC concerning Southern  
 Co & subsidiaries  
 DAKES, D L Affiliation Unknown 79/04/23 2pp.

7907020483 Confirms 790531 meeting to review licensing actions re  
 proposed const of low enriched fuel fabrication facilities  
 in Autauga County, AL  
 BATSON, D M Westinghouse Electric Corp 79/05/15 1p

7907190056 Responds to FOIA request for documents re proposed  
 Westinghouse nuclear fuel assembly plant in Prattville, AL &  
 certain Southern Interstate Energy Board correspondence  
 re proposed Westinghouse 790515 ltr. w/o encl.  
 FELTON, J M Division of Rules and Records 79/06/29 2pp

## PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

#### DOCKET 71-0003 EXXON NUCLEAR CO, INC

7907190572 Submits Revision 1A to XN-NF-439 "QA Program for Nuclear  
 Fuels Dept Shipping Containers" Satisfies request that  
 currently approved version of XN-NF1A, Revision 2, be ref in  
 body of document  
 NILSON, R Exxon Nuclear Co, Inc (subs of Exxon Corp) 79/05/22  
 1p

--7907190577 Revision 1A to XN-NF-439 "QA Program for Nuclear Fuels Dept  
 Shipping Containers"  
 DAVIS, L L Exxon Nuclear Co, Inc. (subs of Exxon Corp)  
 XN-NF-439 79/05/24 7pp

7907250244 Forwards QA program approval for radioactive matl package  
 MACDONALD, C E Transportation Branch 79/06/13 1p

--7907250246 QA program approval for radioactive matl package 0003,  
 Revision 0  
 MACDONALD, C E Transportation Branch 79/06/13 1p

#### DOCKET 71-0005 MAGNAFLUX CORP

7907060113 Requests addl info re QA program w/acceptance criteria to  
 evaluate QA program for transportation packages for  
 normal/special form of radioactive matl  
 MACDONALD, C E Transportation Branch 79/05/30 12pp

#### DOCKET 71-0009 ISOMEDIX, INC

7907130080 Forwards request for addl info to complete review of QA  
 program  
 MACDONALD, C E Transportation Branch 79/06/01 12pp

#### DOCKET 71-0011 ARROW TANK & ENGINEERING CO

7907230622 Forwards QA program approval for radioactive matl package  
 MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230630 QA program approval for radioactive matl package 0011,  
 Revision 0  
 MACDONALD, C E Transportation Branch. 79/06/11 1p

#### DOCKET 71-0015 CHICAGO BRIDGE & IRON CO

7907240009 Forwards QA program approval for radioactive matl package  
 MACDONALD, C E Transportation Branch 79/06/29 1p

--7907240014 QA program approval for radioactive matl package 0015,  
 Revision 0  
 MACDONALD, C E Transportation Branch 79/06/29 1p.

#### DOCKET 71-0022 NEWPORT NEWS INDUSTRIAL CORP.

7907280027 Forwards QA program approval for radioactive matl package  
 MACDONALD, C E Transportation Branch 79/06/29 1p

--7907280029 QA program approval for radioactive matl package 0022,  
 Revision 0  
 MACDONALD, C E Transportation Branch 79/06/29 1p

#### DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP.

7907270396 Requests extension to 790706 for submittal of revised QA  
 program  
 ROWE, B S Hittman Nuclear & Development Corp (subs of Hittman  
 Corp.) 79/06/18 1p

#### DOCKET 71-0028 BORG-WARNER CORP.

7907230214 Forwards QA program approval for radioactive matl package.  
 MACDONALD, C E Transportation Branch. 79/06/11 1p

# DOCKETED ITEMS

319

--7907230225 GA program approval for radioactive matl package 0028,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230283 GA program approval for radioactive matl package 0047,  
Revisions 0  
MACDONALD, C E Transportation Branch 79/06/11 1p.

## DOCKET 71-0031 MARYLAND SHIPBUILDING & DRY DOCK CO

## DOCKET 71-0051 HARRISON STEEL CASTINGS CO

7907190017 Forwards rept, "49NDT15 Administrative, Operating & Emergency  
Instructions to QC Personnel for Handling of Iridium 192  
Radioisotope"  
CARTER, W K Maryland Shipbuilding & Drydock Co 79/05/30 1p

7907230258 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907190021 "49NDT15 Administrative, Operating & Emergency Instructions  
to QC Personnel for Handling of Ir-192 Radioisotope"  
CARTER, W K Maryland Shipbuilding & Drydock Co 79/05/23 25pp

--7907230267 GA program approval for radioactive matl package 0051,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

7907230595 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0054 OKLAHOMA TESTING LABORATORIES

7907160228 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/06/01 12pp

## DOCKET 71-0032 PANHANDLE EASTERN PIPE LINE CO

## DOCKET 71-0055 H R INSPECTION SERVICE

7907230655 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

7907230662 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230658 GA program approval for radioactive matl package 0032,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230664 GA program approval for radioactive matl package 0055,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0034 BABCOCK & WILCOX CO

## DOCKET 71-0057 EXXON CO USA, EXXON CORP

7907230634 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

7907230673 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230639 GA program approval for radioactive matl package 0034,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230680 GA program approval for radioactive matl package 0057,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0037 NAVY, DEPT OF

## DOCKET 71-0059 GENERAL ELECTRIC CO

7907180457 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

7907230293 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907180459 GA program approval for radioactive matl package 0037,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230300 GA program approval for radioactive matl package 0059,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0039 WALWORTH CO

## DOCKET 71-0061 NAVY, DEPT OF

7907180735 Forwards organization chart as part of 790510 GA program  
STEPHEN, W R Walworth Co (subs of IU International Corp.)  
79/05/21 2pp

7907180448 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/12 1p

7907260350 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907180452 GA program approval for radioactive matl package 0061,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/12 1p.

--7907260355 GA program approval for radioactive matl package 0039,  
Revision 0  
MACDONALD, C E Transportation Branch. 79/05/21 1p

## DOCKET 71-0066 CERTIFIED TESTING LABS, INC

## DOCKET 71-0040 TECHNICAL OPERATIONS, INC.

7907060009 Forwards revised GA program for industrial radiography per  
790427 request  
PLUMSTEAD, R.F. Certified Testing Laboratories, Inc 79/05/04 1p.

7907110469 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/06/06 3pp

--7907060011 Revised GA program for industrial radiography  
\* Certified Testing Laboratories, Inc 79/05/04 3pp

## DOCKET 71-0046 TELEDYNE ENERGY SYSTEMS

## DOCKET 71-0067 MEDI-PHYSICS, INC

7907130063 Forwards request for addl info to complete review of GA  
program.  
MACDONALD, C E Transportation Branch 79/06/06 3pp

7907130083 Forwards request for addl info to complete review of GA  
program.  
MACDONALD, C E Transportation Branch 79/06/01 12pp

## DOCKET 71-0047 CAPITOL INTERNATIONAL AWAY, INC

## DOCKET 71-0074 NUCLEAR WELDING, INC

7907230278 Forwards GA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch. 79/06/11. 1p.

7907260341 Forwards GA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/29 1p.

## DOCKETED ITEMS

--7907240346 GA program approval for radioactive matl package 0074,  
Revision 0  
MACDONALD, C E Transportation Branch 79/05/07 1p

## DOCKET 71-0075 NORFOLK SHIPBUILDING &amp; DRY DOCK CO

7907240584 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240590 GA program approval for radioactive matl package 0075,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0076 BABCOCK &amp; WILCOX CO

7907240593 Forwards GA program approval for radioactive matl package,  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240601 GA program approval for radioactive matl package 0076,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0077 MIDSTATE TESTING LAB

7907240647 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240636 GA program approval for radioactive matl package 0077,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0079 BABCOCK &amp; WILCOX CO

7907230391 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0080 TRANSWORLD AIRLINES, INC

7907230007 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230009 GA program approval for radioactive matl package 0080,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0087 NAVY, DEPT OF

7907050513 Forwards GA program for industrial radiography per 790420  
request  
KERRIGAN, R J Navy, Dept of 79/05/17 1p

--7907050519 GA program for industrial radiography.  
KERRIGAN, R J Navy, Dept of 79/05/17 3pp

7907180453 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/12 1p

--7907180454 GA program approval for radioactive matl package 0087,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/12 1p

## DOCKET 71-0089 NAVY, DEPT. OF

7907240465 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907240467 GA program approval for radioactive matl package 0089,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/16 1p

## DOCKET 71-0095 UNITED STATES TESTING CO., INC

7190279 Forwards GA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/11 1p

7190286 GA program approval for radioactive matl package 0095,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0096 PAN AMERICAN WORLD AIRWAYS

7907180732 Requests 180-day extension for submittal of revised  
application describing GA program Request is result of  
impending changes to airline status as licensee  
BUNN, N M Pan American World Airways, Inc 79/05/15 2pp

7907110419 Grants request for 180-day extension for submittal of  
revised GA program description  
MACDONALD, C E Transportation Branch 79/06/01 1p

## DOCKET 71-0099 FOSTER WHEELER ENERGY CORP

7907110709 Responds to 790504 ltr re GA program Requests addl info  
outlining senior radiographer responsibility in areas re  
radiography packages  
MACDONALD, C E Transportation Branch 79/05/23 1p

7907300487 Forwards revised GA program  
KAVACB, F B Foster Wheeler Corp 79/05/30 1p

--7907300490 GA program, Revision 2, for License 29-03369-03  
KOVACB, B Foster Wheeler Corp 79/05/30 8pp

## DOCKET 71-0102 SOURCE PROD &amp; EQUIP CO, INC

7907020488 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/06/06 2pp

7907180743 Submits acceptance criteria for transportation packages  
MACDONALD, C E Transportation Branch 79/06/12 12pp

## DOCKET 71-0103 TWIN CITY TESTING &amp; ENGR LAB

7907230787 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230792 GA program approval for radioactive matl package 0103,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0104 CHICAGO BRIDGE &amp; IRON CO

7907230786 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230789 GA program approval for radioactive matl package 0104,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0105 UNIVERSAL TESTING LABORATORIES

7907230776 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230782 GA program approval for radioactive matl package 0105,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0110 BUCKEYE STEEL CASTINGS

7907240499 Forwards GA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240508 GA program approval for radioactive matl package 0110,  
Revision 0  
MACDONALD, C E Transportation Branch 79/04/27 1p

## DOCKET 71-0113 NOOTER CORP

7907230037 Forwards GA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230049 GA program approval for radioactive matl package 0113,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

# DOCKETED ITEMS

3

## DOCKET 71-0116 NAVY, DEPT OF

7907050499 Requests 60-day extension to cover completion of proposed GA program & interim period which may occur during program review  
BLOCK, L K Navy, Dept of 79/05/23 1p

7907110288 Grants request for 60-day extension re submittal of revised GA program  
MACDONALD, C E Transportation Branch 79/06/05 1p

## DOCKET 71-0119 INGERSOLL-RAND CO

7907240537 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240545 GA program approval for radioactive matl package 0119,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0120 DANIEL INTERNATIONAL CORP

7907230028 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230033 GA program approval for radioactive matl package 0120,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0121 NEUTRON PRODUCTS, INC

7907050238 Responds to NRC 790427 ltr requesting addl info re evaluation of GA program Proposes to prepare overall GA plan which will cover transportation packages for both normal & special form radioactive matl & source fabrication  
KREYBA, F J Neutron Products, Inc 79/06/06 1p

## DOCKET 71-0123 HERRON TESTING LABS, INC

7907230034 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230069 GA program approval for radioactive matl package 0123,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0127 NATIONAL ANNEALING BOX CO

7907240107 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240110 GA program approval for radioactive matl package 0127,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0128 AMOCO OIL CO

7907050167 Forwards GA program as required by 10CFR71.51. Mgt of Amoco Oil Co establishes & implements program Radiation Safety Ofc is responsible for administration of program training & certification, document control & auditing  
NORGAARD, J A Amoco Oil Co (subs of Standard Oil Co of Indiana) 79/05/23 3pp

## DOCKET 71-0130 CHICAGO BRIDGE & IRON CO

7907020324 Forwards GA program for License 37-12156-01.  
PLATE, C. Chicago Bridge & Iron Co 79/05/16 1p

--7907020326 GA program for License 37-12156-01  
\* Chicago Bridge & Iron Co. 79/05/16 3pp.

7907240577 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240580 GA program approval for radioactive matl package 0130,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0132 ADVANCED RADIATION SERVICE

7907240553 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240561 GA program approval for radioactive matl package 0132,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0133 NAVY, DEPT OF

7907260446 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907260454 GA program approval for radioactive matl package 0133,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/27 1p

## DOCKET 71-0134 LABARGE, INC

7907240566 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240571 GA program approval for radioactive matl package 0134,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0136 PARKER IND X-RAY LAB CORP

7907250359 Forwards request for addl info to complete review of GA program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0137 METALB TESTING CO, INC

7907250423 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907250426 GA program approval for radioactive matl package 0137,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0140 WALWORTH CO

7907240524 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907240531 GA program approval for radioactive matl package 0140,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p.

## DOCKET 71-0145 THAYER INSPECTION SERVICE, INC

7907230237 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230248 GA program approval for radioactive matl package 0145,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKET 71-0148 UNITED ENGINEERS & CONSTRUCTION, INC

7907240513 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p.

--7907240522 GA program approval for radioactive matl package 0148,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/28 1p.

## DOCKET 71-0150 PEARODY TESTING SERVICES

7907230643 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/11 1p

--7907230653 GA program approval for radioactive matl package 0150,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/11 1p

## DOCKETED ITEMS

## DOCKET 71-0151 HESS OIL VIRGIN ISLANDS CORP

7907260432 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907260439 QA program approval for radioactive matl package 0151,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0152 VIRGINIA DEPT OF HIGHWAYS &amp; TRANSPORTATION

7907260401 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907260411 QA program approval for radioactive matl package 0152,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0153 ANCHOR-DARLING VALVE CO

7907240228 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907240236 QA program approval for radioactive matl package 0153,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p..

## DOCKET 71-0154 GENERAL DYNAMICS

7907260421 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907260428 QA program approval for radioactive matl package 0154,  
Revision 0  
MACDONALD, C E Transportation Branch 79/05/09 1p.

## DOCKET 71-0156 INDUSTRIAL FABRICATING CO

7907050447 Forwards QA program per 790427 request  
BOZARTH, B Industrial Fabricating 79/05/16 1p

--7907050452 QA program  
\* Industrial Fabricating 79/05/16 3pp

7907260379 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907260386 QA program approval for radioactive matl package 0156,  
Revision 0  
MACDONALD, C E Transportation Branch 79/05/16 1p

## DOCKET 71-0157 FRIEHLING &amp; ROBERTSON, INC

7907260370 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907260373 QA program approval for radioactive matl package 0157,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/28 1p

## DOCKET 71-0161 CURTIS-WRIGHT CORP

750019 Forwards QA program approval for radioactive matl package.  
DONALD, C E Transportation Branch 79/06/29 1p

750023 QA program approval for radioactive matl package 0161,  
Revision 0  
DONALD, C E Transportation Branch 79/06/29 1p.

## 71-0162 EBASCO SERVICES, INC

72 Forwards QA program approval for radioactive matl package  
LD, C E Transportation Branch 79/06/29 1p

8 QA program approval for radioactive matl package 0162,  
Revision 0  
LD, C E Transportation Branch 79/06/29 1p.

## DOCKET 71-0163 CLARK INSP SERVICE, INC

7907250368 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0166 NEW YORK TESTING LABS, INC

7907180740 Forwards organization chart requested 790413  
HUFF, E M New York Testing Laboratories, Inc 79/05/15 2pp

7907240042 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907240044 QA program approval for radioactive matl package 0166,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0168 QUALITY ASSURANCE LABS

7907020459 Requests correction of terminology re emergency & operating  
procedures in June 1978 application  
SHIPLETT, J J, TRAUTVETTER, C Trautvetter Corp 79/05/21 1p

7907240046 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907240049 QA program approval for radioactive matl package 0168,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0175 GC SERVICES, INC

7907020460 Forwards QA program for License 04-14875-01  
HUDDLESTON, E W G C Services, Inc 79/05/18 1p

--7907020462 QA program for License 04-14875-01  
HUDDLESTON, E W G C Services, Inc 79/05/18 5pp

## DOCKET 71-0177 FEDERAL AVIATION ADMIN

7907250374 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0178 ENERGY PRODUCTS GROUP

7907050032 Responds to 790413 request Forwards organizational chart  
of radiography dept  
ALLEN, B W Energy Products Group 79/05/10 2pp

## DOCKET 71-0181 CONSOLIDATED X-RAY SERVICE CORP

7907050412 Forwards 790521 revised application for QA program  
CULLINGTON, R F Consolidated X-Ray Service, Inc. 79/05/21 1p.

--7907050416 QA Manual  
\* Consolidated X-Ray Service, Inc 79/05/21 5pp

## DOCKET 71-0184 PULLMAN POWER PRODUCTS

7907240038 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p.

--7907240040 QA program approval for radioactive matl package 0184,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0189 TODD SHIPYARDS CORP

7907110476 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/06/05 12pp.

## DOCKET 71-0192 NUCLEAR PACKAGING, INC

7907050501 Advises that revised QA program description will be submitted by 790627  
OLIVADOTI, J R Nuclear Packaging, Inc 79/05/14 1p

## DOCKET 71-0198 NUCLEAR FUEL SERVICES, INC

7907110472 Forwards request for addl info to complete review of QA program  
MACDONALD, C E Transportation Branch 79/06/05 6pp

## DOCKET 71-0205 QUALITY TESTING, INC

7907260361 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907260364 QA program approval for radioactive matl package 0205,  
Revision O  
MACDONALD, C E Transportation Branch 79/05/01 1p

## DOCKET 71-0208 NORTHEAST NUCLEAR ENERGY CO

7907050556 Advises of intention to apply requirements of QA topical  
rept NU-QA-1, Revision 3A, to meet criteria of 10CFR71.51  
COUNSIL, W O Northeast Utilities 79/05/15 1p

## DOCKET 71-0209 JACKSONVILLE SHIPYARDS, INC

7907050504 Forwards revised QA program for License 09-15611-01  
MCINNIS, E L Jacksonville Shipyards, Inc 79/05/18 1p

--7907050510 Revised QA program for License 09-15611-01  
MCINNIS, E L Jacksonville Shipyards, Inc 79/05/09 5pp

## DOCKET 71-0210 GULF OIL CORP

7907260337 Forwards request for addl info to complete review of QA  
program  
\* Transportation Branch 79/07/02 2pp

## DOCKET 71-0214 GAS RENTALS, INC

7907110417 Forwards QA program in response to 790427 ltr Program  
described is designated to ensure safe radiographic  
operations  
ROBINSON, E L Gas Rentals, 79/05/24 1p

--7907110630 QA program re use of approved radiographic gamma projectors  
\* Gas Rentals 79/05/24 5pp

## DOCKET 71-0215 SPACE SCIENCE SERVICES

7907030162 Forwards NRC 790427 ltr & revised QA program  
GEIGER, D A Space Science Services, Inc 79/05/23 1p.

--7907030166 Requests revision of proposed QA program submitted 781212  
MACDONALD, C E Transportation Branch. 79/04/27. 1p

--7907030168 Revised QA program for industrial radiography license  
09-07550-01  
\* Space Science Services, Inc 79/05/23. 4pp

## DOCKET 71-0216 NUCLEAR ENERGY SERVICES, INC

7907230019 Forwards QA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/29 1p.

--7907230025 QA program approval for radioactive matl package 0216,  
Revision O  
MACDONALD, C E. Transportation Branch. 79/06/29. 1p.

## DOCKET 71-0217 PULLMAN KELLOGG, INC

7907230030 Forwards QA program approval for radioactive matl package.  
MACDONALD, C E. Transportation Branch. 79/06/29. 1p.

--7907230036 QA program approval for radioactive matl package: 0217,  
Revision O  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0218 CUMBERLAND BRIDGE CO

7907240018 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907240023 QA program approval for radioactive matl package: 0218,  
Revision O  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0219 TEREX DIV /GM CORP.

7907240028 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p.

--7907240034 QA program approval for radioactive matl package 0219,  
Revision O  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0225 NAVY, DEPT OF

7907230042 Forwards QA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/29. 1p.

--7907230047 QA program approval for radioactive matl package 0225,  
Revision O  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0226 NEW YORK, STATE UNIV OF

7907310486 Amends QA program for facility, per 781222 request Part 7 of  
submittal is changed to indicate that auditors have no  
responsibilities in activities  
HAAS, M N New York, State Univ of, Buffalo 79/06/12 2pp

7907240032 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907240037 QA program approval for radioactive matl package: 0226,  
Revision O  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0228 CAPITAL X-RAY SERVICE

7907230614 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05. 2pp.

## DOCKET 71-0235 ARMY, DEPT. OF

\*  
7907110570 Responds to 781222 ltr re QA requirements Does not  
anticipate shipping any radioactive sources; licensed  
vendors are contacted to exchange or remove sources when  
required  
PHILLIPS, J H Army, Dept of, Electronic Proving Ground 79/06/01.  
1p.

## DOCKET 71-0236 AMERICAN AIRLINES

7907230469 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp.

## DOCKET 71-0239 NAVY, DEPT OF

7907180845 Notifies that Amend 3 to License 04-17976-01 has been  
forwarded  
FOWELL, W L Navy, Dept of. 79/05/21. 1p

## DOCKET 71-0246 INSPECTION SERVICES CORP.

7907230476 Forwards request for addl info to complete review of QA  
program.  
MACDONALD, C E. Transportation Branch 79/07/05 2pp.

## DOCKETED ITEMS

## DOCKET 71-0247 IRT CORP

7907060517 Requests registration as user of Model 51032-1  
CROSBIE, K L IRT Corp 79/05/15 2pp

## DOCKET 71-0248 MONSANTO RESEARCH CORP

7907110410 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/06/05 13pp

## DOCKET 71-0251 WESTINGHOUSE ELECTRIC CORP

7907230613 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0252 DAVTON X-RAY CO

7907230616 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0257 INDUSTRIAL LABS, INC

7907020037 Forwards QA program for License 41-04226-02.  
WELLS, S R Industrial Laboratories, Inc 79/05/17 1p

--7907020038 QA program for License 41-04226-02  
WELLS, S R Industrial Laboratories, Inc 79/05/17 3pp

## DOCKET 71-0259 NUCLEAR ENGINEERING CO, INC

7907180830 Discusses misconception of current status of Nuclear  
Engineering Co Comments or questions re Nuclear Engineering  
Co QA approval application should be directed to that co;  
Teledyne is not interested party  
MCORCH, J W Teledyne, Inc 79/05/21 1p

## DOCKET 71-0262 WIGCONSIN INDUSTRIAL TESTING, INC

7907230587 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0263 YUBA HEAT TRANSFER CORP

7907230583 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## DOCKET 71-0264 AUTOMATON INDUS, INC

7907110464 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/06/05 12pp

## DOCKET 71-0265 NAVY, DEPT OF

7907230604 Forwards request for addl info to complete review of QA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

## KET 71-0268 NAVY, DEPT OF

090018 Submits repair dept instruction 9900 3A incorporating  
visions to QA program as requested in NRC 790420 ltr.  
DROPBKI, S S Navy, Dept of 79/05/18 14pp

## T 71-0279 UNIVERSAL TESTING, INC

30456 Forwards revised QA program for License 43-11213-02  
ULIKIN, M S Universal Testing Labs, Inc. 79/05/21 1p.

--7907020457 Revised QA program for License 43-11213-02  
ULIKIN, M S Universal Testing Labs, Inc 79/05/21 4pp

7907310613 Forwards revision to QA program  
ULIKIN, M S Universal Testing Labs, Inc 79/06/06 1p

--7907310622 Revision to QA program  
\* Universal Testing Labs, Inc 79/06/06 4pp

## DOCKET 71-0281 DELTA AIRLINES, INC

7907280397 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907280400 QA program approval for radioactive matl package 0281,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-0284 ULTRABONIC SPECIALISTS, INC

7907230115 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230120 QA program approval for radioactive matl package 0284,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

## DOCKET 71-0292 INDUSTRIAL GAMMA INSPECTION

7907300314 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907300317 QA program approval for radioactive matl package 0292,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

## DOCKET 71-0294 APPLIED ENGINEERING CO

7907230104 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230111 QA program approval for radioactive matl package 0294,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p.

## DOCKET 71-0298 STEEL TANK CONSTRUCTION CO

7907230156 Forwards QA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p.

--7907230159 QA program approval for radioactive matl package 0298,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

## DOCKET 71-0304 TELEDYNE BROWN ENGINEERING CO.

7907190601 Forwards QA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907190604 QA program approval for radioactive matl package 0304,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

## DOCKET 71-0305 AMERICAN X-RAY &amp; INSPECTION, INC.

7907230279 Forwards QA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230281 QA program approval for radioactive matl package 0305,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

## DOCKET 71-0306 SNYDER DRILLING-WELL SERVICING CO.

7907190610 Forwards QA program approval for radioactive matl package.  
MACDONALD, C E Transportation Branch 79/06/20 1p.



--7907190613 GA program approval for radioactive matl package 0306,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

DOCKET 71-0307 TEXAS PIPE BENDING CO OF PUERTO RICO

7907230269 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230272 GA program approval for radioactive matl package 0307,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

DOCKET 71-0308 ALASKA INDUSTRIAL X-RAY

7907230606 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

DOCKET 71-0310 BUCYRUS-ERIE CO

7907060137 Forwards organization chart as addl info to GA program  
submitted w/790404 ltr  
MERTZ, J M Bucyrus-Erie Co 79/05/24 2pp

7907300533 Discusses License 48-06390-01 GA program submitted in 790404  
& 0524 ltrs Defines position of radiation protection  
officer Forwards App E to GA program  
MERTZ, J M Bucyrus-Erie Co 79/06/05 1p

7907230386 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/29 1p

--7907250393 GA program approval for radioactive matl package 0310,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/29 1p

DOCKET 71-0314 SMITH-EMERY CO

7907230262 Forwards GA program approval for radioactive matl package,  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230266 GA program approval for radioactive matl package 0314,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

DOCKET 71-0316 MASON & HANGER-BILAS MASON CO , INC

7907230620 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

DOCKET 71-0318 MARATHON OIL CO

7907230610 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

DOCKET 71-0319 GENERAL TESTING & INSPECTION CO

7907230096 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230099 GA program approval for radioactive matl package: 0319,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

DOCKET 71-0320 PITTSBURGH-DEB MOINES STEEL CO

7907230126 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230130 GA program approval for radioactive matl package: 0320,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

DOCKET 71-0321 EXAM CO

7907230609 Forwards request for addl info to complete review of GA  
program  
MACDONALD, C E Transportation Branch 79/07/05 2pp

DOCKET 71-0322 CONTROL COMPONENTS INTERNATIONAL

7907230326 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230331 GA program approval for radioactive matl package: 0322,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

DOCKET 71-0325 CONSUMERS POWER CO

7907180756 Discusses GA for radioactive matl transportation Util will  
use latest version of GA topical rept CPC-1-A for  
radioactive matl transportation & plant operations  
HOFFMAN, D P Consumers Power Co 79/05/15 1p

7907060070 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/01 1p

--7907060071 GA program approval for radioactive matl package 0325  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/01 1p

DOCKET 71-0326 INDUSTRIAL HEAT TREATING & METALLURGICAL CO , INC

7907230309 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/20 1p

--7907230319 GA program approval for radioactive matl package 0326,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/20 1p

DOCKET 71-0327 PORTLAND GENERAL ELECTRIC CO.

7907110145 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/01 1p

--7907110151 GA program approval for radioactive matl package 0327,  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/01 1p

DOCKET 71-0328 PUBLIC SERVICE ELECTRIC & GAS CO

7907060044 Notifies that GA program meets requirements of 10CFR50.  
App B. GA program was submitted to NRC in FSAR App D  
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey.  
79/05/17 1p

7907060067 Forwards GA Program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/06/01 1p

--7907060068 GA program approval for radioactive matl package: 0328  
Revision 0  
MACDONALD, C E Transportation Branch 79/06/01 1p

DOCKET 71-0334 METROPOLITAN EDISON CO.

7907250459 Forwards GA program approval for radioactive matl package  
MACDONALD, C E Transportation Branch 79/07/03 1p

--7907250463 GA program approval for radioactive matl package: 0334,  
Revision 0  
MACDONALD, C E Transportation Branch 79/07/03 1p

DOCKET 71-0361 MODEL: PAT-1, RAMSEY ENGINEERING CO

7907310480 Requests present Certificate of compliance 0361 be revised  
due to administrative flaw  
ROSS, D. M. Energy, Dept of 79/06/12 1p

## DOCKETED ITEMS

7907180701 Notification of registration as user of Model PAT-1  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-4949 MODEL UNC-1484, COMBUSTION ENGINEERING CO, INC

7907180763 Requests renewal of Certificate of Compliance 4949  
Forwards current certificate w/o encl  
MICHEL, C J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.)  
79/03/01 1p

7907190363 Ack expiration notice re Certificate of Compliance 4949  
Requests continued registration as user of Model UNC-1484  
shipping packages  
MCHRY, W R General Atomic Co (subs. of Gulf Oil Corp) 79/05/18  
1p

7907180851 Documents info given to NRC in T Congado 790524 telcon re  
consolidated application for renewal of Certificate of  
Compliance 4949 for Model UNC-1484 Participation in  
consolidated application not necessary  
AUSTIN, M A Babcock & Wilcox Co, Nuclear Material Div 79/03/29  
1p

7907190026 Ack receipt of 790522 ltr requesting 90-day extension of  
validity of Certificate of Compliance 4949 Administrative  
fee of \$150 required to process request  
WEISS, D License Fee Management Branch 79/05/30 1p

--7907190030 Requests 90-day extension to collect required data &  
prepare submittal for consolidated application for renewal  
of Certificate of Compliance 4949 for Model UNC-1484  
GREGG, R J United Nuclear Corp 79/05/22 1p

7907230251 Forwards Revision 1 of Certificate of Compliance 4949 for  
shipping package Model UNC-1484  
MACDONALD, C E Transportation Branch 79/06/13 2pp

--7907230255 Certificate of Compliance 4949, Revision 1, for radioactive  
matl shipping package Model UNC-1484  
MACDONALD, C E Transportation Branch 79/06/13 2pp

## DOCKET 71-4986 MODEL RA-2, EXXON NUCLEAR CO, INC

7907180821 Notification of registration as user of Model RA-2.  
MACDONALD, C E Transportation Branch 79/06/29 1p

7907200239 Notification of registration as user of Model RA-2  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-5026 MODEL BC-48-220, ATCOR, INC

7907110621 Notifies that Certificates of Compliance 5026, 6275 & 6601  
for Models BC-48-220, LL-28-4 & LL-50-100, respectively, will  
expire on 790831 unless consolidated application is  
submitted.  
MACDONALD, C E Transportation Branch, 79/05/31. 1p

07190024 Notifies of expiration of Certificate of Compliance 5026 for  
Model BC-48-220 Consolidated application should be submitted  
in order to continue using package  
MACDONALD, C E Transportation Branch, 79/06/01 2pp.

07310456 Requests continuation of Certificate of Compliance 5026  
LEWIS, L Duke Power Co 79/06/11 1p.

707230370 Requests registration as user of Model 5026  
DUNN, C N Duquesne Light Co 79/06/14 1p

## DOCKET 71-5149 MODEL B14A, BABCOCK &amp; WILCOX CO

7907250333 Notifies of expiration of Certificates of Compliance 5149,  
5341, 5563, 5910, 6172 & 6357 for Models B14A, NFD 55, 660B &  
60C, NNFD-BA-2, 961A & NNFD-10, respectively To continue using  
package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch, 79/06/06 1p

## IT 71-5341 MODEL NFP-55, BABCOCK &amp; WILCOX CO

07250333 Notifies of expiration of Certificates of Compliance 5149,  
5341, 5563, 5910, 6172 & 6357 for Models B14A, NFD 55, 660B &  
60C, NNFD-BA-2, 961A & NNFD-10, respectively To continue using  
package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch, 79/06/06 1p.

7907260574 Notifies of expiration of Certificate of Compliance 5341  
for Model NFP-55. To continue using package, should request  
continuation as user of certificate per IOCFR71  
MACDONALD, C E Transportation Branch 79/06/14 1p

## DOCKET 71-5364 MODEL NPI-67-0442 NEUTRON PRODUCTS, INC

7907180837 Notification of registration as user of Model NPI-67-0442  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-5395 MODEL CC, WESTINGHOUSE ELECTRIC CORP

7907120099 Notifies of expiration of Certificate of Compliance 5395 for  
Model CC To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

## DOCKET 71-5450 MODEL RCC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP.

7907100613 Requests addl info re request for amend to model RCC  
Series packaging Requests vendor delineate changes made to  
previously approved packaging & discuss or analyze their  
safety significance  
MACDONALD, C E Transportation Branch 79/05/30 1p

7907180795 Notification of registration as user of Model RCC  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-5455 MODEL QA SERIES PB, GENERAL ATOMIC CO

7907120267 Notifies of expiration of Certificate of Compliance 5455 for  
Model QA Series PB To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

## DOCKET 71-5563 MODEL 660C, BABCOCK &amp; WILCOX CO

7907250333 Notifies of expiration of Certificates of Compliance 5149,  
5341, 5563, 5910, 6172 & 6357 for Models B14A, NFD 55, 660B &  
660C, NNFD-BA-2, 961A & NNFD-10, respectively To continue using  
package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

## DOCKET 71-5754 MODEL RMQ-172, NUCLEAR FUEL SERVICES, INC

7907190037 Notifies of expiration of Certificate of Compliance 5754 for  
Model RMQ-172. To continue using package, should request  
renewal of existing certificate of compliance.  
MACDONALD, C E Transportation Branch 79/06/06 1p

## DOCKET 71-5768 MODEL BB-250-2, COMBUSTION ENGINEERING CO, INC

7907110304 Notifies of expiration of Certificates of Compliance 5768,  
6078 & 9022 for Models BB-250-2, 927A1 & C1 & CE-250-2,  
respectively in order to continue use, consolidated  
application should be submitted for each renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907240475 Notifies of expiration of Certificate of Compliance 5768 for  
Model BB-250-2. To continue using package, should submit  
consolidated application for renewal.  
MACDONALD, C E Transportation Branch 79/06/18 1p

## DOCKET 71-5805 MODEL ATCOR VNDB CASK, ATCOR, INC.

7907180812 Responds to 790510 ltr Lists as-built changes to drawing  
0999-D-07 Changes have no safety significance to cask shock  
absorber.  
REYNOLDS, L E Chem-Nuclear Systems, Inc 79/05/17. 2pp

## DOCKET 71-5901 MODEL NFS 100, NUCLEAR FUEL SERVICES, INC.

7907120092 Notifies of expiration of Certificate of Compliance 5901 for  
Model 100. To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p.

7907240407 Notifies of expiration of Certificate of Compliance 5901 for Model NFS 100 To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/18 1p

DOCKET 71-5908 MODEL DOT-6M TYPE B, BABCOCK & WILCOX CO

7907300029 Requests registration as user of Model DOT-6M Type B  
FAUST, H M Battelle Memorial Institute, Columbus Laboratories  
79/06/06 1p

7907230244 Notification of registration as user of Model DOT-6M Type B in response to 790606 request  
MACDONALD, C E Transportation Branch 79/06/19 1p

DOCKET 71-5910 MODEL NNFD-BA-2, BABCOCK & WILCOX CO

7907250333 Notifies of expiration of Certificates of Compliance 5149, 5341, 5563, 5910, 6172 & 6357 for Models 814A, NFD 55, 660B & 660C, NNFD-BA-2, 961A & NNFD-10, respectively To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907250280 Notifies of expiration of Certificate of Compliance 5910 for Model NNFD-BA-2 To continue using package, should submit request for renewal  
MACDONALD, C E Transportation Branch 79/06/18 1p

DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO

7907090046 Requests authorization to ship irradiated fuel plates by placing threaded steel rod/plywood cask basket inside GE 700 cask  
ASHRAUGH, C E California, Univ of, Los Angeles 79/08/18 2pp

7907180841 Forwards Revision 2 of Certificate of Compliance 5942 for shipping package Model GE-700  
MACDONALD, C E Transportation Branch 79/06/12 2pp

7907180848 Certificate of Compliance 5942, Revision 2, for radioactive matl shipping package Model GE-700  
MACDONALD, C E Transportation Branch 79/06/12 4pp

7907230238 Notification of registration as user of Model GE-700 in response to 790522 request  
MACDONALD, C E Transportation Branch, 79/06/21 1p

DOCKET 71-5977 MODEL CORE II FUEL, TODD SHIPYARDS CORP

7907250305 Notifies of expiration of Certificate of Compliance 5977 for Model Core II Fuel To continue using package, should submit request for renewal.  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907240385 Notifies of expiration of Certificate of Compliance 5977 for Model Core II fuel To continue using package, should request renewal  
MACDONALD, C E Transportation Branch, 79/06/18 1p

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO

7907090457 Notifies of expiration of Certificates of Compliance 5980 & 6697 for Models GE-600 & 8900, To continue using package, should submit consolidated application for each renewal.  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907240394 Notifies of expiration of Certificate of Compliance 5980 for Model GE-600 To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch, 79/06/18 1p.

DOCKET 71-6058 MODEL B3-1, NUCLEAR ENGINEERING CO

7907060116 Requests continued status as registered User of Model B3-1  
OLSEN, A. F. Babcock & Wilcox Co 79/05/24 1p

7907240048 Requests registration as user of Model B3-1  
REHLEY, M E Rockwell International Corp 79/05/29 1p.

7907090428 Intends to ship radioactive matl from facilities using package B3-1  
MAYER, L. P Northern States Power Co. 79/06/08 1p.

7907090432 Notifies that Certificate of Compliance 6058 for Model B3-1 expires on 791231 Licensees must request continuation as user  
MACDONALD, C E Transportation Branch 79/05/16 2pp

7907310452 Requests continuation of Certificate of Compliance 6058  
EMSWILER, T R Battelle Memorial Institute, Columbus Laboratories  
79/06/11 1p

DOCKET 71-6078 MODEL 927 A1 & C1, COMBUSTION ENGINEERING, INC

7907110304 Notifies of expiration of Certificates of Compliance 576B, 6078 & 9022 for Models BB-250-2, 927A1 & C1 & CE-250-2, respectively In order to continue use, consolidated application should be submitted for each renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907260527 Notifies of expiration of Certificate of Compliance 6078 for Models 927A1 & 927C1 To continue using package, should request continuation as user of Certificate per 10CFR71  
MACDONALD, C E Transportation Branch 79/06/14 1p

DOCKET 71-6104 MODEL ANL-390-SPM, ENERGY, DEPT OF, CHICAGO

7907090031 Requests addl info in order to complete review of 771230 ltr for review of Model ANL-390-SPM 2 package info re shipping cask structure, containment & acceptance tests & maint program are needed  
MACDONALD, C E Transportation Branch, 79/05/30 3pp

DOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO

7907240050 Requests registration as user of Model CNBI 16-160B  
LEONARD, J D Power Authority State of New York 79/05/31 1p

7907060507 Notifies of expiration of Certificate of Compliance 6144 Consolidated application for renewal is necessary for continued use of package.  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907260539 Notifies of expiration of Certificate of Compliance 6144 for Model 6144 To continue using package, should request continuation as user of Certificate per 10CFR71  
MACDONALD, C E Transportation Branch 79/06/19 2pp

7907180918 Notification of registration as user of Model 6144  
MACDONALD, C E Transportation Branch 79/06/29 1p

DOCKET 71-6172 MODEL 961A, BABCOCK & WILCOX CO

7907250333 Notifies of expiration of Certificates of Compliance 5149, 5341, 5563, 5910, 6172 & 6357 for Models 814A, NFD 55, 660B & 660C, NNFD-BA-2, 961A & NNFD-10, respectively To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907260575 Notifies of expiration of Certificate of Compliance 6172 for Model 961A To continue using package, should request continuation as user of Certificate per 10CFR71.  
MACDONALD, C E Transportation Branch 79/06/14 1p

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

7907050227 Certificate of Compliance 6244, Revision 2, for radioactive matl shipping package Model 6244  
MACDONALD, C E Transportation Branch 79/05/25 3pp

7907050232 Forwards Revision 1 of Certificate of Compliance 6244 for shipping package Model 6244  
MACDONALD, C E Transportation Branch 79/05/25 2pp

7907300187 Request that Certificate of Compliance 6244 be amended to reflect changes in various components Revised portions of drawings 6930-1 enc1 Forwards oversized drawings  
REYNOLDS, L E Chem-Nuclear Systems, Inc 79/06/05 6pp

## DOCKETED ITEMS

## DOCKET 71-6275 MODEL LL-2B-4, CHEM-NUCLEAR SYSTEMS, INC

7907110621 Notifies that Certificates of Compliance 8026, 6275 & 6401 for Models BC-4B-220, LL-2B-4 & LL-50-100, respectively, will expire on 790831 unless consolidated application is submitted  
MACDONALD, C E Transportation Branch 79/05/31 1p

7907110054 Notification of expiration of Certificate of Compliance 6575 for Model LL-2B-4  
MACDONALD, C E Transportation Branch 79/06/01 2pp

7907310454 Requests continuation of Certificate of Compliance 6275 LEWIS, L Duke Power Co 79/06/11 1p

7907250066 Requests registration as user of Model LL-2B-4 BAYNARD, P Y Florida Power Corp 79/06/15 1p

## DOCKET 71-6280 MODEL A-0109

7907090447 Notifies of expiration of Certificate of Compliance 6280 Model A-0109 To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907240494 Notifies of expiration of Certificate of Compliance 6280 for Model A-0109 To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/18 1p.

## DOCKET 71-6291 MODEL 400

7907100663 Notifies of expiration of Certificate of Compliance 6291 for Model 400 To continue using package, should request renewal of existing Certificate of Compliance  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907100668 Notifies of expiration of Certificate of Compliance 6291 for Model 400 To continue using package, should request continuation as user of Certificate per 10CFR71.12(b)  
MACDONALD, C E Transportation Branch 79/06/06 1p

## DOCKET 71-6357 MODEL NNFD-10, BABCOCK &amp; WILCOX

7907250333 Notifies of expiration of Certificates of Compliance 5149, 5341, 5563, 5910, 6172 & 6357 for Models B14A, NFD-35, 650B & 660C, NNFD-SA-2, 961A & NNFD-10, respectively To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907240501 Notifies of expiration of Certificate of Compliance 6357 for Model NNFD-10 To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/18 1p

7907180865 Notification of registration as user of Model NNFD-10  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-6375 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC

7907240045 Requests registration as user of Model CNSI A-45  
LEONARD, J D Power Authority State of New York 79/05/30 1p

7907100634 Notification of registration as user of Model PB-1  
MACDONALD, C E Transportation Branch 79/05/31 1p

7907250039 Requests registration as user of Model PB-1  
LEWIS, L Duke Power Co 79/05/31 1p

7907250062 Requests registration as user of Model PB-1.  
BAYNARD, P Y Florida Power Corp 79/06/15 1p

## DOCKET 71-6387 MODEL 60, BATTELLE MEMORIAL INSTITUTE

7907080273 Forwards Drawing H-3-44280 showing 36 pin pinholder insert for Model 60 radioactive matl shipping container  
SMITH, F M Hanford Engineering Development Laboratory 79/05/23 1p

7907050279 Oversized drawing of 36 pin pinholder insert for Certificate of Compliance 6387.  
\* Hanford Engineering Development Laboratory. 78/04/25 1p

## DOCKET 71-6400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

7907100608 Requests an analysis or test demonstrating that fiberglass reinforced plywood containers within Super Tiger packaging provides containment under accident conditions of transport.  
MACDONALD, D E Transportation Branch 79/05/30 1p

## DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR &amp; DEVELOPMENT CORP

7907180745 Requests registration as user of Hittman Nuclear & Development Corp shipping packages HN-200 & HN-600  
MODDY, D E Yankee Atomic Electric Co 79/05/29 1p

7907090436 Notifies of expiration of Certificate of Compliance 6514 for Model HN-200 To continue using package, should request renewal of existing Certificate of Compliance  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907310142 Notifies of expiration of Certificate of Compliance 6574 for Model HN-200 To continue using package, should request renewal of certificate  
MACDONALD, C E Transportation Branch 79/06/18 2pp

## DOCKET 71-6581 MODEL 51032-1 &amp; 1A, EXXON NUCLEAR CO, INC

7907190572 Submits Revision 1A to XN-NF-439 "QA Program for Nuclear Fuels Dept Shipping Containers" Satisfies request that currently approved version of XN-NF1A, Revision 2, be ref in body of document  
NILSON, R Exxon Nuclear Co, Inc (subs of Exxon Corp) 79/05/22 1p

--7907190577 Revision 1A to XN-NF-439 "QA Program for Nuclear Fuels Dept Shipping Containers"  
DAVIS, L L Exxon Nuclear Co, Inc. (subs of Exxon Corp) XN-NF-439 79/05/24 7pp.

7907240313 Notifies of expiration of Certificate of Compliance 6581 for Models 51032-1 & 1A To continue using package, should submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/25 1p

7907230492 Discusses partial refund of renewal fee due to overpayment for Certificate of Compliance 6581  
WEISS, D License Fee Management Branch 79/06/27 1p

--7907230496 Discusses partial refund of renewal fee due to overpayment  
WEISS, D License Fee Management Branch 79/06/26 1p.

--7907230499 Requests fee of \$150 for renewal of Certificate of Compliance 6581  
WEISS, D License Fee Management Branch 79/06/22 1p

--7907230504 Forwards \$690 check for licensing fee re 790614 application for renewal & revision of Certificate of Compliance 6581  
NECHODOM, W S Exxon Nuclear Co, Inc. (subs of Exxon Corp) 79/06/15 1p

--7907230511 "Consolidated License Application for Exxon Nuclear Co, Inc Model 51032-1 & 1A Shipping Containers."  
HANSEN, L E, MCCULLUGH, R W, SOFER, G A Exxon Nuclear Co, Inc (subs. of Exxon Corp) 79/06/30 271pp.

## DOCKET 71-6601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC.

7907240552 Requests registration as user of Model LL-50-100  
VOIGHT, A F Iowa State Univ. 79/05/25 1p

7907110621 Notifies that Certificates of Compliance 8026, 6275 & 6401 for Models BC-4B-220, LL-2B-4 & LL-50-100, respectively, will expire on 790831 unless consolidated application is submitted  
MACDONALD, C E Transportation Branch 79/05/31 1p

7907180717 Notification of expiration of Certificate of Compliance 6601 for Model LL-50-100.  
MACDONALD, C E Transportation Branch 79/06/01 2pp

7907250056 Requests registration as user of Model CNSI-LL-50-100.  
DENHITT, T F United Nuclear Corp 79/06/01 1p

7907310448 Requests continuation of Certificate of Compliance 6601.  
LEWIS, L Duke Power Co. 79/06/11 1p

7260577 Requests registration as user of Model LL-50/100  
ISLA, S F Consolidated Edison Co of New York 79/06/12 1p

7180847 Notification of registration as user of Model LL-50-100  
ACDONALD, C E Transportation Branch 79/06/29 1p

KEY 71-6642 MODEL 4 5 TON CF, ENERGY, DEPT OF

7100641 Notification of registration as user of Model 4 5 TON CF  
ACDONALD, C E Transportation Branch 79/05/31 1p

KEY 71-6697 MODEL 8500 PKG, GENERAL ELECTRIC CO

7090457 Notices of expiration of Certificates of Compliance 5980 &  
697 for Models GE-600 & 8500 To continue using package,  
should submit consolidated application for each renewal  
ACDONALD, C E Transportation Branch 79/06/06 1p

7240390 Notices of expiration of Certificate of Compliance 6697  
or Model 8500 To continue using package, should submit  
consolidated application for renewal  
ACDONALD, C E Transportation Branch 79/06/18 1p.

KEY 71-6698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC

7060454 Notices of 790425 review of inner cavity measurement for  
IAG-1B fuel shipping cask  
HITENER, H L Region 2, Atlanta, Office of the Director  
79/05/09, 3pp.

7060111 Ack receipt of NRC 790511 ltr to Duke power Co Expresses  
appreciation for extension until 790613 to file answer re  
790406 order to show cause  
ICGARRY, J M Debevoise & Lieberman 79/05/15 1p

7130292 IE Insp Rept 71-6698/79-01 on 790419-20 No noncompliance  
noted. Major areas inspected spent fuel casks dimensional  
examination  
MCNEILL, W M Region 4, Dallas, Vendor Inspection Branch.  
79/05/18 7pp.

73300200 Responds to WJ Dircks 790406 ltr re order to show cause  
IAC-1 casks mfg by Excelco were in accordance w/mfg plan QA  
records, summary of comparison between shop & design drawings  
for certificate of compliance & internal measurements encl.  
COLLINS, J D Nuclear Assurance Corp 79/06/08, 5pp

7907300205 "QA Audit of Fabrication of NAC-1 Spent Fuel Casks "  
\* Nuclear Assurance Corp 79/06/08, 38pp

7907300208 "Cavity Measurements of NAC-1 Spent Fuel Shippings Casks "  
CARLSON, R W Nuclear Assurance Corp 79/05/31 46pp

7907300215 Revision 17 to Drawing E10089, Sheets 1-4 to incorporate  
tolerance & dimensional changes as result of comparison  
between shop & design drawings for certificate of  
compliance  
\* Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/06/11  
4pp.

KEY 71-9001 MODEL, IF-300, GENERAL ELECTRIC CO

07090454 Notices of expiration of Certificate of Compliance 9001 for  
Model IF-300 To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

07240485 Notices of expiration of Certificate of Compliance 9001 for  
Model IF-300 To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/18 1p.

KEY 71-9005 MODEL, MAL-1

07100665 Notices of expiration of Certificate of Compliance 9005 for  
Model MAL-1 To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06, 1p.

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

7907050386 Amends 790511 request for IAEA certification of FL 10-1  
package to cover only urgent export of certain Pu & U  
oxide Forwards info re proposed package description  
CUNNINGHAM, O E General Electric Co, Nuclear Energy Products Div  
79/05/16 1p

--7907050389 "Assessment of FL 10-1 Package Per 1973 IAEA Regulations for  
Solid Form Contents "  
\* General Electric Co, Nuclear Energy Products Div 79/05/16  
7pp

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

7907100621 Notification of registration as user of Model NLI-1/2  
MACDONALD, C E Transportation Branch 79/05/31 1p

7907240301 Notification of registration as user of Model NLI-1/2  
MACDONALD, C E Transportation Branch 79/06/29 1p

7907240307 Notification of registration as user of Model NLI-1/2  
MACDONALD, C E Transportation Branch 79/06/29 1p

DOCKET 71-9017 MODEL SNAP-23A, MD 1000, NAVY, DEPT OF

7907120125 Notices of expiration of Certificate of Compliance 9017 for  
Model SNAP-23A To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907240439 Notices of expiration of Certificate of Compliance 9017  
for Model Snap 23A 1000 To continue using package, should  
submit consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/18 1p

DOCKET 71-9018 MODEL BU-6, GENERAL ELECTRIC CO

7907300345 Notices of expiration of Certificate of Compliance 9018 for  
Model BU-6 To continue using package, should request  
renewal of certificate  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907310176 Notices of expiration of Certificates of Compliance 9018 &  
9019 for Models BU-6 & BU-7, respectively To continue using  
package, should request renewal of existing certificates of  
compliance  
MACDONALD, C E Transportation Branch 79/06/06 1p

DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO

7907310169 Notices of expiration of Certificate of Compliance 9019 for  
Model BU-7 To continue using package, should request  
renewal of existing certificates  
MACDONALD, C E Transportation Branch 79/06/06 1p

7907310176 Notices of expiration of Certificates of Compliance 9018 &  
9019 for Models BU-6 & BU-7, respectively To continue using  
package, should request renewal of existing certificates of  
compliance  
MACDONALD, C E Transportation Branch, 79/06/06 1p

7907230060 Requests registration as user of Model BU-7  
ZEFF, D W Babcock & Wilcox Co 79/06/18 1p.

DOCKET 71-9022 MODEL: GE-250-2, COMBUSTION ENGINEERING CO, INC.

7907110304 Notices of expiration of Certificates of Compliance 576B,  
607B & 9022 for Models BB-250-2, 927A1 & C1 & GE-250-2,  
respectively. In order to continue use, consolidated  
application should be submitted for each renewal  
MACDONALD, C E Transportation Branch 79/06/06 1p.

7907240458 Notices of expiration of Certificate of Compliance 9022  
for Model GE-250-2. To continue using package, should submit  
consolidated application for renewal  
MACDONALD, C E Transportation Branch 79/06/18 1p

## DOCKETED ITEMS

## DOCKET 71-9033 MODEL 660 &amp; 660E, TECHNICAL OPERATIONS, INC

7907260960 Requests renewal of Certificate of Compliance 9033 issued for Models 660 & 660E Type B Packages Discusses changes to certificate re encl Drawings 66025  
MUNRO, J J Tech/Ops (Technical Operations, Inc) 79/06/15 5pp

7907310162 Notifies of expiration of Certificate of Compliance 9033 for Models 660 & 660E To continue using package, should request renewal  
MACDONALD, C E Transportation Branch 79/06/18 5pp

7907180783 Notification of registration as user of Model 660  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

7907180832 Notification of registration as user of Model GE-1600  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

7907190397 Requests registration as user of Model CNSI 1-5 radioactive shipping cask  
LUCAS, B Union Carbide Corp 79/05/16 1p.

7907040021 Notifies that failure to file QA program by 790101 has caused termination of authorization to deliver licensed matl to carrier for transport QA program must be approved prior to registration as package user or delivery to carrier  
MACDONALD, C E Transportation Branch 79/05/24 1p.

7907180855 Notification of registration as user of Model N-55  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-9074 MODEL AP-100, ANEFCO, INC

7907100619 Notification of registration as user of Model AP-100  
MACDONALD, C E Transportation Branch 79/05/31 1p

## DOCKET 71-9080 MODEL HN-600, HITTMAN NUCLEAR &amp; DEVELOPMENT CORP

7907180745 Requests registration as user of Hittman Nuclear & Development Corp shipping packages HN-200 & HN-600  
MOODY, D E Yankee Atomic Electric Co 79/05/29 1p

## DOCKET 71-9081 MODEL CNSI-1600, CHEM-NUCLEAR SYSTEMS, INC

7907180808 Notification of registration as user of Model CNS-1600  
MACDONALD, C E Transportation Branch 79/06/29 1p

7907180917 Notification of registration as user of Model CNS-1600  
MACDONALD, C E Transportation Branch 79/06/29 1p

7907100623 Notification of registration as user of Model CNS-1600  
MACDONALD, C E Transportation Branch 79/05/31 1p

## DOCKET 71-9108 MODEL AL-33-90, ATCOR, INC

7907180702 Notification of registration as user of Model AL-33-90  
MACDONALD, C E Transportation Branch 79/06/29 1p

## DOCKET 71-9113 MODEL 7-100, CHEM-NUCLEAR SYSTEMS, INC

7907190002 Notification of registration as user of Model 7-100  
MACDONALD, C E Transportation Branch 79/06/29 1p

# NONDOCKETED ITEMS

## 10CR- COMMISSION MEETING RECORDS

7906260446 Summary of 790320 meeting in Washington, DC re projected Mar 1979 power reactor licensing schedule referenced in BECY-79-179  
CHILKIS J. Office of the Secretary of the Commission 79/03/21.  
1p

7907030089 Transcript of TVA 790625 presentation in Washington, DC re safety rept Pp 1-36  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/25  
37pp

7907030309 Transcript of 790625 public meeting in Washington, DC to discuss personnel matter Pp 1-40  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/25  
41pp

7907030343 Transcript of 790614 public meeting, Affirmation Session 17, in Washington, DC Pp 1-6  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/14 7pp

7907030354 Transcript of 790614 public meeting in Washington, DC on power needs of PA, NJ & MD Pp 1-23  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/14  
24pp

7907030360 Transcript of 790524 open meeting in Washington, DC re City of Lancaster, PA lawsuit Pp 1-27  
GILINSKY, V., KENNEDY, R. T., BRADFORD, P. A. Commission 79/05/24  
27pp

7907030366 Transcript of 790207 closed meeting in Washington, DC re testimony before House Foreign Affairs Committee Pp 1-15  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/05/29  
16pp

7907030395 Transcript of 790614 public meeting in Washington, DC on nuclear power needs of PA, NJ & MD Pp 1-38  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/14  
37pp

7907030407 Transcript of 790614 briefing in Washington, DC by Ofc of Project Mgt on Senior Executive SVC performance appraisal  
sys Pp 1-45  
HENDRIE, J. M., KENNEDY, R. T., BRADFORD, P. A. Commission 79/06/14  
46pp

7907030410 Transcript of 790215 discussion in Washington, DC re Tarapur Pp 1-41 Portions deleted per Sunshine Act  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/14  
43pp

7907030413 Transcript of 790618 public meeting in Washington, DC on American Atomic plant shutdown Pp 1-74  
GILINSKY, V., KENNEDY, R. T., BRADFORD, P. A. Commission 79/06/18  
75pp.

7907090011 Transcript of 790530 meeting in Washington, DC re license deferral options Pp 1-63.  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/05/30  
63pp

---7907090013 Discusses options for placing limitations on reactor licensing Describes six options for formalizing current licensing freeze & four long-term limitation options  
Discusses future implications & impact on current actions  
BICKMUT, L. Office of the General Counsel, 79/05/29 10pp.

7907090028 IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor."  
\* Office of Inspection & Enforcement 79/05/29 9pp.

7907090030 Transcript of 790530 briefing in Washington, DC on incident response program Pp 1-45  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/05/30  
46pp

7907090032 Transcript of 790530 meeting in Washington, DC re Affirmation Session 79-10 Pp 1-4  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/05/30 4pp

7907100441 Transcript of 790514 deposition of AS Klomprens in Midland, MI Pp 1-53  
KLOMPRENS, A. S. Affiliation Unknown 79/05/14 54pp

7907110714 Transcript of 790515 deposition of LF Nute in Midland, MI Pp 1-204  
NUTE, L. F. Affiliation Unknown 79/05/15 205pp

7907120013 Transcript of 790515 deposition of DA Durand in Midland, MI Pp 121-198  
DURAND, D. A. Affiliation Unknown 79/05/15 78pp

7907120499 Transcript of 790628 public meeting in Washington, DC re seismic design capability of operating reactors & responses to IE bulletin on seismic analysis Pp 1-41  
HENDRIE, J. M., GILINSKY, V. Commission 79/06/28 42pp

7907120520 Transcript of 790628 public meeting in Washington, DC re emergency planning task force Pp 1-80  
HENDRIE, J. M., GILINSKY, V. Commission 79/06/28 51pp

7907130078 Transcript of 790529 Commission meeting in Washington, DC re S-3 Pp 1-15  
HENDRIE, J. M., KENNEDY, R. T., BRADFORD, P. A. Commission 79/05/29  
17pp

7907160172 Transcript of 790629 public meeting in Washington, DC re briefing by EPA on radiation stds & criteria for waste mgt Pp 1-32  
HENDRIE, J. M., KENNEDY, R. T., AHEARNE, J. F. Commission 79/06/29  
33pp

7907160186 Transcript of 790621 meeting in Washington, DC re BECY-79-110A & proposed Executive Branch format for analysis of export applications Pp 1-41  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/21 42p

7907160211 Transcript of 790621 public meeting in Washington, DC re feedwater nozzle cracks in Westinghouse reactors Pp 1-26  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/06/21.  
26pp

7907160229 Transcript of 790605 public meeting in Washington, DC re performance appraisal teams, Pp 1-33 Viewgraphs encl.  
HENDRIE, J. M., BRADFORD, P. A., AHEARNE, J. F. Commission 79/06/05  
48pp

7907160246 Transcript of 790605 public meeting in Washington, DC re Mark I containment Pp 1-38 Viewgraphs & photographs encl.  
HENDRIE, J. M., GILINSKY, V., BRADFORD, P. A. Commission 79/06/05.  
42pp

7907160255 Transcript of 790607 public meeting in Washington, DC re second periodic review of NRC FY79 operating budget & decision unit tracking, Pp 1-72. Viewgraphs encl.  
HENDRIE, J. M., GILINSKY, V., AHEARNE, J. F. Commission 79/06/07  
71pp.

7907190573 Transcript of 790705 public meeting in Washington, DC w/DOE & Euratom representatives re export matters, Pp 1-24 Viewgraphs encl.  
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/07/05.  
32pp

7907230189 Forwards BECY-79-36B re Transnuclear, Inc application for export license to transport source matl to France  
MCOREGOR, E. W. Office of the Secretary of the Commission. 79/06/12  
1p.

## NONDOCKETED ITEMS

7907250276 "Annual Rept for 1978 on Administration of Govt in Sunshine Act of 1976"  
\* Commission 78/12/31 28pp

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

7907020465 Summary of 790131 meeting w/various utils & vendors in Washington DC re ATWS for LWRs  
\* ACRS - Advisory Committee on Reactor Safeguards 79/03/24 38pp

7907030284 Transcript of 790620 meeting of ACRS Subcommittee on ECCS in Washington, DC Pp 240-462 Presentation encl  
PLESSET, M S, EBERSOLE, J ACRS - Advisory Committee on Reactor Safeguards 79/06/20 370pp

7907030295 Transcript of 790617 meeting of ACRS Subcommittee on ECCS in Washington, DC Pp 1-259 Presentation encl  
PLESSET, M S, EBERSOLE, J ACRS - Advisory Committee on Reactor Safeguards 79/06/19 348pp

7907050061 Summary of Evaluation of LER Subcommittee 790301-02 meeting in Washington, DC re types of analyses being performed on planned w/LERs & NRC recommendations for LER study  
\* ACRS - Advisory Committee on Reactor Safeguards 79/04/24 19pp

7907050350 Summary of 790319-20 meeting w/ECCS Subcommittee in Los Angeles, CA re code work on transient two-phase flow, status of physical inputs to codes, std problem program, DDYN code review & analysis of Semiscale Test S-07-6  
CATTON, I ACRS - Advisory Committee on Reactor Safeguards 79/05/01 3pp

7907050460 Comments on functions of integrated protection sys as discussed at 790330 meeting. More matl is necessary re issue of acceptability of single sys to accomplish reactor shutdown  
EPLER, E P Elbert P Epler 79/04/12 10pp

7907060288 Summary of 790321-23 meeting w/MARK II owners group in Palo Alto, CA re new series of AT tests  
CATTON, I ACRS - Advisory Committee on Reactor Safeguards 79/05/01 5pp

7907090244 Forwards discussion of imprecision in evaluating buckling criteria for free-standing containment shells of nuclear power plants. Suggests research to evaluate existing experimental results & development of computer program  
ZUDANS, Z Franklin Institute 79/04/16 8pp

7907120338 Transcript of 790613 meeting of ACRS Subcommittee on Regulatory Activities in Washington, DC Pp 1-112 Exhibits encl  
KERR, W, BENDER, M, RAY, J J ACRS - Advisory Committee on Reactor Safeguards 79/06/13 185pp

7907130429 Transcript of ACRS 230th general meeting on 790614 in Washington, DC Pp 1-261 Documentation encl  
\* ACRS - Advisory Committee on Reactor Safeguards 79/06/14 399pp

7907130434 Transcript of ACRS 230th general meeting on 790615 in Washington, DC Pp 262-576 Documentation encl  
\* ACRS - Advisory Committee on Reactor Safeguards 79/06/15 395pp

7907170239 Summary of 790319-20 meeting of ACRS ECCS Subcommittee in Los Angeles, CA re code work on transient two-phase flow, analysis of LDFT test, std problem program, DDYN code review & analysis of semiscale test  
GARLID, K L Washington, Univ of 79/04/17 3pp

7907190562 Transcript of 790511 ACRS 229th general meeting in Washington, DC Pp 385-702 Viewgraphs encl  
CARBON, M W, PLESSET, M S, BENDER, M ACRS - Advisory Committee on Reactor Safeguards 79/05/11 358pp

7907200482 Transcript of 790626 meeting of Subcommittee on Improved Sys in Washington, DC Pp 1-254 Viewgraphs encl  
\* ACE Federal Reporters, Inc 79/06/26 332pp

7907230634 Transcript of 790710 meeting of ACRS Subcommittee on Metal Components in Washington, DC Pp 1-346 Presentations by EPRI, IBM, GE, C-E & Westinghouse encl  
HEMMON, P O, BENDER, M, ETHERINGTON, M ACRS - Advisory Committee on Reactor Safeguards 79/07/10 658pp

7907230714 Transcript of 790710 meeting of ACRS Subcommittee on Reactor Safety Research Pp 1-72 Presentation encl  
BRENT, D, KERR, W, MARK, J C ACRS - Advisory Committee on Reactor Safeguards 79/07/10 77pp

7907250064 Transcript of 740325 meeting of ACRS Working Group 4 in Washington, DC Pp 1-248 Presentations encl  
IBBIN, H S, BUSH, B H, CARBON, M W ACRS - Advisory Committee on Reactor Safeguards 76/03/25 372pp

7907310251 Advises that no special press facilities are necessary for ACRS TMI Subcommittee 790606-07 meeting at Penn State Univ  
MULLER, R ACRS - Advisory Committee on Reactor Safeguards 79/05/18 1p

AGREEMENT STATE AGREEMENTS AND PROGRAMS

7907270259 Ack receipt of 790523 ltr requesting termination of agreement between AZ & NRC due to conditions at American Atomics Corp. NRC is monitoring case & will be present at 790616 hearings to review AZ actions before final decision  
RYAN, R O Office of State Programs 79/06/18 2pp

COMMISSION NRC COMMISSIONERS

7907060050 Weekly info rept for week ending 790518  
REHM, T A Office of the Executive Director for Operations 79/05/23 30pp

7907060089 Ack receipt of 790508 ltr Anticipates funding proposed studies through RFP. Will forward RFP when available  
LEVINE, S Office of Nuclear Regulatory Research 79/06/03 1p

--7907060094 Describes proposed communications feasibility studies for NRC, w/estimated costs  
MALLET, R A Information & Communication Applications, Inc 79/05/08 2pp

7907060235 Discusses requested insp of PA nuclear facilities. No items of direct safety concern noted  
HENDRIE, J M Commission 79/05/25 5pp

--7907060237 Requests info re completion date of insp of PA nuclear facilities.  
THORNBURGH, R Pennsylvania, State of 79/05/03 1p

7907060368 Apologizes for ref to blind people made during TMI-2 incident  
HENDRIE, J M Commission 79/05/07 1p

7907060414 Ack 790501 ltr re forthcoming Girls' Nation meeting. Accepts invitation to address group  
HENDRIE, J M Commission 79/05/09 1p

--7907060419 Extends invitation to participate in forthcoming govt training course for Girls' Nation  
BIGALOW, E Affiliation Unknown 79/05/01 2pp

7907110138 Weekly info rept for week ending 790525  
REHM, T A Office of the Executive Director for Operations, 79/06/01 26pp.

7907110309 Provides info requested re worker exposure to radiation & radioactive matl in connection w/TMI accident.  
HENDRIE, J M Commission 79/05/23 2pp

7907130512 Ack receipt of 790502 ltr. Welcomes suggestions & comments on TMI event. Appreciative of suggestion for NRC to keep informed on what other agencies are doing re event  
HENDRIE, J M Commission 79/06/21 1p.

7907130527 Expresses appreciation for support DOE provided during NRC response to TMI accident  
HENDRIE, J M Commission 79/06/22 1p.

7907130529 Expresses appreciation for support HEW provided during NRC response to TMI accident.  
HENDRIE, J M Commission, 79/06/22 1p

7907130532 Expresses appreciation for support EPA provided during NRC response to TMI accident  
HENDRIE, J M Commission, 79/06/22 1p.



7907130535 Expresses appreciation for support HUD provided during NRC response to TMI accident  
HENDRIE, J M Commission 79/06/22 1p

7907130537 Expresses appreciation for support Dept of Agriculture provided during NRC response to TMI accident  
HENDRIE, J M Commission 79/06/22 1p

7907130539 Expresses appreciation for support Dept of Commerce provided during NRC response to TMI accident  
HENDRIE, J M Commission 79/06/22 1p

7907130541 Expresses appreciation for support DOD provided during NRC response to TMI accident  
HENDRIE, J M Commission 79/06/22 1p

7907130547 Forwards NRC statement of actions re GAO recommendations to NRC Response is directed to GAO Rept to Congress, "Areas Around Nuclear Facilities Should Be Better Prepared for Radiological Emergencies " W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907130550 Forwards NRC statement of actions re GAO recommendations to NRC Response is directed to GAO Rept to Congress, "Areas Around Nuclear Facilities Should Be Better Prepared for Radiological Emergencies " W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907130552 Forwards NRC statement of actions re GAO recommendations to NRC Response is directed to GAO Rept to Congress, "Areas Around Nuclear Facilities Should Be Better Prepared for Radiological Emergencies " W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907130554 Forwards NRC statement of actions re GAO recommendations to NRC Response is directed to GAO Rept to Congress, "Areas Around Nuclear Facilities Should Be Better Prepared for Radiological Emergencies " W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907130557 Forwards NRC statement of actions re GAO recommendations to NRC Response is directed to GAO Rept to Congress, "Areas Around Nuclear Facilities Should Be Better Prepared for Radiological Emergencies " W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907130561 Forwards NRC statement of actions re GAO recommendations to NRC Response is directed to GAO Rept to Congress, "Areas Around Nuclear Facilities Should Be Better Prepared for Radiological Emergencies " W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907130562 Forwards NRC statement of actions re GAO recommendations to NRC Response is directed to GAO Rept to Congress, "Areas Around Nuclear Facilities Should Be Better Prepared for Radiological Emergencies " W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907130569 Forwards NRC comments on technical & structural aspects of draft EPA std, "Environ Radiation Protection Requirements for Spent Nuclear Fuel & High Level Radioactive Waste " Std encl.  
HENDRIE, J M Commission 79/06/22 8pp

7907160021 Responds to 790611 ltr re social, psychological & financial adjustments of resident inspectors & families. Agency is investigating problems encountered by families involved in program  
HENDRIE, J M Commission 79/06/21 1p.

--7907160031 Comments on social, psychological & financial adjustments of resident inspectors & families Program is asset to NRC. Recommends actions to alleviate difficulties experienced by families  
COOK, L. Affiliation Unknown 79/06/11 4pp

7907160035 Discusses development of technology in disposal of nuclear radwaste No authoritative work demonstrates that safe permanent disposal cannot be accomplished  
HENDRIE, J M Commission. 79/06/21 1p

--7907160038 Comments that no safe method for storing nuclear radwaste exists Public health is endangered by continued production of toxic matl  
NOYES, G. E. Affiliation Unknown 79/06/21 1p.

7907160041 Notifies of necessity for radiological emergency response planning GAO urges operation of nuclear facilities in areas where state & local plans meet NRC requirements NRC offers assistance in formulating state emergency response  
HENDRIE, J M Commission 79/06/18 1p

7907160045 Memorandum of understanding between NRC & DOT for regulation of safety in transportation of radioactive matl NRC is responsible for regulating safety in receipt of matl & DOT is responsible for regulating safety in transportation  
ADAMS, B Transportation, Dept of HENDRIE, J M Commission 79/06/08 11pp

7907160047 Comments on Schwartz & Collins 790625 appeal re reclassification of positions to GS-16 NRC has legal authority to reject recommendation of subordinate official  
BICKWIT, L Office of the General Counsel 79/06/28 4pp

7907160053 Requests info re health hazards to travelers in central PA as result of TMI-2 accident  
WALKER, R B House of Rep 79/05/23 1p

7907160052 Expresses appreciation for installation of emergency communication sys for reactor & fuel facility sites  
HENDRIE, J M Commission 79/06/26 1p

7907160056 Responds to 790615 ltr re complimentary copies of US News & World Rept Publication is informative & appreciated  
HENDRIE, J M Commission 79/06/23 1p

--7907160060 Notifies that complimentary copies of US News & World Rept will be sent to NRC  
SWEET, J H U S News & World Report 79/06/15. 1p

7907160068 Responds to 790508 memo re relative merits of stainless steel & zircaloy fuel rod cladding For accident similar to TMI, stainless steel would not have performance advantage over zircaloy  
CARBON, M W ACRB - Advisory Committee on Reactor Safeguards 79/06/18 2pp

7907160071 Apologizes for rude actions of NRC telephone operator  
HENDRIE, J M Commission 79/06/27 1p

7907160073 Ack receipt of 790525 ltr re proposal to share regulatory authority over sources of ionizing radiation in State of RI Notice will be published in FR Forwards public announcement re proposal  
HENDRIE, J M Commission 79/06/29 1p

--7907160083 Requests assumption of part of NRC regulatory authority over sources of ionization radiation in State of RI Program exists to protect public health & safety w/respect to matl covered by agreement.  
GARRAHEY, J J Rhode Island, State of 79/05/25 2pp

--7907160088 Unexecuted agreement between NRC & State of RI for discontinuance of certain NRC regulatory authority & responsibility within State of RI  
GARRAHEY, J J Rhode Island, State of 79/05/25 6pp

7907160137 Discusses problems in JT Long 780613 memo re alleged thefts or diversions of strategic SNM Majority of relevant threat info, compiled by JH Coran, was not used  
COCHRAN, T B Natural Resources Defense Council 78/07/18 2pp

7907160096 Submits info & estimates re vol of nuclear waste produced from spent nuclear fuel.  
HENDRIE, J M Commission. 79/06/27 2pp

7907160112 Responds to 790525 ltr re NRC authority to approve operational decisions at TMI & future damaged reactors. Authority comes from Atomic Energy Act. Forwards draft amend to Section 189 of Act to clarify authority in emergencies  
HENDRIE, J M Commission 79/06/28 3pp

7907160141 Comments on S 2, "Sunset Act of 1979." NRC strongly supports objectives of bill to promote govt efficiency by eliminating inactive & overlapping federal programs through periodic review of existing budget authority  
HENDRIE, J. M. Commission 79/06/29. 2pp

--7907160162 Forwards S 2, "Sunset Act of 1979." Requests NRC views & recommendations re provisions of bill & possible Committee action.  
RIBICOFF, A. Senate, Governmental Affairs 79/06/01 1p

## NONDOCKETED ITEMS

7907160168 Ack receipt of 790621 ltr providing addl info on successful effort for amend re resident inspector program NRC is prepared to implement Congressional mandate as soon as possible  
HENDRIE, J M Commission 79/06/29 1p

--7907160192 Informs of amend offered to HR 4388 to add \$5 million to NRC appropriations to permit hiring & training of resident inspectors Forwards pages of Congressional Record covering debate on amend  
GLICKMAN, D House of Rep 79/06/21 5p

7907160202 Responds to 790514 query re emergency preparedness & nuclear waste disposal Provides personal views on proposed licensing & rulemaking re state responsibility for emergency planning & role of states in waste mgt Forwards NUREG-0529 W/o encl  
HENDRIE, J M Commission 79/06/26 5pp

7907160239 Responds to 790514 request for NRC views on proposed amend to HR 2608 re authority to charge fees for licenses, permits & insps Summarizes activity costs & forwards fee schedule Legislation is not needed at present.  
HENDRIE, J M Commission 79/06/21 3pp

--7907160254 Forwards amend to HR 2608 re recovery of costs by NRC for permits, licenses & insps Requests info re NRC cost recovery program & estimated total annual unrecovered expenditures, by category  
VENTO, B F House of Rep 79/05/14 6pp

--7907160263 Forwards FR notice re revised license fee schedule for NRC Facility & matl licenses  
DONOGHUE, D J Office of Administration 78/02/28. 24pp

7907160278 Responds to 790514 info request Forwards NRC rept containing contract info & data re OMB Circular A-76  
HENDRIE, J M Commission 79/06/18 4pp

--7907160303 Requests info re practice of contracting out by Federal agencies of industrial type goods & svcs, as regards OMB Circular A-76  
HARRIS, H E House of Rep 79/05/14 1p

7907160312 Ack receipt of 790309 ltr re low level waste disposal Discusses comments & reviews NRC program re waste disposal Forwards NUREG-0456 & NUREG-0240, 780818 FR notice & notice of proposed rulemaking  
HENDRIE, J M Commission 79/06/18 3pp

--7907160336 Expresses concern about disposal of low level waste Definition of low level waste is misleading & method for disposal must never produce increase in population exposure Shallow land burial allows for migration of matls  
STEVENSON, A E Senate, Commerce, Science & Transportation 79/05/09 3pp

--7907160344 FR notice re development of radioactive waste disposal classification sys.  
DRAGONETTE, K S Low Level Waste Branch (Pre 790501) 78/08/18 4pp

--7907160351 NUREG-0240  
"Low Level Radioactive Waste Mgt Program"  
\* Division of Fuel Cycle & Material Safety 77/09/30 32pp

--7907160358 Advance notice of proposed rulemaking re mgt & disposal of low level wastes by shallow land burial & alternative disposal methods  
CHILK, S J Office of the Secretary of the Commission 78/10/25 2pp

7907180613 Forwards IE Bulletin 79-07 "Seismic Stress Analysis of Safety-Related Piping" & forwards draft cover letter  
MOSELEY, N C Division of Reactor Operations Inspections. 79/04/14 2pp

--7907180622 IE Bulletin 79-07 Seismic Stress Analysis of Safety-Related Piping  
\* Office of Inspection & Enforcement. 79/04/14 3pp.

7907190253 Weekly info rept for week ending 790608  
REHM, T A Office of the Executive Director for Operations. 79/06/14. 27pp.

7907230178 Ack receipt of 790213 ltr re specific statutory authority for issuance of 10CFR73.40.  
BICKNIT, L Office of the General Counsel. 79/07/04 5pp.

--7907230180 Requests formal statement re specific basis for issuance of 10CFR73.40  
WILENS, P Justice, Dept of 79/02/13 2pp

7907230187 Denies 781023 petition to reconsider issuance of security, personnel qualification, training & equipment requirements NUREG-0219 & NUREG-0464 do not overlap guidance Burden of requirements is considered acceptable  
HENDRIE, J M Commission 79/07/10 3pp

--7907230198 FR notice re denial of KMC, Inc petition for deferral of implementation of rule in 10CFR73 "Security Personnel Qualifications, Training & Equipment Requirements"  
CHILK, S J Office of the Secretary of the Commission 79/07/10 7pp

--7907230191 Review Guideline 23 re protection of nuclear power plants against industrial sabotage by insider  
CLARK, R A Reactor Safeguards Licensing Branch 79/07/10 4pp

--7907230201 "Study to Assess Radiological Sabotage Potential of Operating Nuclear Power Plants"  
\* KMC, Inc 79/07/10 21pp

7907230472 Submits statement on NRC actions being taken re QAO rept, "Comments on NRC Use of DOE Labs & of Outside Contractors & Consultants" Forwards response to QAO rept W/o encl  
HENDRIE, J M Commission 79/07/05 1p

7907230484 Submits statement on NRC actions being taken re QAO rept, "Comments on NRC Use of DOE Labs & of Outside Contractors & Consultants" Forwards response to QAO rept W/o encl  
HENDRIE, J M Commission 79/07/05 1p.

7907230490 Submits statement on NRC actions being taken re QAO rept, "Comments on NRC Use of DOE Labs & of Outside Contractors & Consultants" Forwards response to QAO rept, W/o encl  
HENDRIE, J M Commission 79/07/05 1p

7907230500 Submits statement on NRC actions being taken re QAO rept, "Comments on NRC Use of DOE Labs & of Outside Contractors & Consultants" Forwards response to QAO rept W/o encl  
HENDRIE, J M Commission 79/07/05 1p

7907230518 Submits statement on NRC actions being taken re QAO rept, "Comments on NRC Use of DOE Labs & of Outside Contractors & Consultants" Forwards response to QAO rept W/o encl  
HENDRIE, J M Commission 79/07/05 1p

7907230534 Submits statement on NRC actions being taken re QAO rept, "Comments on NRC Use of DOE Labs & of Outside Contractors & Consultants" Forwards response to QAO rept  
HENDRIE, J M Commission 79/07/05 27pp

7907230554 Responds to 790411 questions re 10CFR71 App E, "QA Criteria for Shipping Packages for Radioactive Matl" & policy for notifying agreement states of NRC developments Forwards correspondence w/QAO & relevant policies & procedures  
HENDRIE, J M Commission 79/07/06 3pp

--7907230565 Forwards Std Form 83 & supporting statement covering 10CFR71 51 62(c) & 71 63(c)  
FELTON, J M Division of Rules and Records 77/07/27 6pp

--7907230586 Responds to 770727 request for review & clearance of new recording & recordkeeping requirements in 10CFR71 51, 71 62(c) & 71 63(c) Requirements are consistent w/provisions of Public Law 93-153  
LOVELADY, J M General Accounting Office B-180225 77/09/12 2pp.

--7907230611 Policy & procedures re notifying agreement states of NRC developments  
\* Commission 76/11/20 3pp

--7907230619 Requests info re economic consequences of 10CFR71 App E if allowed to apply to both fissile & byproduct matls, info re policy for informing agreement states of NRC developments  
PAUL, R. House of Rep 79/04/11 1p

7907230627 Responds to 790531 ltr re review of crashworthiness requirements for containers used to ship small quantities of Pu by air Discusses background & explains crashworthiness requirements, necessary per Public Law 94-79  
HENDRIE, J M Commission 79/07/06 2pp.

--7907230635 Requests review of crashworthiness requirements for containers in which small quantities of radioactive materials are shipped, in light of IAEA need for rapid shipment of safeguard samples of Pu  
GLENN, J Senate, Governmental Affairs 79/05/31 2pp.

7907230657 Ack receipt of Port Authority of NY & NJ 790529 invitation to attend 790621 Congress for Regional Recovery Attendance precluded by previous commitment  
HENDRIE, J M Commission 79/06/08 1p

--7907230660 Invites JM Hendrie to participate in Congress for Regional Recovery 790621 conference re guidance strategies for regions policies through next decade  
GOLDMARK, P C Affiliation Unknown 79/05/29 1p

7907240516 Weekly info rept for week ending 790601  
REHM, T A Office of the Executive Director for Operations 79/06/08 33pp

7907250157 Supports objectives of Executive Order 11991 to make EIS process more useful to decision-makers Statement does not provide guidance on how CEQ & NRC conflicts can best be resolved Outlines guidelines which could be used  
HENDRIE, J M Commission 79/05/31 2pp

7907250171 Ack receipt of 790305 ltr which enumerated public misconceptions that have been generated by policy statement re WASH-1400 NRC has supplemental policy statement in testimony at Congressional hearing  
HENDRIE, J M Commission 79/06/05 1p

--7907250173 Outlines misconceptions re NRC policy statement on WASH-1400  
REICHLE, L Ebasco Services, Inc (subs of Enserch Corp) 79/03/05 3pp

7907250180 Ack receipt of statement before Subcommittee on Energy Research & Production Explanation of Naval reactor principles was straightforward, interesting & helpful  
HENDRIE, J M Commission 79/06/05 1p

7907250247 Weekly info rept for week ending 790615  
REHM, T A Office of the Executive Director for Operations 79/06/21 27pp

7907250610 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments  
HENDRIE, J M Commission 79/06/01 2pp

7907260431 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments  
HENDRIE, J M Commission 79/06/01 1p

--7907260464 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comment  
HENDRIE, J M Commission 79/06/01 1p

--7907260473 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments  
HENDRIE, J M Commission 79/06/01 1p.

--7907260482 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments  
HENDRIE, J M Commission 79/06/01 1p

--7907260491 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments.  
HENDRIE, J M Commission 79/06/01 1p

--7907260496 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments  
HENDRIE, J M Commission 79/06/01 1p

--7907260513 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments  
HENDRIE, J M Commission 79/06/01 1p

--7907260521 Pledges NRC assistance to improve emergency preparedness down to county & municipal govt levels Notes GAO position that nuclear power plants should begin operation only where emergency plans conform to NRC stds Requests comments  
HENDRIE, J M Commission 79/06/01 1p

7907260569 Ack receipt of 790419 ltr re NRC investigation of TMI Ltr will be considered during investigation  
HENDRIE, J M Commission 79/06/01 1p

--7907260571 Requests info re NRC procedures for investigating & making public causes & consequences of serious reactor accidents, since no comprehensive guidelines appear to exist Enquires re wide-ranging ramifications of TMI accident  
VARANINI, E E California, State of 79/04/19 2pp

7907270210 Ack receipt of 790309 ltr re release of WASH-1400 & Lewis rept Disagrees that NRC press release re Lewis rept was inaccurate Suggests media repts distorted NRC position Forwards policy statement, 780907 briefing & press release  
HENDRIE, J M Commission 79/06/05 3pp

--7907270217 Finds NRC press release re Lewis rept inconsistent w/rept itself Press release should be modified Enquires re NRC course of action  
KIMEL, W E American Nuclear Society 79/03/09 3pp

--7907270220 Transcript of 780907 Commission meeting w/Risk Assessment Review Group in Washington, DC Pg 1-64  
HENDRIE, J M, BRADFORD, P A, KENNEDY, R T Commission 78/09/07 66pp

7907300465 Ack receipt of 790405 ltr forwarding 790405 memo re state radiological emergency response plans  
HENDRIE, J M Commission 79/05/07 1p

--7907300475 Forwards HUD 790405 memo re radiological emergency response plan  
WILCOX, W H Housing & Urban Development, Dept of, Federal Disaster Assistance Admin 79/04/05 2pp

7907300493 Extends appreciation for arranging informative & enjoyable tour of "Flying Fish" & cruise of "Nimitz" on 790325-26  
HENDRIE, J M Commission 79/06/14 1p

7907300502 Extends appreciation for arranging tour of "Nimitz" on 790326  
HENDRIE, J M Commission 79/06/14 1p

7907300511 Extends appreciation of opportunity to tour "Flying Fish" on 790325  
HENDRIE, J M Commission 79/06/14 1p

7907300515 Extends thanks for arrangement of visits aboard "Flying Fish" & "Nimitz"  
HENDRIE, J M Commission 79/06/14 1p

7907310048 Ack receipt of 790605 invitation to address National Wholesale Druggists Association annual meeting Declines due to other commitments  
HENDRIE, J M Commission 79/06/18 1p

--7907310053 Extends invitation to address National Wholesale Druggists Association annual meeting in Nov 1979  
JOHNSON, G R, American Cyanamid Co 79/06/05 1p

7907310492 Forwards quarterly rept to Congress on number of full-time permanent employees hired & promoted during Jan-Mar 1979.  
HENDRIE, J M Commission 79/06/01 1p

--7907310500 Forwards quarterly rept to Congress on number of full-time permanent employees hired & promoted during Jan-Mar 1979.  
W/o encl.  
HENDRIE, J M Commission 79/06/01. 1p

--7907310508 Forwards quarterly rept to Congress on number of full-time permanent employees hired & promoted in period Jan-Mar 1979  
W/o encl.  
HENDRIE, J M Commission 79/06/01 1p

## NONDOCKETED ITEMS

- 7907310516 Forwards quarterly rept to Congress on number of full-time permanent employees hired & promoted in period Jan-Mar 1979  
HENRIE, J M Commission 79/05/01 1p
- 7907310527 Forwards quarterly rept to Congress on number of full-time permanent employees hired & promoted in period Jan-Mar 1979  
HENRIE, J M Commission 79/05/01 3pp
- 7907310541 Responds to 790412 ltr re impact of NRC regulation of nuclear pharmacies NRC has authority to license & regulate possession & use of byproduct mfgs FDA has authority to regulate mfg, sale & distribution of all drugs  
HENRIE, J M Commission 79/05/05 2pp
- 7907310551 FR notice re NRC regulation of medical uses of radioisotopes & statement of general policy  
CHILK, S J Office of the Secretary of the Commission 79/02/09 App
- 7907310556 Forwards RD Ice, Dean of Pharmacy at Univ of OK, 790330 ltr re NRC regulation of nuclear pharmacy Requests info & clarification re impact of Regulations on state control of pharmacy practice  
BELLMON, H Senate 79/04/12 App
- 7907310564 Responds to 790411 ltr re impact of NRC regulation of nuclear pharmacies NRC has authority to license & regulate possession & use of byproduct mfgs FDA has authority to regulate mfg, sale & distribution of all drugs  
HENRIE, J M Commission 79/05/05 2pp
- 7907310578 Forwards RD Ice, Dean of Pharmacy at Univ of OK, 790330 ltr re NRC regulation of nuclear pharmacy Requests info & clarification re impact of Regulations on state control of pharmacy practice  
SYNAR, M House of Rep 79/04/11 App
- 7907310605 Requests support for legislation to resolve questions re effective date provisions of U Mill Tailings Radiation Control Act of 1978 Forwards draft of statutory language & section-by-section analysis  
HENRIE, J M Commission 79/05/05 8pp
- 7907310621 Explains intent of Congress in U Mill Tailings Radiation Control Act of 1978 NRC has immediate authority over mill tailings in non-agreement states Agreement states have 3 years in which to meet new statute requirement  
RANDOLPH, J, HART, G, DOMENICI, P Senate 79/04/26 2pp
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 7907030268 Notification of contract execution, Mod 4 to "JURIS Automatic Legal Research Sys"  
MAGAN, T F Administrative Contracts Branch NRC-14-76-335 79/05/17 1p
- 7907030274 Mod 4, incorporating contract effort for FY79, increasing obligation of funds & changing contract number to "JURIS Automatic Legal Research Sys"  
MATTIA, M J Division of Contracts NRC-14-76-335 79/05/17 1p
- 7907090113 Notification of contract execution "TMI Incident Special Inquiry Team," awarded to BC Doyle  
MORTON, K V Research Contracts Branch FIN B-1560 NRC-17-79-453 79/05/31 1p
- 7907090118 Contract "TMI Incident Special Inquiry Team," awarded to BC Doyle  
DOMOGHUE, D J Division of Contracts NRC-17-79-453 79/05/16 8pp
- 907090463 Mod 1, deleting Task II in its entirety & adding new Task II for data collection, tabulation & mechanization  
MORTON, K V Research Contracts Branch NRC-05-78-300 78/08/03 1p
- 7907100003 Notification of contract execution, Mod 6 to "Pipe Rupture Studies" Contractor Battelle Columbus Lab  
MYNATT, A Research Contracts Branch FIN B-5409 NRC-04-76-293-0 79/03/22 1p
- 7907100006 Mod 6 adding addl work & increasing fees to "Pipe Rupture Studies"  
MORTON, K V Research Contracts Branch FIN B-5409 NRC-04-76-293 79/05/23 2pp
- 7907100008 Notification of contract execution, Mod 2 to "Studies of Methods of Generating Few Broad-Group Cross-Sections for Fast Reactor Accident Analysis" Contractor Howard Univ  
HAGEY, H Research Contracts Branch FIN B-6265 NRC-04-77-12 79/04/01 1p
- 7907100013 Mod 2 extending period of performance to "Studies of Methods of Generating Few Broad-Group Cross-Sections for Fast Reactor Accident Analysis"  
MORTON, K V Research Contracts Branch FIN B-6265 NRC-04-77-156 79/04/01 2pp
- 7907100698 Notification of contract execution, Mod 07 to "BWR-Blowdown Heat Transfer Research" Contractor OE  
MYNATT, A Research Contracts Branch FIN B-3014 NRC-04-76-21 79/05/11 1p
- 7907100705 Mod 07 increasing funding to "BWR-Blowdown Heat Transfer Research"  
ON, K V Research Contracts Branch FIN B-3014 NRC-04-76-21 79/05/11 2pp
- 7907100704 Notification of contract execution "Canadian Seismic Agreement," awarded to Canadian Commercial Corp  
MYNATT, A Research Contracts Branch FIN B-6275 NRC-04-79-15 79/05/09 1p
- 7907100707 Contract for "Canadian Seismic Agreement," awarded to Canadian Commercial Corp  
MORTON, K V Research Contracts Branch FIN B-6275 NRC-04-79-160 79/05/09 5pp
- 7907100711 Notification of contract execution, Mod 02 to "Application of Acoustic Emission as On-Line Monitoring Sys for Nuclear Reactors" Contractor Dunagan/Endevco  
MORTON, K V Research Contracts Branch FIN B-3013 AT(49-241-0219 79/05/11 1p
- 7907100716 Mod 02 extending period of performance & increasing funding to "Application of Acoustic Emission as On-Line Monitoring Sys for Nuclear Reactors"  
MORTON, K V Research Contracts Branch FIN B-3013 AT(49-241-0219 79/05/11 1p
- 7907100723 Notification of contract execution "Radiation Monitoring Svc," awarded to Radiation Mgt Corp  
MORROW, L A Administrative Contracts Branch FIN B-1004 NRC-05-79-265 79/05/30 1p
- 7907100728 Contract for "Radiation Monitoring Svc," awarded to Radiation Mgt Corp  
MATTIA, M J Administrative Contracts Branch FIN B-1004 NRC-05-79-265 79/05/30 14pp
- 7907110061 Notification of contract execution, Mod 3 to "Effect of Scale on Two-Phase Countercurrent Flow Flooding in Vertical Tubes" Contractor Dartmouth College  
HAGEY, H Research Contracts Branch FIN B-5816 NRC-04-76-329 79/04/01 1p
- 7907110063 Mod 3, extending period of performance to "Effect of Scale on Two-Phase Countercurrent Flow Flooding in Vertical Tubes"  
MORTON, K V Research Contracts Branch FIN B-5816 NRC-04-76-329 79/04/01 2pp
- 7907110387 Notification of contract execution, Mod 3 to "Modular Approach to Fault-Tree & Reliability Analysis" Contractor MIT  
HAGEY, H Research Contracts Branch FIN B-6256 NRC-04-77-150 79/05/23 1p
- 7907110439 Mod 3, extending period of performance for 2 months, at no cost, to "Modular Approach to Fault-Tree & Reliability Analysis"  
MORTON, K V Research Contracts Branch FIN B-6256 NRC-04-77-150 79/05/23, 2pp.
- 7907110532 Notification of contract execution "TMI Incident Special Inquiry Team," awarded to CD Miller  
MORTON, K V Research Contracts Branch NRC-17-79-452 79/05/16 1p
- 7907110547 Contract "TMI Incident Special Inquiry Team," awarded to CD Miller  
DOMOGHUE, D J Office of Administration NRC-17-79-452 79/05/16 8pp

7907120139 Notification of contract execution, Mod 4 to "Study of New England Seismicity w/Emphasis on MA & NH " Contractor MIT  
HAGEY, H Research Contracts Branch FIN A-4058 NRC-04-76-209  
79/05/23 1p

--7907120152 Mod 4, extending period of performance for three months to "Study of New England Seismicity w/Emphasis on MA & NH " MORTON, K V Research Contracts Branch FIN A-4058  
NRC-04-76-209 79/05/23 2pp

7907120174 Notification of contract execution, Mod 3, to "Commercial LMFBR Safety Study " Contractor UCLA  
MYNATT, A Research Contracts Branch FIN B-3019 NRC-04-76-246  
79/05/23 1p

--7907120181 Mod 3 revising work scope, extending period of performance & increasing funding to "Commercial LMFBR Safety Study " MORTON, K V Research Contracts Branch FIN B-3019  
NRC-04-76-246 79/05/23 3pp

7907130061 Notification of contract execution, Mod 1 to "Payroll Requirements Analysis " Contractor Small Business Administration  
MEDROW, L A Administrative Contracts Branch FIN B-5131  
NRC-09-790388 79/06/04 1p

--7907130073 Mod 1, revising period of performance to 790608, to "Payroll Requirements Analysis " MATTIA, M J Administrative Contracts Branch FIN B-5131  
NRC-09-79-388 79/06/04 3pp

7907180316 Notification of contract execution, Mod 1 to "Study of Regional Tectonics & Seismicity for IA " Contractor State of IA  
WOLLETT, S A Research Contracts Branch FIN B-6312  
NRC-04-78-228 79/06/28 1p

--7907180322 Mod 1, extending period of performance to 790630 to "Study of Regional Tectonics & Seismicity for IA " MORTON, K V Research Contracts Branch FIN B-6312  
NRC-04-78-228 79/05/01 1p

7907180327 Notification of contract execution, Mod 1 to "Solubility of Uraninite & Migration of Fission Products Released From Spent Fuel Matrix " Contractor Harvard College  
HAGEY, H Research Contracts Branch FIN B-6662 NRC-04-78-265  
79/06/26 1p

--7907180333 Mod 1, increasing funding to "Solubility of Uraninite & Migration of Fission Products Released From Spent Fuel Matrix " MORTON, K V Research Contracts Branch FIN B-6662  
NRC-04-78-265 79/06/26 4pp

7907180344 Notification of contract execution "Study to Determine Feasibility of Conducting Epidemiologic Investigation of Health Effects of Low Level Ionizing Radiation," awarded to Systemedics, Inc  
GUSTAVE, R P Research Contracts Branch FIN V-10909  
NRC-01-79-010 79/07/10 1p

--7907180349 Contract "Study to Determine Feasibility of Conducting Epidemiologic Investigation of Health Effects of Low Level Ionizing Radiation," awarded to Systemedics, Inc  
MORTON, K V Research Contracts Branch FIN B-10909  
NRC-01-79-010, 79/07/02 6pp

7907190755 Notification of contract execution "Subsurface Radar Profiling Study of Maxey Flats, KY Waste Disposal Region," awarded to Geo-Centers, Inc  
WOLLETT, S A Research Contracts Branch FIN B-6349  
NRC-04-79-190 79/05/31 1p

--7907190765 Contract "Subsurface Radar Profiling Study of Maxey Flats, KY Waste Disposal Region " Contractor Geo-Centers, Inc  
MORTON, K V Research Contracts Branch FIN B-6349  
NRC-04-79-190 79/05/31 7pp.

7907190777 Notification of contract execution, Mod 9 to "Seismic Shear Transfer in Secondary Containment Vessels," Contractor Cornell Univ  
HAGEY, H Research Contracts Branch FIN B-5688 NRC-04-76-234.  
79/05/31 2pp

--7907190786 Mod 6, continuing funding for three yrs for "Seismic Shear Transfer in Secondary Containment Vessels," Contractor Cornell Univ  
MORTON, K V Research Contracts Branch FIN B-5688  
NRC-04-76-234 79/05/31 5pp.

7907190795 Notification of contract execution, Mod 5 to "Modeling Tornado Dynamics " Contractor Aeronautical Research Associates of Princeton  
WOLLETT, S A Research Contracts Branch FIN B-5795  
NRC-04-76-218 79/05/31 1p

--7907190812 Mod 5, increasing funding to "Modeling Tornado Dynamics " Contractor Aeronautical Research Associates of Princeton  
MORTON, K V Research Contracts Branch FIN B-5795  
NRC-04-76-218 79/05/24 1p

7907190854 Notification of contract execution, Mod 10 to "Document Distribution " Contractor Computer Data Sys, Inc  
HAGAN, T F Administrative Contracts Branch FIN 31X020 409  
NRC-10-79-399 79/06/15 1p

--7907190862 Mod 10, deleting name Electronic Composition, Inc & substituting Computer Data Sys, Inc to "Document Distribution " MATTIA, M J Administrative Contracts Branch FIN 31X0200 409  
NRC-10-79-399 79/04/09 1p

7907230694 Notification of contract execution, Mod 3 to "Evaluation of Thorium Content of Human Tissues from Grand Junction, CO " Contractor NY Univ Medical Ctr  
HAGEY, H Research Contracts Branch FIN B-5756 NRC-04-76-358  
79/05/23 1p

--7907230699 Mod 3, increasing funding to "Evaluation of Thorium Content of Human Tissues from Grand Junction, Co " MORTON, K V Research Contracts Branch FIN B-5756 79/04/16  
1p

7907230705 Notification of contract execution, Mod 5 to "Tornado Parameters for Nuclear Power Plants " Contractor Univ of Chicago  
HAGEY, H Research Contracts Branch FIN A-4059 NRC-04-74-239  
79/05/10 1p

--7907230713 Mod 5, increasing funding to "Tornado Parameters for Nuclear Power Plants " \* Division of Contracts FIN A-4059 NRC-04-74-239 79/05/10  
4pp

7907230719 Notification of contract execution, Mod 17 to "Downcomer Effects Experimental Program " Contractor CREARE, Inc  
WOLLETT, S A Research Contracts Branch FIN A-4070  
NRC-04-75-162 79/07/12 1p

--7907230722 Mod 17, increasing funding to "Downcomer Effects Experimental Program " MORTON, K V Division of Contracts FIN A-4070 NRC-04-75-162  
79/06/01 2pp

7907230728 Notification of contract execution, Mod 1 to "Evaluation of Retention & Migration Data from Natural & Inadvertent Repositories " Contractor Stanford Univ  
HAGEY, H Research Contracts Branch FIN B-6341 NRC-04-78-266  
79/06/04 1p

7907240282 Notification of contract execution "Tearing Stability Analysis for LWR Piping," awarded to Washington Univ  
MENCZER, W B Technical Assistance Contracts Branch  
NRC-03-79-134, 79/06/06 1p

--7907240286 Contract, "Technical Assistance in Tearing Stability Analysis in LWR Piping," awarded to Washington Univ  
DOUGHERTY, D J Division of Contracts FIN B-6571 79/06/06  
15pp

7907250121 Notification of contract execution "Analysis of Limit of Error Inventory Difference Calculations at Specific Nuclear Facility," awarded to Science Applications, Inc  
MCNULTY, A Purchasing Section FIN B-6452-9 NRC-02-79-044  
79/06/13 1p

--7907250124 Contract: "Analysis of Limit of Error Inventory Difference Calculations at Specific Nuclear Facility," awarded to Science Applications, Inc  
HARGETT, D J Division of Contracts FIN B-6452-9 79/06/13  
11pp.

7907250127 Notification of contract execution, Mod 1 to "Document Registration, Announcement, Marketing & Purchases " Contractor: Dept of Commerce, NTIS  
MEDROW, L K Administrative Contracts Branch NRC-10-75-106  
AT(49-24)-0106 79/05/14 1p



# NONDOCKETED ITEMS

33

7907270018 Notification of contract execution, Mod 11 to "Document Distribution " Contractor Computer Data Systems Inc  
HAGAN, T F Research Contracts Branch FIN 31X0200 409  
NRC-10-78-399 79/06/21 1p

--7907270023 Mod 11, increasing funding for issuance of job orders to "Document Distribution"  
MATTIA, M J Research Contracts Branch FIN 31X0200 409  
NRC-10-78-399 79/06/01 2pp

7907270027 Notification of contract execution, Mod 3 to "PDR Micrographic Storage & Retrieval Sys " Contractor ACCESS  
MEDROW, L A Administrative Contracts Branch FIN B-6357 NRC  
17-79-449 79/06/21 2p

--7907270031 Mod 3, changing Items 1016 & 1017, changing specs for sys, adding new line item 2007, changing delivery schedule & increasing total amount of contract  
MATTIA, M S Administrative Contracts Branch FIN B-6357  
NRC-17-79-449 79/06/14 61pp

7907270034 Notification of contract execution, Mod 2 to "Implementation & Operation of NRC Document Control Sys " Contractor TERA  
Advanced Svcs Corp  
MATTIA, M J Administrative Contracts Branch NRC-10-78-580  
31X0200 409 79/06/26 1p

--7907270041 Mod 2, forwarding addl funding increment to "Implementation & Operation of NRC Document Control Sys "  
HALMAN, E L Division of Contracts NRC-10-78-580 31X0200-409  
79/06/26 1p

7907270076 Notification of contract execution, Mod 4 to "Studies of Dynamic Loads on Pressure Suppression Containment " Contractor Regents of UCLA  
HAGEY, H Research Contracts Branch FIN B-5875 NRC-04-76-342  
79/06/11 1p

--7907270083 Mod 4, changing principal investigator from I Catton to VK Dhir, to "Studies of Dynamic Loads on Pressure Suppression Containment "  
MORTON, K V Research Contracts Branch FIN B-5875 79/05/15  
2pp

7907270093 Notification of contract execution, Mod 4 to "Extreme Max/Min Temp Analysis " Contractor Dept of Commerce (NOAA)  
GUSTAVE, R P Research Contracts Branch FIN B-10318  
NRC-01-76-340 79/05/07 1p

--7907270101 Mod 4, extending period of performance from 29 to 30 months to "Extreme Max/Min Temp Analysis "  
MORTON, K V Research Contracts Branch FIN B-10318  
NRC-01-76-340 79/05/07 1p

7907300261 Notification of contract execution "Effects on Explosives " Contractor Naval Surface Weapons Ctr.  
GLAGOLA, A F Technical Assistance Contracts Branch  
NRC-03-79-153 79/06/04 1p

--7907300271 Forwards terms of contract between NRC & Naval Surface Weapons Center  
DOUGHERTY, D J Technical Assistance Contracts Branch.  
NRC-03-79-153 79/04/24 3pp.

7907300459 Notification of contract execution, Mod 3 to "Technical Assistance for Independent Evaluation of Equipment Seismic Qualifications " Contractor Wyle Labs, Eastern Operations  
GLAGOLA, A F Technical Assistance Contracts Branch FIN B-1196  
NRC-03-78-126 79/06/07. 1p

--7907300485 Mod 3, issuing stop work order for period not to exceed 90 days to "Technical Assistance for Independent Evaluation of Equipment Seismic Qualifications "  
DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-1196. NRC-03-78-126 79/06/07. 1p

7907300473 Notification of contract execution, Mod 1 to "Sys Maint Programming " Contractor: Rehab Group, Inc  
HAGAN, T F Administrative Contracts Branch NRC-10-79-375  
79/06/14. 1p

7907300498 Notification of contract execution, Mod 3 to "Fire Protection Program Review & Evaluation." Contractor Gage-Babcock & Associates.  
GLAGOLA, A F Administrative Contracts Branch NRC-03-79-109.  
79/06/30 1p

--7907300505 Mod 3, extending period of performance through 790930 w/no addl cost to govt, to "Fire Protection Program Review & Evaluation "  
DOUGHERTY, D J Division of Contracts NRC-03-79-109 79/06/30 1p

7907300510 Mod 1, increasing funding to "Sys Maint Programming "  
MATTIA, M J Administrative Contracts Branch NRC-10-79-375  
79/06/05 2pp

7907300529 Notification of contract execution, Mod 3 to "Wind-Tunnel Measurements of Dispersion & Turbulence in Wakes of Nuclear Power Plants " Contractor CD State Univ  
HAGEY, H Administrative Contracts Branch FIN B-5827  
NRC-04-76-236 79/05/23 1p

--7907300534 Mod 3, increasing funding for one final-year period of performance to "Wind-Tunnel Measurements of Dispersion & Turbulence in Wakes of Nuclear Power Plants "  
MORTON, K V Research Contracts Branch NRC-04-76-236  
79/05/23 4pp

7907300557 Notification of contract execution: "Measurement & Stds Development for Nuclear Metals Safeguards," awarded to Dept of Commerce, NBS  
BAISEN, L Administrative Contracts Branch FIN B-60160  
NRC-01-79-011 79/06/05 1p

--7907300559 Contract for "Measurement & Stds Development for Nuclear Metals Safeguards," awarded to Dept of Commerce, NBS  
MORTON, K V Research Contracts Branch NRC-01-79-011  
79/03/14 4pp

7907300564 Notification of contract execution, Mod 14 to "Reactor Effluent & Environ Radioactivity Stds " Contractor Dept of Commerce, NBS  
BAISEN, L Administrative Contracts Branch FIN B-5118  
NRC-05-72-100 79/06/14 1p

--7907300567 Mod 14, expanding work tasks & providing funding for FY79, to "Reactor Effluent & Environ Radioactivity Stds " Contractor Dept of Commerce, NBS  
MORTON, K V Division of Contracts FIN B-5118 NRC-05-72-100  
79/06/14. 2pp

7907310051 Notification of contract execution "Automobile Impact Forces on Concrete Wall Panels " Contractor Chiapetta, Welch & Associates, Ltd  
WOLLETT, S A Research Contracts Branch FIN B-6609  
NRC-04-79-188 79/06/08 1p

--7907310057 Contract for "Automobile Impact Forces on Concrete Wall Panels," awarded to Chiapetta, Welch & Associates, Ltd.  
MORTON, K V Research Contracts Branch FIN B-6609  
NRC-04-79-188 79/06/14 7pp.

7907310073 Notification of contract execution "Workshops for State Review of NRC Policy on Decommissioning at Nuclear Facilities," awarded to Small Business Administration, subcontracted to Peer Consultants, Inc  
WIGGINS, E Administrative Contracts Branch FIN 31-0200809  
NRC-06-79-304. 79/07/10 1p

--7907310090 Contract "Workshops for State Review of NRC Policy on Decommissioning at Nuclear Facilities," awarded to Peer Consultants, Inc  
BECHET, L J Division of Contracts FIN 31-0200 809  
NRC-06-79-304 79/07/10. 23pp

7907310498 Notification of contract execution "Review of Foundations & Piling for Bailey Generating Station, Nuclear-1," awarded to RF Scott,  
LITTLE, M Purchasing Section FIN B-1557 NRC-11-79-407  
79/07/10 1p

--7907310504 Contract "Review of Foundations & Piling for Bailey Generating Station, Nuclear-1," awarded to RF Scott  
HARGETT, D J. Division of Contracts FIN B-1557. NRC-11-79-407.  
79/07/10 5pp

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

7904110054 FOIA request for info re discovery & analysis of discrepancy between original results of piping analysis for seismic stresses & results of currently acceptable S&W code  
WEISS, E R Sheldon, Harmon & Roisman 79/03/19. 3pp

- 7904110054 FOIA request for info re discovery & analysis of discrepancy between original results of piping analysis for seismic stresses & results of currently acceptable B&W code  
WEISS, E R Sheldon, Harmon & Roisman 79/03/19 3pp
- 7904110054 FOIA request for info re discovery & analysis of discrepancy between original results of piping analysis for seismic stresses & results of currently acceptable B&W code  
WEISS, E R Sheldon, Harmon & Roisman 79/03/19 3pp
- 7905010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41, info on seismic issues prepared for SEP & insp repts for Beaver Valley  
WEISS, E R Sheldon, Harmon & Roisman 79/03/19 2pp
- 7905010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41, info on seismic issues prepared for SEP & insp repts for Beaver Valley  
WEISS, E R Sheldon, Harmon & Roisman 79/03/19 2pp
- 7906010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41, info on seismic issues prepared for SEP & insp repts for Beaver Valley  
WEISS, E R Sheldon, Harmon & Roisman 79/03/19 2pp
- 7906070309 Forwards redraft of NRC response to Senator Hart 790403 ltr, listing major changes Encl Withheld (ref FOIA Exemption 5)  
HAMMERER, C Office of Congressional Affairs 79/04/17 2pp
- 7907020097 Forwards summary of B&W plant insp for 790416 w/IE site inspector daily repts of B&W reactors for 790416  
DAVIS, J G Office of Inspection & Enforcement 79/04/20 2pp
- 7907020098 FOIA request for all documents re nuclear reactors at Univ of UT  
ROBINSON, N Deseret News Salt Lake City, UT 79/04/02 1p
- 7907020100 Responds to 790402 request for documents re nuclear reactors at Univ of UT As result of TMI accident & public interest in investigation, will be unable to complete response to request within statutory time limits  
FELTON, J M Division of Rules and Records 79/06/11 2pp
- 7907020105 Responds to request for documents related to LWR Insp Programs MC-2512 & MC-2515 for const & operation phases Info may be found in publication, "IE Manual" located in NRC PDR  
FELTON, J M Division of Rules and Records 79/06/11 1p
- 7907020106 FOIA request for documents relating to LWR Insp Programs MC-2512 & MC-2515 for const & operation phases  
FAUTH, W L W L Fauth & Associates, Inc 79-61 79/05/16 3pp
- 7907020111 Responds to FOIA request for documents or correspondence between NRC & ME Deutsch, LW Mead, Mead Diagnostics, Inc &/or Thyroid Diagnostics, Inc  
FELTON, J M Division of Rules and Records 79/05/30 6pp
- 7907020116 FOIA request for any documents or correspondence between NRC & ME Deutsch, LW Mead, Mead Diagnostics, Inc &/or Thyroid Diagnostics, Inc  
LEE, W F Haie & Door 79/03/22 2pp
- 7907020122 Responds to 790316 request for documents indexed or maintained under Cornell Univ Forwards listing of documents available Info partially withheld social security numbers & salary statements of individuals (ref FOIA Exemption 6)  
FELTON, J M Division of Rules and Records 79/05/30 53pp
- 7907020122 Responds to 790316 request for documents indexed or maintained under Cornell Univ Forwards listing of documents available Info partially withheld social security numbers & salary statements of individuals (ref FOIA Exemption 6)  
FELTON, J M Division of Rules and Records 79/05/30 53pp
- 7907020128 Corrects info contained in 790530 ltr Info partially withheld social security numbers & salary statements of individuals (ref FOIA Exemption 6)  
FELTON, J M Division of Rules and Records 79/06/07 1p
- 7907020128 Corrects info contained in 790530 ltr Info partially withheld social security numbers & salary statements of individuals (ref FOIA Exemption 6)  
FELTON, J M Division of Rules and Records 79/06/07 1p
- 7907020132 FOIA request for documents indexed or maint under name of Cornell Univ & documents retrievable in a search relating in any way to Cornell Univ  
LOWE, T J Civil Liberties Union, New York, Cornell Chapter 79/02 2pp
- 7907020132 FOIA request for documents indexed or maint under name of Cornell Univ & documents retrievable in a search relating in any way to Cornell Univ  
LOWE, T J Civil Liberties Union, New York, Cornell Chapter 79/02 2pp
- 7907020134 Forwards IE site inspector daily repts of B&W reactors  
790418  
DAVIS, J G Office of Inspection & Enforcement 79/04/20 1p
- 7907020143 FOIA request for RFP under Contract NRC-04-74-2403 10, "Shipping Cask Sabotage Source Term Investigation"  
MASSENGALE, E W ORI, Inc 79/06/12 1p
- 7907020146 Responds to FOIA request for RFP under Contract NRC-04-74-2403-10, "Shipping Cask Sabotage Source Term Investigation" Confirms 790622 telcon withdrawing request  
FELTON, J M Division of Rules and Records 79/06/21 1p
- 7907020297 "Transients & Natural Circulation in Westinghouse Plant" \* Commission 79/06/18 76pp
- 7907020329 Addresses Westinghouse response to Item 7c of IE Bulletin 79-06A Concurs w/vendor position re incorporation of reactor coolant pressure operating limits & overview of safety analysis re procedural changes  
OLEHINSKI, J Division of Systems Safety 79/05/23 2pp
- 7907020330 Forwards addl info re small breaks, to 790516 submittal  
ANDERSON, T M Westinghouse Electric Corp NG-TMA-2009 79/05/21 18pp
- 7907020341 Requests info re technical axis for steam generator dryout times in support of data provided by Westinghouse 790501 ltr  
THADANI, A Division of Systems Safety 79/05/23 1p
- 7907020407 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Draft forwarding ltr encl  
MOSELEY, N C Office of Inspection & Enforcement 79/05/10 2pp
- 7907020411 IE Bulletin 79-10, "Requalification Training Program Statistics" \* Office of Inspection & Enforcement 79/05/11 7pp
- 7907020414 Discusses policy matters requiring settlement re bulletin Bulletin review group has completed initial appraisal Proposes ltr be sent to each util, summarizing major deficiencies of entire class of plant Draft ltr encl  
ROSS, D F Division of Project Management 79/05/22 3pp
- 7907020482 Forwards questions re small break analyses for C-C & Westinghouse licenses  
ROBZTOCZY, Z R Analysis Branch 79/05/08 7pp
- 7907020484 Advises that A Thadani 790518 memo re stuck open power relief valve at foreign PWR has been changed from confidential to proprietary  
BURKE, K D Office of International Programs 79/05/24 1p
- 7907020489 Submits daily digest for 790531  
ROSS, D F Division of Project Management 79/06/01 2pp
- 7907020490 Forwards 790529 memo requesting Opc of Nuclear Reactor Regulation evaluate concerns raised by Region 3 inspector JS Creswell Requests input by 790615  
MATTSO, R, J Division of Systems Safety 79/05/30 1p
- 7907020492 Forwards list of safety concerns raised by JS Creswell as result of TMI incident. Requests evaluation & input  
MOSELEY, N C Division of Reactor Operations Inspections 79/05/27 1p.
- 7907020505 Forwards comments on ACRS recommendations & B&W position re natural circulation & instrumentation to diagnose & follow accident  
HELMES, C J Standardization Branch 79/06/01 1p.



# NONDOCKETED ITEMS

33

--7907020507 Comments on ACRS recommendations & B&W position re natural circulation & instrumentation to diagnose & follow accident  
KANE, E Babcock & Wilcox Co 79/05/30 21pp

7907020510 Submits input to Dfc of Nuclear Regulatory Research draft budget amend Research should be directed toward upgrading control & protection of safety std  
ROSS, D F Division of Project Management 79/06/01 6pp

7907030100 FOIA request for info re Metals & Controls Corp  
SULLIVAN, J W Affiliation Unknown 79/05/05 2pp

7907030106 Responds to FOIA request for info re Metals & Controls Corp  
Forwards files re Metals & Control, Inc & TX Instruments, Inc 1959-73 insps info partially withheld names of exposed individuals (ref FOIA Exemption 6)  
FELTON, J M Division of Rules and Records 79/05/25 800pp

7907030108 Responds to 790403 request to DOE relative to TMI  
Forwards list of documents Documents subject to FOIA request 79-78 & are in NRC PDR  
FELTON, J M Division of Rules and Records A2R/DOE/79/3 79/06/27 2pp

7907030110 Responds to FOIA request for info re gas enrichment plant being developed by Pakistan No NRC-originated documents exist Request has been referred to CIA, Dept of State & Defense Intelligence Agency  
FELTON, J M Division of Rules and Records NRDC/TBC/79-14 79/06/19 1p

7907030112 FOIA request for info re gas centrifuge enrichment plant being developed by Pakistan as it relates to nuclear weapons proliferation Requests info related to financing of plant by other countries  
COCHRAN, T B Natural Resources Defense Council 79/04/26 1p

7907030134 Forwards fourth NRC Annual Rept for transmittal to Congress re NRC activities from 771001-780930  
HENDRIE, J M Commission 79/02/14 26pp

7907030146 Responds to FOIA request for records re NRC policies governing waiver of search & copying fees for documents requested under FOIA  
FELTON, J M Division of Rules and Records 79/06/15 1p

7907030148 FOIA request for info re waiving &/or reduction of fees charged for searching & reproducing documents requested in public interest  
MARTIN, D E Affiliation Unknown 79/01/25 1p

7907030149 FOIA request for rept describing nature of work performed in reactors w/summary of precautions taken to ensure safe operation & summary of any accident - evacuation plans  
PETRUSKA, M Affiliation Unknown 79/03/28 1p

7907030150 FOIA request for info re 10CFR11 Request includes info re organizational structure of ASLB, duties, responsibilities & authorities of panel, procedures for selecting panel members & review procedures for board & panel decisions  
HUNT, B D Affiliation Unknown 79/05/30 1p

7907030153 Responds to FOIA request Forwards documents re 10CFR11, including details of subjects related to NRC ASLB subgroups & boards  
FELTON, J M Division of Rules and Records 79/06/13 35pp

--7907030155 Submits 790604 revised structural organization chart for NRC  
HALLER, N M Office of Management and Program Analysis 79/06/04 2pp

--7907030157 "NRC Functional Organization Charts."  
FETTI Office of Management and Program Analysis 79/01/01 6pp

7907030154 Responds to FOIA request re nature of work performed in reactor, w/summary of precautions taken to ensure safe operation of reactor & summary of any accident-evaluation plans.  
FELTON, J M Division of Rules and Records 79/05/31 2pp

--7907030156 SER for facility  
LEVINE, B Atomic Energy Commission, Directorate of Licensing (Pre-1975) 65/07/29 4pp

--7907030160 SER for facility.  
LEVINE, B Atomic Energy Commission, Directorate of Licensing (Pre-1975) 65/12/10 3pp

--7907030163 Emergency procedures re evacuation  
TOTERBIER, R E Pennsylvania State Univ 74/03/06 4pp

--7907030213 Forwards IE Insp Rept 50-005/77-04 on 771207-09  
No noncompliance noted  
NELSON, P R Region 1, Philadelphia, Safeguards Branch 79/01/09 2pp

--7907030220 IE Insp Rept 50-005/77-04 on 771207-09 No noncompliance noted Major areas inspected environ protection, emergency planning & radiation control programs  
KOTTAN, J J, STOHR, J P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/01/06 8pp

7907030159 Forwards TB Cochran of NRDC 790427 FOIA request for info re MB-10 applications for retransfer of spent nuclear fuel from Japan, Switzerland, Spain & Sweden  
SLAWSON, R N Energy, Dept of 79/05/25 2pp

7907030165 Responds to FOIA request for info re MB-10 application for retransfer of spent nuclear fuel from Japan, Switzerland, Spain & Sweden Forwards 790328 & 790511 ltrs from J Shea to H Bengelsdorf re Swedish retransfers of fuel assemblies  
FELTON, J M Division of Rules and Records NRDC/TBC/79-12 79/06/11 1p

--7907030169 Addresses proposed retransfer from Sweden to United Kingdom of 182 irradiated fuel assemblies NRC has no objections  
Confident assessment of US controls over retransfer depends on knowing provisions of contract, which is unavailable  
SHEA, J R Office of International Programs 79/03/28 1p

--7907030172 Addresses proposed retransfers from Switzerland to United Kingdom of 40 irradiated PWR fuel assemblies & retransfer from Switzerland to France of 63 BWR fuel assemblies NRC has no objection  
SHEA, J R Office of International Programs 79/03/11 1p

7907030264 Responds to 790426 request for info re sabotage in France of nuclear reactor equipment destined for Iraq No NRC-originated records subj to request One requested document originated by CIA Request being referred to CIA  
FELTON, J M Division of Rules and Records 79/06/25 1p

7907030274 FOIA request for info re sabotage of nuclear reactor equipment in France destined for Iraq  
COCHRAN, T B Natural Resources Defense Council NRDC/TBC/79-18 79/04/26 1p

7907030307 Responds to FOIA request for drawings & specs of Co-60 teletherapy unit, Model Eldorado 60 mfg by AECL Forwards specs Drawings withheld (ref FOIA Exemption 4)  
FELTON, J M Division of Rules and Records 79/06/19 2pp

7907030310 FOIA request for drawings & specs of Co-60 teletherapy unit Model Eldorado 60 mfg by AECL  
KREYBA, F J Northeast Utilities 79/05/15 1p

7907030311 Forwards AZ Roisman of NRDC 790403 FOIA request for documents related to TMI Incident Requests NRC review encl documents & respond directly to NRDC w/o encl  
RUDDLPH, J E Energy, Dept of 79/05/01 1p

--7907030314 FOIA request for documents relating to TMI  
ROISHAN, A Z Natural Resources Defense Council 79/04/03 1p

7907030315 Responds to FOIA request for winning proposal for Contract NRC-02-79-028, "Development of Improved Techniques"  
Forwards Science Applications, Inc Proposal 1-016-71-790-24 Document partially withheld (ref FOIA Exemption 4).  
FELTON, J M Division of Rules and Records 79/06/25 1p

7907030317 FOIA request for winning technical proposal for Contract NRC-02-79-028, "Development of Improved Techniques"  
RAGAN, K M Kinetic Research, Inc 79/05/21 1p

7907030321 Further response to NRDC 790404 ltr. Forwards rept "Title List, Publicly Available Documents, TMI-2, Docket 50-320." Will be advised within few days re records withheld w/o encl  
FELTON, J M Division of Rules and Records 79/06/26 1p

7907030331 Responds to FOIA request for 730101-0331 documents made available to NRC by DOJ, obtained by DOJ by civil investigative demand re P&E proposal to construct Mendocino project  
FELTON, J M Division of Rules and Records 79/06/01 1p

## NONDOCKETED ITEMS

- 740700339 Responds to 740405 request for copies of OL & indemnification agreement re TMI Forwards requested records w/o encl  
FELTON, J M Division of Rules and Records 79/06/21 1p
- 790700339 FOIA request for copies of OL & indemnification agreements re TMI  
MAGS, S L Outzel & Kass 79/06/05 1p
- 790700339 Submits draft IE info notice "Deficient Procedures" re controls of emergency feedwater sys. for review & comment  
BRYAN, S E Division of Reactor Operations Inspections 79/06/04 5pp
- 7907003013 Responds to FOIA request for access to documents re possible nuclear waste disposal sites in Trumbull or Mahoning Counties OH No such documents exist  
FELTON, J M Division of Rules and Records 79/06/07 1p
- 7907003017 FOIA request for access to documents re possible nuclear waste disposal sites in Trumbull or Mahoning Counties in OH  
PAULIC, J M Affiliation Unknown 79/05/04 1p
- 7907003020 Responds to 790531 FOIA request for license files for TX Instruments & Timex Corp Forwards license files w/o encl  
FELTON, J M Division of Rules and Records 79/06/21 1p
- 7907003024 FOIA request for copy of license files for TX Instruments & Timex Corp  
MATHEWS, D M Arkansas, Univ of 79/05/31 1p
- 7907003049 FOIA request for disclosure of Reed rept  
CLINE, A Affiliation Unknown 79/06/05 1p
- 7907003053 Responds to FOIA request for disclosure of Reed rept Forwards documents supporting decision to withhold rept Rept withheld (ref FOIA Exemption 4)  
MCLFE, S J Atomic Safety and Licensing Board Panel 79/06/18 2pp
- 7907003059 Review of GE nuclear reactor study (Reed Rept) did not identify any instances of new areas of safety concern  
MINNERS, W Reactor Systems Branch KNUTH, D F Division of Reactor Safety Research 76/02/25 4pp
- 7907003063 Requests GE provide NRC w/copy of nuclear reactor study on list of safety issues identified in study  
HATTISON, R J Division of Systems Safety 78/03/06 2pp
- 7907003066 Responds to 780306 FOIA request Forwards list of safety issues identified in nuclear reactor study Request list be withheld (ref 10CFR2 790) Supporting affidavit encl  
SHERWOOD, G G General Electric Co 78/03/22 5pp
- 7907003082 Forwards summary of 27 licensing issues identified in GE nuclear reactor study (Reed rept) Requests matl be withheld (ref 10CFR2 790) Supporting affidavit encl  
SHERWOOD, G G General Electric Co 78/05/26 5pp
- 7907003085 Grants request for withholding matl re list of safety issues identified in GE nuclear reactor study (Reed rept) Withheld (ref 10CFR2 790)  
HATTISON, R J Division of Systems Safety 78/07/10 7pp
- 7907003089 Requests addl info re current status of info claimed to be proprietary Refers to FOIA-79-51 & FOIA-79-70  
FELTON, J M Division of Rules and Records 79/04/13 2pp
- 7907003092 Responds to 790413 request for addl info re status of withholding Reed rept Supporting affidavit encl Refers to FOIA-79-51 & FOIA-79-70  
EDGAR, G L Morgan, Lewis & Bockius 79/05/04 27pp
- 7907060073 Requests info re NRC policies governing waiver of search & copying fees for documents requested under FOIA  
BORLINE, J E Oregon, Univ. of, School of Law 79/05/11 2pp.
- 7907060075 Responds to 790511 ltr requesting info re NRC policies governing waiver of search & copying fees for documents requested under FOIA Forwards documents re NRC procedures & policies which became effective 790416 per 10CFR9  
FELTON, J M Division of Rules and Records 79/06/15 200pp
- 7907060142 Responds to FOIA 790530 request for documents re transportation of nuclear matl through southern IL, info on Paducah, KY facility & Allied Chemical Co in Metropolis, IL  
FELTON, J M Division of Rules and Records 79/06/25 3pp
- 7907060146 FOIA request for records re transportation of nuclear matl through southern IL, nuclear matl transported in & out of gaseous diffusion plant in Paducah, KY & info on Allied Chemical Co plant in Metropolis, IL  
ABEL, J Little Egypt Prairie Alliance 79/05/24 2pp
- 7907060439 FOIA request for ARECL ltr to NRC re claim of privilege for six drawings  
KREYBA, F. J Neutron Products, Inc 79/05/02 1p
- 7907060445 Comments on justification for continuing confidentiality of documents in App A re Theratron 80 Co-60 teletherapy unit Info is business confidential & not representative of full investment into production design  
RIDOUT, E F Atomic Energy of Canada, Ltd Q2 1 1 79/04/05 3pp
- 7907060445 Comments on justification for continuing confidentiality of documents in App A re Theratron 80 Co-60 teletherapy unit Info is business confidential & not representative of full investment into production design  
RIDOUT, E F Atomic Energy of Canada, Ltd Q2 1 1 79/04/05 3pp
- 7907060449 Responds to FOIA request for ARECL ltr to NRC re claim of privilege for six drawings Forwards EF Ridout 790405 & 0310 ltrs to JM Felton  
FELTON, J M Division of Rules and Records 79/06/20 7pp
- 7907060456 Forwards addl info to 790405 ltr re confidentiality of documents in App A. Business advantage gained by other company through release of info would constitute breach of confidence  
RIDOUT, E F Atomic Energy of Canada, Ltd 79/05/10 3pp
- 7907060456 Forwards addl info to 790405 ltr re confidentiality of documents in App A. Business advantage gained by other company through release of info would constitute breach of confidence  
RIDOUT, E F Atomic Energy of Canada, Ltd 79/05/10 3pp
- 7907090417 Responds to IE Bulletins 78-12 & 12A re atypical weld matl in reactor pressure vessel welds  
KELLEY, R E Chicago Bridge & Iron Co 79/04/24 26pp
- 7907090419 "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Response to IE Bulletins 78-12 & 78-12A - Suppl" for Mar 1979  
\* Babcock & Wilcox Co 79/03/31 200pp
- 7907090404 Responds in part to 790426 ltr re FOIA 79-86 Request was answered in 790517 ltr All info has been placed in NRC PDR  
FELTON, J M Division of Rules and Records 79/06/21 1p
- 7907090410 Appeals partial denial of request re Task Action Plans A-40 & A-41 & denial of request on seismic stress repts UCS seeks matl to evaluate potential danger to people residing near plant  
WEISS, E R Sheldon, Harmon & Roisman 79/04/26 2pp
- 7907090410 Appeals partial denial of request re Task Action Plans A-40 & A-41 & denial of request on seismic stress repts UCS seeks matl to evaluate potential danger to people residing near plant  
WEISS, E R Sheldon, Harmon & Roisman 79/04/26 2pp
- 7907090410 Appeals partial denial of request re Task Action Plans A-40 & A-41 & denial of request on seismic stress repts UCS seeks matl to evaluate potential danger to people residing near plant.  
WEISS, E R Sheldon, Harmon & Roisman 79/04/26 2pp.
- 7907090442 Appeals partial denial of 790301 request re results of survey of IE employees. Requests verbatim answers to Questions 6 & 47  
WEISS, E R Sheldon, Harmon & Roisman 79/04/26 1p.
- 7907090442 Appeals partial denial of 790301 request re results of survey of IE employees. Requests verbatim answers to Questions 6 & 47  
WEISS, E R Sheldon, Harmon & Roisman 79/04/26 1p

# NONDOCKETED ITEMS

339

790709044B Responds to W Jordan & CA Reed 790523 telcon Verbatim answers were not required under contract Forwards memo to IE personnel, final contractor rept & Mod 1 of contract re statement of work  
FELTON, J M Division of Rules and Records 79/06/21 31pp

790709044B Responds to W Jordan & CA Reed 790523 telcon Verbatim answers were not required under contract Forwards memo to IE personnel, final contractor rept & Mod 1 of contract re statement of work  
FELTON, J M Division of Rules and Records 79/06/21 31pp

--7907090451 Discusses IE personnel survey to be concluded by Opinion Research Corp  
DAVIS, J G Office of Inspection & Enforcement 78/08/01 2pp

--7907090463 Mod 1, deleting Task 11 in its entirety & adding new Task 11 for data collection, tabulation & mechanization  
MORTON, K V Research Contracts Branch NRC-05-7B-300 78/08/03 1p

--7907090464 "Special Survey Rept for Employees of IE "  
COOPER, M R Opinion Research Corp 79/03/31 27pp

790710003A Responds to FOIA request for access to documents in SH Hanauer "Nugget File" that had not previously been released to UCS Documents are in NRC PDR  
FELTON, J M Division of Rules and Records 79/06/21 1p

7907100039 FOIA request for all documents in SH Hanauer "Nugget File" that have not previously been provided to UCS Forwards list of previously released documents  
WEISS, E R Sheldon, Harmon & Roisman 79/04/25 18pp

7907100156 Responds to 790404 request Forwards 790320 message from PA Emergency Mgt Agency  
GIRSTANTAS, W A Defense Civil Preparedness Agency 79/06/25 1p

--7907100162 Forwards AZ Roisman 790404 request Ofc must determine appropriate disposition of documents originated by agency Documents subject to request are encl W/o encl  
FELTON, J M Division of Rules and Records 79/06/11 2pp

7907110157 Summarizes info available re relief & safety valve flow discharge (water & two-phase), operation & testing Summary of ETEC capabilities encl  
STOLZENBERG, H D Research Support Branch 79/05/18 10pp

7907120651 "C-E Guidelines & Operating Plant Procedures " Typical C-E guidelines & actual sample procedures from operating plants re LOCA, reactor trip, main steam line break & reactor coolant leak  
\* Combustion Engineering, Inc 79/04/12 69pp

7907120681 Forwards IE Circular 77-13, "Reactor Safety Signals Negated During Testing" for distribution to licensees Draft forwarding ltr encl  
THORNBURG, H D Division of Reactor Operations Inspections 77/09/22 2pp

--7907120686 IE Circular 77-13, "Reactor Safety Signals Negated During Testing "  
\* Office of Inspection & Enforcement 77/09/22 3pp

7907120739 Discusses comparison of feedwater transient frequencies of B&W, C-E & Westinghouse designed plants Design differences of newness may account for 60% greater frequency of transients in B&W plants  
ANDERSON, N Reactor Safety Branch 79/05/07 1p

790712074B Denies request for extension of comment period since rept already has been available for comment for five months  
RYAN, R G Office of State Programs 79/05/22 1p

--7907120752 Requests extension of 90 days for comments on rept of NRC/EPA Task Force on Emergency Planning re state & local govt emergency response plans  
REED, C. Commonwealth Edison Co 79/05/10 1p

7907160005 "Decay Heat Removal Problems Associated w/Recovery From Very Small Break LOCA for B&W 205 Fuel-Assembly PWR "  
\* Analysis Branch 77/09/01 57pp

--7907160012 Forwards NRC evaluation of topical repts BAW-10062, Revision 1, BAW-10074, Revision 1 & BAW-10075, Revision 1 re small break analyses for B&W plants  
SCHWENGER, A Light Water Reactors Branch 2 76/01/08 3pp

--7907160018 Evaluation of B&W topical repts re small break analyses for B&W 145, 177 & 205 plants BAW-10062, Revision 1, BAW-10074, Revision 1 & BAW-10075, Revision 1 Repts are acceptable  
\* Light Water Reactors Branch 2 76/01/08 3pp

7907160249 "Decay Heat Removal Problem Associated w/Recovery From Very Small Break LOCA for C-E Sys 80 PWR "  
\* Analysis Branch 77/05/15 49pp

7907160355 Transmits contents of Davis-Case undated memo, informing of establishment of task group to evaluate generic aspects of feedwater transients  
DAVIS, D K Systematic Evaluation Programs Branch (Pre 790625) 79/03/28 1p

7907180124 "Background Matl for Development of Radiation Protection Stds, Protective Action Guides for Sr-89, Sr-90 & Cs-137, " Rept 7  
\* Federal Radiation Council 65/05/31 47pp Available at QPO

7907180137 ERDA App 0601, Annex 16, Attachment 4, "Agreement Between US ERDA & NRC for Planning, Preparedness & Response to Emergencies "  
DANBUD, A D Energy, Dept of GOSSICK, L V Office of the Executive Director for Operations 77/08/10 7pp

7907180142 Notification of 790622 meeting of Federal Interagency Central Coordinating Committee for Radiological Emergency Preparedness in Bethesda, MD  
RYAN, R G Office of State Programs 79/05/24 2pp

7907180150 Notification of 790615 meeting of NRC/EPA Task Force on Emergency Planning & consultants in Bethesda, MD re NUREG-0396 ACRS meeting will follow in Washington, DC  
GRIMES, B K Office of Nuclear Reactor Regulation COLLINS, H E Office of State Programs 79/06/05 1p

7907180155 Notification of 790619 meeting of Interorganizational Advisory Committee meeting in Bethesda, MD to discuss NUREG-0396  
COLLINS, H E Office of State Programs 79/06/04 21pp

7907180162 "Protective Action Evaluation Part I: Effectiveness of Sheltering as Protective Action Against Nuclear Accidents Involving Gaseous Releases "  
ANNOD, G H, DORE, M A Environmental Protection Agency 78/04/30 2pp

790718016B "Protective Action Evaluation Part II: Evacuation & Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Releases "  
ANNOD, G H, DORE, M A Environmental Protection Agency 78/09/30 2pp

7907180173 "Background Matl for Development of Radiation Protection Stds, " Rept 5  
\* Federal Radiation Council 64/07/31 22pp Available at QPO

7907180456 FOIA request for winning proposal in response to NRC-RFP-78-192, "Post-Licensing Studies of Socioeconomic Impacts of Nuclear Power Station Siting," submitted by Mountain W Research, Inc  
DIMENTO, L J NUS Corp NESD-79-589/RUP 79/06/29 1p

7907180682 Responds to FOIA request for winning proposal in response to NRC-RFP-78-192, "Post-Licensing Studies of Socioeconomic Impacts of Nuclear Power Station Siting "  
FELTON, J M Division of Rules and Records 79/07/10 1p

7907180707 FOIA request for L Bickwit 790329 memo to NRC which led to SECY-A-79-42 re order concerning Nuclear Engineering Co, Inc disposal site at Sheffield, IL. Request includes 790101-0607 documents which relate to order to show cause  
CONNER, T B Conner, Moore & Corber 79/06/07 2pp

7907180715 Responds to FOIA request for documents re order to show cause & notice of hearing for period 790101-0607 Forwards App A listing documents available Documents 1-5 encl Documents 6-10 withheld (ref FOIA Exemption 5)  
FELTON, J M Division of Rules and Records 79/06/29 3pp

# NONDOCKETED ITEMS

340

- 7907190681 Responds to FOIA request for encl 1 to V Stello 790619 memo  
Commissioner Forwards requested memo & attachment, "Intosim  
Radiological Sequence of Events as of 790614" w/o encl  
FELTON, J M Division of Rules and Records 79/07/11 1p
- 7907190734 FOIA request for documents re development, const, mfg, sale or  
export of high explosive implosion devices & related  
hardware for R&D, since 1950  
COCHRAN, T B Natural Resources Defense Council 79/04/05 1p
- 7907190752 Responds to FOIA request for documents re mfg, sale or export  
of high explosive implosion devices Forwarded "Nuclear  
Weapons & Power-Related Pub" & "Resources Required to  
Make Fission Explosives" Withheld (ref JOCF2 770)  
FELTON, J M Division of Rules and Records 79/07/06 15pp
- 7907230004 Responds to 790426 FOIA request for current version of Water  
Reactor Analysis Package, JOBHUA sys & requisite  
documentation WRAP package, when completed, will contain  
proprietary info NRC evaluation of WRAP not performed  
FELTON, J M Division of Rules and Records 79/07/13 2pp
- 7907230223 Responds to 790607 FOIA request for L. Dickwit 790127 memo re  
NRC re New England Engineering Co order & other documents  
for 790101-0607 Forwards documents subj to request &  
supporting documentation  
FELTON, J M Division of Rules and Records 79/07/11 61pp
- 7907230229 PNO-79-51 summarizes visit to Sheffield waste burial site  
direct radiation detected above levels acceptable for  
release of facilities for unrestricted use  
\* Office of Inspection & Enforcement 79/03/12 1p
- 7907230235 Forwards draft order to show cause re Nuclear Engineering Co  
notification of license termination for activities at waste  
disposal site  
HIGGINSBOTHAM, L Office of Inspection & Enforcement 79/03/21  
14pp
- 7907250398 Responds to FOIA request for records re possible theft of  
more than 200 lbs of highly enriched U from B&W, Apollo  
facility & documents relating to investigation concerning  
B&W  
FELTON, J M Division of Rules and Records 79/07/09 4pp
- 7907250402 Discusses inquiry conducted at B&W on 790509-11 re MR  
Chobanian ltr to JM Hendrie concerning exposure rates &  
employment status of Chobanian  
SMITH, R H Region 1, Philadelphia, Safeguards Branch  
79/06/25 6pp
- 7907250407 Summarizes 790501 telcon w/MR Chobanian in New Kensington.  
PA re MR Chobanian 790404 ltr, Chobanian did not want to meet  
w/NRC to discuss ltr Addl info can be obtained from  
congressman  
SMITH, R H Region 1, Philadelphia, Safeguards Branch  
79/05/03 5pp
- 7907250415 Discusses NRC actions re MR Chobanian 790404 ltr to JM  
Hendrie Chobanian was contacted on 790501 to schedule  
meeting to clarify ltr items Invitation was declined Ltr  
inquiry conducted 790509-11  
SMITH, R H Region 1, Philadelphia, Safeguards Branch  
79/06/25 2pp
- 7907250435 Requests assistance in obtaining info for MR Chobanian re  
radiation exposure associated w/66130 glove box explosion  
COCHRAN, T B Natural Resources Defense Council 79/06/21 1p
- 7907250470 Requests documents re Nov 1966 exposure at NUREC Park  
Township, PA Pu facility & concerning MR Chobanian  
BZIEWIETZ, J B. Babcock & Wilcox Co 76/08/05 1p
- 7907250481 Forwards 661230 investigation rept & EL Baenger  
670404 & 0605 ltrs to L Dubinski w/Wechsler rept, w/o encl  
THOMPSON, D Office of Inspection & Enforcement 76/08/24 1p
- 7907250500 Confirms 760825 telcon re NRDC ltr to NRC requesting  
exposure info Headquarters ofc in Bethesda, MD has been  
notified of request  
SMITH, R H Region 1, Philadelphia, Office of the Director  
76/08/31 1p
- 7907250512 Forwards 661230 investigation rept & EL Baenger  
670404 & 0605 ltrs to L Dubinski w/Wechsler rept, w/o encl.  
THOMPSON, D Office of Inspection & Enforcement 76/09/20 2pp
- 7907190681 Responds to FOIA request for encl 1 to V Stello 790619 memo &  
order during 790605 Affirmation Session 79-16 re  
SECY-A-79-42 Nuclear Engineering Co, Inc disposal site at  
Sherriff, IL  
FELTON, J M Office of the Secretary of the Commission 79/06/07  
1p
- 7907190734 Comments in SECY-A-79-42 paper re Nuclear Engineering Co  
show cause order for license 13-10042-01  
FELTON, J M Commission 79/05/18 1p
- 7907190742 Consent calendar item response note re SECY-A-79-42  
Approved as modified Requests response and/or comments  
to Ofc of General Counsel/Ofc of Policy Evaluation Memo, if  
13-10042  
FELTON, J M Commission 79/05/18 1p
- 7907190752 Requests addl info re SECY-A-79-42 show cause order  
withdrew previous correspondence  
FELTON, J M Commission 79/05/11 1p
- 7907190757 Consent calendar item response note re SECY-A-79-42  
Approved as modified  
FELTON, J M Commission 79/05/10 2pp
- 7907190805 FOIA request for documents re transportation of nuclear matl  
through southern IL & info on Paducah, Ky facility & Allied  
Chemical Co plant in Metropolis, IL  
FELTON, J M Affiliation Unknown 79/05/24 2pp
- 7907190807 Responds to 790530 FOIA request Corrects error in NRC 790625  
ltr Review of requested documents was complete Ltr of 790625  
did respond to all records  
FELTON, J M Division of Rules and Records 79/07/10 1p
- 7907190831 Responds to FOIA request for NRC meeting transcripts  
Transcripts of 790313 & 0509 & portion of 790425 in PDR  
Remaining portion withheld (ref FOIA Exemptions 6 & 7)  
Transcripts 790313 & 0531 withheld (ref FOIA Exemption 1D)  
FELTON, J M Division of Rules and Records 79/06/30 2pp
- 7907190876 FOIA request for transcript of NRC meetings held on  
790313 & 10 790425 & 790508-10 & 31  
MALET, E J Affiliation Unknown 79/05/28 1p
- 7907190917 FOIA request for all responses to TM Novak 780110 memo re  
loop seals in pressurizer surge line & other documents by or  
to TM Novak which discuss issues of loop seals in B&W  
pressurizer surge lines  
WEISS, E R Union of Concerned Scientists 79/05/31 1p
- 7907190918 Responds to 790531 FOIA request for responses to TM Novak  
780110 memo re loop seals in pressurizer surge lines  
Forwards pertinent documents  
FELTON, J M Division of Rules and Records 79/07/06 2pp
- 7907190919 Discusses loop seals in pressurizer surge line Recommends  
bases for design requirement be studied for all CP reviews  
For CL reviews, procedures should be reviewed to ensure  
adequate info before operator terminates makeup flow  
NOVAK, T M Reactor Systems Branch 78/01/10 2pp
- 7907190919 Comments on TM Novak 780110 memo re loop seal Believes  
problem is one of operator training  
WATT, J J Reactor Systems Branch 79/04/09 3pp
- 7907190922 Reviews status of applicant responses to questions re PSAR  
Request for addl info encl  
IGNATOWICZ, A Reactor Systems Branch 78/01/27 10pp
- 7907190937 FOIA request for all revisions & updates of NUREG-0485  
CONNOR, L Doc-Search Associates 79/06/29 1p
- 7907190942 Responds to FOIA request for revisions & updates of  
NUREG-0485  
FELTON, J M Division of Rules and Records 79/07/13 2pp
- 7907190949 Discusses ER Weiss FOIA Request 79-76 NRC has completed  
response to original 790319 request No further action to be  
taken on 790426 appeal re NRC failure to provide response to  
790319 request  
FELTON, J M Division of Rules and Records 79/06/29 1p
- to V Stello 790619 memo to  
Defense Council AIR/NRC/79/2

- 7907250524 Confirms 790501 telcon w/RH Smith re MR Chobanian 790404 ltr to JM Hendrie Purpose of telcon was to obtain clarification of items in ltr  
MARTIN, W G Region 1, Philadelphia, Safeguards Branch  
79/05/14 1p
- 7907250537 Summarizes 790625 telcon w/M Burke in Tarentum, PA re investigation status of allegations received by NRC related to B&W facilities at Apollo, PA  
SMITH, R H Region 1, Philadelphia, Safeguards Branch  
79/06/26 1p
- 7907250532 Forwards M Burke 790430 FOIA request for info re possible theft of 200 lbs highly enriched U at nuclear fuels facility in Apollo & Parks Township, PA  
SNYDER, G L Region 1, Philadelphia, Office of the Director  
79/05/04 1p
- 7907250499 FOIA request for FY78 budgetary allotment to sponsor & attend conferences, travel vouchers for NRC chairman & commissioners & total travel expenditures for ACRS, ASLB & ASLAW  
SHOCKLEY, M T NBC, Inc., NBC Television Stations Div 79/06/11 1p
- 7907250504 FOIA request for winning proposal re RFP-RS-NRR-79-107, "Reactor Coolant Pump/Motor Structural Integrity"  
COFFMAN, W A Affiliation Unknown 79/06/14 1p
- 7907250515 Responds to FOIA request for winning proposal re RFP-RS-NRR-79-107 Forwards copy of winning technical proposal w/o encl  
FELTON, J M Division of Rules and Records 79/07/18 1p
- 7907250517 Responds to FOIA request for travel expenditure info of certain NRC officials Forwards responses to three previous FOIA requests w/o encl  
FELTON, J M Division of Rules and Records 79/07/06 1p
- 7907250562 Approves lease agreement between State of NV & Nuclear Engineering Co permitting storage &/or burial of low level radioactive waste  
PAUL, L W Nevada, State of 62/02/15 2pp
- 7907250567 Branch position, "Low Level Waste Burial Ground Site Closure & Stabilization"  
\* Low Level Waste Branch (Pre 790501) 79/05/17 7pp
- 7907250573 "Task Force Rpt on Bonding & Perpetual Care of Licensed Nuclear Activities"  
WILSON, F Conference of Radiation Control Program Directors, Inc 76/04/05 39pp
- 7907250586 Lease of lands for disposal of radioactive wastes; opinion of Atty General of NV  
\* Nevada, State of 61/10/06 3pp
- 7907250592 Assembly Bill 444, laws of 1961, "Acquisition of Lands for Disposal of Radioactive Matls"  
\* Nevada, State of 61/05/04 2pp
- 7907250599 Forwards unsigned copy of lease between State of NV & Nuclear Engineering Co for waste disposal facility  
CORBETT, J B Nuclear Engineering Co, Inc (subs of Teledyne, Inc) 62/02/02 10pp.
- 7907250572 Responds to FOIA request for all documents re facility & Applications XR-120, XCOM-13 & XBNM-1471 Three documents withheld (ref FOIA Exemption 1)  
FELTON, J M Division of Rules and Records 79/07/06 3pp.
- 7907260447 Responds to FOIA request for 1978 rept on nuclear wastes by Natl Academy of Sciences for NRC Forwards rept:  
"Solidification of High Level Radioactive Wastes" w/o encl  
FELTON, J M Division of Rules and Records 79/07/18 1p
- 7907260452 FOIA request for 1978 rept on nuclear wastes by Natl Academy of Sciences for NRC.  
LOUGHSIN, D Affiliation Unknown 79/07/02 1p.
- 7907300149 Requests all records re development or promulgation of form of nuclear energy liability policy in 10CFR140 91 App A  
MONEY, M M Sullivan & Cronwell 79/06/15 2pp
- 7907300136 Responds to 790615 request re development & promulgation of form of nuclear energy liability policy for facilities in 10CFR140 91, App A Forwards list of relevant documents  
FELTON, J M Division of Rules and Records, 79/07/18 2pp
- 7907300168 Notifies of Commission 600324 decision re AEC-R 29/9 amend governing financial protection requirements & indemnity agreements  
ANAMOSA, H D Atomic Energy Commission 60/03/28 2pp
- 7907300180 Forwards amend re financial protection & indemnity regulations & proposed amend re revision of indemnity agreement for JCAE Nuclear liability policy offered by NELIA & MAELU is acceptable w/o encl  
LUEDECKE, A R Atomic Energy Commission 60/03/31 1p
- 7907300206 Forwards AEC-R 29/4 "Proposed Form of Nuclear Energy Liability Insurance Policy"  
MCCOOL, W B Atomic Energy Commission 58/08/04 1p
- 7907300211 AEC-R 29/4 "Proposed Form of Nuclear Energy Liability Insurance Policy"  
\* Atomic Energy Commission, Directorate of Licensing (Pre-1975) 58/08/04 33pp
- 7907300216 Notifies of AEC 580808 decision re AEC-R 29/4, proposed form of nuclear liability insurance policy Decision states that nonsubstantial changes made by insurance firm should be implemented  
MCCOOL, W B Atomic Energy Commission 58/08/13 2pp
- 7907300227 Forwards FR notice 10CFR140 "Financial Protection Requirements & Indemnity Agreements - Notice of Proposed Rulemaking"  
SHEA, K H Office of the General Counsel 58/08/22 1p
- 7907300235 Notice of issuance of 10CFR140 "Financial Protection Requirements & Indemnity Agreements - Notice of Proposed Rulemaking"  
\* Atomic Energy Commission 58/08/27 18pp
- 7907300249 Forwards AEC-R 29/9 "Amends to Regulations Governing Financial Protection Requirements & Indemnity Agreements"  
ANAMOSA, H D Atomic Energy Commission 60/03/19 1p
- 7907300253 "Amends to Regulations Governing Financial Protection Requirements & Indemnity Agreements"  
\* Atomic Energy Commission, Directorate of Licensing (Pre-1975) 60/03/19 50pp
- 7907300268 Summary of AEC 600324 meeting in Washington, DC re AEC-R 29/7 & AEC-R 29/8 concerning financial protection requirements & indemnity agreements  
ANAMOSA, H D Atomic Energy Commission 60/07/27 7pp
- 7907300258 Forwards FR notice 10CFR140, "Financial Protection Requirements & Indemnity Agreements"  
\* Office of the General Counsel 60/03/31 1p
- 7907300263 Notice of issuance of 10CFR140, "Financial Protection Requirements & Indemnity Agreements"  
\* Atomic Energy Commission, Directorate of Licensing (Pre-1975) 60/04/07 30pp.
- 7907300384 Charter of B&W 177 Fuel Assembly Owners Group.  
WILLIAM, D Arkansas Power & Light Co BAUMAN, R Consumers Power Co HOLT, D Duke Power Co 77/06/02 5pp.
- 7907300396 Notifies that bulletin review group has identified four potential BWR short-term generic concerns from responses to IE Bulletin 79-08  
HELTEMEG, C J TMI-2 Bulletins & Orders 79/07/03 2pp
- 7907300438 Notice that licensee has satisfactorily completed actions per NRC 790516 shutdown order. Plant may resume operations  
REID, R W Operating Reactors Branch 4 79/07/06 5pp
- 7907310573 FOIA request for all documents re facility & applications XR-120, XCOM-13, & XBNM-1471  
ASHER, T R Asher, T R, PC. 79/05/14 5pp.
- 7907310589 Discusses request for licensing expert to join IAEA team to evaluate PBR for two Westinghouse reactors Senior staff member not available  
FELTON, J M Division of Rules and Records 77/12/27 1p.

# NONDOCKETED ITEMS

## GEN TEC IS GENERIC TECHNICAL ISSUES

7907060266 Forwards lists of licensees who would not commit to 90-h containment purging limit. Suggests meetings w/ listed licensees. Also forwards review team responses for Big Rock Point re containment purge valves.  
GRIMES, C I Plant Systems Branch 79/05/22 3pp

7907180842 Notification of 790615 meeting w/ Mark I owners' group in Bethesda, MD to discuss Mark I long-term program schedule & pool swell pressure load definition. Proposed agenda encl.  
GRIMES, C I Plant Systems Branch 79/06/11 2pp

7907180913 Notification of 790612-13 meeting w/ Sandia Labs in Bethesda, MD to discuss status of work accomplished & resources used & to review detail of fault trees presented in second interim rept.  
ANGELO, J Light Water Reactors Branch 1 79/06/04 1p

7907190470 Notification of 790622 meeting w/ Mark I owners in Bethesda, MD to discuss proposed staff positions on pool swell vertical pressure loads for Mark I containment long term program.  
GRIMES, C I Plant Systems Branch 79/06/20 2pp

7907190474 Notification of 790725 meeting w/ Westinghouse, C-E, B&W & AIF to discuss possible impact of TMI-2 accident on evaluation of ATWS events for PWRs.  
CHERNY, F C Division of Systems Safety 79/06/19 1p

7907200508 Forwards GE ATWS generic analysis Encl withheld (ref 10CFR2 790).  
CHERNY, F C Division of Systems Safety 79/07/02 1p

7907200512 Discusses status of resolving ATWS safety issue TMI-2 incident has had minimal effect on BWRs but adequacy of ATWS resolution for PWRs is questionable. Unresolved ACRS questions re BWRs from 790308-10 encl.  
HANAUER, S H TMI-2 Unresolved Safety Issues 79/07/06 12pp

## I&E INSPECTION AND ENFORCEMENT

7902150354 Forwards IE Info Notice 79-03, "Limiting Valve Gearing Limit Switch Lubricant." w/ draft transmitted letter for 790209 dispatching w/ list of 11 Systematic Evaluation Program plants for which no action is required.  
MOSELEY, N C Division of Reactor Operations Inspections 79/02/06 2pp

7902210141 Forwards IE Bulletin 79-01, "Environ Qualification of Class IE Equipment," w/ draft transmitted letter for 790209 dispatching w/ list of 11 Systematic Evaluation Program plants for which no action is required.  
MOSELEY, N C Office of Inspection & Enforcement 79/02/06 2pp.

7904270127 IE Bulletin 79-08, "Events Relevant to BWRs Reactors Identified During TMI Incident."  
\* Office of Inspection & Enforcement 79/04/14 4pp

7907020173 IE Bulletin 79-01A, "Environ Qualification of Class IE Equipment (Deficiencies in Environ Qualification of ASCO Solenoid Valves)."  
\* Office of Inspection & Enforcement 79/06/06 8pp.

7907020181 IE Info Notice 79-15, "Efficient Procedures."  
\* Office of Inspection & Enforcement 79/06/07 7pp

7907030121 IE Circular 77-07, "Short Period During Reactor Startup."  
\* Office of Inspection & Enforcement 77/04/14 3pp

7907060295 IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys."  
\* Office of Inspection & Enforcement 79/07/02 9pp

7907090028 IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor."  
\* Office of Inspection & Enforcement 79/05/29 9pp.

7907120387 IE Info Notice 79-18, "Skylab Reentry."  
KEPPLER, J O Office of Inspection & Enforcement. 79/07/06 3pp

907120486 IE Circular 77-13, "Reactor Safety Signals Negated During Testing."  
\* Office of Inspection & Enforcement 77/09/22 3pp.

7907180120 Forwards IE Bulletin 79-15, "Deep Draft Pump Deficiencies." Bulletin should be sent to all power reactor licensees w/ CPs &/or DLs no later than 790711. Draft ltr encl.  
THORNBURG, H D Division of Reactor Construction Inspection 79/07/09 2pp

--7907180125 IE Bulletin 79-15, "Deep Draft Pump Deficiencies."  
\* Office of Inspection & Enforcement 79/07/11 9pp

7907180129 Forwards IE Circular 79-14, "Unauthorized Procurement & Distribution of Xe-133." Circular should be issued to all medical licensees, except teletherapy medical licensees, & to all radiopharmaceutical suppliers. Draft ltr encl.  
BNIEZEK, J H Division of Fuel Facility & Materials Safety 79/07/06 2pp

--7907180135 IE Circular 79-14, "Unauthorized Procurement & Distribution of Xe-133."  
\* Office of Inspection & Enforcement 79/07/13 5pp

7907180622 IE Bulletin 79-07 Seismic Stress Analysis of Safety-Related Piping.  
\* Office of Inspection & Enforcement 79/04/14 3pp

7907190128 IE Circular 79-13, "Replacement of Diesel Fire Pump Starting Contactors."  
\* Office of Inspection & Enforcement 79/07/13 6pp

7907230164 IE Info Notice 79-19, "Pipe Cracks in Stagnant Bored Water Sys at PWR Plants."  
\* Office of Inspection & Enforcement 79/07/17 8pp

7907230229 PNO-79-51 summarizes visit to Sheffield waste burial site. No direct radiation detected above levels acceptable for release of facilities for unrestricted use.  
\* Office of Inspection & Enforcement 79/03/12 1p

7907250430 IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys."  
\* Office of Inspection & Enforcement 79/07/18 1p

7907310200 IE Circular 76-06, "Stress Corrosion Cracks in Stagnant, Low Pressure Stainless Piping Containing Boric Acid Solution at PWRs."  
\* Office of Inspection & Enforcement 76/11/26 3pp

## NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

7812290071 NUREG-0460  
Forwards NUREG-0460, Vol 3, re ATWS Rept reflects NRC view that numerical safety objective is not satisfactory for use in regulatory decisions w/o supplemental evaluation.  
W/O encl.  
DENTON, H R Office of Nuclear Reactor Regulation 78/12/19 2pp

7812290248 Responds to constituent 781027 ltr re decommissioning of nuclear facilities & amount of land committed to nuclear facilities.  
GROSSICK, L V Office of the Executive Director for Operations 78/12/20 2pp

7907030261 NUREG-0020 V3 N5  
Grey book Operating Units Status Rept, data as of 790430  
\* Commission 79/06/18 100pp

7907030426 NUREG/CR-0664  
Bibliography for "Analytical Techniques for Stress Analysis of Nuclear Steam-Supply Sys."  
HEDDLESON, F A Oak Ridge National Laboratory FIN B-126 79/03/20 220pp

7907030434 NUREG/CR-0807  
"QA for TRAC Development," informal rept  
SICILIAN, J M, PRYOR, R J Los Alamos Scientific Laboratory FIN A-7016 LA-7812-MS 79/05/30 10pp

7907030441 NUREG/CR-0455  
"Multirad Burst Test Program Progress Rept for July-Dec 1978."  
CHAPMAN, R H Oak Ridge National Laboratory FIN B-120 79/06/30 172pp

7907050145 NUREG/CR-0650  
"Comparative Evaluation of Containment Spray Additives: Detrimental Impacts of Inadvertent Spray Actuation."  
POBTA, A K Benton City Technology TAM, P Accident Analysis Branch AT-449-240-1-86 M004 79/04/30 35pp Available at NTIS

7907050149 NUREG/CR-0484 "Sensitivity of Macrocyttis Gametophytes to Copper " SMITH, B M , HARRISON, F L Lawrence Livermore Laboratory FIN A-0119 UCRL-92481 79/05/31 40pp Available at NTIS	7907090052 NUREG-0555 2 6 Environ SRP Section 2 6 "Geology " * Office of Nuclear Reactor Regulation 79/02/28 2pp Available at NTIS
7907060442 NUREG/CR-0678 "Analysis of Heat & Mass Transfer Processes of U Dioxide Bubble in Sodium for Fuel Aerosol Simulant Test (FAST) " TOBIAS, M L Oak Ridge National Laboratory FIN 0-0121 79/05/31 54pp Available at NTIS	7907090055 NUREG-0555 2 7 Environ SRP Section 2 7 "Meteorology " * Office of Nuclear Reactor Regulation 79/02/28 15pp Available at NTIS
7907090016 NUREG-0555 "Environ SRPs for Environ Review of CP Applications for Nuclear Power Plants " * Office of Nuclear Reactor Regulation 79/05/31 780pp Available at NTIS \$24 00	7907090057 NUREG-0555 2 8 Environ SRP Section 2 8 "Related Federal Project Activities " * Office of Nuclear Reactor Regulation 79/02/28 Available at NTIS
7907090020 NUREG-0555 1 1 Environ SRP Section 1 1 "Introduction-the Proposed Project " * Office of Nuclear Reactor Regulation 79/02/28 5pp Available at NTIS	7907090059 NUREG-0555 3 1 Environ SRP Section 3 1 "External Appearance & Plant Layout " * Office of Nuclear Reactor Regulation 79/02/28 5pp Available at NTIS
7907090021 NUREG-0555 1 2 Environ SRP Section 1 2 "Introduction-Status of Reviews & Approvals " * Office of Nuclear Reactor Regulation 79/02/28 6pp Available at NTIS	7907090064 NUREG-0555 3 2 Environ SRP Section 3 2 "Reactor Steam-Electric Sys " * Office of Nuclear Reactor Regulation 79/02/28 7pp Available at NTIS
7907090023 NUREG-0555 2 1 Environ SRP Section 2 1 "Description of Station Location " * Office of Nuclear Reactor Regulation 79/02/28 3pp Available at NTIS	7907090067 NUREG-0555 3 3 1 Environ SRP Section 3 3 1 "Plant Water Use-Water Consumption " * Office of Nuclear Reactor Regulation. 79/02/28 5pp Available at NTIS
7907090025 NUREG-0555 2 2 1 Environ SRP Section 2 2 1 "Land-Site & Vicinity " * Office of Nuclear Reactor Regulation 79/02/28 6pp Available at NTIS	7907090069 NUREG-0555 3 3 2 Environ SRP Section 3 3 2 "Plant Water Use-Water Treatment " * Office of Nuclear Reactor Regulation 79/02/28 5pp Available at NTIS
7907090027 NUREG-0555 2 2 2 Environ SRP Section 2 2 2 "Land-Transmission Corridors & Offsite Areas " * Office of Nuclear Reactor Regulation 79/02/28 6pp Available at NTIS	7907090070 NUREG-0555 3 4 1 Environ SRP Section 3 4 1 "Cooling Sys-Sys Description & Operational Modes " * Office of Nuclear Reactor Regulation 79/02/28 5pp Available at NTIS
7907090029 NUREG-0555 2 2 3 Environ SRP Section 2 2 3 "Land-The Region " * Office of Nuclear Reactor Regulation 79/02/28 5pp Available at NTIS	7907090074 NUREG-0555 3 4 2 Environ SRP Section 3 4 2 "Cooling Sys-Component Descriptions " * Office of Nuclear Reactor Regulation. 79/02/28 12pp Available at NTIS
7907090033 NUREG-0555 2 3 1 Environ SRP Section 2 3 1 "Hydrology " * Office of Nuclear Reactor Regulation 79/02/28 11pp Available at NTIS	7907090075 NUREG-0555 3 5 Environ SRP Section 3 5 "Radioactive Waste Mgt Sys " * Office of Nuclear Reactor Regulation 79/02/28 6pp Available at NTIS
7907090034 NUREG-0555 2 3 2 Environ SRP Section 2 3 2 "Water Use " * Office of Nuclear Reactor Regulation 79/02/28. 11pp Available at NTIS	7907090078 NUREG-0555 3 6 1 Environ SRP Section 3 6 1 "Nonradioactive Wastes Sys-Wastes Containing Chemicals or Biocides " * Office of Nuclear Reactor Regulation 79/02/28 7pp Available at NTIS
7907090037 NUREG-0555 2 3 3 Environ SRP Section 2 3 3 "Water Quality " * Office of Nuclear Reactor Regulation 79/02/28 7pp Available at NTIS	7907090079 NUREG-0555 3 6 2 Environ SRP Section 3 6 2 "Nonradioactive Wastes Sys- Sanitary Sys Wastes. " * Office of Nuclear Reactor Regulation 79/02/28 4pp Available at NTIS
7907090039 NUREG-0555 2 4 1 Environ SRP Section 2 4 1 "Terrestrial Ecology " * Office of Nuclear Reactor Regulation 79/02/28 9pp. Available at NTIS	7907090082 NUREG-0555 3 6 3 Environ SRP Section 3 6 3 "Nonradioactive Wastes Sys-Other Wastes " * Office of Nuclear Reactor Regulation. 79/02/28 5pp Available at NTIS
7907090042 NUREG-0555 2 4 2 Environ SRP Section 2 4 2 "Aquatic Ecology " * Office of Nuclear Reactor Regulation 79/02/28 9pp Available at NTIS	7907090086 NUREG-0555 3 7 Environ SRP Section 3 7 "Power Transmission Sys " * Office of Nuclear Reactor Regulation 79/02/28 5pp Available at NTIS
7907090044 NUREG-0555 2 5 1 Environ SRP Section 2 5 1 "Socioeconomics-Demography " * Office of Nuclear Reactor Regulation 79/02/28 7pp Available at NTIS	7907090087 NUREG-0555 3 8 Environ SRP Section 3 8 "Transportation of Radioactive Matl " * Office of Nuclear Reactor Regulation 79/02/28 5pp Available at NTIS
7907090048 NUREG-0555 2 5 2 Environ SRP Section 2 5 2 "Socioeconomics-Community Characteristics " * Office of Nuclear Reactor Regulation. 79/02/28. 7pp. Available at NTIS	7907090090 NUREG-0555 4 1.1 Environ SRP Section 4 1.1 "Environ Impacts of Const- Land-Use Impacts Site & Vicinity " * Office of Nuclear Reactor Regulation 79/02/28 11pp p Available at NTIS
7907090050 NUREG-0555 2 5 3 Environ SRP Section 2 5 3 "Socioeconomics-Historic & Archaeological Sites & Natural Landmarks " * Office of Nuclear Reactor Regulation. 79/02/28 7pp. Available at NTIS	

790709092 NUREG-0555 4 1 2  
Environ SRP Section 4 1 2 "Environ Impacts of Const-  
Land-Use Impacts Transmission Corridors & Offsite Areas "  
\* Office of Nuclear Reactor Regulation 79/02/28 9pp Available  
at NTIS

790709096 NUREG-0555 4 1 3  
Environ SRP Section 4 1 3 "Environ Impacts of Const-  
Historic & Archeological Sites " Section 4 1 3 1 "Site &  
Vicinity " Section 4 1 3 2 "Transmission Corridors &  
Offsite Areas "  
\* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
at NTIS

790709093 NUREG-0555 4 2 1  
Environ SRP Section 4 2 1 "Environ Impacts of Const-  
Hydrologic Alterations & Water-Use Impacts Hydrological  
Alterations "  
\* Office of Nuclear Reactor Regulation 79/02/28 11pp Available  
at NTIS

790709094 NUREG-0555 4 2 2  
Environ SRP Section 4 2 2 "Environ Impacts of Const-  
Hydrological Alterations & Water-Use Impacts Water-Use  
Impacts "  
\* Office of Nuclear Reactor Regulation 79/02/28 13pp Available  
at NTIS

790709097 NUREG-0555 4 3 1  
Environ SRP Section 4 3 1 "Environ Impacts of Const-  
Ecological Impacts Terrestrial Ecosystems " Section 4 3 1 1  
"Site & Vicinity " Section 4 3 1 2 "Transmission Corridors  
& Offsite Areas "  
\* Office of Nuclear Reactor Regulation 79/02/28 18pp Available  
at NTIS

790709099 NUREG-0555 4 3 2  
Environ SRP Section 4 3 2 "Environ Impacts of Const-  
Ecological Impacts-Aquatic Ecosystems " Section 4 3 2 1  
"Site & Vicinity " Section 4 3 2 2 "Transmission Corridors  
& Offsite Areas "  
\* Office of Nuclear Reactor Regulation 79/02/28 27pp Available  
at NTIS

790709091 NUREG-0555 4 4 1  
Environ SRP Section 4 4 1 "Environ Aspects of Const-  
Socioeconomic Impacts Physical "  
\* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
at NTIS

790709092 NUREG-0555 4 4 2  
Environ SRP Section 4 4 2 "Environ Impacts of Station  
Const-Socioeconomic Impacts Social & Economics "  
\* Office of Nuclear Reactor Regulation 79/02/28 10pp Available  
at NTIS

790709094 NUREG-0555 4 5  
Environ SRP Section 4 5 "Radiation Exposure to Const  
Workers "  
\* Office of Nuclear Reactor Regulation 79/02/28 9pp Available  
at NTIS

790709096 NUREG-0555 4 6  
Environ SRP Section 4 6 "Measures & Controls to Limit  
Adverse Impacts During Const "  
\* Office of Nuclear Reactor Regulation 79/02/28 9pp Available  
at NTIS

790709097 NUREG-0555 5 1 1  
Environ SRP Section 5 1 1 "Environ Impacts of Station  
Operation - Land-Use Impacts Site & Vicinity "  
\* Office of Nuclear Reactor Regulation 79/02/28 5pp Available  
at NTIS

790709099 NUREG-0555 5 1 2  
Environ SRP Section 5 1 2 "Environ Impacts of Station  
Operation - Land-Use Impacts Transmission Corridors &  
Offsite Areas "  
\* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
at NTIS

790709100 NUREG-0555 5 1 3  
Environ SRP Section 5 1 3 "Environ Impacts of Station  
Operation - Land-Use Impacts Historic/Archaeological Sites "  
\* Office of Nuclear Reactor Regulation 79/02/28 4pp Available  
at NTIS

790709102 NUREG-0555 5 2 1  
Environ SRP Section 5 2 1 "Hydrological Alterations, Plant  
Water Supply & Water-Use Impacts Hydrological Alterations &  
Plant Water Supply "  
\* Office of Nuclear Reactor Regulation 79/02/28 11pp Available  
at NTIS

790709105 NUREG-0555 5 2 2  
Environ SRP Section 5 2 2 "Hydrological Alterations, Plant  
Water Supply & Water-Use Impacts Water Use Impacts "  
\* Office of Nuclear Reactor Regulation 79/02/28 14pp Available  
at NTIS

790709107 NUREG-0555 5 3 1 1  
Environ SRP Section 5 3 1 1 "Cooling Sys Impacts - Intake  
Sys Hydrodynamic Descriptions & Physical Impacts "  
\* Office of Nuclear Reactor Regulation 79/02/28 9pp Available  
at NTIS

790709108 NUREG-0555 5 3 1 2  
Environ SRP Section 5 3 1 2 "Cooling Sys Impacts - Intake  
Sys Aquatic Impacts "  
\* Office of Nuclear Reactor Regulation 79/02/28 19pp Available  
at NTIS

790709109 NUREG-0555 5 3 2 1  
Environ SRP Section 5 3 2 1 "Cooling Sys Impacts -  
Discharge Sys Thermal Description & Physical Impacts "  
\* Office of Nuclear Reactor Regulation 79/02/28 11pp Available  
at NTIS

790709109 NUREG-0555 5 3 2 2  
Environ SRP Section 5 3 2 2 "Cooling Sys Impacts -  
Discharge Sys Aquatic Impacts "  
\* Office of Nuclear Reactor Regulation 79/02/28 17pp Available  
at NTIS

790709109 NUREG-0555 5 3 3 1  
Environ SRP Section 5 3 3 1 "Cooling Sys Impacts - Heat  
Dissipation Sys Heat Dissipation to Atmosphere "  
\* Office of Nuclear Reactor Regulation 79/02/28 10pp Available  
at NTIS

790709109 NUREG-0555 5 3 3 2  
Environ SRP Section 5 3 3 2 "Cooling Sys Impacts - Heat  
Dissipation Sys Impacts to Terrestrial Ecosystems "  
\* Office of Nuclear Reactor Regulation 79/02/28 9pp Available  
at NTIS

790709109 NUREG-0555 5 4 1  
Environ SRP Section 5 4 1 "Radiological Impacts of Normal  
Operation Exposure Pathways "  
\* Office of Nuclear Reactor Regulation 79/02/28 11pp Available  
at NTIS

790709109 NUREG-0555 5 4 2  
Environ SRP Section 5 4 2 "Radiological Impacts of Normal  
Operation Dose Commitments "  
\* Office of Nuclear Reactor Regulation 79/02/28 16pp Available  
at NTIS

790709109 NUREG-0555 5 4 3  
Environ SRP Section 5 4 3 "Radiological Impacts of Normal  
Operation Impacts to Man "  
\* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
at NTIS

790709109 NUREG-0555 5 4 4  
Environ SRP Section 5 4 4 "Radiological Impacts of Normal  
Operation Impacts to Biota Other than Man "  
\* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
at NTIS

790709109 NUREG-0555 5 5  
Environ SRP Section 5 5 "Environ Impacts of Station  
Operation Nonradioactive Waste Sys Impacts."  
\* Office of Nuclear Reactor Regulation 79/02/28 8pp Available  
at NTIS

790709109 NUREG-0555 5 6 1  
Environ SRP Section 5 6 1 "Environ Impacts of Station  
Operation - Transmission Sys Impacts Terrestrial."  
\* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
at NTIS

790709109 NUREG-0555 5 6 2  
Environ SRP Section 5 6 2 "Environ Impacts of Station  
Operation - Transmission Sys Impacts Aquatic."  
\* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
at NTIS

790709109 NUREG-0555 5 6 3  
Environ SRP Section 5 6 3 "Environ Impacts of Station  
Operation - Transmission Sys Impacts Impacts to Man "  
\* Office of Nuclear Reactor Regulation 79/02/28 8pp Available  
at NTIS



# NONDOCKETED ITEMS

7907090154 NUREG-0555 5 8 2  
 Environ SRP Section 5 8 2 "Environ Impacts of Station  
 Operation - Socioeconomic Impacts Social & Economic "  
 \* Office of Nuclear Reactor Regulation 79/02/28 8pp Available  
 at NTIS

7907090155 NUREG-0555 5 9  
 Environ SRP Section 5 9 "Decommissioning "  
 \* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
 at NTIS

7907090156 NUREG-0555 5 10  
 Environ SRP Section 5 10 "Measures & Controls to Limit  
 Adverse Impacts During Operation " Section 5 10 1  
 "Applicant Commitments " Section 5 10 2 "Staff Evaluation &  
 Recommendations "  
 \* Office of Nuclear Reactor Regulation 79/02/28 8pp Available  
 at NTIS

7907090157 NUREG-0555 6 1  
 Environ SRP Section 6 1 "Environ Measurements & Monitoring  
 Programs Thermal "  
 \* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
 at NTIS

7907090160 NUREG-0555 6 2  
 Environ SRP Section 6 2 "Environ Measurements & Monitoring  
 Programs Radiological "  
 \* Office of Nuclear Reactor Regulation 79/02/28 11pp Available  
 at NTIS

7907090163 NUREG-0555 6 3  
 Environ SRP Section 6 3 "Environ Measurements & Monitoring  
 Programs Hydrological "  
 \* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
 at NTIS

7907090165 NUREG-0555 6 4  
 Environ SRP Section 6 4 "Environ Measurements & Monitoring  
 Programs Meteorological "  
 \* Office of Nuclear Reactor Regulation 79/02/28 10pp Available  
 at NTIS

7907090167 NUREG-0555 6 5 1  
 Environ SRP Section 6 5 1 "Environ Measurements &  
 Monitoring Programs - Biological Terrestrial Ecology &  
 Land-Use "  
 \* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
 at NTIS

7907090170 NUREG-0555 6 5 2  
 Environ SRP Section 6 5 2 "Environ Measurements &  
 Monitoring Programs-Aquatic Ecology,"  
 \* Office of Nuclear Reactor Regulation 79/02/28 8pp Available  
 at NTIS

7907090172 NUREG-0555 6 6  
 Environ SRP Section 6 6 "Environ Measurements & Monitoring  
 Programs Chemical "  
 \* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
 at NTIS

7907090175 NUREG-0555 6 7  
 Environ SRP Section 6 7: "Environ Measurements & Monitoring  
 Programs Staff Recommendations " Section 6 7 1, "Bite  
 Preparations & Const Monitoring " Section 6 7 2  
 Preoperational Monitoring "  
 \* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
 at NTIS

7907090176 NUREG-0555 7 1  
 Environ SRP Section 7 1 "Environ Impacts of Postulated  
 Accidents Involving Radioactive Matl Plant Accidents,"  
 \* Office of Nuclear Reactor Regulation 79/02/28 12pp. Available  
 at NTIS

7907090178 NUREG-0555 7 2  
 Environ SRP Section 7 2 "Transportation Accidents "  
 \* Office of Nuclear Reactor Regulation 79/02/28 6pp. Available  
 at NTIS

7907090179 NUREG-0555 8 1  
 Preliminary environ SRP Section 8 1 "Description of Power  
 Sys " Section 8 1 1, "Sys Area," Section 8 1 2 "Regional  
 Relationships,"  
 \* Office of Nuclear Reactor Regulation 79/02/28 5pp Available  
 at NTIS.

7907090152 NUREG-0555 5 7  
 Environ SRP Section 5 7 "U Fuel Cycle Impacts "  
 \* Office of Nuclear Reactor Regulation 79/02/28 29pp Available  
 at NTIS

7907090180 NUREG-0555 8 2 1  
 Preliminary environ SRP Section 8 2 1 "Power & Energy  
 Requirements " Section 8 2 1 1 "Electrical Energy Demand "  
 Section 8 2 1 2 "Peakload Demand "  
 \* Office of Nuclear Reactor Regulation 79/02/28 8pp Available  
 at NTIS

7907090185 NUREG-0555 8 2 2  
 Preliminary environ SRP Section 8 2 2 "Factors Affecting  
 Growth of Demand " Section 8 2 2 1 "Economic & Demographic  
 Trends " Section 8 2 2 2 "Conservation & Substitution "  
 Section 8 2 2 3 "Price & Rate Structure "  
 \* Office of Nuclear Reactor Regulation 79/02/28 12pp Available  
 at NTIS

7907090187 NUREG-0555 8 3  
 Preliminary environ SRP Section 8 3 "Power Supply " Section  
 8 3 1 "Existing & Planned Generating Capacity " Section  
 8 3 2 Purchases & Sales "  
 \* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
 at NTIS

7907090191 NUREG-0555 8 4  
 Preliminary environ SRP Section 8 4 "Staff Assessment of  
 Need " Section 8 4 1 "Assessment of Baseload Generating  
 Capacity " Section 8 4 2 "Reserve Margin Assessment "  
 Sections 8 4 3, 8 4 4 & 8 4 5  
 \* Office of Nuclear Reactor Regulation 79/02/28 9pp Available  
 at NTIS

7907090193 NUREG-0555 9 1 1  
 Environ SRP Section 9 1 1 "Alternatives Not Requiring New  
 Generating Capacity,"  
 \* Office of Nuclear Reactor Regulation 79/02/28 7pp Available  
 at NTIS

7907090194 NUREG-0555 9 1 2  
 Environ SRP Section 9 1 2 "Alternatives Requiring New  
 Generating Capacity "  
 \* Office of Nuclear Reactor Regulation 79/02/28 13pp Available  
 at NTIS

7907090197 NUREG-0555 9 1 3  
 Environ SRP Section 9 1 3 "Staff Assessment of Alternative  
 Energy Sources & Sys "  
 \* Office of Nuclear Reactor Regulation 79/02/28 28pp Available  
 at NTIS

7907090199 NUREG-0555 9 2  
 Preliminary environ SRP Section 9 2 "Alternative Sites "  
 \* Office of Nuclear Reactor Regulation 79/02/28 25pp Available  
 at NTIS

7907090201 NUREG-0555 9 3 1  
 Environ SRP Section 9 3 1 "Alternative Plant & Transmission  
 Sys Heat Dissipation Sys "  
 \* Office of Nuclear Reactor Regulation 79/02/28 16pp Available  
 at NTIS

7907090203 NUREG-0555 9 3 2  
 Environ SRP Section 9 3 2 "Alternative Plant & Transmission  
 Sys Circulating Water Sys " Section 9 3 2 1 "Intake Sys "  
 Section 9 3 2 2 "Discharge Sys " Section 9 3 2 3 "Water  
 Supply " Section 9 3 2 4, "Water Treatment,"  
 \* Office of Nuclear Reactor Regulation 79/02/28 20pp Available  
 at NTIS

7907090204 NUREG-0555 9 3 3  
 Environ SRP Section 9 3 3 "Alternative Plant & Transmission  
 Sys:Nonradioactive-Waste Treatment Sys "  
 \* Office of Nuclear Reactor Regulation 79/02/28. 17pp Available  
 at NTIS

7907090205 NUREG-0555 9 3 4  
 Environ SRP Section 9 3 4, "Alternative Plant & Transmission  
 Sys-Transmission Sys " Section 9 3 4 1 "Alternative  
 Routes," Section 9 3 4 2 "Alternative Design, Const &  
 Maint "  
 \* Office of Nuclear Reactor Regulation 79/02/28. 17pp Available  
 at NTIS

7907090207 NUREG-0555 10 1  
 Environ SRP Section 10 01 "Unavoidable Adverse Environ  
 Impacts,"  
 \* Office of Nuclear Reactor Regulation 79/02/28. 6pp Available  
 at NTIS

- 7907090208 NUREQ-0555 10 2  
Environ SRP Section 10 2 "Irreversible & Irretrievable  
Commitments of Resources "  
\* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
at NTIS
- 7907090209 NUREQ-0555 10 3  
Environ SRP Section 10 3 "Relationship Between Short-Term  
Uses & Long-Term Productivity of Man's Environ "  
\* Office of Nuclear Reactor Regulation 79/02/28 4pp Available  
at NTIS
- 7907090210 NUREQ-0555 10 4 1  
Environ SRP Section 10 4 1 "Benefit/Cost Balance Benefits "  
\* Office of Nuclear Reactor Regulation 79/02/28 5pp Available  
at NTIS
- 7907090211 NUREQ-0555 10 4 2  
Environ SRP Section 10 4 2 "Benefit/Cost Balance Costs "  
\* Office of Nuclear Reactor Regulation 79/02/28 6pp Available  
at NTIS
- 7907090212 NUREQ-0555 10 4 3  
Environ SRP Section 10 4 3 "Benefit/Cost Balance Summary "  
\* Office of Nuclear Reactor Regulation 79/02/28 4pp Available  
at NTIS
- 7907090223 Ack receipt of 790515 ltr to JH Hendrie submitting  
recommendations for addl analyses of transient & accidents  
HATTSON,R J Division of Systems Safety 79/06/08 1p
- 7907090226 Recommends that scope of accident analysis section of FSAR  
should be expanded  
MARIANI,L P American Nuclear Insurers 79/05/15 2pp
- 7907090270 NUREQ-0555 5 8 1  
Environ SRP Section 5 8 1 "Environ Impacts of Station  
Operation - Socioeconomic Impacts Physical "  
\* Office of Nuclear Reactor Regulation 79/02/28 29pp Available  
at NTIS
- 7907100672 NUREQ/CR-0771  
Naval Research Lab Memo Rept 4006, "Effects of Weathering on  
Charcoal Performance "  
BEITZ,V R Navy, Dept of, Naval Research Laboratory FIN B-6003  
Rd 79/05/10 79pp Available at NTIS
- 7907110283 NUREQ/CR-0759  
"Physics of Reactor Safety," quarterly rept, Oct-Dec 1978  
\* Argonne National Laboratory FIN A-2015 ANL-79-19 79/03/31  
74pp Available at NTIS
- 7907110622 Notice of extension until 790621 of comment period on  
NUREG-0555, "Review & Assessment of Package Requirements  
(Yellowcake) & Emergency Response to Transportation  
Accidents "  
DIRCKS,W J Office of Nuclear Material Safety & Safeguards  
79/05/30 1p
- 7907110635 NUREQ/CR-0845  
"Steam-Water Mixing & Sys Hydrodynamics Program," Task 4,  
quarterly progress rept, Oct-Dec 1978  
COLLIER,R P, DHORAK,J A, FLANIGAN,L J Battelle Memorial  
Institute, Columbus Laboratories BHI-2028 79/05/31 53pp  
Available at NTIS
- 7907110659 NUREQ 0030 VR N2  
Yellow Book Const Status Rept, data as of 790430  
\* Office of Management and Program Analysis 79/05/31 165pp  
Available at NTIS
- 7907110734 NUREQ/CR-0839  
"Study of Thermal & Hydrodynamic Processes Associated  
W/Melting of Horizontal Substrate "  
TAQHAVI-TAFRESH, DHR,V K, CAYTON,I California, Univ of, Los  
Angeles FIN B-3019 R7 79/05/31. 100pp Available at NTIS
- 7907120156 NUREQ/CR-0776  
"DASH Multicomponent Time-Dependent Concentration  
Diffusion W/Radioactive Decay Program," informal rept.  
CARRUTHERS,L M, APPERSON,C E, LEE,C E Los Alamos Scientific  
Laboratory FIN A-7014-9 LA-77933-MB, 79/04/30 96pp
- 7907120748 Denies request for extension of comment period since rept  
already has been available for comment for five months  
RYAN,R G Office of State Programs. 79/05/22 1p
- 7907120752 Requests extension of 90 days for comments on rept of  
NRC/EPA Task Force on Emergency Planning re state & local  
govt emergency response plans.  
REED,C Commonwealth Edison Co. 79/05/10, 1p.
- 7907160351 NUREQ-0240  
"Low Level Radioactive Waste Mgt Program "  
\* Division of Fuel Cycle & Material Safety 77/09/30 32pp
- 7907170110 NUREQ/CR-0705  
"Nuclear Data Library of Fission Products for Decay Power  
Calculation "  
TASAKA,K Idaho National Engineering Laboratory FIN A-6046  
TREE-1325 79/05/31. 194pp Available at NTIS
- 7907170121 NUREQ/CR-0500  
"Assessment of Fuel Melting, Radial Extrusion & Cladding  
Thermal Failure During Power-Cooling-Mismatch Event in  
LWRs "  
EL-GENK,M S Idaho National Engineering Laboratory FIN A-6045  
TREE-1270 79/05/31 74pp Available at NTIS
- 7907170136 NUREQ/CR-0312  
"Effect of Scale on Two-Phase Countercurrent Flow Flooding,"  
final rept for July 1977-June 1978  
RICHTER,H J, WALLIS,G B, SPEERS,M S Dartmouth College FIN  
B-5816 78/06/30 49pp Available at NTIS
- 7907170167 NUREQ/CR-0863  
"K-FIX Computer Program for Transient, Two-Dimensional,  
Two-Fluid Flow; THREEED Extension of K-FIX Code for  
Three-Dimensional Calculations "  
RIVARD,W C, TORREY,M D Los Alamos Scientific Laboratory  
LA-NUREG-6623 79/01/31 144pp Available at NTIS
- 7907170187 NUREQ/CR-0872  
"CRAB User's Manual "  
JORDAN,H, QIEBEKE,J A, SCHUMACHER,P M Battelle Memorial  
Institute, Columbus Laboratories FIN A-4063 BHI-2027 79/06/30  
31pp Available at NTIS
- 7907170197 NUREQ/CR-0745  
"Measured & Predicted Gas Flow Rates Through Rough  
Capillaries "  
CWZARSKI,P C, BUTTER,B L, SCHWENDIMAN,L C Battelle Memorial  
Institute, Pacific Northwest Laboratory FIN B-2093 PNL-2623  
79/06/30 107pp, Available at NTIS
- 7907170204 NUREQ/CR-0679  
"DYNASYL General-Purpose Dynamic Simulator for Chemical  
Processes "  
PATTERSON,G K, ROZSA,R B Lawrence Livermore Laboratory FIN  
A-0115 UCRL-52561 78/09/05 100pp Available at NTIS
- 7907170217 NUREQ/CR-0850  
"ECC Bypass Scaling "  
RICHTER,H J, WALLIS,G B Dartmouth College NRC-04-76-329  
79/06/30 44pp Available at NTIS
- 7907170231 NUREQ/CR-0770  
"Asbestos in Cooling-Tower Waters," final rept  
LEWIS,B G Argonne National Laboratory FIN A-2031 ANL/E8-71  
79/03/31 105pp Available at NTIS
- 7907180116 NUREQ/CR-0711  
"Evaluation of Methods for Determination of X-Ray &  
Gamma-Ray Exposure Attributable to Nuclear Facility Using  
Environmental TLD Measurements "  
DE PLANQUE,G Energy, Dept of, Environmental Measurements Laboratory  
FIN A-3075-B EML-355 79/06/30. 44pp Available at NTIS
- 7907180134 NUREQ/CR-0727  
"BWR Offgas Sys Evaluation "  
KELLER,J H, MCCLURE,L W. Allied Chemical Corp, Nuclear Services  
Div LD.R Environmental Evaluation Branch (Pre 790629) FIN  
A-6261-9 79/06/30 56pp Available at NTIS
- 7907180130 Notification of 790615 meeting of NRC/EPA Task Force on  
Emergency Planning & consultants in Bethesda, MD re  
NUREG-0396 ACRS meeting will follow in Washington, DC  
GRIMES,B K Office of Nuclear Reactor Regulation COLLINS,H E  
Office of State Programs 79/06/05 1p.
- 7907180155 Notification of 790619 meeting of Interorganizational  
Advisory Committee meeting in Bethesda, MD to discuss  
NUREG-0396  
COLLINS,H E Office of State Programs. 79/06/04 21pp
- 7907180171 NUREQ-0562  
"Fuel Rod Failure as Consequence of DNB or Dryout "  
VAN HOUTEN,R Fuel Behavior Branch. 79/06/30 41pp. Available  
at NTIS
- 7907180182 NUREQ/CR-0498  
"INBITE Info Sys Data Graphs "  
HUBER,C C, JUSKO,M J Argonne National Laboratory. FIN A-2012-B  
ANL/EES-TH-45 79/04/30 253pp Available at NTIS.

#

7907250403 NUREG/CR-0597

"Descriptions of US U Resource Areas Suppl to GEIS on U Milling"  
MONTET, Q L, BENIDOFF, P A, CURTIS, B A Argonne National Laboratory  
FIN A-2143 ANL/ES-75 79/06/30 271pp Available at NTIS

7907250514 NUREG/CR-0668

"Evaluation of Potential Chemical/Mechanical Degradation Processes Affecting Fuel & Structural Matls Under Long-Term Water Storage"  
ZIMA, G E Battelle Memorial Institute, Pacific Northwest Laboratory  
FIN B-21199 PNL-2379 79/05/30 48pp Available at NTIS

7907250538 NUREG/CR-0762

"Nuclear Reactor Safety," quarterly progress rept, Oct-Dec 1978  
JACKSON, J F, STEVENSON, H O Los Alamos Scientific Laboratory  
LA-7769-PR 79/05/31 234pp Available at NTIS

7907250607 NUREG-0200 V3 N6

Gray Book Operating Units Status Rept, data as of 790531  
\* Commission 79/07/16 171pp Available at NTIS \$10 00

7907260563 NUREG/CR-0661 V9

"LWR Safety Research Program," quarterly rept, Jul-Sept 1978  
\* Sandia Laboratories FIN A-1019 SAND79-0359 79/04/30 115pp  
Available at NTIS

7907270030 Interim final rule re physical protection of irradiated

reactor fuel in transit NUREG-0561 will be issued as guide to assist licensees in implementation of requirements  
Comment period ends on 790817  
CHILK, B J Office of the Secretary of the Commission 79/06/12  
8pp

7907270357 NUREG/CR-0550

"LWR Pressure Vessel Irradiation Surveillance Dosimetry," quarterly progress rept, Apr-June 1978  
GUTHRIE, Q L, MCCLROY, W N, LIPPINCOTT, E P Hanford Engineering Development Laboratory FIN D-5988-7 HEDL-THE 78-7 78/06/30  
110pp

7907270366 NUREG/CR-0553

"Dispersion & Dosimetry (UDAD) Code"  
MOMENI, M H, YUAN, Y, ZIELEN, A J Argonne National Laboratory  
ANL/ES-72 79/05/31 315pp Available at NTIS

7907270388 NUREG/CR-0840

"FRAP-TS Computer Code for Transient Analysis of Oxide Fuel Rods"  
STEFEN, L J, BOHN, M P, PECK, S O Idaho National Engineering Laboratory FIN A-6050 TREE-1281 79/04/30 357pp Available at NTIS

7907270400 NUREG/CR-0618

"PBF-LOCA Test Series Test LOC-11 Test Results Rept"  
LARBON, J R, BROUGHTON, J M, SPORE, J W Idaho National Engineering Laboratory FIN A-6041 TREE-1329 79/04/30 73pp Available at NTIS

7907270404 NUREG/CR-0577

"Probabilistic Safety Analysis for Solidified High Level Nuclear Waste Mgt Sys"  
HECKMAN, R A, HOLDSWORTH, T Lawrence Livermore Laboratory FIN A-0277 UCRL-52632 79/07/31 301pp Available at NTIS

7907300047 NUREG/CR-0828

"LWR Safety Research Program," quarterly progress rept, ct-Dec 1978  
ACHS, R O, KYGER, J A Argonne National Laboratory FIN A-2014 NL-79-18 79/04/30 46pp Available at NTIS

7300057 NUREG/CR-0647

"Fuel Rod Behavior during Test PCM-2"  
SHNER, A S, VINJAMURI, K Idaho National Engineering Laboratory  
IN A-6041 TREE-1332 79/04/30 82pp Available at NTIS

/07300068 NUREG/CR-0800

"Estimate of Feasibility to Develop Acoustic Emission-Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels"  
HUTTON, P H, SCHWENK, E B, KURTZ, R J Battelle Memorial Institute, Pacific Northwest Laboratory FIN D-2088, PNL-R777, 79/04/30  
49pp. Available at NTIS.

907300099 NUREG/CR-0615

"Index to Nuclear Safety Technical Progress Review by Chronology, Permuted Title & Author, Vol 11(1) - Vol 19(6)"  
OTTRELL, W B, PASSIAKOS, M Oak Ridge National Laboratory, FIN 0126, ORNL/NUREG/NBIC, 79/07/31 139pp Available at NTIS

7907300248 NUREG-0380 V3 N7

"Program Summary Rept," Vol 3 Number 7  
\* Office of Management and Program Analysis 79/07/20, 100pp  
Available at NTIS \$12 50

7907310035 NUREG/CR-0851

"Computational Methods in Thermal Reactor Safety"  
PRYOR, R J Los Alamos Scientific Laboratory FIN A-7016  
LA-7856-MS 79/06/30 22pp Available at NTIS

7907310068 NUREG/CR-0667

"Properties of Radioactive Wastes & Waste Containers," Progress Rept 9, Apr-June 1978  
GOLDMAN, P, NEILSON, R M Brookhaven National Laboratory FIN A-3027 BNL-NUREG-50966 78/11/30 57pp Available at NTIS

# ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

7905020344 Responds to 790226 ltr requesting NRC coordinate efforts w/EPA & SD Dept of Environ Protection to conduct assessment of radiation doses to inhabitants of Edgemont & Cottonwood, SD Continued efforts under way to assess radiation doses  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards 79/04/10 1p

7906130475 Responds to 790419 memo No comment on proposed projects: none are germane to nuclear regulatory program  
MINDQUE, R B Office of Standards Development 79/05/02 1p

7906270273 Informs of acceptability of request for NRC approval for use of ASME Code Case 1992 in design of certain portions of hydrogen recombiner units for post-LOCA conditions  
BAER, R L Light Water Reactors Branch 2 79/05/23 2pp

7907020275 Notifies IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" was sent to listed parties  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/27 3pp.

7907020406 Forwards IE Info Notice 79-17, "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Grid Plate"  
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/06/20 1p

7907030058 Ack receipt of 790406 ltr re containment sys design Forwards NUREG-0438 describing proposed research re risk reduction potential of alternate containment concepts & core retention measures W/o encl  
LEVINE, S Office of Nuclear Regulatory Research 79/08/14 1p.

7907050362 Ack receipt of 790427 ltr re UCS petition & NRC 790516 meeting Review of matl indicates adequate fire protection & environ qualification programs in force UCS concerns are based on speculation & inferences  
BARNWARTH, C S Affiliation Unknown 79/05/10 1p

7907060001 Forwards IE Circular 79-10, "Pipefittings Mfg from Unacceptable Matl" No action required Lists parties to whom circular was sent  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/27 2pp

7907060492 Notification of two changes to light water breeder reactor operations First change involves predicted flow coefficient of reactivity, Second change is further reduction in plant operating pressure  
BRODBK, R S Energy, Dept of 79/05/22 3pp.

7907100487 Advises that IE Circular 79-12, "Potential Diesel Generator Turbocharger Problem," was sent to listed utils  
PAPPAS, H Region 3, Chicago, Office of the Director, 79/06/28 2pp.

7907110198 Forwards IE Circular 79-09, "Occurrences of Split or Punctured Regulator Diaphragms in Certain Self-Contained Breathing Apparatus" No action required  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/22 1p

7907110718 Furnishes alphabetical & by-ofc lists of NRC personnel involved in development of nuclear stds & stds organizations & committees (NRC-15)  
WEISS, E Office of Standards Development 79/05/22 38pp

7907120293 Advises that IE Bulletin 79-02, Revision 1, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts," was distributed to listed utils.  
PAPPAS, H Region 3, Chicago, Office of the Director, 79/06/22 2pp

7907130001 Acks receipt of NRC 790427 ltr re 790516 Commission meeting to discuss UCS petition for emergency & remedial action TVA will not participate nor be represented by any other party at meeting  
OILLELAND, J E Tennessee Valley Authority 79/03/09 1p

7907230421 Forwards IE Info Notice 79-16, "Nuclear Incident at TMI " No action required  
PAPPAS, H Region 3, Chicago, Office of the Director 79/06/23 2pp

7907240245 Forwards IE Info Notice 79-14, "Safety Classification of Electrical Cable Support Sys " No action required  
KEPPLER, J G Region 3, Chicago, Office of the Director 79/06/12 2pp

7907250343 Forwards IE Info Notice 79-18, "Skylab Reentry " No action required  
PAPPAS, H Region 3, Chicago, Office of the Director 79/07/06 1p

7907270293 Notifies that IE Bulletin 79-15, Suppl 1, was sent to utils listed  
PAPPAS, H Region 3, Chicago, Office of the Director 79/07/20 1p

PR PROPOSED RULE

7906280255 Responds to 790427 ltr re DS Gaden ltr questioning fee for insp of radioisotope program Discusses NRC authority to perform insps & charge fees Forwards 10CFR30.35 & 170 & FR notice W/O encls  
GOSBICK, L V Office of the Executive Director for Operations 79/05/25 3pp

7907020320 Forwards comments on proposed rules 10CFR71 & 73  
SOLON, L R New York, State of 78/11/09 1p

7907020320 Forwards comments on proposed rules 10CFR71 & 73  
SOLON, L R New York, State of 78/11/09 1p

--7907020322 Testimony re public health & regulatory aspects in transportation of radioactive mats involving City of NY Public risk can be minimized by keeping dangerous cargo out of NY City  
SOLON, L R New York, State of 78/08/16 19pp

--7907020322 Testimony re public health & regulatory aspects in transportation of radioactive mats involving City of NY Public risk can be minimized by keeping dangerous cargo out of NY City  
SOLON, L R New York, State of 78/08/16 19pp.

7907050270 Comments on proposed rule 10CFR90: presents modified version of Phase 1 rulemaking procedures Recommends delay in initiation of Phase 2 until Phase 1 is complete  
CDUMBIL, W G Northeast Nuclear Energy Co (Northeast Utilities) 79/02/05 4pp

7907050280 Comments on proposed rule 10CFR30 discusses ECCB acceptance criteria requiring formal public rulemaking procedures & effect on safety margins  
D'TOOLE, J D Consolidated Edison Co of New York 79/02/05 4pp

7907050461 Comments on proposed rules 10CFR19 & 20 lauds elimination of 5(N-1B) dose formula & establishment of 5-rem annual & 3-rem quarterly dose limit for whole body exposure  
DEBOER, T K New York, State of 79/05/04 2pp

7907050461 Comments on proposed rules 10CFR19 & 20 lauds elimination of 5(N-1B) dose formula & establishment of 3-rem annual & 3-rem quarterly dose limit for whole body exposure  
DEBOER, T K New York, State of 79/05/04 2pp

7907060156 Comments on proposed rule 10CFR50: Subsection 1 b would not dispense w/recalculations unless code corrections demonstrated reduction in peak clad temp Better to base need for recalculation on availability of margin.  
UHRIG, R E Florida Power & Light Co. L-79-54 79/03/08 1p.

7907060164 Requests to be placed on mailing lists that would keep Dept of Mechanical Engineering & Matis Science apprised of NRC research needs  
JOHNSON, C E Duke Univ 79/02/26 1p.

7907060175 Comments on proposed rule 10CFR50 proposed changes in App K rules are appropriate & highly desirable Endorses changes to appropriate technical & nontechnical requirements within existing rule  
SHERWOOD, G G General Electric Co, Nuclear Energy Products Div MFN 030-79 79/03/01 5pp

7907060184 Comments on proposed rule 10CFR50 agrees w/proposed changes re specific assumptions in analyses & agrees w/proposed changes to 10CFR50.34 which would allow certain corrections to vendor ECCB performance until OL review  
SCHERER, A E Combustion Engineering, Inc LD-79-013 79/02/13 2pp

7907060341 Comments on proposed rule 10CFR50 urges NRC to replace present provisions to facilitate implementation of rule under current circumstances  
REED, C Commonwealth Edison Co 79/03/05 5pp

7907110018 Comments on proposed rules 10CFR31 & 32 approves suggested change for veterinary licensure from specific one for in vitro clinical or lab testing of byproduct matl to general licensure authorizing such use  
MANNING, J P Illinois, Univ of, Urbana-Champaign 79/05/09 1p

7907110018 Comments on proposed rules 10CFR31 & 32 approves suggested change for veterinary licensure from specific one for in vitro clinical or lab testing of byproduct matl to general licensure authorizing such use  
MANNING, J P Illinois, Univ of, Urbana-Champaign 79/05/09 1p

7907110024 Comments on proposed rules 10CFR31 & 32 approves proposal which would eliminate inconvenience & red tape  
LORD, P F Yale Univ 79/05/07 1p

7907110024 Comments on proposed rules 10CFR31 & 32 approves proposal which would eliminate inconvenience & red tape  
LORD, P F Yale Univ 79/05/07 1p

7907110028 Comments on proposed rules 10CFR70 & 73 concurs w/contents  
KIRK, W F United Nuclear Corp 79/05/02 1p

7907110028 Comments on proposed rules 10CFR70 & 73 concurs w/contents  
KIRK, W F United Nuclear Corp 79/05/02 1p

7907110036 Comments on proposed rules 10CFR31 & 32 favors including veterinarians among those authorized under general license for use of byproduct matl for in vitro clinical or lab testing  
RENDANO, V T Cornell Univ 79/05/09 1p

7907110036 Comments on proposed rules 10CFR31 & 32 favors including veterinarians among those authorized under general license for use of byproduct matl for in vitro clinical or lab testing  
RENDANO, V T Cornell Univ 79/05/09 1p

7907110613 Notice of authorization of certain medical licensees to prepare radiopharmaceuticals from radioisotope generators NRC is considering requiring licensees to test radiopharmaceuticals for contaminant Mo-99  
CHILK, B J Office of the Secretary of the Commission 7590-01 79/05/31 7pp

7907110613 Notice of authorization of certain medical licensees to prepare radiopharmaceuticals from radioisotope generators NRC is considering requiring licensees to test radiopharmaceuticals for contaminant Mo-99  
CHILK, B J Office of the Secretary of the Commission 7590-01 79/05/31 7pp

7907120381 Comments on proposed rule 10CFR9, portion of proposed implementing regulation should be modified to delete 10 working day limitation of requester  
HOFFMAN, W J Navy, Dept of 79/05/18 1p

7907120830 Comments on proposed rule 10CFR9 proposed revision is well-written & sufficiently clear  
WIKEEN, D B Navy, Dept of 0970. 79/05/23 1p

7907130033 Comments on proposed rule 10CFR9 urges proper indentation in order to distinguish hierarchy of various sentences & phrases in regulations  
KARNEY, P T St. Louis, MO 79/05/10 1p

7907130043 Comments on proposed rule 10CFR9 commends efforts to simplify wording of original FOIA  
MERRIMAN, M B Navy, Dept. of, US Marine Corps. 79/05/17 1p

## NONDOCKETED ITEMS

- 7707130100 Comments on proposed rule 10CFR9 further revisions in style, organization & format do not appear necessary  
HEWMAN P Plateau Resources, Ltd 79/05/16 2pp
- 7707130103 Comments on proposed rule 10CFR140 urges changes which would make proposed policy & certificate forms conform w/those submitted on behalf of NELIA & MAELU  
ALTON C O American Nuclear Insurers 79/05/31 13pp
- 7707160359 Advance notice of proposed rulemaking re mgt & disposal of low level wastes by shallow land burial & alternative disposal methods  
CHILK S J Office of the Secretary of the Commission 78/10/25 2pp
- 7707180264 Comments on proposed rule 10CFR140 suggests clarification re effect of regulations' operative provisions where single reactor is owned by multiple licensees  
RITSHER J A Ropes & Gray 79/05/29 5pp
- 7707180286 Comments on proposed rule 10CFR2 unclear how extra 30 days of pre-docketing review can shorten SER preparation by 12 months  
UHRIG R E Florida Power & Light Co L-79-133 79/05/22 1p
- 7707180298 Comments on proposed rule 10CFR4 urges self-study requirements be met by prior self-studies completed for other Federal agencies  
LEARNLEY M F West Virginia Univ 79/05/11 1p
- 7707180352 Comments on proposed rule 10CFR2 finds definition of "ex parte communication" set forth in 2.780(b) confusing & poorly drafted Suggests "participants" in "all participants in proceeding" be replaced w/"parties," to reduce vagueness  
STEPTOE P Isham, Lincoln & Beale 79/04/17 2pp
- 7707180353 No comments on proposed rule 10CFR2  
MEIERATTO L E Interior, Dept of 79/06/25 1p
- 7707180360 Comments on proposed rule 10CFR4 requirements of State of WA remain compatible w/federal govt regulations by HEW & pose no conflict in implementation  
WILL R C Washington, State of 79/06/21 1p
- 7707180367 Comments on proposed rule 10CFR4 clarifies application of nondiscrimination principle to program & activities funded by NRC  
LAH J T New York, State of 79/06/20 1p
- 7707180371 Comments on proposed rule 10CFR35 further mod needed Radiation safety committee should be chaired by physician w/nuclear medicine specialty  
STAHL T J Middlesex General Hosp 79/06/20 1p
- 7707180384 Comments on proposed rules 10CFR31 & 32 supports adding veterinarians to list Process should extend to other categories of personnel as well  
VAN PELT W R Hoffman-La Roche, Inc (subs of F Hoffman-La Roche & Co, Ltd) 79/06/15 2pp
- 7707180384 Comments on proposed rules 10CFR31 & 32 supports adding veterinarians to list Process should extend to other categories of personnel as well  
VAN PELT W R Hoffman-La Roche, Inc (subs of F Hoffman-La Roche & Co, Ltd) 79/06/15 2pp
- 7707190118 Comments on proposed rule 10CFR35 supports amend because it reduces unnecessary personnel & maintains quality of procedures  
QUIGLEY W S Guernsey Memorial Hosp GH/CA 79/05/07 1p
- 7707190179 Comments on proposed rule 10CFR9 dislikes organization of info, readability & clarity of FOIA rule Forwards marked-up 790423 cover ltr, press release & FR notice  
CDRBOY J M Affiliation Unknown 79/05/07 6pp
- 7707190521 Comments on proposed rule 10CFR35 suggests current structure of isotope committee is advantageous in total patient care Deleting physician representatives would be counterproductive  
WISOFF C P Norfolk General Hosp 79/05/07 1p
- 7707190596 Comments on proposed rule 10CFR30 concurs w/proposed changes  
SHERWOOD G Q General Electric Co MFN-126-79 79/04/27 1p
- 7707190678 Comments on proposed rule 10CFR9 supports "plain English" revision of FOIA rule  
EINSTEIN P P Notre Dame, Univ of 79/05/09 1p.
- 7707190688 Comments on proposed rule 10CFR39 criticizes proposed committee as too large & unwieldy Requests definition of coordination function  
LOKEN M K Affiliation Unknown 79/05/31 1p
- 7707190698 Comments on proposed rules 10CFR70 & 73 proposed changes are excessive & confining in scope  
DIPIAZZA R P Westinghouse Electric Corp WRG-LBFO-757 79/05/3pp
- 7707190698 Comments on proposed rules 10CFR70 & 73 proposed changes are excessive & confining in scope  
DIPIAZZA R P Westinghouse Electric Corp WRG-LBFO-757 79/05/3pp
- 7707190704 Comments on proposed rules 10CFR31 & 32 supports licensi of veterinarians as users of byproduct matl for in vitro testing  
ALLEN T A Affiliation Unknown 79/05/16 1p
- 7707190704 Comments on proposed rules 10CFR31 & 32 supports licensi of veterinarians as users of byproduct matl for in vitro testing  
ALLEN T A Affiliation Unknown 79/05/16 1p
- 7707190717 Comments on proposed rule 10CFR35 opposes appointment of radiation safety committee because of addl expense & inefficiency  
MARTIN N D Kettering Medical Center GH/KC 79/05/09 1p
- 7707190719 Comments on proposed rule 10CFR35 supports amend  
AHUJA M St Francis Hosp CO, Missouri 79/05/04 1p
- 7707190725 Comments on proposed rule 10CFR9 supports new version ltr refs should be placed in separate index  
ROBMUSSEN T L Winona Memorial Hosp 79/05/04 1p.
- 7707190728 Comments on proposed rule 10CFR9 approves of revision  
SCHULTZ D P Interior, Dept of, Fish & Wildlife Service 79/05/03 1p
- 7707190733 Comments on proposed rule 10CFR9 requests expansion w/ "plain English" revisions of 10CFR19, 20, 21, 30, 33, 34, 71, 110 & toll-free svc for "plain English" interpretation  
AMMERHANN E G Vet Admin Hosp BA, Virginia 658/115 79/05/07 1p
- 7707190740 Comments on proposed rule 10CFR9 requests plain English revisions of 10CFR19, 20, 21, 30, 33, 34, 71, 110, 170 & toll-free service for plain English interpretation  
CROWLEY J L CTL Engineers, Inc 79/05/08 1p
- 7707190747 Comments on proposed rule 10CFR9 individuals or organizations should be notified of FOIA request for release documents pertaining to those individuals or organizations  
CHESSIN H Affiliation Unknown 79/05/05 1p
- 7707190756 Comments on proposed rule 10CFR9 requests clarification of 10CFR30 App B & NRC organization & responsibilities Suggests revision of reg guides using "plain English" approach  
ZADINA E United States Testing Co, Inc 79/05/10 1p.
- 7707190762 Comments on proposed rule 10CFR9 opposes allocation of fnd to change language of rules  
PREGIBON M M Cordis Corp 79/05/10 1p
- 7707190770 Comments on proposed rule 10CFR35 supports change for small institutions  
DYER L Affiliation Unknown 79/05/24 1p
- 7707190775 Comments on proposed rule 10CFR35 recommends proposed committee in small institutions only  
WEIR G J Marshfield Clinic 79/05/31 1p
- 7707190781 Comments on proposed rule 10CFR35 recommends inclusion of hospital security officer on proposed committee  
NAROYANAN C Lutheran Hosp IN/FO 79/05/31 1p
- 7707190785 Comments on proposed rule 10CFR35 requests info on proposal & criteria for membership or election to committee  
STOLZ K Johns Hopkins Univ 79/05/22 1p
- 7707190793 Comments on proposed rule 10CFR35 supports proposal to establish radiation safety committee  
KASHY T A Bridgeton Hosp 79/05/01 1p.

7907190800 Comments on proposed rule 10CFR35 no section directed to handling & disposing of waste  
BROWN, D E Affiliation Unknown 79/05/11 1p

7907190806 Comments on proposed rule 10CFR9 requires "plain English" revision  
SCOTT, H W Lutheran Medical Center MD/ST 79/05/04 1p

7907190809 Comments on proposed rule 10CFR9 supports "plain English" revision  
FISCHER, P E Chevron Oil Co (subs of Standard Oil Co of California) 79/05/10 1p

7907190815 Comments on proposed rule 10CFR35 supports adoption of proposed rule Administration of committee more flexible & less costly  
MCDONALD, K J Affiliation Unknown 79/05/31 1p

7907190824 Comments on proposed rule 10CFR35 opposes proposed change for larger institutions w/established committees & radiation safety procedures Revision would be counterproductive  
LAUGHLIN, J S Affiliation Unknown 79/05/21 2pp

7907190831 Comments on proposed rule 10CFR35 supports change in committee as applied to smaller institutions Foresees difficulties in including internists & hematologists  
GRISINGER, B Delaware Valley Hosp PA/OR 79/05/22 1p

7907190839 Comments on proposed rule 10CFR35 suggests several depts be included on committee, rather than each dept Questions inclusion of nurse on committee instead of nuclear medicine specialist  
RIVERA, J V Puerto Rico, Univ of 79/05/23 1p

7907190849 Comments on proposed rule 10CFR35 too many committees currently exist Requests that NRC consult w/ Joint Commission on Accreditation of Hospitals to eliminate duplication  
PAUL, J Greater Community Hosp 79/05/29 1p

7907190859 Comments on proposed rules 10CFR20-13 opposes certification of health physics personnel, as petitioned Proposes licensee-controlled certification, as used by ANSI in recommended practices BNT-TC-1A, June 1975  
DALTROFF, S L Philadelphia Electric Co 79/05/02 2pp

7907200273 Comments on proposed rules 10CFR19 & 20 opposes elimination of accumulated dose averaging formula Proposed amends should include provisions for planned special radiation exposures  
JONES, J A Carolina Power & Light Co 79/05/15 2pp

7907200273 Comments on proposed rules 10CFR19 & 20 opposes elimination of accumulated dose averaging formula Proposed amends should include provisions for planned special radiation exposures  
JONES, J A Carolina Power & Light Co 79/05/15 2pp

7907230132 Comments on proposed rule 10CFR35 radiation safety committee would be too large & unwieldy Urges NRC to modify plan to address medical ctrs w/extensive research programs  
DELAND, F H Kentucky, Univ of 79/05/10 1p

7907230138 Comments on proposed rule 10CFR35 objects to including physician-specialist from each dept using radionuclides on radiation safety committee Large number of medical specialists would tend to dominate decisions  
WILLIAMS, L E Affiliation Unknown 79/05/10 1p

7907230148 Comments on proposed rule 10CFR35 concurs w/proposal  
KASTL, W H Vet Admin Hosp AL, Louisiana 79/05/11 1p

7907230157 Comments on proposed rule 10CFR35 endorses changes to radioactive isotopes committee  
KOERPER, J E Affiliation Unknown 79/05/03 1p

7907230166 Comments on proposed rule 10CFR35 larger radiation safety committee is unwieldy Addition of individuals w/little knowledge & no involvement in this area will not improve present conditions  
BERGERON, D A Affiliation Unknown 79/05/11 1p

7907230175 Comments on proposed rule 10CFR35 requests verification as to what institutions are covered  
TREASE, H W Iowa, Univ of 79/04/24 1p

7907230182 Comments on proposed rule 10CFR9 supports "plain English" revision of rule  
BROUGHTON, P L Affiliation Unknown 79/05/09 3pp

7907230190 Comments on proposed rule 10CFR35 radiation safety committee duplicates existing univ committee Requirement for representative from each user dept would result in unworkable number  
PENDLETON, R C Utah, Univ of 79/04/30 1p

7907200393 Comments on proposed rule 10CFR2 addl delay in issuance of CP will increase risks associated w/decreased energy supply situation  
GORDON, J B Affiliation Unknown 79/06/20 1p

7907200510 Comments on proposed rule 10CFR19,20 concurs w/deletion of accumulated dose averaging formula, elimination of NRC-4 forms & initiation of worker requirement re statement of previous exposure  
DALTROFF, S L Philadelphia Electric Co 79/04/25 2pp

7907200510 Comments on proposed rule 10CFR19,20 concurs w/deletion of accumulated dose averaging formula, elimination of NRC-4 forms & initiation of worker requirement re statement of previous exposure  
DALTROFF, S L Philadelphia Electric Co 79/04/25 2pp

7907230110 Comments on proposed rules 10CFR19 & 20 supports further reduction of dose limit std for workers to 0.5 rems/yr over 3-yr period & monitoring on consecutive rather than calendar basis  
HANSELL, D Illinois, State of 79/05/04 7pp

7907230110 Comments on proposed rules 10CFR19 & 20 supports further reduction of dose limit std for workers to 0.5 rems/yr over 3-yr period & monitoring on consecutive rather than calendar basis  
HANSELL, D Illinois, State of 79/05/04 7pp

7907230122 Comments on proposed rules 10CFR19 & 20 recommends mod of period of application for annual limits from calendar yr to any four consecutive quarters Objects to deletion of ALARA requirement  
DEBDER, T K New York, State of 79/05/04 2pp

7907230122 Comments on proposed rules 10CFR19 & 20 recommends mod of period of application for annual limits from calendar yr to any four consecutive quarters Objects to deletion of ALARA requirement  
DEBDER, T K New York, State of 79/05/04 2pp

7907230200 Comments on proposed rule 10CFR35 radiation trained certified individuals should comprise radiation safety committee & committee should monitor set area or sites of survey, as determined by chairman  
YOSBAUGH, J J St John Medical OH/ST 79/05/01 1p

7907230211 Comments on proposed rule 10CFR9 supports "plain English" revision of rule  
BOWEN, V T Woods Hole Oceanographic Institute 79/05/07 1p

7907230215 Comments on proposed rule 10CFR35 endorses proposal to replace radioactive isotopes committee  
KELHAM, G Grand Valley Hosp 79/04/27 1p

7907230221 Comments on proposed rule 10CFR35 commands use of term "isotope" & exclusion of hematologist from committee membership Suggests narrowing committee membership in larger institutions Questions NRC legal authority  
HUBBARD, L B Affiliation Unknown 79/05/12 2pp

7907230254 Comments on proposed rule 10CFR35 supports proposal. Medical staff from each dept using isotopes & from institution mgt should be on radiation safety committee  
NEESE, A S, HAINES, J F Unity Hosp FR, Minnesota 79/04/30 1p

7907230275 Comments on proposed rule 10CFR35 commands addition of nurse as member of committee Bad features include downgrading of committee technical competence & initiation of jurisdictional disputes within hosp  
JOHNSON, A B Michael Reese Hosp & Medical Center 79/05/25 3pp

7907230299 Comments on proposed rule 10CFR35 favors proposed committee as more useful to smaller institutions than current isotopes committee  
BREIT, D H Affiliation Unknown 79/05/11 1p

7907230779 Comments on proposed rules 10CFR30 & 35 changes will clarify conditions & frequency that eluates must be checked before patient administration.  
HAMILTON, D R Affiliation Unknown 79/06/12 1p

- 7907230779 Comments on proposed rules 10CFR30 & 35 changes will clarify conditions & frequency that eluates must be checked before patient administration  
HAMILTON, D R Affiliation Unknown 79/06/12 1p
- 7907260176 Comments on proposed rule 10CFR35 would reduce effectiveness of newly formed committees by creating large & unwieldy groups  
SPITZNAUOLE, L Connecticut, Univ of 79/06/04 1p
- 7907260187 Comments on proposed rule 10CFR35 opposes proposal on grounds that new committee would be too unwieldy & have less authority to evaluate proposed uses of radioisotopes  
MAYBERRY, W E Mayo Clinic 79/06/04 1p
- 7907260193 Comments on proposed rule 10CFR35 supports inclusion of mgt representative on proposed committee Suggests mod to proposal calling for representative from each dept  
CHU, H K Oklahoma Children's Memorial Hosp 79/06/06 1p
- 7907260198 Comments on proposed rule 10CFR35 endorses amend as beneficial to small institution  
HARDOCKS, W Vet Admin Hosp Des Moines, IA 79/06/07 1p
- 7907260204 Comments on proposed rule 10CFR35 requests waiver due to temporarily discontinued radiation therapy svcs  
SMITH, R B Lutheran Hosp WI/MI 79/05/31 1p
- 7907260210 Comments on proposed rule 10CFR4 supports amend re nondiscrimination against handicapped.  
JONES, B H Georgia, State of 79/06/14 1p
- 7907260215 Comments on proposed rule 10CFR35 commends efforts to simplify govt procedures & regulations.  
WOLF, W South Carolina, Univ of 79/06/04 1p
- 7907260225 Comments on proposed rule 10CFR35 proposed change better reflects radiation safety surveillance role of committee  
Representation from each dept would only serve to inflate committee size  
WEBSTER, E W Massachusetts General Hosp 79/06/05 1p
- 7907260228 Comments on proposed rule 10CFR35 new committee should supervise all sources of ionizing radiations  
SHINGLE, K F Vet Admin Medical Center CA/LB 600/114A 79/06/01 1p
- 7907260234 Comments on proposed rule 10CFR35 agrees in principle, but questions definition of mgt representative New committee would be cost effective by replacing four committees w/one  
DIELMAN, R Affiliation Unknown 79/05/15 1p
- 7907260243 Comments on proposed rule 10CFR4 offers no comments re nondiscrimination in federally-assisted commission programs as applied to handicapped  
MENDOZA, A A Puerto Rico 79/06/11 1p
- 7907260585 Comments on proposed rule 10CFR20-13 further certification of health physics personnel is unwarranted  
Prohibiting licensee from overriding decisions of health physicist gives physicist undue authority over mgt  
BALZER, J L Affiliation Unknown 3812 79/04/30. 2pp
- 7907260958 Comments on proposed rule 10CFR9 general public would not readily understand rules & regulations as written GA requirements in 10CFR71 re industrial radiography are difficult to understand  
MATHENS, R D Amoco Oil Co (subs of Standard Oil Co of Indiana) 79/06/06 2pp
- 7907260968 Comments on proposed rule 10CFR9 revised rule not significant enough change to warrant expenditure of time & funds Further experiments should be directed to 10CFR21  
Agrees that all new amends be written as clear as possible  
BURSTEIN, S Wisconsin Electric Power Co 79/06/14 2pp
- 7907261014 Comments on proposed rule 10CFR9 change ltrs & numbers in tabulations to engineering & business format Forwards addl suggested changes, Supporting documentation encl.  
JUBIZ, W., REES, K Y Vet. Admin Hosp. SL, Utah 660/115 79/05/14 18pp
- 7907270030 Interim final rule re physical protection of irradiated reactor fuel in transit. NUREG-0561 will be issued as guide to assist licensees in implementation of requirements.  
Comment period ends on 790817.  
ILK, S J Office of the Secretary of the Commission. 79/06/12 1p
- 7907270111 Comments on proposed rules 10CFR31 & 32 endorses authorization of veterinarians to use limited quantities of byproduct matl for in vitro testing  
KNELLER, S K Illinois, Univ of, Urbana-Champaign 79/05/29 1p
- 7907270112 Comments on proposed rules 10CFR31 & 32 endorses authorization of veterinarians to use limited quantities of byproduct matl for in vitro testing  
KNELLER, S K Illinois, Univ of, Urbana-Champaign 79/05/29 1p
- 7907270128 Comments on proposed rules 10CFR31 & 32 endorses authorization of veterinarians to use byproduct matls under general license  
JASPER, D E California, Univ of, Davis 79/05/15 1p
- 7907270128 Comments on proposed rules 10CFR31 & 32 endorses authorization of veterinarians to use byproduct matls under general license  
JASPER, D E California, Univ of, Davis 79/05/15 1p
- 7907270147 Comments on proposed rules 10CFR31 & 32 supports proposed amend authorizing veterinary use of byproduct matl for in vitro testing  
BULL, R W Michigan State Univ 79/05/15 1p
- 7907270153 Comments on proposed rules 10CFR31 & 32 strongly supports rule authorizing & regulating veterinary use of byproduct matls  
KITCHEN, H Tennessee, Univ of 79/05/21 1p
- 7907270153 Comments on proposed rules 10CFR31 & 32 strongly supports rule authorizing & regulating veterinary use of byproduct matls  
KITCHEN, H Tennessee, Univ of 79/05/21 1p
- 7907270158 Comments on proposed rules 10CFR31 & 32 supports authorization of veterinarians to use byproduct matl for in vitro testing  
BORING, J G Mississippi State Univ, 79/05/10 1p
- 7907270158 Comments on proposed rules 10CFR31 & 32 supports authorization of veterinarians to use byproduct matl for in vitro testing  
BORING, J G Mississippi State Univ 79/05/10 1p
- 7907270167 Comments on proposed rules 10CFR31 & 32 endorses addition of veterinarians to in vitro general license  
BLEVINS, W E Purdue Univ 79/05/18 1p
- 7907270167 Comments on proposed rules 10CFR31 & 32 endorses addition of veterinarians to in vitro general license  
BLEVINS, W E Purdue Univ 79/05/18 1p
- 7907300020 Comments on proposed rule 10CFR35 supports change in function & membership of medical isotopes committee  
VINARDI, G B St Francis MO/IA 79/05/29 1p.
- 7907300238 Comments on petition for rulemaking 10CFR19.20 requests separate hearing pursuant to 10CFR2 804 & 10CFR2 805 re elimination of current accumulated dose averaging formula 5(N-18) & substitution of annual & quarterly dose limits  
STRELOW, R Leva, Hawes, Byington, Martin & Oppenheimer 79/04/19 6pp.
- 7907300238 Comments on petition for rulemaking 10CFR19.20 requests separate hearing pursuant to 10CFR2 804 & 10CFR2 805 re elimination of current accumulated dose averaging formula 5(N-18) & substitution of annual & quarterly dose limits  
STRELOW, R Leva, Hawes, Byington, Martin & Oppenheimer 79/04/19 4pp
- 7907300257 Comments on proposed rules 10CFR31 & 32 supports inclusion of veterinarians under general license for use of radioactive byproduct matl for in vitro testing Regulation would treat medical personnel doing similar lab work alike  
SDRENSSEN, D. K. Affiliation Unknown. 79/06/06 1p
- 7907300257 Comments on proposed rules 10CFR31 & 32 supports inclusion of veterinarians under general license for use of radioactive byproduct matl for in vitro testing Regulation would treat medical personnel doing similar lab work alike  
SDRENSSEN, D. K Affiliation Unknown 79/06/06 1p
- 7907300273 Comments on proposed rules 10CFR31 & 32 supports inclusion of veterinarians under general license for in vitro testing of radioactive byproduct matl Eliminates necessity of veterinarians to obtain specific licensure.  
GUSTAFSON, D P, Affiliation Unknown NRC. 79/06/01 1p



7907300273 Comments on proposed rules 10CFR31 & 32 supports inclusion of veterinarians under general license for in vitro testing of radioactive byproduct matl Eliminates necessity of veterinarians to obtain specific licensure  
GUSTAFSON, D P Affiliation Unknown NRC 79/06/01 1p

7907300275 Comments on proposed rules 10CFR31 & 32 supports inclusion of veterinarians under general license for use of radioactive byproduct matl for in vitro testing  
WILLIAMS, J F Michigan State Univ 79/06/14 1p

7907300275 Comments on proposed rules 10CFR31 & 32 supports inclusion of veterinarians under general license for use of radioactive byproduct matl for in vitro testing  
WILLIAMS, J F Michigan State Univ 79/06/14 1p

7907300551 Comments on proposed rules 10CFR31 & 32 favors inclusion of veterinarians under general license for in vitro testing of byproduct matl Veterinarians have necessary training to perform tests & interpret results  
HIGHTOWER, D Texas A & M Univ 79/06/11 1p

7907300551 Comments on proposed rules 10CFR31 & 32 favors inclusion of veterinarians under general license for in vitro testing of byproduct matl Veterinarians have necessary training to perform tests & interpret results  
HIGHTOWER, D Texas A & M Univ 79/06/11 1p

7907300554 Comments on proposed rules 10CFR31 & 32 supports proposed rule to include veterinarians under general license for in vitro testing of byproduct matl  
BURK, R L Affiliation Unknown 79/06/09 1p

7907300556 Comments on proposed rules 10CFR31 & 32 supports proposed rule to include veterinarians under general license for in vitro testing of byproduct matl  
BURK, R L Affiliation Unknown 79/06/09 1p

7907300561 Comments on proposed rules 10CFR31 & 32 supports proposal re addition of veterinarians to general license for in vitro testing of byproduct matl  
ROSE, P E Affiliation Unknown 79/06/07 1p

7907300561 Comments on proposed rules 10CFR31 & 32 supports proposal re addition of veterinarians to general license for in vitro testing of byproduct matl  
ROSE, P E Affiliation Unknown 79/06/07 1p

7907300566 Comments on proposed rule 10CFR4 no comment on rule re nondiscrimination in federally-assisted Commission programs against handicapped  
MILLER, R B South Carolina, State of 79/06/07 1p

7907300570 Comments on proposed rule 10CFR4 favors proposal to correct discrimination against handicapped in federally-assisted Commission programs  
FOLEY, E New Hampshire, State of 79/06/06 1p

7907300574 Comments on proposed rule 10CFR9 editorial changes & deletions should be made to clarify rule for general public  
BERK, J J Health, Education & Welfare, Dept of 79/06/18 2pp

7907310043 Comments on proposed rule 10CFR35 endorses establishment of radiation safety committee, but responsibilities should be clarified Recommends revision to specify inclusion of radiopharmacist when matl is handled by pharmacy dept  
GREENBERG, R B Affiliation Unknown 79/06/08 2pp

7907310049 Comments on proposed rule 10CFR35 endorses revised focus on radiation safety & committee representation by mgt, nursing staff & each user dept, Group VI licensees should have radiation safety committee  
DEBOER, T R New York, State of 79/06/18 2pp.

7907310056 Comments on proposed rule 10CFR35 endorses proposed radiation safety committee w/o inclusion of nurse.  
ADAMS, O. D Oklahoma, Univ of 79/06/04. 2pp.

7907310063 Comments on proposed rules 10CFR31 & 32 favors inclusion of veterinarians under general license Rules would allow greater research efforts  
KALLFELZ, F. A Affiliation Unknown 79/05/31 1p

7907310063 Comments on proposed rules 10CFR31 & 32 favors inclusion of veterinarians under general license. Rules would allow greater research efforts  
KALLFELZ, F. A Affiliation Unknown. 79/05/31 1p.

7907310075 Comments on proposed rule 10CFR35 objects to lack of physician representation & unwieldy size of proposed committee Opposes changes in rules governing composition of radiation safety committee  
LULL, R J Affiliation Unknown 79/06/05 2pp

7907310088 Comments on proposed rule 10CFR35 suggests extension to 790715 for comments Favors revision of rule to establish committee w/expanded membership Amend should require inclusion of high-level administrator  
CLASS, R N Vet Admin Hosp Cleveland, OH 79/06/07 2pp

7907310101 Comments on proposed rule 10CFR35 questions authority & capability of radiation safety committee to review research projects & approve studies involving administration of radioactive matl to humans  
ZELAC, R E Temple Univ 79/06/06 2pp

PRM PETITION FOR RULEMAKING

7907040460 Notification that UCB & NRDC have filed comments on rulemaking action & petition for rulemaking PRM-2-8  
CHILK, S J Office of the Secretary of the Commission 79/05/30 3pp

7907090038 BECY 78-163  
Analyzes issues of NRDC petition for rulemaking PRM-20-7 Recommends response & requests approval of proposed FR notice re Commission response  
SMITH, C V Office of Nuclear Material Safety & Safeguards 78/11/24 6pp

--7907090043 Expresses concern re radioactive wastes & low level waste disposal Requests NRC preparation of EIS re NRC low level waste disposal program & all reasonable alternatives  
COTTON, R LASH, R Natural Resources Defense Council 76/08/06 2pp

--7907090049 Petition to adopt interim regulations governing disposal of low level radioactive waste  
COTTON, R Natural Resources Defense Council 78/08/06 95pp.

--7907090053 Outline of comments received on NRDC petition for rulemaking PRM-20-7 re low level wastes Overall response was opposed to petition  
\* Commission 79/05/03 16pp

--7907090058 Draft notice of denial re petition for rulemaking PRM-20-7  
CHILK, S J Office of the Secretary of the Commission 79/05/30 25pp

--7907090063 Draft ltr forwarding notice of denial re 780806 petition for rulemaking PRM-20-7.  
CHILK, S J Office of the Secretary of the Commission 78/11/24 2pp.

--7907090068 Draft ltr forwarding notice of denial re petition for rulemaking PRM-20-7  
HART, O Senate, Environment & Public Works DINGELL, J D House of Rep , Interstate & Foreign Commerce UDALL, M K House of Rep , Interior & Insular Affairs 78/11/24. 3pp

7907090080 BECY-78-613A  
Revises BECY-78-613 to incorporate comments by Ofc of Policy Evaluation & Ofc of General Counsel Revised draft FR notice of denial re NRDC petition for rulemaking PRM-20-7 encl.  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards 79/01/02 2pp

--7907090084 Draft FR notice of denial of NRDC petition for rulemaking PRM-20-7  
CHILK, S J Office of the Secretary of the Commission 79/01/02 25pp.

7907090091 BECY-78-613B  
Forwards revisions to BECY-78-613 & 613A re response to NRDC petition for rulemaking PRM-20-7 Responses by NMSB to comments by Commissioners Kennedy & Ahearns encl  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards. 79/02/16 4pp

--7907090097 Draft FR notice of denial of petition for rulemaking PRM-20-7.  
CHILK, S J Office of the Secretary of the Commission 79/02/16 31pp

## NONDOCKETED ITEMS

--7907090103 Draft ltr forwarding FR notice re denial of petition for rulemaking PRM-20-7  
CHILK, S J Office of the Secretary of the Commission 79/02/16  
2pp

--7907090106 Draft ltr forwarding FR notice of denial of petition for rulemaking PRM-20-7  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards  
79/02/16 3pp

7907090138 SECY-78-690  
Requests approval of proposed ltr to KMC, Inc denying  
petition to reconsider issuance of security personnel  
qualification training & equipment requirements Approval of  
draft FR notice of denial of petition for rulemaking sought  
HINDGUE, R B Office of Standards Development 78/12/27 6pp

--7907090157 Memo in support of petition for reconsideration of proposed  
implementation of security personnel qualification training  
& equipment requirements  
KNUTH, D F KMC, Inc 78/10/23 14pp

--7907090164 Draft ltr forwarding FR notice of denial re petition to  
reconsider issuance of security personnel qualification  
training & equipment requirements  
CHILK, S J Office of the Secretary of the Commission 78/12/27  
7pp

--7907090169 Draft FR notice of denial of KMC, Inc petition for  
rulemaking  
CHILK, S J Office of the Secretary of the Commission 78/12/27  
8pp

7907090174 SECY-78-690A  
Forwards mods to SECY-78-690, Encl B & C, per 790130 request  
ODSICK, L V Office of the Executive Director for Operations  
79/03/19 1p

--7907090181 Returns SECY-78-690 for mods following NRC review  
Response to KMC, Inc petition should be expanded to more  
completely respond to contention that NUREG guidance  
documents re-establish deleted training requirements  
CHILK, S J Office of the Secretary of the Commission 79/01/30  
2pp

--7907090186 Draft ltr forwarding FR notice re denial of petition for  
rulemaking submitted by KMC, Inc  
HENDRIE, J M Commission 79/03/19 8pp

--7907090189 Draft FR notice re denial of petition for rulemaking  
submitted by KMC, Inc.  
CHILK, S J Office of the Secretary of the Commission 79/03/19  
8pp

7907090325 Comments on petition for rulemaking 10CFR20-13 ability of  
health physics personnel to perform responsibilities is  
dependent upon training & experience relating to particular  
unit Certification would not be beneficial  
DALTROFF, S L Philadelphia Electric Co 79/05/02 2pp

7907090333 Comments on petition for rulemaking 10CFR20-13, no formal  
certification of health physics personnel by NRC is  
warranted Compliance w/Reg Guide 1.8 & ANSI 18.1 will  
assure necessary experience & expertise  
JONES, J A Carolina Power & Light Co 79/05/03 1p

7907090339 Comments on petition for rulemaking 10CFR20-13 min stds &  
qualifications adequately described in existing ANSI Std  
3.1-1978 & Reg Guide 1.8, Revision 1 Addl stds would be  
superfluous Petition should be rejected  
COUGHLIN, J Public Service Co of Indiana, Inc 79/04/27 2pp

7907090346 Comments on petition for rulemaking 10CFR20-13 methods  
for health physics qualification presently used in nuclear  
power industry are more than adequate to provide necessary  
guidance & protection against radiation  
NICHOLB, T C South Carolina Electric & Gas Co 79/04/27 1p

7907090355 Comments on petition for rulemaking 10CFR20-13, certification  
program as proposed is unwisely Downgraded need for formal  
education in favor of experience as determined by working  
certain number of hours in licensed facility  
GILLELAND, J E Tennessee Valley Authority 79/05/11 2pp.

790710403 Comments on petition for rulemaking 10CFR20-6A persons  
w/indicator diseases should be notified of risk of low level  
radiation  
\* Affiliation Unknown 78/10/07. 2pp

7907130204 Notice of receipt of UCS & NRDC 790302 ltr commenting on  
781019 amend to 10CFR21, "Reporting of Defects &  
Noncompliance"  
CHILK, S J Office of the Secretary of the Commission 79/05/30  
3pp

7907130229 Notice of Joint Intervenor's 790509 petition to renew & suppl  
750506 evacuation plans Provisions will improve licensee &  
governmental ability to cope w/radiological dangers  
following nuclear accident  
CHILK, S J Office of the Secretary of the Commission 79/05/30  
5pp

7907130288 Notice of denial of Chem-Nuclear Sys, Inc 770924 petition  
requesting exemption for package owner from requirements of  
10CFR71 Concerns of public outweigh concerns of petitioner  
ODSICK, L V Office of the Executive Director for Operations  
7590-01 79/05/30 6pp.

7907160351 NUREG-0240  
"Low Level Radioactive Waste Mgt Program"  
\* Division of Fuel Cycle & Material Safety 77/09/30 32pp

7907180254 Comments on petition for rulemaking 10CFR30-56 petition is  
w/o merit re byproduct matl fees for application, amend &  
insp, as compared to fissile matl fees  
KIRK, W F Affiliation Unknown 79/05/25 1p

7907180691 Comments on petition for rulemaking 10CFR20-6A no specific  
amend proposed & raw data not available to duplicate  
experiment  
STRELOW, R. Leva, Hawes, Symington, Martin & Oppenheimer 78/10/20  
12pp

7907190147 Comments on petition for rulemaking 10CFR20-13 ignores  
existing certification programs by American Board of Health  
Physics & Natl Registry of Radiation Protection  
Technologists Certification by NRC is conflict of interest  
MUELLER, M A Health Physics Society 79/04/19 2pp

7907190263 Comments on petition for rulemaking 10CFR20-13 opposes  
rulemaking because present stds already require highly  
qualified radiation protection personnel & rulemaking would  
reduce licensee responsibility for facility radiation safety  
LYON, P. W Power Authority State of New York 79/04/30 3pp

7907190273 Comments on petition for rulemaking 10CFR20-13 no need  
exists for further certification of health physicists, Unwise  
for mgt not to be able to override decision of health  
physicists Safety record does not show undue mgt pressure.  
CUNNINGHAM, O E General Electric Co, Nuclear Energy Products Div  
79/04/30 2pp

7907190635 Comments on petition for rulemaking 10CFR35-1 supports  
removal of restrictions on use of radiopharmaceuticals  
ALAVI, A, EYMONITT, M J, HANBELL, J R Affiliation Unknown 79/05/11  
1p

7907190642 Comments on petition for rulemaking 10CFR35-1 supports  
removal of restrictions on use of radiopharmaceuticals  
Proposed limitation is more restrictive than Food & Drug  
Administration, leaving more to physician jurisdiction  
LAWRENCE, J H California, Univ of, Berkeley 79/05/31 1p

7907190646 Comments on petition for rulemaking 10CFR35-1, supports  
removal of restrictions on use of radiopharmaceuticals NRC  
recommendations would restrict clinical application & hinder  
further development of newer applications of approved drugs  
COHAN, R J Affiliation Unknown 79/05/29 1p

7907190649 Comments on petition for rulemaking 10CFR35-1 supports  
removal of restrictions on use of radiopharmaceuticals.  
MAYNARD, C D Affiliation Unknown 79/05/28 1p

7907190654 Comments on petition for rulemaking 10CFR35-1, supports  
removal of restrictions on use of radiopharmaceuticals  
CHANDLER, H L Mount Auburn Hosp 79/05/28 1p

7907190659 Comments on petition for rulemaking 10CFR35-1, supports  
removal of restrictions on use of radiopharmaceuticals NRC  
amend would preclude use of certain drugs w/potential  
benefit to patients.  
DWORKIN, H J. Affiliation Unknown 79/06/01 1p

7907190679 Comments on petition for rulemaking 10CFR20-13 matters in  
suggested program for certification of health physics  
personnel are already addressed in reg guides or individual  
license terms Proposal should be denied.  
DISE, D P Niagara Mohawk Power Corp. 79/05/31 2pp.

7907190710 Comments on petition for rulemaking 10CFR71-7 requests extension of due date & suggests public meeting to discuss enactment  
SANTORO, M P Automation Industries, Inc 79/05/31 1p

7907190714 Comments on petition for rulemaking 10CFR20-13 accreditation of health physicists should be left to appropriate educational institutions & prof socs Licensee insps & personnel review can determine program quality  
KIRK, W F Affiliation Unknown 79/05/29 1p

7907190766 Comments on petition for rulemaking 10CFR20-13 opposes NRC certification of health physics personnel Duplicates American Board of Health Physics program Present licensing program adequate  
BRADLEY, F J New York, State of 79/05/14 2pp

7907190801 Comments on petition for rulemaking 10CFR20-13 weakens radiation protection efforts & places pressure on health physics personnel to avoid make decisions & overlook poor practices Reg guides & ANSI stds give adequate guidelines  
RENDERGER, D L Washington Public Power Supply System 79/04/30 3pp

7907190856 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals  
NELP, W B Affiliation Unknown 79/05/31 1p

7907200263 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals Often drugs can & should be used in manner not outlined in package insert  
HAMILTON, G W ; LARSON, B M Vet Admin Hosp WA/SE 79/05/24 1p

7907200268 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals Recent NRC regulation would eliminate safe alternative uses of certain drugs  
GROSSMAN, Z D Affiliation Unknown 79/05/24 Bpp

7907200487 Comments on petition for rulemaking 10CFR2-7 supports petition & recognizes that intent to circumvent NRC rules would invalidate otherwise legitimate late filing  
EDDLEMAN, W Affiliation Unknown 79/06/14 2pp

7907200494 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals  
GOODWIN, D A Vet Admin Hosp LL, California 79/05/23 1p

7907200499 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals  
POTCHEN, E J Michigan State Univ 79/05/29 1p

7907200506 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals NRC regulation hinders development of new applications of approved drugs  
CHABE, P J JFK Memorial Hosp 79/06/06 2pp

7907200507 Comments on petition for rulemaking 10CFR35-1 supports removing restrictions on use of radiopharmaceuticals. NRC regulation prevents physician from using best judgment in patient care & developing new applications for safe drugs  
ATKINS, H L New York, State Univ of, Stony Brook 79/05/25 1p

7907230234 Comments on petition for rulemaking 10CFR20-13 existing license insp procedures ensure quality of radiation surveillance & radiation protection New radiation level not justified w/low present exposure  
BAVIGNAC, N F. United Nuclear Corp 79/05/01 1p

7907230247 Comments on petition for rulemaking 10CFR20-13 no formal NRC certification of health physics personnel is warranted  
JONES, J A Carolina Power & Light Co 79/05/03 1p

7907240116 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals  
MYERS, W Q Affiliation Unknown, 79/05/24 1p

7907240461 Comments on petition for rulemaking 10CFR20-13 present health physics personnel certification programs are adequate Forwards info re American Board of Health Physics certification & registration programs.  
TERPILAK, M B. American Board of Health Physics 79/05/23 305pp

7907240507 Comments on petition for rulemaking 10CFR35-1 urges revision of proposed rule to allow greater discretionary radiopharmaceutical use.  
BLAND, W H Affiliation Unknown 79/05/25 1p

7907240511 Comments on petition for rulemaking 10CFR35-1 endorses removal of restrictions on use of radiopharmaceuticals Cites NCR ambiguity in allowing intravenous application of drug but not oral administration of lesser amount of drug  
BOOLEY, M B Affiliation Unknown 79/05/11 1p

7907240527 Comments on petition for rulemaking 10CFR35-1 supports removal of restrictions for use of radiopharmaceuticals Food & Drug Administration has acknowledged that package inserts frequently lag behind medical developments  
TEATRE, C D Virginia, Univ of 79/05/18 1p

7907240532 Comments on petition for rulemaking 10CFR35-1 supports petition to remove restrictions on use of radiopharmaceuticals  
HARRIS, C C Duke Univ 79/05/24 1p

7907240536 Comments on petition for rulemaking 10CFR35-1 supports removal of restrictions on use of radiopharmaceuticals Comments on two addl techniques which are orally administered, are simple, sensitive & involve less radiation  
FREEMAN, L M Montefiore Hosp /Montefiore Hosp Assoc of Western PA P1, PA 79/05/24 2pp

7907240542 Comments on petition for rulemaking 10CFR35-1 supports removal of restrictions on use of radiopharmaceuticals Inhalation & imaging is 100 times cheaper than current methods  
O'CONNELL, P Winchester Memorial Hosp , Virginia 79/05/24 1p

7907240551 Comments on petition for rulemaking 10CFR35-1 supports removal of restrictions on use of radiopharmaceuticals Believes regulation hinders development of new applications of approved drugs  
O'BRIEN, H A New Mexico, Univ of 79/05/23 1p

7907240559 Comments on petition for rulemaking 10CFR35-1 supports removal of restrictions on radiopharmaceuticals  
SHOAK, W M Miami, FL, Univ of 79/05/31 1p

7907240572 Comments on petition for rulemaking 10CFR35-1 supports removal of restrictions on use of radiopharmaceuticals  
SAENGER, E L Cincinnati, Univ of, Medical School 79/05/29 1p.

7907240579 Comments on petition for rulemaking 10CFR35-1 supports removal of restrictions on radiopharmaceuticals Cites long-term effect ensuring stagnation of medical practice through use of outmoded techniques  
HAYES, M. Affiliation Unknown 79/05/31 1p

7907240586 Comments on petition for rulemaking 10CFR35-1 concurs w/removal of limitations of pharmaceuticals Cites possibility that present rules would stifle utilization of improved technology  
MECKELBURG, R Meckelburg, R L MD 79/05/10 1p

7907240594 Comments on petition for rulemaking 10CFR35-1 physicians should be allowed to perform clinical procedures w/radiopharmaceuticals not specifically listed on package inserts  
LOKEN, M K Minnesota, Univ of, Minneapolis 79/05/31 1p

7907240597 Comments on petition for rulemaking 10CFR20-13 creates unreasonable responsibility for health physicist & erodes licensee control of facility Rulemaking not warranted  
REED, C Commonwealth Edison Co 79/05/14. 1p

7907240617 Comments on petition for rulemaking 10CFR20-13 opposes petition Certification would not guarantee competence or immunity from bad practice Requirements for evaluations & decisionmaking impose severe restrictions on licensee  
MANN, J R Health Physics Society 79/04/27 3pp

7907240629 Comments on petition for rulemaking 10CFR20-13 opposes petition Suggests mod of license application forms to require training & experience resumes  
TARAS, D N Army, Dept of, Headquarters Material Development & Readiness Command 79/04/26 2pp

7907240635 Comments on petition for rulemaking 10CFR20-13 opposes petition because health physicist qualifications are part of license application Proposed recertification & validation are unwieldy for small staffs  
GRANLUND, R W Pennsylvania State Univ 79/03/13 2pp

## NONDOCKETED ITEMS

7907260659 Comments on petition for rulemaking 10CFR20-13 believes petition duplicates current health physics qualifications sys & overregulates by requiring certified health physicist to make all decisions re radiation protection  
WILLIAMS, P R Dow Corning Corp 79/04/23 2pp

7907260668 Comments on petition for rulemaking 10CFR20-13 foresees certification process as addl administrative burden  
Questions legality of authorizing health physicists to establish regulations  
RENZETTI, J L Navy, Dept of, Naval Facilities Engineering Command 79/04/30 1p

7907260678 Comments on petition for rulemaking 10CFR20-13 supports petition Suggests contacting Natl Registry of Radiation Protection Technologists for info re certification program  
SMITH, H P Affiliation Unknown 79/04/09 2pp

7907260973 Comments on proposed rulemaking 10CFR30-56 supports petition re dividing separate reg body to control non-fissile matls & separate regulations for byproduct users  
HOPCRAFT, C P NL Industries, Inc 79/06/14 2pp

7907270056 Comments on petition for rulemaking 10CFR20-13 supports health physicist certification Some THM mistakes might have been avoided w/more effective health physics plan, including adequate emergency plan  
HORGAN, K Z Georgia Institute of Technology 79/05/15 1p

7907270098 Comments on petition for rulemaking 10CFR20-13 personal experience of petitioner not representative of std practice  
Adequate certification programs for health physicists already exist  
WISBINK, R O Affiliation Unknown 79/04/24 2pp

7907270065 Comments on petition for rulemaking 10CFR20-13 public interest adequately protected by state & federal regulations No need for proposed rulemaking  
WARD, J O California, State of 79/05/15 1p

7907270072 Comments on petition for rulemaking 10CFR20-13 proposes referral procedures in event of disagreement between health physicists Contract health physics groups should employ at least one master health physicist  
BELMAN, R L Affiliation Unknown 79/06/06 1p

7907270080 Comments on petition for rulemaking 10CFR20-13 requests clarification re whether certification of health physicists would extend to employees of state or territorial govts  
ROSBARIO, J C Guam 79/04/11 1p

7907270162 Comments on petition for rulemaking 10CFR20-13 suggests effective utilization of existing programs & more explicit criteria re health physics staff qualifications  
SLABACK, L A Affiliation Unknown 79/05/17 2pp

7907310236 Comments on petition for rulemaking 10CFR20-13 opposes petition Current regulations & certification programs assure professional responsibility  
DIPIAZZA, R P Westinghouse Electric Corp WRD-LB&S-743 79/04/30 3pp

7907310257 Comments on petition for rulemaking 10CFR20-13 agrees w/health physicists certification program but foresees implementation difficulties due to varying staff size.  
Certification should also cover radiation safety officers  
PEEPLES, W P Affiliation Unknown 79/03/05 1p

PROJ PROJECTS - PREDOCKET LICENSING

7907020014 POLE third set of interrogatories to intervenor Northern CA Power Agency Certificate of Svc encl.  
DOYLE, M H, ARMSTRONG, W H, FURBUSH, H H McCutchen, Doyle, Brown & Emerson 79/05/29 3pp

7907060124 Forwards analysis of well water samples re ongoing seepage monitoring & control program for 781231-790331 relating to Cobler Corp Canon City Mill expansion project  
MCGRATH, E J, McGrath, E. J 79/05/25 3pp

7907060400 Motion by Northern CA Power Agency for protective order re util 790529 fourth set of interrogatories Questions seek opinions of lawyers about documents supporting case & are duplicative of 790127 interrogatories deferred by ASLB  
DAVIDSON, D I Spiegel & McDiarmid 79/06/18 5pp

7907100074 Forwards TE Circular 79-08, "Attempted Extortion - Lew Enriched" No action required  
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 1p

7907110488 Identifies personnel to whom correspondence should be addressed  
SHEPARD, L B International Generation & Transmission Co, Inc 79/06/15 1p

7907110497 Notices of status of discussions w/DOE re replacement of oil-fired generators in New England through importation of power from Canada Company will arrange for technical & executive meetings  
HARRIS, J N International Generation & Transmission Co, Inc 79/06/14 2pp

7907120644 Forwards "Evaluation of Secondary Heat Transport Sys Transient Natural Circulation Test"  
BOUCHEY, G D Energy, Dept of 79/07/05 3pp

7907120649 "Evaluation of Secondary Heat Transport Sys Transient Natural Circulation Test," prepared by Hanford Engineering Development Lab of Westinghouse  
\* Energy, Dept of TB-3A018 PART C 79/06/13 24pp

7907160097 Affirms ASLB 790125 order modified to reflect content of CA Dept of Water Resources 790607 ltr Pacific Gas & Electric Co agrees to make available documents supplied by Southern CA Edison Co re FERC proceeding.  
ROSENTHAL, A S, FARRAR, M C, SALZMAN, R S Atomic Safety and Licensing Appeal Panel 79/06/15 36pp

7907180728 Responds to NRC first set of interrogatories & document requests Submits info re load dropping ability, reserve capacity, min load, native load & energy back account  
Supporting documentation & Certificate of Svc encl  
MEISS, R L Pacific Gas & Electric Co DOYLE, M H McCutchen, Doyle, Brown & Emerson 79/06/15 178pp

7907180804 Discusses review of NUREG-0535 re yellowcake transportation accidents Forwards "U Ore Concentrate Shippers & Transporters Recommended Transportation Accident Response Guide"  
LANO, E A Atomic Industrial Forum 79/05/18 17pp

7907190371 Comments on NUREG-0535 re Yellowcake packaging & emergency responses to transportation accidents Forwards Electric Util ad hoc Nuclear transportation group statement  
Recommendations endorsed in general  
TROSTEN, L M LeBoeuf, Lamb, Leiby & MacRae 79/05/21 13pp

7907190378 Comments on NUREG-0535 & NUREG/CR-0558 re transportation accidents involving natural U concentrate voluntary industry response to event would be sufficient Proposed mods to 55-gallon shipping drum are not warranted  
SHELLEY, W J Kerr-McGee Corp 79/05/16 2pp

7907240248 Opposition by util to Northern CA Power Agency motion for protective order re 790529 interrogatories "Smoking pistol" documents have been categorized but have not previously been requested Certificate of Svc encl  
FALLIN, J F, McCutchen, Doyle, Brown & Emerson 79/06/27 9pp

7907260246 Responds to 790424 ltr re 8 Battle questions Discusses waste disposal & decontamination at THM, DDE plant at Shippingport.  
PA & estimates costs of nuclear power for state of PA  
OBSICK, L V Office of the Executive Director for Operations 79/06/13 2pp

7907260259 Forwards 8 Battle 790412 ltr w/questions re THM waste disposal, plant at Shippingport, PA & nuclear power costs  
IRELAND, A House of Rep 79/04/24 4pp

7907270227 Forwards comments on seven Nuclear Alternative Sys Assessment Program preliminary safety & environ info documents & backup documents submitted by DOE  
HALLER, N M Office of Management and Program Analysis 79/06/13 155pp

7907270366 NUREG/CR-0553  
"Dispersion & Dosimetry (UDAD) Code."  
MOMENT, M H, YUAN, Y, ZIELEN, A J Argonne National Laboratory ANL/R-72 79/05/31 315pp. Available at NTIS

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

7907240260 Submits results of analysis of injection pump failures per 780922 Part 21 rept re emergency diesel generators Injection pumps removed & revised Pumps are presently in good condition & units ready to startup  
MORIARTY, J M Colt Industries, Inc 79/03/23 1p

7907250190 Submits info as followup to 790412 US Steel has tested 150 loose & installed fittings Will contact customers to review records & rept on installed fittings  
GEORGE, H H Chemetron Corp 79/05/10 2pp

GA999 QUALITY ASSURANCE INSPECTIONS

7907030019 Forwards QA Program Insp Rept 99900364/79-01 on 790327-28 No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/26 2pp

--7907030026 GA Program Insp Rept 99900364/79-01 on 790327-28 No noncompliance noted Major areas inspected followup on const deficiency repts re failed resistance welds in strut matl  
ELLERSHAW, L E, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/04/26 4pp

7907030029 Forwards QA Program Insp Rept 99900404/79-02 on 790403-04 No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/26 2pp

--7907030032 GA Program Insp Rept 99900404/79-02 on 790403-04 No noncompliance noted Major areas inspected followup on IE Bulletin 79-04 re topical rept WCAP-8370 & stress analysis of safety-related piping  
ANDERSON, D G, POTAPQVB, U, HALE, C J Region 4, Dallas, Vendor Inspection Branch 79/04/24 8pp

7907030036 Forwards QA Program Insp Rept 99900061/79-01 on 790403-05 No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/26 2pp

--7907030039 GA Program Insp Rept 99900061/79-01 on 790403-05 No noncompliance noted Major areas inspected implementation of 10CFR50, App B & applicable codes & stds re vendor activities, mfg process control, training & audits  
KELLEY, W D, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch CLEMENSON, F Plant Systems Branch 79/04/25 11pp

7907030084 Ack receipt of 790412 & 27 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900526/79-01  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/05/22 1p

--7907030093 Responds to NRC 790402 ltr re deviation noted in QA Program Insp Rept 99900526/79-01 Corrective actions, will prepare nonconforming item repts re five drawings cited Further conformances will be documented on these repts  
ADAM, P J, Black & Veatch, 79/04/27, 2pp

--7907030097 Ack receipt of QA Program Insp Rept 99900526/79-01 on 790312-16 No proprietary info  
ADAM, P J, Black & Veatch 79/04/12 1p

--7907050101 Forwards QA Program Insp Rept 99900526/79-01 on 790312-16 & notice of deviation  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/02 2pp

--7907050104 Notice of deviation from insp on 790312-16  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/03/30 1p

--7907050109 QA Program Insp Rept 99900526/79-01 on 790312-16 Noncompliance noted, containment spray sys-nuclear requirements authorized w/o approval of QA manager & drawings approved w/o check & signoff by checker.  
BRICKLEY, R H, HALE, C J Region 4, Dallas, Vendor Inspection Branch 79/03/30 6pp.

7907050377 Responds to U Potapova 790509 ltr re QA Program Insp 99900507/79-01 Action to prevent recurrence of deviations confirmed, written instructions will be issued per B&L procedures & will be available for insp on 790601.  
MC FARLAND, J E, Bargent & Lundy, Inc. PROJECT 0037-00 79/05/14, 1p.

7907050530 Forwards QA Program Insp Rept 99900362/79-01 on 790326-27 No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/27 2pp

--7907050536 QA Program Insp Rept 99900362/79-01 on 790326-27 No noncompliance noted Major areas inspected followup of const deficiency rept re failed resistance welds in strut matl  
ELLERSHAW, L E, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/04/27 4pp

7907060041 Forwards QA Program Insp Rept 99900363/79-01 on 790329 No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/26 2pp

--7907060046 QA Program Insp Rept 99900363/79-01 on 790329 No noncompliance noted Major areas inspected follow-up of const deficiency rept re failed resistance welds in strut matl  
ELLERSHAW, L E, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/04/26 3pp

7907090381 Discusses possibility of NRC inspectors signing nondisclosure agreements Ofc of Executive Legal Director advises that inspectors should not sign such agreements  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/05/22 2pp

7907090394 Discusses insp of implementation of QA program described in Topical Rept SL-TR-1A, Revision 5 Implementation is satisfactory  
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/17 2pp

7907090397 Forwards 790227 ltr from Tube Turns re QA Program Insp Rept 99900028/79-02, hand delivered during 790515 insp Original ltr sent to NRC not received  
OLLER, R E Region 4, Dallas, Vendor Inspection Branch 79/05/29 1p

--7907090403 Discusses subcontractor certification for calibr performed in June 1978 on Rockwell Testers 41V05 & 41V06 & gas flow meters on welding equipment not calibr or not on calibr schedule  
SEAY, J L Chemetron Corp, Tube Turns Div 79/02/27 8pp

7907090462 Forwards QA Program Insp Rept 99900300/79-01 on 790402-03 No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/27 2pp

--7907090466 QA Program Insp Rept 99900300/79-01 on 790402-03 No noncompliance noted Major areas inspected implementation of Part 21 rept requirements re fuel injection pump failures & exhaust rocker arm failures  
FOSTER, W E, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/04/25 8pp

7907090470 Forwards QA Program Insp Rept 99900029/79-01 on 781102-03 & 790123-25 No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch 79/04/06, 2pp

--7907090474 QA Program Insp Rept 99900029/79-01 on 781102-03 & 790123-25 No noncompliance noted Major areas inspected implementation of 10CFR50, App B & generic considerations re rejection of SA-312 austenitic stainless steel piping  
OLLER, R E, ROBERDS, H W, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/04/06 12pp

7907090476 Forwards QA Program Insp Rept 99900070/79-01 on 790402-03. No noncompliance noted  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch, 79/04/26 2pp

--7907090478 QA Program Insp Rept 99900070/79-01 on 790402-03 No noncompliance noted Major areas inspected implementation of 10CFR50, App B criteria & codes, including qualification of nondestructive examination personnel  
ROBERDS, H W, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/04/26 5pp

7907100721 Ack receipt of 790509 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900042/79-01  
POTAPQVB, U Region 4, Dallas, Vendor Inspection Branch, 79/05/22, 1p

## NONDOCKETED ITEMS

- 7907100727 Responds to NRC 79041B ltr re deviation noted in QA Program Insp Rept 99900042/79-01 Corrective actions containers of electrodes & flux have been scrapped Warehouse storage area will be maintained in accordance w/procedure HUTCHINSON, L R Babcock & Wilcox Co 79/05/09 2pp
- 7907100733 QA Program Insp Rept 99900042/79-01 on 790326-29 HUNTER, V H, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch 79/04/16 5pp
- 7907100730 Forwards QA Program Insp Rept 99900042/79-01 on 790326-29 & notice of deviation POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/04/16 2pp
- 790710060 Forwards QA Program Insp Rept 99900617/79-01 on 790319-23 No noncompliance noted POTAPQVS, U Region 4, Dallas, Office of the Director 79/04/02 2pp
- 790710069 QA Program Insp Rept 99900617/79-01 on 790330 No noncompliance noted Major areas inspected qualification, experience & training of commissioned inspectors, investigations, records maint & test control ANDERSON, D G, HALE, C J, POTAPQVS, U Region 4, Dallas, Office of the Director 79/03/30 7pp
- 7907100186 Ack receipt of 790330 & 0504 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900089/79-01 POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/03/21 1p
- 7907100191 Responds to NRC 790309 ltr re deviation noted in QA Program Insp Rept 99900089/79-01 Corrective actions visual examination procedure will be revised to include ref to general shop welding std for insp of matl HAN, K Huico, Inc. 79/05/04 2pp
- 7907100194 Responds to NRC 790309 ltr re deviation noted in QA Program Insp Rept 99900089/79-01 Corrective actions issued Acceptance/Receiving Procedure detailing procedure to be followed for dimensional insp of rolled plates HAN, K Huico, Inc 79/03/30 4pp
- 7907100199 Forwards QA Program Insp Rept 99900089/79-01 on 790205-08 & notice of deviation POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/03/09 2pp
- 7907100206 Notice of deviation from insp on 790205-08 \* Region 4, Dallas, Vendor Inspection Branch 79/02/22 2pp
- 7907100213 QA Program Insp Rept 99900089/79-01 on 790205-08. Noncompliance noted dimensional insp not documented by detailed written procedure & welding procedure spec did not document performance of root pass welding MCNEILL, W M, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch 79/02/22 9pp
- 7907100221 Ack receipt of 790330, 0501 & 15 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900116/79-01 POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/05/22 1p
- 7907100228 Responds to NRC 790316 ltr re deviation noted in QA Program Insp Rept 99900116/79-01 Corrective actions all wires/lugs have been reinspected & wires requiring rework have been machined WRIGHT, H D Bunker-Ramo Corp, Amphenol North America Div 79/05/15 5pp.
- 7907100246 Responds to NRC 790316 ltr re deviation noted in QA Program Insp Rept 99900116/79-01 Corrective actions GA mgt has generated GA Engineers "On Job Training Form" Form will be used to document GA Engineer's training Sample forms encl. WRIGHT, H D Bunker-Ramo Corp., Amphenol North America Div 79/05/01 7pp
- 7907100251 Responds to NRC 790316 ltr re deviation noted in QA program Insp Rept 99900116/79-01 Requests addl 30 days to comply. WRIGHT, H D Bunker-Ramo Corp, Amphenol North America Div 79/03/30 1p
- 7907100369 Forwards QA Program Insp Rept 99900116/79-01 on 790220-23 & notice of deviation POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch. 79/03/16, 2pp
- 7907100370 Notice of deviation from insp on 790220-23 \* Region 4, Dallas, Vendor Inspection Branch 79/03/15 1p
- 7907100372 QA Program Insp Rept 99900116/79-01 on 790220-23 Noncompliance noted QA dept personnel had not received specific auditor training AGE, J R, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/03/15 10pp
- 7907100335 Forwards QA Program Insp Rept 99900505/79-02 on 790409-13 No noncompliance noted POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/04/27 2pp
- 7907100349 QA Program Insp Rept 99900505/79-02 on 790409-13 No noncompliance noted Major areas inspected implementation of topical rept ETR-1001 re design inputs, design corrective action & product acceptance COSTELLO, J R, BROWN, R L, HALE, C J Region 4, Dallas, Vendor Inspection Branch 79/04/26 14pp
- 7907100732 Forwards QA Program Insp Rept 99900058/79-01 on 790417-19 No noncompliance noted POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/05/08 2pp
- 7907100742 QA Program Insp Rept 99900058/79-01 on 790417-19 No noncompliance noted Major areas inspected implementation of 10CFR50 App B, including design verification, computer program & weld heat KELLEY, W D, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch 79/05/07 10pp
- 7907230055 Ack receipt of 790531 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900519/79-02 POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/06/15 1p
- 7907230059 Responds to NRC 790503 ltr re deviation noted in QA Program Insp Rept 99900519/79-02 Corrective actions log established to include action items from all verification meetings & program procedure prepared for sys descriptions BALD, C E Bechtel Power Corp (subs of Bechtel Corp) 79/05/31 18pp
- 7907230061 Forwards QA Program Insp Rept 99900519/79-02 on 790409-13 & notice of deviation POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/05/03 2pp
- 7907230067 Notice of deviation from insp on 790409-13 \* Region 4, Dallas, Vendor Inspection Branch 79/05/03 3pp
- 7907230074 QA Program Insp Rept 99900519/79-02 on 790409-13 Noncompliance noted log for unresolved issues & positive closure sys not established as required by project procedures & personnel not adequately trained HALE, C J, BRICKLEY, R H, JOHNSON, J M Region 4, Dallas, Vendor Inspection Branch 79/05/03 19pp
- 7907230286 Ack receipt of 790608 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99900401/79-02 POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/06/18 1p
- 7907230291 Responds to NRC 790510 ltr re deviation noted in QA Program Insp Rept 99900401/79-02 Corrective actions GC corrective action log updated to indicate status of corrective action audit records & log book to be reviewed monthly ETHERIDGE, M R Combustion Engineering, Inc 79/06/08 2pp
- 7907230297 Forwards QA Program Insp Rept 99900401/79-02 on 790423-27 & notice of deviation POTAPQVS, U Region 4, Dallas, Vendor Inspection Branch 79/05/10 2pp
- 7907230302 Notice of deviation from insp on 790423-27 \* Region 4, Dallas, Vendor Inspection Branch 79/05/09 1p
- 7907230308 QA Program Insp Rept 99900401/79-02 on 790423-27 Noncompliance noted some audit repts undated & two different corrective action repts assigned same ID number HALE, C J, BROWN, R L, COSTELLO, J R Region 4, Dallas, Vendor Inspection Branch 79/05/09 25pp

7907230730 Forwards GA Program Insp Rept 99900502/79-02 on 790507-11 No noncompliance noted  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/05/25 2pp

--7907230736 GA Program Insp Rept 99900502/79-02 on 790507-11 No noncompliance noted Major areas inspected implementation of 10CFR50, App B & Topical Rept B&R-002A, including design change control & action on previous insp findings  
ANDERSON, D O , HALE, C J Region 4, Dallas, Vendor Inspection Branch 79/05/23 8pp

7907240261 Ack receipt of 790612 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept  
99900307/79-01  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/06/28 1p

--7907240262 Responds to NRC 790522 ltr re deviation noted in GA Program Insp Rept 99900307/79-01 Corrective actions GA manual clarifications re use of tools, instruments, gages, measuring & testing devices will be completed within 30 days  
PANCIERA, N Litton Bionetics, Inc (subs of Litton Industries, Inc ) 79/06/12 2pp

--7907240263 Forwards GA Program Insp Rept 99900307/79-01 on 790409-13 & notice of deviation  
POTAPQVS,U Region 4, Dallas, Office of the Director 79/05/22 2pp

--7907240264 Notice of deviation from insp on 790409-13  
\* Region 4, Dallas, Vendor Inspection Branch 79/05/21 1p

--7907240265 GA Program Insp Rept 99900307/79-01 on 790409-13 Noncompliance noted all tools, gauges & instruments used in mfg activities not calibr & pressure gauges not clearly marked  
SUTTON, J W , WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/05/21 7pp

790725009B Forwards GA Program Insp Rept 99900048/79-01 on 790409-12 No noncompliance noted  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/05/02 23pp

--7907250102 GA Program Insp Rept 99900048/79-01 on 790409-12 No noncompliance noted Major areas inspected implementation of 10CFR50 criteria & applicable codes & stds, including mgt meeting, inspector interface & mfg process control  
HUNTER, V H, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/04/28 2pp

7907250149 Forwards GA Program Insp Rept 99900118/79-01 on 790507-09 No noncompliance noted  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/05/21 2pp

--7907250154 GA Program Insp Rept 99900118/79-01 on 790507-09 No noncompliance noted Major areas inspected implementation of 10CFR50 App B & applicable codes & stds & vendor action on previously identified items  
KELLEY, W D , WHITESELL, D E, Region 4, Dallas, Vendor Inspection Branch 79/05/17 12pp

7907250190 Ack receipt of 790510 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept  
99900293/79-01  
POTAPQVS,U Region 4, Dallas, Fuel Facility & Materials Safety Branch. 79/06/03. 1p

--7907250192 Responds to NRC 790423 ltr re deviation noted in GA Program Insp Rept 99900293/79-01 Corrective actions weld procedure HS-BA-6 revised & requalified to include tighter control of interpass temp  
CAPRON, L P Gulf & Western Industries, Inc 79/05/10 2pp

--7907250195 Forwards GA Program Insp Rept 99900293/79-01 on 790326-30 & notice of deviation  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/04/23. 1p

--7907250196 Notice of deviation from insp on 790326-30  
\* Region 4, Dallas, Vendor Inspection Branch 79/04/19 2pp

--7907250197 GA Program Insp Rept 99900293/79-01 on 790326-30 Noncompliance noted welding procedure gas flow rate not maintained as required. Specific weld metal deposit & flux identified in procedure qualification record  
SUTTON, J W , WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch. 79/04/19 5pp

7907250328 Ack receipt of 790511 & 0613 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept  
99900113/79-01  
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/06/22 1p

--7907250334 Responds to NRC 790601 ltr re deviation noted in GA Program Insp Rept 99900113/79-01 Corrective actions manager of engineering svcs instructed employees to ensure that all documents are complete prior to filing  
WELT, O International Telephone & Telegraph Corp 79/06/13 6pp

--7907250339 Responds to NRC 790601 ltr re deviation noted in GA Program Insp Rept 99900113/79-01 Corrective actions manager of engineering svcs has been replaced Std & procedures engineer hired to maintain std & procedures  
WELT, O International Telephone & Telegraph Corp 79/05/11 3pp

--7907250347 Ack receipt of 790511 ltr Requests addl info re steps taken to correct documents referred to in Item A of notice of deviation  
SEYFRIT, K V Region 4, Dallas, Office of the Director  
79/06/01 1p

--7907250355 Forwards GA Program Insp Rept 99900113/79-01 on 790220-23 & notice of deviation  
SEYFRIT, K V Region 4, Dallas, Office of the Director  
79/04/10 2pp

--7907250360 Notice of deviation from insp on 790220-23  
\* Region 4, Dallas, Office of the Director 79/06/26 2pp

--7907250367 GA Program Insp Rept 99900113/79-01 on 790220-23 Noncompliance noted failure to take committed corrective actions relative to Insp Rept 78-01  
FOSTER, W E , HUNNICUTT, D M Region 4, Dallas, Office of the Director 79/03/26 6pp

7907250348 Ack receipt of 790524 ltr informing NRC of steps taken to correct unresolved item noted in GA Program Insp Rept  
99900404/79-02  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/06/07 1p

--7907250553 Responds to NRC 790426 ltr re unresolved item noted in GA Program Insp Rept 99900404/79-02, Corrective actions investigation of effects of valve discrepancy, notification of customers, correction of drawings & QA surveillance  
JACOB, W M Westinghouse Electric Corp PAS-EJH-79-131 79/06/24 4pp

7907250558 Ack receipt of 790529 ltr informing NRC of steps taken to correct finding noted in GA Program Insp Rept  
99900177/78-02  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/06/12 1p

--7907250561 Responds to NRC 790402 & 781219 ltrs re finding noted in GA Program Insp Rept 99900177/78-02 Corrective actions weld test specs & procedures changed & personnel alerted of problem  
SCHWAB, O Dravo Corp. 79/05/29 1p

7907250563 Ack receipt of 790614 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept  
99900004/79-02  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch.  
79/06/28 1p

--7907250569 Responds to NRC 790426 ltr re deviation noted in GA Program Insp Rept 99900004/79-02 Corrective actions, GA review of analytical chemistry lab procedures will accomplish desired degree of control w/o conversion of those procedures  
RICKARD, C L General Atomic Co. (subs of Oulf Oil Corp ). 79/06/14 1p

7907260010 Ack receipt of 790615 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept  
99900266/79-01  
POTAPQVS,U Region 4, Dallas, Vendor Inspection Branch  
79/06/28 1p

--7907260029 Responds to NRC 790530 ltr re deviation noted in GA Program Insp Rept 99900266/79-01, Corrective actions, welders reminded of emergency sys group requirement & weld procedure evaluated & revised.  
MCDERMOTT, R J Rockwell International Corp 79/06/15 2pp

## NONDOCKETED ITEMS

- 7907260045 Forwards QA Program Insp Rept 99900266/79-01 on 790430-0502 & notice of deviation  
PDTAPOVS,U Region 4, Dallas, Vendor Inspection Branch  
79/03/30 2pp
- 7907260081 Notice of deviation from insp on 790430-0502  
\* Region 4, Dallas, Office of the Director 79/03/29 1p
- 7907260090 QA Program Insp Rept 99900266/79-01 on 790430-0502  
Noncompliance noted failure to weld per specified amperage range  
HUNTER, V H, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch  
79/03/29 5pp
- 7907260100 Act receipt of 790521 & 0611 ltrs informing NRC of steps taken to correct deviations noted in QA Program Insp Rept  
99900100/79-01  
PDTAPOVS,U Region 4, Dallas, Vendor Inspection Branch  
79/06/21 1p
- 7907260116 Responds to NRC 790426 ltr re deviation noted in QA Program Insp Rept 99900100/79-01  
Corrective actions welding will be performed & data will be maintained to furnish evidence of personnel qualifications  
GRQOME,K Limitorque Corp 79/06/11 2pp
- 7907260130 Act receipt of 790521 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept  
99900100/79-01  
PDTAPOVS,U Region 4, Dallas, Vendor Inspection Branch  
79/06/01 1p
- 7907260138 Responds to NRC 790426 ltr re deviation noted in QA Program Insp Rept 99900100/79-01  
Corrective actions welding procedure will be revised & welder in process of being qualified  
GRQOME,K Limitorque Corp 79/05/21 2pp
- 7907260144 Forwards QA Program Insp Rept 99900100/79-01 on 790326-29 & notice of deviation  
PDTAPOVS,U Region 4, Dallas, Vendor Inspection Branch  
79/04/26 2pp
- 7907260147 Notice of deviation from insp on 790326-29  
\* Region 4, Dallas, Vendor Inspection Branch 79/04/24 1p
- 7907260158 QA Program Insp Rept 99900100/79-01 on 790326-29  
Noncompliance noted failure of welding control procedure to provide parameters necessary for BNAW & GMAW control & failure to maintain records of welder qualification  
OLLER, R E, ADER, J R, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/04/24 18pp
- REGGD REGULATORY GUIDES
- 7906210407 Comments on proposed Revision 2 to Reg Guide 1 B requests extension of comment period for at least another 30 days due to involvement in TMI incident  
TERPILAK, M S American Board of Health Physics 79/04/20 1p
- 7907090241 Notification of intent to use respiratory protective equipment in accordance w/Reg Guide B 15  
WISSINK, R O 3M Co., Minnesota Mining & Mfg Co 79/06/05 1p
- 7907100048 Reg Guide 1 1, "Net Positive Suction Head for Emergency Core Cooling & Containment Heat Removal Sys Pumps."  
\* Office of Standards Development 70/11/02 1p
- 7907100050 Reg Guide 1 2, "Thermal Shock to Reactor Pressure Vessels"  
\* Office of Standards Development 70/11/02 2pp
- 7907100054 Reg Guide 1 3, Revision 2, "Assumptions Used for Evaluating Potential Radiological Consequences of LOCA for BWR"  
\* Office of Standards Development 74/06/30 12pp
- 7907100058 Reg Guide 1 4, "Assumptions Used for Evaluating Potential Radiological Consequences of LOCA for BWR"  
\* Office of Standards Development 74/06/30 6pp
- 7907100059 Reg Guide 1 5, "Assumptions Used for Evaluating Potential Radiological Consequences of Steam Line Break Accident for BWRs"  
\* Office of Standards Development 71/03/10 4pp
- 7907100064 Reg Guide 1 6, "Independence Between Redundant Standby (Onsite) Power Sources & Between Their Distribution Sys"  
\* Office of Standards Development 72/12/31 2pp
- 7907100073 Reg Guide 1 8, Revision 1R, "Personnel Selection & Training"  
\* Office of Standards Development 77/03/31 2pp
- 7907100075 Reg Guide 1 10, Revision 1, "Mechanical (Cadmold) Splices in Reinforcing Bars of Category 1 Concrete Structures"  
\* Office of Standards Development 73/01/02 3pp
- 7907100077 Reg Guide 1 12, Revision 1, "Instrumentation for Earthquakes"  
\* Office of Standards Development 74/04/30 3pp
- 7907100079 "For Comment" issue of Reg Guide 1 13, Revision 1, "Open Fuel Storage Facility Design Basis"  
\* Office of Standards Development 79/12/31 3pp
- 7907100083 "For Comment" issue of Reg Guide 1 14, Revision 1, "Reactor Coolant Pump Flywheel Integrity"  
\* Office of Standards Development 79/08/31 4pp
- 7907100086 Reg Guide 1 15, Revision 1, "Testing of Reinforcing Bars for Category 1 Concrete Structures"  
\* Office of Standards Development 72/12/25 2pp
- 7907100088 "For Comment" issue of Reg Guide 1 16, Revision 4, "Reporting of Operating Info - App A Tech Specs"  
\* Office of Standards Development 75/08/31 15pp
- 7907100091 Reg Guide 1 17, "Protection of Nuclear Power Plants Against Industrial Sabotage"  
\* Office of Standards Development 73/06/30 2pp
- 7907100098 Reg Guide 1 19, Revision 1, "Nondestructive Examination of Primary Containment Liner Welds"  
\* Office of Standards Development 72/08/11 4pp
- 7907100101 Reg Guide 1 20, Revision 2, "Comprehensive Vibration Assessment Program for Reactor Internals During Preoperational & Initial Startup Testing"  
\* Office of Standards Development 76/05/31 8pp
- 7907100104 Reg Guide 1 21, Revision 1, "Measuring, Evaluating & Reporting Radioactivity in Solid Waste & Releases of Radioactive Matter in Liquid & Gaseous Effluents from Light Water Cooled Nuclear Power Plants"  
\* Office of Standards Development 74/06/30 21pp
- 7907100108 Reg Guide 1 22, "Periodic Testing of Protection Sys Actuation Functions"  
\* Office of Standards Development 72/02/17 3pp
- 7907100112 Reg Guide 1 23, "Onsite Meteorological Programs"  
\* Office of Standards Development 72/02/17 6pp
- 7907100119 Reg Guide 1 24, "Assumptions Used for Evaluating Potential Radiological Consequences of PWR Radioactive Gas Storage Tank Failure"  
\* Office of Standards Development 72/03/23 6pp
- 7907100118 Reg Guide 1 25, "Assumptions Used for Evaluating Potential Radiological Consequences of Fuel Handling Accident in Fuel Handling & Storage Facility for BWRs & PWRs"  
\* Office of Standards Development 72/03/23 10pp
- 7907100120 "For Comment" issue of Reg Guide 1 26, Revision 3, "Quality Group Classifications & Stds for Water, Steam & Radioactive Waste Containing Components of Nuclear Power Plants."  
\* Office of Standards Development 76/02/29 3pp
- 7907100126 "For Comment" issue of Reg Guide 1 27, Revision 2, "Ultimate Heat Sink for Nuclear Power Plants"  
\* Office of Standards Development 76/01/31 5pp
- 7907100128 "For Comment" issue of Reg Guide 1 28, Revision 1, "QA Program Requirements (Design & Const)."  
\* Office of Standards Development 78/03/31 2pp
- 7907100134 Reg Guide 1 30, "QA Requirements for Installation, Insp & Testing of Instrumentation & Electric Equipment"  
\* Office of Standards Development 72/08/11 1p



7907100138 Reg Guide 1 31, Revision 3, "Control of Ferrite Content in Stainless Steel Weld Metal "	* Office of Standards Development	78/04/30	5pp
7907100141 Reg Guide 1 32, Revision 2, "Criteria for Safety-Related Electric Power Sys for Nuclear Power Plants "	* Office of Standards Development	77/02/28	3pp
7907100144 Reg Guide 1 33, Revision 2, "QA Program Requirements (Operation) "	* Office of Standards Development	78/02/28	7pp
7907100147 Reg Guide 1 34, "Control of Electroslag Weld Properties "	* Office of Standards Development	72/12/28	3pp
7907100149 Reg Guide 1 35, Revision 2, "Inservice Insp of UngROUTed Tendons in Prestressed Concrete Containment Structures "	* Office of Standards Development	76/01/31	4pp
7907100152 Reg Guide 1 36, "Nonmetallic Thermal Insulation for Austenitic Stainless Steel "	* Office of Standards Development	73/02/23	3pp
7907100157 Reg Guide 1 37, "QA Requirements for Cleaning of Fluid Sys & Associated Components of Water Cooled Nuclear Power Plants "	* Office of Standards Development	73/03/16	2pp
7907100158 Reg Guide 1 38, Revision 2, "QA Requirements for Packaging, Shipping, Receiving, Storage & Handling of Items for Water Cooled Nuclear Power Plants "	* Office of Standards Development	77/05/31	2pp
7907100163 Reg Guide 1 39, Revision 2, "Housekeeping Requirements for Water Cooled Nuclear Power Plants "	* Office of Standards Development	77/09/30,	2pp
7907100166 Reg Guide 1 40, "Qualification Tests of Continuous Duty Motors Installed in Containment of Water Cooled Nuclear Power Plants "	* Office of Standards Development	73/03/16	1p
7907100171 Reg Guide 1 41, "Preoperational Testing of Redundant Onsite Electric Power Sys to Verify Proper Load Group Assignments "	* Office of Standards Development	73/03/16	2pp
7907100174 NRC has withdrawn Reg Guide 1 42, Revision 1, "Interim Licensing Policy on as Low as Practicable for Gaseous Radiiodine Releases from Light Water Cooled Nuclear Power Reactors " See Reg Guides 1 109, 1 111 & 1 112 for guidance HINDQUE, R B	* Office of Standards Development	76/03/18	1p
7907100178 Reg Guide 1 43, "Control of Stainless Steel Weld Cladding of Low Alloy Steel Components "	* Office of Standards Development	73/05/31	3pp
7907100182 Reg Guide 1 44, "Control of Use of Sensitized Stainless Steel "	* Office of Standards Development	73/05/31	3pp
7907100185 Reg Guide 1 45, "Reactor Coolant Pressure Boundary Leakage Detection Sys "	* Office of Standards Development	73/05/31	4pp
7907100189 Reg Guide 1 46, "Protection Against Pipe Whip Inside Containment "	* Office of Standards Development	73/05/31	4pp
7907100191 Reg Guide 1 47, "Bypasses & Inoperable Status Indication for Nuclear Power Plant Safety Sys "	* Office of Standards Development	73/05/31	3pp
7907100195 Reg Guide 1 48, "Design Limits & Loading Combinations for Seismic Category I Fluid Sys Components "	* Office of Standards Development	73/05/31	8pp
7907100197 Reg Guide 1 49, Revision 1, "Power Levels of Nuclear Power Plants "	* Office of Standards Development	73/12/31	2pp
7907100199 Reg Guide 1 50, "Control of Preheat Temp for Welding of Low Alloy Steel "	* Office of Standards Development	73/05/31	2pp
7907100205 NRC has withdrawn Reg Guide 1 51, "Inservice Insp of ASME Code Class 2 & 3 Nuclear Power Plant Components " Guidance is incorporated in ASME Boiler & Pressure Vessel Code Section XI, 1974 edition, currently referenced in licensing	* Office of Standards Development	75/07/15	1p.
7907100211 Reg Guide 1 52, Revision 2, "Design, Testing & Maint Criteria for Post-Accident Engineered Safety Feature Atmosphere Cleanup Sys Air Filtration & Absorption Units of Light Water Cooled Nuclear Power Plants "	* Office of Standards Development	78/03/31	8pp
7907100213 Reg Guide 1 53, "Application of Single Failure Criteria to Nuclear Power Plant Protection Sys "	* Office of Standards Development	73/06/30	2pp
7907100215 Reg Guide 1 54, "QA Requirements for Protective Coatings Applied to Water Cooled Nuclear Power Plants "	* Office of Standards Development	73/06/30	2pp
7907100218 Reg Guide 1 55, "Concrete Placement in Category 1 Structures "	* Office of Standards Development	73/06/30	3pp
7907100220 Reg Guide 1 57, "Design Limits & Loading Combinations for Metal Primary Reactor Containment Sys Components "	* Office of Standards Development	73/06/30	6pp
7907100224 Reg Guide 1 58, "Qualification of Nuclear Power Plant Insp, Examination & Testing Personnel "	* Office of Standards Development	73/08/31	2pp
7907100225 Reg Guide 1 59, Revision 2, "Design Basic Floods for Nuclear Power Plants "	* Office of Standards Development	77/08/31	66pp
7907100227 Reg Guide 1 60, Revision 1, "Design Response Spectra for Seismic Design of Nuclear Power Plants "	* Office of Standards Development	73/12/31	6pp
7907100231 Reg Guide 1 61, "Damping Values for Seismic Design of Nuclear Power Plants "	* Office of Standards Development	73/10/31	2pp
7907100235 Reg Guide 1 62, "Manual Initiation of Protective Actions "	* Office of Standards Development	73/10/31	2pp
7907100240 Reg Guide 1 63, Revision 2, "Electric Penetration Assemblies in Containment Structures for Light-Water-Cooled Nuclear Power Plants "	* Office of Standards Development	78/07/31	3pp
7907100242 Reg Guide 1 64, Revision 2, "QA Requirements for Design of Nuclear Power Plants "	* Office of Standards Development	76/06/30	2pp
7907100246 Reg Guide 1 65, "Mats & Insp for Reactor Vessel Closure Studs "	* Office of Standards Development	73/01/31	4pp
7907100250 NRC has withdrawn Reg Guide 1 66, "Nondestructive Examination of Tubular Products " Guide was supplemental to ASME Code for tubular products, which has now incorporated Guide's important regulatory positions HINDQUE, R B	* Office of Standards Development	77/09/28	1p
7907100253 Reg Guide 1 67, "Installation of Overpressure Protection Devices."	* Office of Standards Development	73/10/31	2pp
7907100257 Reg Guide 1 68, Revision 2, "Initial Test Programs for Water Cooled Nuclear Power Plants "	* Office of Standards Development.	78/08/31	23pp
7907100261 Reg Guide 1 68 1, Revision 1, "Preoperational & Initial Startup Testing of Feedwater & Condensate Sys for DWR Power Plants "	* Office of Standards Development	77/01/31	3pp
7907100265 Reg Guide 1 68 2, Revision 1, "Initial Startup Test Program to Demonstrate Remote Shutdown Capability for Water Cooled Nuclear Power Plants "	* Office of Standards Development	78/07/31	3pp
7907100274 Reg Guide 1 69, "Concrete Radiation Shields for Nuclear Power Plants "	* Office of Standards Development.	73/12/31	2pp.
7907100275 Reg Guide 1 71, "Welder Qualification for Areas of Limited Accessibility."	* Office of Standards Development	73/12/31.	2pp

## NONDOCKETED ITEMS

- 7907100220 Reg Guide 1 74, "QA Terms & Definitions "  
\* Office of Standards Development 74/02/28 1p
- 7907100297 Reg Guide 1 76, "Design Basis Tornado for Nuclear Power Plants "  
\* Office of Standards Development 74/04/30 3pp
- 7907100299 Reg Guide 1 77, "Assumptions Used for Evaluating Control Rod Ejection Accident for FWRs "  
\* Office of Standards Development 74/03/31 11pr
- 7907100301 Reg Guide 1 78, "Assumptions Used for Evaluating Habitability of Nuclear Power Plant Control Room During Postulated Hazardous Chemical Release "  
\* Office of Standards Development 74/06/30 10pp
- 7907100310 Reg Guide 1 80, "Preoperational Testing of Operations: Air Sys "  
\* Office of Standards Development 74/06/30 2pp
- 7907100314 Reg Guide 1 81, Revision 1, "Shared Emergency & Shutdown Electric Sys for Multi-Unit Nuclear Power Plants "  
\* Office of Standards Development 73/01/31 2pp
- 7907100317 Reg Guide 1 83, Revision 1, "Inservice Insp of PWR Steam Generator Tubes "  
\* Office of Standards Development 74/07/31 5pp
- 7907100321 Reg Guide 1 86, "Termination of Operating Licenses for Nuclear Reactors "  
\* Office of Standards Development 74/06/30 5pp
- 7907100323 Reg Guide 1 88, Revision 2, "Collection, Storage & Maint of Nuclear Power Plant QA Records "  
\* Office of Standards Development 76/10/31 2pp
- 7907100326 Reg Guide 1 89, "Qualification of Class IE Equipment for Nuclear Power Plants "  
\* Office of Standards Development 74/11/30 2pp
- 7907100329 Reg Guide 1 90, Revision 1, "Inservice Insp of Prestressed Concrete Containment Structures w/Grouted Tendons "  
\* Office of Standards Development 77/08/31 12pp
- 7907100333 "For Comment" issue of Reg Guide 1 91, Revision 1, "Evaluations of Explosions Postulated to Occur on Transportation Routes Near Nuclear Power Plants "  
\* Office of Standards Development 78/02/28 6pp
- 7907100336 Reg Guide 1 92, Revision 1, "Combining Modal Responses & Spatial Components in Seismic Response Analysis "  
\* Office of Standards Development 76/02/28 5pp
- 7907100337 Reg Guide 1 93, "Availability of Electric Power Sources "  
\* Office of Standards Development 74/12/31 9pp
- 7907100342 Reg Guide 1 94, Revision 1, "QA Requirements for Installation, Insp & Testing of Structural Concrete & Structural Steel During Const Phase of Nuclear Power Plants "  
\* Office of Standards Development 76/04/30 2pp
- 7907100345 Reg Guide 1 95, Revision 1, "Protection of Nuclear Power Plant Control Room Operators Against Accidental Chlorine Release "  
\* Office of Standards Development 77/01/31 6pp
- 7907100349 Reg Guide 1 96, Revision 1, "Design of Main Steam Isolation Valve Leakage Control Sys for BWR Nuclear Power Plants "  
\* Office of Standards Development 76/06/30 5pp
- 7907100354 Reg Guide 1 97, Revision 1, "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant Conditions During & Following Accident "  
\* Office of Standards Development 77/08/31 4pp
- 7907100358 Reg Guide 1 98, "Assumptions Used for Evaluating Potential Radiological Consequences of Radioactive Offgas Sys Failure in a BWR "  
\* Office of Standards Development 76/03/31 6pp
- 7907100362 Reg Guide 1 99, Revision 1, "Effects of Residual Elements on Predicted Radiation Damage to Reactor Vessel Metals "  
\* Office of Standards Development 77/04/30 6pp
- 7907100366 Reg Guide 1 100, Revision 1, "Seismic Qualification of Electric Equipment for Nuclear Power Plants "  
\* Office of Standards Development 77/03/31 2pp
- 7907100372 Reg Guide 1 102, Revision 1, "Flood Protection for Nuclear Power Plants "  
\* Office of Standards Development 76/09/30 9pp
- 7907100377 Reg Guide 1 103, Revision 1, "Post-Tensioned Prestressing Sys for Concrete Reactor Vessels & Containments "  
\* Office of Standards Development 76/10/31 4pp
- 7907100383 "For Comment" issue of Reg Guide 1 104 "Overhead Crane Handling Sys for Nuclear Power Plants, "  
\* Office of Standards Development 76/02/28 10pp
- 7907100386 Reg Guide 1 105, Revision 1, "Instrument Selpoints "  
\* Office of Standards Development 76/11/30 2pp
- 7907100392 Reg Guide 1 106, Revision 1, "Thermal Overload Protection for Electric Motors on Motor-Operated Valves "  
\* Office of Standards Development 77/03/31 2pp
- 7907100394 Reg Guide 1 107, Revision 1, "Qualifications for Cement Grouting for Prestressing Tendons in Containment Structures "  
\* Office of Standards Development 77/02/28 7pp
- 7907100397 Reg Guide 1 108, Revision 1, "Periodic Testing of Diesel Generator Units Used as Onsite Electric Power Sys at Nuclear Power Plants, " Errata sheet encl  
\* Office of Standards Development 77/08/31 5pp
- 7907100401 Reg Guide 1 109, Revision 1, "Calculation of Annual Doses to Man from Routine Releases of Reactor Effluents for Purpose of Evaluating Compliance w/10CFR90, App 1 "  
\* Office of Standards Development 77/10/31 80pp
- 7907100403 "For Comment" issue of Reg Guide 1 110, "Cost/Benefit Analysis for Radwaste Sys for Light Water Cooled Nuclear Power Reactors "  
\* Office of Standards Development 76/03/31 89pp
- 790710072 Reg Guide 1 111, Revision 1, "Methods for Estimating Atmospheric Transport & Dispersion of Gaseous Effluents in Routine Releases from Light-Water-Cooled Reactors "  
\* Office of Standards Development 77/07/31 24pp
- 790710083 Reg Guide 1 112, Revision D-R, "Calculation of Releases of Radioactive Matl in Gaseous & Liquid Effluents from Light Water Cooled Power Reactors "  
\* Office of Standards Development 76/04/30 13pp
- 790710090 Reg Guide 1 113, Revision 1, "Estimating Aquatic Dispersion of Effluents from Accidental & Routine Reactor Releases for Purpose of Implementing App 1 "  
\* Office of Standards Development 77/04/30 55pp
- 790710094 Reg Guide 1 115, Revision 1, "Protection Against Low-Trajectory Turbine Missiles, "  
\* Office of Standards Development 77/07/31 4pp
- 790710099 Reg Guide 1 116, Revision D-R, "QA Requirements for Installation, Insp & Testing of Mechanical Equipment & Sys "  
\* Office of Standards Development 77/03/31 2pp
- 790710104 Reg Guide 1 117, Revision 1, "Tornado Design Classification "  
\* Office of Standards Development 78/04/30 3pp
- 790710110 Reg Guide 1 118, Revision 2, "Periodic Testing of Electric Power & Protection Sys "  
\* Office of Standards Development 78/06/30 3pp
- 790710117 Notifies that NRC has withdrawn Reg Guide 1 119, "Surveillance Program for New Fuel Assembly Designs, " Need for data from fuel surveillance programs will be addressed in updates of Reg Guide 1 70  
MINDQUE, R B Office of Standards Development 77/06/23 1p
- 790710123 "For Comment" issue of Reg Guide 1 120, Revision 1, "Fire Protection Guidelines for Nuclear Power Plants, "  
\* Office of Standards Development 77/11/30 29pp
- 790710128 "For Comment" issue of Reg Guide 1 121, "Rules for Plugging Degraded PWR Steam Generator Tubes "  
\* Office of Standards Development 76/08/31 8pp

- 7907110133 Reg Guide 1 122, Revision 1, "Development of Floor Design Response Spectra for Seismic Design of Floor-Supported Equipment or Components "
- \* Office of Standards Development 78/02/28 4pp
- 7907110140 Reg Guide 1 124, Revision 1, "Svr Limits & Loading Combinations for Class 1 Linear-Type Component Supports "
- \* Office of Standards Development 78/01/31 6pp
- 7907110144 Reg Guide 1 126, Revision 1, "Acceptable Model & Related Statistical Methods for Analysis of Fuel Densification "
- \* Office of Standards Development 78/03/31 5pp
- 7907110147 Reg Guide 1 127, Revision 1, "Insp of Water-Control Structures Associated W/Nuclear Power Plants "
- \* Office of Standards Development 78/03/31 8pp
- 7907110155 Reg Guide 1 129, Revision 1, "Maint, Testing & Replacement of Large Lead Storage Batteries for Nuclear Power Plants "
- \* Office of Standards Development 78/02/28 2pp
- 7907110158 "For Comment" issue of Reg Guide 1 131, "Qualification Tests of Electric Cables, Field Splices & Connections for Light Water Cooled Nuclear Power Plants "
- \* Office of Standards Development 77/08/31 4pp
- 7907110161 "For Comment" issue of Reg Guide 1 132, "Site Investigations for Foundations of Nuclear Power Plants "
- \* Office of Standards Development 77/09/30 30pp
- 7907110168 "For Comment" issue of Reg Guide 1 133, "Loose Part Detection Program for Primary Sys of Light Water Cooled Reactors "
- \* Office of Standards Development 77/09/30 6pp
- 7907110173 "For Comment" issue of Reg Guide 1 135, "Normal Water Level & Discharge at Nuclear Power Plants "
- \* Office of Standards Development 77/09/30 5pp
- 7907110181 "For Comment" issue of Reg Guide 1 137, "Fuel-Oil Sys for Standby Diesel Generators "
- \* Office of Standards Development 78/01/31 4pp
- 7907110184 "For Comment" issue of Reg Guide 1 138, "Lab Investigations of Soils for Engineering Analysis & Design of Nuclear Power Plants "
- \* Office of Standards Development 78/04/30 18pp
- 7907110190 Reg Guide 2 1, "Shield Test Program for Evaluation of Installed Biological Shielding in Research & Training Reactors "
- \* Office of Standards Development 73/05/31 2pp
- 7907110193 Reg Guide 2 2, "Development of Tech Specs for Experiments in Research Reactors "
- \* Office of Standards Development 73/11/30 4pp
- 7907110204 Reg Guide 2 3, Revision 1, "Quality Verification for Plate-Type U-Al Fuel Elements for Use in Research Reactors "
- \* Office of Standards Development 76/07/31 3pp
- 7907110214 Reg Guide 2 4, Revision O-R, "Review of Experiments for Research Reactors " Front page reissued May 1977
- \* Office of Standards Development 76/07/31 6pp
- 7907110221 Reg Guide 2 5, Revision O-R, "QA Program Requirements for Research Reactors " (Reissue of first page w/words "For Comment" deleted )
- \* Office of Standards Development 77/10/31 2pp
- 7907110229 Reg Guide 3 1, "Use of Borosilicate-Glass Rashig Rings as Neutron Absorber in Solutions of Fissile Matl "
- \* Office of Standards Development 73/01/08 1p
- 7907110233 Reg Guide 3 2, "Efficiency Testing of Air-Cleaning Sys Containing Devices for Removal of Particles."
- \* Office of Standards Development 73/01/08 1p
- 7907110237 Reg Guide 3 3, Revision 1, "QA Program Requirements for Fuel Reprocessing Plants & for Pu Processing & Fuel Fabrication Plants "
- \* Office of Standards Development 74/03/31 1p
- 7907110244 Reg Guide 3 4, Revision 1-R, "Nuclear Criticality Safety in Operations W/Fissionable Matls Outside Reactors "
- \* Office of Standards Development 78/02/28 1,2pp
- 7907110250 Reg Guide 3 6, "Content of Tech Specs for Fuel Reprocessing Plants "
- \* Office of Standards Development 73/04/09 8pp
- 7907110260 Reg Guide 3 7, "Monitoring of Combustible Gases & Vapors in Pu Processing & Fuel Fabrication Plants "
- \* Office of Standards Development 73/03/21 2pp
- 7907110270 "For Comment" issue of Reg Guide 3 8, Revision 1, "Preparation of Environ Repts for U Mills "
- \* Office of Standards Development 78/09/30 60pp
- 7907110273 Reg Guide 3 9, "Concrete Radiation Shields "
- \* Office of Standards Development 73/06/30 2pp
- 7907110280 Reg Guide 3 10, "Liquid Waste Treatment Sys Design Guide for Pu Processing & Fuel Fabrication Plants "
- \* Office of Standards Development 73/06/30 3pp
- 7907110282 Reg Guide 3 11, Revision 2, "Design Const & Insp of Embankment Retention Sys for U Mills "
- \* Office of Standards Development 77/12/31 9pp
- 7907110287 Reg Guide 3 2, "General Design Guide for Ventilation Sys of Pu Processing & Fuel Fabrication Plants "
- \* Office of Standards Development 73/08/31 6pp
- 7907110405 Reg Guide 1 123, Revision 1, "QA Requirements for Control of Procurement Items & Svcs for Nuclear Power Plants "
- \* Office of Standards Development 77/07/31 3pp
- 7907110500 Notice of issuance & availability of Reg Guide 1 B4, Revision 15, "Design & Fabrication Code Case Acceptability, ASME Section III Div 1, " & Reg Guide 1 B5, Revision 15, "Matls Code Case Acceptability, ASME Section III Div 1 " MINOQUE, R B Office of Standards Development 7596-01 79/05/30 2pp
- 7907110500 Notice of issuance & availability of Reg Guide 1 B4, Revision 15, "Design & Fabrication Code Case Acceptability, ASME Section III Div 1, " & Reg Guide 1 B5, Revision 15, "Matls Code Case Acceptability, ASME Section III Div 1 " MINOQUE, R B Office of Standards Development 7596-01 79/05/30 2pp
- 7907110512 Reg Guide 1 B4, Revision 15, "Design & Fabrication Code Case Acceptability, ASME Section III Div 1 "
- \* Office of Standards Development 79/05/31 10pp
- 7907110591 Reg Guide 1 B5, Revision 15, "Matls Code Case Acceptability -- ASME Section III, Div 1 "
- \* Office of Standards Development 79/05/31 6pp
- 7907110591 Reg Guide 1 B5, Revision 15, "Matls Code Case Acceptability -- ASME Section III, Div 1 "
- \* Office of Standards Development 79/05/31 6pp
- 7907120040 Notice of issuance & availability of draft Reg Guide 1 XXX, "Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination" & associated value/impact statement ARLOTTQ, G A Division of Engineering Standards 7590-01 79/06/04 2pp
- 7907120055 Draft reg guide: "Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination," May 1979 issued "For Comment "
- \* Office of Standards Development 79/05/31 16pp
- 7907120067 Draft value/impact statement associated w/"Ultrasonic Testing of Reactor Vessel Welds during Inservice Examination," May 1979 issued "For Comment." Guide provides interim ultrasonic techniques
- \* Office of Standards Development 79/05/31 17pp
- 7907130027 Comments on proposed Reg Guide 2 & concurs w/various aspects of plan as outlined in Annex A. Suggests that introductory remarks recommend assistance be obtained, if needed, from outside reactor line organization.
- BHMDT, T R Sandia Laboratories 79/05/11 2pp.
- 7907130030 Comments on draft Reg Guide Quality Group D is not safety-related & should be omitted. Suggests clarification of definition of "manually operated" valves.
- MCWHORTER, R J Ohio Edison Co. 79/05/07 2pp.
- 7907130034 Comments on proposed Reg Guide 1 B, Revision 2: Position C 2 should be expanded to include four years of technical experience as equivalent of bachelor degree
- BULLIVAN, T J Consumers Power Co 79/05/08 2pp

- 7907130104 Comments on proposed Reg Guide 4.15, Revision 1 Position C 4 re Record retention requirements should be modified  
SULLIVAN, T. J. Consumers Power Co 79/05/01 1p
- 7907130109 Comments on proposed Reg Guide 5 XXX draft paragraph concerning applicability of guide to NRC licensees & applicants should be revised to reflect exemptions listed in 10CFR73 &  
CHARTER, R. J. Ohio Edison Co 79/05/02 1p
- 7907130116 Comments on proposed Reg Guide 1.144 believes audit should be based on results of evaluation of info re supplier performance  
CRANE, P. A. Pacific Gas & Electric Co 79/05/04 2pp
- 7907140129 Comments on proposed Reg Guide 1.8, Revision 2 Position C 8 should be revised to more clearly define which licensed operations come under jurisdiction of Reg Guide  
DALTROFF, S. L. Philadelphia Electric Co 79/05/02 4pp
- 7907140224 Comments on proposed revision to Reg Guide 8.8 NRC should place greater emphasis on American Board of Health Physics certification Draft revisions should be further revised along lines that would support & endorse certification  
KATHREN, R. L. Affiliation Unknown 79/04/26 2pp
- 7907170236 "For Comment" issue of proposed Revision 1 to Reg Guide 5.7, "Entry/Exit Control to Protected Areas, Vital Areas & Matl Access Areas"  
\* Office of Standards Development 79/05/31 16pp
- 7907170238 "For Comment" issue of proposed Revision 1 to Reg Guide 5.14, "Use of Observation (Visual Surveillance) Techniques in Matl Access Areas"  
\* Office of Standards Development 79/05/31 13pp
- 7907190603 Comments on proposed Reg Guide 4.15 requirements for qualifications of auditors already described in other reg guides Recommends deletion of "qualified in radiochemistry & monitoring techniques" from Section C.9  
UHRIG, R. E. Florida Power & Light Co 79/05/22 1p
- 7907190729 Comments on proposed Reg Guide 3.11.1 suggests daily examination & recording of pond water elevations unnecessary in new mill tailing ponds Need for quarterly surveying of embankment slopes questionable  
POWERS, K. H. The Southern Co 79/05/30 1p
- 7907190780 Comments on proposed Reg Guide 10.8 objects to area survey procedures Thin window survey meter not necessary to detect low level radiation Sensitivity requirement for area wipe tests too low to be practical  
LUCAS, A. M. Riverview Hosp WI 79/05/22 1p
- 7907190818 Ack receipt of 790504 ltr describing wind measuring sys  
HINQUE, R. B. Office of Standards Development 79/06/07 1p
- 7907190852 Requests that wind measuring sys should be considered for use as early warning sys  
KEEL, W. S. Approach Fish, Inc 79/05/04 6pp
- 7907240311 Discusses rebar coupler sys re bid rejection Future nuclear plant const applications will ref mechanical rebar coupler sys that are acceptable to util, appear to have economic merit & that have ACI/ASME Code approval  
RING, L. E. Tennessee Valley Authority 79/05/24 1p.
- 7907240368 Notifies that staff is reviewing correspondence re rebar coupler sys in response to 790322 ltr  
RING, L. E. Tennessee Valley Authority 79/04/27 1p
- 7907240372 Discusses rejection of 770308 bid, Ref Number 72-822237 Since util is federal agency, procurement must be open for competitive bids Forwards response of HR Denton W/o encl  
FOX, C. J. Fox Industries 79/03/22 2pp
- 7907240377 Notifies of review of rejected bid re Invitation for Bids 73-824811, Use of coupler which is not approved by NRC will result in significant expenditures to revise PSAR.  
RING, L. E. Tennessee Valley Authority 79/03/07 1p.
- 7907240381 Ack receipt of 790130 ltr re award of Contract 79K73-824811 to Ericc Products Investigation being made of allegations  
RING, D. E. Tennessee Valley Authority, 79/02/21, 1p
- 7907240384 Discusses Invitation for Bids 73-824811, indefinite quantity term contract for rebar splicing matl for nuclear plant Reg Guides state that methods & solutions different from those specified in guide are acceptable under certain conditions  
FOX, C. J. Fox Industries 79/01/30 2pp
- 7907240388 Discusses loss of contract bid re rebar splicing matl Qualified suppliers should not be precluded from bidding on govt work Forwards ltr to L Seiber, General Manager of TVA W/o encl  
FOX, D. J. Fox Industries 79/02/02 1p
- 7907240395 Forwards ltr from Dechtel Power Corp & TVA in support of Fox Industries Topical Rept, "Taper Threaded Reinforcing Steel Coupler"  
FOX, C. J. Fox Industries 78/04/28 4pp
- 7907240406 Accepts for review Fox Industries topical rept "Taper Threaded Reinforcing Steel Coupler" Review will not begin until June 1978 due to higher priority work  
KNIEL, K. Light Water Reactors Branch 2 78/03/22, 1p
- 7907240412 Forwards sketch of device for situations requiring major adjustments re couplers in response to 780221 telcon  
FOX, C. J. Fox Industries 78/02/22 3pp
- 7907240419 Notifies that topical rept is unacceptable Two commitments are required from nuclear plant applicants re ref of product in applications Forwards NUREG-0370, "Topical Rept Review Status" W/o encl  
KNIEL, K. Light Water Reactors Branch 2 77/12/08 1p
- 7907240426 Notifies of 770826 submittal of topical rept "Taper Threaded Reinforcing Steel Coupler" Expresses interest in expediting review process  
FOX, C. J. Fox Industries 77/11/18 1p
- 7907250129 Comments on proposed Reg Guide 1.XXX seat leakage limits should not be specified for BWR safety relief valves  
SHERWOOD, G. G. General Electric Co, Nuclear Energy Products Div MFN 127-79 79/05/09 2pp
- 7907250134 Comments on proposed Reg Guide 1.XXX would impose unnecessarily stringent impact on industry, which could be avoided by endorsement of ANBI consolidation document  
ANDERSON, T. M. Westinghouse Electric Corp N5-TMA-2074 79/05/23 4pp
- 7907250141 Comments on proposed Reg Guide 1.75, Revision 2 departure from current practice & existing NRC position on fire protection is unjustified  
SHERWOOD, G. G. General Electric Co, Nuclear Energy Products Div MFN 127-79 79/05/01 2pp
- 7907250419 Comments on draft reg guide, "Functional Specs for Safety-Related Valve Assemblies in Nuclear Power Plants" terminology needs clarification & seismic response spectra is unnecessary  
BURSTEIN, S. Wisconsin Electric Power Co 79/05/07 3pp
- 7907260249 Comments on proposed Reg Guide 1.8, Revision 2 supports proposed revision Criticizes specifying where radiation protection manager should be located as unnecessarily limiting Forwards info re continuing certification program  
TERPILAK, M. S. American Board of Health Physics 79/03/23 206pp
- 7907260382 "Prompt Neutron & Gamma Doses from Accidental Criticality" Ref for Reg Guides 3.34, Revision 1 & 3.35, Revision 1  
HILLIS, C. A. U S Embassies 79/07/26 9pp
- 7907260382 "Prompt Neutron & Gamma Doses from Accidental Criticality" Ref for Reg Guides 3.34, Revision 1 & 3.35, Revision 1  
HILLIS, C. A. U S Embassies 79/07/26 9pp
- 7907270090 Comments on proposed Reg Guide 1.35.1 suggests clarification of computation values Notes typographical error  
RUSSELL, H. O. Portland Cement Association 79/05/22 1p
- 7907270124 Comments on proposed Reg Guide 1.8, Revision 2 requirement of onsite health physicist could cause hardship to util not employing one at each plant Recommends incorporation of transition period in implementation section.  
COPELAND, R. L. Energy, Dept of, Clinch River Breeder Reactor Plant 79/04/23 1p
- 7907300014 Comments on proposed Reg Guide 1.134, Revision 1. Recommends mod of wording to ensure confidentiality of medical info Requests definition of professional personnel for evaluation of potentially disqualifying medical conditions  
SULLIVAN, T. J. Consumers Power Co C 79/05/23 1p

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

7907030243 "Study of Plutonium Oxide Leak Rates from Shipping Containers," quarterly progress rept for Jan-Mar 1979  
MADIA, H. J., MISHIMA, J., SUTTER, S. L. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2093 PNL-2240-10 79/05/30 40pp

7907050520 "Creare Downcomer Effects Program," monthly progress rept, Apr 1979  
BLOCK, J. A. Creare, Inc NRC-04-75-162 79/05/07 3pp

7907060245 "Water Reactor Safety Research, Heat Transfer Highlights," Feb 1979  
LOTTE, P. A. Argonne National Laboratory 79/02/28 19pp

7907060446 "Safeguards Analysis for Byproduct Matls & Small Quantities of SNM," progress rept for Apr 1979  
FESTER, R. D. Oak Ridge National Laboratory 79/05/09 7pp

7907060455 "Evaluation of Docket Files for Terminated Licenses," progress rept for Apr 1979  
ROHMER, P. S. Oak Ridge National Laboratory 79/05/16 6pp

7907090137 "Code Assessment & Applications Program, Comparison of RELAP4/MCDB to THTF Test 177"  
DAVIS, C. B. EG & G, Inc FIN A-6047 CAAP-TR-049 79/05/31 47pp

7907090429 "Environ Statements Project," monthly progress rept for Mar 1979  
ZITTEL, H. E. Oak Ridge National Laboratory FIN B-0001 79/03/31 6pp.

7907090443 "L2-3 Pre-LOCA Maneuver Core Safety Analysis"  
ATKINSON, B. A., BATTERWHITE, D. EG & G, Inc 79/04/30 150pp

790710064 "Forecasting Electricity Demand by States in US on Annual Basis," monthly progress rept for Apr 1979  
CHERN, W. B. Oak Ridge National Laboratory FIN B-0190 ORNL/ED/EAS-79/ 79/05/09 5pp

790710113 "Loft Design Thermal Transient Rake Pin Stress Analysis"  
MOSEBY, W. R. EG & G, Inc FIN A-6048 RE-A-78-211 79/01/31 15pp

790710149 "Stress Analysis of Ultrasonic Density Detector for LOFT Core Inlet Steady State & LOCA Conditions," Suppl 1  
MOSEBY, W. R. EG & G, Inc RE-A-78-135 79/04/30 20pp.

790710316 "Water Reactor Research Directorate (WRRD) Monthly Rept" for April 1979  
YBARRONDO, L. J. EG & G, Inc FIN A-6038 79/06/11 120pp

790710483 "Pressure & Void Distributions in Converging-Diverging Nozzle W/Nonequilibrium Water Vapor Generation," informal rept  
JONES, D. C., ZIMMER, G. A., WU, B. J. C. Brookhaven National Laboratory FIN A-3045 BNL-NUREG-26003 79/04/30 219pp

7907120036 "Physical Protection of Nuclear Facilities," progress rept for Mar 1979  
CHAPMAN, L. D. Sandia Laboratories FIN A-1060 79/04/23 11pp

7907120062 "Research in Field of Eddy-Current Testing in German Labs," trip rept  
ODDB, C. V. Oak Ridge National Laboratory FIN B-0417 ORNL/FTR-601 79/05/25 13pp

7907120070 "Rept of Foreign Travel of Staff Engineers for Advanced Instrumentation for Studies (AIRB) Program"  
HARDY, J. E., LEAVELL, W. H., PAULUS, T. J. Oak Ridge National Laboratory FIN B-0413 79/05/16 7pp

7907120076 "FLECHT-SEASET Program," informal monthly progress rept, Apr 1979  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 79/04/30 12pp

7907120082 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Apr 1979  
ZITTEL, H. E. Oak Ridge National Laboratory FIN B-0279 79/04/30 6pp.

7907120097 "Matl Control at Licensed Processing Facilities," informal progress rept for Feb 1979  
O'BRIEN, J. H. Lawrence Livermore Laboratory FIN A-0115 79/04/24 4pp.

7907120103 "FLECHT-SEASET Program," informal monthly progress rept for Aug 1978  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 78/09/26 8pp

7907120107 "FLECHT-SEASET Program," informal monthly progress rept for Sept 1978  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 78/10/26 28pp

7907120109 "FLECHT-SEASET Program," informal monthly progress rept for Feb 1979  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 79/06/26 10pp

7907120115 "FLECHT-SEASET Program," informal monthly progress rept for Mar 1979  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 79/05/10 12pp

7907120123 "FLECHT-SEASET Program," informal monthly progress rept for Jan 1979  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 79/03/08 8pp

7907120126 "FLECHT-SEASET Program," informal monthly progress rept for Dec 1978  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 79/01/31 30pp

7907120131 "FLECHT-SEASET Program," Informal monthly progress rept for Oct 1978  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 78/11/17 8pp

7907120138 "FLECHT-SEASET Program," informal monthly progress rept for Nov 1978  
MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 78/12/14 13pp

7907120146 "Matl Control at Licensed Processing Facilities," progress rept for Mar 1979  
O'BRIEN, J. H. Lawrence Livermore Laboratory MC 79-272 79/05/18 5pp

7907120165 Research Info Ltr SS CONCEPT computer code & capital costs for high & low sulfur coal plants at 1,200 MW Forwards  
NUREG-0243, "Capital Cost High & Low Sulfur Coal Plants - 1200 MW," Vols 1-3  
LEVINE, S. Office of Nuclear Regulatory Research 79/05/29 8pp

--7907120171 "Capital Cost High & Low Sulfur Coal Plants - 1,200 MW," Vols 1-3  
\* United Engineers & Constructors, Inc (subs of Raytheon Co)  
AT(49-24)-0351 70D-2477-7 79/05/29 450pp Available at NTIS

7907190637 "Aerosol Measurements & Modeling for Fast Reactor Safety," monthly progress rept for May 1979  
SIEBEKE, J. A. Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293-07 79/06/21 3pp

7907190675 "Forecasting Electricity Demand by States in US on Annual Basis," progress rept for May 1979  
CHERN, W. B. Oak Ridge National Laboratory FIN B-0190-8 ORNL/ED/EAS-79/ 79/06/06 5pp

7907190691 "Source Term Measurements at PWRs," progress rept for May 1979  
MANDLER, J. W. EG & G, Inc FIN A-6075 79/06/13 4pp

7907300282 "Assessment of Radiation Doses Resulting from Releases of Rn-222 & Radium-226 from U Mining & Milling Activities," interim rept, Apr 1975  
TRAVIS, C. C., MCCOWELL-BOYER, WATSON, A. P. Oak Ridge National Laboratory FIN B-0281 ORNL/HASRD-38 79/05/20 4pp.

7907300306 "Rept of Foreign Travel of MB Herskovitz, I&C Development Engineer & HR Payne, Design Engineer, Advanced Instrumentation for Reflood Studies (AIRB) Program," interim rept  
HERBSKOVITZ, M. B., PAYNE, H. R. Oak Ridge National Laboratory FIN B-0413 ORNL/ENR/FTR-60 79/05/30 12pp

7907300368 "Environ Statements Project," interim rept, Apr 1979  
ZITTEL, H. E. Oak Ridge National Laboratory FIN B-0001 ORNL/ED/EIS-92 79/04/30 8pp

7907300381 "Crack Arrest Technology," monthly progress rept  
ROSENFIELD, A. R. Battelle Memorial Institute, Columbus Laboratories AT(49-24)-0293 79/04/04 5pp

## NONDOCKETED ITEMS

7907300421 "Safeguards Analysis for Byproduct Matl & Small Quantities of SNM," monthly progress rept May 1979  
CHESTER, R O , KIRKSCEY, K A , RANDOLPH, M L Oak Ridge National Laboratory FIN B-6108 ORNL/HASRD-40 79/06/19 7pp

7907300436 7904300436  
"Aerosol Measurements & Modeling for Fast Reactor Safety," monthly progress rept, Apr 1979  
GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293-07 79/06/12 3pp

7907300448 "Fission Product Transport Analysis," monthly progress rept, Mar 1979  
GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293-02 79/06/11 3pp

7907300458 "Aerosol Measurements & Modeling for Fast Reactor Safety," monthly progress rept, Mar 1979  
GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293-07 79/06/11 3pp

7907300467 "Fission Product Transport Analysis," interim rept, Apr 1979  
GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293-02 79/06/12 3pp

7907300489 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels," interim rept, May 1979  
HUTTON, P H , SCHWENK, E B , KURTZ, R J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2088 79/06/15 8pp

7907300507 "Evaluation of Docket Files of Terminated Licenses," interim rept, May 1979  
HOLWAY, C F , LANTZ, P M , DICKSON, H W Oak Ridge National Laboratory FIN A-9085-7 ORNL/HASRD-39 79/05/31 App.

7907300527 "Accident-Induced Flow & Matl Transport in Nuclear Facilities," interim rept, May 1979  
OREGORY, W S , MARTIN, R A Los Alamos Scientific Laboratory FIN A-7029 79/06/27 3pp

7907300541 "Rept of Foreign Travel of JD Hylton, I&C Div, for Advanced Instrumentation for Reflood Studies (AIRS) Program," interim rept  
HYLTON, J D Oak Ridge National Laboratory FIN B-0413 ORNL/FTR-633 79/06/28 3pp

7907300554 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels," interim rept, June 1979  
HUTTON, P H , SCHWENK, E B , KURTZ, R J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2088 79/07/19 3pp

7907300585 "LWR Thermal Hydraulic Development Program," interim rept, June 1979  
JONES, D C Brookhaven National Laboratory FIN A-3045 79/07/18 6pp

7907310109 "Thermal Hydraulic LMFR Safety Experiments," interim rept, June 1979  
JONES, D C Brookhaven National Laboratory FIN A-3024 79/06/30 4pp

7907310133 "Advanced Reactor Safety Analysis, Technical Assistance, Reactor Projects," interim rept, June 1979  
BARI, R A Brookhaven National Laboratory FIN A-3000 79/07/05 5pp

7907310149 "Stds Steering Committee Code Development & Validation," interim rept, June 1979  
AGRAWAL, A K , CUPPY, J Q Brookhaven National Laboratory FIN A-3015-8 79/07/17 7pp

7907310208 "Fission Product Transport Analysis," interim rept, June 1979  
GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293-02 79/07/23 3pp

7907310219 "Aerosol Measurements & Modeling for Fast Reactor Safety," interim rept, June 1979  
GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories, NRC-04-76-293-07 79/07/20 3pp

907310303 "BWR Blowdown/ECC," interim rept, June 1979  
BURNETTE, Q W - General Electric Co., Nuclear Energy Products Div. NRC-04-76-215 79/06/30 15pp

7907310320 "LWR Source Term Measurements Program," interim rept, June 1979  
HANDLER, J W EQ & G, Inc FIN A-6075 79/07/11 4pp

7907310555 PNL-SA-7618  
"Criticality Experiments w/Subcritical Clusters of Low Enriched U Oxide Rods in Water w/U of Lead Reflecting Walls"  
BIERMAN, S R , DURST, B M , CLAYTON, E D Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/31 25pp

7907310591 "Dynamic Photoelastic Study of Crack Arrest," progress rept for Apr 1979  
DALLY, J W Maryland, Univ of NRC-04-76-172 79/05/02 5pp

7907310620 PNL-2898  
"Environ Radon & Radon Daughter Dosimetry in Respiratory Tract"  
MCIPHERSON, R B Battelle Memorial Institute, Pacific Northwest Laboratory FIN A-2136 79/04/30 24pp

#### REVIEW GRP NRC RESEARCH REVIEW GROUPS

7905240950 Lists four types of LOFT documents currently filed in FDA Project number will be listed on cover of all LOFT documents for easy identification  
MCIPHERSON, G D Division of Reactor Safety Research 79/05/02 1p

7906220227 Notification of 790625 meeting in Idaho Falls, ID to review Zircaloy cladding program  
FICKLESIMER, M L Fuel Behavior Branch 79/05/15 3pp

7907050335 Forwards info promised in 790419 notice re next review group meeting info pertains to small break model & backup handouts  
MCIPHERSON, G D Division of Reactor Safety Research 79/05/24 1p

--7907050359 "Loft Small Break RELAP-4 Model" & related vignettes  
\* EQ & G, Inc 881952481 79/05/02 117pp

7907090271 Forwards summary of Qualification Testing Research Review Group meeting on 790516 to discuss NRC connector tests  
FEIT, R Division of Reactor Safety Research 79/05/30 1p

--7907090272 Summary of 790516 Qualification Testing Research Review Group meeting in Bethesda, MD to discuss final Sandia test plan for NRC directed connector test & LOCA test facility performance  
FEIT, R Division of Reactor Safety Research 79/05/30 3pp

7907090273 Notifies of time change to 12 PM for 790531 meeting re LOFT L2-3 presentation  
NDRIAN, P Analysis Branch 79/05/30 1p

7907100371 Requests NRC assistance in answering hypothetical situations in encl seismic evaluations info will be used to develop manual of general practices & earthquake motions  
KRINITZKY, E L Army, Dept of, Corps of Engineers 79/06/28 1p

7907190033 Forwards minutes of 790608 meeting of Surveillance & Noise Diagnostics Review Group  
FARMER, W S Division of Reactor Safety Research 79/06/19 2pp

--7907190035 Summary of Surveillance & Noise Diagnostics Review Group 790608 meeting re recent accomplishments at ORNL for NRC-funded programs  
\* Division of Operating Reactors 79/06/08 100pp

7907300080 Summary of 790606 meeting in Bethesda, MD of Qualification Testing Evaluation Research Review Group re Sandia LOCA test facility performance  
FEIT, R Research Support Branch 79/06/13 7pp

#### SECY POSITION PAPERS BEFORE THE COMMISSION

7907030173 Seeks approval of plan to formalize interim organizational structure to deal w/impacts of TMI incident, using resources & priorities within office. Forwards task description, chart of organization structure & casework impacts  
DENTON, H R Office of Nuclear Reactor Regulation 79/05/19 33pp

- 7907090038 SECY-78-163  
Analyzes issues of NRDC petition for rulemaking PRM-20-7  
Recommends response & requests approval of proposed FR  
notice re Commission response  
SMITH, C V Office of Nuclear Material Safety & Safeguards  
78/11/24 6pp
- 7907090043 Expresses concern re radioactive wastes & low level waste  
disposal Requests NRC preparation of EIS re NRC low level  
waste disposal program & all reasonable alternatives  
COTTON, R. LASH, R Natural Resources Defense Council 76/08/06  
2pp
- 7907090049 Petition to adopt interim regulations governing disposal of  
low level radioactive waste  
COTTON, R Natural Resources Defense Council 78/08/06 95pp
- 7907090053 Outline of comments received on NRDC petition for rulemaking  
PRM-20-7 re low level wastes Overall response was opposed to  
petition  
\* Commission 79/05/03 16pp
- 7907090058 Draft notice of denial re petition for rulemaking PRM-20-7  
CHILK, S J Office of the Secretary of the Commission 79/05/30  
25pp
- 7907090063 Draft ltr forwarding notice of denial re 760806 petition for  
rulemaking PRM-20-7  
CHILK, S J Office of the Secretary of the Commission 78/11/24  
2pp
- 7907090068 Draft ltr forwarding notice of denial re petition for  
rulemaking PRM-20-7  
HART, O Senate, Environment & Public Works DINGELL, J D House  
of Rep, Interstate & Foreign Commerce UDALL, M K House of Rep,  
Interior & Insular Affairs 78/11/24 3pp
- 7907090080 SECY-78-613A  
Revises SECY-78-613 to incorporate comments by Dfc of Policy  
Evaluation & Ofc of General Counsel Revised draft FR notice  
of denial re NRDC petition for rulemaking PRM-20-7 encl  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards  
79/01/02 2pp
- 7907090084 Draft FR notice of denial of NRDC petition for rulemaking  
PRM-20-7  
CHILK, S J Office of the Secretary of the Commission 79/01/02  
28pp
- 7907090091 SECY-78-613B  
Forwards revisions to SECY-78-613 & 613A re response to NRDC  
petition for rulemaking PRM-20-7 Responses by NMSS to  
comments by Commissioners Kennedy & Ahearns encl  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards  
79/02/16 4pp
- 7907090097 Draft FR notice of denial of petition for rulemaking  
PRM-20-7,  
CHILK, S J Office of the Secretary of the Commission 79/02/16  
31pp
- 7907090103 Draft ltr forwarding FR notice re denial of petition for  
rulemaking PRM-20-7  
CHILK, S J Office of the Secretary of the Commission 79/02/16  
2pp
- 7907090106 Draft ltr forwarding FR notice of denial of petition for  
rulemaking PRM-20-7  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards  
79/02/16 3pp
- 7907090138 SECY-78-690  
Requests approval of proposed ltr to KMC, Inc denying  
petition to reconsider issuance of security personnel  
qualification training & equipment requirements Approval of  
draft FR notice of denial of petition for rulemaking sought  
MINGOUE, R B Office of Standards Development 78/12/27, 6pp
- 7907090157 Memo in support of petition for reconsideration of proposed  
implementation of security personnel qualification training  
& equipment requirements.  
KNUTH, D F KMC, Inc. 78/10/23 14pp
- 7907090164 Draft ltr forwarding FR notice of denial re petition to  
reconsider issuance of security personnel qualification  
training & equipment requirements  
CHILK, S J Office of the Secretary of the Commission 78/12/27  
7pp.
- 7907090169 Draft FR notice of denial of KMC, Inc petition for  
rulemaking  
CHILK, S J Office of the Secretary of the Commission 78/12/27  
8pp
- 7907090174 SECY-78-690A  
Forwards mods to SECY-78-690, Encl B & C, per 790130 request  
GOSBICK, L V Office of the Executive Director for Operations  
79/03/19 1p
- 7907090181 Returns SECY-78-690 for mods following NRC review  
Response to KMC, Inc petition should be expanded to more  
completely respond to contention that NUREG guidance  
documents re-establish deleted training requirements  
CHILK, S J Office of the Secretary of the Commission 79/01/30  
2pp
- 7907090186 Draft ltr forwarding FR notice re denial of petition for  
rulemaking submitted by KMC, Inc  
HENDRIE, J M Commission 79/03/19 8pp
- 7907090189 Draft FR notice re denial of petition for rulemaking  
submitted by KMC, Inc  
CHILK, S J Office of the Secretary of the Commission 79/03/19  
8pp.
- 7907120273 Notices of approval of BWR LOCA-ECCS cooperative research  
program w/EPRI & GE Forwards dissenting opinion of  
Commissioner Gilinsky  
CHILK, S J Office of the Secretary of the Commission 79/05/09  
20pp
- 7907120278 SECY-79-215  
Requests NRC approval for joint NRC/EPRI/GE program on BWP  
LOCA/ECCS research to study countercurrent flow-limiting  
phenomena & funding for research effort Forwards breakdown  
of past & future costs  
LEVINE, S Office of Nuclear Regulatory Research 79/03/26 7pp
- 7907120289 Forwards organization of conflict of interest waiver &  
Findings & Determination prepared by Division of Contracts  
Waiver is necessary in awarding contract to GE Concur  
w/conclusions in Findings & Determination  
LEVINE, S Office of Nuclear Regulatory Research 79/05/09 7pp
- 7907120422 SECY-79-278A  
Provides NRC w/supplemental info re SECY-79-278 Discusses  
two methods of implementing requirements by order modifying  
license or by rulemaking process  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards  
79/05/07 3pp
- 7907120439 Informs of philosophical agreement w/rept on physical  
protection of irradiated fuel shipments Subject was  
addressed w/o consideration of other radioactive matl  
shipments  
DAVIS, J O Office of Inspection & Enforcement, 79/05/03 1p
- 7907120452 Discusses proposed rule on safeguarding spent fuel  
shipments Offers no objection to interim rept from Sandia  
Lab; will wait until final rept Shipments through areas of  
high population density should be kept at min  
MILLER, J R. Assistant Director for Site & Safeguards 79/04/27  
1p
- 7907120466 SECY-79-27B  
Seeks NRC approval of proposed amends to 10CFR73 requiring  
physical protection of irradiated fuel shipments Forwards  
draft of FR notice  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards  
79/04/18 45pp
- 7907120466 SECY-79-27B  
Seeks NRC approval of proposed amends to 10CFR73 requiring  
physical protection of irradiated fuel shipments Forwards  
draft of FR notice  
DIRCKS, W J Office of Nuclear Material Safety & Safeguards  
79/04/18 45pp
- 7907130427 SECY-79-100  
Recommends NRC approve Westinghouse license to export  
various components to Philippines  
SHEA, J R Office of International Programs, 79/05/08, 9pp
- 7907130441 Executive Branch position re Westinghouse application for  
license to export various components to Philippines.  
License should be issued  
NOSENZO, L V State, Dept. of 78/11/03 9pp.

## NONDOCKETED ITEMS

- 7907180707 FOIA request for L Bickwit 790327 memo to NRC which led to SECY-A-79-42 re order concerning Nuclear Engineering Co. Inc disposal site at Sheffield, IL Request includes 790101-0507 documents which relate to order to show cause CONNER, T B Conner, Moore & Corber 79/06/07 2pp
- 7907180730 Notifies that NRC approved notice of hearing & memo & order during 790605 Affirmation Session 79-16 re SECY-A-79-42, Nuclear Engineering Co. Inc disposal site at Sheffield, IL CHILK, S J Office of the Secretary of the Commission 79/06/07 1p
- 7907180733 Concurs in SECY-A-79-42 paper re Nuclear Engineering Co show cause order for License 13-10042-01 KENNEDY, R T Commission 79/05/18 1p
- 7907180742 Consent calendar item response note re SECY-A-79-42 Approved as modified Requests response and/or comments on Ofc of General Counsel/Ofc of Policy Evaluation memo, if issued BRADFORD, P A Commission 79/05/18 1p
- 7907180750 Requests addl info re SECY-A-79-42 show cause order Withdraws previous concurrence KENNEDY, R T Commission 79/05/11 1p
- 7907180757 Consent calendar item response note re SECY-A-79-42 Approved as modified AHEARN, J F Commission 79/05/10 2pp
- 7907180852 Forwards SECY-79-72A re Executive Director response on pending application to export highly enriched U to Japan MCQUEGON, E W Office of the Executive Director for Operations 79/06/12 1p
- 7907180860 SECY-79-72A Forwards Executive Branch position re GE application to export 161 kg U-235, contained in 5,875 kg U enriched to max of 3 1/2, to Japan Requests Commissioner input SHEA, J R Assistant Director for Export/Import & International Safeguards 79/06/05 1p
- 7907180869 Executive Branch position re GE application for license to export 161 kg U-235, contained in 5,875 kg U enriched to max of 3 1/2, to Japan Ltr of assurance encl License should be granted NOSENZO, L V State, Dept of 79/05/29 3pp
- 7907190009 SECY-78-655A Forwards Executive Branch position re pending application for Mitsui & Co. Inc license to export highly enriched U to Japan SHEA, J R Office of International Programs 79/05/29 1p
- 7907190012 Executive Branch position re Mitsui & Co. Inc application for license to export 3,511 kg U-235 to Japan License should be granted End use statement encl NOSENZO, L V State, Dept of 79/05/23 2pp
- 7907230188 SECY-79-368 Notification of receipt of Transnuclear, Inc application to export 22,089 g U enriched to 3.35% max, & 126,000 kg depleted U, enriched to 0.3% max U-235, to France SHEA, J R Office of International Programs 79/06/04 2pp
- 7907230196 Application by Transnuclear, Inc to export depleted U, in form of U metal as derbies at 0.3% U-235, & depleted U in form of depleted U hexafluoride as heels, at max of 0.3% U-235, to France End use statement encl Transnuclear, Inc 79/05/03 2pp
- 7907240393 SECY-78-616A Forwards for Commissioner action revised draft annual rept section re unresolved safety issues DENTON, H R Office of Nuclear Reactor Regulation 78/12/28 45pp
- 7907240404 SECY-78-616 Forwards for Commissioner action draft section of NRC annual rept re progress of resolution of unresolved safety issues DENTON, H R Office of Nuclear Reactor Regulation 78/11/27 200pp
- 7907240416 SECY-78-110 Forwards protocol of visit to US by USSR LWR safety delegation SHEA, J R Office of International Programs 78/05/09 9pp.
- 7907240421 SECY-79-300 Info rept for Commissioners summarizing issues re seismic & geologic siting regulation, policy & practice for nuclear power plants Background info re geoscience, engineering design, policy & technical issues encl MINOQUE, R B Office of Standards Development 79/04/27 92pp
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 7906240134 Discusses evaluation of topical rept G&W-JUN-25311, "Nuclear Main Steam Isolation Valve Sys" Satisfies Criteria 1-3, stipulated in NUREG-0390 VASSALLO, D B Assistant Director for Light Water Reactors 79/05/15 2pp
- 7907030357 Forwards Revision B to QA Program CE-1-A JANECEK, R F Commonwealth Edison Co 79/06/21 1p
- 7907260584 Revision B to QA program \* Commonwealth Edison Co 79/06/21 34pp
- 7907030448 Forwards Mark I containment activity review, May 1979 BOBON, L J General Electric Co, Nuclear Energy Products Div MFN-172-79 79/06/26 3pp
- 7907030480 Forwards "Solid Radwaste Sys," Mar 1979 DEGRDOT, B Stock Equipment Co 79/04/09 1p
- 7907030482 SRS-001-NP "Solid Radwaste Sys," Mar 1979 \* Stock Equipment Co 79/03/31 187pp
- 7907060249 Forwards Revision 1 to BAW-10139, "LOCA Mass & Energy Release for Containment Design," which corrects typographical errors in equations for complete mixing model TAYLOR, J H Babcock & Wilcox Co 79/04/23 1p
- 7907060252 "LOCA Mass & Energy Release for Containment Design," Revision 1 SMITH, K C, DUNN, B M Babcock & Wilcox Co 79/04/23 4pp
- 7907060279 Advises that WESTBYN computer code analysis of benchmark problems will be completed by 790731 ANDERSON, T M Westinghouse Electric Corp NB-TMA-2105 79/06/26 1p
- 7907060287 Forwards response to NRC request for addl info re control blade life (B4C loss) ORTLEVEY, R L General Electric Co, Nuclear Energy Products Div MFN-178-79 79/06/29 3pp
- 7907060324 Forwards results of comparisons to two-loop test apparatus peak cladding temps w/GE licensing evaluation model Model conservatively predicts average power test by approx 1,000 F. SHERWOOD, G O General Electric Co, Nuclear Energy Products, Div MFN-177-79, 79/06/29 4pp
- 7907100574 Forwards "Guide Thimble Tube Wear in Westinghouse Fuel Assemblies," May 1979 Rept withheld (ref 10CFR2.790) ANDERSON, T M Westinghouse Electric Corp NB-TMA-2102 79/06/27 1p
- 7907100580 Discusses storing of proprietary info in shared computer sys If heat number & batch number entries of Table 1 are eliminated, propriety will be protected. TAYLOR, J H Babcock & Wilcox Co 79/07/03 1p.
- 7907110429 Requests NRC assistance in reviewing B&W request for tax exempt status for VA installations which remove pollutants from water Question exists as to whether pollution abatement is primary purpose of facility. BELL, J R Virginia, State of 2-35 79/07/03 4pp
- 7907110451 Forwards XN-NF-78-30(A) & XN-NF-78-30, Amend 1(A), "Exxon Nuclear Co WREM-Based Generic PWR ECCB Evaluation Model Update ENC WREM-ITA, Responses to NRC Request for Addl Info," May 1979. GUSLEY, G F Exxon Nuclear Co, Inc. (subs. of Exxon Corp) 79/05/23 1p
- 7907110459 XN-NF-78-30(A)A01 "Exxon Nuclear Co WREM-Based Generic PWR ECCB Evaluation Model Update Exxon Nuclear Co WREM-ITA, Responses to NRC Request for Addl Info," Amend 1(A) to rept. JENSEN, S E, JENSEN, R T, GALLBRAITH, K F, Exxon Nuclear Co., Inc. (subs of Exxon Corp) 79/05/17 46pp.



7907110454 Forwards responses to concerns raised at 790312 meeting w/NRC re procedure for calculating min critical power ratio & summarizing data base for critical heat flux correlation Response withheld (ref 10CFR2 790)  
WHITE, J A Exxon Nuclear Co, Inc (subs of Exxon Corp)  
79/07/05 App

7907180983 Forwards "Application of Leibnitz Rule in GE LOCA Evaluation LOCA Evaluation Model." final rept  
BUCHHOLZ, R H General Electric Co, Nuclear Energy Products Div  
MFN-183-79 79/07/13 2pp

- 7907180586 "Application of Leibnitz Rule in GE LOCA Evaluation Model." final rept  
\* General Electric Co, Nuclear Energy Products Div 79/07/13 5pp

7907180912 Requests addl info in order to complete review of CENPD-177-P, "CEDNBR - Computer Code for Transient Thermal Margin Analysis of Reactor Core"  
BAER, R L Light Water Reactors Branch 2 79/06/08 3pp

7907180916 Requests addl info re small break LOCA analysis  
ROSS, D F Division of Project Management 79/06/04 9pp

7907190342 Forwards Revision 9 to Comm Ed GA program topical rept CE-1-A Revisions reflect implementation of organizational changes at remaining operating nuclear stations  
JANECEK, R F Commonwealth Edison Co. 79/07/16 1p

--7907190357 Revision 9 to Comm Ed GA program topical rept CE-1-A  
\* Commonwealth Edison Co 79/07/16 31pp

7907200194 Forwards Amend 1 to NEDE-24076-P, "Design Rept & Safety Evaluations For High Density Fuel Storage Sys" Requests rept be withheld (ref 10CFR2 790)  
QUIRK, J General Electric Co, Nuclear Energy Products Div MFN 162-79 79/06/08 1p

7907200209 Forwards Amend 2 to NEDE-24057-P, "Assessment of Reactor Internals Vibration in BWR/4 & BWR/5 Plants" Requests rept be withheld (ref 10CFR2 790)  
QUIRK, J General Electric Co, Nuclear Energy Products Div MFN 170-79 79/06/26 1p

7907200288 Forwards BAW-153B, Revision 1: "Assumptions, Methodology & Acceptance Criteria Rept for Asymmetric LOCA Loads Evaluation"  
TAYLOR, J H Babcock & Wilcox Co 79/07/16 1p

--7907200293 BAW-153B REV 1  
"Assumptions, Methodology & Acceptance Criteria Rept For Asymmetric LOCA Loads Evaluation"  
\* Babcock & Wilcox Co 79/04/30 38pp

7907200299 Forwards nonproprietary version of WCAP-9405, "Study of Reactor Vessel Upper Head Region Fluid Temp"  
ANDERSON, T M Westinghouse Electric Corp NS-TMA-2070 79/07/11 1p

--7907200305 WCAP-9405  
"Study of Reactor Vessel Upper Head Region Fluid Temp," nonproprietary version  
\* Westinghouse Electric Corp. 78/12/31 141pp

7907200352 Forwards proprietary version of WCAP-9404, "Study Reactor Vessel Upper Head Region Fluid Temp" Application for withholding & affidavit encl  
ANDERSON, T M Westinghouse Electric Corp NS-TMA-2070 79/07/11 9pp

7907240395 Forwards ltrs from Bechtel Power Corp & TVA in support of Fox Industries Topical Rept, "Taper Threaded Reinforcing Steel Coupler"  
FOX, C J. Fox Industries 78/04/28 App.

--7907240406 Accepts for review Fox Industries topical rept "Taper Threaded Reinforcing Steel Coupler" Review will not begin until June 1978 due to higher priority work  
KNIEL, K. Light Water Reactors Branch 2 78/03/22 1p

--7907240419 Notifies that topical rept is unacceptable Two commitments are required from nuclear plant applicants re ref of product in applications Forwards NUREG-0390, "Topical Rept Review Status." w/o encl  
KNIEL, K. Light Water Reactors Branch 2 77/12/05 1p

--7907240426 Notifies of 770826 submittal of topical rept "Taper Threaded Reinforcing Steel Coupler" Expresses interest in expediting review process  
FOX, C J. Fox Industries 77/11/18 1p

7907240443 Summary of 790524 meeting w/GE re implications of two loop apparatus results on GE ECCS evaluation model Slides presented by GE encl  
HODGEB, W. Analysis Branch 79/06/12 87pp.

7907110502 Notifies of schedule for review of CENPD-177-P, "CEDNBR-A Computer Code for Transient Thermal Margin Analysis of Reactor Core," in response to BL Uaer 790608 request Addl info will be provided during fourth quarter of 1979  
SCHERER, A E C-E Power Systems LD-79-039 79/07/03 1p

7907120039 "Thermal Reactor Safety Code Development, Highlights for Apr 1979"  
\* Brookhaven National Laboratory 79/04/30 9pp

7907120354 Forwards addl info to complete review of first part of NEDE-21888, "Mark I Containment Program Load Definition Rept," in response to NRC 790803 request  
SOBON, L J General Electric Co, Nuclear Energy Products Div MFN-180-79 79/07/06 74pp

7907130239 Forwards Westinghouse rept: "Rept on Small Break Accidents for Westinghouse NSSS Sys" Rept withheld (ref 10CFR2 790)  
ANDERSON, T M Westinghouse Electric Corp NS-TMA-210B 79/07/09 2pp

--7907130245 Notifies that proprietary info re Westinghouse rept "Rept on Small Break Accidents for Westinghouse NSSS Sys" supplements matl previously submitted re development of ECCS models Info encl  
WEISEMANN, R A Westinghouse Electric Corp CAW-79-24 79/06/29 1p

7907160012 Forwards NRC evaluation of topical repts BAW-10062, Revision 1, BAW-10074, Revision 1 & BAW-10075, Revision 1 re small break analyses for B&W plants  
SCHWENCER, A Light Water Reactors Branch 2 76/01/08 3pp

--7907160018 Evaluation of B&W topical repts re small break analyses for B&W 145, 177 & 205 plants BAW-10062, Revision 1, BAW-10074, Revision 1 & BAW-10075, Revision 1 Repts are acceptable  
\* Light Water Reactors Branch 2 76/01/08 5pp

7907160328 Forwards Mark I containment program rept NEDE-25090, "Analytical Model For T-Quencher Water Jet Loads On Submerged Structures"  
SOBON, L J General Electric Co MFN-174-79 79/06/28 1p

--7907160334 NEDE-25090  
"Analytical Model For T-Quencher Water Jet Loads On Submerged Structures"  
BODGE, F T, LABIER, L, IANNI, P W General Electric Co 79/05/31 73pp.

7907170021 Ack receipt of NRC 790614 ltr re organizational changes Responsibilities of fuel QA were consolidated in QA engineering section  
TAYLOR, J H Babcock & Wilcox Co 79/07/03 2pp

7907170143 Submits status rept on progress of PIBYS analysis of five NRC benchmark problems, per Hartzman 790512 ltr Forwards info re problems  
GRIDLEY, R L General Electric Co, Nuclear Energy Products Div 096-79 79/07/06 5pp

7907170170 Forwards page 4 of 6 to Revision 3 to App C of FPLTQAR 1-74A, Topical QA Rept  
WHIRIO, R C Florida Power & Light Co 79/07/11 2pp

7907170173 Forwards NEDE-2510-P, "Mark II Containment Supporting Program Caorso Safety Relief Valve Tests, Phase I Test Rept," May 1979 Rept withheld (ref 10CFR2 790)  
SOBON, L J General Electric Co, Nuclear Energy Products Div MFN-176-79 79/06/28 1p

7907180834 Forwards 790705 "Interim Rept on Results of ATHS Verification Analyses"  
TAYLOR, J H Babcock & Wilcox Co. 79/07/11 1p

--7907180840 "Interim Rept on Results of ATHS Verification Analyses"  
\* Babcock & Wilcox Co. 79/07/05 26pp.

## NONDOCKETED ITEMS

7907240480 Forwards summary of 790614 steam generator meeting in Silver Spring, MD to review & assess BNL experience in modeling U-Tube (USTO) & once-through steam generators  
ZUBER, Z Analysis Development Branch 79/06/25 40pp

7907250200 Notification of 790615 meeting w/C-E to discuss info needs from C-E on small break analyses  
SHERON, B W Analysis Branch 79/06/13 1p

7907250254 Submits further clarification of addl info in GE 790615 ltr re two-loop test apparatus scheduled for submission by 7/07/31  
STROUPE, E P General Electric Co, Nuclear Energy Products Div MFN 185-79 79/07/20 3pp

7907250320 Submits void fraction data in response to NRC 790430 ltr requesting addl clarification re uncertainty in neutron effective void correlation  
COOK, K W General Electric Co, Nuclear Energy Products Div MFN-186-79 79/07/19 4pp

7907250392 Forwards "Mod of GE Thermal Limit Evaluation" Technical portion of QA process for implementation completed. Remaining items to be completed by Jul 1979  
COOK, K W General Electric Co, Nuclear Energy Products Div MFN-171-79 79/07/20 1pp

--7907250395 "Mod of GE Thermal Limit Evaluation"  
\* General Electric Co, Nuclear Energy Products Div 79/07/20 3pp

7907250604 Summary of 790509 meeting w/Westinghouse in Bethesda, MD re recommended response to Item 7c of IE Bulletins 79-06A & 79-06A, Revision 1  
O'REILLY, P D Standardization Branch 79/06/12 6pp

7907250609 Summary of 790518 meeting w/BNL & Naval Research Lab re resolution of potential PWR neutron shield tank low fracture toughness  
SNAIDER, R P Systematic Evaluation Programs Branch (Pre 790625) 79/05/25 4pp

7907300189 Responds to BNL 790522 ltr Discusses NRC policy toward inservice testing reviews & reasons for not reviewing relief requests for non-safety related valves  
WAND, A Plant Systems Branch 79/06/12 1p

7907300232 Notification of 790621 meeting w/BNL & GE in Bethesda, MD to discuss basis for definition of condensation oscillation, chugging, downcomer lateral & submerged structure drag loads for Mark I long term program  
GRIMES, C I Division of Operating Reactors, 79/06/13 1p

7907300349 Notification of 790622 meeting w/C-E in Washington, DC to discuss revision to CENPD-153  
SCHEMEL, R Core Performance Branch 79/06/22 2pp

7907310313 Forwards June 1979 "Mark I Containment Activity Review"  
SOBON, L J General Electric Co, Nuclear Energy Products Div MFN-187-79 79/07/23 1p

--7907310317 "Mark I Containment Activity Review," June 1979  
\* General Electric Co, Nuclear Energy Products Div 79/06/30 6pp

7907310457 Forwards topical rept evaluation of BAW-10120-P, "Comparison of Core Physics Calculations w/Measurements"  
VARGA, S A Light Water Reactors Branch A 79/06/14 2pp

--7907310465 Topical rept evaluation of BAW-10120-P, "Comparison of Core Physics Calculations w/Measurements" Rept acceptable for ref in licensing actions.  
BROOKS, W L Core Performance Branch 79/06/14 4pp

#### WASTE MGT NUCLEAR WASTE MANAGEMENT

7905240076 Responds to 790304 ltr re problem of nuclear wastes. Forwards info re heat emanating from U pellets & freezing coolant water after use in reactor  
DENTON, M R Office of Nuclear Reactor Regulation 79/04/24 6pp

--7905240084 Requests clarification re fuel rods & fission & coolant water  
LISOVITCA, V V Affiliation Unknown, 79/03/04 1p.

7907060208 Notification of 790522 meeting w/DOE in Germantown, MD to discuss NRC high level waste program Agenda encl  
MALARD, J C High Level & Transuranic Waste Branch (Pre 790501) 79/05/08 2pp

7907180875 Requests placement on distribution list for meeting notices re radwaste repositories  
WELDEN, R C Hooker, Alley & Weldon 79/05/08 1p

7907190188 Confirms agreement to postpone next briefing for NRC on nuclear waste isolation program until 790523  
MEYER, S Energy, Dept of 79/05/11 3pp

7907190270 Requests placement on distribution list for meeting notices re radwaste repositories  
DAY, O R Illinois, State of 79/05/14 1p

7907190283 Requests placement on distribution list for meeting notices re radwaste repositories  
KELL, D S Florida, State of, 79/05/14 1p

7907190293 Notifies of postponement of NRC/DOE meeting on radwaste repositories  
MALARD, J C High Level Waste Licensing Management Branch 79/05/15 1p

7907190302 Requests placement on distribution list for meeting notices re radwaste repositories  
LOWERRE, R W Texas, State of 79/05/15 1p

7907190312 Requests placement on distribution list for meeting notices  
LONOLEY, M Y Vermont, State of 79/05/15 1p

7907190321 Requests placement on distribution list for meeting notices re radwaste repositories  
SHEALY, H O South Carolina, State of 79/05/15 1p

7907190330 Requests placement on distribution list for meeting notices re radwaste repositories  
MUDREY, M O Wisconsin, Univ of, Madison 79/05/15 1p

7907190333 Requests placement on distribution list for meeting notices re radwaste repositories  
FERMAN, J W Minnesota, State of 79/05/15 1p

7907190344 Requests placement on distribution list for meeting notices re radwaste repositories  
ALLEN, G W Kansas, State of 79/05/15 1p

7907190351 Requests placement on distribution list for meeting notices re radwaste repositories  
SETSER, J L Georgia, State of 79/05/15 1p

7907190360 Requests placement on distribution list for meeting notices re radwaste repositories  
CASHMAN, T J New York, State of 79/05/15 1p.

7907190365 Requests placement on distribution list for meeting notices re radwaste repositories  
DOTZENROD, R C North Dakota, State of 79/05/15 1p

7907190372 Requests placement on distribution list for meeting notices re radwaste repositories  
VEGBELS, R D New York, State of 79/05/15 1p

7907190380 Requests placement on distribution list for meeting notices re radwaste repositories  
OLSON, N K South Carolina, State of 79/05/15 1p

7907190386 Requests placement on distribution list for meeting notices re radwaste repositories  
LIBERATORE, A Illinois, State of, 79/05/14 1p

7907190394 Requests placement on distribution list for meeting notices re radwaste repositories  
MABBICOT, P Maryland, State of 79/05/15 1p

7907190405 Requests placement on distribution list for meeting notices re radwaste repositories.  
\* Energy Research Group, Inc. 79/05/14 1p

7907190413 Requests placement on distribution list for meeting notices re radwaste repositories  
RICE, E R Washington, State of 79/05/16 1p

7907190422 Requests placement on distribution list for meeting notices re radwaste repositories  
EWOLDBEN, H M Woodward-Clyde Consultants 79/05/16 1p

7907190427 Requests placement on distribution list for meeting notices re radwaste repositories  
HATEM, T J Maryland, State of 79/05/16 1p

7907190434 Requests placement on distribution list for meeting notices re radwaste repositories  
RYBARCZYK, R G Pennsylvania, State of 79/05/16 1p

7907190444 Requests placement on distribution list for meeting notices re radwaste repositories  
MORGENSTERN, L Massachusetts, State of 79/05/16 1p

7907190449 Requests placement on distribution list for meeting notices re radwaste repositories  
VANN, J New Jersey, State of 79/05/16 1p

7907190454 Requests placement on distribution list for meeting notices re radwaste repositories  
FUNDERBURG, R D Idaho, State of 79/05/17 1p

7907190473 Requests placement on distribution list for meeting notices re radwaste repositories  
O'BRIAN, B F Pennsylvania, State of 79/05/17 1p

7907190481 Requests placement on distribution list for meeting notices re radwaste repositories  
NEILL, R. H New Mexico, State of 79/05/17 1p

7907190486 Requests placement on distribution list for meeting notices re radwaste repositories  
KALLEMEYN, V South Dakota, State of 79/05/17 1p

7907190491 Requests placement on distribution list for meeting notices re radwaste repositories  
HULL, D A Oregon, State of 79/05/17 1p

7907190496 Requests placement on distribution list for meeting notices re radwaste repositories  
WILL, R C Washington, State of 79/05/18 1p

7907190505 Notifies that name has been placed on distribution list for meeting notices re radwaste repositories  
MALABO, J C High Level Waste Licensing Management Branch 79/05/02 1p

7907190509 Notifies that NRC & DOE will hold meetings on radwaste repositories  
RYAN, R G. Office of State Programs 79/05/07 1p

7907190819 Requests placement on distribution list for meeting notices re radwaste repositories  
RATTE, C A Vermont, State of 79/05/15 1p

EXPORT LIC EXPORT AND IMPORT LICENSES

781300307 Lic for Gen Elec Co to export tools, equip, components & matls to Switzerland  
SHEA, J R Office of International Programs 78/11/20 3pp

7906140602 Application by Transnuclear, Inc for license to export 125,500 kg U, enriched to 0.35% U-235, & 500 kg U hexafluoride, enriched to 0.35 U-235, to France  
MATSUN, V Transnuclear, Inc 79/05/03 1p

7907020500 Forwards export license application  
ROGERS, W F Metal Bellows Corp A14009 79/05/21 1p.

--7907020501 Application by Metal Bellows Corp for license to export flexible metal hose to Spain  
ROGERS, W F Metal Bellows Corp 79/05/21 1p.

7907030104 Requests renewal of license to export thorium contained in optical glass, photographic lens & dye transfer paper  
HARTER, E. S., SCHERBERGER, R. F Eastman Kodak Co. 79/05/01 1p.

7907030190 Notifies of request for withdrawal of export license by Westinghouse  
OPLINGER, G. G. Assistant Director for Export/Import & International Safeguards 79/05/29 1p.

7907030196 Requests quantity of U-235 in export license application be raised 2 g  
MARCHAL, J European Communities, Commission of 79/05/17 1p

7907030291 Application by Westinghouse for license to export two Type WL 8073 fission chambers, enriched to 93% U-235, to France  
SCHNAUTZ, C E Westinghouse Electric Corp 79/05/16 3pp

7907030297 Application by GE for license to export 100 pieces of unfinished Zr tubing designed for fabrication of nuclear fuel to Switzerland  
WILSON, B D General Electric Co 79/05/22 1p

7907030303 Application by Reuter-Stokes, Inc for license to export U-235, deposited as U dioxide on internal surface of Model RS-C6-0201-231 radiation detector, to West Germany  
\* Reuter-Stokes, Inc 79/05/17 2pp

7907030318 License for Isotope Products Labs to export 10 uCi Cm-244 contained in Model PH-244 sealed x-ray source to Kenya  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/31 2pp

7907030320 Amend 1 to license for Mitsubishi Intl Corp increasing quantity of matl to 12 500 g U-235 for export to Japan  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards. 79/05/29 1p

7907030324 License for Reuter-Stokes, Inc to export two Model RS-C1-1210-135 compensated ion chambers to France  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/23 1p.

7907030333 Forwards 790516 application for export license & 790517 ltr of assurance  
GOPPEL, M European Communities, Commission of 79/05/17 1p

--7907030337 Application by Delegation of Commission of European Communities for license to export 2 g U-0002, 1 g U-500 & 1 g U-940 to France Ltr of assurance encl  
\* European Communities, Commission of 79/05/16 3pp

7907050108 Requests Executive Branch position re Transnuclear, Inc application for license to export 17,889 kg U, enriched to 0.35% U-235, to The Netherlands  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/05 1p

7907050245 Requests Executive Branch position re Mitsui & Co application for license to export 30,451 kg U, enriched to 0.75% U-235, for use as reload fuel for Fukushima I, Unit 3, in Japan  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 1p.

7907050248 Forwards application for export license for minor nuclear export Ltr of assurance required  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 1p

7907050252 Forwards application for export license for minor nuclear export Ltr of assurance required  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 1p

7907050282 Reviews application by Transnuclear, Inc to export SNM to Switzerland Recommends license be issued.  
MOORE, R N Office of International Programs. 79/05/29 1p

7907050311 Reviews application by Rhone-Poulenc, Inc to export source matl to France Recommends license be issued  
MOORE, R N. Office of International Programs 79/05/24 2pp

7907050314 Discusses GE application to export Zr tubing to Switzerland License issued w/o waiting period  
OPLINGER, G. G Assistant Director for Export/Import & International Safeguards. 79/05/24 1p

7907050482 License for Transnuclear, Inc to export 740 012 kg U-235 & 0 034 kg U-235 as U hexafluoride to Switzerland,  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards. 79/05/29 2pp

7907060045 License for Sigma Chemical Co to export 2 kg heavy water to India  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/30 2pp.

- 7907060049 License for Sigma Chemical Co to export 5 kg heavy water to India  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/23 2pp
- 7907060051 License for Sigma Chemical Co to export 8 kg heavy water to Mexico  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/23 2pp
- 7907060053 License for Rhone-Poulenc, Inc to export 11,500 kg thorium & U to France  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 2pp
- 7907060080 Isotope Products Lab License to export 0.01 micrograms Cf-252 to Australia  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/23 2pp
- 7907060082 Confirms 790524 telcon Requests that export license to ship 10,000 Ci Co-60 to Hanoi, Vietnam be extended to 800601  
DAVIDSON, T Bach Mai Hosp Emergency Relief Fund DD, Massachusetts 79/05/24 1p
- 7907060086 License for GE to export 100 pieces of unfinished zirconium tubing to Switzerland  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 1p
- 7907060091 License for GE to export nozzle fittings to The Netherlands  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/25 1p
- 7907060253 Amends Exxon Nuclear Co export license for West Germany, extending expiration date to 800201  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 1p
- 7907060255 Amends Westinghouse license to export reactor pressure tubes, 7r tubes & specially-designed components to Canada, increasing value of exported items  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 1p
- 7907060259 Amends Transnuclear, Inc export license for France, increasing quantity of U-235 to 4.2 g  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/24 1p
- 7907060262 License for United Kingdom Treasury & Supply Delegation to export 150 pieces of Zircaloy-4 tubing to United Kingdom  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/23 1p.
- 7907060286 Requests amend to Westinghouse License XCDM-149, increasing value of export of reactor pressure tubes to Canada  
HERSCH, M M Westinghouse Electric Corp 79/05/18 1p
- 7907060290 Discusses delay in processing License XSNM-1517  
WRIGHT, B. L. Office of International Programs 79/05/24 1p
- 7907060440 Forwards License XB-1012 for export of 110,000 Ci tritium to Radium-Chemis Ltd in Switzerland for production of luminous compounds w/o encl  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/01 1p
- 7907060443 Notifies that action on License XBNM-1379 to export low enriched U fuel to India has not been completed. Action deferred by Executive Branch pending clarification of certain issues.  
SHEA, J R Office of International Programs 79/06/04 1p.
- 7907060467 Requests 6-month extension of export license to 800201. License authorizes export of U oxide fuel pellets to West Germany.  
NECHODOM, W S Exxon Nuclear Co, Inc (subs of Exxon Corp) 79/05/11 1p
- 7907060485 Executive Branch position re GE application for license to export 161 kg U-235, contained in 5,875 kg U enriched to max 3.1%, to Japan  
NOSENZO, L. V. State, Dept of 79/05/29 3pp.
- 7907060491 Executive Branch position re Transnuclear, Inc application for license to export 227,073 kg U-235 contained in 10,221 kg U enriched to max of 3% plus 0.125 kg U-235 in 4 kg U, to West Germany. License should be granted  
NOSENZO, L. V. State, Dept of. 79/06/01 3pp
- 7907060497 Executive Branch position re Mitsui Co, Inc application for license to export 756 kg U-235, contained in 26,902 kg U enriched to max of 3.95%, to Japan. License should be granted  
NOSENZO, L. V. State, Dept of 79/05/29 4pp
- 7907090389 Ack 790531 telcon re license application. Part 8(a) should be changed to reflect two units w/elemental weight shown as 3832.56 mg. Part 8(b) should be changed to reflect two units w/isotopic weight of 3564.28 & 3832.56 mg total U  
GERAGHTY, C Reuter-Stokes, Inc 79/05/31 1p
- 7907090408 Certifies that 0.007 g of U-235 contained in 0.037 g U & transfer of matl will be subj to all terms & conditions of Add'l Agreement for Cooperation, dtd 500725, as amended. Intermediate & ultimate consignees authorized by EURATOM  
GOPPEL, M European Communities, Commission of 79/05/30 1p
- 7907090415 Forwards notification of corp name change. Also forwards AF Gerald 790529 ltr detailing nature & reason for change  
PACHT, E Scallop Corp, Scallop Materials Service Div 79/05/29 1p
- 7907090423 Notification that Asiatic Petroleum Corp is now known as Scallop Corp  
GERALD, A F Scallop Corp, Scallop Materials Service Div 79/05/29 1p
- 7907090418 Requests amend of NRC License XCDM-119, re reactor vessel studs, nuts & washers for export to Spain  
MUIR, H S Babcock & Wilcox Co 79/05/31 1p
- 7907100043 Confirms that transfer of matl identified on license will be subject to terms & conditions of Agreement for Cooperation  
KEEFE, R Canada, Atomic Energy Control Board 79/05/24 1p
- 7907100047 Executive Branch position re Westinghouse application to amend export license by adding new ultimate consignees in France. License should be granted  
MURFEN, L V State, Dept of 79/06/01 2pp
- 7907100053 Requests Export License XBNM-1373 be amended to reflect that matl will be in form of U dioxide  
MATSON, V Transnuclear, Inc 79/06/04 1p
- 7907100306 License for Eberline Instrument Corp to export 22 micrograms Pu-239 electroplated on 1.75 inch stainless steel disc for calibr of radiation detection equipment to Canada  
SHEA, J R Office of International Programs 79/06/06 2pp
- 7907100343 License for NASA to export 1 g Th-232, 0.6 g U-238 & 0.05 g Np-237, contained in foil, to Soviet Union  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/08 2pp
- 7907110053 License for Unipax Intl to export 700 kg U, in form of depleted U metal bars containing 15 kgs matl to be used for shielding purposes, to South Korea  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/31 2pp
- 7907110701 Ltr of assurance re Delegation of Commission of European Communities application for license to export U-235 to France  
MARCHEL, J European Communities, Commission of 79/05/22 1p
- 7907110739 Application by Aramco Svc Co for license to export 54 kg depleted U to Saudi Arabia  
INFANTE, R. Aramco Services Co 79/04/02 1p.
- 7907110744 Requests amend of License XBNM-749 extending expiration date to 800701  
WILSON, B D General Electric Co 79/05/31 1p
- 7907120047 Certifies that 0.033 mg of Pu-239, as mentioned in application OER 1, dtd 790315 will be subj to all terms & conditions of 600725 Add'l Agreement for Cooperation  
MARCHEL, J, GOPPEL, M European Communities, Commission of. 79/05/21 3pp
- 7907120047 Certifies that 0.033 mg of Pu-239, as mentioned in application OER 1, dtd 790315 will be subj to all terms & conditions of 600725 Add'l Agreement for Cooperation  
MARCHEL, J, GOPPEL, M European Communities, Commission of. 79/05/21 3pp
- 7907120047 Certifies that 0.033 mg of Pu-239, as mentioned in application OER 1, dtd 790315 will be subj to all terms & conditions of 600725 Add'l Agreement for Cooperation  
MARCHEL, J, GOPPEL, M European Communities, Commission of. 79/05/21. 3pp

7907120360 Forwards application by Mitsui & Co. Inc for two licenses to export SNM in form of U hexafluoride or U dioxide to Japan  
MOMDEN, T Mitsui & Co , Ltd 79/05/01 1p

--7907120495 Application by Mitsui & Co. Inc for license to export 397 kg enriched U hexafluoride & 483 kg enriched U dioxide to Japan  
\* Mitsui & Co , Ltd 79/05/01 1p

7907120382 Forwards telex providing more detailed explanation of end use listed in application XU-B461  
MATSON, V Transnuclear, Inc 79/05/25 2pp

--7907120683 Application by Transnuclear, Inc for license to export 129,500 kg depleted U in form of U metal as derbies, enriched to 0.3% U-235 & 500 kg depleted U in form of U hexafluoride, enriched to 0.3% U-235  
\* Transnuclear, Inc 79/05/03 2pp

7907120394 Forwards application by GE for license to export Zr tubing to Switzerland  
WILSON, S D General Electric Co BDW-79135 79/05/23 1p

7907130053 Requests Executive Branch position re Westinghouse application for license to export reactor pressure tubes & specially designed components to Argentina  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/01 1p

7907130098 Requests Executive Branch position re Mitsubishi Intl Corp application for license to export 40,023 kg U enriched to 0.25% U-235, to Japan  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/01 1p

7907130068 Requests Executive Branch position re GE application for license to export one fuel grapple assembly to Italy  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/01 1p

7907130074 Requests Executive Branch position re Metal Bellows Corp application for license to export specifically designed components to Spain  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/01 1p

7907130089 Amend 3 to Transnuclear, Inc export license to include U in form of U oxide as well as UF<sub>6</sub> in export to France  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/01 1p

7907130234 Forwards application for license to export 20 NBS stds U-030 & U hexafluoride to Italy  
GOPPEL, M European Communities, Commission of 79/05/16 2pp

--7907130240 Application by Delegation of Commission of European Communities for license to export 20 g U-030 enriched U oxide to Italy  
\* European Communities, Commission of 79/05/16 2pp

7907130427 SECY-79-100  
Recommends NRC approve Westinghouse license to export various components to Philippines  
SHEA, J R Office of International Programs 79/05/08 9pp

--7907130441 Executive Branch position re Westinghouse application for license to export various components to Philippines  
License should be issued  
NOSENZO, L V State, Dept of 78/11/03 9pp

7907130508 Certifies matl & transport procedures re export license XBNM-1813 comply w/all terms & conditions of 600725 Addl Agreement for Cooperation  
GOPPEL, M European Communities, Commission of 79/05/17 2pp

7907180277 Forwards license application for minor nuclear export Ltr of assurance required W/o encl  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/06 1p

7907180284 Requests Executive Branch position re Eberline Instrument Corp application for license to export BNH to Chile.  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/06 1p

7907180546 License for Delegation of Commission of European Communities to export 2,486 g U-235 to France  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/01 2pp

7907180550 License for Westinghouse to export 0.0164 g U-235 to South Korea  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards FE-20040 79/06/01 2pp

7907180563 Application by Transnuclear, Inc for license to export U, enriched to max of 1.16% U-235, to France  
MATSON, V Transnuclear, Inc 79-155/01 TNP28 79/05/30 3pp

7907180660 License for Reuter-Stokes, Inc to export 0.0001 g U-235, enriched to 72% max in U-235, to West Germany  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards U-8060 79/06/05 2pp

7907180665 License for Transnuclear, Inc to export 277.073 kg U-235, enriched to 3% w/o max, & 0.120 kg U enriched to 3% w/o max, to West Germany  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 270 EU/26 79-06 79/06/05 2pp

7907180668 License for Reuter-Stokes, Inc to export 0.007 g U-235, enriched to 18% w/o max, to West Germany  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards U-8063 79/06/05 2pp

7907180675 License for Reactor Experiments, Inc to export 0.033 mg Pu-239 to West Germany  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards GER-1 79/06/01 2pp

7907180678 License for Reactor Experiments, Inc to export 0.095 mg U-235 enriched to 93.15 w/o max, electrodeposited onto nickel foil, to West Germany  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards GER-1 79/06/01 2pp

7907180820 Requests amend to include Borg-Warner Nuclear Valve Div of Borg-Warner BV 4870 AB Etten-Leur, The Netherlands, as intermediate consignee  
HAN, S Y Borg-Warner Corp 79/05/30 2pp

7907180838 Application by Sigma Chemical Co for license to export compounds containing deuterium, over 2-yr period, to New Zealand  
STERN, W C Sigma Chemical Co (subs of Sigma Aldrich Corp ) 79/06/05 1p

7907180852 Forwards BECY-79-72A re Executive Director response on pending application to export highly enriched U to Japan  
MCGREGOR, E W Office of the Executive Director for Operations 79/06/12 1p

--7907180860 SECY-79-72A  
Forwards Executive Branch position re GE application to export 161 kg U-235, contained in 5,875 kg U enriched to max of 3.1%, to Japan Requests Commissioner input  
SHEA, J R Assistant Director for Export/Import & International Safeguards 79/06/05 1p

--7907180869 Executive Branch position re GE application for license to export 161 kg U-235, contained in 5,875 kg U enriched to max of 3.1%, to Japan Ltr of assurance encl License should be granted  
NOSENZO, L V State, Dept of 79/05/29 3pp

7907180861 Application by Matheson Gas Products for license to export 200 liters deuterium, chemically pure, 36 g & two Size 4 cylinders, each containing 100 liters, to South Africa  
\* Matheson Gas Products 79/06/05 2pp

7907180868 Application by Marubeni America Corp for license to export U-30B, w/ various max weights of U-235, to Japan End use statement encl  
MAHIYA, S Marubeni America Corp (subs of Marubeni Corp ) 79/05/17 3pp

7907180873 License for Westinghouse to export three compensated ionization chambers, Type WL-23944, to France  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/11 1p

7907180877 Forwards TX Nuclear Div application for license to export 30 mCi Pu-235 to Italy  
HENDRICK, W G Ramsay Engineering Co , Texas Nuclear Div 79/06/12 1p

--7907180900 Application by TX Nuclear Div for license to export 30 mCi Pu-235, as sealed source contained in Model 9256 source holder, to Italy  
HENDRICK, W G Ramsay Engineering Co , Texas Nuclear Div 79/06/12 1p

## NONDOCKETED ITEMS

- 7907180880 Amend 2 to OA Co export license, increasing U-235 by 390 g contained in 1,970 g U  
SHEA, J R Assistant Director for Export/Import & International Safeguards 79/06/08 1p
- 7907180909 License for United Kingdom Treasury & Supply Delegation to export 3 914 g U-235 to United Kingdom  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards F-2391/01-7028 79/06/01 2pp
- 7907190001 Application by Westinghouse for license to export one compensated ionization chamber to Japan  
PUCHAL, W F Westinghouse Electric Corp 79/06/05 1p
- 7907190009 SECY-78-655A  
Forwards Executive Branch position re pending application for Mitsui & Co, Inc license to export highly enriched U to Japan  
SHEA, J R Office of International Programs 79/05/29 1p
- 7907190012 Executive Branch position re Mitsui & Co, Inc application for license to export 3,511 kg U-235 to Japan license should be granted End use statement encl  
NOSENZO, L V State, Dept of 79/05/23 2pp
- 7907190034 Requests Executive Branch position re WJ Woolley Co application for license to export specially-designed equipment to South Korea  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p
- 7907190163 Execution Branch position re OA Co application for license to export increased amount (390 g) U-235, contained in 1,970 g U, enriched to 19 Bk, to Turkey  
NOSENZO, L V State, Dept of 79/06/05 4pp
- 7907190615 License for Hoke, Inc to export two 1 5-inch bellows-sealed control valves to Canada  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 1p
- 7907190621 License for World Wide Import/Export Svc, Ltd to export one uncompensated ionization chamber, Model WL-6937A, & one compensated ionization chamber, Model WL-23084, to Brazil  
SHEA, J R Office of International Programs 79/06/22 1p
- 7907190624 License for Chase Nuclear (US) to export one Zircaloy-2 extruded tube to Korea  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 1p
- 7907190627 License for Westinghouse to export one compensated ionization chamber, Type WL-23084, to Japan  
SHEA, J R Office of International Programs 79/06/27 1p
- 7907190630 License for Hoke, Inc to export two 1 5-inch bellows-sealed control valves to Canada  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 1p
- 7907190633 License for Edlow Intl Co to export 0 09 micrograms Pu-242, contained in 15 g solution nitric acid, NBS Std 4335, to Sweden  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/25 2pp
- 7907190636 License for TX Nuclear Div to export 2 830 mg Pu-239, contained in 3 520 mg Pu as sealed sources in Models 9256 & 9264 source holders, to Singapore  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/25 2pp
- 7907190640 License for Transnuclear, Inc to export 0 273 kg U-235, enriched to 1 16% w/o max, to France  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 2pp
- 7907190644 License for Westinghouse to export 3 36 g U-235, contained in 3 62 g U, in two fission chambers, enriched to 93% w/o max, to France  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 2pp
- 7907190648 License for TX Nuclear Div to export 1 415 mg Pu-238, contained in 1 76 mg Pu as sealed source in Model 9256  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 2pp
- 7907190653 License for Sigma Chemical Co to export 5 kg deuterium oxide, contained in compounds, to New Zealand  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 2pp
- 7907190657 License for Matheson Gas Products to export 36 g deuterium, chemically pure, contained in two Size 4 cylinders, to South Africa  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 2pp
- 7907190663 License for Reuter-Stokes, Inc to export 0 0004 g U-235, enriched to 93% w/o max, as detectors in Model RB-06-0201-231, to West Germany  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 2pp
- 7907190668 License for Monsanto Research Corp to export 0 33 g Pu-238, contained in one Pu-238 beryllium sealed neutron source, MRC Model 2724, to Turkey  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 2pp
- 7907190676 License for Metal Bellows Corp to export six pieces of 1-inch hose assemblies 769-89, 18 pieces of 3-inch hose assemblies 769-90 & 100 pieces of instrumentation hose 739-89 to Spain  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/26 1p
- 7907190683 License for Transnuclear, Inc to export 520 13 kg U-235, contained in 12 282 11 kg U, & 0 043 kg U-235, contained in 1 kg U, to France  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/25 1p
- 7907190686 License for Reactor Experiments, Inc to export 0 2014 mg Np-237, electrodeposited into nickel foil, to Czechoslovakia  
SHEA, J R Office of International Programs 79/06/20 2pp
- 7907190692 License for Transnuclear, Inc to export 458 25 kg U-235, contained in 12 100 kg U, & 0 033 kg U-235, contained in 1 kg U, to Sweden  
SHEA, J R Office of International Programs 79/06/20 2pp
- 7907190697 License for Gearhart Owen Industries, Inc to export 2 Ci Cs-137 source contained in density tool, 3 Ci Am-241 source for Gamma Ray-CCL-neutron tool & 250 mCi Am-241 source contained in oilwell density tool to Poland  
SHEA, J R Office of International Programs 79/06/20 2pp
- 7907190705 License for Byron Jackson Pump Div to export miscellaneous specially-designed or prepared parts & components, for use in coolant pumps of listed reactors, to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 2pp
- 7907190709 License for GE to export two offgas filter vessels & associated valves to Italy  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p
- 7907190715 License for Edlow Intl Co to export 1,000,000 kg U, contained in 1,180,000 kg U-308, to United Kingdom  
SHEA, J R Office of International Programs 79/06/21 2pp
- 7907190720 License for GE to export pipe whip restraints, specially designed for use in nuclear reactor, to Belgium  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p
- 7907190749 License for Delegation of Commission of European Communities to export 0 061 g U-235, contained in 20 g U, as NBS Std U-030, to Italy  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/08 2pp
- 7907190758 License for Delegation of Commission of European Communities to export 2 g U as U oxide depleted, as NBS Std U-0002, & 1 48 g U-235, contained in 2 g U, as NBS Stds U-500 & U-970, to France  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/06/08 2pp
- 7907190764 License for Mitsui & Co, Inc to export 29,463 lbs Zircaloy-4 tube shells to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p

- 7907190772 License for Carpenter Technology Corp to export 615 Zircaloy-4 alloy fuel channels to West Germany  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/08/01 1p
- 7907190778 License for Borg-Warner Corp to export globe & check valves, carbon & stainless steel, pneumatically, electrically & manually-operated, per Section III of ASME Boiler & pressure Vessel Code to The Netherlands  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p
- 7907190783 License for Westinghouse to export reactor internals, reactor control mechanisms & other specifically-designed or prepared parts & components for use in nuclear reactor to Switzerland  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p
- 7907190791 Amend 2 to Transnuclear, Inc export license, extending expiration date to 800601  
OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/06/05 1p
- 7907190797 Amend 2 to Transnuclear, Inc export license, extending expiration date 800701  
OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/06/05 1p
- 7907190805 Amend 1 to Westinghouse export license, adding specified French nuclear reactor facilities as ultimate consignee  
revising items authorized for export  
SHEA, J R Office of International Programs 79/06/06 2pp
- 7907190810 Amend 1 to Westinghouse export license, changing other party to Westinghouse Electric Corp, c/o HM St John Co  
OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/06/06 1p
- 7907190814 Amend 3 to GE export license, extending expiration date to 800701  
SHEA, J R Office of International Programs 79/06/06 1p
- 7907190825 Amend 1 to Scallop Metals Svc export license, changing name of licensee from Asiatic Petroleum Corp & changing ultimate consignee to read all countries except Cambodia, Cuba, North Korea, Rhodesia & Uganda  
SHEA, J R Office of International Programs 79/06/06 1p
- 7907190830 Amend 1 to B&W export license, adding intermediate consignee in Spain & M Snedeker Corp as other party to export  
OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/06/05 1p
- 7907190837 License for Westinghouse to export three compensated ionization chambers, Type WL-2394A, to France  
OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/06/05 1p
- 7907190843 Forwards application for license for minor nuclear export Ltr of assurance required  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/25 1p
- 7907190855 Application by Isotope Products Labs for license to export 1 microgram Pu-238, 1 microgram Pu-239 & 1 microgram Pu-236 to West Germany  
AMLAUER, K Isotope Products Laboratories 79/06/12 1p
- 7907230032 Application by Eberline Instrument Corp for license to export one Pu-239 disc, electroplated on stainless steel, to United Kingdom  
DOLES, A E Eberline Instrument Corp. 79/06/18 1p
- 7907230046 Application by Transnuclear, Inc for license to export U in form of U hexafluoride enriched to 93.30% U-235, to West Germany. End use statement encl  
HATSDON, V Transnuclear, Inc. 79/06/03 2pp
- 7907230052 Forwards application for license to export 33.0 kg U, containing 30.8 kg U-235 enriched to 93.30% U-235, to France.  
HATSDON, V Transnuclear, Inc. 79/06/05 7pp
- 7907230090 Application by Gearhart Owen Industries, Inc for license to export 2 Ci Cs-137 source for density tool & 3 Ci Am-241 radioactive neutron source for Gamma Ray-CCL-neutron tool to Poland.  
CLAUNCH, A Gearhart-Owen Industries, Inc, 60 Wireline Services Div 79/06/01 2pp
- 7907230135 License for JT Baker Chemical Co to export 14.03 lb depleted U, contained in 25 lb uranyl acetate, to Mexico  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 2pp
- 7907230140 Application by TX Nuclear Div for license to export 30 mCi Pu-238, as sealed source contained in Model 9264, to Singapore  
HENDRICK, W G Ramsay Engineering Co, Texas Nuclear Div 79/06/18 1p
- 7907230144 Requests expediting of export license since rigid shipping schedule is required License encl  
HENDRICK, W G Ramsay Engineering Co, Texas Nuclear Div 79/06/18 1p
- 7907230149 Executive Branch position re Byron Jackson Pump Div application for license to export components for coolant pumps to India License should be granted  
NOSENZO, L V State, Dept of 79/06/15 2pp
- 7907230162 Application by Reuter-Stokes, Inc for license to export RS-C6-1100 local power range monitor assembly Type U-234/U-235 mixture sensitive matl to Sweden  
SKURUPA, J O Reuter-Stokes, Inc 79/06/18 3pp
- 7907230168 Executive Branch position re Mitsui & Co application for license to export Zircaloy-2 tube shells, to be used as fuel cladding, to Japan License should be granted  
NOSENZO, L V State, Dept of 79/06/15 2pp
- 7907230171 Amend 2 to Westinghouse export license, to extend expiration date to 801231  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 1p
- 7907230177 Amend 1 to Westinghouse export license, to extend expiration date to 810501, delete Condition 3 & change max enrichment percentage  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/25 1p
- 7907230179 Executive Branch position re Reactor Experiments, Inc application for license to export 0.2014 mg Np-237 electrodeposited on nickel foil, to Czechoslovakia License should be granted  
NOSENZO, L V State, Dept of 79/06/15 2pp
- 7907230185 Forwards SECY-79-368 re Transnuclear, Inc application for export license to transport source matl to France.  
MCOREGOR, E W Office of the Secretary of the Commission 79/06/12 1p
- 7907230188 SECY-79-368  
Notification of receipt of Transnuclear, Inc application to export 22.0679 kg U, enriched to 3.35% max, & 126.000 kg depleted U, enriched to 0.3% max U-235, to France  
SHEA, J R Office of International Programs 79/06/04 2pp
- 7907230196 Application by Transnuclear, Inc to export depleted U, in form of U metal, as debris at 0.3% U-235, & depleted U in form of depleted U hexafluoride as heels, at max of 0.3% U-235, to France End use statement encl.  
\* Transnuclear, Inc 79/05/03 2pp
- 7907230193 Executive Branch position re GE application for license to export pipe whip restraints to Belgium License should be granted  
NOSENZO, L V State, Dept of 79/06/15 2pp
- 7907230210 Amend 2 to GE export license, to add Conditions 11 & 12  
SHEA, J R Office of International Programs 79/06/28 1p
- 7907230227 Amend 3 to Transnuclear, Inc export license, to add Conditions 10-12 re shipments of highly enriched U  
SHEA, J R Office of International Programs 79/06/28 2pp
- 7907230230 Amend 1 to TX Nuclear Div export license, to add Ramsay REC, Ltd, Canada as additional intermediate consignee  
SHEA, J R Office of International Programs 79/05/20 1p
- 7907230443 Executive Branch position re Carpenter Technology Corp application for license to export Zircaloy-4 alloy fuel channels to West Germany  
NOSENZO, L V State, Dept of 79/06/15 2pp
- 7907230445 Executive Branch position re GE application for license to export offgas filter vessels & associated valves to Italy.  
NOSENZO, L V State, Dept of 79/06/15 2pp

## NONDOCKETED ITEMS

790723044B Executive Branch position re Transnuclear Inc application for license to export 52B 13 kg U-235, enriched to 4.3%, & 0.043 kg U-235, contained in 1 kg U, to France  
NOSENZO, L V State, Dept of 79/06/15 2pp

7907230457 Executive Branch position re Nuclear Value Div, Borg-Warner Corp application for license to export globe & check valves to Belgium  
NOSENZO, L V State, Dept of 79/06/15 2pp

7907230521 Submit application to amend license to export nuclear matl to Spain Requests change in ultimate consignee  
WILSON, B D General Electric Co, Nuclear Energy Products Div  
BDW-79161 79/06/14 1p

7907230600 Requests Executive Branch position re Edlow Intl Co application for license to export U-235 to Sweden  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/02 1p

7907230629 Requests Executive Branch position re Mitsui & Co application for license to export Zircaloy-2 tubes to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 1p

7907230632 Requests Executive Branch position re Mitsui & Co (USA), Inc application for license to export U-235 to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 1p

7907230636 Requests Executive Branch position re Par Sys Corp application for license to export neutron absorber tubes to Spain  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/02 1p

7907230641 Requests Executive Branch position re Westinghouse application for license to export 122,229 kg U, enriched to 3.5% U-235, to Switzerland  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/29 1p

7907230646 Requests Executive Branch position re Isotope Products Labs application for license to export byproduct matl to Argentina  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/28 1p

7907230651 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/05 1p

7907230656 Requests amend to extend export license to B10801  
WILSON, B D General Electric Co, Nuclear Energy Products Div  
79/06/18 1p

7907230659 License for Amersham Corp to export 400 mCi Cm-244 to United Kingdom  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 2pp

7907230661 License for Air Products & Chemicals, Inc to export 167 g deuterium to Canada  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/29 2pp

7907230664 License for Mitsubishi to export 500 mCi of Cf-252 to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/28 2pp

7907230668 Executive Branch position re Byron Jackson Pump Div application for license to export parts for coolant pumps to India License should be granted  
NOSENZO, L V State, Dept of 79/06/15 2pp

7907230671 License for Westinghouse to export 3.36 g U-235, enriched to 93% w/o max, to Sweden  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/28 2pp

7907230674 License for Reuter-Stokes Inc to export 40 986 mg U-235, enriched to 93% w/o max, to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/02 2pp

7907230686 Executive Branch position re Sandvic Special Metals Corp application for license to export 2100 zirconium tubes, for use as cladding for fuel elements, to Sweden License should be issued  
NOSENZO, L V State, Dept of 79/07/02 2pp

7907230690 Executive Branch position re Mitsui & Co application for license to export Zircaloy-4 tube shells to Japan License should be granted  
NOSENZO, L V State, Dept of 79/06/15 2pp

7907230702 License for Mitsubishi Intl Corp to export 0.41g U-235, contained in 40.57 g depleted U, to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/29 2pp

7907240007 License for GE to export one fuel grapple assembly & mod ltr to Italy  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/05 1p

7907240008 Amend 1 to TX Nuclear Div export license, to add Ramsey REC, Ltd as addl intermediate consignee  
SHEA, J R Office of International Programs 79/06/20 1p

7907240010 License for Westinghouse to export reactor pressure tubes & miscellaneous reactor parts & components to Argentina  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/05 1p

7907240012 License for Mitsui & Co to export 25,463 lb of Zircaloy-4 tube shells to Japan  
SHEA, J R Office of International Programs 79/06/20 1p

7907240015 License for Westinghouse to export one compensated ionization chamber, Type WL-23729, to Switzerland  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 1p

7907240017 License for Byron Jackson Pump Div to export parts for use in coolant pumps to India  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p

7907240019 License for Westinghouse to export two compensated ionization chambers, Model WL-6377, to The Netherlands  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 1p

7907240024 License for GE to export 331 kg U-235, enriched to 3.1% max, to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 2pp

7907240031 License for Byron Jackson Pump Div to export one tandem-type mechanical seal cartridge for use in coolant pumps to India  
SHEA, J R Office of International Programs 79/06/20 2pp

7907240036 License for Byron Jackson Pump Div to export 56 coil springs for use in coolant pumps to India  
SHEA, J R Office of International Programs 79/06/20 1p

7907240039 Amend 1 to TX Nuclear Div export license, to add Ramsey REC, Ltd as intermediate consignee  
SHEA, J R Office of International Programs 79/06/20 1p

7907240054 License for Transnuclear, Inc to export 411.23 kg U-235, enriched to 3.5%, & 0.0355 kg U-235, contained in 1 kg U, enriched to 3.5%, to Switzerland  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 2pp

7907240056 License for TX Nuclear Div to export 1.415 mg Pu-238, contained in 1.76 mg plutonium, to Italy  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 2pp

7907240059 License for Mitsubishi Intl Corp to export 342 kg U-235, enriched to 2.5%, to Japan  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/03 2pp

7907240103 Application by Amersham Corp for license to export 400 mCi Cm-244 as sealed source to United Kingdom  
BELGRAIR, D P Amersham Corp 79/06/06 1p



- 790724011 Application by Westinghouse for license to export one compensated ionization chamber to Switzerland  
POCHAL, W F Westinghouse Electric Corp 79/06/13 1p
- 790724015 Application by Air Products & Chemicals, Inc for license to export 167 g deuterium to Canada  
NOVAKOVICH, D Air Products & Chemicals, Inc 79/06/08 1p
- 790724016 Executive Branch position re GE application for license to export one fuel grapple assembly & mod kit to Italy License should be granted  
NOSENZO, L V State, Dept of 79/07/02 2pp
- 7907240162 Executive Branch position re Westinghouse application for license to export reactor pressure tubes & components to Argentina License should be granted  
NOSENZO, L V State, Dept of 79/07/02 2pp
- 7907240177 Executive Branch position re Hoke, Inc application for license to export bellows sealed instrument isolating valves to Argentina License should be granted  
NOSENZO, L V State, Dept of 79/07/02 2pp
- 7907240190 Application by Westinghouse for license to export two fission chambers to France  
POCHAL, W E Westinghouse Electric Corp 79/05/16 1pp
- 7907240205 Forwards application to export U as U-hexafluoride, for use in fabrication of reload fuel, to Sweden.  
HARMON, D W Edlow International Co 79/06/26 1p
- 7907240209 Application by Edlow Intl Co for license to export U as U-hexafluoride, for use in fabrication of reload fuel, to Sweden  
HARMON, D W Edlow International Co 79/06/26 1p
- 7907240213 Forwards application to export enriched U-hexafluoride to Japan Use not specified  
MONDEN, T Mitsui & Co, Ltd 79/06/21 1p
- 7907240218 Application by Mitsui & Co for license to export enriched U-hexafluoride to Japan Use not specified  
MONDON, T Mitsui & Co, Ltd 79/06/21 1p
- 7907240223 Forwards application to export 30 mCi of Pu-238, for use in analysis of carbon & alloy steels, to Canada  
HENDRICK, W G Ramsey Engineering Company T-1482 79/06/21 1p
- 7907240277 Application by Ramsey Engineering Corp, TX Nuclear Div, for license to export 30 mCi Pu-238, for use in analysis of carbon & alloy steels, to Canada.  
HENDRICK, W G Ramsey Engineering Company 79/06/21 1p
- 7907240280 Forwards application to export U-dioxide pellets, to be assembled in fuel rods, to Spain  
KEENAN, R P Westinghouse Electric Corp 1CS-8821 79/06/21 1p.
- 7907240284 Application by Westinghouse for license to export U-dioxide sintered pellets, encapsulated in sealed fuel rods & assembled in fuel assemblies, to Spain  
KEENAN, R P Westinghouse Electric Corp 1CS-8821 79/06/21 1p.
- 7907240289 Application by Mitsubishi Intl Corp for license to export 500 mCi Cf-252, for use as primary neutron source rods, to Japan  
TANAKA, N Mitsubishi International Corp (subs of Mitsubishi Corp) 64-714L-8 79/06/15 1p
- 7907240292 Application by Hoke, Inc for license to export 1.5 inch bellow sealed control valve, for use in D-2-O collection tank level control, to Canada.  
LINDNER, T P Hoke, Inc 79/06/20 1p
- 7907240294 Application by Hoke, Inc for license to export 1.5-inch bellow sealuu control valves, for use in D-2-O collection tank level control, to Canada  
LINDNER, T P Hoke, Inc 79/06/20 1p
- 7907240465 Executive Branch position re World Wide Import/Export Svc, Ltd application for license to export one uncompensated & one compensated ionization chamber to Brazil Ltr of assurance encl. License should be granted  
NOSENZO, L V State, Dept. of. 79/06/21 3pp
- 7907240488 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl  
PETERSON, M R Assistant Director for Export/Import & International Safeguards. 79/06/22 1p
- 7907250017 Application by Chase Nuclear Div for license to export one Zircaloy-2 extruded tube to South Korea  
Chase Brass & Copper Co, Inc (subs of Kennecott Copper Corp) 79/05/29 1p
- 7907250033 Application by Westinghouse for license to export two compensated ionization chambers & two fission counters to The Netherlands  
SCHNAUTZ, C E Westinghouse Electric Corp 79/06/13 1p
- 7907250038 Amend 1 to NUS Corp export license, deleting Republic of China as ultimate consignee  
SHEA, J R Office of International Programs 79/06/13 1p
- 7907250053 Requests extension of expiration dates for Licenses XSNM-937 & XSNM-1072 to 800601 & 800701, respectively  
MATSON, V Transnuclear, Inc 79/05/30 1p
- 7907250053 Requests extension of expiration dates for Licenses XSNM-937 & XSNM-1072 to 800601 & 800701, respectively  
MATSON, V Transnuclear, Inc 79/05/30 1p
- 7907250074 Executive Branch position re GE application for license to export 796 kg U-235, contained in 29,526 kg U as U oxide powder enriched to max 3.65%, to Japan License should be granted  
NOSENZO, L V State, Dept of 79/06/22 3pp
- 7907250088 Amend 1 to Edlow Intl Co export license, replacing Republic of China w/Taiwan as ultimate consignee  
SHEA, J R Office of International Programs 79/06/13 1p
- 7907250096 Amend 1 to GE export license, deleting Republic of China as ultimate consignee  
SHEA, J R Office of International Programs 79/06/13 1p
- 7907250101 Amend 1 to Westinghouse export license, deleting Republic of China as ultimate consignee  
SHEA, J R Office of International Programs 79/06/13 1p
- 7907250108 Amend 2 to Mitsubishi Intl Corp export license, increasing enrichment of matl to be exported to 3.1637% w/o max  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/15 1p
- 7907250113 Amend 1 to Mitsubishi Intl Corp export license, increasing amount of matl for export to Japan from 1.2 to 1.2214 g U-235  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/15 1p
- 7907250235 Amend 1 to license for Edlow Intl Co to import U from South Africa Amend changes expiration date to 811231  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/29 1p
- 7907250236 Application by Mitsui & Co, Inc for license to export Zircaloy-2 tube shells to Japan  
MONDEN, T Mitsui & Co, Ltd 79/06/27 1p
- 7907250238 Forwards application for license to export 30 assembled projectiles to France  
TARAS, D N Army, Dept of 79/06/29 1p
- 7907250240 Application by US Army Tank Main Armament Sys for license to export cartridges containing one metallic depleted U penetrator to France  
LOOAN, J A Army, Dept. of. 79/06/25 1p
- 7907250242 License for Hoke, Inc to export bellows-sealed instrument isolating valves to Canada  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/05 1p.
- 7907250422 Amend 1 to GE export license, reflecting change in name of ultimate consignee  
Assistant Director for Export/Import & International Safeguards 79/06/27 1p
- 7907250431 Amend 1 to GE export license, extending expiration date from 790801 to 810801.  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/27 1p
- 7907250546 Amend 6 to GE Technical Svc Co, Inc export license, extending expiration date to 810801  
PETERSON, M R Assistant Director for Export/Import & International Safeguards. 79/06/27 1p

7907230572 Responds to FOIA request for all documents re facility & Applications XR-120, XCOM-13 & XSNM-1471 Three documents withheld (ref FOIA Exemption 1)  
FELTON, J M Division of Rules and Records 79/07/06 3pp

7907230572 Responds to FOIA request for all documents re facility & Applications XR-120, XCOM-13 & XSNM-1471 Three documents withheld (ref FOIA Exemption 1).  
FELTON, J M Division of Rules and Records 79/07/06 3pp

7907260023 Executive Branch position re Byron Jackson Pump Div application for license to export parts for primary coolant pumps to Japan License should be granted  
NOSENZO, L V State, Dept of 79/06/15 2pp

7907260191 License for Radium Chemical Co to export 110,000 Ci tritium in gaseous form to Switzerland  
OPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/06/01 2pp

7907260203 Amend 1 to Bach Mai Hosp Emergency Relief Fund, Inc export license, extending expiration date to 800601  
OPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/06/01 1p

7907260353 Executive Branch position re Mitsubishi Intl Corp application for license to export 40 37 g U, containing 0 23 g U-235 for centrifuge R&D, to Japan Ltr of assurance encl License should be granted.  
NOSENZO, L V State, Dept of 79/06/22 3pp

7907260363 Executive Branch position re Metal Bellows Corp application for license to export specially designed & prepared flexible metal hose to Spain License should be granted  
NOSENZO, L V State, Dept of 79/06/22 2pp

7907260365 Executive Branch position re Westinghouse application for license to export 25,005 kg U-235, in 727,175 kg enriched to max of 3 5%, to South Korea Ltr of assurance encl License should be granted.  
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 79/06/11 3pp

7907260369 Executive Branch position re Westinghouse application for license to export nuclear reactor components to Switzerland License should be granted  
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 79/06/11 2pp

7907260372 Executive Branch position re GE application for license to export thermal sleeves for use in reactors to India License should be granted  
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 79/06/11 2pp

7907260552 Executive Branch position re Transnuclear, Inc application for license to export 438 25 kg U-235, contained in 14,1 kg U enriched to 3 25%, to Sweden Recommends license be issued Forwards ltr of assurance.  
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 79/06/06 4pp

7907260555 Executive Branch position re United Kingdom Treasury & Supply Delegation application for license to export 780 kg depleted U to United Kingdom Recommends license be issued  
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 79/06/06 2pp

7907260591 Application by Isotope Products Labs for license to export 50 microcuries Po-210, contained in Model AR-1, & 50 microcuries Ca-252, contained in Model FF-252, to Argentina  
AMLAUER, K Isotope Products Laboratories 79/06/20 1p

7907260852 License for Edlow Intl Co to export 10,000 kg U as depleted U to Taiwan  
SHEA, J R Assistant Director for Export/Import & International Safeguards 79/06/08 2pp

7907260913 Executive Branch position re OA Co application for license to export instrumentation replacements for research reactor to Philippines License should be granted Ltr of assurance encl  
NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 79/06/11 3pp.

7907270107 Submits application to amend licenses to reflect shipment to Canada  
HENDRICK, W O Ramsey Engineering Company. 79/06/12 1p

7907270107 Submits application to amend licenses to reflect shipment to Canada.  
HENDRICK, W O Ramsey Engineering Company 79/06/12 1p

7907270107 Submits application to amend licenses to reflect shipment to Canada  
HENDRICK, W O Ramsey Engineering Company 79/06/12 1p.

7907300005 License for GE to export 4500 kg U-235 to Taiwan  
OPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/06/08 2pp

7907300006 License for Westinghouse to export two PWRs w/thermal power of 2,785 MW each, plus components & associated equipment from listed categories, to Taiwan  
OPLINGER, G O Assistant Director for Export/Import & International Safeguards 79/06/08 3pp

7907300025 Submits application for Amend & to export license, extending expiration date to 810801  
WILSON, B D General Electric Co, Nuclear Energy Products Div 79/06/18 1p

7907300162 Corrects max enrichment figures License XSNM-1426 should be 2 55%, License XSNM-1432 should be 3 95% & License XSNM-1436 should 3 1%  
MIYABAYASHI, M Japan. 79/06/15 1p

7907300162 Corrects max enrichment figures License XSNM-1426 should be 2 55%, License XSNM-1432 should be 3 95% & License XSNM-1436 should 3 1%  
MIYABAYASHI, M Japan 79/06/15 1p

7907300162 Corrects max enrichment figures License XSNM-1426 should be 2 55%, License XSNM-1432 should be 3 95% & License XSNM-1436 should 3 1%  
MIYABAYASHI, M Japan 79/06/15 1p

7907300165 Ltr of assurance for Westinghouse to export 3 36 g U-235, contained in 3 62g U, to France  
ODPEL, M European Communities, Commission of 79/06/18 1p

7907300172 Application by Westinghouse to amend license to export 3 36g U, contained in 3 62 g U-235 enriched 93%  
SCHANUTZ, C E Westinghouse Electric Corp 79/06/12 1p

7907300294 Ltr of assurance re Westinghouse applications to export 0 004 g U-235 to Sweden  
HANJUSEN, C Sweden 79/06/15 1p

7907300294 Ltr of assurance re Westinghouse applications to export 0 004 g U-235 to Sweden  
HANJUSEN, C Sweden 79/06/15 1p

7907300304 Ltr of assurance re Edlow Intl application to export 0 09 microgram Pu-242 to Sweden  
HANJUSEN, C. Sweden 79/06/15 1p

7907310037 Application by Edlow Intl Co for license to export 3 units of NBS Std BRM4334 & 0 9 micrograms Pu-242, contained in 12-g solution of 5 molar nitric acid, to Sweden  
HARMON, D W Edlow International Co 79/06/28 2pp.

7907310040 Application by Sigma Chemical Co for license to export 5 kg deuterium liquid over 2-yr period to Australia  
STERN, W C Sigma Chemical Co (subs of Sigma Aldrich Corp.) 79/06/29 1p

7907310047 License for Sandvik Special Metals Corp to export 2,100 pieces of Sandvik Zircaloy-2 seamless fuel cladding to Sweden  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/06 1p

7907310052 License for Westinghouse to export reactor control drive mechanisms, reactor internals & other parts to Spain  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/06 1p

7907310058 License for OA Co to export 1 72 g U-235, contained in 1 84 g U, enriched to 93% w/o max, as fission counter, to Philippines.  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/07/06 2pp

7907310103 Ltr of assurance for Reuter-Stokes, Inc to export radiation detector containing 0 0004 g U-235, in 0 0004 g U enriched to 93%, to West Germany  
ODPEL, M European Communities, Commission of 79/06/18 1p.

7907310113 Ltr of assurance for Transnuclear, Inc to export 0 237 kg U-235, contained in 23,611 kg U, to France  
ODPEL, M European Communities, Commission of 79/06/18 1p.

7907310114 Confirms addition of Hitachi America, Ltd as addl party to export license No license amend required  
PETERSON, M R Assistant Director for Export/Import & International Safeguards 79/06/20 1p

7907310154 Amend 2 to Eastman Kodak Co export license, extending expiration date until 800701  
OPLINGER, G G Assistant Director for Export/Import & International Safeguards STB-8274 79/06/01 1p

7907310301 Forwards 790613 telex reply re end use statement for depleted U, in response to 790605 request  
HATSDON, V Transnuclear, Inc 78-357/01 79/06/13 2pp

7907310353 Discusses Executive Branch views on application by United Kingdom Treasury & Supply Delegation to export 750 kg depleted U to United Kingdom for research into use of high density high strength matl in mfg penetrators  
MOORE, R N Assistant Director for Export/Import & International Safeguards 79/06/20 1p

7907310361 Discusses Executive Branch views on Transnuclear, Inc application to export 14,101 kg of U enriched to 3 25% U-235, to Sweden for use in nuclear plant License should be granted  
MOORE, R N Assistant Director for Export/Import & International Safeguards 79/06/20 1p

7907310573 FOIA request for all documents re facility & applications XR-120, XCOM-13, & XSNM-1471  
ASHER, T R Asher, T R PC 79/05/14 5pp

7907310573 FOIA request for all documents re facility & applications XR-120, XCOM-13, & XSNM-1471  
ASHER, T R Asher, T R PC 79/05/14 5pp

7907310608 Executive Branch position re JT Baker Chemical Corp application for license to export 14 03 lb depleted U, contained in 25 lb uranyl acetate, to Mexico License should be granted  
NOBENZO, L V State, Dept of 79/06/15 2pp



# PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ABBOTT, W B	7907110553	50-471 0	ANDERSON, T. M	7907130239	TOPREP
ABBOTT, W B	7907180324	50-471 0	ANDERSON, T. M	7907200299	TOPREP
ABBOTT, W B	7907190738*	50-471 0	ANDERSON, T. M	7907200392	TOPREP
ABEL, J	7907190005	FOIA	ANDERSON, P. L	7907110566*	50-309 B
ABEL, J	7907060146	FOIA	ANDERSON, C. R	7907060490*	50-244 0
ADAMS, M B	7907300395*	50-358 F	ANDERSON, D. 0	7907110069*	0A999
ACKERMANN, N. J	7907110218	50-320 P	ANDERSON, D. 0	7907030032*	0A999
ADAM, P. J	7907050097*	0A999	ANDERSON, D. 0	7907230736*	0A999
ADAM, P. J	7907050093*	0A999	ANDERSON, N	7907120739	FOIA
ADAMS, G. D	7907310056	PR	ANDERSON, C. J	7907130018	50-322 A
ADAMS, B	7907160045	COMMISSION	ANDERSON, C. J	7907180415	50-322 A
ADAMS, W. E	7907170178	50-255 R	ANDERSON, C. J	7907090251	50-322 A
ADAMS, J	7907310473*	50-346 B	ANDERSON, C. J	7907250063	50-322 A
AGE, J. R.	7907130372*	0A999	ANDERSON, C. J	79072300171	50-322 A
AGEE, J. R.	7907260158*	0A999	ANDERSON, C. J.	7907250097	50-387 A
AGRAWAL, A. K	7907240085	NUREG	ANDOGNINI, 0. C	7907020221	50-293 J
AGRAWAL, A. K	7907310149	REB	ANDOGNINI, 0. C	7907200444*	50-293 0
AHEARNE, J. F	7907180757*	FOIA	ANDOGNINI, 0. C	7907190680	50-293 0
AHEARNE, J. F	7907180229	10CFR	ANDOGNINI, 0. C	7907100647	50-293 0
AHEARNE, J. F	7907160255	10CFR	ANDOGNINI, 0. C	7907190396	50-293 P
AHEARNE, J. F	7907160172	10CFR	ANDOGNINI, 0. C.	7907240253	50-293 F
AHRENDT, D	7907250394	50-269 V	ANDOGNINI, 0. C.	7907260708	50-293 H
AHUJA, M	7907190719	PR	ANDREWS, R. D	7907240331	40-8452
ALAVI, A	7907190635	PRM	ANDREWS, R. D	7907100036	40-8452
ALBERT, W. G	7907260649*	50-361 0	ANDREWS, R. L	7907230533	50-285 B
ALDAKER, V	7907100656	50-358 0	ANDREWS, D. L	7907160268*	70-143
ALDEN, W. M	7907130431*	50-277 R	ANDREWS, D. L	7907110598*	50-400 0
ALDEN, W. M	7907260632	50-171 R	ANDREWS, D. L	7907100482	50-320 H
ALDERMAN, H.	7907110076	50-320 0	ANG, W. P	7907190149*	50-413 0
ALDERMAN, H.	7907110101	50-320 P	ANG, W. P	7907110743*	50-339 0
ALDRICH, H. N	7907020506*	50-309 H	ANG, W. P.	7907110657*	50-413 0
ALEXANDERSON, E.	7907300375*	50-16 R	ANG, W. P.	7907250106*	50-348 0
ALEXANDER, D. R	7907250332	50-267 P	ANG, W. P.	7907260076*	50-287 0
ALLEN, B	7907060157	70-1193	ANGELO, J.	7907180913	0EN TEC 1B
ALLEN, J	7907180827*	50-338 0	ANNO, G. H	7907180162	FOIA
ALLEN, T. A	7907190704	PR	ANNO, G. H	7907180168	FOIA
ALLEN, B. W	7907050032	71-178	APPENDIX, C. E.	7907120156	NUREG
ALLEN, O. W.	7907190344	WASTE MGT	ARCHITZEL, R	7907230479*	50-220 0
ALLEN, P. B	7907170222*	50-321 R	ARLOTTO, G. A	7907120040	REG00
ALMEYER, F. M.	7907230226*	50-295 0	ARMAND, M. P.	7907160034*	50-389 0
ALTON, C. 0	7907130103	PR	ARMSTRONG, W. H	7907020011	PROJ
ALTON, C. 0.	7907090357	50-293 0	ARNOLD, R. C	7907180041*	50-320 T
ALTON, C. 0	7907250315	50-219 J	ARNOLD, J. M.	7907110350	50-320 0
AMLAUER, K.	7907190855*	XPORTLIC	ARTHUR, J. E	7907110302	50-485 0
AMLAUER, K.	7907260591	XPORTLIC	ARTHUR, J. E	7907180110	50-485 0
AMHERMANN, E. G.	7907190733	PR	ARTHUR, J. E.	7907020487	50-485 0
ANAGBA, H. D.	7907300249*	FOIA	BEHNSAUGH, C. E	7907090046	50-142 P
ANAGBA, H. D.	7907300168*	FOIA	ASHENDEN, M. C	7907300018*	50-338 0
ANAGBA, H. D.	7907300268*	FOIA	ASHENDEN, M. C.	7907190078*	50-280 0
ANDERSON, L. P.	7907290582*	27-47	ASHENDEN, M. C	7907100541	50-320 H
ANDERSON, T. M.	7907020130*	50-320 P	ASHER, T. R	7907310573	50-574 A
ANDERSON, T. M.	7907020330	FOIA	ASWELL, D. L	7907110677*	50-382 0
ANDERSON, T. M.	7907290134	REG00	ASWELL, D. L	7907240118*	50-382 0
ANDERSON, T. M.	7907060279	TOPREP	ASWELL, D. L.	7907260063	50-382 0
ANDERSON, T. M.	7907100574	TOPREP			

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ASHELL, D L	7907240070	50-382 Q	BANKS, H R	7907060403	50-324 S
ASWELL, D L	7907090227	50-382 S	BANKS, H R	7907060405	50-324 S
ASWELL, D L	7907240621	50-382 S	BANKS, H R	7907060406	50-325 S
ASWELL, D L	7907200249	50-382 A	BANKS, H R	7907060408	50-325 S
ASWELL, D L	7907240214	50-382 F	BANKS, H R	7907090229	50-324 S
ASWELL, D L	7907240346	50-382 K			
ASWELL, D L	7907240349*	50-382 K	BANKS, H R	7907100357	50-261 S
ATKINSON, J B	7907180363	50-466 Q	BANKS, H R	7907190480	50-325 S
ATKINSON, S A	7907090443	RES	BANKS, H R	7907130339	50-325 S
ATKINS, H L	7907200507	PRM	BANKS, H R	7907130340	50-325 S
AUDETTE, R F	7907260503	50-320 H	BANKS, H R	7907130451	50-261 R
AUSTIN, H A	7907050475	70-135			
AUSTIN, H A	7907060504	70-344	BANKS, H R	7907160360	50-324 S
AUSTIN, H A	7907180891	71-4949	BANKS, H R	7907160392	50-324 S
AUTIO, H A	7907100485	50-29 S	BANKS, H R	7907160371	50-324 S
AUTIO, H A	7907100493	50-29 S	BANKS, H R	7907190373	50-324 S
			BANKS, H R	7907190531	50-324 S
AXELROD, M	7907130081	50-344 Q			
AXELROD, M	7907180739	50-344 Q	BANKS, H R	7907230315	50-325 S
AXELSON, W L	7907300412*	50-305 Q	BANKS, H R	7907230551	50-324 S
AXELSON, W L	7907300194*	50-266 Q	BANKS, H R	7907230588	50-324 S
AXELSON, W L	7907100405	50-320 H	BANKS, H R	7907240357	50-325 S
			BANKS, H R	7907230325	50-325 S
AXELSON, W L	7907250282*	50-409 Q			
AYCOCK, M	7907100026	50-320 P	BANKS, H R	7907240348	50-261 S
AYCOCK, M	7907070092	50-320 P	BANKS, H R	7907240366	50-324 S
AYCOCK, M	7907100031	50-320 P	BANKS, H R	7907300423	50-324 S
AYER, J E	7907180894	70-1257	BANNISTER, R W	7907190079*	50-309 H
			BANWARTH, C S	7907050362	OR9
AYRES, G W	7907250037*	50-272 H			
BABBITT, B	7907180085	50-320 T	BARD, L	7907090328	50-592 Q
BABBITT, B	7907180077	50-320 T	BARI, R A	7907310133	RES
BABBITT, B	7907180092	50-320 T	BARKER, J L	7907190507*	50-110 Q
BABBITT, B	7907180106	50-320 T	BARKER, J L	7907300486	50-237 Q
			BARKER, J L	7907260822*	50-237 Q
BABBITT, B	7907180109*	50-320 T			
BABBITT, B	7907180022	50-320 T	BARLETT, R M	7907050471	50-471 H
BABBITT, B	7907180013	50-320 T	BARRETT, P. A	7907230746*	50-456 Q
BABBITT, B	7907180073	50-320 T	BARRETT, L	7907160222	50-320 P
BABBITT, B	7907180003	50-320 T	BARRETT, L	7907160099	50-320 P
			BARTELLS, P B	7907260674	50-320 P
BACHNER, D	7906210421*	50-466 Q			
BACKUS, R A	7907100719*	50-443 Q	BARTH, C A	7907090461	50-255 Q
BACON, J L	7907090366	50-329 K	BARTH, C A	7907200222	50-255 Q
BACON, J L	7907170006	50-329 C	BARTH, C A	7907060383	50-580 Q
BAER, R L	7906270273	OR0	BARTLETT, J	7907020491	50-410 Q
			BASDEKAB, D L	7907090441	50-320 H
BAER, R L	7907110164	50-445 A			
BAER, R L	7907190008	50-437 A	BASDEKAB, D L	7907160200	50-320 Q
BAER, R L	7907180892	50-445 A	BASKIN, K P	7907310531	50-361 Q
BAER, R L	7907180912	TOPREP	BASKIN, K P	7907090238	50-361 Q
BAER, R L	7907270389	50-445 A	BASKIN, K P	7907090235	50-361 Q
			BASKIN, K P	7907050378	50-361 A
BAILEY, R	7907130163*	50-184 Q			
BAILEY, R J	7907270386*	50-220 Q	BASKIN, K P	7907100602	50-206 S
BAIR, G G	7907120613*	50-344 R	BASKIN, K P	7907100629	50-206 P
BAIRD, J B	7907260534*	50-206 Q	BASKIN, K P	7907260666	50-361 A
BAIRDEN, L	7907300557	CONTRACT	BASKIN, K P	7907190549	50-206 P
			BASSIN, N	7907050074*	70-364
BAISDEN, L	7907300564	CONTRACT			
BAKER, D C	7906210234*	50-397 A	BATCH, S N	7907100444*	50-346 S
BAKER, C E	7907020464	40-8681	BATES, E F	7907310393*	50-128 R
BAKER, C E	7907030221	40-8681	BATES, R W	7907230487*	50-336 S
BAKER, K R	7907020115*	50-346 Q	BATES, R W	7907260592*	50-336 S
			BATES, A	7907100200	50-269 P
BAKER, K R	7907270407*	50-315 Q			
BAKER, R E	7907190301	50-320 H	BATES, A	7907090456	50-320 P
BALD, C E	7907230059*	QA999	BATES, A	7907110214	50-320 Q
BALDWIN, W A	7907130347	50-275 Q	BATES, A	7907110525	50-320 Q
BALLARD, R L	7901110268	50-437 D	BATES, J W	7907200054*	70-1113
			BATES, J W	7907200074*	70-1113
BALLARD, R L	7907020495	50-568 A			
BALLARD, R L	7907130015	50-327 A	BATSON, D M	7907020483	70-2909
BALLARD, R L	7907130019*	50-327 A	BAUMAN, R	7907300384	FOIA
BALLARD, R L	7907130086	50-568 D	BAUNACK, W H	7907310017*	50-213 Q
BALLARD, R L	7907250193	50-568 D	BAUNACK, W H	7907100486	50-320 H
			BAUSER, M A	7907110668	50-250 Q
BALLARD, R L	7907250198	50-568 D			
BALLARD, R L	7907250199	50-568 D	BAUSER, M A	7907190472	50-250 Q
BALLARD, R L	7907250201	50-568 D	BAXLEY, S X	7907020264*	50-366 S
BALLARD, R L	7907250202	50-568 D	BAXLEY, S X	7907050376*	50-366 S
BALLARD, R L	7907250203	50-568 D	BAXLEY, S X	7907170105*	50-366 S
			BAXLEY, S X	7907170096*	50-366 S
BALLARD, R L	7907250205	50-568 D			
BALLARD, R L	7907250207	50-568 D	BAYNARD, P Y	7907250062	50-302 P
BALLARD, R L	7907250208	50-568 D	BAYNARD, P Y	7907250062	50-302 P
BALLARD, R L	7907250210	50-568 D	BAYNE, J P	7907120030	50-286 Q
BALLARD, R L	7907060427	50-358 D	BAYNE, J P	7907050249	50-286 Q
BALLARD, R L	7907110023	50-599 A	BAYNE, J P	7907190861	50-286 Q
BALLARD, R L	7907310162	50-437 A	BAYNE, J P	7907100423	50-286 S
BALLOUGH, R C	7907050444	50-445 M	BAYNE, J P	7907170007	50-286 R
BALSLEY, J R	7907110737	50-344 H	BEACH, A B	7907110747*	50-482 Q
BALZER, J L	7907260585	PR	BEACH, A B	7907310126*	50-466 Q
BANKS, H R	7907110543	50-325 S	BEAN, J	7907190055*	50-309 H
BANKS, H R	7907110470	50-325 S	BEAN, L B	7907060360*	50-295 Q
BANKS, H R	7907240413*	50-324 Q	BEARD, J T	7907120642	50-320 P
BANKS, H R	7907050310	50-325 S	BEARD, J T	7907120643	50-320 P
BANKS, H R	7907060284	50-325 P	BEATON, R H	7907060211	70-1113
			BEATON, R H	7907060223	70-1308

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BEATON, R. H.	7907180771	70-754	BIRKEL, R. A.	7907300290	50-437 Q
BÉCHET, L. J.	7907310090*	CONTRACT			
BECHHOEFER, C.	7907260761	50-387 Q	BISCHOFF, C. A.	7907050371	50-592 Q
BECHHOEFER, C.	7907100674	50-498 Q	BISCHOFF, C. A.	7907060038	50-592 Q
BECHHOEFER, C.	7907130067	50-358 Q	BISCHOFF, C. A.	7907180119	50-592 Q
BECHHOEFER, C.	7907180596	50-387 Q	BISCHOFF, C. A.	7907180313	50-592 Q
BECHHOEFER, C.	7907090099	50-358 T	BISCHOFF, C. A.	7907180078	50-592 Q
BECHHOEFER, C.	7907030265	50-358 T			
BECHHOEFER, C.	7907030388	50-358 T	BISCHOFF, C. A.	7907020006	50-592 Q
			BISCHOFF, C. A.	7907190706	50-592 Q
BECHHOEFER, C.	7907120294	50-358 T	BISCHOFF, C. A.	7907190483	50-592 Q
BECHHOEFER, C.	7907120170	50-358 T	BISHOP, T. A.	7907190711	NUREG
BECHHOEFER, C.	7907120303	50-358 T	BISHOP, C. J.	7907180714	50-338 Q
BECHHOEFER, C.	7907120400	50-358 T			
BECHHOEFER, C.	7907120158	50-358 T			
BECHHOEFER, C.	7907120446	50-358 T	BISHOP, C. J.	7907240382	50-485 Q
BECHHOEFER, C.	7907120449	50-358 T	BISHOP, T. W.	7907030094*	50-397 Q
BECKMAN, D. A.	7907100558	50-320 H	BISHOP, T. W.	7907050372*	50-397 Q
BECKEL, R. H.	7907250026	50-382 Q	BISHOP, T. W.	7907110634*	50-397 Q
BEDNAR, L.	7907170061*	50-298 S	BISHOP, T. W.	7907260587*	50-397 Q
BEELER, T.	7907170034*	50-346 S	BISSELT, F. J.	7907030418	50-334 R
BEHLING, B. R.	7907300464	50-320 P	BISSELT, P. H.	7907180734*	70-820
BELANGER, J. L.	7907300285*	50-243 Q	BISSET, P.	7907200490*	70-820
BELEM, Q. L.	7907100544*	50-390 Q	DIVANS, E. L.	7907140034*	50-359 Q
BELEM, Q. L.	7907100569*	50-390 Q	DIVENS, W. B.	7907090003*	50-522 Q
BELGRAIR, D. P.	7907240103	XPORTLIC	BIXEL, D. A.	7907190289	50-155 Q
BELISLE, Q. A.	7907020108*	50-269 Q	BIXEL, D. A.	7907160234	50-155 Q
BELL, J. R.	7907110429	TOPREP	BIXEL, D. A.	7907190239	50-155 Q
BELLMON, H.	7907310556*	COMMISSION	BIXEL, D. A.	7907240324	50-155 Q
BELLMAN, T. P.	7907190520*	50-315 S	BIXEL, D. A.	7907270215	50-155 Q
BELLMAN, T. P.	7907190537*	50-316 S	BIXEL, D. A.	7907260727	50-155 P
BENDER, M.	7907100223	50-320 Q	BLACK, R. L.	7907020494	50-522 Q
BENDER, M.	7907130519*	50-320 Q	BLACK, R. L.	7906260534	50-522 Q
BENDER, M.	7907190562	ACRB			
BENDER, M.	7907120338	ACRB	BLACK, R. L.	7906260536	50-522 Q
			BLACK, R. L.	7907090001	50-522 Q
BENDER, M.	7907230654	ACRB	BLACK, R. L.	7907020025	70-1308
BENEDICT, R. A.	7907240424	50-363 A	BLACK, R. L.	7907020029*	70-1308
BENEDICT, R. A.	7907240620	50-362 A	BLACK, R. L.	7907190660	70-1308
BENICOFF, P. A.	7907230403	NUREG	BLACK, R. L.	7907190611	50-522 Q
BENNETT, N. J.	7907130495	50-599 Q	BLACK, R. L.	7907260490	50-522 Q
BENNETT, N. J.	7907130505*	50-599 Q	BLADROVE, N.	7907300577	50-338 Q
BENNETT, N. J.	7907190339	50-599 Q	BLAKE, J. J.	7907180801*	50-395 Q
BENNETT, N. J.	7907190716	50-599 Q	BLAKE, J. J.	7907190319*	50-416 Q
BENNETT, N. J.	7907190784*	50-599 Q			
BENSON, Q. J.	7907100627*	50-128 I	BLAKE, J. J.	7907260542*	50-348 Q
			BLAND, W. H.	7907240507	FRM
BERATAN, L. L.	7907110645*	50-338 Q	BLATT, M.	7907050337	50-3 P
BERATAN, L. L.	7907110654*	50-338 Q	BLEVINS, W. E.	7907270167	FR
			BLIVEN, Q. F.	7907180870	50-568 H
BERGERON, D. A.	7907230166	PR	BLUCK, J. A.	7907050520	RES
BERGHUIS, F. C.	7907120299	50-518 S	BLUCK, L. K.	7907050499	71-114
BERKSON, H.	7907020439	50-320 P			
BERKY, J. J.	7907300574	PR	BLUM, S.	7907190058	70-2623
BERNARD, B. R.	7907190501	NUREG	BODINE, J.	7907160404*	50-244 S
BEVAN, R. B.	7907130054	50-324 P	BODTKE, P. J.	7907170181*	50-235 R
BEVAN, R. B.	7907190266	50-254 Q	BDEGLI, J. B.	7907260120	50-369 A
BEVAN, R. B.	7907110745	50-324 Q	BQEHL, D. J.	7907240330	50-344 P
BEVAN, R. B.	7907310218	50-324 Q	BQENERT, P.	7907110020	50-320 Q
BEVAN, R. B.	7907260645	50-254 P	BQODEN, Q.	7907310150	40-1162
BEVAN, R. B.	7907300341	50-254 P			
BICKWIT, L.	7907100287	50-320 Q	BQODEN, Q.	7907030290	40-1162
BICKWIT, L.	7907090013*	10CFR	BQOOS, R.	7907190160*	50-352 A
			BQOIN, M. B.	7907310573	50-374 A
BICKWIT, L.	7907100181	50-320 J	BQHN, R. J.	7907060232	50-367 R
BICKWIT, L.	7907100133	50-320 Q	BQHN, R. J.	7907120587	50-367 R
BICKWIT, L.	7907160047	COMMISSION	BQHN, R. J.	7907230566	50-367 R
BICKWIT, L.	7907230178	COMMISSION	BQHN, R. J.	7907270245	50-367 R
BIDDLE, C. T.	7907110353*	50-466 Q	BQHN, M. P.	7907270388	NUREG
BIDDLE, C. T.	7907130546	50-466 Q	BOLLMAN, C. T.	7907090295	50-320 J
BIDDLE, C. T.	7907130560	50-466 Q	BOLZ, R. E.	7907200311	50-134 P
BIDDLE, C. T.	7907190701	50-466 Q	BONTINE, J. E.	7907060073	FDIA
BIDDLE, C. T.	7907190419	50-466 Q	BONNER, J. F.	7907130118*	50-275 Q
BIDDLE, C. T.	7907230098	50-466 Q	BONNER, J. A.	7907260832	CONTRACT
BIDDLE, C. T.	7907200497	50-466 Q	BOOK, H. E.	7907300260*	70-25
BIEL, W. A.	7907110139	50-320 P	BOOK, H. E.	7907300245	70-25
BIELAWSKI, A. P.	7907180346	50-295 Q	BOOK, H. E.	7907260543	50-275 Q
BIELAWSKI, A. P.	7907060344	50-295 Q			
BIELAWSKI, A. P.	7907180828	50-436 Q	BOOK, H. E.	7907260549*	50-275 Q
			BOOK, H. E.	7907180261*	70-754
BIELAWSKI, A. P.	7907180844	50-454 Q	BOOK, H. E.	7907180243	70-754
BIERMAN, S. R.	7907310595	RES	BOOK, H. E.	7907260528	50-206 Q
BIGALOW, E.	7907060419*	COMMISSION	BOOK, H. E.	7907260534*	50-206 Q
BIRKEL, R. A.	7907060247	50-369 A	BORDENICK, B. M.	7907160131	50-277 Q
			BORDENICK, B. M.	7907060522	50-582 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BORDENICK, B M	7907160196	50-516 Q	BRUDSKY, A	7907120743	50-320 P
BORDENICK, B M	7907180168	50-277 Q	BROEHL, D J	7907050400	50-344 Q
BORER, P J	7907170234*	50-298 R	BROEHL, D J	7907090144	50-344 Q
BORGSMANN, E A	7907130153	50-358 Q	BROEHL, D J	7907170175	50-344 P
BORGSMANN, E A	7907190151	50-358 Q	BROOKS, E H	7907230740*	50-338 Q
BORGSMANN, E A	7907090425	50-358 Q	BROOKS, W L	7907310163*	TOPREP
BORGSMANN, E A	7907190687	50-358 Q	BROUGHTON, P L	7907230162	PR
BORGSMANN, E A	7907170084	50-358 K	BROUGHTON, J M	7907270400	NJREQ
BORGSMANN, E A	7907300387	50-358 F	BROWN, W P	7907030141*	50-320 P
BORGSMANN, E A	7907230491	50-358 K	BROWN, P D	7907060906	50-356 Q
BORGSMANN, E A	7907310429	50-358 A	BROWN, P D	7907160169	50-356 Q
BORING, J O	7907270158	PR	BROWN, D E	7907190800	PR
BORNS, H W	7907190833	NJREQ	BROWN, E O	7907060149*	50-275 W
BORYSIAK, M	7907100458*	50-346 S	BROWN, S C	7907020477	50-404 Q
BOSSENMAIER, W S	7907310352	50-312 P	BROWN, S C	7907100183	50-404 Q
BOSTIAN, R W	7907130273*	70-2623	BROWN, S C	7907100186	50-339 Q
BOUCHEY, Q D	7907120644	PROJ	BROWN, S C	7907100206	50-404 Q
BOUMNIGHT, J A	7907190435	50-445 H	BROWN, S C	7907190311	50-339 Q
BOUTIN, A	7907240434	50-373 E	BROWN, S C	7907190347	50-339 Q
BOUTON, D A	7907130331	50-338 Q	BROWN, S C	7907090399	50-339 S
BOUFON, D A	7907060444*	50-338 Q	BROWN, S C	7907080360	50-404 S
BOWEN, V T	7907230211	PR	BROWN, S C	7907120582	50-339 S
BOWERS, C E	7907060493	70-820	BROWN, S C	7907280326	50-339 S
BOWERS, C E	7907180698*	70-820	BROWN, S C	7907260406	50-338 F
BOWERS, E S	7907180645	50-322 Q	BROWNLEE, V L	7907240347*	50-339 Q
BOWERS, E S	7907240300	50-445 Q	BROWN, R A	7906200393	50-320 P
BOYD, D C	7907120166	50-320 H	BROWNLEE, V L	7907190078*	50-280 Q
BOYD, D C	7907180323*	50-295 Q	BROWN, O D	7906140594*	40-8006
BOYD, D C	7907240630*	50-305 Q	BROWN, O D	7906140884	40-8006
BOYD, D C	7907260264*	50-409 Q	BROWN, O D	7907090446*	50-313 Q
BOYD, D C	7907300479	50-155 Q	BROWN, O D	7907190049*	50-298 Q
BOYD, D C	7907100400	50-320 H	BROWN, O D	7907310574*	50-478 Q
BOYD, D C	7907240152*	50-266 Q	BROWN, O D	7907310552*	50-313 Q
BOYD, R S	7907160107	50-275 A	BROWN, R L	7907130349*	QA999
BOYD, R S	7907120226*	50-322 A	BROWN, R L	7907230308*	QA999
BOYD, R S	7907100691	50-275 A	BRUNGER, R M	7907050322	50-186 S
BOYD, R S	7907050029	50-495 A	BRUNNER, E J	7907200406*	50-37 Q
BOYD, R S	7907050034*	50-495 A	BRUNNER, E J	7907200453*	50-293 Q
BOYD, R S	7907110724	50-528 A	BRUNNER, E J	7907200501	50-289 Q
BOYD, R S	7907120333	50-275 H	BRUNNER, E J	7907200431	50-293 Q
BOYER, V S	7907230348*	50-352 Q	BRUNNER, E J	7907130226	50-387 Q
BOYER, V S	7907050468	50-352 Q	BRUNNER, E J	7907230549	50-272 Q
BOYER, V S	7907060244	50-352 Q	BRUNNER, E J	7907230471	50-220 Q
BOYER, V S	7907130316	50-352 Q	BRUNNER, E J	7907310115*	50-333 Q
BOYER, V S	7907190074	50-352 Q	BRUNNER, E J	7907110421	50-333 Q
BOZARTH, B	7907050447	71-156	BRUNNER, E J	7907110489	50-311 Q
BRADFORD, W H	7907100435	50-320 H	BRUNNER, E J	7907310011*	50-213 Q
BRADFORD, P A	7907270220*	COMMISSION	BRUNNER, E J	7907110534	50-272 Q
BRADFORD, P A	7907060147	50-309 H	BRUNNER, E J	7907180471	50-247 Q
BRADFORD, P A	7907190210	50-16 P	BRUNNER, E J	7907180430	50-286 Q
BRADFORD, P A	7907190219*	50-16 P	BRUNNER, E J	7907180441	50-336 Q
BRADFORD, P A	7907180742*	FOIA	BRUNNER, E J	7907110633	50-277 Q
BRADFORD, P A	7907030360	10CFR	BRUNNER, E J	7907200395	50-57 Q
BRADFORD, P A	7907130078	10CFR	BRUNNER, E J	7907310006	50-213 Q
BRADFORD, P A	7907100130*	50-320 T	BRYAN, J K	7907300316	50-483 Q
BRADFORD, P A	7907160229	10CFR	BRYAN, S E	7907100322*	50-320 Q
BRADFORD, P A	7907160246	10CFR	BRYAN, S E	7907050008	50-313 Q
BRADFORD, P A	7907030407	10CFR	BRYANT, J C	7907110743*	50-339 Q
BRADFORD, P A	7907030413	10CFR	BRYANT, J C	7907240227*	50-400 Q
BRADFORD, P A	7907170093	50-289 T	BRYANT, J C	7907110678*	50-338 Q
BRADLEY, F J	7907190766	PRM	BRYANT, J C	7907190121*	50-321 Q
BRADLEY, E J	7907130326	50-277 J	BRYANT, J C	7907190149*	50-413 Q
BRADLEY, E J	7907130374	50-171 J	BRYANT, J C	7907200250*	50-348 Q
BRADLEY, R D	7907080189*	50-400 Q	BRYANT, J C	7907130443*	50-318 Q
BRADY, W J	7907170199	50-374 A	BRYANT, J C	7907050157*	50-413 Q
BRAUN, D J	7907180609*	50-285 P	BRYANT, J C	7907230768*	50-390 Q
BREAUX, J	7907310253*	50-382 U	BRYANT, J C	7907110657*	50-413 Q
BREIT, D H	7907230299	PR	BRYANT, J C	7907090433*	50-491 Q
BRENNER, L	7907030131*	50-458 A	BRYANT, J C	7907240201*	50-390 Q
BRETTA, L F	7907120563	50-568 D	BRYANT, J C	7907110568*	50-413 Q
BRICKLEY, R H	7907050109*	QA999	BRYANT, J C	7907240163*	50-369 Q
BRICKLEY, R H	7907230074*	QA999	BRYANT, J C	7907250106*	50-348 Q
BRIGGS, L	7907100531	50-320 H	BRYANT, J C	7907260131*	50-395 Q
BRIGHT, Q O	7907090099	50-358 T	BRYSON, J E	7907260583*	50-592 Q
BRIGHT, Q O	7907030265	50-358 T	BUCHHOLZ, R H	7907180583	TOPREP
BRIGHT, Q O	7907030388	50-358 T	BUCHORN, P.	7907110166	50-478 Q
BRIGHT, Q O	7907120294	50-358 T	BUCKHAM, J A.	7907120308	50-332 B
BRIGHT, Q O	7907120170	50-358 T	BUCKLEY, B C	7907240373	50-461 A
BRIGHT, Q O	7907120303	50-358 T	BUCKLEY, B C	7907180199	50-461 A
BRIGHT, Q O	7907120400	50-358 T	BUDNITZ, R J	7907160271*	50-320 H
BRIGHT, Q O	7907120158	50-358 T	BUKATY, S A	7907060102*	50-482 Q
BRIGHT, Q O	7907120446	50-358 T	BUKATY, S A	7907060107*	50-482 Q
BRIGHT, Q O	7907120469	50-358 T	BULL, R W	7907270147	PR
BROCKENB, R W	7907060289	50-448 A	BUNCH, D	7907020132	50-320 P
BRODSKY, R S	7907060492	ORQ	BURDETTE, T E	7907240099*	50-518 Q
			BURGIN, R F.	7907100461	50-320 H



AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BURKHARDT, W	7907110232	70-364	CARLSON, R T	7907110329*	50-320 Q
BURK, R L	7907300556	PR	CARLSON, R T	7907110680*	50-387 Q
BURKE, K D	7907020486	FOIA	CARLSON, R T	7907230453*	50-412 Q
BURKE, D J	7907240279*	50-280 Q	CARLSON, R T	7907230579*	50-387 Q
BURKHARDT, W	7907180894	70-1257	CARLSON, R T	7907050494	50-363 Q
BURNETTE, G W	7907310303	RES	CARLSON, R T	7907050923	50-423 Q
BURNETT, P T	7907120560*	50-324 Q	CARLSON, R T	790713029*	50-286 Q
BURNETT, P T	7907300043*	50-302 Q	CARLSON, R T	7907190016*	50-387 Q
BURNETT, R F	7907160122*	70-143	CARLSON, R T	7907300374*	50-410 Q
BURNETT, R F	7907050464	70-33	CARLSON, R T	7907110688	50-471 Q
BURNETT, R F	7907110427	70-135	CARLSON, R T	7907160252	50-412 Q
BURROW, J F	7907260530	50-320 P	CARLSON, R T	7907240216*	50-443 Q
BURSTEIN, B	7907250419	REGO	CARLSON, R T	7907110013	50-423 Q
BURSTEIN, B	7907130162	50-266 Q	CARLSON, R T	7907180389	50-247 Q
BURSTEIN, B	7907260968	PR	CARLSON, R T	7907270379	50-220 Q
BURSTEIN, B	7907100605	50-502 J	CARLSON, R T	7907240609	50-334 Q
BURSTEIN, B	7907290277*	50-266 B	CARLSON, R T	7907110663	50-387 Q
BURSTEIN, B	7907160321	50-266 P	CARLSON, R T	7907110510	50-289 Q
BURSTEIN, B	7907170160	50-266 R	CARLSON, R T	7907190006	50-387 Q
BURT, L	7907180773	50-471 Q	CARLSON, R T	7907230558	50-387 Q
BURT, L	7907190650	50-471 Q	CARLSON, R T	7907300322	50-311 B
BUSCH, R W	7907060318	50-522 Q	CARLSON, R T	7907230060	50-412 Q
BUSCH, R W	7907190318	50-522 Q	CARLSON, R T	7907230342	50-352 Q
BUSCH, R W	7907190324*	50-522 Q	CARLSON, R T	7907240204	50-443 Q
BUSH, S H	7907250064	ACRS	CARLSON, R T	7907300364	50-410 Q
BUTLER, W R	7907230174*	50-320 P	CARLSON, R T	7907230005	50-311 Q
BUTLER, W R	7907260483	50-320 P	CARLSON, R T	7907230440*	50-352 Q
BUTZEL, A K	7907160116	50-549 Q	CARLSON, J D	7907270290*	50-397 Q
BUTZEL, A K	7907160125*	50-549 Q	CARMODY, J T	7907190206	50-389 Q
BYRD, H F	7907180816*	50-338 Q	CARR, A V	7907130081	50-344 Q
CABA, E C	7907110520*	50-346 R	CARR, A V	7907180739	50-344 Q
CADMAN, W K	7907310357*	50-482 A	CARR, R	7907110086*	50-320 Q
CAHILL, W J	7907270257*	50-3 J	CARRICK, J T	7907240267*	50-294 Q
CAHILL, W J	7907120409	50-3 Q	CARRIER, W C	7907170235*	50-320 J
CAHILL, W J	7907100591	50-3 J	CARRIER, W C	7907030389	50-320 Q
CAHILL, W J	7907170094	50-3 H	CARRIER, W C	7907030489	50-320 J
CAHILL, W J	7907170132	50-247 P	CARRIER, W C	7907100597	50-320 J
CAHILL, W J	7907170519	50-3 H	CARRIER, W C	7907170232	50-320 J
CAHILL, W J	7907200389	50-247 B	CARRIER, W C	7907260684	50-320 Q
CAHILL, W J	7907180490	50-3 R	CARROLL, J T	7907270170	50-219 B
CAHILL, W J	7907240389	50-247 B	CARRUTHERS, L M	7907160156	NUREQ
CAHILL, W J	7907250251	50-3 Q	CARTER, W K	7907190021*	71-31
CAHILL, W J	7907250337	50-247 Q	CARTER, W K	7907190017	71-31
CAHILL, W J	7907270255	50-3 J	CARTER, T F	7907110572*	50-237 Q
CAHILL, W J	7907310249	50-247 P	CARTWRIGHT, W R	7907060333*	50-338 B
CAHILL, W J	7907310449	50-3 F	CARTWRIGHT, W R	7907060334*	50-338 B
CAHILL, W J	7907300287	50-247 B	CARTWRIGHT, W R	7907030425*	50-338 B
CAHILL, W J	7907300393	50-247 P	CARTWRIGHT, W R	7907030425*	50-338 B
CAIN, C	7907190049*	50-298 Q	CARTWRIGHT, W R	7907030425*	50-338 B
CALDWELL, R A	7907180653*	50-298 Q	CARTWRIGHT, W R	7907060332*	50-338 B
CALLIHAN, D	7907300444*	50-201 I	CARTWRIGHT, W R	7907090285*	50-338 B
CALLIHAN, D	7907300144	50-471 T	CARTWRIGHT, W R	7907110541*	50-338 B
CALLIHAN, D	7907250194	50-471 T	CARTWRIGHT, W R	7907170221*	50-338 B
CALLIHAN, D	7907310044	50-471 T	CARTWRIGHT, W R	7907230546*	50-338 B
CALLIHAN, D	7907310054	50-471 T	CARTWRIGHT, W R	7907230580*	50-338 B
CALLIHAN, D	7907300133	50-471 T	CARTWRIGHT, W R	7907310436*	50-338 B
CANTER, H L	7906210231*	50-397 A	CASE, E Q	7907260493	50-320 H
CANTER, H L	7907270015*	50-206 Q	CASHMAN, T J	7907190360	WASTE MOT
CANTER, H L	7907130179*	50-70 Q	CASTRO, R D	7907020513*	50-312 Q
CANTRELL, F B	7907260508*	50-250 Q	CATCHPOLE, G J	7907310366	40-8693
CANTRELL, F B	7907200411*	50-280 Q	CATTON, I	7907110734	NUREQ
CANTRELL, F B	7907180658*	50-348 Q	CATTON, I	7907050350	ACRS
CANTRELL, F B	7907240279*	50-280 Q	CATTON, I	7907060288	ACRS
CANTRELL, F B	7907050071*	50-338 Q	CAVANAUGH, W	7907310439	50-368 P
CANTRELL, F B	7907310203*	50-338 Q	CERNE, A C	7907050527*	50-423 Q
CANTRELL, F B	7907250147*	50-355 Q	CERNE, A C	7907110628*	50-482 Q
CAPHTON, D L	7907110426*	50-353 Q	CHAN, J	7907030408*	50-237 B
CAPHTON, D L	7907110494*	50-311 Q	CHANDLER, H L	7907190634	PRM
CAPHTON, D L	7907110544*	50-272 Q	CHANDLER, L J	7907310488	50-361 Q
CAPHTON, D L	7907180445*	50-336 Q	CHANDLER, L J	7907180555	50-445 Q
CAPHTON, D L	7907190083	50-596 Q	CHAPMAN, R H	7907030441	NUREQ
CAPLAN, B	7907230324	50-320 P	CHAPMAN, L D	7907120056	RES
CAPRA, R A	7907300411	50-346 B	CHARNOFF, G	7907190304	50-329 Q
CAPRA, R A	7907130084	50-594 A	CHABE, P J	7907200506	PRM
CAPRON, L P	7907250192*	QA999	CHEN, M J	7907190310	NUREQ
CARBON, M W	7907250064	ACRS	CHEN, P Y	7907110262	50-311 A
CARBON, M W	7907020104	50-320 Q	CHERN, W B	7907110064	RES
CARBON, M W	7907100192	50-320 Q	CHERN, W B	7907190675	RES
CARBON, M W	7907190562	ACRS	CHERNY, F C	7907190474	GEN TEC IB
CARBON, M W	7907020394	50-320 Q	CHERNY, F C	7907200508	GEN TEC IB
CARBON, M W	7907020404*	50-320 Q	CHERNY, F C	7907120240	50-320 H
CARBON, M W	7907160068	COMMIBSION	CHEBKO, R C	7907100472*	50-346 B
CARBON, M W	7907260728	50-320 T	CHESBIN, H	7907190747	PR
CARLSON, R T	7907300208*	71-6698	CHESTER, R O	7907060446	RES
CARLSON, R T	7907230011*	50-311 Q	CHESTER, R O	7907300421	RES
CARLSON, R T	7907200491*	50-387 Q	CHILDS, W V	7907130467*	50-333 B
CARLSON, R T	7907200477	50-187 Q	CHILDS, W V	7907170039*	50-333 B
			CHILDS, W V	7907230292*	50-333 B

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHILDS, W V	7907260452*	50-333 S	CLAYTON, F L	7907030435	50-348 P
CHILDS, W V	7907260747*	50-333 S	CLAYTON, F L	7907100286	50-348 S
CHILK, S J	7907260396*	50-272 Q	CLAYTON, F L	7907170049	50-348 S
CHILK, S J	7907160358*	COMMISSION	CLAYTON, F L	7907180469	50-348 R
CHILK, S J	7907090063*	SECY	CLAYTON, F L	7907180596	50-348 P
CHILK, S J	7907090164*	SECY	CLAYTON, F L	7907170183	50-348 P
CHILK, S J	7907090169*	SECY	CLAYTON, F L	7907290340	50-348 P
CHILK, S J	7907090084*	SECY	CLAYTON, F L	7907240359	50-348 S
CHILK, S J	7907090181*	SECY	CLAYTON, F L	7907300321	50-348 P
CHILK, S J	7907310551*	COMMISSION	CLAYTON, E D	7907310555	REG
CHILK, S J	7907090097*	SECY	CLEARY, P Q	7907130276	50-295 Q
CHILK, S J	7907090103*	SECY	CLEMENSON, F	7907030039*	QA999
CHILK, S J	7907090189*	SECY	CLEMENSON, F	7907240414	50-263 P
CHILK, S J	7906260446	IOCFR	CLEMENSON, F	7907300072	50-263 S
CHILK, S J	7906260325	50-400 A	CLEMENS, P E	7907310178*	50-29 Q
CHILK, S J	7906260292	50-269 P	CLINE, K	7907050049	FOIA
CHILK, S J	7907180273	SECY	CLUBEN, R C	7907110009*	50-320 U
CHILK, S J	7907230752*	50-280 U	COBERLEY, M E	7907250204	50-522 Q
CHILK, S J	7907100067	50-320 D	COCHRAN, T B	7907160150*	70-143
CHILK, S J	7907020475	50-269 Q	COCHRAN, T B	7907160137*	COMMISSION
CHILK, S J	7907060460	PRM	COCHRAN, T B	7907160134*	70-143
CHILK, S J	7907090058*	SECY	COCHRAN, T B	7907190734	FOIA
CHILK, S J	7907130204	PRM	COCHRAN, T B	7907030112	FOIA
CHILK, S J	7907130229	PRM	COCHRAN, T B	7907030274	FOIA
CHILK, S J	7907110613	PR	COCHRAN, T B	7907060037*	70-2623
CHILK, S J	7907100180	50-320 H	COCHRAN, T B	7907200203*	50-237 Q
CHILK, S J	7906260194	50-269 P	COCHRAN, T B	7907250480*	70-2623
CHILK, S J	7907100679	50-466 Q	COCHRAN, T B	7907250497*	70-2623
CHILK, S J	7907180127*	50-219 Q	COCHRAN, T B	7907250435*	FOIA
CHILK, S J	7907100188*	50-320 J	COCHRAN, R Q	7907030249*	50-59 R
CHILK, S J	7907180730*	FOIA	COCHRAN, R Q	7907030247	50-59 R
CHILK, S J	7907270030	PR	COCHRAN, R Q	7907090314	50-59 P
CHILK, S J	7907100061	50-320 Q	COCHRAN, T B	7907310211*	50-382 U
CHILK, S J	7907160130	27-39	COCHRAN, B J	7907180640*	50-390 Q
CHILK, S J	7907180727	50-312 Q	COCHRAN, B J	7907110678*	50-338 Q
CHILK, S J	7907190292	50-320 D	COCHRAN, B J	7907240391*	50-390 Q
CHILK, S J	7907180907	50-443 Q	COE, W E	7907160034*	50-389 Q
CHILK, S J	7907100148	50-320 P	COFFMAN, W A	7907250504	FOIA
CHILK, S J	7907190652	50-344 Q	COHEN, J	7907250307	NUREG
CHILK, S J	7907230198*	COMMISSION	COHEN, I.	7907130050*	70-1100
CHIRASANTA, K	7907060026*	50-320 P	COHEN, I	7907240297*	70-33
CHOULES, N C	7907100458	50-320 H	COLE, R F	7907200228	50-261 Q
CHOULES, N C	7907280083*	50-266 Q	COLE, R F	7907240300	50-445 Q
CHOULES, N C	7907240112*	50-301 Q	COLE, R F	7907300144	50-471 T
CHOULES, N C	7907100355	50-320 H	COLE, R F	7907250194	50-471 T
CHOW, E T.	7907260300*	50-155 Q	COLE, R F	7907310044	50-471 T
CHOW, E T	7907300339*	50-263 Q	COLE, R F	7907310054	50-471 T
CHRISTMAN, J N	7907120019	50-338 Q	COLE, R F	7907300133	50-471 T
CHRISTMAN, J N	7907130082	50-338 Q	COLEMAN, M	7907120415*	50-280 P
CHRISTMAN, J N	7907110726	50-338 Q	COLL, N A	7907160027	50-389 Q
CHRISTMAN, J N	7907110746	50-338 Q	COLL, N A	7907230071	50-389 Q
CHRISTMAN, J N	7907130294	50-338 Q	COLLIER, R P	7907110635	NUREG
CHRISTMAN, S N	7907180330	50-338 Q	COLLIER, R P	7907190711	NUREG
CHRISTMAN, J N	7907180339	50-338 Q	COLLINS, H E	7907130836*	50-346 Q
CHRISTMAN, J N	7907180589	50-338 Q	COLLINS, H E	7907180155	FOIA
CHRISTENBURY, E	7907270008	50-261 Q	COLLINS, H E	7907180150	FOIA
CHRIBSOTIMOS, N	7907310096*	50-254 Q	COLLINS, P M	7907260023*	50-281 Q
CHRIBSOTIMOS, N	7907180455*	50-254 Q	COLLINS, P F	7907110365	50-320 A
CHRIBSOTIMOS, N	7907300491	50-254 Q	COLLINS, P F	7907100685	50-452 A
CHU, W K	7907260193	PR	COLOMBO, R W	7907180308*	50-312 R
CIESZKIEWICZ, S	7907170078*	50-10 R	COLOMBO, P	7907310068	NUREG
CLANCY, W.	7907100632	50-20 B	COMPTON, R M	7907050157*	50-413 Q
CLARK, R H	7907180040	50-445 M	COMPTON, R M	7907240201*	50-390 Q
CLARK, D R	7907060132	40-4492	COMPTON, R M	7907250106*	50-348 Q
CLARK, L	7907230107*	70-938	COMPTON, R M	7907190121*	50-321 Q
CLARK, L	7907100632	50-20 B	CONLON, T E	7907260822*	50-395 Q
CLARK, L	7907110528	50-20 B	CONLON, T E	7907050103*	50-327 Q
CLARKE, W L.	7907230750	NUREG	CONLON, T E	7907180801*	50-395 Q
CLARK, D.	7907110462*	50-254 B	CONLON, T E	7907190319*	50-416 Q
CLARK, R. J	7907130048	50-259 P	CONLON, T E	7907240186*	50-438 Q
CLARK, R. J	7907250120	50-259 P	CONNER, T B	7907110432	50-358 Q
CLARK, R. J	7907250116*	50-277 P	CONNER, T B	7907180707	FOIA
CLARK, R. J	7907250122*	50-301 P	CONNER, T B	7907060006	50-358 Q
CLARK, R. A	7907230191*	COMMISSION	CONNER, T B	7907100708	50-358 Q
CLARK, R. N	7907310088	PR	CONNER, T B	7907020012	27-39
CLAUNCH, A	7907230090	XPORTRIC	CONNER, T B	7907300492*	50-201 I
CLAY, E L	7907200074*	70-1113	CONNER, T B	7907300466*	50-201 I
CLAY, E L	7907200054*	70-1113	CONNER, T B	7907300440*	50-201 I
CLAYTON, F. L.	7907110409	50-348 B	CONNELL, C	7907170010*	50-286 R
CLAYTON, F. L.	7907110455	50-348 B	CONNOR, L.	7907190437	FOIA
CLAYTON, F. L.	7907180172	50-348 Q	CONRAD, V L	7907020199	50-556 A
CLAYTON, F. L.	7907190165	50-364 Q	CONRAD, V L	7907200274	50-556 Q
CLAYTON, F. L.	7907310326	50-348 Q	CONSTABLE, G. L	7907050198*	50-298 Q
CLAYTON, F. L.	7907230100	50-348 Q	CONTE, R. J.	7907310130*	50-333 Q
CLAYTON, F. L.	7907260506*	50-348 Q	CONTI, P L	7907060386	50-201 I

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CUNWAY, W F	7907260595	50-271 S	CORNELL, E K	7907160348	50-320 P
CUNWAY, W F	7907260599*	50-271 S	CORREA, A O	7907160691*	50-309 H
COOK, L	7907160031*	COMMISSION	CORREA, C	7907180493	50-535 J
COOK, K W	7907110466	50-277 P	CORRY, A F	7907160304	50-293 F
COOK, K W	7907250320	TOPREP	CORRY, A F	7907230447	50-293 P
COOK, K W	7907250392	TOPREP	CORYELL, O P	7907230652*	70-143
COOK, R J	7907300096*	50-329 G	COSTELLO, D J	7907170004*	50-280 R
COOLEY, W J	7907300260*	70-25	COSTELLO, F M	7907100249	50-320 H
COOLEY, W J	7907180261*	70-754	COSTELLO, F M	7907110664*	40-7983
COONEY, M J	7907090296	50-278 S	COSTELLO, J R	7907130349*	GA999
COONEY, M J	7907090298*	50-278 S	COSTELLO, J R	7907230308*	GA999
COONEY, M J	7907120592	50-278 S	COSTLE, D M	7907160182*	50-320 P
COONEY, M J	7907120597*	50-278 S	COTA, P C	7907230687	50-382 A
COONEY, M J	7907170157	50-278 S	COTHMAN, H E	7907190483	NUREG
COONEY, M J	7907170166*	50-278 S	COTTON, M	7907050267	50-482 H
COONEY, M J	7907230522	50-278 S	COTTON, R	7907090043*	SECY
COONEY, M J	7907130428	50-277 R	COTTON, R	7907090049*	SECY
COONEY, M J	7907170102	50-277 S	COTYRELL, W D	7907300099	NUREG
COONEY, M J	7907180504	50-277 S	COUGHLIN, J	7907090339	PRM
COONEY, M J	7907180509*	50-277 S	COUGHLIN, J	7907110267	50-546 G
COONEY, M J	7907270206	50-277 S	COUGHLIN, J	7907100111	50-546 G
COONEY, M J	7907270221*	50-277 S	COUGHLIN, J	7907100214	50-546 G
COONEY, M J	7907270238	50-278 S	COUGHLIN, J	7907100568	50-546 G
COONEY, M J	7907270247	50-278 S	COUGHLIN, J	7907120518	50-546 S
COOPER, J	7907110490	50-302 S	COUGHLIN, J	7907120633	50-546 S
COOPER, J	7907030455*	50-302 S	COUGHLIN, J	7907190561	50-546 S
COOPER, J	7907030486*	50-302 S	COUNSIL, W O	7907060468	50-213 G
COOPER, J	7907090234*	50-302 S	COUNSIL, W O	7907310008*	50-213 G
COOPER, J	7907130367*	50-302 S	COUNSIL, W O	7907030378	50-213 F
COOPER, J	7907180524*	50-302 S	COUNSIL, W O	7907060167	50-213 G
COOPER, J	7907180553*	50-302 S	COUNSIL, W O	7907180343	50-213 F
COOPER, J	7907300358*	50-302 S	COUNSIL, W O	7907230528	50-213 G
COOPER, M R	7907090464*	FOIA	COUNSIL, W O	7907050270	PR
COOPERSTEIN, R	7907110178	40-8385	COUNSIL, W O	7907050160	50-213 G
COOPERSTEIN, R	7907110175	40-8722	COUNSIL, W O	7907100018	50-336 G
COOPERSTEIN, R	7907110188	40-8663	COUNSIL, W O	7907090385	50-423 G
COOPERSTEIN, R	7907120105*	40-8722	COUNSIL, W O	7907110607	50-245 G
COPELAND, J O	7907110152	50-445 H	COUNSIL, W O	7907020225	50-293 G
COPELAND, J O	7907090056	50-498 H	COUNSIL, W O	7907110640	50-336 G
COPELAND, J O	7907110342	50-466 G	COUNSIL, W O	7907050556	50-245 P
COPELAND, J O	7907130546	50-466 G	COUNSIL, W O	7907050233	50-245 G
COPELAND, J O	7907130560	50-466 G	COUNSIL, W O	7907020458	50-336 G
COPELAND, J O	7907190701	50-466 G	COUNSIL, W O	7907190090	50-423 G
COPELAND, J O	7907190823	50-466 G	COUNSIL, W O	7907190106	50-423 G
COPELAND, J O	7907190866	50-466 G	COUNSIL, W O	7907260183	50-245 G
COPELAND, J O	7907190435	50-445 H	COUNSIL, W O	7907050316	50-336 G
COPELAND, J O	7907190419	50-466 G	COUNSIL, W O	7907050257	50-245 P
COPELAND, J O	7907230088	50-466 G	COUNSIL, W O	7907060282	50-336 G
COPELAND, J O	7907200497	50-466 G	COUNSIL, W O	7907120638	50-245 P
COPELAND, R L	7907020191	50-537 B	COUNSIL, W O	7907200349	50-245 P
COPELAND, R L	7907020195*	50-537 B	COUNSIL, W O	7907260737	50-213 F
COPELAND, R L	7907270124	REGO	COUNSIL, W O	7907230578	50-213 F
CORBETT, J B	7907280597*	FOIA	COWAN, R J	7907310339	50-336 P
CORBOY, J M	7907190179	PR	COWAN, R J	7907190646	PRM
CORE, M R	7907230543*	50-285 S	COWAN, B Z	7907250421	50-437 G
CORNELL, E K	7907130414*	50-320 P	COWAN, B Z	7907250428*	50-437 G
CORNELL, E K	7907030008	50-320 H	COX, T H	7907130362	50-320 H
CORNELL, E K	7907130343	50-320 H	CRANE, P A	7907130116	REGO
CORNELL, E K	7907130402	50-320 P	CRANE, P A	7907130496	50-275 G
CORNELL, E K	7907030006	50-320 H	CRANE, P A	7907190381	50-275 G
CORNELL, E K	7907130365	50-320 G	CRANE, P A	7907270376	70-173B
CORNELL, E K	7907030001	50-320 H	CRANE, P A	7907090398	50-275 G
CORNELL, E K	7907030002	50-320 H	CRANE, P A	7907090161	50-133 G
CORNELL, E K	7907030003	50-320 H	CRANE, P A	7907230242	50-133 P
CORNELL, E K	7907030004	50-320 H	CRANE, P A	7907240234	50-275 F
CORNELL, E K	7907030028	50-320 H	CRANE, P A	7907260643	50-275 F
CORNELL, E K	7907030293	50-320 H	CREEDE, J R	7907240164*	50-329 G
CORNELL, E K	7907030302	50-320 H	CREITZ, W M	7907180034*	50-320 T
CORNELL, E K	7907030303	50-320 H	CREWS, E H	7907100100	50-395 G
CORNELL, E K	7907030304	50-320 H	CREWS, E H	7907090406	50-395 G
CORNELL, E K	7907030024	50-320 H	CREWS, E H	7907190340	50-395 G
CORNELL, E K	7907030043	50-320 T	CREWS, E H	7907030217	50-395 F
CORNELL, E K	7907030048	50-320 H	CREWS, E H	7907050365	50-395 A
CORNELL, E K	7907030052	50-320 H	CREWS, J L	7907110078	50-133 G
CORNELL, E K	7907030130	50-320 H	CREWS, J L	7907130171	50-70 G
CORNELL, E K	7907030280	50-320 H	CREWS, J L	7907270140	50-275 G
CORNELL, E K	7907030285	50-320 H	CREWS, J L	7907300119	50-344 G
CORNELL, E K	7907130261	50-320 P	CREWS, J L	7907190478	50-224 G
CORNELL, E K	7907130283	50-320 H	CREWS, J L	7907270270	50-344 G
CORNELL, E K	7907130318	50-320 H	CREWS, J L	7907270009	50-206 G
CORNELL, E K	7907130346	50-320 H	CREWS, J L	7907270268	50-275 G
CORNELL, E K	7907130274	50-320 O	CREWS, J L	7907270287	50-397 G
CORNELL, E K	7907130308	50-320 H	CREWS, J L	7907300450*	50-312 P
CORNELL, E K	7907130312	50-320 H	CREWS, J L	7907300219	50-344 G
CORNELL, E K	7907160338	50-320 P	CROCKET, L	7907110727	50-219 P

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CROCKER, H W	7907090449*	50-213 Q	DAILE, L C	7907110555	50-413 Q
CROCKER, H W	7907030048*	50-333 Q	DAILE, L C	7907090420	50-491 Q
CROCKER, H W	7907230126*	70-938	DAILE, L F	7907190332	50-416 Q
CROCKER, H W	7907110440*	50-245 Q	DAILE, L F	7907190557	50-416 Q
CROCKER, H W	7907230057*	50-220 Q	DAILE, L F	7907190303*	50-416 Q
CROCKER, H W	7907310178*	50-297 Q	DAILE, L F	7907030490	50-416 B
CROSSIE, K L	7907060517	71-247	DAILE, L F	7907090324	50-416 B
CROSSMAN, W A	7907130139*	50-482 Q	DAILE, L F	7907190523	50-416 B
CROSSMAN, W A	7907050187*	50-482 Q	DAILE, L F	7907060191	50-416 A
CROSSMAN, W A	7907030179*	50-498 Q	DAILE, L F	7907200390	50-416 A
CROSSMAN, W A	7907110593*	50-445 Q	DAILE, L F	7907250256	50-416 H
CROSSMAN, W A	7907250486*	50-482 Q	DALLY, J W	7907310591	RES
CROSSMAN, W A	7907260561*	50-445 Q	DALTROFF, S L	7907250093*	50-277 Q
CROSSMAN, W A	7907300058*	50-498 Q	DALTROFF, S L	7907200510	PR
CROSSMAN, W A	7907310603*	50-482 Q	DALTROFF, S L	7907110719*	50-277 Q
CROSSMAN, W A	7907110612*	50-498 Q	DALTROFF, S L	7907090325	PRM
CROSSMAN, W A	7907110418*	50-382 Q	DALTROFF, S L	7907160139	REGGD
CROSSMAN, W A	7907250518*	50-445 Q	DALTROFF, S L	7907190859	PR
CROSSMAN, W A	7907260492*	50-498 Q	DALTROFF, S L	7907020090	50-277 Q
CROSSMAN, W A	7907250226*	50-482 Q	DALTROFF, S L	7907050446	50-277 Q
CROSSMAN, W A	7907300256*	50-445 Q	DALTROFF, S L	7907190080	50-277 Q
CROW, W T	7907310526*	50-361 Q	DALTROFF, S L	7907110533	50-277 F
CROW, W T	7907050490	70-2443	DALY, H	7907190083	50-596 Q
CROW, W T	7907050077	70-1207	DALY, H	7907240235	50-596 Q
CROW, W T	7907110605	70-1151	DANBUD, A D	7907180137	FOIA
CROW, W T	7907110611	70-371	DANCE, H C	7907310165*	50-259 Q
CROW, W T	7907060039	70-33	DANCE, H C	7907270053*	50-261 Q
CROW, W T	7907090365	70-1113	DANCE, H C	7907230790*	50-259 Q
CROW, W T	7907160227	70-27	DANCE, H C	7907100535	50-320 H
CROW, W T	7907120118	70-992	DANIELSON, D H	7907180319*	50-155 Q
CROW, W T	7907100717*	70-2838	DANIELSON, J	7907250458*	50-320 P
CROW, W T	7907020466	70-1100	DANIELS, T	7907020149*	50-346 Q
CROW, W T	7907110183	40-2061	DANIELS, T	7907020076*	50-346 Q
CROW, W T	7907230718	70-1113	DANIELSON, D H	7907050117*	50-305 Q
CROW, W T	7907230725	70-36	DANIELSON, D H	7907130354*	50-315 Q
CROW, W T	7907100692	70-2838	DANIELS, F T	7907240200*	50-282 Q
CROWLEY, J L	7907190740	PR	DANIELSON, D H	7907050553*	50-304 Q
CROWLEY, C T	7907100645	50-568 D	DANIELSON, D H	7907180357*	50-454 Q
CRUTCHFIELD, D M	7907190256	50-320 H	DANIELSON, D H	7907180382*	50-282 Q
CULLINGTON, R F	7907050412	71-181	DANIELSON, D H	7907180335*	50-315 Q
CULP, R H	7907130546	50-466 Q	DANIELSON, D H	7907240138*	50-237 Q
CUNNINGHAM, R O	7907130420	50-5 F	DANIELSON, D H	7907300071*	50-255 Q
CUNNINGHAM, Q E	7907090378	70-754	DANKMEYER, J R	7907090409*	50-322 Q
CUNNINGHAM, Q E	7907190273	PRM	DANKO, J C	7907230750	NUREG
CUNNINGHAM, Q E	7907050386	71-9009	DARMITZEL, R W	7906200236	50-73 P
CUNNINGHAM, Q H	7907020512	50-312 Q	DARMITZEL, R W	7907120383	50-73 P
CUNNINGHAM, Q H	7907020474	50-312 Q	DARMITZEL, R W	7907190616	50-70 P
CUNNINGHAM, A L	7907240148*	50-553 Q	DART, C	7907100538*	50-329 B
CUNNINGHAM, A L	7907160268*	70-143	DAUGHERTY, T M	7907250421	50-437 Q
CUNNINGHAM, A L	7907110598*	50-400 Q	DAUGHERTY, T M	7907250428*	50-437 Q
CUNNINGHAM, R E	7907100726	70-2219	DAVIDSON, D I	7907060400	PROJ
CUNNINGHAM, R E	7907120195	70-143	DAVIDSON, T	7907060982	XPORTLIC
CUPP, E A	7907300484*	50-298 Q	DAVIDSON, D R	7907110251	50-440 Q
CUPP, E A	7907200220*	50-192 Q	DAVIDSON, D R	7907110289	50-440 Q
CURRAN, J M	7907100599	50-206 R	DAVIDSON, D R	7907110231	50-440 Q
CURRIE, R S	7907100375	50-206 R	DAVIDSON, D R	7907250082*	50-440 Q
CURTIS, N W	7907050254	50-387 Q	DAVIDSON, D R	7907260017*	50-440 Q
CURTIS, N W	7907260087	50-387 Q	DAVIS, C B	7907090137	RES
CURTIS, N W	7907260192	50-387 Q	DAVIS, L L	7907190577*	71-3
CURTIS, N W	7907260156	50-387 Q	DAVIS, J F	7907170080	50-312 P
CURTIS, N W	7907030353*	50-387 K	DAVIS, S M	7907250298*	50-317 B
CURTIS, N W	7907030327	50-387 S	DAVIS, S M	7907250304*	50-318 B
CURTIS, N W	7907030349	50-387 K	DAVIS, S M	7907260663*	50-318 B
CURTIS, N W	7907170045	50-387 A	DAVIS, L D	7907020493	50-556 H
CURTIS, N W	7907260651	50-387 S	DAVIS, L D	7907060379	50-556 Q
CURTIS, N W	7907260457	50-387 A	DAVIS, L D	7907020010	50-556 Q
CURTIS, N W	7907270258	50-387 B	DAVIS, L D	7907200255	50-275 Q
CURTIS, A E	7907060450*	50-244 Q	DAVIS, L D	7907160075	50-275 Q
CURTIS, A E	7907260596*	50-244 B	DAVIS, J O	7907090451*	FOIA
CURTIS, S A	7907250403	NUREG	DAVIS, J O	7907020065	50-269 Q
CURTIS, J R	7907260534*	50-206 Q	DAVIS, J O	7907020097	FOIA
CUTCHIN, J M	7907130501	50-387 Q	DAVIS, J O	7907020134	FOIA
CUTCHIN, J M	7907190722	50-892 Q	DAVIS, J O	7907120439*	BECY
CUTCHIN, J M	7907060487	50-387 Q	DAVIS, J O	7907120698*	50-320 P
CYBULSKI, P	7907260716*	50-320 P	DAVIS, J O	7907020469	50-313 P
CYPHER, S B	7907180040	50-445 H	DAVIS, J O	7907130178	50-220 Q
D'AMORE, M	7907300062*	70-1151	DAVIS, A B	7907190042	50-10 Q
BACKO, B S	7907250318	50-445 A	DAVIS, A B	7907130310	50-341 Q
DAILE, L C	7907020503	50-413 Q	DAVIS, A B	7907110434	70-925
DAILE, L C	7907050118	50-488 Q	DAVIS, A B	7907180492	50-295 Q
DAILE, L C	7907050151	50-413 Q	DAVIS, A B	7907180554	50-295 Q
DAILE, L C	7907190667	50-413 Q	DAVIS, A B	7907190851	40-8616
DAILE, L C	7907190132*	50-413 Q	DAVIS, A B	7907250270	50-409 Q
DAILE, L C	7907190122	50-413 Q	DAVIS, A B	7907250206	50-255 Q
DAILE, L C	7907190176	50-488 Q	DAVIS, A B	7907260182	50-329 Q

# PERSONAL AUTHOR INDEX

389

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DAVIS, A B	7907260223	50-10 Q	DENTON, H R	7907110025*	50-346 P
DAVIS, A B	7907260272	50-186 Q	DENTON, H R	7907110030	50-346 Q
DAVIS, A B	7907300419	50-305 Q	DENTON, H R	7907230464	50-346 P
DAVIS, A B	7907300191	50-246 Q	DENTON, H R	7907110194	50-320 Q
DAVIS, A B	7907300326	50-367 Q	DENTON, H R	7907130014*	50-352 Q
DAVIS, A B	7907300403	50-305 Q	DENTON, H R	7907130020*	50-352 Q
DAVIS, A B	7907250576	50-275 Q	DENTON, H R	7907190075	50-309 H
DAVIS, D K	7907160355	FOIA	DENTON, H R	7907190208	50-427 Q
DAVIS, D	7907160102	50-320 P	DENTON, H R	7907190229	50-352 H
DAVIS, D	7907160078	50-320 P	DENTON, H R	7907110685	50-309 H
DAWSON, D M	7907060160	70-130B	DENTON, H R	7907110697	50-320 H
DAWSON, D M	7907190091	70-130B	DENTON, H R	7907190020	50-309 H
DAY, G R	7907190270	WASTE MGT	DENTON, H R	7907130243	50-320 P
DAYLEY, C	7907230482*	50-366 S	DENTON, H R	7907120513	50-280 Q
DE FLANGUE, G	7907180116	NUREG	DENTON, H R	7907120532*	50-280 Q
DEAKYNE, K	7907310373*	50-346 S	DENTON, H R	7907110307	50-416 M
DEALE, V B	7907170240	50-338 Q	DENTON, H R	7907110320*	50-416 M
DEALE, V B	7907180258	50-338 Q	DENTON, H R	7907180906	50-309 H
DEALE, V B	7907310083	50-338 Q	DENTON, H R	7907190025	50-309 H
DEALE, V B	7907130302	50-338 Q	DENTON, H R	7907190760	50-309 H
DEALE, V B	7907300270	50-338 Q	DENTON, H R	7907310039*	50-339 A
DEALE, V B	7907300113	50-522 T	DENTON, H R	7907130464	50-280 Q
DEALE, V B	7907270285	50-522 T	DENTON, H R	7907300573	50-269 P
DEALE, V B	7907270265	50-522 T	DENTON, H R	7907300539	50-409 Q
DEARNLEY, M F	7907180298	PR	DENTON, H R	7907300545*	50-409 Q
DEARTH, A E	7907300537	40-3453	DENTON, H R	7907020514	50-313 P
DEBOER, T K	7907050461	PR	DENTON, H R	7907240370	50-331 Q
DEBOER, T K	7907230122	PR	DENTON, H R	7907300426	50-312 P
DEBOER, T R	7907310049	PR	DENTON, H R	7907190291	50-320 P
DEGREGORIO, C	7907250525	50-466 Q	DENTON, H R	7907300414	50-312 H
DEGROOT, B	7907030480	TOPREP	DENTON, H R	7907300454	50-302 P
DEITZ, V R	7907100672	NUREG	DENTON, H R	7907300583*	50-312 H
DELAND, F H	7907230132	PR	DENTON, H R	7907300431*	50-346 Q
DELANEY, J C	7907050493*	70-2443	DENTON, H R	7907300460*	50-302 P
DELANEY, J C	7907230738	70-143	DENTON, H R	7907110684	50-320 H
DELGEORGE, L D	7907060031	50-373 Q	DEPASQUALE, J D	7907250382*	50-311 E
DELGEORGE, L D	7907050229	50-373 A	DEPEW, L	7907090259*	50-244 R
DELGEORGE, L D	7907240230	50-373 A	DEPHILLIPS, A A	7907190358*	40-0584
DELULJAK, J	7907300494*	50-346 Q	DEBEYN, R J	7907250353	50-244 P
DELWICHE, P	7907060210	50-409 P	DETENMEIER, R W	7907180627*	50-358 Q
DEMARS, R V	7907260644	50-320 P	DEVINE	7907200145*	50-516 Q
DEMLOW, D J	7907050281	50-329 H	DEVLIN, J	7907050054*	70-2662
DEMLOW, D J	7907080283*	50-329 H	DEVLIN, J W	7907130163*	50-184 Q
DEMMITT, T F	7907250056	71-6601	DEVLIN, J W	7907270386*	50-220 Q
DENISE, R P	7907130010*	50-352 Q	DEWEASE, J Q	7907170120	50-259 R
DENISE, R P	7907190304	50-320 P	DEWITT, R B	7907190540*	50-155 P
DENNING, R B	7907260711*	50-320 P	DEWITT, R B	7907190550*	50-155 P
DENTON, H R	7907240404	SECY	DEWITT, R B	7907310308*	50-255 P
DENTON, H R	7812290071	NUREG	DEYOUNG, R C	7907130190	50-320 P
DENTON, H R	7907240393	SECY	DEYOUNG, R	7907130414*	50-320 P
DENTON, H R	7905240076	WASTE MGT	DEYOUNG, R C	7907160230*	50-320 H
DENTON, H R	7907100714*	50-443 Q	DHIR, V K	7907110734	NUREG
DENTON, H R	7907120408	50-280 P	DIBERNARDO, M	7907050086*	50-272 Q
DENTON, H R	7907040343	50-280 H	DICEY, B B	7907100315	50-320 H
DENTON, H R	7907250037	50-272 H	DICKERSON, M W	7907050146*	50-267 Q
DENTON, H R	7907260641	50-320 S	DICKERSON, M W	7907050168*	50-267 Q
DENTON, H R	7907020312	50-269 P	DICKERSON, M W	7907270118*	50-267 Q
DENTON, H R	7907060179	50-3 P	DICKSON, H W	7907300507	REB
DENTON, H R	7907030173	SECY	DIDONATO, M J	7907100576	50-320 H
DENTON, H R	7907090460	50-280 H	DIECKAMP, H M	7907110111*	50-320 Q
DENTON, H R	7907120284	50-280 Q	DIECKAMP, H M	7907100334*	50-320 Q
DENTON, H R	7907190048	50-309 H	DIECKAMP, H M	7907180055*	50-320 T
DENTON, H R	7907160320	50-320 H	DIECKAMP, H M	7907050564	50-320 J
DENTON, H R	7907020498	50-309 H	DIECKAMP, H M	7907180030*	50-320 T
DENTON, H R	7907020504	50-309 H	DIEHL, B E	7907100660	50-358 Q
DENTON, H R	7907050124	50-309 H	DIELMAN, R	7907260234	PR
DENTON, H R	7907050542	50-280 H	DINHART, A V	7907300549	50-484 Q
DENTON, H R	7907060159*	50-309 Q	DIOGB, R H	7907110731	50-313 P
DENTON, H R	7907060293	50-280 H	DIOGB, R H	7907310534	50-409 P
DENTON, H R	7907090431	50-269 Q	DIOGB, R H	7907190330*	50-302 P
DENTON, H R	7907090440*	50-269 Q	DIGNAN, T Q	7907250042	50-568 Q
DENTON, H R	7907100678	50-443 Q	DIGNAN, T Q	7907180878	50-443 Q
DENTON, H R	7907100689*	50-443 Q	DIGNAN, T Q	7907180895*	50-443 Q
DENTON, H R	7907130148	50-443 Q	DIGNAN, T Q	7907180726	50-443 Q
DENTON, H R	7907130465	50-346 P	DIGNAN, T Q	7907270197	50-443 I
DENTON, H R	7907190173	50-443 Q	DI IANNI, D	7907240399	50-289 P
DENTON, H R	7907130277	50-320 H	DILLMAN, L T	7907190501	NUREG
DENTON, H R	7907090450	50-313 P	DIMENTO, L J	7907180656	FOIA
DENTON, H R	7907050190	50-546 H	DIMENNA, R A	7907180609*	50-285 P
DENTON, H R	7907100277	50-320 P	DINGELL, J D	7907090068*	SECY
DENTON, H R	7907100288*	50-320 P	DINGELL, J D	7907180633*	50-280 U
DENTON, H R	7907130002	50-352 Q	DIPIAZZA, R P	7907310238	PRH
DENTON, H R	7907190096	50-313 P	DIPIAZZA, R P	7907060482	70-1143
DENTON, H R	7907060513	50-346 Q	DIPIAZZA, R P	7907190698	PR
DENTON, H R	7907110017	50-346 P	DIPIAZZA, R P	7907100702	70-1143

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DIRCKS, H J	7907090080	SECY	DUNCAN, R H	7907180102*	50-320 P
DIRCKS, H J	7907090091	SECY	DUNKLEY, K	7907090343	50-374 H
DIRCKS, H J	7907090106*	SECY	DUNN, N M	7907180732	71-96
DIRCKS, H J	7905020344	DRQ	DUNN, B M	7907060252*	TOPREP
DIRCKS, H J	7907120466*	SECY			
DIRCKS, H J	7907120422	SECY	DUNN, C N	7907020083	50-334 Q
DIRCKS, H J	7907120016	27-47	DUNN, C N	7907110650	50-334 Q
DIRCKS, H J	7907120022*	27-47	DUNN, C N	7907230370	71-5026
DIRCKS, H J	7907110522	NUREQ	DUNN, C N	7907020168	50-334 P
DIRKS, H J	7907090005	50-201 U	DUNN, C N	7907020172	50-334 P
DISE, D P	7907190679	PRM	DUNN, C N	7907170047	50-334 R
DISE, D P	7907230151*	50-220 P	DUNN, C N	7907270164	50-334 Q
DISE, D P	7907260634	50-220 P	DUNN, C N	7907200472	50-334 P
DOANE, J	7907100701	50-482 Q	DUNN, C N	7907260438	50-334 Q
DOOD, C V	7907120062	RES	DUPONT, P S	7907260390*	50-272 Q
DOOD, C V	7907190488	NUREQ			
DOODS, R T	7907260978*	50-361 Q	DURAISHAWY, S	7907110156	50-320 Q
DOODS, R T	7907300451*	50-361 Q	DURAND, D A	7907120013	10CFR
DOODS, R T	7907270306*	50-508 Q	DURAND, D A	7907130093	50-329 T
DOODE, F T	7907160334*	TOPREP	DURHAM, J W	7907240364	50-314 Q
DOHERTY, J F	7907110073	50-466 Q	DURR, J P	7907190029*	50-387 Q
DOHERTY, J F	7907190658	50-466 Q	DURR, J P	7907240615*	50-334 Q
DOHERTY, J F	7907190664*	50-466 Q	DURR, J P	7907230444*	50-332 Q
DOHERTY, J F	7907190671*	50-466 Q	DURST, B M	7907310565	RES
DOHERTY, J F	7907190736*	50-466 Q	DUSEK, A J	7907170186	50-192 J
DOHERTY, J F	7907050516	50-466 Q	DWRACK, J A	7907110635	NUREQ
DOHLAN, J E	7907100470	50-315 P	DWRACK, J A	7907190711	NUREQ
DOHLAN, J E	7907050046	50-315 Q	DWORKIN, H J	7907190659	PRM
DOHLAN, J E	7907260697	50-315 P	DYER, L	7907190770	PR
DOHLAN, J E	7907260705	50-315 J	DYER, J A	7906200127*	50-269 Q
			DYER, J A	7906200428	50-320 P
DOLES, A E	7907230032	XPORTLIC	DYER, J A	7907130490*	50-338 Q
DOMANUS, H M	7907190510	NUREQ	DYER, J A	7907300043*	50-302 Q
DOMENICK, P	7907310621*	COMMISSION	DZIEWITZ, J B	7907250470*	FOIA
DOMERICK, A	7907300350	50-396 A	EARLY, P J	7907190278	50-333 Q
DONAHUE, J F	7907240164*	50-329 Q	EARLY, P J	7907190694	50-286 Q
DONAT, T	7907130359*	50-327 Q	EARLY, P J	7907030463	50-333 P
DONICH, T R	7907290299	NUREQ	EARLY, P J	7907020228	50-286 Q
DONOHUE, D J	7907160263*	COMMISSION	EARLY, P J	7907020270	50-333 P
DONOHUE, D J	7907110547*	CONTRACT	EARLY, P J	7907050363	50-333 P
DONOHUE, D J	7907090118*	CONTRACT	EARLY, P J	7907100601	50-333 F
DONOHUE, J N	7907230345*	50-295 Q	EARLY, P J	7907090383	50-286 Q
DONOHUE, J N	7907230361*	50-295 Q	EARLY, P J	7907100590	50-286 P
DOOLEY, M B	7907240911	PRM	EARLY, P J	7907170046	50-286 Q
DORR, M A	7907180162	FOIA	EARLY, P J	7907200301	50-286 F
DORR, M A	7907180168	FOIA	EARLY, P J	7907200283	50-286 Q
DOTENROD, R C	7907190365	WASTE MGT	EARLY, P J	7907200291	50-286 R
DOUGHERTY, J B	7907120555*	50-280 Q	EARLY, P J	7907230462	50-286 F
DOUGHERTY, J B	7907120556*	50-280 Q	EARLY, P J	7907230494	50-333 P
DOUGHERTY, J B	7907060501	50-338 Q	EARLY, P J	7907240293	50-286 P
DOUGHERTY, J B	7907180236	50-338 Q	EARLY, P J	7907270218	50-286 Q
DOUGHERTY, J B	7907180265*	50-338 Q	EBERSOLE, J	7907030295	ACR8
DOUGHERTY, J B	7907180271*	50-338 Q	EBERSOLE, J	7907030284	ACR8
DOUGHERTY, J B	7907180279*	50-338 Q	EBERT, M. W.	7907020207*	50-29 Q
DOUGHERTY, J B	7907060457	50-338 Q	EBNETER, S D	7907110542*	50-320 Q
DOUGHERTY, J B	7907060464*	50-338 Q	EBNETER, S D	7907230023*	50-311 Q
DOUGHERTY, J B	7907130368	50-338 Q	EBNETER, S D	7907230598*	50-387 Q
DOUGHERTY, J B	7907130371*	50-338 Q	EBNETER, S D	7907180399*	50-247 Q
DOUGHERTY, J B	7907180744	50-338 Q	ECKHARDT, J H	7907050392*	50-397 Q
DOUGHERTY, D J	7907260818*	CONTRACT	ECKHARDT, J H	7907110634*	50-397 Q
DOUGHERTY, D J	7907240286*	CONTRACT	ECKHARDT, J H	7907120419*	50-460 Q
DOUGHERTY, D J	7907260380*	CONTRACT	ECKHARDT, J H	7907300451*	50-361 Q
DOUGHERTY, D J	7907260845*	CONTRACT	EDDLERMAN, W	7907200487	PRM
DOUGHERTY, D J	7907300505*	CONTRACT	EDGAR, G L	7907050092*	FOIA
DOUGHERTY, D J	7907300271*	CONTRACT	EDWARDS, D W.	7907020202	50-29 Q
DOUGHERTY, D J	7907300485*	CONTRACT	EGEMEIER, S J.	7907260701*	50-596 Q
DOUGHERTY, D J	7907260660*	CONTRACT			
DOYLE, M M	7907020011	PROJ	EHRENSPERGER, W	7907230195	50-366 K
DOYLE, M M	7907180728	PROJ	EHRENSPERGER, W	7907230280	50-321 P
DRAONETTE, K S	7907160344*	COMMISSION	EHRENSPERGER, W	7907240339	50-321 P
DRAONETTE, K S	7907230743	27-39	EHRENSPERGER, W	7907200337	50-321 P
DRAONETTE, K S	7907240472	27-39	EILPERIN, S F.	7907180387	27-39
DRAKE, J H	7907310274	50-361 A			
DRAKE, J H	7907310286*	50-361 A	EISENHOWER, E. H	7907310402	50-294 P
DRALEY, J E	7907110706	50-295 Q	EISENHUT, D. G.	7907090477	50-320 U
DROMERICK, A	7907030099	50-311 A	EISENHUT, D. G.	7907060270	50-334 P
DROMERICK, A	7907250052	50-311 A	EISENHUT, D. G.	7907090024	50-219 T
DROMERICK, A	7907280069	50-576 A	EISENHUT, D. G.	7907240100*	50-336 P
DRUM, D E	7907050548*	50-280 H			
DUBERT, J	7907110610	50-599 Q	EISENHUT, D. G.	7907130123	50-334 P
DUBRY, N E.	7907110438*	70-925 Q	EL-GENK, M. S.	7907170121	NUREQ
DUBRY, N E.	7907180500*	50-295 Q	ELKINS, B. T.	7907190125	50-320 P
DUBRY, N E	7907260281*	50-184 Q	ELLERSHAW, L. E	7907030026*	QA999
DUDA, E	7907050354*	50-220 S	ELLERSHAW, L. E.	7907060046*	QA999
DUDA, E	7907130382*	50-220 S	ELLERSHAW, L. E.	7907050536*	QA999
DUDA, E	7907130385*	50-220 S	ELLIA, J. W.	7907060201*	50-522 A
			ELLIOTT, J. M.	7907130244*	70-2623
			ELLIS, J	7907180768	50-445 Q
			ELLIS, J. W.	7907060196	50-522 A
DUNBAR, J	7907100311*	50-249 S			
			ELROD, S. A.	7907200411*	50-280 Q

# PERSONAL AUTHOR INDEX

391

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EL ROD, S A	7907300082*	50-280 Q	ENGELKEN, R H	7907230361	50-394 Q
EMBILER, T R	7907310452	71-6058	ENGELKEN, R H	7907230362	50-106 Q
ENGEL, D	7907180240	50-596 Q	ENGELKEN, R H	7907230364	50-288 Q
ENGELHARDT, T F	7907240462	50-466 Q			
			ENGELKEN, R H	7907230568	50-113 Q
ENGELKEN, R H	79041130346	50-133 Q	ENGELKEN, R H	7907230584	50-224 Q
ENGELKEN, R H	7904160043	50-133 Q	ENGELKEN, R H	7907230590	50-326 Q
ENGELKEN, R H	7907030091*	50-397 Q	ENGELKEN, R H	7907230594	50-142 Q
ENGELKEN, R H	7905020227	50-133 Q	ENGELKEN, R H	7907230599	50-433 Q
ENGELKEN, R H	7905020296	50-133 S			
			ENGELKEN, R H	7907230601	50-139 Q
ENGELKEN, R H	7906200052	50-133 Q	ENGELKEN, R H	7907230602	50-27 Q
ENGELKEN, R H	7907030073	50-397 Q	ENGELKEN, R H	7907120615	50-528 Q
ENGELKEN, R H	7907120471*	50-460 Q	ENGELKEN, R H	7907120617	50-193 Q
ENGELKEN, R H	7907200367	50-528 Q	ENGELKEN, R H	7907120621	50-275 Q
ENGELKEN, R H	7907200370	50-344 Q			
			ENGELKEN, R H	7907120622	50-344 Q
ENGELKEN, R H	7907200372	50-206 Q	ENGELKEN, R H	7907120624	50-206 Q
ENGELKEN, R H	7907200374	50-361 Q	ENGELKEN, R H	7907120625	50-361 Q
ENGELKEN, R H	7907200379	50-397 Q	ENGELKEN, R H	7907120627	50-312 Q
ENGELKEN, R H	7907020280	50-528 S	ENGELKEN, R H	7907120630	50-397 Q
ENGELKEN, R H	7907020282	50-133 S			
			ENGELKEN, R H	7907050528	50-928 S
ENGELKEN, R H	7907020284	50-344 S	ENGELKEN, R H	7907050531	50-133 S
ENGELKEN, R H	7907020287	50-206 S	ENGELKEN, R H	7907050533	50-344 S
ENGELKEN, R H	7907020288	50-312 S	ENGELKEN, R H	7907050538	50-206 S
ENGELKEN, R H	7907020291	50-397 S	ENGELKEN, R H	7907050541	50-312 S
ENGELKEN, R H	7907190416	50-528 Q			
			ENGELKEN, R H	7907050543	50-397 S
ENGELKEN, R H	7907190417	50-133 Q	ENGELKEN, R H	7907050513	50-528 Q
ENGELKEN, R H	7907190423	50-275 Q	ENGELKEN, R H	7907060216	50-133 Q
ENGELKEN, R H	7907190425	50-344 Q	ENGELKEN, R H	7907060218	50-344 Q
ENGELKEN, R H	7907190426	50-206 Q	ENGELKEN, R H	7907060219	50-206 Q
ENGELKEN, R H	7907190428	50-361 Q			
			ENGELKEN, R H	7907060224	50-312 Q
ENGELKEN, R H	7907190431	50-312 Q	ENGELKEN, R H	7907060226	50-397 Q
ENGELKEN, R H	7907190436	50-397 Q	ENGELKEN, R H	7907050491	50-528 Q
ENGELKEN, R H	7907060027	50-528 Q	ENGELKEN, R H	7907050492	50-275 Q
ENGELKEN, R H	7907060029	50-133 Q	ENGELKEN, R H	7907050495	50-361 Q
ENGELKEN, R H	7907060030	50-344 Q			
			ENGELKEN, R H	7907050497	50-397 Q
ENGELKEN, R H	7907060032	50-206 Q	ENGELKEN, R H	7907100529	50-133 Q
ENGELKEN, R H	7907060034	50-312 Q	ENGELKEN, R H	7907100530	50-344 Q
ENGELKEN, R H	7907060036	50-397 Q	ENGELKEN, R H	7907100531	50-206 Q
ENGELKEN, R H	7907020262	50-528 Q	ENGELKEN, R H	7907100532	50-312 Q
ENGELKEN, R H	7907020265	50-275 Q			
			ENGELKEN, R H	7907100534	50-397 Q
ENGELKEN, R H	7907020267	50-361 Q	ENGELKEN, R H	7907110019	50-528 Q
ENGELKEN, R H	7907020271	50-397 Q	ENGELKEN, R H	7907100651	50-361 S
ENGELKEN, R H	7907030186	50-528 S	ENGELKEN, R H	7907100673	50-361 S
ENGELKEN, R H	7907030193	50-344 S	ENGELKEN, R H	7907100992	50-361 S
ENGELKEN, R H	7907030195	50-206 S			
			ENGELKEN, R H	7907130198	50-528 Q
ENGELKEN, R H	7907030198	50-312 S	ENGELKEN, R H	7907130203	50-133 Q
ENGELKEN, R H	7907030200	50-397 S	ENGELKEN, R H	7907130205	50-275 Q
ENGELKEN, R H	7907180541	50-397 S	ENGELKEN, R H	7907130208	50-344 Q
ENGELKEN, R H	7907180738	50-361 S	ENGELKEN, R H	7907130212	50-206 Q
ENGELKEN, R H	7907190101	50-361 Q			
			ENGELKEN, R H	7907130216	50-361 Q
ENGELKEN, R H	7907030191	50-133 S	ENGELKEN, R H	7907130218	50-312 Q
ENGELKEN, R H	7907120365	50-206 Q	ENGELKEN, R H	7907130222	50-397 Q
ENGELKEN, R H	7907030229	50-528 S	ENGELKEN, R H	7907130383	50-528 S
ENGELKEN, R H	7907030232	50-133 S	ENGELKEN, R H	7907130384	50-133 S
ENGELKEN, R H	7907030235	50-344 S			
			ENGELKEN, R H	7907130386	50-344 S
ENGELKEN, R H	7907030238	50-206 S	ENGELKEN, R H	7907130387	50-206 S
ENGELKEN, R H	7907030242	50-312 S	ENGELKEN, R H	7907130389	50-312 S
ENGELKEN, R H	7907030244	50-397 S	ENGELKEN, R H	7907130390	50-397 S
ENGELKEN, R H	7907020447	50-528 Q	ENGELKEN, R H	7907230744	50-360 Q
ENGELKEN, R H	7907020448	50-133 Q			
			ENGELKEN, R H	7907230745	50-288 Q
ENGELKEN, R H	7907020449	50-344 Q	ENGELKEN, R H	7907230747	50-69 Q
ENGELKEN, R H	7907020450	50-206 Q	ENGELKEN, R H	7907230749	50-70 Q
ENGELKEN, R H	7907020451	50-312 Q	ENGELKEN, R H	7907230753	50-187 Q
ENGELKEN, R H	7907020453	50-397 Q	ENGELKEN, R H	7907230754	50-94 Q
ENGELKEN, R H	7907120005	50-528 Q			
			ENGELKEN, R H	7907230759	50-106 Q
ENGELKEN, R H	7907120006	50-275 Q	ENGELKEN, R H	7907230760	50-288 Q
ENGELKEN, R H	7907120008	50-133 Q	ENGELKEN, R H	7907230761	50-113 Q
ENGELKEN, R H	7907120010	50-344 Q	ENGELKEN, R H	7907230764	50-224 Q
ENGELKEN, R H	7907120012	50-206 Q	ENGELKEN, R H	7907230765	50-326 Q
ENGELKEN, R H	7907120014	50-361 Q			
			ENGELKEN, R H	7907230766	50-142 Q
ENGELKEN, R H	7907120015	50-312 Q	ENGELKEN, R H	7907230769	50-433 Q
ENGELKEN, R H	7907120017	50-397 Q	ENGELKEN, R H	7907230772	50-139 Q
ENGELKEN, R H	7907100450	70-984	ENGELKEN, R H	7907230774	50-27 Q
ENGELKEN, R H	7907100453	70-25	ENGELKEN, R H	7907230777	50-133 Q
ENGELKEN, R H	7907100454	70-734			
			ENGELKEN, R H	7907230780	50-344 Q
ENGELKEN, R H	7907100457	70-754	ENGELKEN, R H	7907230781	50-206 Q
ENGELKEN, R H	7907100460	70-1257	ENGELKEN, R H	7907230783	50-312 Q
ENGELKEN, R H	7907110200	50-133 Q	ENGELKEN, R H	7907310166	50-394 Q
ENGELKEN, R H	7907110201	50-344 Q	ENGELKEN, R H	7907180699	50-528 Q
ENGELKEN, R H	7907110205	50-206 Q			
			ENGELKEN, R H	7907180700	50-275 Q
ENGELKEN, R H	7907110208	50-312 Q	ENGELKEN, R H	7907180703	50-344 Q
ENGELKEN, R H	7907230520	50-360 Q	ENGELKEN, R H	7907180704	50-361 Q
ENGELKEN, R H	7907230527	50-228 Q	ENGELKEN, R H	7907180706	50-206 Q
ENGELKEN, R H	7907230536	50-89 Q	ENGELKEN, R H	7907180708	50-312 Q
ENGELKEN, R H	7907230542	50-70 Q			
			ENGELKEN, R H	7907180711	50-397 Q
ENGELKEN, R H	7907230544	50-187 Q	ENGELKEN, R H	7907270377	50-133 Q
ENGELKEN, R H	7907230547	50-94 Q	ENGELKEN, R H	7907310395	50-528 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ENGELKEN, R H	7907310396	50-133 Q	FELTON, J M	7907050013	FOIA
ENGELKEN, R H	7907310397	50-344 Q	FELTON, J M	7907060131	50-289 P
ENGELKEN, R H	7907310399	50-206 Q	FELTON, J M	7907020100	FOIA
ENGELKEN, R H	7907310400	50-312 Q	FELTON, J M	7907020105	FOIA
ENGELKEN, R H	7907310401	50-397 Q	FELTON, J M	7907030117	50-461 A
ENGELKEN, R H	7907240315	50-397 S	FELTON, J M	7907030165	FOIA
ENGELKEN, R H	7907260267	50-528 Q	FELTON, J M	7907100162*	FOIA
ENGELKEN, R H	7907260270	50-133 Q	FELTON, J M	7907030139	50-295 P
ENGELKEN, R H	7907260274	50-344 Q	FELTON, J M	7907060465	40-1739
ENGELKEN, R H	7907260277	50-206 Q	FELTON, J M	7907020094	50-22 P
ENGELKEN, R H	7907260278	50-312 Q	FELTON, J M	7907030153	FOIA
ENGELKEN, R H	7907260286	50-397 Q	FELTON, J M	7907060173	50-338 P
ENGLE, L B	7907250072*	50-368 P	FELTON, J M	7907190124	50-498 H
EPLER, E P	7907050460	ACRS	FELTON, J M	7907030146	FOIA
ERB, C M	7907200290*	50-281 Q	FELTON, J M	7907060075	FOIA
ERB, C M	7907261011*	50-461 Q	FELTON, J M	7907030110	FOIA
ERICKSON, L W	7907190375*	50-344 Q	FELTON, J M	7907030307	FOIA
ERICSON, D M	7907260470	50-320 P	FELTON, J M	7907060449	FOIA
ERNST, M L	7907260497	50-320 H	FELTON, J M	7907020136	50-320 P
ESSIG, T H	7907130320*	50-341 Q	FELTON, J M	7907020146	FOIA
ESSIG, T H	7907260196*	50-329 Q	FELTON, J M	7907030335	FOIA
ESSIG, T H	7907260240*	50-10 Q	FELTON, J M	7907050020	FOIA
ESSIG, T H	7907300328*	50-367 Q	FELTON, J M	7907090404	FOIA
ESSIG, T H	7907300412*	50-305 Q	FELTON, J M	7907090448	FOIA
ESSIG, T H	7907300194*	50-266 Q	FELTON, J M	7907100034	FOIA
ESSIG, T H	7907100284	50-320 H	FELTON, J M	7907090327	50-312 Q
ESSIG, T H	7907180587*	50-295 Q	FELTON, J M	7907030264	FOIA
ESSIG, T H	7907250282*	50-409 Q	FELTON, J M	7907030315	FOIA
ESSINGTON, E H	7907190192	MUREQ	FELTON, J M	7907060142	FOIA
ESTEY, H P	7907250044	70-1257	FELTON, J M	7907060162	70-1193
ETHERIDGE, M R	7907230291*	0A999	FELTON, J M	7907030237	50-424 A
ETHERINGTON, H	7907230654	ACRS	FELTON, J M	7907030321	FOIA
ETTOUNEY, M H	7906210238*	50-397 A	FELTON, J M	7907030108	FOIA
EVANS, C A	7907180533*	50-298 Q	FELTON, J M	7907050019	50-320 P
EVERETT, J L	7907130077*	50-463 Q	FELTON, J M	7907050027	50-320 P
EVERETT, R J	7907310574*	50-498 Q	FELTON, J M	7907050035	50-320 P
EVERETT, R J	7907310592*	50-313 Q	FELTON, J M	7907050045	50-320 P
EWALD, S C	7907230724*	50-280 Q	FELTON, J M	7907180715	FOIA
EWALD, S C	7907300028*	50-280 Q	FELTON, J M	7907180784	50-320 P
EWING, J F	7907230505*	70-27	FELTON, J M	7907190036	50-348 P
EWING, T N	7907170193	50-556 L	FELTON, J M	7907190088	50-320 Q
EWOLDBEN, H M	7907190422	WASTE MGT	FELTON, J M	7907190248	50-320 P
EYED, J A	7907100559	50-546 Q	FELTON, J M	7907190629	FOIA
EYMONTT, M J	7907190635	PRM	FELTON, J M	7907250438	50-320 P
FAIST, F R	7907110340	50-320 P	FELTON, J M	7907190031	FOIA
FALCO, P D	7907100633	50-592 D	FELTON, J M	7907190171	50-461 A
FALKENSTEIN, E J	7907100637	50-312 H	FELTON, J M	7907190107	50-320 P
FALLIN, J F	7907240248	PRDJ	FELTON, J M	7907190115	50-320 P
FANKHAUSER, D B	7907190748	50-358 Q	FELTON, J M	7907190141	50-320 P
FARBER, G	7906210421*	50-466 Q	FELTON, J M	7907110001	50-320 Q
FARMER, W B	7907190033	REVIEW GRP	FELTON, J M	7907190183	FOIA
FARON, R S	7907230224	50-244 P	FELTON, J M	7907190669	50-320 P
FARRAR, M C	7907160097	PRDJ	FELTON, J M	7907190731	50-289 P
FARRIS, J R	7907110089	50-556 Q	FELTON, J M	7907190752	FOIA
FAULKENBERRY, B	7907190484*	50-224 Q	FELTON, J M	7907190803	50-247 P
FAULKENBERRY, B	7907160048*	50-312 Q	FELTON, J M	7907250517	FOIA
FAULKENBERRY, B	7907160067	50-312 Q	FELTON, J M	7907250572	FOIA
FAULKENBERRY, B	7907130179*	50-70 Q	FELTON, J M	7907190221	50-16 P
FAULKENBERRY, B	7907270015*	50-206 Q	FELTON, J M	7907250398	FOIA
FAULKENBERRY, B	7907300404	50-312 Q	FELTON, J M	7907250484	50-546 A
FAUST, H M	7907300029	71-3908	FELTON, J M	7907180682	FOIA
FAUTH, W L	7907020106	FOIA	FELTON, J M	7907190007	FOIA
FAY, C W	7907110240	50-266 Q	FELTON, J M	7907190180	50-352 A
FAY, C W	7907030372	50-301 P	FELTON, J M	7907190264	50-320 P
FAY, C W	7907100338	50-502 C	FELTON, J M	7907250476	50-352 A
FAY, C W	7907250267	50-266 S	FELTON, J M	7907190481	FOIA
FAY, C W	7907300286	50-266 Q	FELTON, J M	7907200226	50-320 P
FEE, W F	7907310339	50-336 P	FELTON, J M	7907230223	FOIA
FETERABEND, C D	7907240200*	50-282 Q	FELTON, J M	7907250556	50-201 P
FEIT, R	7907090271	REVIEW GRP	FELTON, J M	7907190442	FOIA
FEIT, R	7907090272*	REVIEW GRP	FELTON, J M	7907230004	FOIA
FEIT, R	7907300080	REVIEW GRP	FELTON, J M	7907250396	50-322 A
FELD, S E	7907190494	50-471 Q	FELTON, J M	7907250413	50-293 P
FELDMAN, J H	7907110505*	50-358 Q	FELTON, J M	7907250447	50-320 P
FELTON, J M	7907230565*	COMMISSION	FELTON, J M	7907190703	27-39
FELTON, J M	7907310589*	FOIA	FELTON, J M	7907250408	50-269 V
FELTON, J M	7907050089*	FOIA	FELTON, J M	7907250515	FOIA
FELTON, J M	7906060069	50-309 P	FELTON, J M	7907260447	FOIA
FELTON, J M	7907030106	FOIA	FELTON, J M	7907300156	FOIA
FELTON, J M	7907020111	FOIA	FELTON, J M	7907300410	50-201 I
FELTON, J M	7907020122	FOIA	FELTZ, D E	7907170040	50-128 S
FELTON, J M	7907030154	FOIA	FELTZ, D E	7907310393*	50-128 R
FELTON, J M	7907030174	FOIA	FELTZ, D E	7907180465	50-128 P
FELTON, J M	7907030184	50-29 S	FENNER, E H	7907100627*	50-128 I
FELTON, J M	7907060150	50-344 P	FERGUSON, W	7907300517*	50-201 I
FELTON, J M	7907020128	FOIA	FERGUSON, R L	7907110638*	50-338 Q
			FERMAN, J W	7907190333	WASTE MGT



# PERSONAL AUTHOR INDEX

39

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FICKLESIMER, M L	7906220227	REVIEW GRP	FIDELSON, S A	7907240222*	50-443 Q
FILDER, J	7907030459	50-348 J	FONG, F F	7907300260*	70-25
FIELDB, S R	7907190341	NUREG	FORD, W	7907310193*	50-546 U
FIENO, D B	7907310587*	50-338 P	FORD, M R	7907190801	50-338 Q
FILCOCCO, N I	7907250429*	50-320 P	FORD, E J	7907240123*	50-369 Q
FINFROCK, I R	7907050223	50-219 Q			
FINFROCK, I R	7907090390	50-363 Q	FOSTER, H	7907060393	70-1151
FINFROCK, I R	7907190223	50-363 Q	FOSTER, J E	7907180354*	50-315 Q
			FOSTER, W E	7907250367*	0A999
FINFROCK, I R	7907020180	50-219 F	FOSTER, W E	7907090466*	0A999
FINFROCK, I R	7907100399	50-219 R	FOUKE, R L	7907170243	50-445 Q
FINKEL, A E	7907230023*	50-311 Q			
FINKEL, A E	7907230598*	50-387 Q	FDUKE, R L	7907180612	50-445 Q
FINKEL, A E	7907190029*	50-387 Q	FDUKE, R L	7907140207	50-445 Q
			FDWLER, E B	7907190192	NUREG
FINKEL, A E	7907100585	50-320 H	FOX, C J	7907240426*	REGOD
FINKEL, A E	7907100464	50-320 H	FOX, C J	7907240412*	REGOD
FIORRELLI, Q	7907130351	50-315 Q			
FIORRELLI, Q	7907230741	50-456 Q	FOX, C J	7907240395*	REGOD
FIORRELLI, Q	7907180522	50-456 Q	FOX, C J	7907240384*	REGOD
			FOX, C J	7907240372*	REGOD
FIORRELLI, Q	7907200498	50-341 S	FOX, D J	7907240388*	REGOD
FIORRELLI, Q	7907050549	50-304 Q	FOX, H B	7907050304	50-260 S
FIORRELLI, Q	7907300038	50-373 Q			
FIORRELLI, Q	7907180456	50-546 Q	FOX, H B	7907090348	50-260 S
FIORRELLI, Q	7907300088	50-329 Q	FOX, H B	7907100479	50-260 S
			FOX, H B	7907170107	50-259 S
FIORRELLI, Q	7907180429	50-451 Q	FOX, H B	7907170200	50-296 S
FIORRELLI, Q	7907080112	50-305 Q	FOX, H B	7907180531	50-260 S
FIORRELLI, Q	7907180307	50-155 Q			
FIORRELLI, Q	7907250436	50-440 Q	FRAGA, C D	7907100616	50-592 D
FIORRELLI, Q	7907180369	50-282 Q	FRALAY, R F	7907110330	50-320 Q
			FRALAY, R F	7907190275	50-320 Q
FIORRELLI, Q	7907180336	50-454 Q	FRANK, L	7907100462	50-344 P
FIORRELLI, Q	7907180325	50-315 Q	FRASER, J	7907020091	50-22 P
FIORRELLI, Q	7907240172*	50-546 Q			
FIORRELLI, Q	7907250212	50-483 Q	FREEMAN, L M	7907240536	PRM
FIORRELLI, Q	7907110716	50-373 S	FREITAG, J D	7907230524	50-302 J
			FRENZEL, C A	7907120723	50-320 P
FIORRELLI, Q	7907240134	50-237 Q	FROST, R R	7907120658*	50-267 S
FIORRELLI, Q	7907130187	50-483 S	FUJITA, T	7907260091*	50-445 U
FIORRELLI, Q	7907250290	50-373 Q			
FIORRELLI, Q	7907270104	50-304 Q	FULLER, J K	7907260166	50-267 Q
FIORRELLI, Q	7907140264	50-454 Q	FULLER, J K	7907240445	50-267 P
			FULLER, J K	7907300116*	50-267 Q
FIORRELLI, Q	7907300067	50-255 Q	FULTON, J H	7907200514	50-293 S
FIORRELLI, Q	7907260160	50-341 Q	FULTON, J H	7907260692*	50-293 S
FIORRELLI, Q	7907260999	50-461 Q			
FIORRELLI, Q	7907180463	50-440 S	FULTON, J H	7907260703*	50-293 S
FIORRELLI, Q	7907090098	50-341 S	FULTON, J H	7907260679*	50-293 S
			FULTON, J H	7907260745	50-293 S
FIORRELLI, Q	7907190086	50-341 Q	FULTON, J H	7907300312*	50-293 S
FIORRELLI, Q	7907310197	50-315 Q	FUNDERBURG, R D	7907190454	WASTE MGT
FIORRELLI, Q	7907300481	50-305 Q			
FIORRELLI, Q	7907250077	50-440 Q	FURBUSH, M H	7907020011	PRDJ
FIORRELLI, Q	7907260006	50-440 Q	FURBUSH, M H	7907090206	50-275 A
			FURR, B J	7907190566	50-324 Q
FIORRELLI, Q	7907300077	50-373 Q	FURR, B J	7907130348	50-261 S
FIORRELLI, Q	7907180094	50-295 R	FURR, B J	7907170025	50-324 R
FIORRELLI, Q	7907300506	50-295 P			
FISCHER, P E	7907190809	PR	GAD, R K	7907250042	50-56B Q
FISH, R F	7907100410	50-320 H	GAD, R K	7907180878	50-443 Q
			GAD, R K	7907180895*	50-443 Q
FISHER, C. R	7907180514	50-267 P	GAD, R K	7907180726	50-443 Q
FISHER, W L	7907180354*	50-315 Q	GAGE, L W	7907110542*	50-320 Q
FISHER, W L	7907190073*	50-10 Q			
FISHER, W L	7907100302	50-320 H	GAHM, J W	7907060229*	50-267 R
FISHER, W L	7907110438*	70-925	GAHM, J W	7907120106*	50-267 R
			GAHM, J W	7907120663*	50-267 S
FISHER, W L	7907180500*	50-295 Q	GAHM, J W	7907130391*	50-267 S
FISHER, W L	7907250211*	50-255 Q	GAHM, J W	7907180444*	50-267 S
FISHER, W L	7907260281*	50-186 Q			
FISHER, W L	7907300430*	50-305 Q	GAHM, J W	7907180575*	50-267 S
FITTI	7907030157*	FDIA	GALBRAITH, K P	7907110499*	TOPREP
FITZGERALD, J. A	7907100168	50-320 P	GALLAGHER, J W	7907110644*	50-277 Q
FITZGERALD, J. A	7907100165	50-320 P	GALLAGHER, J W	7907090089	50-277 Q
FITZGERALD, J. A	7907100154	50-320 P	GALLAGHER, J W	7907180914	50-277 Q
FITZGERALD, J. A	7907100209	50-320 H			
FITZGERALD, J. A	7907100194	50-320 H	GALLAGHER, E. J.	7907300526*	50-303 Q
			GALLAGHER, E. J.	7907310206*	50-315 Q
FITZGERALD, J. A	7907100095	50-320 E	GALLINA, C.	7907130163*	50-184 Q
FITZGERALD, J. A	7907100140*	50-320 Q	GALLO, J	7907060515	50-556 Q
FITZGERALD, J. A	7907100082	50-320 T	GALLO, J	7907060367	50-556 Q
FITZGERALD, J. A	7907130398	50-320 H			
FITZGERALD, J. A	7907130358	50-320 H	GALLO, J	7907060503	50-556 Q
			GALLO, J.	7907130425	50-556 Q
FITZGERALD, J. A	7907130395	50-320 H	GALLO, R M	7907110696*	50-387 Q
FLACK, O	7907030138	50-424 A	GALLO, R M	7907200503*	50-387 Q
FLACK, O	7907240341	50-424 Q	GALPIN, F.	7907130536*	50-346 Q
FLANIGAN, L. J.	7907110635	NUREG			
FLEISCHMANN, R	7907030221	50-277 S	GAMMILL, W. P	7907180064*	50-261 P
			GAMMILL, W. P	7907260143	50-267 P
FLUGGER, F. O.	7907230080*	50-389 Q	GAMMILL, W. P	7907260149*	50-267 P
FLYNN, P. O.	7907090741	50-498 M	GAMMILL, W. P	7907090214	50-267 P
FLYNN, M.	7907030203	50-549 Q	GARCIA, P. J	7907230770	40-8452
FOGO, W. O	7907300318	50-155 F			
FOLEY, E.	7907300570	PR	GARCIA, P. J	7907230785	40-8102
			GARLID, K L	7907170239	ACR8
FOLEY	7907200145*	50-516 Q	GARRAHY, J. J.	7907160083*	COMMISSION
FOLEY, T	7907180445*	50-336 Q	GARRAHY, J. J.	7907160088*	COMMISSION
FOLBOM, B. A.	7907240727*	50-412 Q	GARRETT, W. L.	7907170248	50-445 Q
FOLBOM, B. A.	7907160258*	50-412 Q			

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GARRICK, B. J.	7907130242*	70-2623	GILLET, H. T.	7907200321*	50-315 R
GARRISON, O. B.	7907250882*	27-47	GILLET, H. T.	7907200333*	50-316 R
GARY, R. J.	7907110660*	50-445 Q	GILLELAND, J. E.	7907180602*	50-390 Q
GARY, R. J.	7907310895	50-445 Q	GILLELAND, J. E.	7907130001	ORR
GARY, R. J.	7907310600	50-445 Q	GILLELAND, J. E.	7907090355	PRM
GARY, R. J.	7907300236*	50-445 Q	GILLELAND, J. E.	7907230763*	50-259 Q
GARY, R. J.	7907270305*	50-445 Q	GILLELAND, J. E.	7907100179	50-259 Q
GARY, R. J.	7907260647	50-445 B	GILLELAND, J. E.	7907250454*	50-341 Q
GARY, R. J.	7907030392	50-445 B	GILLELAND, J. E.	7907190207	50-327 Q
GARY, R. J.	7907090247	50-445 A	GILLELAND, J. E.	7907310170	50-327 Q
GARY, R. J.	7907110346	50-445 S	GILLELAND, J. E.	7907090388	50-318 S
GARY, R. J.	7907180552	50-445 S	GILLELAND, J. E.	7907190196	50-327 Q
GARY, R. J.	7907190216	50-445 S	GILLELAND, J. E.	7907300360*	50-390 Q
GARY, R. J.	7907230298	50-445 S	GILLELAND, J. E.	7907230056	50-259 Q
GARY, R. J.	7907230284	50-445 S	GILLELAND, J. E.	7906220369	50-259 R
GAY, G. M.	7907170248	50-445 Q	GILLELAND, J. E.	7907090351	50-327 S
GAZARIK, R.	7907020091	50-22 P	GILLELAND, J. E.	7907090316	50-327 S
GEHR, A. C.	7907060038	50-592 Q	GILLELAND, J. E.	7907090331	50-428 S
GEHR, A. C.	7907020007	50-592 Q	GILLELAND, J. E.	7907030348	50-428 Q
GEHR, A. C.	7907180119	50-592 Q	GILLELAND, J. E.	7907030351	50-390 S
GEHR, A. C.	7907180313	50-592 Q	GILLELAND, J. E.	7907030450	50-428 Q
GEHR, A. C.	7907130110	50-275 Q	GILLELAND, J. E.	7907030492	50-327 A
GEHR, A. C.	7907180078	50-592 Q	GILLELAND, J. E.	7907060309	50-327 A
GEHR, A. C.	7907020006	50-592 Q	GILLELAND, J. E.	7907060188	50-259 P
GEHR, A. C.	7907190706	50-592 Q	GILLELAND, J. E.	7907060354	50-259 P
GEHR, A. C.	7907190493	50-592 Q	GILLESPIE, F. P.	7907230523*	70-27
GEIGER, D. A.	7907030162	71-215	GILLESPIE, F. P.	7907200034*	70-1113
GEISLER, G. O.	7907270182	50-269 P	GILLESPIE, F. P.	7907200074*	70-1113
GEORGE, H. H.	7907250140	PT21	GILLESPIE, F. P.	7907230488*	50-339 Q
GERAGHTY, E. P.	7907190326	NUREQ	GILLESPIE, F. P.	7907300070*	70-1151
GERAGHTY, E. P.	7907190374	NUREQ	GILLEN, D. M.	7907190046*	50-329 A
GERAGHTY, E. P.	7907190420	NUREQ	GILLINS, R. L.	7907240126	NUREQ
GERAGHTY, E. P.	7907190433	NUREQ	GIRARD, E. H.	7907260522*	50-395 Q
GERAGHTY, C.	7907090389	XPORTLIC	GIRSTANTAS, W. A.	7907160156	FOIA
GERALD, A. F.	7907090423*	XPORTLIC	GLAGOLA, A. F.	7907260809	CONTRACT
GETTY, B. C.	7907180409*	50-133 R	GLAGOLA, A. F.	7907300498	CONTRACT
GHONIM, N. M.	7907190353	NUREQ	GLAGOLA, A. F.	7907300261	CONTRACT
GIBBONS, T. D.	7907110568*	50-413 Q	GLAGOLA, A. F.	7907300459	CONTRACT
GIBBS, H. E.	7907180285	50-329 Q	GLASBERG, V. M.	7907060169	50-338 P
GIBBS, H. E.	7907060367	50-556 Q	GLASIER, G. E.	7907240575	40-8681
GIBBS, H. E.	7907160120	50-556 Q	GLENN, J.	7907110006*	50-320 Q
GIBBS, H. E.	7907180595	50-556 Q	GLENN, J.	7907230633*	COMMISSION
GIBBS, H. E.	7907130047	50-255 Q	GLENN, R. D.	7907100684	70-2623
GIBBS, H. E.	7907060503	50-556 Q	GLICKMAN, D.	7907160192*	COMMISSION
GIBSON, G. T.	7907050203*	50-302 Q	GLUDEMAN, J. R.	7907260556	50-320 P
GIBSON, G. T.	7907130511*	50-302 Q	GODDARD, R. J.	7907170250	50-295 Q
GIBSON, G. T.	7907110596*	50-269 Q	GODDARD, R. J.	7907230186	50-295 Q
GIBSON, A. F.	7907180695*	50-280 Q	GODDARD, R. J.	7907130013	50-295 Q
GIESEKE, J. A.	7907300448	RES	GODDARD, R. J.	7907160015	50-599 Q
GIESEKE, J. A.	7907300458	RES	GODDARD, R. J.	7907190595	50-599 Q
GIESEKE, J. A.	7907300436	RES	GODDARD, R. J.	7907190387	50-599 Q
GIESEKE, J. A.	7907300467	RES	GODDARD, R. J.	7907190602	50-599 Q
GIESEKE, J. A.	7907190637	RES	GODDARD, R. J.	7907190618	50-599 Q
GIESEKE, J. A.	7907170187	NUREQ	GOLDBERG, S. C.	7907060478	50-338 Q
GIESEKE, J. A.	7907310219	RES	GOLDBERG, S. C.	7907090071	50-338 A
GIESEKE, J. A.	7907310208	RES	GOLDBERG, S. C.	7907130128	50-338 Q
GILBERT, L. D.	7907260492*	50-498 Q	GOLDBERG, S. C.	7907180928	50-338 Q
GILBERT, L. D.	7907050195*	50-298 Q	GOLDBERG, S. C.	7907190457	50-250 Q
GILBERT, R. A.	7907090326	50-592 Q	GOLDMARK, P. C.	7907230660*	COMMISSION
GILINSKY, V.	7907160159*	70-143	GOLDSMITH, M. W.	7907090409*	50-322 Q
GILINSKY, V.	7907030360	10CFR	GOLDSTEIN, R. M.	7907090003*	50-522 Q
GILINSKY, V.	7907030364	10CFR	GOLDSMITH, R.	7907050406	50-320 P
GILINSKY, V.	7907090011	10CFR	GOLDSMITH, R.	7907120208	50-320 H
GILINSKY, V.	7907090015	50-334 T	GOLLER, K. R.	7907190311	50-320 H
GILINSKY, V.	7907090019	50-219 T	GODDHOPE, A. C.	7907190499	50-471 Q
GILINSKY, V.	7907090030	10CFR	GODDHOPE, A. C.	7907300144	50-471 T
GILINSKY, V.	7907090032	10CFR	GODDHOPE, A. C.	7907250194	50-471 T
GILINSKY, V.	7907160246	10CFR	GODDHOPE, A. C.	7907310044	50-471 T
GILINSKY, V.	7907160255	10CFR	GODDHOPE, A. C.	7907310054	50-471 T
GILINSKY, V.	7907030343	10CFR	GODDHOPE, A. C.	7907300139	50-471 T
GILINSKY, V.	7907030354	10CFR	GODWIN, D. A.	7907200494	PRM
GILINSKY, V.	7907030375	10CFR	GODWIN, W. L.	7907300062*	70-1151
GILINSKY, V.	7907030410	10CFR	GODWIN, C.	7907090245	50-344 S
GILINSKY, V.	7907030413	10CFR	GODWIN, C.	7907050407	50-344 Q
GILINSKY, V.	7907100122	50-320 T	GODWIN, C.	7907090183	50-344 Q
GILINSKY, V.	7907100124	50-320 T	GODWIN, C.	7907030432	50-344 Q
GILINSKY, V.	7907160186	10CFR	GODWIN, C.	7907190590	50-344 F
GILINSKY, V.	7907160211	10CFR	GODWIN, C.	7907300366	50-344 F
GILINSKY, V.	7907030089	10CFR	GOPPEL, M.	7907130234	XPORTLIC
GILINSKY, V.	7907030309	10CFR	GOPPEL, M.	7907300333	XPORTLIC
GILINSKY, V.	7907100121	50-320 T	GOPPEL, M.	7907130508	XPORTLIC
GILINSKY, V.	7907120499	10CFR	GOPPEL, M.	7907120047	XPORTLIC
GILINSKY, V.	7907120520	10CFR	GOPPEL, M.	7907090408	XPORTLIC
GILINSKY, V.	7907170093	50-289 T	GOPPEL, M.	7907300165	XPORTLIC
GILINSKY, V.	7907190573	10CFR	GOPPEL, M.	7907310105	XPORTLIC

# PERSONAL AUTHOR INDEX

395

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GOPPEL, M	7907310113	XPORTLIC	GRIDLEY, R L	7907060287	TOPREP
GORDON, J B	7907200393	FR	GRIDLEY, R L	7907170143	TOPREP
GORDON, Q M	7907230750	NUREQ	GRIDLEY, B H	7907070444	50-213 Q
GORE, J W	7907090219	50-317 P	GRIDLEY, B H	7907100230	50-57 Q
GORMLY, H J	7907020452	50-275 Q	GRIDLEY, B H	7907100233	50-201 Q
GOSSELIN, P Q	7907030180	50-29 S	GRIDLEY, B H	7907100239	50-193 Q
GOSBICK, L V	7907180137	FOIA	GRIDLEY, B H	7907030054	50-333 Q
GOSBICK, L V	7812290248	NUREQ	GRIDLEY, B H	7907060373	50-293 Q
GOSBICK, L V	7907090174	SECY	GRIDLEY, B H	7907060375	50-317 Q
GOSBICK, L V	7905040159	50-320 P	GRIDLEY, B H	7907060376	50-3 Q
GOSBICK, L V	7905040162*	50-320 P	GRIDLEY, B H	7907060377	50-213 Q
GOSBICK, L V	7907120710	50-320 P	GRIDLEY, B H	7907060380	50-334 Q
GOSBICK, L V	7905230310	50-320 P	GRIDLEY, B H	7907060381	50-412 Q
GOSBICK, L V	7906280255	FR	GRIDLEY, B H	7907060382	50-219 Q
GOSBICK, L V	7907060144	50-275 Q	GRIDLEY, B H	7907060384	50-363 Q
GOSBICK, L V	7907110646	50-320 H	GRIDLEY, B H	7907060387	50-322 Q
GOSBICK, L V	7907120349*	50-275 H	GRIDLEY, B H	7907060388	50-289 Q
GOSBICK, L V	7907130288	PRM	GRIDLEY, B H	7907060389	50-309 Q
GOSBICK, L V	7907090472	50-320 P	GRIDLEY, B H	7907060392	50-245 Q
GOSBICK, L V	7907260082	50-445 U	GRIDLEY, B H	7907060394	50-410 Q
GOSBICK, L V	7907260520	50-320 U	GRIDLEY, B H	7907060395	50-220 Q
GOSBICK, L V	7907260398	50-255 U	GRIDLEY, B H	7907060398	50-286 Q
GOSBICK, L V	7907260059	50-313 U	GRIDLEY, B H	7907060399	50-333 Q
GOSBICK, L V	7907260246	PRDJ	GRIDLEY, B H	7907060401	50-277 Q
GOSBICK, L V	7907260388	50-272 Q	GRIDLEY, B H	7907060422	50-352 Q
GOSBICK, L V	7907230739	50-280 U	GRIDLEY, B H	7907060423	50-387 Q
GOSBICK, L V	7907260009	50-309 U	GRIDLEY, B H	7907060425	50-311 Q
GOSBICK, L V	7907180809*	50-338 Q	GRIDLEY, B H	7907060428	50-272 Q
GOSBICK, L V	7907310071	50-463 U	GRIDLEY, B H	7907060429	50-443 Q
GOSBICK, L V	7907310122	50-382 U	GRIDLEY, B H	7907060431	50-244 Q
GOSBICK, L V	7907310145	50-275 U	GRIDLEY, B H	7907060432	50-485 Q
GOSBICK, L V	7907310172	50-546 U	GRIDLEY, B H	7907060433	50-271 Q
GOSBICK, L V	7907310202	50-382 U	GRIDLEY, B H	7907060436	50-29 Q
GOSBICK, L V	7907310244	50-382 U	GRIDLEY, B H	7907260008	70-364
GOSBICK, L V	7907310261	50-338 U	GRIDLEY, B H	7907260012	50-201 P
GOSBICK, L V	7907030057	50-320 P	GRIDLEY, B H	7907260013	70-33
GOSBICK, L V	7907030071	50-320 U	GRIDLEY, B H	7907260015	70-820
GOTCHY, R	7907120729	50-320 T	GRIDLEY, B H	7907260019	70-371
GOUGE, M J	7907240285*	50-424 Q	GRIDLEY, B H	7907260021	70-1143
GOULDING, P E	7907120565*	50-568 A	GRIDLEY, B H	7907260033	50-293 P
GOWER, Q C	7907240340	50-320 B	GRIDLEY, B H	7907260037	50-317 P
GRAHAM, M E	7907030336	50-324 J	GRIDLEY, B H	7907260040	50-247 P
GRAHAM, M E	7907240321	50-324 J	GRIDLEY, B H	7907260042	50-213 P
GRAHAM, M J	7907120560*	50-324 Q	GRIDLEY, B H	7907260049	50-334 P
GRANLUND, R W	7907260635	PRM	GRIDLEY, B H	7907260052	50-219 P
GRANT, J B	7907050015	50-346 Q	GRIDLEY, B H	7907260053	50-320 P
GRANT, J B	7907090085	50-346 Q	GRIDLEY, B H	7907260054	50-289 P
GRANT, J B	7907180270*	50-346 Q	GRIDLEY, B H	7907260058	50-309 P
GRANT, M B	7907260240*	50-10 Q	GRIDLEY, B H	7907260060	50-245 P
GRANT, M B	7907100347	50-320 H	GRIDLEY, B H	7907260061	50-220 P
GRAVELLE, R. D.	7907260583*	50-592 Q	GRIDLEY, B H	7907260064	50-333 P
GRAVES, R. H.	7907170017	50-213 S	GRIDLEY, B H	7907260067	50-286 P
GRAVES, R. H.	7907180525	50-213 S	GRIDLEY, B H	7907260069	50-277 P
GRAVES, R. H.	7907260710	50-213 S	GRIDLEY, B H	7907260071	50-272 P
GRAY, J R	7907030207	50-344 Q	GRIDLEY, B H	7907260072	50-311 A
GRAY, J R.	7907030179	50-344 Q	GRIDLEY, B H	7907260073	50-244 P
GRAY, J R.	7907060321	50-344 Q	GRIDLEY, B H	7907260077	50-271 P
GRAY, J R.	7907120161	50-463 Q	GRIDLEY, B H	7907260080	50-29 P
GRAY, J R.	7907060320	50-344 Q	GRIDLEY, B H	7907030016	50-293 Q
GRAY, J R.	7907130051	50-344 Q	GRIDLEY, B H	7907030018	50-317 Q
GRAY, J R.	7907160284	50-463 Q	GRIDLEY, B H	7907030021	50-3 Q
GRAY, J R.	7907180716	50-344 Q	GRIDLEY, B H	7907030023	50-213 Q
GRAY, J R.	7907180719*	50-344 Q	GRIDLEY, B H	7907030025	50-334 Q
GREENAUD, S	7907190198	50-361 Q	GRIDLEY, B H	7907030027	50-412 Q
GREEN, I. D.	7907110206	50-312 P	GRIDLEY, B H	7907030030	50-219 Q
GREENBERG, R. B.	7907310045	FR	GRIDLEY, B H	7907030033	50-322 Q
GREENE, T. V.	7907110485*	50-321 S	GRIDLEY, B H	7907030037	50-320 Q
GREENE, T. V.	7907090344*	50-366 S	GRIDLEY, B H	7907030038	50-309 Q
GREENE, T. V.	7907170218*	50-321 S	GRIDLEY, B H	7907030041	50-245 Q
GREENE, T. V.	7907180499*	50-321 S	GRIDLEY, B H	7907030044	50-220 Q
GREENE, T. V.	7907180551*	50-366 S	GRIDLEY, B H.	7907030046	50-410 Q
GREENE, T. V.	7907170209*	50-321 S	GRIDLEY, B H.	7907030049	50-333 Q
GREENE, T. V.	7907170219*	50-366 S	GRIDLEY, B H.	7907030050	50-286 Q
GREENE, T. V.	7907230553*	50-366 S	GRIDLEY, B H.	7907030053	50-277 Q
GREEN, D.	7907170126*	50-259 R	GRIDLEY, B H	7907030055	50-352 Q
GREER, R. J.	7907130320*	50-341 Q	GRIDLEY, B H	7907030059	50-387 Q
GREER, R. J.	7907260240*	50-10 Q	GRIDLEY, B H.	7907030061	50-311 Q
GREGER, L. R.	7907100441	50-320 H	GRIDLEY, B H.	7907030064	50-272 Q
GREGER, L. R.	7907280211*	50-255 Q	GRIDLEY, B H.	7907030069	50-443 Q
REGO, R. J.	7907190030*	71-4949	GRIDLEY, B H	7907030072	50-485 Q
GREGORY, M. B.	7907130051	FR	GRIDLEY, B H.	7907030074	50-244 Q
GREW, P. C.	7907170080	50-312 P	GRIDLEY, B H.	7907030077	50-271 Q
GREY, R.	7907180240	50-596 Q	GRIDLEY, B H	7907030078	50-29 Q
GREY, R.	7907260476	50-596 Q	GRIDLEY, B H.	7907260078	50-293 Q
GRIBBLE, R. M.	7907260566	50-320 P	GRIDLEY, B H	7907260086	50-3 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GRIER, B. H.	7907200093	50-213 Q	GRIER, B. H.	7907020054	50-443 Q
GRIER, B. H.	7907200095	50-334 Q	GRIER, B. H.	7907020056	50-485 Q
GRIER, B. H.	7907200098	50-412 Q	GRIER, B. H.	7907020057	50-567 Q
GRIER, B. H.	7907200103	50-219 Q	GRIER, B. H.	7907020059	50-568 Q
GRIER, B. H.	7907200104	50-363 Q	GRIER, B. H.	7907270384	50-220 Q
GRIER, B. H.	7907200107	50-322 Q	GRIER, B. H.	7907110710	50-277 Q
GRIER, B. H.	7907200108	50-320 Q	GRIER, B. H.	7907100466	50-293 Q
GRIER, B. H.	7907200110	50-309 Q	GRIER, B. H.	7907100467	50-317 Q
GRIER, B. H.	7907200114	50-336 Q	GRIER, B. H.	7907100468	50-363 Q
GRIER, B. H.	7907200115	50-245 Q	GRIER, B. H.	7907100471	50-322 Q
GRIER, B. H.	7907200117	50-220 Q	GRIER, B. H.	7907100473	50-245 Q
GRIER, B. H.	7907200121	50-410 Q	GRIER, B. H.	7907100475	50-220 Q
GRIER, B. H.	7907200124	50-333 Q	GRIER, B. H.	7907100476	50-286 Q
GRIER, B. H.	7907200126	50-286 Q	GRIER, B. H.	7907100478	50-272 Q
GRIER, B. H.	7907200131	50-277 Q	GRIER, B. H.	7907100480	50-244 Q
GRIER, B. H.	7907200134	50-352 Q	GRIER, B. H.	7907100481	50-29 Q
GRIER, B. H.	7907200139	50-387 Q	GRIER, B. H.	7907110361	50-3 Q
GRIER, B. H.	7907200142	50-311 Q	GRIER, B. H.	7907110363	50-213 Q
GRIER, B. H.	7907200144	50-272 Q	GRIER, B. H.	7907110364	50-334 Q
GRIER, B. H.	7907200147	50-443 Q	GRIER, B. H.	7907110367	50-412 Q
GRIER, B. H.	7907200150	50-465 Q	GRIER, B. H.	7907110368	50-219 Q
GRIER, B. H.	7907200151	50-244 Q	GRIER, B. H.	7907110370	50-289 Q
GRIER, B. H.	7907200153	50-271 Q	GRIER, B. H.	7907110373	50-309 Q
GRIER, B. H.	7907200156	50-29 Q	GRIER, B. H.	7907110375	50-410 Q
GRIER, B. H.	7907190040	50-293 Q	GRIER, B. H.	7907110378	50-333 Q
GRIER, B. H.	7907190043	50-317 Q	GRIER, B. H.	7907110379	50-352 Q
GRIER, B. H.	7907190044	50-3 Q	GRIER, B. H.	7907110381	50-277 Q
GRIER, B. H.	7907190045	50-213 Q	GRIER, B. H.	7907110386	50-387 Q
GRIER, B. H.	7907190047	50-412 Q	GRIER, B. H.	7907110389	50-311 Q
GRIER, B. H.	7907190051	50-334 Q	GRIER, B. H.	7907110391	50-443 Q
GRIER, B. H.	7907190052	50-219 Q	GRIER, B. H.	7907110392	50-485 Q
GRIER, B. H.	7907190054	50-363 Q	GRIER, B. H.	7907110394	50-271 Q
GRIER, B. H.	7907190057	50-322 Q	GRIER, B. H.	7907230642	50-293 Q
GRIER, B. H.	7907190062	50-320 Q	GRIER, B. H.	7907230644	50-317 Q
GRIER, B. H.	7907190064	50-309 Q	GRIER, B. H.	7907230647	50-3 Q
GRIER, B. H.	7907190069	50-245 Q	GRIER, B. H.	7907230650	50-213 Q
GRIER, B. H.	7907190071	50-410 Q	GRIER, B. H.	7907230663	50-334 Q
GRIER, B. H.	7907190084	50-220 Q	GRIER, B. H.	7907230665	50-412 Q
GRIER, B. H.	7907190087	50-286 Q	GRIER, B. H.	7907230669	50-219 Q
GRIER, B. H.	7907190089	50-333 Q	GRIER, B. H.	7907230672	50-363 Q
GRIER, B. H.	7907190094	50-277 Q	GRIER, B. H.	7907230674	50-322 Q
GRIER, B. H.	7907190098	50-352 Q	GRIER, B. H.	7907230677	50-320 Q
GRIER, B. H.	7907190099	50-387 Q	GRIER, B. H.	7907230679	50-309 Q
GRIER, B. H.	7907190102	50-311 Q	GRIER, B. H.	7907230681	50-245 Q
GRIER, B. H.	7907190104	50-272 Q	GRIER, B. H.	7907230683	50-410 Q
GRIER, B. H.	7907190109	50-443 Q	GRIER, B. H.	7907230685	50-220 Q
GRIER, B. H.	7907190113	50-485 Q	GRIER, B. H.	7907230689	50-286 Q
GRIER, B. H.	7907190116	50-244 Q	GRIER, B. H.	7907230691	50-333 Q
GRIER, B. H.	7907190119	50-271 Q	GRIER, B. H.	7907230693	50-277 Q
GRIER, B. H.	7907190123	50-29 Q	GRIER, B. H.	7907230695	50-352 Q
GRIER, B. H.	7907060079	50-293 Q	GRIER, B. H.	7907230697	50-387 Q
GRIER, B. H.	7907060081	50-317 Q	GRIER, B. H.	7907230700	50-311 Q
GRIER, B. H.	7907060083	50-3 Q	GRIER, B. H.	7907230704	50-272 Q
GRIER, B. H.	7907060084	50-213 Q	GRIER, B. H.	7907230706	50-244 Q
GRIER, B. H.	7907060090	50-234 Q	GRIER, B. H.	7907230709	50-485 Q
GRIER, B. H.	7907060092	50-412 Q	GRIER, B. H.	7907230712	50-271 Q
GRIER, B. H.	7907060095	50-219 Q	GRIER, B. H.	7907230715	50-29 Q
GRIER, B. H.	7907060096	50-363 Q	GRIER, B. H.	7907230388	50-84 Q
GRIER, B. H.	7907060101	50-322 Q	GRIER, B. H.	7907230392	50-77 Q
GRIER, B. H.	7907060103	50-320 Q	GRIER, B. H.	7907230394	50-208 Q
GRIER, B. H.	7907060105	50-309 Q	GRIER, B. H.	7907230396	50-97 Q
GRIER, B. H.	7907060106	50-245 Q	GRIER, B. H.	7907230398	50-199 Q
GRIER, B. H.	7907060109	50-220 Q	GRIER, B. H.	7907230400	50-20 Q
GRIER, B. H.	7907060110	50-410 Q	GRIER, B. H.	7907240135	40-3392
GRIER, B. H.	7907060114	50-286 Q	GRIER, B. H.	7907240139	70-135
GRIER, B. H.	7907060115	50-333 Q	GRIER, B. H.	7907240142	70-1100
GRIER, B. H.	7907060118	50-352 Q	GRIER, B. H.	7907240143	70-36
GRIER, B. H.	7907060121	50-277 Q	GRIER, B. H.	7907240160	70-33
GRIER, B. H.	7907060123	50-387 Q	GRIER, B. H.	7907240161	70-371
GRIER, B. H.	7907060126	50-272 Q	GRIER, B. H.	7907240165	70-820
GRIER, B. H.	7907060128	50-311 Q	GRIER, B. H.	7907240171	70-698
GRIER, B. H.	7907060130	50-443 Q	GRIER, B. H.	7907240128	50-293 Q
GRIER, B. H.	7907060133	50-244 Q	GRIER, B. H.	7907240131	50-317 Q
GRIER, B. H.	7907060135	50-485 Q	GRIER, B. H.	7907240136	50-3 Q
GRIER, B. H.	7907060145	50-271 Q	GRIER, B. H.	7907240140	50-213 Q
GRIER, B. H.			GRIER, B. H.	7907240147	50-334 Q
GRIER, B. H.			GRIER, B. H.	7907240150	50-217 Q
GRIER, B. H.			GRIER, B. H.	7907240154	50-320 Q
GRIER, B. H.			GRIER, B. H.	7907240166	50-309 Q
GRIER, B. H.			GRIER, B. H.	7907240174	50-245 Q
GRIER, B. H.			GRIER, B. H.	7907240182	50-220 Q
GRIER, B. H.			GRIER, B. H.	7907240185	50-286 Q
GRIER, B. H.			GRIER, B. H.	7907240194	50-333 Q
GRIER, B. H.			GRIER, B. H.	7907240198	50-277 Q
GRIER, B. H.			GRIER, B. H.	7907240202	50-272 Q

# PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ORIER, B. H.	7907240203	50-244 Q	ORIER, B. H.	7907110026	50-334 Q
ORIER, B. H.	7907240208	50-271 Q	ORIER, B. H.	7907110027	50-245 Q
ORIER, B. H.	7907240211	50-29 Q	ORIER, B. H.	7907110029	50-286 Q
ORIER, B. H.	7907120474	50-293 Q	ORIER, B. H.	7907110031	50-277 Q
ORIER, B. H.	7907120479	50-317 Q	ORIER, B. H.	7907110033	50-387 Q
ORIER, B. H.	7907120483	50-3 Q	ORIER, B. H.	7907110035	50-311 Q
ORIER, B. H.	7907120487	50-213 Q	ORIER, B. H.	7907110038	50-443 Q
ORIER, B. H.	7907120489	50-412 Q	ORIER, B. H.	7907110039	50-485 Q
ORIER, B. H.	7907120491	50-334 Q	ORIER, B. H.	7907180615	50-320 Q
ORIER, B. H.	7907120494	50-219 Q	ORIER, B. H.	7907310094	50-333 Q
ORIER, B. H.	7907120497	50-363 Q	ORIER, B. H.	7907180746	50-293 Q
ORIER, B. H.	7907120500	50-322 Q	ORIER, B. H.	7907180748	50-317 Q
ORIER, B. H.	7907120504	50-309 Q	ORIER, B. H.	7907180753	50-3 Q
ORIER, B. H.	7907120507	50-245 Q	ORIER, B. H.	7907180758	50-213 Q
ORIER, B. H.	7907120509	50-336 Q	ORIER, B. H.	7907180760	50-412 Q
ORIER, B. H.	7907120510	50-220 Q	ORIER, B. H.	7907180764	50-334 Q
ORIER, B. H.	7907120515	50-410 Q	ORIER, B. H.	7907180767	50-363 Q
ORIER, B. H.	7907120516	50-333 Q	ORIER, B. H.	7907180770	50-217 Q
ORIER, B. H.	7907120519	50-286 Q	ORIER, B. H.	7907180775	50-322 Q
ORIER, B. H.	7907120522	50-352 Q	ORIER, B. H.	7907180776	50-309 Q
ORIER, B. H.	7907120526	50-277 Q	ORIER, B. H.	7907180779	50-245 Q
ORIER, B. H.	7907120528	50-387 Q	ORIER, B. H.	7907180782	50-220 Q
ORIER, B. H.	7907120536	50-311 Q	ORIER, B. H.	7907180788	50-410 Q
ORIER, B. H.	7907120539	50-272 Q	ORIER, B. H.	7907180790	50-286 Q
ORIER, B. H.	7907120543	50-443 Q	ORIER, B. H.	7907180793	50-333 Q
ORIER, B. H.	7907120578	50-244 Q	ORIER, B. H.	7907180799	50-277 Q
ORIER, B. H.	7907120581	50-485 Q	ORIER, B. H.	7907180802	50-352 Q
ORIER, B. H.	7907120584	50-271 Q	ORIER, B. H.	7907180805	50-387 Q
ORIER, B. H.	7907120585	50-29 Q	ORIER, B. H.	7907180811	50-311 Q
ORIER, B. H.	7907180365	50-320 Q	ORIER, B. H.	7907180814	50-272 Q
ORIER, B. H.	7907060172	50-293 Q	ORIER, B. H.	7907180818	50-443 Q
ORIER, B. H.	7907060174	50-317 Q	ORIER, B. H.	7907180822	50-244 Q
ORIER, B. H.	7907060177	50-3 Q	ORIER, B. H.	7907180823	50-485 Q
ORIER, B. H.	7907060180	50-213 Q	ORIER, B. H.	7907180831	50-271 Q
ORIER, B. H.	7907060182	50-334 Q	ORIER, B. H.	7907180834	50-29 Q
ORIER, B. H.	7907060185	50-363 Q	ORIER, B. H.	7907250348	50-193 Q
ORIER, B. H.	7907060187	50-219 Q	ORIER, B. H.	7907250352	50-54 Q
ORIER, B. H.	7907060190	50-289 Q	ORIER, B. H.	7907250357	50-22 Q
ORIER, B. H.	7907060192	50-309 Q	ORIER, B. H.	7907250437	50-170 Q
ORIER, B. H.	7907060195	50-245 Q	ORIER, B. H.	7907250440	50-47 Q
ORIER, B. H.	7907060198	50-220 Q	ORIER, B. H.	7907250442	50-184 Q
ORIER, B. H.	7907060200	50-277 Q	ORIER, B. H.	7907250450	50-77 Q
ORIER, B. H.	7907100308	50-412 Q	ORIER, B. H.	7907250451	50-208 Q
ORIER, B. H.	7907100308	50-322 Q	ORIER, B. H.	7907250453	50-97 Q
ORIER, B. H.	7907100316	50-410 Q	ORIER, B. H.	7907250454	50-199 Q
ORIER, B. H.	7907100348	50-286 Q	ORIER, B. H.	7907250457	50-20 Q
ORIER, B. H.	7907100351	50-333 Q	ORIER, B. H.	7907250460	50-5 Q
ORIER, B. H.	7907100353	50-352 Q	ORIER, B. H.	7907250467	50-87 Q
ORIER, B. H.	7907100361	50-387 Q	ORIER, B. H.	7907250469	50-223 Q
ORIER, B. H.	7907100363	50-311 Q	ORIER, B. H.	7907250471	50-166 Q
ORIER, B. H.	7907100367	50-272 Q	ORIER, B. H.	7907250474	50-2 Q
ORIER, B. H.	7907100371	50-443 Q	ORIER, B. H.	7907250477	50-134 Q
ORIER, B. H.	7907100373	50-485 Q	ORIER, B. H.	7907250490	50-293 Q
ORIER, B. H.	7907100376	50-244 Q	ORIER, B. H.	7907250492	50-317 Q
ORIER, B. H.	7907100379	50-271 Q	ORIER, B. H.	7907250494	50-3 Q
ORIER, B. H.	7907100381	50-29 Q	ORIER, B. H.	7907250496	50-213 Q
ORIER, B. H.	7907100409	50-596 Q	ORIER, B. H.	7907250501	50-334 Q
ORIER, B. H.	7907100412	50-568 Q	ORIER, B. H.	7907250503	50-219 Q
ORIER, B. H.	7907100413	50-471 Q	ORIER, B. H.	7907250505	50-309 Q
ORIER, B. H.	7907100415	50-412 Q	ORIER, B. H.	7907250509	50-245 Q
ORIER, B. H.	7907100416	50-363 Q	ORIER, B. H.	7907250510	50-220 Q
ORIER, B. H.	7907100418	50-322 Q	ORIER, B. H.	7907250513	50-333 Q
ORIER, B. H.	7907100420	50-423 Q	ORIER, B. H.	7907250520	50-886 Q
ORIER, B. H.	7907100422	50-410 Q	ORIER, B. H.	7907250521	50-277 Q
ORIER, B. H.	7907100424	50-352 Q	ORIER, B. H.	7907250522	50-272 Q
ORIER, B. H.	7907100426	50-387 Q	ORIER, B. H.	7907250527	50-244 Q
ORIER, B. H.	7907100429	50-311 Q	ORIER, B. H.	7907250529	50-271 Q
ORIER, B. H.	7907100431	50-443 Q	ORIER, B. H.	7907250532	50-29 Q
ORIER, B. H.	7907100434	50-485 Q	ORIER, B. H.	7907260257	50-223 Q
ORIER, B. H.	7907100491	50-293 Q	ORIER, B. H.	7907270316	50-293 Q
ORIER, B. H.	7907100492	50-317 Q	ORIER, B. H.	7907270318	50-317 Q
ORIER, B. H.	7907100494	50-3 Q	ORIER, B. H.	7907270320	50-3 Q
ORIER, B. H.	7907100496	50-213 Q	ORIER, B. H.	7907270326	50-213 Q
ORIER, B. H.	7907100497	50-412 Q	ORIER, B. H.	7907270329	50-334 Q
ORIER, B. H.	7907100498	50-219 Q	ORIER, B. H.	7907270331	50-412 Q
ORIER, B. H.	7907100501	50-363 Q	ORIER, B. H.	7907270333	50-219 Q
ORIER, B. H.	7907100502	50-322 Q	ORIER, B. H.	7907270335	50-363 Q
ORIER, B. H.	7907100503	50-309 Q	ORIER, B. H.	7907270337	50-322 Q
ORIER, B. H.	7907100505	50-410 Q	ORIER, B. H.	7907270339	50-309 Q
ORIER, B. H.	7907100506	50-333 Q	ORIER, B. H.	7907270342	50-245 Q
ORIER, B. H.	7907100507	50-352 Q	ORIER, B. H.	7907270344	50-410 Q
ORIER, B. H.	7907100508	50-272 Q	ORIER, B. H.	7907270347	50-220 Q
ORIER, B. H.	7907100510	50-244 Q	ORIER, B. H.	7907270349	50-286 Q
ORIER, B. H.	7907100512	50-271 Q	ORIER, B. H.	7907270352	50-333 Q
ORIER, B. H.	7907100513	50-29 Q	ORIER, B. H.	7907270353	50-352 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ORIER, B H	7907270358	50-277 Q	GRIMES, C I	7907180842	OEN TEC 1B
ORIER, B H	7907270359	50-387 Q	GRIMES, C I	7907190470	OEN TEC 1B
ORIER, B H	7907270361	50-311 Q	GRIBSINGER, B	7907190831	FR
ORIER, B H	7907270363	50-272 Q	GROCE, R H	7907090102	50-309 Q
ORIER, B H	7907270365	50-443 Q	GROCE, R H	7907260590	50-309 P
ORIER, B H	7907270367	50-244 Q	GROCE, R H	7907300441	50-309 P
ORIER, B H	7907270368	50-485 Q	GROCE, R H	7907310247	50-309 P
ORIER, B H	7907270371	50-271 Q	GROCE, R H	7907030373	50-271 Q
ORIER, B H	7907270373	50-29 Q	GROCE, R H	7907120372	50-271 P
ORIER, B H	7907310482	50-293 Q	GROCE, R H	7907170009	50-271 P
ORIER, B H	7907310483	50-317 Q	GROCE, R H	7907310434	50-271 P
ORIER, B H	7907310487	50-3 Q	GROCE, R H	7907090076	50-29 Q
ORIER, B H	7907310489	50-213 Q	GROCE, R H	7907100427	50-29 P
ORIER, B H	7907310490	50-334 Q	GROCE, R H	7907100594	50-29 P
ORIER, B H	7907310494	50-412 Q	GROCE, R H	7907130283	50-29 P
ORIER, B H	7907310495	50-363 Q	GROCE, R H	7907170145	50-29 P
ORIER, B H	7907310499	50-219 Q	GRDOME, K	7907260138*	GA999
ORIER, B H	7907310502	50-322 Q	GRDOME, K	7907260116*	GA999
ORIER, B H	7907310505	50-289 Q	GROSSMAN, K	7907250385	50-322 A
ORIER, B H	7907310506	50-309 Q	GROSSMAN, Z D	7907200268	PRH
ORIER, B H	7907310509	50-245 Q	GRDTENHUIS, M	7907300514	50-250 P
ORIER, B H	7907310511	50-220 Q	GRDTENHUIS, M	7907020243	50-338 P
ORIER, B H	7907310513	50-410 Q	GRDTENHUIS, M	7907110694	50-250 P
ORIER, B H	7907310520	50-286 Q	GRUENEICH, D M	7907190479	50-592 Q
ORIER, B H	7907310521	50-333 Q	GULBRANSEN, E A	7907180687*	50-272 Q
ORIER, B H	7907310528	50-277 Q	GUMBLE, F W	7907100432*	50-286 S
ORIER, B H	7907310530	50-352 Q	GUNN, T. M	7907060469*	40-1739
ORIER, B H	7907310532	50-387 Q	GUNN, T. W	7907060475*	40-1739
ORIER, B H	7907310533	50-272 Q	GUPPY, J G	7907310149	RES
ORIER, B H	7907310536	50-311 Q	GUSTAFSON, D P	7907300273	PR
ORIER, B H	7907310538	50-443 Q	GUSTAFSON, P F	7907160325*	50-320 P
ORIER, B H	7907310539	50-485 Q	GUSTAVE, R P	7907270093	CONTRACT
ORIER, B H	7907310542	50-244 Q	GUSTAVE, R P	7907260618	CONTRACT
ORIER, B H	7907310544	50-271 Q	GUSTAVE, R P	7907180344	CONTRACT
ORIER, B H	7907310547	50-29 Q	GUTHRIE, G L	7907270337	NUREG
GRIESMEYER, J M	7907190353	NUREG	HAAS, M N	7907020485	70-247
GRIMES, B K	7907130536*	50-346 Q	HAAS, M N	7907310486	71-226
GRIMES, B K	7907180150	FOIA	HAAS, W P	7907260500	50-320 H
GRIMES, C I	7907300232	TOPREP	HAAS, W P	7907110112	50-445 A
GRIMES, B K	7907260533	50-320 H	HAAS, W P	7907060186	50-416 A
GRIMES, B K	7907180235	50-309 P	HAGA, P B	7907250293	50-437 Q
GRIMES, B K	7907130028	50-263 Q	HAGA, P B	7907250380	50-437 A
GRIMES, B K	7907180230	50-344 P	HAGA, P B	7907170180	50-437 A
GRIMES, B K	7907180604	50-348 P	HAGA, P B	7907270173	50-437 A
GRIMES, B K	7907180607	50-293 P	HAGAN, T F	7907080268	CONTRACT
GRIMES, B K	7907180610	50-249 P	HAGAN, T F	7907300473	CONTRACT
GRIMES, B K	7907180618	50-3 P	HAGAN, T F	7907190884	CONTRACT
GRIMES, B K	7907180620	50-261 P	HAGAN, T F	7907270018	CONTRACT
GRIMES, B K	7907180624	50-324 P	HAGEN, E H	7907190169	NUREG
GRIMES, B K	7907180626	50-334 P	HAGER, S B	7907130257*	70-2623
GRIMES, B K	7907180628	50-302 P	HAGEY, H	7907300529	CONTRACT
GRIMES, B K	7907180631	50-335 P	HAGEY, H	7907260602	CONTRACT
GRIMES, B K	7907180632	50-321 P	HAGEY, H	7907100008	CONTRACT
GRIMES, B K	7907180636	50-331 P	HAGEY, H	7907110061	CONTRACT
GRIMES, B K	7907180637	50-313 P	HAGEY, H	7907230705	CONTRACT
GRIMES, B K	7907180639	50-289 P	HAGEY, H	7907110387	CONTRACT
GRIMES, B K	7907180641	50-309 P	HAGEY, H	7907120139	CONTRACT
GRIMES, B K	7907180642	50-336 P	HAGEY, H	7907230694	CONTRACT
GRIMES, B K	7907180644	50-220 P	HAGEY, H	7907190777	CONTRACT
GRIMES, B K	7907180647	50-263 P	HAGEY, H	7907230728	CONTRACT
GRIMES, B K	7907180648	50-298 P	HAGEY, H	7907270076	CONTRACT
GRIMES, B K	7907180649	50-283 P	HAGEY, H	7907180327	CONTRACT
GRIMES, B K	7907180655	50-333 P	HAGGERTY, P E	7907180085	50-320 T
GRIMES, B K	7907180657	50-133 P	HAGGERTY, P E	7907180077	50-320 T
GRIMES, B K	7907180659	50-272 P	HAGGERTY, P E	7907180092	50-320 T
GRIMES, B K	7907180661	50-346 P	HAGGERTY, P E	7907180106	50-320 T
GRIMES, B K	7907180663	50-271 P	HAGGERTY, P E	7907180109*	50-320 T
GRIMES, B K	7907250001	50-317 P	HAGGERTY, P E	7907180022	50-320 T
GRIMES, B K	7907250004	50-254 P	HAGGERTY, P E	7907180013	50-320 T
GRIMES, B K	7907250006	50-295 P	HAGGERTY, P E	7907180073	50-320 T
GRIMES, B K	7907250007	50-249 P	HAGGERTY, P E	7907180003	50-320 T
GRIMES, B K	7907250008	50-250 P	HAGUE, R L	7907100331	50-320 H
GRIMES, B K	7907250009	50-315 P	HAINES, J F	7907250284	PR
GRIMES, B K	7907250012	50-282 P	HAIRSTON, W G	7907090364	50-348 A
GRIMES, B K	7907250013	50-286 P	HAIRSTON, W G	7907180473*	50-348 R
GRIMES, B K	7907250014	50-277 P	HAIRSTON, W G	7907100295*	50-348 S
GRIMES, B K	7907250015	50-312 P	HAIRSTON, W G	7907170059*	50-348 S
GRIMES, B K	7907250018	50-259 P	HAIRSTON, W G	7907170071*	50-348 S
GRIMES, B K	7907250020	50-280 P	HAIRSTON, W G	7907240367*	50-348 S
GRIMES, B K	7907250021	50-266 P	HAIRSTON, W G	7907240376*	50-348 S
GRIMES, B K	7907250025	50-303 P	HAIRSTON, W G	7907240379*	50-348 S
GRIMES, B K	7907100057	50-320 P	HAIST, D. P	7907110725*	50-361 Q
GRIMES, B K	7907100123	50-320 P	HAIST, D. P	7907260649*	50-361 Q
GRIMES, B K	7907250595*	50-269 P	HAIST, D. P	7907270015*	50-206 Q
GRIMES, C I	7907060266	OEN TEC 1B	HALAPATZ, J	7907120193	50-320 W

# PERSONAL AUTHOR INDEX

399

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HALE, C J	7907110069*	GA999	HART, G	7907310621*	COMMISSION
HALE, C J	7907050109*	GA999	HART, G	7907090068*	SECY
HALE, C J	7907030032*	GA999	HARTER, E B	7907030104	XPORTLIC
HALE, C J	7907130349*	GA999	HARTMAN, C J	7907130393	50-155
HALE, C J	7907230074*	GA999	HARVEY, S W	7907130397	50-302 P
HALE, C J	7907230308*	GA999	HASTINGS, W	7907050051	50-514
HALE, C J	7907230736*	GA999	HASTINGS, W	7907180837	50-522
HALL, R E	7907300393	50-266 F	HAYEN, T J	7907190427	WASTE HOT
HALL, R E	7907100533	50-282 F	HATLING, J	7907050023	50-320 P
HALL, R E	7907310175	50-282 F	HAUGHNEY, C F	7907110238	50-201 P
HALL, R E	7907230913	50-10 F	HAUGHNEY, C J	7907130079	50-201 P
HALL, R E	7907310186	50-10 F	HAUPT, C A	7907110656	50-599 A
HALL, R E	7907110747*	50-482 G	HAVERKAMP, D R	7907200904*	50-289 G
HALL, R E	7907260561*	50-445 G	HAWKINS, F C	7907180474*	50-546 G
HALL, R E	7907310603*	50-482 G	HAWKINS, D G	7907110008*	50-320 D
HALL, R E	7907180226*	50-382 G	HAWKINS, F C	7907240172*	50-546 G
HALL, R E	7907110418*	50-382 G	HAYES, H	7907240579	PRM
HALL, R E	7907310126*	50-466 G	HAYES, D W	7907300926*	50-305 G
HALL, R E	7907260492*	50-498 G	HAYES, D W	7907300046*	50-373 G
HALLER, N M	7907030155*	FDIA	HAYES, D W	7907240172*	50-546 G
HALLER, N M	7907270227	PROJ	HAYES, D W	7907310206*	50-315 G
HALMAN, E L	7907270041*	CONTRACT	HAYNES, J Q	7907030455	50-206 P
HAMILTON, D R	7907230779	PR	HAYNES, J Q	7907030474	50-206 P
HAMILTON, O W	7907200263	PRM	HAYNES, J Q	7907090252	50-361 K
HAMILTON, L D	7907130237*	70-2623	HAYNES, J Q	7907170212	50-206 P
HAMMOND, E L	7907090242	50-331 P	HAYNES, J Q	7907130459	50-361 A
HAMMOND, E L	7907100562	50-331 S	HAYNES, J Q	7907090261	50-206 P
HAMMOND, E L	7907200366	50-331 S	HAYNES, R C	7907120419*	50-460 G
HAMMOND, E L	7907190571	50-331 R	HAYNES, R C	7907030094*	50-397 G
HAMMOND, E L	7907230555	50-331 S	HAYNES, R C	79070500392*	50-397 G
HAN, K	7907130194*	GA999	HAYNES, R C	7907110725*	50-361 G
HAN, K	7907130191*	GA999	HAYNES, R C	7907110634*	50-397 G
HAN, S Y	7907180820	XPORTLIC	HAYNES, R C	7907260649*	50-361 G
HANAUER, S H	7907020144	50-320 P	HAYNES, R C	7907300107*	50-508 G
HANAUER, S H	7907260493*	50-320 P	HAYNES, R C	7907260557*	50-397 G
HANAUER, S H	7907200512	OEN TEC IS	HEAD, J T	7907050413	50-206 G
HAND, R C	7907090409*	50-322 G	HEAD, J T	7907050390	50-206 G
HAND, C H	7907250070	70-2623	HEAD, J T	7907300052	50-206 G
HAND, C H	7907030291	70-2623	HEAD, J T	7907050442	50-206 G
HAND, C H	7907030189	70-2623	HEADON, F	7907160345	50-320 P
HAND, C H	7907120121	70-2623	HECKMAN, R A	7907250299	NUREQ
HAND, C H	7907250105	70-2623	HECKMAN, R A	7907270404	NUREQ
HAND, C H	7907250146	70-2623	HEEDLESON, F A	7907030426	NUREQ
HAND, C H	7907290081	70-2623	HEISHMAN, R F	7907270127	50-263 G
HAND, C H	7907250092	70-2623	HEISHMAN, R F	7907260524	50-301 G
HAND, C H	7907250135	70-2623	HEISHMAN, R F	7907110120	50-305 G
HAND, C H	7907250162	70-2623	HEISHMAN, R F	7907260290	50-155 G
HANDLER, S J	7907060153	50-295 P	HEISHMAN, R F	7907270392	50-315 G
HANECEK, R F	7907170059	50-10 P	HEISHMAN, R F	7907180416	50-331 G
HANES, J F	7907180247	50-329 T	HEISHMAN, R F	7907190492	50-10 G
HANNON, J N	7907030051	50-324 P	HEISHMAN, R F	7907180274	50-295 G
HANNON, J N	7907090374	50-293 G	HEISHMAN, R F	7907180394	50-255 G
HANNON, J N	7907190297	50-324 P	HEISHMAN, R F	7907240106	50-301 G
HANNON, J N	7907230335	50-324 P	HEISHMAN, R F	7907240187	50-409 G
HANNON, J N	7907260031	50-10 P	HEISHMAN, R F	7907240195	50-282 G
HANNUM, D	7907240369	50-254 R	HEISHMAN, R F	7907250076	50-266 G
HANNUM, D	7907240362	50-254 R	HEISHMAN, R F	7907240623	50-305 G
HANB, J M	7907110192*	50-320 G	HEISHMAN, R F	7907240124	50-373 G
HANBELL, J R	7907190635	PRM	HEISHMAN, R F	7907240144	50-266 G
HANSEN, L E	7907230511*	71-6581	HEISHMAN, R F	7907260252	50-409 G
HANSELL, D	7907230110	PR	HEISHMAN, R F	7907300331	50-263 G
HANSEN, W A	7907050187*	50-482 G	HEISHMAN, R F	7907180296*	50-346 G
HANSEN, W A	7907250216*	50-483 G	HEISHMAN, R F	7907260810	50-237 G
HARDIN, A K	7907180658*	50-348 G	HEISHMAN, R F	7907300083	50-315 G
HARDIN, A K	7907060448	50-269 P	HEISHMAN, R F	7907310015	50-331 G
HARDY, J E	7907120070	RES	HEISHMAN, R F	7907310080	50-254 G
HARGETT, D J	7907250124*	CONTRACT	HEISHMAN, R F	7907310180	50-116 G
HARGETT, D J	7907310504*	CONTRACT	HEISHMAN, R F	7907310213	50-388 G
HARGETT, D J	7907250231*	CONTRACT	HEISHMAN, R F	7907180304	50-284 G
HARMON, D W	7907240205	XPORTLIC	HEISHMAN, R F	7907300017	50-331 G
HARMON, D W	7907240209*	XPORTLIC	HEISHMAN, R F	7907300280	50-295 G
HARMON, D W	7907310037	XPORTLIC	HEISHMAN, R F	7907240273	50-10 G
HARNE, R L	7907260562	50-320 P	HELLER, L W	7907190739	40-4492
HARPBSTER, T L	7907270133*	50-263 G	HELLER, L W	7907190350	40-8584
HARRIS, J N	7907110497*	PROJ	HELTEHES, C J	7906220115	50-320 P
HARRIS, C C	7907240532	PRM	HELTEHES, C J	7907020505	FOIA
HARRIS, C E	7907310393*	50-128 R	HELTEHES, C J	7907050038*	50-495 A
HARRIS, J L	7907180040	50-445 H	HELTEHES, C J	7907300471	50-289 P
HARRIS, J L	7907260038	50-445 H	HELTEHES, C J	7907300396	FOIA
HARRIS, H E	7907160303*	COMMISSION	HENDRIX, C E	7907300464	50-320 P
HARRINGTON, J	7907100380	50-568 A	HENDRICK, W G	7907270107	XPORTLIC
HARRISON, F L	7907050149	NUREQ	HENDRICK, W G	7907240223	XPORTLIC
HARRISON, F L	7907190218	NUREQ	HENDRICK, W G	7907240277*	XPORTLIC
HARRIS, J R	7907240227*	50-400 G	HENDRICK, W G	7907180877	XPORTLIC
HART, G	7906060054	50-320 U	HENDRICK, W G	7907180900*	XPORTLIC
			HENDRICK, W G	7907230140	XPORTLIC

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HENDRICK, H. O.	7907230146*	XPORTRIC	HENDRIE, J. M.	7907130950	COMMISSION
HENDRIE, J. M.	7907270220*	COMMISSION	HENDRIE, J. M.	7907130552	COMMISSION
HENDRIE, J. M.	7907030134*	FOIA	HENDRIE, J. M.	7907130554	COMMISSION
HENDRIE, J. M.	7907090166*	SECY	HENDRIE, J. M.	7907130557	COMMISSION
HENDRIE, J. M.	7907060348	COMMISSION	HENDRIE, J. M.	7907130561	COMMISSION
HENDRIE, J. M.	7907300445	COMMISSION	HENDRIE, J. M.	7907130562	COMMISSION
HENDRIE, J. M.	7907060414	COMMISSION	HENDRIE, J. M.	7907160052	COMMISSION
HENDRIE, J. M.	7906110416	50-320 U	HENDRIE, J. M.	7907160176	50-320 P
HENDRIE, J. M.	7907100666	50-201 H	HENDRIE, J. M.	7907160202	COMMISSION
HENDRIE, J. M.	7907110309	COMMISSION	HENDRIE, J. M.	7907160071	COMMISSION
HENDRIE, J. M.	7907180896	27-39	HENDRIE, J. M.	7907160096	COMMISSION
HENDRIE, J. M.	7907060235	COMMISSION	HENDRIE, J. M.	7907180588	50-280 U
HENDRIE, J. M.	7907030366	10CFR	HENDRIE, J. M.	7907180721	50-320 U
HENDRIE, J. M.	7907130078	10CFR	HENDRIE, J. M.	7907180736*	50-320 U
HENDRIE, J. M.	7907090011	10CFR	HENDRIE, J. M.	7907180751*	50-320 U
HENDRIE, J. M.	7907090013	50-334 T	HENDRIE, J. M.	7907180766*	50-320 U
HENDRIE, J. M.	7907090019	50-219 T	HENDRIE, J. M.	7907180785*	50-320 U
HENDRIE, J. M.	7907090030	10CFR	HENDRIE, J. M.	7907120499	10CFR
HENDRIE, J. M.	7907090032	10CFR	HENDRIE, J. M.	7907120520	10CFR
HENDRIE, J. M.	7907250139	COMMISSION	HENDRIE, J. M.	7907160050	50-320 U
HENDRIE, J. M.	7907160329	50-320 H	HENDRIE, J. M.	7907160112	COMMISSION
HENDRIE, J. M.	7907250610	COMMISSION	HENDRIE, J. M.	7907180651	50-320 U
HENDRIE, J. M.	7907260451	COMMISSION	HENDRIE, J. M.	7907180696	50-171 U
HENDRIE, J. M.	7907260464*	COMMISSION	HENDRIE, J. M.	7907160073	COMMISSION
HENDRIE, J. M.	7907260473*	COMMISSION	HENDRIE, J. M.	7907160090	70-143
HENDRIE, J. M.	7907260482*	COMMISSION	HENDRIE, J. M.	7907160141	COMMISSION
HENDRIE, J. M.	7907260491*	COMMISSION	HENDRIE, J. M.	7907160168	COMMISSION
HENDRIE, J. M.	7907260496*	COMMISSION	HENDRIE, J. M.	7907160172	10CFR
HENDRIE, J. M.	7907260513*	COMMISSION	HENDRIE, J. M.	7907170093	50-289 T
HENDRIE, J. M.	7907260521*	COMMISSION	HENDRIE, J. M.	7907200449	50-320 H
HENDRIE, J. M.	7907260569	COMMISSION	HENDRIE, J. M.	7907190573	10CFR
HENDRIE, J. M.	7907310492	COMMISSION	HENDRIE, J. M.	7907200457	50-320 H
HENDRIE, J. M.	7907310500*	COMMISSION	HENDRIE, J. M.	7907230170	50-320 P
HENDRIE, J. M.	7907310508*	COMMISSION	HENDRIE, J. M.	7907230472	COMMISSION
HENDRIE, J. M.	7907310516*	COMMISSION	HENDRIE, J. M.	7907230484	COMMISSION
HENDRIE, J. M.	7907310527*	COMMISSION	HENDRIE, J. M.	7907230490	COMMISSION
HENDRIE, J. M.	7907160229	10CFR	HENDRIE, J. M.	7907230500	COMMISSION
HENDRIE, J. M.	7907160246	10CFR	HENDRIE, J. M.	7907230518	COMMISSION
HENDRIE, J. M.	7907160316	50-320 P	HENDRIE, J. M.	7907230534	COMMISSION
HENDRIE, J. M.	7907250171	COMMISSION	HENDRIE, J. M.	7907230821	50-201 P
HENDRIE, J. M.	7907250180	COMMISSION	HENDRIE, J. M.	7907230554	COMMISSION
HENDRIE, J. M.	7907270210	COMMISSION	HENDRIE, J. M.	7907230627	COMMISSION
HENDRIE, J. M.	7907310541	COMMISSION	HENDRIE, J. M.	7907230187	COMMISSION
HENDRIE, J. M.	7907310564	COMMISSION	HENDRIE, J. M.	7907230250*	50-201 P
HENDRIE, J. M.	7907310585	50-280 U	HENNINGSOHN, P. J.	7907260360	50-320 P
HENDRIE, J. M.	7907310604	COMMISSION	HENNINGSOHN, P. J.	7907260572	50-320 P
HENDRIE, J. M.	7907160255	10CFR	HENSLEY, K. D.	7907060437	70-143
HENDRIE, J. M.	7907160045	COMMISSION	HENSLEY, K. D.	7907020472	70-143
HENDRIE, J. M.	7907190068	50-367 Q	HENSLEY, K. D.	7907180766	70-143
HENDRIE, J. M.	7907230659	COMMISSION	HERBEIN, J. O.	7907110521*	50-320 Q
HENDRIE, J. M.	7907030343	10CFR	HERBEIN, J. O.	7907180037*	50-320 T
HENDRIE, J. M.	7907030354	10CFR	HERBEIN, J. O.	7907110122*	50-320 Q
HENDRIE, J. M.	7907030395	10CFR	HERBEIN, J. O.	7907090240	50-289 Q
HENDRIE, J. M.	7907030407	10CFR	HERBEIN, J. O.	7907180854	50-320 Q
HENDRIE, J. M.	7907030410	10CFR	HERBEIN, J. O.	7907050379	50-320 P
HENDRIE, J. M.	7907300493	COMMISSION	HERBEIN, J. O.	7907110323	50-289 B
HENDRIE, J. M.	7907300502	COMMISSION	HERBEIN, J. O.	7907100653	50-289 R
HENDRIE, J. M.	7907300511	COMMISSION	HERBEIN, J. O.	7907110514	50-289 F
HENDRIE, J. M.	7907300515	COMMISSION	HERBEIN, J. O.	7907180472	50-289 B
HENDRIE, J. M.	7907100087*	50-320 T	HERBEIN, J. O.	7907180477	50-289 B
HENDRIE, J. M.	7907160041	COMMISSION	HERBEIN, J. O.	7907170077	50-289 F
HENDRIE, J. M.	7907160278	COMMISSION	HERBEIN, J. O.	7907190568	50-289 F
HENDRIE, J. M.	7907160312	COMMISSION	HERBEIN, J. O.	7907190581*	50-289 F
HENDRIE, J. M.	7907310048	COMMISSION	HERBEIN, J. O.	7907200302	50-289 P
HENDRIE, J. M.	7907100122	50-320 T	HERBEIN, J. O.	7907230626	50-320 P
HENDRIE, J. M.	7907100124	50-320 T	HERBEIN, J. O.	7907170189	50-289 P
HENDRIE, J. M.	7907130512	COMMISSION	HERBEIN, J. O.	7907270190	50-289 R
HENDRIE, J. M.	7907160021	COMMISSION	HERBEIN, J. O.	7907270269	50-320 P
HENDRIE, J. M.	7907160035	COMMISSION	HERDT, A. R.	7907180640*	50-390 Q
HENDRIE, J. M.	7907160186	10CFR	HERDT, A. R.	7907120533*	50-424 Q
HENDRIE, J. M.	7907160211	10CFR	HERDT, A. R.	7907050143*	50-438 Q
HENDRIE, J. M.	7907160239	COMMISSION	HERDT, A. R.	7907090438*	50-281 Q
HENDRIE, J. M.	7907130527	COMMISSION	HERDT, A. R.	7907240391*	50-390 Q
HENDRIE, J. M.	7907130529	COMMISSION	HERDT, A. R.	7907240285*	50-424 Q
HENDRIE, J. M.	7907130532	COMMISSION	HERDT, A. R.	7907130225*	50-395 Q
HENDRIE, J. M.	7907130535	COMMISSION	HERDT, A. R.	7907240099*	50-518 Q
HENDRIE, J. M.	7907130537	COMMISSION	HERDT, A. R.	7907050189*	50-400 Q
HENDRIE, J. M.	7907130539	COMMISSION	HERDT, A. R.	7907240129*	50-327 Q
HENDRIE, J. M.	7907130541	COMMISSION	HERDT, A. R.	7907270387*	50-369 Q
HENDRIE, J. M.	7907130569	COMMISSION	HERDT, A. R.	7907260142*	50-353 Q
HENDRIE, J. M.	7907160036	COMMISSION	HERDT, A. R.	7907260342*	50-348 Q
HENDRIE, J. M.	7907030089	10CFR	HERDT, A. R.	7907260076*	50-287 Q
HENDRIE, J. M.	7907030309	10CFR	HERR, P. B.	7907050507	50-471 Q
HENDRIE, J. M.	7907100121	50-320 T	HERSCH, M. M.	7907060286	XPORTRIC
HENDRIE, J. M.	7907130547	COMMISSION	HERSKOVITZ, M. B.	7907300306	RES
			HESTICK, M. L.	7907030275*	50-282 R



# PERSONAL AUTHOR INDEX

401

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HIATT, R M	7907260565	50-320 P	HOOPER, F F	7907300113	50-322 T
HIATT, R M	7907260570	50-320 P	HOOPER, F F	7907270285	50-322 T
HIATT, J W	7907300412*	50-305 Q	HOOPER, F F	7907270285	50-322 T
HIATT, J W	7907300194*	50-266 Q	HOPCRAFT, C P	7907260973	PRM
HIATT, J W	7907190073*	50-10 Q	HOPPER, D	7907090310*	50-338 P
HIATT, J W	7907100309	50-320 H	HORN, A J	7907190484*	50-224 Q
HICKEY, C R	7907020420	50-320 P	HORWOOD, J N	7907110343*	50-416 M
HICKEY, C R	7907090465	50-320 P	HOSSEY, C M	7907180695*	50-280 Q
HICKLE, B J	7907180398*	50-285 R	HOSSEY, C M	7907230724*	50-280 Q
HICKS, L H	7907090554*	50-361 H	HOSSEY, C M	7907100566	50-320 H
HICKS, L H	7907090551	50-361 H	HOSSEIN, G A	7907060351*	50-295 Q
HIESTAND, D S	7907120639	50-409 Q	HOWARD, J E	7907050250	50-293 P
HIGGINBOTHAM, L	7907230235*	FOIA	HOWE, P W	7907050175	50-400 Q
HIGGINS, J C	7907180445*	50-336 Q	HOWE, P W	7907240215*	50-400 Q
HIGGINS, J C	7907110426*	50-333 Q	HOWE, P W	7907110578	50-400 Q
HIGHTOWER, D	7907300351	PR	HOWE, P W	7907240210	50-400 Q
HIMENBAUGH, N	7907130399*	50-155 R	HOWE, P W	7907250090	50-400 Q
HIND, J A	7907090163*	50-346 Q	HOWELL, S H	7907050243	50-329 F
HIND, J A	7907300285*	50-263 Q	HOWELL, S H	7907110702	50-329 Q
HIND, J A	7907090159	50-346 Q	HOWELL, S H	7907130166	50-329 Q
HIND, J A	7907300274	50-263 Q	HOWELL, S H	7907110215	50-329 Q
HIND, J A	7907240266	50-294 Q	HOWELL, S H	7907300531	50-329 Q
HIND, J A	7907180263	50-346 Q	HOWELL, S H	7907020256	50-329 R
HINES, E	7907190092*	50-341 Q	HOWELL, S H	7907160604	50-329 S
HINSON, J	7907160091*	50-416 U	HOWELL, S H	7907030277	50-329 K
HINSON, J	7907160086*	50-416 U	HOWELL, S H	7907030448*	50-329 K
HOGAN, K E	7907110727	50-219 P	HOWELL, S H	7907030470	50-329 K
HOBBBS, F T	7907190242*	50-16 P	HOWELL, S H	7907050306	50-329 C
HODGES, J W	7907230488*	50-337 Q	HOWELL, S H	7907100527	50-329 S
HODGES, W	7907240443	TOPREP	HOWELL, S H	7907110416	50-329 A
HOEFLING, R K	7907120159	50-322 Q	HOWELL, S H	7907250325	50-329 S
HOEFLING, R K	7907170244	50-322 Q	HOWELL, S H	7907260475	50-329 A
HOEFLING, R K	7907310259	70-2623	HOWELL, S H	7907110437*	50-358 Q
HOEFLING, R K	7907060519	50-322 Q	HOWELL, J C	7907300285*	50-263 Q
HOEFLING, R K	7907180755*	50-322 Q	HOWLETT, O H	7907180470*	50-336 R
HOEFLING, R K	7907180752	50-322 Q	HOYLE, J C	7907190845*	50-409 Q
HOEFLING, R K	7907310472	50-322 A	HOYLE, J C	7907190135*	50-409 Q
HOEFF, W D.	7907120465*	70-1308	HOYLE, J C	7907270264*	50-409 Q
HOFFMAN, W J	7907120381	PR	HOYLE, J C	7907190284*	50-320 Q
HOFFMAN, D P	7907180756	50-155 P	HOYLE, J C	7907190298*	50-320 Q
HOFFMAN, D P	7907110715	50-255 Q	HOYLE, J C	7907300391	50-346 Q
HOFFMAN, D P	7907110278	50-255 Q	HUBACEK, W G	7907050179*	50-498 Q
HOFFMAN, D P	7907190336	50-255 Q	HUBACEK, W G	7907300058*	50-498 Q
HOFFMAN, D P	7907030476	50-255 B	HUBACEK, W G	7907110612*	50-498 Q
HOFFMAN, D P	7907120331	50-255 P	HUBACEK, W G	7907310126*	50-466 Q
HOFFMAN, D P	7907090284	50-255 B	HUBBARD, L B	7907230221	PR
HOFFMAN, D P	7907100319	50-255 B	HUBER, C C	7907180182	NUREQ
HOFFMAN, D P	7907170024	50-155 P	HUDDESTON, E W	7907020460	71-175
HOFFMAN, D P	7907170037	50-255 B	HUDDESTON, E W	7907020462*	71-175
HOFFMAN, D P	7907190512	50-255 R	HUETER, L J	7907110438*	70-925
HOFFMAN, D P	7907200378	50-155 B	HUETER, L J	7907100589	50-320 H
HOFFMAN, D P	7907190415	50-155 F	HUETER, L J	7907250211*	50-255 Q
HOFFMAN, D P	7907190536	50-155 P	HUFF, E M	7907180740	71-166
HOFFMAN, D P	7907300383	50-255 B	HUFFERD, C	7907120024	50-556 Q
HOFFMAN, D P	7907310299	50-255 P	HUFHAM, J W	7907130511*	50-302 Q
HOFFMAN, D P	7907310432	50-255 P	HUFHAM, J W	7907090203*	50-302 Q
HOFFMAYER, C	7907020434	50-320 P	HUFHAM, J W	7907110596*	50-267 Q
HOFFSTADTER, E P	7907110475*	50-358 Q	HUFHAM, J W	7907160268*	70-143
HOFFSTADTER, E P	7907190136*	50-358 Q	HUFHAM, J W	7907200234*	70-27
HOLAHAN, O M	7907160084	50-320 P	HUFHAM, J W	7907110598*	50-400 Q
HOLAHAN, O M	7907190306	50-320 H	HUFHAM, J W	7907240148*	50-553 Q
HOLDBWORTH, T	7907270404	NUREQ	HUGH, B	7907230548	50-358 Q
HOLM, D	7906210421*	50-466 Q	HUGHES, J	7907280452*	50-440 Q
HOLMAN, J J	7907110365	50-320 A	HUGHES, J	7907260169*	50-341 Q
HOLLOWAY, C F	7907300507	RES	HUGHES, J	7907300046*	50-373 Q
HOLT, B.	7907090448*	50-269 Q	HULL, W A	7907170491	HASTE MOT
HOLT, D.	7907300384	FOIA	HUNNICUTT, D M	7907250357*	QA999
HOLMAN, P	7907110720	50-10 Q	HUNNICUTT, D M	7907130372*	QA999
HOOD, D S	7905230663	50-329 A	HUNNICUTT, D M	7907090474*	QA999
HOOD, D S	7905240952	50-329 A	HUNNICUTT, D M	7907260158*	QA999
HOOD, D S	7907130057	50-329 A	HUNNICUTT, D M	7907090466*	QA999
HOOD, D S	7907190028	50-329 A	HUNNICUTT, D M	7907030026*	QA999
HOOD, D S	7907240053	50-329 A	HUNNICUTT, D M	7907060046*	QA999
HOOD, D S	7907190039	50-329 A	HUNNICUTT, D M	7907090478*	QA999
HOOD, D S	7907300579	50-329 A	HUNNICUTT, D M	7907050536*	QA999
HOOPER, R. F.	7907090099	50-358 T	HUNSTAD, A. A.	7907050303*	50-282 S
HOOPER, F. F.	7907030265	50-358 T	HUNSTAD, A. A.	7907050414*	50-282 S
HOOPER, F. F.	7907030388	50-358 T	HUNSTAD, A. A.	7907180516*	50-282 R
HOOPER, F. F.	7907120294	50-358 T	HUNSTAD, A. A.	7907130473*	50-282 S
HOOPER, F. F.	7907120170	50-358 T	HUNT, B D.	7907030150	FOIA
HOOPER, F. F.	7907120303	50-358 T	HUNT, M D	7907120533*	50-424 Q
HOOPER, F. F.	7907120400	50-358 T	HUNT, M D.	7907270387*	50-367 Q
HOOPER, F. F.	7907120158	50-358 T	HUNTER, R. S.	7907230365	50-313 P
HOOPER, F. F.	7907120446	50-358 T	HUNTER, V. H.	7907100733*	QA999
HOOPER, F. F.	7907120469	50-358 T	HUNTER, V. H.	7907250102*	QA999
			HUNTER, V. H.	7907260090*	QA999
			HURSH, Q.	7907020513*	50-312 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HUTCHINSON, L. R.	7907100727*	GA999	JACKSON, J. F.	7907250538	NUREG
HUTSON, T. W.	7907300107*	50-508 Q	JACKSON, R. E.	7907110223	50-423 A
HUTSON, T. W.	7907270206*	50-508 Q	JACKSON, R. E.	7907240433	50-70 P
HUTTON, P. H.	7907300048	NUREG	JACKSON, R. E.	7907170140	50-400 A
HUTTON, P. H.	7907300487	RES	JACOBSON, N. H.	7907170243	50-445 Q
HUTTON, P. H.	7907300554	RES	JACOBSON, N. H.	7907180612	50-445 Q
HYLTON, J. O.	7907300541	RES	JACOBSON, N. H.	7907250553*	GA999
IANNI, P. W.	7907160334*	TOPREP	JANECEK, R. F.	7907050224	50-10 P
IONATONIS, A.	7907190202*	FOIA	JANECEK, R. F.	7907050290	50-249 F
ILLIO, F. J.	7907250382*	50-311 E	JANECEK, R. F.	7907100449	50-10 P
INDYKE, C. H.	7907110700	50-596 A	JANECEK, R. F.	7907050284	50-237 P
INDYKE, C.	7907180240	50-596 Q	JANECEK, R. F.	7907030357	TOPREP
INFANTE, R.	7907110739	XPORTLIC	JANECEK, R. F.	7907060272	50-237 Q
INGRAM, R.	7907200211	50-269 P	JANECEK, R. F.	7907120366	50-237 P
IPPOLITO, T. A.	7907030113	50-298 P	JANECEK, R. F.	7907170070	50-254 P
IPPOLITO, T. A.	7907060087	50-271 P	JANECEK, R. F.	7907190200	50-249 F
IPPOLITO, T. A.	7907060488	50-293 F	JANECEK, R. F.	7907190342	TOPREP
IPPOLITO, T. A.	7907060078	50-293 F	JANECEK, R. F.	7907190363	50-237 P
IPPOLITO, T. A.	7907050022	50-263 P	JANECEK, R. F.	7907230275	50-237 P
IPPOLITO, T. A.	7907050026*	50-263 P	JANECEK, R. F.	7907240345	50-237 P
IPPOLITO, T. A.	7907050033*	50-263 P	JANNARONE, J. R.	7907180754	50-247 Q
IPPOLITO, T. A.	7907100548	50-298 P	JANNARONE, J. R.	7907120512	50-247 Q
IPPOLITO, T. A.	7907060117	50-333 Q	JARE, F.	7907020137*	50-269 Q
IPPOLITO, T. A.	7907060127	50-271 P	JARE, F.	7907020072*	50-269 Q
IPPOLITO, T. A.	7907170048	50-298 P	JARE, F.	7906290406	50-320 P
IPPOLITO, T. A.	7907170076*	50-298 P	JASKE, R. T.	7907110404	50-320 A
IPPOLITO, T. A.	7907170109*	50-298 P	JASKE, R.	7907110197	50-320 P
IPPOLITO, T. A.	7907180245	50-333 F	JASPER, D. E.	7907270128	PR
IPPOLITO, T. A.	7907130406	50-260 P	JENKENS, G. R.	7907260023*	50-281 Q
IPPOLITO, T. A.	7907130411*	50-260 P	JENKINS, G. R.	7907260538*	50-327 Q
IPPOLITO, R. A.	7907240614	50-293 Q	JENKINS, H. D.	7907240192*	50-339 Q
IPPOLITO, T. A.	7907060085	50-259 P	JENKINS, G. R.	7906200415	50-320 P
IPPOLITO, T. A.	7907110683	50-263 P	JENKINS, G. R.	7907230724*	50-280 Q
IPPOLITO, T. A.	7907240387	50-263 P	JENKINS, G. R.	7907270406*	50-302 Q
IPPOLITO, T. A.	7907110698	50-277 P	JENKINS, G. R.	7907300028*	50-280 Q
IPPOLITO, T. A.	7907120180	50-277 P	JENKINS, H. D.	7907300018*	50-338 Q
IPPOLITO, T. A.	7907120190*	50-277 P	JENNEKENS, J. H.	7907200479*	50-320 H
IPPOLITO, T. A.	7907120200*	50-277 P	JENS, W. H.	7907130417	50-341 F
IPPOLITO, T. A.	7907120052	50-324 Q	JENSEN, S. E.	7907110459*	TOPREP
IPPOLITO, T. A.	7907110741	50-298 F	JERNIGAN, E. P.	7907270381*	50-220 Q
IPPOLITO, T. A.	7907240374	50-220 P	JOHNSRUD, J.	7907060452	50-387 Q
IPPOLITO, T. A.	7907240380*	50-220 P	JOHNSRUD, J. H.	7907300447	50-289 Q
IPPOLITO, T. A.	7907240382*	50-220 P	JOHNSON, C. E.	7907060164	PR
IPPOLITO, T. A.	7907310224	50-321 P	JOHNSON, A. S.	7907230275	PR
IPPOLITO, T. A.	7907310232*	50-321 P	JOHNSON, G. R.	7907310053*	COMMISSION
IPPOLITO, T. A.	7907310234*	50-321 P	JOHNSON, D. L.	7907190093*	40-299
IPPOLITO, T. A.	7907310459	50-333 P	JOHNSON, L.	7907060479*	40-1739
IPPOLITO, T. A.	7907310462	50-254 P	JOHNSON, L.	7907060490*	40-1739
IPPOLITO, T. A.	7907250107	50-277 P	JOHNSON, L.	7907060486*	40-1739
IPPOLITO, T. A.	7907250110*	50-277 P	JOHNSON, L.	7907060484*	40-1739
IPPOLITO, T. A.	7907250112	50-331 P	JOHNSON, R. W.	7907190366	50-344 Q
IPPOLITO, T. A.	7907250117*	50-331 P	JOHNSON, R. W.	7907190370*	50-344 Q
IPPOLITO, T. A.	7907310470	50-293 P	JOHNSON, R. W.	7907130081	50-344 Q
IPPOLITO, T. A.	7907180401	50-220 Q	JOHNSON, R. W.	7907180739	50-344 Q
IPPOLITO, T. A.	7907240392*	50-263 P	JOHNSON, R. W.	7907180712	50-344 Q
IPPOLITO, T. A.	7907240396*	50-263 P	JOHNSON, R. W.	7907030463	50-344 P
IPPOLITO, T. A.	7907240363*	50-263 P	JOHNSON, R. W.	7907110474	50-344 P
IPPOLITO, T. A.	7907240378*	50-220 P	JOHNSON, R. W.	7907110479	50-344 P
IPPOLITO, T. A.	7907300518	50-333 P	JOHNSON, H. C.	7907130200	50-395 Q
IPPOLITO, T. A.	7907270307	50-366 P	JOHNSON, H. C.	7907170067	50-395 S
IPPOLITO, T. A.	7907270322*	50-366 P	JOHNSON, W. P.	7907030375	50-271 P
IPPOLITO, T. A.	7907270332*	50-366 P	JOHNSON, A. B.	7907060363*	50-295 Q
IPPOLITO, T. A.	7907270336	50-366 P	JOHNSON, D. H.	7907110002	50-320 Q
IPPOLITO, T. A.	7907270341*	50-366 P	JOHNSON, D.	7907180483*	50-247 Q
IPPOLITO, T. A.	7907270350*	50-366 P	JOHNSON, D.	7907180437*	50-286 Q
IPPOLITO, T. A.	7907270355	50-331 P	JOHNSON, J. R.	7907100563	50-320 H
IPPOLITO, T. A.	7907270360*	50-331 P	JOHNSON, A. H.	7907240070*	50-250 Q
IPPOLITO, T. A.	7907270369*	50-331 P	JOHNSON, E. H.	7907050140*	50-298 Q
IRELAND, A.	7907260259*	PROJ	JOHNSON, E. H.	7907300484*	50-298 Q
IRELAND, R. E.	7907120800*	50-320 P	JOHNSON, E. H.	7907200220*	50-192 Q
IRWIN, D. P.	7907180600	50-463 Q	JOHNSON, W. D.	7907120007*	50-313 Q
IRWIN, D. P.	7907130056	50-463 Q	JOHNSON, J. M.	7907230074*	GA999
IRWIN, D. P.	7907130070*	50-463 Q	JOHNSON, A.	7907020123*	50-312 Q
ISACHSEN, Y. W.	7907190326	NUREG	JOHNSON, A.	7907020157*	50-312 Q
ISACHSEN, Y. W.	7907190374	NUREG	JOHNSON, A.	7907020080*	50-312 Q
ISACHSEN, Y. W.	7907190420	NUREG	JOHNSTON, G. W.	7907130179*	50-70 Q
ISACHSEN, Y. W.	7907190433	NUREG	JOHNSTON, P. H.	7907270276*	50-344 Q
ISBIN, H. S.	7907250046	ACRS	JOHNSTON, P. H.	7907270290*	50-397 Q
ISHIYAMA, T.	7907090437*	50-320 P	JOHNSTON, A.	7907300404	50-312 Q
IVERSON, D. N.	7907030344*	50-263 S	JOHNSTON, W. V.	7907120150	50-320 P
JABBOUR, K. N.	7907230053	50-244 P	JOHNSON, T. L.	7907190004	50-293 P
JABBOUR, K.	7907260961	50-255 P	JONES, L. L.	7907130114	50-382 Q
JABLON, R. A.	7907190846*	50-445 H	JONES, L. L.	7907130195	50-382 Q
JACKIE, I. N.	7907300474	50-331 Q	JONES, J. H.	7907260558	50-320 P
JACKIN, I. N.	7907180425*	50-331 Q	JONES, B. M.	7907260210	PR
JACKSON, A. B.	7907260351	50-320 P	JONES, J. R.	7907050534	50-556 U
			JONES, F.	7907110433*	50-237 S

## PERSONAL AUTHOR INDEX

403

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JONES, F A	7907260720*	50-237 B	KELLEY, W D	7907030039*	6A999
JONES, J A	7907090333	PRM	KELLEY, W D	7907190742*	6A999
JONES, J A	7907230247	PRM			
JONES, J A	7907200273	PR	KELLEY, W D	7907250154*	6A999
JONES, R H	7907130223*	70-2623	KELLOGG, P J	7907240192*	50-339 Q
JONES, D C	7907110483	RES	KELLOGG, P J	7907240123*	50-338 Q
JONES, D C	7907310109	RES	KELLOGG, P J	7907300018*	50-338 Q
JONES, D C	7907300583	RES	KELLOGG, P J	7907160193*	50-369 Q
JONES, D W	7907300070*	70-1151	KELLOGG, P J	7907190078*	50-280 Q
JONES, D W	7907230523*	70-27	KELLOGG, P J	7907240347*	50-337 Q
JONES, C E	7907230744*	50-456 Q	KELLOGG, P J	7907300082*	50-280 Q
JORDAN, W B	7907190342	50-968 Q	KELLY, P J	7907130315	50-338 J
JORDAN, W B	7907190547*	50-968 Q	KELLY, D L	7907020206	50-285 Q
JORDAN, H	7907170187	NUREQ			
JORDAN, W H	7907120083	50-594 T	KEMENY, J	7907180085	50-320 T
JORDAN, E L	7907100686	50-331 Q	KEMENY, J	7907180077	50-320 T
JORDAN, E L	7907240288	50-315 P	KEMENY, J	7907180092	50-320 T
JORDAN, E L	7907090427	50-206 Q	KEMENY, J	7907180104	50-320 T
JORGENSEN, B	7907100092*	50-320 T	KEMENY, J	7907180109*	50-320 T
JORGENSEN, B L	7907100365	50-320 H	KEMENY, J		
JORGENSEN, B L	7907180411*	50-255 Q	KEMENY, J	7907180022	50-320 T
JOYNER, J H	7907130050*	70-1100	KEMENY, J	7907180013	50-320 T
JOYNER, J H	7907180734*	70-820	KEMENY, J	7907180017	50-320 T
JOYNER, J H	7907240297*	70-33	KEMENY, J	7907180073	50-320 T
JOYNER, J H	7907200490*	70-820	KEMENY, J	7907180003	50-320 T
JOYBIZ, W	7907261014	PR	KEMENY, J		
JULIAN, C A	7907120560*	50-324 Q	KEMENY, J	7907180010	50-320 T
JULIAN, C	7907300037*	50-261 Q	KENDERGER, D L	7906210227	50-397 A
JURGENSEN, R W	7907300480	50-315 Q	KENDRICK, J R	7907250428*	50-437 Q
JURGENSEN, R W	7907030457	50-315 P	KENNA, W B	7907130145*	70-143
JUSKO, M J	7907180182	NUREQ	KENNA, W B	7907050190	50-324 Q
KAFIN, R J	7907060507*	50-556 Q			
KAFIN, R J	7907060510*	50-556 Q	KENNA, W B	7907230515*	70-27
KALIVIANAKIS, N	7907190023	50-254 P	KENNA, W B	7907300064*	70-1151
KALIVIANAKIS, N	7907110488	50-254 S	KENNA, W B	7907200225	50-83 Q
KALIVIANAKIS, N	7907190343	50-254 P	KENNA, W B	7907230483	50-339 Q
KALIVIANAKIS, N	7907250297	50-265 B	KENNA, W B	7907200047*	70-1113
KALIVIANAKAS, N	7907250264	50-265 B			
KALIVIANAKIS, N	7907250366	50-254 S	KENNA, W B	7907200070*	70-1113
KALLEMEYN, V	7907190484	WASTE MOT	KENNA, W B	7907130091	50-324 Q
KALLFELZ, F A	7907310063	PR	KENNA, W B	7907130111	70-143
KALMAN, G	7907110544*	50-272 Q	KENNA, W B	7907230498	70-27
KAMMERER, C	7906070309	FOIA	KENNA, W B	7907300060	70-1151
KAMMERER, C	7906260593*	50-250 U			
KAMRAB, J	7907050366	50-466 Q	KENNA, W B	7907200039	70-1113
KANE, C	7907020507*	FOIA	KENNA, W B	7907200057	70-1113
KANE, W F	7907190325	50-10 P	KENNEDY, W J L	7907230350	50-495 K
KANE, W F	7907180189	50-320 S	KENNEDY, R K	7907110077	50-320 P
KAPLAN, A L	7907060463	70-1113	KENNEDY, R T	7907270220*	CONMISSION
KAPLAN, A L	7907200046*	70-1113	KENNEDY, R T	7907260519	50-320 H
KAPLAN, A L	7907200064*	70-1113	KENNEDY, R T	7907180750*	FOIA
KAPLAN, A L	7907180797	70-1113	KENNEDY, R T	7907180732*	FOIA
KAPLAN, A L	7907060404	70-1113	KENNEDY, R T	7907030366	10CFR
KAPLAN, D	7907100509	50-312 P	KENNEDY, R T	7907030366	10CFR
KAPPLER, A W	7907090302*	50-272 B	KENNEDY, R T	7907130078	10CFR
KAPPLER, A W	7907090277*	50-272 B	KENNEDY, R T	KENNEDY, R T	10CFR
KAPPLER, A W	7907260586*	50-272 B	KENNEDY, R T	7907090011	10CFR
KAPPLER, A W	7907260724*	50-272 B	KENNEDY, R T	7907090015	50-334 T
KARNEY, P T	7907130033	PR	KENNEDY, R T	7907090019	50-219 T
KASHY, T A	7907170793	PR	KENNEDY, R T	7907090030	10CFR
KASS, B L	7907030336	FOIA	KENNEDY, R T		
KASTL, W H	7907230148	PR	KENNEDY, R T	7907030410	10CFR
KATHREN, R L	7907160224	RECORD	KENNEDY, R T	7907030413	10CFR
KATO, W Y	7907240089	NUREQ	KENNEDY, R T	7907100122	50-320 T
KAVACH, F B	7907300487	71-99	KENNEDY, R T	7907100124	50-320 T
KAVANAUGH, G M	7907190231*	50-16 P	KENNEDY, R T	7907160186	10CFR
KAVANAUGH, G M	7907190238*	50-16 P	KENNEDY, R T		
KAWULA, L	7907180494*	50-3 R	KENNEDY, R T	7907160211	10CFR
KEEFE, R	7907100043	XPORTLIC	KENNEDY, R T	7907030089	10CFR
KEEL, W B	7907190892*	RECORD	KENNEDY, R T	7907030309	10CFR
KEENAN, R P	7907240280	XPORTLIC	KENNEDY, R T	7907100121	50-320 T
KEENAN, R P	7907240284*	XPORTLIC	KENNEDY, R T	7907160172	10CFR
KEENC, J	7907270374	40-8681	KENNEDY, R T		
KEEPING, W	7907260712*	50-596 Q	KENNEDY, R T	7907190573	10CFR
KEIMIG, R R	7907230570*	50-272 Q	KENRICK, J R	7907250421	50-437 Q
KEIMIG, R R	7907180483*	50-247 Q	KEPFORD, C	7907060452	50-387 Q
KEIMIG, R R	7907180437*	50-286 Q	KEPPLER, A W	7907310372*	50-272 S
KEIMIG, R R	7907200504*	50-289 Q	KEPPLER, J Q	7907310185*	50-546 U
KELHAM, G	7907230215	PR			
KELL, D B	7907190283	WASTE MOT	KEPPLER, J Q	7907120387	1&E
KELLAND, J	7907090310*	50-338 P	KEPPLER, J Q	7907050147	50-305 Q
KELLER, J H	7907180134	NUREQ	KEPPLER, J Q	7907180598	50-358 Q
KELLEY, R E	7907090414*	50-395 Q	KEPPLER, J Q	7907180345	50-315 Q
			KEPPLER, J Q	7907050479	70-925
KELLEY, R E	7907090417*	FOIA			
KELLEY, R E	7907130158*	50-358 Q	KEPPLER, J Q	7907260086	50-315 P
KELLEY, D L	7907020193*	50-313 Q	KEPPLER, J Q	7907260097	50-10 P
			KEPPLER, J Q	7907260095	50-158 P
			KEPPLER, J Q	7907260097	50-409 P
			KEPPLER, J Q	7907260098	50-331 P
			KEPPLER, J Q	7907260103	50-263 P
			KEPPLER, J Q	7907260106	50-346 P
			KEPPLER, J Q	7907260110	50-266 P

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KEPPLER, J. Q.	7907260112	50-305 P	KEPPLER, J. Q.	7907020424	50-409 Q
KEPPLER, J. Q.	7907120184	50-320 H	KEPPLER, J. Q.	7907020426	50-341 Q
KEPPLER, J. Q.	7907240169	50-546 Q	KEPPLER, J. Q.	7907020428	50-331 Q
KEPPLER, J. Q.	7907200287	50-295 Q	KEPPLER, J. Q.	7907020429	50-461 Q
KEPPLER, J. Q.	7907200292	50-10 Q	KEPPLER, J. Q.	7907020431	50-315 Q
KEPPLER, J. Q.	7907200296	50-10 Q	KEPPLER, J. Q.	7907020432	50-367 Q
KEPPLER, J. Q.	7907200300	50-358 Q	KEPPLER, J. Q.	7907020433	50-484 Q
KEPPLER, J. Q.	7907200303	50-440 Q	KEPPLER, J. Q.	7907020435	50-263 Q
KEPPLER, J. Q.	7907200307	50-329 Q	KEPPLER, J. Q.	7907020436	50-545 Q
KEPPLER, J. Q.	7907200308	50-255 Q	KEPPLER, J. Q.	7907020437	50-346 Q
KEPPLER, J. Q.	7907200310	50-155 Q	KEPPLER, J. Q.	7907020438	50-483 Q
KEPPLER, J. Q.	7907200312	50-409 Q	KEPPLER, J. Q.	7907020440	50-266 Q
KEPPLER, J. Q.	7907200314	50-341 Q	KEPPLER, J. Q.	7907020441	50-305 Q
KEPPLER, J. Q.	7907200316	50-331 Q	KEPPLER, J. Q.	7907120198	50-10 Q
KEPPLER, J. Q.	7907200318	50-461 Q	KEPPLER, J. Q.	7907120215	50-358 Q
KEPPLER, J. Q.	7907200320	50-315 Q	KEPPLER, J. Q.	7907120218	50-440 Q
KEPPLER, J. Q.	7907200322	50-367 Q	KEPPLER, J. Q.	7907120221	50-329 Q
KEPPLER, J. Q.	7907200325	50-484 Q	KEPPLER, J. Q.	7907120225	50-155 Q
KEPPLER, J. Q.	7907200326	50-263 Q	KEPPLER, J. Q.	7907120227	50-409 Q
KEPPLER, J. Q.	7907200328	50-282 Q	KEPPLER, J. Q.	7907120229	50-341 Q
KEPPLER, J. Q.	7907200330	50-546 Q	KEPPLER, J. Q.	7907120231	50-331 Q
KEPPLER, J. Q.	7907200332	50-346 Q	KEPPLER, J. Q.	7907120233	50-461 Q
KEPPLER, J. Q.	7907200334	50-483 Q	KEPPLER, J. Q.	7907120238	50-315 Q
KEPPLER, J. Q.	7907200336	50-266 Q	KEPPLER, J. Q.	7907120242	50-367 Q
KEPPLER, J. Q.	7907200338	50-305 Q	KEPPLER, J. Q.	7907120244	50-484 Q
KEPPLER, J. Q.	7907240156	50-329 Q	KEPPLER, J. Q.	7907120248	50-263 Q
KEPPLER, J. Q.	7907110056	70-1379	KEPPLER, J. Q.	7907120252	50-546 Q
KEPPLER, J. Q.	7907190224	50-10 Q	KEPPLER, J. Q.	7907120257	50-346 Q
KEPPLER, J. Q.	7907190230	50-249 Q	KEPPLER, J. Q.	7907120262	50-483 Q
KEPPLER, J. Q.	7907190236	50-358 Q	KEPPLER, J. Q.	7907120268	50-266 Q
KEPPLER, J. Q.	7907190240	50-440 Q	KEPPLER, J. Q.	7907120269	50-305 Q
KEPPLER, J. Q.	7907190244	50-329 Q	KEPPLER, J. Q.	7907050421	70-152
KEPPLER, J. Q.	7907190245	50-155 Q	KEPPLER, J. Q.	7907050422	70-572
KEPPLER, J. Q.	7907190249	50-409 Q	KEPPLER, J. Q.	7907050428	70-8
KEPPLER, J. Q.	7907190258	50-341 Q	KEPPLER, J. Q.	7907050431	40-3392
KEPPLER, J. Q.	7907190267	50-331 Q	KEPPLER, J. Q.	7907050432	70-36
KEPPLER, J. Q.	7907190269	50-461 Q	KEPPLER, J. Q.	7907050436	70-1220
KEPPLER, J. Q.	7907190272	50-315 Q	KEPPLER, J. Q.	7907050437	70-925
KEPPLER, J. Q.	7907190276	50-367 Q	KEPPLER, J. Q.	7907050438	70-1489
KEPPLER, J. Q.	7907190280	50-484 Q	KEPPLER, J. Q.	7907050441	50-10 Q
KEPPLER, J. Q.	7907190285	50-263 Q	KEPPLER, J. Q.	7907050445	50-155 Q
KEPPLER, J. Q.	7907190289	50-546 Q	KEPPLER, J. Q.	7907050448	50-315 Q
KEPPLER, J. Q.	7907190290	50-266 Q	KEPPLER, J. Q.	7907050451	50-263 Q
KEPPLER, J. Q.	7907190293	50-483 Q	KEPPLER, J. Q.	7907050454	50-346 Q
KEPPLER, J. Q.	7907190296	50-266 Q	KEPPLER, J. Q.	7907050455	50-266 Q
KEPPLER, J. Q.	7907190299	50-305 Q	KEPPLER, J. Q.	7907050458	50-305 Q
KEPPLER, J. Q.	7907120173	50-320 H	KEPPLER, J. Q.	7907050521	50-409 Q
KEPPLER, J. Q.	7907240241	50-10 Q	KEPPLER, J. Q.	7907050522	50-331 Q
KEPPLER, J. Q.	7907240246	50-358 Q	KEPPLER, J. Q.	7907230424	50-264 Q
KEPPLER, J. Q.	7907240250	50-440 Q	KEPPLER, J. Q.	7907230425	50-87 Q
KEPPLER, J. Q.	7907240251	50-329 Q	KEPPLER, J. Q.	7907230428	50-116 Q
KEPPLER, J. Q.	7907240252	50-155 Q	KEPPLER, J. Q.	7907230429	50-294 Q
KEPPLER, J. Q.	7907240254	50-409 Q	KEPPLER, J. Q.	7907230430	50-150 Q
KEPPLER, J. Q.	7907240287	50-341 Q	KEPPLER, J. Q.	7907230431	50-182 Q
KEPPLER, J. Q.	7907240422	50-331 Q	KEPPLER, J. Q.	7907230432	50-151 Q
KEPPLER, J. Q.	7907240425	50-461 Q	KEPPLER, J. Q.	7907230433	50-2 Q
KEPPLER, J. Q.	7907240427	50-315 Q	KEPPLER, J. Q.	7907230434	50-186 Q
KEPPLER, J. Q.	7907240428	50-367 Q	KEPPLER, J. Q.	7907230435	50-123 Q
KEPPLER, J. Q.	7907240432	50-263 Q	KEPPLER, J. Q.	7907230436	50-156 Q
KEPPLER, J. Q.	7907240435	50-484 Q	KEPPLER, J. Q.	7907120676	50-315 Q
KEPPLER, J. Q.	7907240438	50-546 Q	KEPPLER, J. Q.	7907120680	50-10 Q
KEPPLER, J. Q.	7907240441	50-346 Q	KEPPLER, J. Q.	7907120691	50-295 Q
KEPPLER, J. Q.	7907240444	50-483 Q	KEPPLER, J. Q.	7907120693	50-358 Q
KEPPLER, J. Q.	7907240448	50-266 Q	KEPPLER, J. Q.	7907120694	50-440 Q
KEPPLER, J. Q.	7907240450	50-305 Q	KEPPLER, J. Q.	7907120696	50-255 Q
KEPPLER, J. Q.	7907020237	50-373 Q	KEPPLER, J. Q.	7907120700	50-155 Q
KEPPLER, J. Q.	7907020242	50-358 Q	KEPPLER, J. Q.	7907130113	50-329 Q
KEPPLER, J. Q.	7907020245	50-440 Q	KEPPLER, J. Q.	7907130117	50-409 Q
KEPPLER, J. Q.	7907020249	50-329 Q	KEPPLER, J. Q.	7907130119	50-341 Q
KEPPLER, J. Q.	7907020252	50-341 Q	KEPPLER, J. Q.	7907130122	50-331 Q
KEPPLER, J. Q.	7907020254	50-461 Q	KEPPLER, J. Q.	7907130123	50-461 Q
KEPPLER, J. Q.	7907020258	50-367 Q	KEPPLER, J. Q.	7907130131	50-367 Q
KEPPLER, J. Q.	7907240226	50-484 Q	KEPPLER, J. Q.	7907130136	50-263 Q
KEPPLER, J. Q.	7907240233	50-346 Q	KEPPLER, J. Q.	7907130138	50-282 Q
KEPPLER, J. Q.	7907240238	50-483 Q	KEPPLER, J. Q.	7907130142	50-484 Q
KEPPLER, J. Q.	7907240245	ORQ	KEPPLER, J. Q.	7907130147	50-346 Q
KEPPLER, J. Q.	7907180462	50-331 P	KEPPLER, J. Q.	7907130150	50-346 Q
KEPPLER, J. Q.	7907180287	50-346 Q	KEPPLER, J. Q.	7907130155	50-483 Q
KEPPLER, J. Q.	7907300535	50-358 A	KEPPLER, J. Q.	7907130165	50-266 Q
KEPPLER, J. Q.	7907020406	ORQ	KEPPLER, J. Q.	7907130169	50-305 Q
KEPPLER, J. Q.	7907020409	50-10 Q	KEPPLER, J. Q.	7907130172	50-580 Q
KEPPLER, J. Q.	7907020416	50-358 Q	KEPPLER, J. Q.	7907060002	50-580 Q
KEPPLER, J. Q.	7907020419	50-440 Q	KEPPLER, J. Q.	7907060003	50-483 Q
KEPPLER, J. Q.	7907020421	50-329 Q	KEPPLER, J. Q.	7907060004	50-266 Q
KEPPLER, J. Q.	7907020423	50-155 Q	KEPPLER, J. Q.	7907060005	50-305 Q
			KEPPLER, J. Q.	7907060302	50-315 Q

# PERSONAL AUTHOR INDEX

405

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KEPPLER, J. G.	7907060303	50-10 Q
KEPPLER, J. G.	7907060306	50-358 Q
KEPPLER, J. G.	7907060307	50-440 Q
KEPPLER, J. G.	7907060308	50-329 Q
KEPPLER, J. G.	7907060310	50-155 Q
KEPPLER, J. G.	7907060311	50-409 Q
KEPPLER, J. G.	7907060312	50-341 Q
KEPPLER, J. G.	7907060313	50-331 Q
KEPPLER, J. G.	7907060314	50-461 Q
KEPPLER, J. G.	7907060315	50-367 Q
KEPPLER, J. G.	7907060317	50-484 Q
KEPPLER, J. G.	7907060318	50-263 Q
KEPPLER, J. G.	7907060319	50-546 Q
KEPPLER, J. G.	7907060320	50-346 Q
KEPPLER, J. G.	7907060321	ORQ
KEPPLER, J. G.	7907060463	50-580 Q
KEPPLER, J. G.	7907050466	50-373 Q
KEPPLER, J. G.	7907050469	50-358 Q
KEPPLER, J. G.	7907050470	50-440 Q
KEPPLER, J. G.	7907050472	50-329 Q
KEPPLER, J. G.	7907050473	50-341 Q
KEPPLER, J. G.	7907050474	50-461 Q
KEPPLER, J. G.	7907050477	50-367 Q
KEPPLER, J. G.	7907050478	50-484 Q
KEPPLER, J. G.	7907050480	50-546 Q
KEPPLER, J. G.	7907050481	50-483 Q
KEPPLER, J. G.	7907100521	50-305 Q
KEPPLER, J. G.	7907100522	50-580 Q
KEPPLER, J. G.	7907100523	50-346 Q
KEPPLER, J. G.	7907100525	50-546 Q
KEPPLER, J. G.	7907100526	50-266 Q
KEPPLER, J. G.	7907100528	50-483 Q
KEPPLER, J. G.	7907180390	50-315 Q
KEPPLER, J. G.	7907180392	50-10 Q
KEPPLER, J. G.	7907180400	50-358 Q
KEPPLER, J. G.	7907180403	50-440 Q
KEPPLER, J. G.	7907180405	50-329 Q
KEPPLER, J. G.	7907180406	50-155 Q
KEPPLER, J. G.	7907180408	50-409 Q
KEPPLER, J. G.	7907180410	50-341 Q
KEPPLER, J. G.	7907180412	50-331 Q
KEPPLER, J. G.	7907180418	50-461 Q
KEPPLER, J. G.	7907180420	50-367 Q
KEPPLER, J. G.	7907180422	50-263 Q
KEPPLER, J. G.	7907180423	50-484 Q
KEPPLER, J. G.	7907240064	50-373 Q
KEPPLER, J. G.	7907130236	50-10 Q
KEPPLER, J. G.	7907130238	50-358 Q
KEPPLER, J. G.	7907130239	50-440 Q
KEPPLER, J. G.	7907130260	50-329 Q
KEPPLER, J. G.	7907130262	50-155 Q
KEPPLER, J. G.	7907130265	50-409 Q
KEPPLER, J. G.	7907130267	50-341 Q
KEPPLER, J. G.	7907130268	50-331 Q
KEPPLER, J. G.	7907130270	50-461 Q
KEPPLER, J. G.	7907130271	50-315 Q
KEPPLER, J. G.	7907130279	50-367 Q
KEPPLER, J. G.	7907130281	50-484 Q
KEPPLER, J. G.	7907130282	50-263 Q
KEPPLER, J. G.	7907130286	50-580 Q
KEPPLER, J. G.	7907130289	50-346 Q
KEPPLER, J. G.	7907130291	50-346 Q
KEPPLER, J. G.	7907130293	50-483 Q
KEPPLER, J. G.	7907130297	50-266 Q
KEPPLER, J. G.	7907130300	50-305 Q
KEPPLER, J. G.	7907240081	50-10 Q
KEPPLER, J. G.	7907240089	50-155 Q
KEPPLER, J. G.	7907240091	50-409 Q
KEPPLER, J. G.	7907240094	50-331 Q
KEPPLER, J. G.	7907240097	50-315 Q
KEPPLER, J. G.	7907240104	50-263 Q
KEPPLER, J. G.	7907240108	50-346 Q
KEPPLER, J. G.	7907240113	50-266 Q
KEPPLER, J. G.	7907240120	50-305 Q
KEPPLER, J. G.	7907240016	50-87 Q
KEPPLER, J. G.	7907240022	50-116 Q
KEPPLER, J. G.	7907240025	50-294 Q
KEPPLER, J. G.	7907240026	50-150 Q
KEPPLER, J. G.	7907240027	50-182 Q
KEPPLER, J. G.	7907240030	50-151 Q
KEPPLER, J. G.	7907240033	50-123 Q
KEPPLER, J. G.	7907240035	50-186 Q
KEPPLER, J. G.	7907240064	50-156 Q
KEPPLER, J. G.	7907310161	50-264 Q
KEPPLER, J. G.	7907310305	50-315 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KEPPLER, J. G.	7907310311	50-10 Q
KEPPLER, J. G.	7907310319	50-358 Q
KEPPLER, J. G.	7907310325	50-440 Q
KEPPLER, J. G.	7907310328	50-155 Q
KEPPLER, J. G.	7907310331	50-329 Q
KEPPLER, J. G.	7907310332	50-409 Q
KEPPLER, J. G.	7907310334	50-341 Q
KEPPLER, J. G.	7907310335	50-331 Q
KEPPLER, J. G.	7907310337	50-461 Q
KEPPLER, J. G.	7907310340	50-367 Q
KEPPLER, J. G.	7907310341	50-484 Q
KEPPLER, J. G.	7907310342	50-263 Q
KEPPLER, J. G.	7907310344	50-580 Q
KEPPLER, J. G.	7907310345	50-546 Q
KEPPLER, J. G.	7907310348	50-346 Q
KEPPLER, J. G.	7907310349	50-483 Q
KEPPLER, J. G.	7907310354	50-266 Q
KEPPLER, J. G.	7907310355	50-305 Q
KEPPLER, J. G.	7907310402	50-315 Q
KEPPLER, J. G.	7907310403	50-10 Q
KEPPLER, J. G.	7907310404	50-440 Q
KEPPLER, J. G.	7907310405	50-358 Q
KEPPLER, J. G.	7907310406	50-155 Q
KEPPLER, J. G.	7907310407	50-329 Q
KEPPLER, J. G.	7907310408	50-409 Q
KEPPLER, J. G.	7907310409	50-341 Q
KEPPLER, J. G.	7907310410	50-331 Q
KEPPLER, J. G.	7907310411	50-461 Q
KEPPLER, J. G.	7907310412	50-367 Q
KEPPLER, J. G.	7907310413	50-484 Q
KEPPLER, J. G.	7907310414	50-263 Q
KEPPLER, J. G.	7907310415	50-580 Q
KEPPLER, J. G.	7907310416	50-546 Q
KEPPLER, J. G.	7907310417	50-346 Q
KEPPLER, J. G.	7907310418	50-483 Q
KEPPLER, J. G.	7907310419	50-266 Q
KEPPLER, J. G.	7907310420	50-305 Q
KEPPLER, J. G.	7907260148	50-315 Q
KEPPLER, J. G.	7907260153	50-10 Q
KEPPLER, J. G.	7907260164	50-358 Q
KEPPLER, J. G.	7907260167	50-440 Q
KEPPLER, J. G.	7907260168	50-155 Q
KEPPLER, J. G.	7907260174	50-329 Q
KEPPLER, J. G.	7907260178	50-409 Q
KEPPLER, J. G.	7907260181	50-341 Q
KEPPLER, J. G.	7907260184	50-331 Q
KEPPLER, J. G.	7907260189	50-461 Q
KEPPLER, J. G.	7907260194	50-367 Q
KEPPLER, J. G.	7907260199	50-263 Q
KEPPLER, J. G.	7907260201	50-484 Q
KEPPLER, J. G.	7907260206	50-580 Q
KEPPLER, J. G.	7907260211	50-546 Q
KEPPLER, J. G.	7907260214	50-346 Q
KEPPLER, J. G.	7907260217	50-483 Q
KEPPLER, J. G.	7907260220	50-266 Q
KEPPLER, J. G.	7907260224	50-305 Q
KEPPLER, J. G.	7907260336	50-10 Q
KEPPLER, J. G.	7907260348	50-358 Q
KEPPLER, J. G.	7907260349	50-440 Q
KEPPLER, J. G.	7907260351	50-329 Q
KEPPLER, J. G.	7907260354	50-155 Q
KEPPLER, J. G.	7907260359	50-409 Q
KEPPLER, J. G.	7907260389	50-341 Q
KEPPLER, J. G.	7907260391	50-331 Q
KEPPLER, J. G.	7907260394	50-461 Q
KEPPLER, J. G.	7907260398	50-315 Q
KEPPLER, J. G.	7907260399	50-367 Q
KEPPLER, J. G.	7907260402	50-263 Q
KEPPLER, J. G.	7907260407	50-484 Q
KEPPLER, J. G.	7907260410	50-580 Q
KEPPLER, J. G.	7907260413	50-346 Q
KEPPLER, J. G.	7907260416	50-346 Q
KEPPLER, J. G.	7907260418	50-483 Q
KEPPLER, J. G.	7907260422	50-266 Q
KEPPLER, J. G.	7907260425	50-305 Q
KEPPLER, J. G.	7907250217	50-10 Q
KEPPLER, J. G.	7907250224	50-358 Q
KEPPLER, J. G.	7907250225	50-440 Q
KEPPLER, J. G.	7907250227	50-329 Q
KEPPLER, J. G.	7907250228	50-155 Q
KEPPLER, J. G.	7907250229	50-315 Q
KERR, J. E.	7907020003	50-592 Q
KERR, J. E.	7907190379	50-592 Q
KERR, J. E.	7907090301	50-592 Q
KERR, W.	7907120338	ACR8
KERR, W.	7907120321	50-409 T

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KERR, W	7907230714	ACRS	KRANISH, A	7907190112	50-320 P
KERR, W	7907260728	50-320 T	KRAZINSKI, J L	7907250288	NUREQ
MERRICAN, R J	7907050513	71-87	KREYBA, F J	7907060439	FOIA
MERRICAN, R J	7907050519*	71-87	KREYBA, F J	7907050238	71-121
METCHEN, E C	7907170247	50-369 G	KREYBA, F J	7907030310	FOIA
METCHEN, E C	7907020008	70-2623	KRINITZSKY, E L	7907100371	REVIEW ORP
METCHEN, E C	7907130023	70-2623	KRODT, I B	7907100638	50-338 Q
METCHEN, E C	7907190723	70-2623	KRODT, I B	7907160186	50-338 Q
MEVERN, T A	7907180396	50-263 P	KRODT, I B	7907170254	50-338 Q
MEVERN, T A	7907180887	50-331 P	KRODT, I B	7907060438	50-338 Q
MEVERN, T A	7907250067	50-331 P	KRODT, I B	7907180606	50-338 Q
MEY, W J	7907050553*	50-304 Q	KRUQ, H E	7907130267	50-320 P
MEY, W J	7907180335*	50-315 Q	KUNIHIO, D M	7907230336*	50-295 Q
MEY, W J	7907240138*	50-237 Q	KURTH, R E	7907260716*	50-320 P
KIDD, M S	7907310203*	50-338 Q	KURTZ, R J	7907300068	NUREQ
KIMEL, W E	7907270217*	COMMISSION	KURTZ, R J	7907300489	REB
KINNEHAN, J	7907110664*	40-7983	KURTZ, R J	7907300554	REB
KINTIGH, A E	7907170012	50-596 C	KUS, C M	7907060297*	50-220 H
KINTIGH, A E	7907310241	50-596 A	KUZMYCZ, G	7907240449	50-257 P
KINTIGH, A E	7907310266	50-596 B	KYGER, J A	7907300047	NUREQ
KINTNER, L L	7907240583	50-341 F	LADD, J	7907190833	NUREQ
KIRK, W F	7907190714	PRM	LAFLEUR, J.	7907170042	50-522 A
KIRK, W F	7907180254	PRM	LAOIEWSKI, J B	7907030393*	50-317 B
KIRK, W F	7907110028	PR	LAOIEWSKI, J B	7907200409*	50-318 B
KIRK, W F	7907060500	70-371	LAOIEWSKI, J B	7907200415*	50-318 B
KIRKSEY, K A	7907300421	RES	LAOIEWSKI, J B	7907250304*	50-310 B
KIRSCH, D F	7907030094*	50-397 Q	LAGOMARSINO, R J	7907310164*	50-275 U
KIRSCH, D F	7907120419*	50-460 Q	LAINAS, O C	7907120732	50-320 P
KIRSCH, D F	7907300107*	50-508 Q	LAINAS, O.	7907110142	50-280 P
KIRSCH, D F	7907270306*	50-508 Q	LAINAS, O	7907110199	50-302 P
KIRSHNER, D	7907030240	50-592 A	LAINAS, O	7907110096	50-261 P
KISTER, H B	7907130238*	50-387 G	LAINAS, O	7907110114	50-267 P
KISTER, H B	7907200469*	50-293 Q	LAINAS, O	7907180864	50-259 Q
KISTER, H B	7907310130*	50-333 Q	LAINAS, O	7907180881	50-245 P
KISTER, H B	7907310017*	50-213 Q	LAINAS, O.	7907180898	50-293 P
KISTER, H B	7907120224	50-320 H	LAINAS, O	7907180899	50-261 P
KITCHEN, H	7907270153	PR	LAINAS, O	7907180705	50-302 P
KLEINSORGE, W P	7907260542*	50-348 Q	LAINAS, O	7907310315	50-348 Q
KLOMPARENS, A S	7907110641	10CFR	LAINAS, O	7907190126	50-286 F
KNELER, S K	7907270111	PR	LAINAS, O.	7907190155	50-237 P
KNIEL, K	7907240419*	RECORD	LAINAS, O.	7907180888	50-277 P
KNIEL, K	7907240406*	RECORD	LAINAS, O.	7907240479	50-266 P
KNOP, R C	7907180474*	50-546 Q	LAINAS, O	7907310466	50-266 P
KNOP, R C	7907180451*	50-451 Q	LAINAS, O	7907310597	50-244 F
KNOP, R C	7907300096*	50-329 Q	LANG, E A	7907180804	PROJ
KNOP, R C	7907250452*	50-440 Q	LANTAB, O	7907180846	50-409 F
KNOP, R C	7907260169*	50-341 Q	LANTZ, P M	7907300507	REB
KNOP, R C	7907261011*	50-461 Q	LANTZ, E	7907230226*	50-293 Q
KNOP, R C	7907250216*	50-483 Q	LANTZ, E	7907230345*	50-295 Q
KNOP, R C	7907250301*	50-373 Q	LARKINS, J T	7907160260	50-320 H
KNOTTS, J B	7907180879	50-445 H	LARKINS, J T	7907160225	50-320 H
KNOTTS, J B	7907020005	50-445 H	LARBEN, H M	7907180478	50-387 A
KNOTTS, J B	7907260014	50-445 H	LARSON, S H	7907200263	PRM
KNUTH, D F	7907090157*	SECY	LARSON, J R	7907270400	NUREQ
KNUTH, D F	7907050059*	FOIA	LASH, R.	7907090043*	SECY
KOERPER, J E	7907230157	PR	LASHER, L	7907160334*	TOPREP
KOESTER, K V	7907110690*	50-482 Q	LASHER, D R.	7907260449*	50-320 P
KOESTER, O L	7907260079	50-482 Q	LAUDIO, S	7907250464	50-546 A
KOESTER, O L	7907300027	50-482 S	LAUHLIN, J B	7907190824	PR
KOESTER, O L	7907230355*	50-482 Q	LAW, J T	7907180367	PR
KOESTER, O L	7907270291*	50-482 Q	LAW, S K	7907100579	50-320 H
KOESTER, O L	7907260607	50-482 S	LAWRENCE, J H	7907190642	PRM
KOESTER, O L	7907180530	50-482 S	LAWRENCE, L I	7907170082*	50-298 B
KOHLER, J E	7907180323*	50-295 Q	LAWROSKI, B	7907120321	50-409 T
KOHLER, J E	7907230276*	50-295 Q	LAWSON, J E.	7907190281	NUREQ
KOHLER, J E	7907230351*	50-295 Q	LAZARUS, W J	7907020467	50-309 P
KOHLER, J E	7907230364*	50-295 Q	LAZO, R. M.	7907130092	50-219 Q
KOHLER, J E	7907300392	50-295 Q	LAZO, R. M.	7907130037	50-454 Q
KOLIVIANAKIS, N	7907110444	50-234 S	LAZO, R. M.	7907240361	50-272 Q
KOLTAY, P S	7907180399*	50-247 Q	LEAVELL, W. H	7907120070	RES
KONKLIN, J E	7907250452*	50-440 Q	LEE, B	7907110135*	50-320 Q
KORNBLITH, L	7907240300	50-445 Q	LEE, C E	7907120156	NUREQ
KOSIK, L S	7907110449	50-358 Q	LEE, E W K	7907180319*	50-155 Q
KOSIK, L S	7907110456*	50-358 Q	LEE, T D.	7907230652*	70-143
KOSIK, L S	7907110463*	50-358 Q	LEE, W F	7907020116	FOIA
KOSIK, L S.	7907110468*	50-358 Q	LEE, W. B	7907110141*	50-320 Q
KOSIK, L S	7907110413	50-358 Q	LEED, R. M.	7907060487	50-522 Q
KOSIK, L S	7907100681	50-358 Q	LEED, R. M.	7907130038	50-522 Q
KOSIK, L S	7907190127	50-358 Q	LEED, R. M.	7907130045	50-522 Q
KOTTAN, J J	7907030220*	FOIA	LEED, R. M.	7907130024	50-522 Q
KOTTAN, J J.	7907300030*	50-244 Q	LEED, R. M.	7907130029	50-522 Q
KOUTS, H J.	7907240085	NUREQ	LEEDS, J V.	7907120412	50-329 T
KOVACS, B	7907300490*	71-99	LEEDS, J V.	7907120364	50-329 T
KRAATZ, R L	7907060349*	50-295 Q	LEEDS, J V.	7907160138	50-329 T
KRAJICEK, J E	7907180609*	50-283 P	LEEDS, J V	7907230540	50-329 T

# PERSONAL AUTHOR INDEX

407

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEEDS, J V	7907120380	50-329 T
LEEDS, J V	7907160151	50-329 T
LEEDS, J V	7907190606	50-329 T
LEEDS, J V	7907190594	50-329 T
LEEDS, J V	7907190853	50-329 T
LEEDS, E A	7907230592	50-329 T
LEEDS, J V	7907230526	50-329 T
LEEDS, J V	7907230874	50-329 T
LEEDS, J V	7907270321	50-329 T
LEEDS, J V	7907250174	50-329 T
LEEDS, J V	7907300153	50-329 T
LEFEVRE, H E	7907030253*	50-566 A
LEIDER, J P	7907060355*	50-295 Q
LEISS, J E	7907310605	50-294 P
LEMANOWICZ, T	7907240298	50-387 Q
LEMANOWICZ, I	7907180664	50-387 Q
LEMPERT, L B	7907130368	50-336 Q
LENAHAN, J J	7907240227*	50-400 Q
LENAHAN, J J	7907090433*	50-491 Q
LEONARD, B M	7907190738*	50-471 Q
LEONARD, J D	7907030058*	50-333 Q
LEONARD, J D	7907130437	50-333 P
LEONARD, J D	7907120066	50-333 Q
LEONARD, J D	7907090094	50-220 Q
LEONARD, J D	7907310107*	50-333 Q
LEONARD, J D	7907050133	50-333 Q
LEONARD, J D	7907240048	71-6375
LEONARD, J D	7907240050	71-6144
LEONARD, J D	7907090421	50-333 Q
LEONARD, J D	7907100607	50-333 R
LEONARD, J D	7907130460	50-333 S
LEONARD, J D	7907170030	50-333 S
LEONARD, J D	7907230287	50-333 S
LEONARD, J D	7907260646	50-333 S
LEONARD, J D	7907260741	50-333 S
LESSOR, L C	7907170054	50-298 S
LESSOR, L C	7907170063	50-298 S
LESSOR, L C	7907170079	50-298 S
LESSOR, L C	7907170027	50-298 S
LESSOR, L C	7907170233	50-298 R
LESSY, R P	7907050319	50-498 H
LESSY, R P	7907260038	50-445 H
LEVIN, H A	7906190135	50-10 P
LEVIN, H A	7907260505	50-213 P
LEVINE, S	7907120278*	SECY
LEVINE, S	7907120289*	SECY
LEVINE, S	7907050058	ORO
LEVINE, S	7907120165	REB
LEVINE, S	7907060089	COMMISSION
LEVINE, S	7907160194	50-320 P
LEVINE, S	7907090435	50-320 P
LEVINE, S	7907030156*	FOIA
LEVINE, S	7907030140*	FOIA
LEWALD, Q H	7907180334	50-471 Q
LEWALD, Q H	7907180829	50-471 Q
LEWALD, Q H	7907190587*	50-471 Q
LEWALD, Q H	7907190438	50-471 Q
LEWALD, Q H	7907120009	50-471 Q
LEWALD, Q H	7907240423*	50-471 Q
LEWIS, M I	7907100715	50-272 Q
LEWIS, H W	7907260509	50-320 H
LEWIS, L	7907250059	71-6375
LEWIS, L	7907130252*	70-2423
LEWIS, L	7907310448	71-6601
LEWIS, L	7907310454	71-6275
LEWIS, L	7907310456	71-5026
LEWIS, S R	7907070266*	50-267 S
LEWIS, S R	7907170165*	50-267 S
LEWIS, S R	7907180488*	50-267 S
LEWIS, S R	7907180305*	50-270 S
LEWIS, S R	7907230363*	50-267 S
LEWIS, B. Q.	7907170231	NUREG
LEWIS, S H	7907250468*	50-261 Q
LEWIS, S H	7907250462	50-261 Q
LEWIS, S H	7907060489	50-549 Q
LEWIS, S H	7907260121	50-596 Q
LEWIS, S H	7907180188	50-277 Q
LEWIS, R. C.	7907180634	50-348 Q
LEWIS, R. C.	7907230711	50-302 Q
LEWIS, R. C.	7907270036	50-364 Q
LEWIS, R. C.	7907270048	50-261 Q
LEWIS, R. C.	7907300032	50-261 Q
LEWIS, R. C.	7907260502	50-250 Q
LEWIS, R. C.	7907300040	50-302 Q
LEWIS, R. C.	7907310155	50-259 Q
LEWIS, R. C.	7907080176	50-320 P
LEWIS, R. C.	7907160072	50-269 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEWIS, R. C.	7907160030*	50-269 Q
LEWIS, R. C.	7907160040*	50-302 Q
LEWIS, R. C.	7906200120*	50-269 Q
LEWIS, R. C.	7907090126	50-335 Q
LEWIS, R. C.	7907120558	50-324 Q
LEWIS, R. C.	7907190046*	50-280 Q
LEWIS, R. C.	7907230775*	50-259 Q
LEWIS, R. C.	7907050067	50-338 Q
LEWIS, R. C.	7907240029*	50-250 Q
LEWIS, R. C.	7907200404	50-280 Q
LEWIS, R. C.	7907130356	50-327 Q
LEWIS, R. C.	7907160191*	50-369 Q
LEWIS, R. C.	7907180233	50-366 Q
LEWIS, R. C.	7907310194*	50-338 Q
LEWIS, R. C.	7907230018*	50-338 Q
LEWIS, R. C.	7907240119	50-338 Q
LEWIS, R. C.	7907240337	50-339 Q
LEWIS, R. C.	7907230734	50-338 Q
LEWIS, R. C.	7907130483*	50-338 Q
LEWIS, R. C.	7907240189	50-339 Q
LEWIS, R. C.	7907240276	50-280 Q
LEWIS, R. C.	7907240170	50-250 Q
LEWIS, R. C.	7907250143	50-335 Q
LEWIS, R. C.	7907300075	50-280 Q
LEWIS, R. C.	7907190050	50-280 Q
LEWIS, R. C.	7907130455	50-338 Q
LEWIS, R. C.	7907230748	50-259 Q
LEWIS, R. C.	7907240004	50-250 Q
LEWIS, R. C.	7907230012	50-338 Q
LEWIS, R. C.	7907310181	50-338 Q
LEWIS, R. C.	7907160253	50-302 Q
LEWIS, S H	7907260694	50-396 Q
LIBASSI, F P	7907110007*	50-320 Q
LIBERMAN, J D	7907100328	50-320 Q
LIBERATORE, A	7907190385	WASTE MGT
LIBRIZZI, F P	7907060044	71-328
LIBRIZZI, F P	7907170226	50-272 R
LIBRIZZI, F P	7907050301	50-272 S
LIBRIZZI, F P	7907090276	50-272 S
LIBRIZZI, F P	7907260582	50-272 S
LIBRIZZI, F P	7907260713	50-272 S
LIBRIZZI, F P	7907310364	50-272 S
LICHTENBERGER, H	7907130026*	70-1100
LICITRA, E A	7907130041	50-482 A
LICITRA, E A	7907110087	50-482 A
LICITRA, E A	7907130065	50-592 A
LICITRA, E A	7907030077	50-482 A
LICITRA, E A	7907030052	50-482 A
LIEBENTHAL, J L	7907160094	50-320 P
LIEBLER, Q E	7907160044*	50-389 Q
LIKE, I.	7907190182	50-322 Q
LIKE, I.	7907200182	50-514 Q
LIKE, I.	7907180755*	50-322 Q
LIKE, I	7907130400	50-322 Q
LIM, T H	7907090322	50-224 H
LIM, T H	7907160370	50-224 H
LINDBERG, C	7907230372*	50-249 S
LINDBLAD, W J	7907080230	50-514 A
LINDER, F	7907020654	50-409 Q
LINDER, F	7907090473	50-409 Q
LINDER, F.	7907050005	50-409 Q
LINDER, F	7907110385	50-409 Q
LINDER, F.	7907090274	50-409 Q
LINDER, F	7907020177	50-409 P
LINDER, F	7907060326	50-409 S
LINDER, F.	7907260481	50-409 F
LINDER, F	7907110535	50-409 P
LINDER, F	7907170043	50-409 P
LINDER, F	7907170018	50-409 P
LINDER, F	7907190580	50-409 P
LINDER, F	7907300388	50-409 P
LINDER, F	7907180519	50-409 R
LINDER, F.	7907260576	50-409 I
LINDER, F	7907260788	50-409 P
LINDLEY, P. A	7907020463	40-8712
LINDNER, T. P.	7907240292	XPORLTIC
LINDNER, T. P.	7907240294	XPORLTIC
LINEHAN, J J	7907060074	40-8452
LINEHAN, J J	7907100710	40-8584
LINEHAN, J. J.	7907020470	40-6659
LINEHAN, J. J.	7907020468	40-1162
LINEHAN, J. J.	7907100706	40-8102
LINENBERGER, G A	7907190114	50-466 Q
LINENBERGER, G A	7907300113	50-522 T
LINENBERGER, G. A	7907270285	50-522 T
LINENBERGER, G A	7907270245	50-522 T
LINLAD, W J	7907100408	50-514 R
LIPPINCOTT, S. M.	7907300373*	50-344 F

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LIPPINCOTT, E P	7907270357	NUREQ
LISQVITCA, V V	7905240084*	WASTE MGT
LITTLE, W S	7907260526*	50-301 Q
LITTLEJOHN, J D	7907180765	50-320 P
LITTLE, D S	7907110733	50-522 Q
LITTLE, D S	7907090009	50-522 Q
LITTLE, L W	7907120249	50-295 T
LITTLE, L W	7907120201	50-295 T
LITTLE, L W	7907300184	50-295 T
LITTLE, M	7907310498	CONTRACT
LITTLE, W S	7907310189*	50-116 Q
LITTLE, W S	7907100382	50-320 H
LIVERMORE, H H	7907200290*	50-281 Q
LIVINGSTON, R L	7907310136*	50-382 U
LO, R	7907180134	NUREQ
LOBEL, R M	7907230345*	50-295 Q
LODGE, T J	7907110021*	50-346 P
LODGE, T J	7907060514*	50-346 Q
LODGE, T J	7907130513	50-346 Q
LODGE, T J	7907130515*	50-346 Q
LODGE, T J	7907130521*	50-346 Q
LOGAN, J A	7907250240*	XPORTLIC
LOGGINS, D	7907260452	FOIA
LOKEN, M K	7907240394	PRM
LOKEN, M K	7907190688	FR
LOMAX, F	7907130524	40-3453
LONG, R L	7907020107	50-320 P
LONG, R L	7907130284	50-320 P
LONG, D O	7907100489*	50-29 S
LONG, D O	7907100500*	50-29 S
LONGLEY, M Y	7907190312	WASTE MGT
LORD, F F	7907110024	PR
LOSH, L L	7907260530	50-320 P
LOTTEB, P A	7907080245	REB
LOVEJOY, C A	7907300497*	50-201 I
LOVELADY, J M	7907230586*	COMMISSION
LOWENSTEIN, R	7907300532*	50-201 I
LOWENSTEIN, R	7907300427*	50-201 I
LOWERRE, R W	7907190302	WASTE MGT
LOWERRE, R W	7907020002	50-466 Q
LOWI, T J	7907020132	FOIA
LUCAS, A M	7907190780	RECD
LUCAS, S	7907190397	71-9070
LUEBBERS, T A	7907050344	50-338 Q
LUEBKE, E A	7907250070	70-2623
LUEBKE, E A	7907030251	70-2623
LUEBKE, E A	7907030189	70-2623
LUEBKE, E A	7907120121	70-2623
LUEBKE, E A	7907250105	70-2623
LUEBKE, E A	7907250146	70-2623
LUEBKE, E A	7907250081	70-2623
LUEBKE, E A	7907250092	70-2623
LUEBKE, E A	7907250135	70-2623
LUEBKE, E A	7907250162	70-2623
LUEBKE, E A	7907120412	50-329 T
LUEBKE, E A	7907120364	50-329 T
LUEBKE, E A	7907160138	50-329 T
LUEBKE, E A	7907230540	50-329 T
LUEBKE, E A	7907120380	50-329 T
LUEBKE, E A	7907160151	50-329 T
LUEBKE, E A	7907190606	50-329 T
LUEBKE, E A	7907190594	50-329 T
LUEBKE, E A	7907190833	50-329 T
LUEBKE, E A	7907230592	50-329 T
LUEBKE, E A	7907230526	50-329 T
LUEBKE, E A	7907230574	50-329 T
LUEBKE, E A	7907270321	50-329 T
LUEBKE, E A	7907250174	50-329 T
LUEBKE, E A	7907300153	50-329 T
LUEDECKE, A R	7907300180*	FOIA
LULL, R J	7907310075	FR
LUNDVALL, A E	7907100033	50-317 Q
LUNDVALL, A E	7907100021	50-317 Q
LUNDVALL, A E	7907200481	50-317 Q
LUNDVALL, A E	7907300091	50-317 Q
LUNDVALL, A E	7907300124	50-317 Q
LUNDVALL, A E	7907030288	50-317 Q
LUNDVALL, A E	7907170062	50-317 P
LUNDVALL, A E	7907190222	50-317 P
LUNDVALL, A E	7907310390	50-317 P
LUTKEN, D C	7907050346	50-416 A
LUTON, E	7907060342	50-293 Q
LUTON, E	7907060246	50-456 Q
LUTON, E	7907180373	50-454 Q
LUTON, E	7907130287	50-70 Q
LUTON, E	7907190631	50-70 Q
LUTON, E	7907180630	50-133 Q
LUZA, K V	7907190281	NUREQ
LYNCH, O D	7907020163	50-320 P
LYON, P W	7907190263	PRM

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MACARTHUR, T C	7907200234*	70-27
MACARTHUR, T C	7907100873	50-320 H
MACDOUGALL, E A	7907300353	50-266 F
MACDOUGALL, E A	7907310175	50-282 F
MACDOUGALL, E A	7907310186	50-10 F
MACDONALD, C E	7907030166*	71-215
MACDONALD, C E	7907240508*	71-110
MACDONALD, C E	7907260364*	71-205
MACDONALD, C E	7907260346*	71-74
MACDONALD, C E	7907260428*	71-134
MACDONALD, C E	7907090432*	50-263 P
MACDONALD, C E	7907260386*	71-156
MACDONALD, C E	7907260355*	71-39
MACDONALD, C E	7907110709	71-99
MACDONALD, C E	7907060021	71-9070
MACDONALD, C E	7907050227	71-6244
MACDONALD, C E	7907030232*	71-6244
MACDONALD, C E	7907060113	71-8
MACDONALD, C E	7907090031	71-6104
MACDONALD, D C	7907100608	71-6400
MACDONALD, C E	7907100613	71-5450
MACDONALD, C E	7907100619	71-9074
MACDONALD, C E	7907100621	71-9010
MACDONALD, C E	7907100623	71-9081
MACDONALD, C E	7907100634	71-6378
MACDONALD, C E	7907100641	71-6642
MACDONALD, C E	7907110621	71-3026
MACDONALD, C E	7907060067	71-328
MACDONALD, C E	7907060068*	71-328
MACDONALD, C E	7907060070	71-325
MACDONALD, C E	7907060071*	71-325
MACDONALD, C E	7907110054	71-6275
MACDONALD, C E	7907110145	71-327
MACDONALD, C E	7907110151*	71-327
MACDONALD, C E	7907110419	71-96
MACDONALD, C E	7907130080	71-9
MACDONALD, C E	7907130083	71-67
MACDONALD, C E	7907160228	71-54
MACDONALD, C E	7907180717	71-6601
MACDONALD, C E	7907190024	71-8026
MACDONALD, C E	7907110288	71-116
MACDONALD, C E	7907110410	71-248
MACDONALD, C E	7907110464	71-264
MACDONALD, C E	7907110472	71-198
MACDONALD, C E	7907110476	71-189
MACDONALD, C E	7907020488	71-102
MACDONALD, C E	7907060507	71-6144
MACDONALD, C E	7907090436	71-6574
MACDONALD, C E	7907090447	71-6280
MACDONALD, C E	7907090454	71-9001
MACDONALD, C E	7907090457	71-5980
MACDONALD, C E	7907100663	71-6291
MACDONALD, C E	7907100665	71-9005
MACDONALD, C E	7907100668	71-6291
MACDONALD, C E	7907110304	71-5768
MACDONALD, C E	7907110469	71-40
MACDONALD, C E	7907120092	71-5901
MACDONALD, C E	7907120099	71-5398
MACDONALD, C E	7907120123	71-9017
MACDONALD, C E	7907120267	71-5455
MACDONALD, C E	7907130063	71-46
MACDONALD, C E	7907190037	71-3754
MACDONALD, C E	7907250305	71-5977
MACDONALD, C E	7907250333	71-5149
MACDONALD, C E	7907300345	71-9018
MACDONALD, C E	7907310169	71-9019
MACDONALD, C E	7907310176	71-9018
MACDONALD, C E	7907180457	71-37
MACDONALD, C E	7907180459*	71-37
MACDONALD, C E	7907190279	71-95
MACDONALD, C E	7907190286*	71-95
MACDONALD, C E	7907230007	71-80
MACDONALD, C E	7907230009*	71-80
MACDONALD, C E	7907230028	71-120
MACDONALD, C E	7907230033*	71-120
MACDONALD, C E	7907230037	71-113
MACDONALD, C E	7907230049*	71-113
MACDONALD, C E	7907230054	71-123
MACDONALD, C E	7907230069*	71-123
MACDONALD, C E	7907230214	71-28
MACDONALD, C E	7907230225*	71-28
MACDONALD, C E	7907230237	71-145
MACDONALD, C E	7907230248*	71-145
MACDONALD, C E	7907230258	71-51
MACDONALD, C E	7907230267*	71-51
MACDONALD, C E	7907230278	71-47



# PERSONAL AUTHOR INDEX

409

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MACDONALD, C E	7907230283*	71-47	MACDONALD, C E	7907230272*	71-307
MACDONALD, C E	7907230293	71-59	MACDONALD, C E	7907230279	71-305
MACDONALD, C E	7907230300*	71-59			
MACDONALD, C E	7907230622	71-11	MACDONALD, C E	7907230281*	71-305
MACDONALD, C E	7907230630*	71-11	MACDONALD, C E	7907230309	71-326
MACDONALD, C E	7907230634	71-34	MACDONALD, C E	7907230319*	71-326
MACDONALD, C E	7907230639*	71-34	MACDONALD, C E	7907230326	71-322
MACDONALD, C E	7907230645	71-150	MACDONALD, C E	7907230331*	71-322
MACDONALD, C E	7907230653*	71-150	MACDONALD, C E	7907300314	71-292
			MACDONALD, C E	7907300317*	71-292
MACDONALD, C E	7907230655	71-32	MACDONALD, C E	7907230238	71-5942
MACDONALD, C E	7907230658*	71-32	MACDONALD, C E	7907240313	71-6581
MACDONALD, C E	7907230662	71-55	MACDONALD, C E	7907260454*	71-133
MACDONALD, C E	7907230666*	71-55			
MACDONALD, C E	7907230673	71-57	MACDONALD, C E	7907240522*	71-148
			MACDONALD, C E	7907260373*	71-157
MACDONALD, C E	7907230680*	71-57	MACDONALD, C E	7907180701	71-361
MACDONALD, C E	7907230776	71-105	MACDONALD, C E	7907180702	71-9108
MACDONALD, C E	7907230782*	71-105	MACDONALD, C E	7907180783	71-9033
MACDONALD, C E	7907230786	71-104			
MACDONALD, C E	7907230787	71-103	MACDONALD, C E	7907240236*	71-153
			MACDONALD, C E	7907240301	71-9010
MACDONALD, C E	7907230789*	71-104	MACDONALD, C E	7907240307	71-9010
MACDONALD, C E	7907230792*	71-103	MACDONALD, C E	7907240531*	71-140
MACDONALD, C E	7907240107	71-127	MACDONALD, C E	7907250019	71-161
MACDONALD, C E	7907240110*	71-127			
MACDONALD, C E	7907240247	71-77	MACDONALD, C E	7907230023*	71-161
			MACDONALD, C E	7907230027	71-22
MACDONALD, C E	7907240256*	71-77	MACDONALD, C E	7907230029*	71-22
MACDONALD, C E	7907240499	71-110	MACDONALD, C E	7907230386	71-310
MACDONALD, C E	7907240513	71-148	MACDONALD, C E	7907230393*	71-310
MACDONALD, C E	7907240524	71-140			
MACDONALD, C E	7907240537	71-119	MACDONALD, C E	7907230397	71-281
			MACDONALD, C E	7907230400*	71-281
MACDONALD, C E	7907240545*	71-119	MACDONALD, C E	7907250423	71-137
MACDONALD, C E	7907240553	71-132	MACDONALD, C E	7907250426*	71-137
MACDONALD, C E	7907240561*	71-132	MACDONALD, C E	7907260341	71-74
MACDONALD, C E	7907240566	71-134			
MACDONALD, C E	7907240571*	71-134	MACDONALD, C E	7907260350	71-39
			MACDONALD, C E	7907260361	71-205
MACDONALD, C E	7907240577	71-130	MACDONALD, C E	7907260370	71-157
MACDONALD, C E	7907240580*	71-130	MACDONALD, C E	7907260379	71-156
MACDONALD, C E	7907240584	71-75	MACDONALD, C E	7907260401	71-152
MACDONALD, C E	7907240590*	71-75			
MACDONALD, C E	7907240595	71-76	MACDONALD, C E	7907260411*	71-152
			MACDONALD, C E	7907260421	71-154
MACDONALD, C E	7907240601*	71-76	MACDONALD, C E	7907260432	71-151
MACDONALD, C E	7907180448	71-61	MACDONALD, C E	7907260439*	71-151
MACDONALD, C E	7907180452*	71-61	MACDONALD, C E	7907260446	71-133
MACDONALD, C E	7907180453	71-87			
MACDONALD, C E	7907180454*	71-87	MACDONALD, C E	7907260465	71-89
			MACDONALD, C E	7907250459	71-334
MACDONALD, C E	7907180743	71-102	MACDONALD, C E	7907250463*	71-334
MACDONALD, C E	7907180841	71-5942	MACDONALD, C E	7907230469	71-236
MACDONALD, C E	7907180848*	71-5942	MACDONALD, C E	7907230476	71-246
MACDONALD, C E	7907230251	71-4949			
MACDONALD, C E	7907230255*	71-4949	MACDONALD, C E	7907230583	71-263
			MACDONALD, C E	7907230587	71-262
MACDONALD, C E	7907250244	71-3	MACDONALD, C E	7907230591	71-79
MACDONALD, C E	7907250246*	71-3	MACDONALD, C E	7907230595	71-31
MACDONALD, C E	7907260527	71-6078	MACDONALD, C E	7907230604	71-265
MACDONALD, C E	7907260574	71-5341			
MACDONALD, C E	7907260575	71-6172	MACDONALD, C E	7907230606	71-308
			MACDONALD, C E	7907230609	71-321
MACDONALD, C E	7907260469*	71-89	MACDONALD, C E	7907230610	71-318
MACDONALD, C E	7907240385	71-5977	MACDONALD, C E	7907230613	71-251
MACDONALD, C E	7907240390	71-6697	MACDONALD, C E	7907230614	71-228
MACDONALD, C E	7907240394	71-5980			
MACDONALD, C E	7907240407	71-5901	MACDONALD, C E	7907230616	71-252
			MACDONALD, C E	7907230620	71-316
MACDONALD, C E	7907240439	71-9017	MACDONALD, C E	7907250359	71-136
MACDONALD, C E	7907240458	71-9022	MACDONALD, C E	7907250368	71-163
MACDONALD, C E	7907240475	71-5768	MACDONALD, C E	7907250374	71-177
MACDONALD, C E	7907240485	71-9001			
MACDONALD, C E	7907240494	71-6280	MACDONALD, C E	7907180795	71-9450
			MACDONALD, C E	7907180808	71-9081
MACDONALD, C E	7907240501	71-6357	MACDONALD, C E	7907180821	71-4986
MACDONALD, C E	7907250280	71-5910	MACDONALD, C E	7907180832	71-9044
MACDONALD, C E	7907310142	71-6574	MACDONALD, C E	7907180837	71-5344
MACDONALD, C E	7907310162	71-9033			
MACDONALD, C E	7907230244	71-5908	MACDONALD, C E	7907180847	71-6601
			MACDONALD, C E	7907180855	71-9070
MACDONALD, C E	7907260539	71-6144	MACDONALD, C E	7907180865	71-6357
MACDONALD, C E	7907190601	71-304	MACDONALD, C E	7907180917	71-9081
MACDONALD, C E	7907190604*	71-304	MACDONALD, C E	7907180918	71-6144
MACDONALD, C E	7907190610	71-306			
MACDONALD, C E	7907190613*	71-306	MACDONALD, C E	7907190602	71-9113
MACDONALD, C E	7907230096	71-319	MACDONALD, C E	7907200239	71-4986
MACDONALD, C E	7907230099*	71-319	MACDONALD, C E	7907230019	71-216
MACDONALD, C E	7907230104	71-294	MACDONALD, C E	7907230023*	71-216
MACDONALD, C E	7907230111*	71-294	MACDONALD, C E	7907230030	71-217
MACDONALD, C E	7907230115	71-284			
			MACDONALD, C E	7907230036*	71-217
MACDONALD, C E	7907230120*	71-284	MACDONALD, C E	7907230042	71-225
MACDONALD, C E	7907230126	71-320	MACDONALD, C E	7907230047*	71-225
MACDONALD, C E	7907230130*	71-320	MACDONALD, C E	7907230692	71-162
MACDONALD, C E	7907230156	71-298	MACDONALD, C E	7907230698*	71-162
MACDONALD, C E	7907230159*	71-298			
			MACDONALD, C E	7907240009	71-15
MACDONALD, C E	7907230262	71-314	MACDONALD, C E	7907240014*	71-15
MACDONALD, C E	7907230266*	71-314	MACDONALD, C E	7907240018	71-218
MACDONALD, C E	7907230269	71-307	MACDONALD, C E	7907240023*	71-218
			MACDONALD, C E	7907240028	71-219

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MACDONALD, C E	7907240032	71-226	MANRY, M	7907110588	50-366 S
MACDONALD, C E	7907240034*	71-219	MANRY, M	7907020248	50-366 S
MACDONALD, C E	7907240037*	71-226	MANRY, M	7907020239	50-366 S
MACDONALD, C E	7907240038	71-184			
MACDONALD, C E	7907240040*	71-184	MANRY, M	7907080283	50-366 S
			MANRY, M	7907020302	50-366 S
MACDONALD, C E	7907240042	71-166	MANRY, M	7907030194	50-366 S
MACDONALD, C E	7907240044*	71-166	MANRY, M	7907090360	50-366 S
MACDONALD, C E	7907240046	71-166	MANRY, M	7907030372	50-366 S
MACDONALD, C E	7907240049*	71-166			
MACDONALD, C E	7907240228	71-153	MANRY, M	7907060234	50-321 R
MACKENZIE, V V	7907190379	50-592 G	MANRY, M	7907060346	50-321 S
MA DOCKES, W	7907260198	PR	MANRY, M	7907090330	50-366 S
MADEDA, T J	7907050163*	50-346 G	MANRY, M	7907060305	50-366 S
MA DIA, W J	7907030243	RES	MANRY, M	7907090336	50-366 S
MA D ISON, W R	7907130272*	50-338 R	MANRY, M	7907090373	50-321 S
			MANRY, M	7907100350	50-321 R
			MANRY, M	7907100369	50-321 S
MA DSEN, O L	7907090439	50-313 G	MANRY, M	7907170133	50-321 S
MA DSEN, O L	7907110742	50-285 G	MANRY, M	7907170214	50-321 S
MA DSEN, O L	7907180643	50-298 G			
MA DSEN, O L	7907310537	50-313 G	MANRY, M	7907170100	50-366 S
MA DSEN, O L	7907160062	50-313 G	MANRY, M	7907180458	50-321 S
			MANRY, M	7907180545	50-366 S
MA DSEN, O L	7907160017*	50-313 G	MANRY, M	7907170220	50-321 R
MA DSEN, O L	7907050138	50-298 G	MANRY, M	7907190564	50-366 R
MA DSEN, O L	7907200220*	50-192 G			
MA DSEN, O L	7907050142	50-267 G	MANRY, M	7907170089	50-366 S
MA DSEN, O L	7907200213	50-192 G	MANRY, M	7907170206	50-321 S
			MANRY, M	7907170216	50-366 S
MA DSEN, O L	7907090165	50-267 G	MANRY, M	7907230480	50-366 S
MA DSEN, O L	7907120001	50-313 G	MANRY, M	7907170086	50-321 S
MA DSEN, O L	7907090191	50-298 G			
MA DSEN, O L	7907020206	50-285 G	MANRY, M	7907170087	50-321 S
MA DSEN, O L	7907090379	50-298 G	MANRY, M	7907230535	50-321 S
			MANRY, M	7907230477	50-366 S
MA DSEN, O L	7907030252	50-298 S	MANRY, M	7907230546	50-366 S
MA DSEN, O L	7907030234	50-267 S	MANRY, M	7907230467	50-366 S
MA DSEN, O L	7907030256	50-313 S			
MA DSEN, O L	7907030258	50-285 S	MANRY, M	7907240224	50-366 S
MA DSEN, O L	7907190038	50-298 G	MANRY, M	7907230516	50-366 S
			MANRY, M	7907260799	50-366 S
MA DSEN, O L	7907080297	50-313 S	MANRY, M	7907260824	50-366 S
MA DSEN, O L	7907080298	50-285 S	MANRY, M	7907260840	50-321 S
MA DSEN, O L	7907080299	50-298 S			
MA DSEN, O L	7907020301	50-267 S	MANBER, W C	7907130132*	70-143
MA DSEN, O L	7907270110	50-267 G	MANBER, W C	7907090368	70-143
			MANBER, W C	7907160247	70-143
MA DSEN, O L	7907300103	50-267 G	MANBER, W C	7907130121*	70-143
MA DSEN, O L	7907300472	50-298 G	MANBER, W C	7907230619*	70-143
MA DSEN, O L	7907180653*	50-298 G			
MA DSEN, O L	7907030175	50-313 S	MARCHAL, J	7907030196	XPORTLIC
MA DSEN, O L	7907030177	50-298 S	MARCHAL, J	7907120047	XPORTLIC
			MARCHAL, J	7907110701	XPORTLIC
MA DSEN, O L	7907030181	50-285 S	MARIANI, L P	7907090226*	NUREO
MA DSEN, O L	7907030183	50-267 S	MARK, J C	7907230714	ACRS
MA DSEN, O L	7907030218	50-313 G			
MA DSEN, O L	7907030223	50-298 S	MARKEY, A K	7907130009	50-295 G
MA DSEN, O L	7907030224	50-285 S	MARROWSKI, R S	7907130238*	50-387 G
			MARRACK, D	7907110558	50-466 G
MA DSEN, O L	7907030226	50-267 S	MARTIN, D E	7907030148	FOIA
MA DSEN, O L	7907130307	50-313 G	MARTIN, T D	7907190132*	50-358 G
MA DSEN, O L	7907130325	50-298 S			
MA DSEN, O L	7907130327	50-285 S	MARTIN, M D	7907190717	PR
MA DSEN, O L	7907130330	50-267 S	MARTIN, T J	7907300871*	50-311 S
			MARTIN, T J	7907230008*	50-311 G
MA DSEN, O L	7907240271	50-313 G	MARTIN, T J	7907030443	50-354 G
MA DSEN, O L	7907180669	50-313 G	MARTIN, T J	7907180114	50-354 G
MA DSEN, O L	7907180671	50-298 S			
MA DSEN, O L	7907180674	50-285 S	MARTIN, T J	7907160144	50-354 G
MA DSEN, O L	7907180677	50-267 S	MARTIN, R A	7907300927	RES
			MARTIN, W Q	7907080047	70-2622
MAHLER, H R	7907260357	50-338 G	MARTIN, W Q	7907130031*	70-1100
MAJOR, R K	7907110324	50-320 G	MARTIN, W Q	7907130160*	50-184 G
MAKEPEACE, J M	7907200401*	50-247 S			
MAKEPEACE, J M	7907240397*	50-247 S	MARTIN, W Q	7907180707*	70-820
MAKEPEACE, J M	7907300293*	50-247 S	MARTIN, W Q	7907250524*	FOIA
			MARTIN, W Q	7907240296	70-33
MALARD, J C	7907060208	WASTE HOT	MARTIN, W Q	7907200485	70-820
MALARD, J C	7907190505	WASTE HOT	MARTIN, W Q	7907130005	70-1100
MALARD, J C	7907190293	WASTE HOT			
MALET, E I	7907190076	FOIA	MARTIN, W Q	7907130156	50-184 G
MALLET, R A	7907060094*	COMMISSION	MARTIN, W Q	7907180684	70-820
			MARTIN, R D	7907090130*	50-335 G
MALMROS, M H	7907300135*	50-344 G	MARTIN, R D	7907130359*	50-327 G
MAMIYA, S	7907180868	XPORTLIC	MARTIN, R D	7907270043*	50-364 G
MANCINI, B	7907280291*	50-10 S			
MANDLER, J W	7907190691	RES	MARTIN, R D	7907240070*	50-250 G
MANDLER, J W	7907310320	RES	MARTIN, R D	7907180244*	50-366 G
			MARTIN, R D	7907230039*	50-338 G
MANEV, M M	7907300149	FOIA	MARTIN, R D	7907230740*	50-338 G
MANGUSI, J	7907120316	70-1375	MARTIN, R D	7907130490*	50-338 G
MANGUSI, J	7907120112	70-1375			
MANHUSEN, C	7907300294	XPORTLIC	MARTIN, R D	7907300037*	50-261 G
MANJUSSEN, C	7907300304	XPORTLIC	MARTIN, R D	7907240184*	50-250 G
			MARTIN, R D	7906200127*	50-269 G
MANN, J R	7907260617	PRM	MARTIN, L E	7907110693*	50-445 G
MANNING, J P	7907110018	PR	MARTIN, L E	7907110612*	50-498 G
MANRY, M	7907110482*	50-321 S			
MANRY, M	7907110478	50-321 S	MARTIN, L E	7907110418*	50-382 G
MANRY, M	7907110491*	50-321 S	MARTIN, L E	7907110628*	50-482 G
			MARTIN, L E	7907250518*	50-445 G
MANRY, M	7907110504	50-366 S	MASBENOALE, E W	7907020143	FOIA
MANRY, M	7907110400	50-366 S	MASSE, R E	7907270407*	50-315 G

# PERSONAL AUTHOR INDEX

41

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MASSE, R E	7907300092*	50-315 G	MATTSEN, C R	7907160301*	70-2623
MASSIE, H W	7907120103	RES	MATTSON, R J	7907020064	50-320 P
MASSIE, H W	7907120107	RES	MATTSON, R J	7907310064	50-320 P
MASSIE, H W	7907120121	RES			
MASSIE, H W	7907120138	RES	MAURA, F A	7907180627*	50-358 Q
MASSIE, H W	7907120126	RES	MAXWELL, O F	7907230746*	50-456 Q
MASSIE, H W	7907120123	RES	MAYBERRY, W E	7907260187	FR
MASSIE, H W	7907120076	RES	MAYER, L O	7907090428	50-263 P
MASSIE, H W	7907120115	RES	MAYER, L O	7907030340	50-263 S
MASSIE, H W	7907120109	RES			
MASSICOT, P	7907190394	WASTE MGT	MAYER, L O	7907030300	50-282 S
MASTBAUM, D	7907180297	50-592 Q	MAYER, L O	7907050404	50-282 S
MATERS, B R	7907170072	50-341 A	MAYER, L O	7907100618	50-263 F
MATHEWS, D H	7907050024	FDIA	MAYER, L O	7907130469	50-282 S
MATHEWS, R D	7907260958	PR	MAYER, L O	7907160346	50-282 S
MATHEWS, E R	7907300452	50-305 Q	MAYER, L O	7907170001	50-263 R
MATHEWS, E R	7907050307	50-305 S	MAYER, L O	7907180511	50-282 R
MATHEWS, E R	7907090281	50-305 S	MAYER, L O	7907190211	50-282 P
MATHEWS, E R	7907090309	50-305 S	MAYER, L O	7907210381	50-263 F
MATHEWS, E R	7907130436	50-305 R	MAYER, L O	7907210388	50-282 F
			MAYNARD, C D	7907190649	PRM
MATHEWS, E R	7907170081	50-305 S	MAZETIS, G R	7907050437	50-346 P
MATHEWS, E R	7907170022	50-305 S	MCALLISTER, R N	7907180676	50-272 Q
MATHEWS, E R	7907190555	50-305 P	MCARDY, J F	7907130479*	50-346 P
MATHEWS, E R	7907300354	50-305 F	MCARDY, J F	7907130474*	50-346 P
MATHIS, C J	7907110509	50-293 S			
			MCCREARY, R A	7907270381*	50-220 Q
MATHIS, C J	7907160324*	50-293 S	MCCABE, E C	7907230479*	50-220 Q
MATHIS, C J	7907170191	50-293 S	MCCABE, E C	7907200420*	50-57 Q
MATHIS, C J	7907190528*	50-293 S	MCCQUIRE, P J	7907260686	50-293 S
MATHIS, C J	7907200275	50-293 S	MCCQUIRE, P J	7907260695	50-293 S
MATHIS, C J	7907240257	50-293 S			
			MCKENZIE, V V	7907020003	50-592 Q
MATHIS, C J	7907190308	50-293 S	MCLANAHAN, H H	7907060394	70-27
MATHIS, C J	7907190323	50-293 S	MCLAIN, C M	7907250354*	50-219 R
MATIN, J A	7907100051	50-320 P	MCELLELLAN, C K	7907190130*	50-498 H
MATSON, V	7906140602*	XPORTLIC	MCLINTOCK, R	7907110664*	40-7583
MATSON, V	7907120382	XPORTLIC			
			MCLURE, L W	7907180134	NUREQ
MATSON, V	7907180563	XPORTLIC	MCLUNG, R W	7907190488	NUREQ
MATSON, V	7907250053	XPORTLIC	MCCONNELL, E R	7907300444*	50-201 I
MATSON, V	7907100053	XPORTLIC	MCCOOL, W B	7907300206*	FDIA
MATSON, V	7907230046	XPORTLIC	MCCOOL, W B	7907300216*	FDIA
MATSON, V	7907230052*	XPORTLIC			
			MCCORKLE, O W	7907050091	70-143
MATSON, V	7907210301	XPORTLIC	MCCORKLE, O W	7907060042	70-2623
MATTHEWS, E R	7907180521	50-305 P	MCCORKLE, O W	7907060193	70-27
MATTHEWS, P	7907110154	50-320 P	MCCORKLE, O W	7907100661	70-754
MATTIMOE, J J	7907090347*	50-312 Q	MCCORKLE, O W	7907110593	70-135
MATTIMOE, J J	7907090352*	50-312 Q			
			MCCORKLE, O W	7907110600	70-734
MATTIMOE, J J	7907090358*	50-312 Q	MCCORKLE, O W	7907090134	70-754
MATTIMOE, J J	7907090341*	50-312 Q	MCCRELESS, T G	7907090458	50-320 P
MATTIMOE, J J	7907090377	50-312 Q	MCCULLUGH, R W	7907230511*	71-6581
MATTIMOE, J J	7907020471	50-312 Q	MCDERMOTT, R J	7907260029*	GA999
MATTIMOE, J J	7907050215	50-312 F			
			MCDIARMID, R C	7907110343*	50-416 H
MATTIMOE, J J	7907050317	50-312 P	MCDIARMID, R C	7907110337*	50-416 H
MATTIMOE, J J	7907300300	50-312 F	MCDIARMID, R C	7907110328*	50-416 H
MATTIMOE, J J	7907170008	50-312 P	MCDIARMID, R C	7907030298	50-416 Q
MATTIMOE, J J	7907300408	50-312 Q	MCDIARMID, R C	7907050299	50-416 H
MATTIMOE, J J	7907250391	50-312 P			
			MCDONALD, J R	7907260127*	50-445 U
MATTIMOE, J J	7907260759	50-312 S	MCDONALD, K J	7907190815	PR
MATTIMOE, J J	7907270180	50-312 S	MCDOWELL, M	7907050008	50-482 Q
MATTIA, M J	7907250130*	CONTRACT	MCDOWELL, B H	7907270248	50-329 R
MATTIA, M J	7907050274*	CONTRACT	MCDOWELL-BOYER	7907300282	RES
MATTIA, M J	7907260857*	CONTRACT			
			MCDUFFIE, M A	7907180153	50-400 Q
MATTIA, M J	7907260934*	CONTRACT	MCDUFFIE, M A	7907190190	50-400 Q
MATTIA, M J	7907190862*	CONTRACT	MCDUFFIE, M A	7907190553	50-400 Q
MATTIA, M J	7907100728*	CONTRACT	MCDUFFIE, M A	7907310204	50-400 Q
MATTIA, M J	7907130073*	CONTRACT	MCDUFFIE, M A	7907030497	50-400 A
MATTIA, M J	7907260801*	CONTRACT	MCDUFFIE, M A	7907260460	50-400 A
			MCELROY, W N	7907270357	NUREQ
MATTIA, M J	7907300510*	CONTRACT	MC FARLAND, J C	7907050377	GA999
MATTIA, M J	7907260781*	CONTRACT	MC FARLAND, C R	7907240129*	50-327 Q
MATTIA, M B	7907270081*	CONTRACT	MC GARRY, J H	7907300090	70-2623
MATTIA, M J	7907270034	CONTRACT			
MATTIA, M J	7907250594*	CONTRACT	MC GARRY, J H	7907050111	71-6698
			MC GARRY, J H	7907130217	70-2623
MATTIA, M J	7907270025*	CONTRACT	MC GARRY, J H	7907050098	70-2623
MATTIA, M J	7907260027*	CONTRACT	MC GARRY, J H	7907050063*	70-2623
MATTIA, J	7907110703*	50-471 Q	MC GARRY, J H	7907050065*	70-2623
MATTIA, J	7907230444*	50-352 Q			
MATTIA, J. C.	7907240222*	50-443 Q	MC GARRY, J H	7907130088	70-2623
			MC GARRY, J H	7907130094*	70-2623
MATTSON, R J	7907050063*	FDIA	MC GARRY, J H	7907130098*	70-2623
MATTSON, R J	7907050085*	FDIA	MC GARRY, J H	7907160216	70-2623
MATTSON, R J	7907120742	50-269 P	MC GARRY, J H	7907160220*	70-2623
MATTSON, R J	7907030135	50-320 P			
MATTSON, R J	7907020490	FDIA	MC GARRY, J H	7907160223*	70-2623
			MC GARRY, J H	7907160232	70-2623
MATTSON, R J	7907060025	50-320 P	MC GARRY, J H	7907160235*	70-2623
MATTSON, R J	7907110258	50-320 P	MC GARRY, J H	7907160238*	70-2623
MATTSON, R J	7907190059	50-320 H	MC GARRY, J H	7907130042	70-2623
MATTSON, R J	7907090223	NUREQ			
MATTSON, R J	7907130303	50-320 P	MC GARRY, J H	7907020019	70-2623
			MC GAUGHY, R W	7906200512	50-320 P
MATTSON, R J	7907190260	50-320 P	MC GAUGHY, R W	7907110696*	50-387 Q
MATTSON, R J	7907260700	50-320 P	MC GAUGHY, R W	7907110703*	50-471 Q
			MC GAUGHY, R.	7907230444*	50-352 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MC GAUGHY, R. W.	7907030527*	50-423 Q	MEYER, R. O.	7907160118	50-320 P
MC GAUGHY, R. W.	7907030498*	50-363 Q	MIAD, C. C.	7907230288	NUREQ
MC GAUGHY, R. W.	7907300385*	50-410 Q	MICA, D. A.	7906260590*	50-250 U
MC GAUGHY, R. W.	7907160258*	50-412 Q	MICHEL, C. J.	7907180763	70-143
MC GAUGHY, R. W.	7907200503*	50-387 Q	MICHEL, C. J.	7907060134	70-143
MC GAUGHY, R. W.	7907110015*	50-423 Q	MICHEL, C. J.	7907190384	70-143
MC GAUGHY, R. W.	7907240222*	50-443 Q	MIDURA, H. J.	7907090213	50-272 S
MC GAUGHY, R. W.	7907120254	50-320 H	MIDURA, H. J.	7907160307	50-272 R
MC GINNESS, J. A.	7907120234	50-320 H	MIERNICKI, M. J.	7907200409*	50-318 S
MC GRATH, E. J.	7907060124	PROJ	MIERNICKI, M. J.	7907250298*	50-317 S
MC GRATH, P. E.	7907160266*	50-320 H	MIERNICKI, M. J.	7907260663*	50-318 S
MC GREGG, J. W.	7907180830	71-258	MIKUS, P. J.	7907030294	50-592 Q
MC GREGG, E. W.	7907180852	SECY	MILHOLLIN, G. L.	7907050080	50-272 Q
MC GREGG, E. W.	7907230189	100FR	MILLAR, F.	7907250085	50-338 Q
MC GUIRE, P. J.	7907160315	50-293 S	MILLER, J.	7907230362	50-338 Q
MC GUIRE, P. J.	7907200509	50-293 S	MILLER, J. E.	7907090236	50-59 J
MC GUIRE, P. J.	7907200251	50-293 S	MILLER, J. E.	7907100318	50-128 P
MC GUIRE, P. J.	7907190522	50-293 S	MILLER, J. E.	7907100596	50-128 F
MC GUIRE, P. J.	7907260738	50-293 S	MILLER, J. E.	7907100624	50-128 I
MC GUIRE, P. J.	7907260667	50-293 S	MILLER, J. E.	7907100324*	50-128 P
MC GUIRE, P. J.	7907300310	50-293 S	MILLER, M. I.	7907130047	50-255 Q
MC GURRIN, H. J.	7907050204	50-376 Q	MILLER, R. B.	7907300566	PR
MC GURRIN, H. J.	7907050476	50-382 Q	MILLER, G. P.	7907180046*	50-320 T
MC GURRIN, H. J.	7907180206	50-382 Q	MILLER, G. P.	7907110129*	50-320 Q
MC GURRIN, H. J.	7907180579	50-382 Q	MILLEN, C. K.	7907190699	50-267 Q
MC HENRY, M.	7907100709	50-374 Q	MILLEN, C. K.	7907190707	50-267 Q
MC HENRY, T.	7907020103*	50-302 Q	MILLER, L. K.	7907160311*	50-272 R
MC HENRY, T. G.	7907020145*	50-302 Q	MILLER, M. E.	7907030453	50-344 Q
MC HENRY, T. J.	7907020069*	50-302 Q	MILLER, M. E.	7907020016	50-329 Q
MC HENRY, T. J.	7907270053*	50-261 Q	MILLER, M. E.	7907180772	50-344 Q
MC INDE, D. W.	7907090349	50-170 P	MILLER, M. E.	7907250070	70-2623
MC INNIS, E. L.	7907030810*	71-209	MILLER, M. E.	7907030251	70-2623
MC INNIS, E. L.	7907050504	71-209	MILLER, M. E.	7907030189	70-2623
MC KEEHN, L. M.	7907100234	50-320 H	MILLER, M. E.	7907120121	70-2623
MC KIBBEN, J. C.	7907090322	50-186 S	MILLER, M. E.	7907250105	70-2623
MC KINLEY, J. L.	7907110248	50-320 Q	MILLER, M. E.	7907250146	70-2623
MC KINLEY, J. C.	7907110011	50-320 Q	MILLER, M. E.	7907250081	70-2623
MC KINLEY, J. C.	7907190129	50-409 Q	MILLER, M. E.	7907250092	70-2623
MC MULLEN, P. R.	7907040514	50-522 Q	MILLER, M. E.	7907250135	70-2623
MC MULLEN, R. B.	7907100690	50-410 A	MILLER, M. E.	7907250162	70-2623
MC NEILL, W. M.	7907120213*	QA999	MILLER, M. E.	7907120412	50-329 T
MC NEILL, W. M.	7907130292	71-4498	MILLER, M. E.	7907120364	50-329 T
MC NULTY, A.	7907250121	CONTRACT	MILLER, M. E.	7907160138	50-329 T
MC PHERSON, R. B.	7907110235*	70-364	MILLER, M. E.	7907230540	50-329 T
MC PHERSON, R. B.	7907310620	RES	MILLER, M. E.	7907120380	50-329 T
MC PHERSON, Q. D.	7905240930	REVIEW GRP	MILLER, M. E.	7907160191	50-329 T
MC PHERSON, Q. D.	7907050335	REVIEW GRP	MILLER, M. E.	7907190606	50-329 T
MC WHORTER, R. J.	7907130109	REGQD	MILLER, M. E.	7907190594	50-329 T
MC WHORTER, R. J.	7907130030	REGQD	MILLER, M. E.	7907190853	50-329 T
MEAD, E.	7907260128*	50-596 Q	MILLER, M. E.	7907230592	50-329 T
MEANS, D. B.	7907060818	50-522 Q	MILLER, M. E.	7907230526	50-329 T
MEANS, D. B.	7907190318	50-522 Q	MILLER, M. E.	7907230574	50-329 T
MEANS, D. B.	7907190324*	50-522 Q	MILLER, M. E.	7907270321	50-329 T
MECH, S. J.	7907190341	NUREQ	MILLER, M. E.	7907250174	50-329 T
HECKELBURG, R.	7907240386	PRM	MILLER, M. E.	7907300153	50-329 T
MEDROW, L. K.	7907250127	CONTRACT	MILLER, W. O.	7907050177	70-27
MEDROW, L. A.	7907100723	CONTRACT	MILLER, W. O.	7907100664	70-371
MEDROW, L. A.	7907130061	CONTRACT	MILLER, W. O.	7907060435	50-311 A
MEDROW, L. K.	7907260024	CONTRACT	MILLER, W. O.	7907250605	50-321 F
MEDROW, L. A.	7907270027	CONTRACT	MILLER, W. O.	7907270251	40-8722
MEHNER, A. S.	7907300037	NUREQ	MILLER, W. O.	7907310243	50-324 P
MEIERATTO, L. E.	7907180353	PR	MILLER, W. O.	7907310525	50-346 P
MEIEROTTO, L. E.	7907130404	50-592 D	MILLER, D. E.	7907190073*	50-10 Q
MEISS, R. L.	7907180728	PROJ	MILLER, D. E.	7907100325	50-320 H
MENCZER, W. B.	7907240282	CONTRACT	MILLER, D. E.	7907300430*	50-305 Q
MENCZER, W. B.	7907260653	CONTRACT	MILLER, L.	7907020123*	50-312 Q
MENDOZA, A. A.	7907260243	PR	MILLER, L. F.	7907190484*	50-224 Q
MENNING, J. E.	7907260526*	50-301 Q	MILLER, J. R.	7907120452*	SECY
MENNING, J. E.	7907270133*	50-243 Q	MILLER, F. W.	7907110359	50-320 A
MENNING, J. E.	7907310222*	50-358 Q	MILLS, L. M.	7907110452	50-259 P
MERRIMAN, M. B.	7907130043	PR	MILLS, L. M.	7907100599	50-259 P
MERSON, A.	7907100587	40-8698	MILLS, L. M.	7907100619	50-259 Q
MERSON, B. D.	7907230271	50-317 R	MILLS, L. M.	7907100596	50-390 Q
MERSON, S. D.	7907230274*	50-317 R	MILLS, L. M.	7907170036	50-390 S
MERTZ, J. M.	7907060137	71-310	MILLS, L. M.	7907170190	50-259 P
MERTZ, J. M.	7907300533	71-310	MILLS, L. M.	7907170124	50-327 A
MESLER, R. B.	7907270151	50-148 R	MILLS, L. M.	7907180484	50-390 S
MEYER, R. A.	7907190391	NUREQ	MILLS, L. M.	7907180533	50-390 S
MEYER, O. A.	7907260564	50-320 P	MILLS, L. M.	7907170038	50-259 Q
MEYERS, O. W.	7907120718	50-320 P	MILLS, L. M.	7907180497	50-390 S
MEYER, M.	7907110125	50-471 Q	MILLS, L. M.	7907180366	50-296 Q
MEYER, M. B.	7907090467	50-471 Q	MILLS, L. M.	7907180496	50-390 S
MEYER, M. B.	7907180817	50-471 Q	MILLS, L. M.	7907200376	50-327 Q
MEYER, M. B.	7907180824*	50-471 Q	MILLS, L. M.	7907250324	50-327 A
MEYER, M. B.	7907190643	50-471 Q	MILLS, L. M.	7907250306	50-327 A
MEYER, M. B.	7907190651*	50-471 Q	MILLS, L. M.	7907260779	50-438 S
MEYER, M. B.	7907190188	WASTE MGT	MILLS, L. M.	7907250272	50-259 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HILLS, L. M.	7907260627	50-296 P	MOORE, J. B.	7907190108*	50-361 Q
HILLS, L. M.	7907260764	50-259 P	MOORE, J. B.	7907100603*	50-206 B
HILLS, L. M.	7907260819	50-259 P	MOORE, J. B.	7907100676*	50-361 S
HILLS, L. M.	7907260837	50-259 P	MOORE, J. B.	7907120607	50-361 S
HILLS, L. M.	7907270156	50-259 P	MOORE, R. N.	7907050311	XPORTLIC
HILLSAP, W. J.	7907260938*	50-327 Q	MOORE, R. N.	7907050282	XPORTLIC
HILLSAP, W. J.	7906290401	50-320 P	MOORE, R. N.	7907310353	XPORTLIC
MINNERS, W.	7907090059*	FOIA	MOORE, R. N.	7907310361	XPORTLIC
MINNICK, L. E.	7907310437	50-29 P	MOORE, J. E.	7907060459	50-549 Q
MINOGUE, R. B.	7907100174	REGGD	MOORE, J. E.	7907180601	50-272 Q
MINOGUE, R. B.	7907110117	REGGD	MOORE, D. E.	7907050155*	50-324 Q
MINOGUE, R. B.	7907100250	REGGD	MOORE, D. E.	7907200241*	50-83 Q
MINOGUE, R. B.	7907090138	SECY	MORGAN, K. Z.	7907270056	PRM
MINOGUE, R. B.	7907240421	SECY	MORGENSTERN, L.	7907190444	WASTE MGT
MINOGUE, R. B.	7906130479	ORG	MORIARTY, J. M.	7907240260	FT21
MINOGUE, R. B.	7907110010*	50-320 D	MORRISSEY, J. C.	7907130110	50-275 Q
MINOGUE, R. B.	7907110500	REGGD	MORRILL, P. J.	7907110092*	50-133 Q
MINOGUE, R. B.	7907190818	REGGD	MORTON, K. V.	7907230722*	CONTRACT
MINOGUE, R. B.	7907130295	50-320 H	MORTON, K. V.	7907300569*	CONTRACT
MINOR, J. E.	7907260127*	50-445 U	MORTON, K. V.	7907090443*	FOIA
MIRAGLIA, F. J.	7904270228	50-320 P	MORTON, K. V.	7907260608*	CONTRACT
MIRAGLIA, F. J.	7907110306	50-320 P	MORTON, K. V.	7907300559*	CONTRACT
MIRAGLIA, F. J.	7904270421	50-320 P	MORTON, K. V.	7907100513*	CONTRACT
MIRAGLIA, F. J.	7907100038	50-320 P	MORTON, K. V.	7907110065*	CONTRACT
MIRAGLIA, F. J.	7907100281	50-320 P	MORTON, K. V.	7907230699*	CONTRACT
MIRAGLIA, F. J.	7904270414	50-320 P	MORTON, K. V.	7907180322*	CONTRACT
MIRAGLIA, F. J.	7905020115	50-320 P	MORTON, K. V.	7907270101*	CONTRACT
MIRAGLIA, F. J.	7905030130	50-320 P	MORTON, K. V.	7907100707*	CONTRACT
MIRAGLIA, F. J.	7907130352	50-320 Q	MORTON, K. V.	7907100711	CONTRACT
MIRAGLIA, F. J.	7907130390	50-320 H	MORTON, E. K.	7907100716*	CONTRACT
MIRAGLIA, F. J.	7907120737	50-320 P	MORTON, K. V.	7907270083*	CONTRACT
MISHIMA, J.	7907030243	RES	MORTON, K. V.	7907110532	CONTRACT
MITCHELL, D. G.	7907270194*	50-289 R	MORTON, K. V.	7907100006*	CONTRACT
MITH, B. H.	7907180667	50-272 Q	MORTON, K. V.	7907110439*	CONTRACT
MITKUS, R. J.	7907250449	50-320 P	MORTON, K. V.	7907120152*	CONTRACT
MITTL, R. L.	7907090317	50-311 A	MORTON, K. V.	7907120181*	CONTRACT
MITTL, R. L.	7907130319*	50-272 Q	MORTON, K. V.	7907300534*	CONTRACT
MITTL, R. L.	7907090347	50-311 A	MORTON, K. V.	7907190812*	CONTRACT
MITTL, R. L.	7907170028	50-311 A	MORTON, K. V.	7907090113	CONTRACT
MITTL, R. L.	7907190514	50-311 A	MORTON, K. V.	7907190765*	CONTRACT
MITTL, R. L.	7907190527	50-311 A	MORTON, K. V.	7907190766*	CONTRACT
MITTL, R. L.	7907190598	50-311 F	MORTON, K. V.	7907250233*	CONTRACT
MITTL, R. L.	7907250375	50-311 E	MORTON, K. V.	7907260640*	CONTRACT
MITTL, R. L.	7907250247	50-311 A	MORTON, K. V.	7907260626*	CONTRACT
MITTL, R. L.	7907250330	50-311 A	MORTON, K. V.	7907310057*	CONTRACT
MIYABAYASHI, M.	7907300162	XPORTLIC	MORTON, K. V.	7907180333*	CONTRACT
MODENOS, L.	7907190121*	50-321 Q	MORTON, K. V.	7907180349*	CONTRACT
MODENOS, L.	7907200250*	50-348 Q	MOSEBY, W. R.	7907110113	RES
MOHANI, M. H.	7907270366	NUREQ	MOSEBY, W. R.	7907110149	RES
MONDEN, T.	7907120360	XPORTLIC	MOSELEY, N. C.	7907210141	I&E
MONDEN, T.	7907240213	XPORTLIC	MOSELEY, N. C.	7907020407	FOIA
MONDEN, T.	7907250236	XPORTLIC	MOSELEY, N. C.	7902150354	I&E
MONDON, T.	7907240210*	XPORTLIC	MOSELEY, N. C.	7904270123	50-320 Q
MONROE, A.	7907190082*	50-309 H	MOSELEY, N. C.	7907180613*	COMMISSION
MONTE, G. L.	7907250403	NUREQ	MOSELEY, N. C.	7907020492*	FOIA
MONTGOMERY, D. M.	7907110596*	50-269 Q	MOSELEY, N. C.	7907100312	50-320 Q
MONTGOMERY, D. M.	7906290389	50-320 P	MOSELEY, N. C.	7907300445	50-312 P
MONTI, W. A.	7907190469	50-247 B	MOSELEY, N. C.	7907110665*	50-338 Q
MONTI, W. A.	7907110420	50-247 B	MOWRY, W. R.	7907190363	71-4949
MONTI, W. A.	7907180569	50-3 R	MOWRY, W. R.	7907050308	50-89 F
MOODY, J. L.	7907050128*	50-309 H	MRAZEK	7907200145*	50-516 Q
MOODY, D. E.	7907050258	50-309 Q	MUDREY, M. O.	7907190330	WASTE MGT
MOODY, D. E.	7907050262	50-309 Q	MUELLER, M. A.	7907190147	PRM
MOODY, D. E.	7907020455	50-271 Q	MUIR, H. B.	7907090419	XPORTLIC
MOODY, D. E.	7907050255	50-271 Q	MULKEY, M. E.	7907020004	50-471 Q
MOODY, D. E.	7907170230	50-271 F	MULKEY, M. E.	7907190895	50-596 Q
MOODY, D. E.	7907170149	50-271 F	MULKEY, M. E.	7907240304	50-346 Q
MOODY, D. E.	7907170148	50-271 R	MULKEY, M. E.	7907300420	50-346 H
MOODY, D. E.	7907300305	50-271 P	MULKEY, M. E.	7907300429	50-346 H
MOODY, D. E.	7907310163*	50-29 Q	MULKEY, M. E.	7907300416	50-346 Q
MOODY, D. E.	7907050153	50-29 Q	MULKEY, M. E.	7907300425	50-346 Q
MOODY, D. E.	7907190684	50-29 Q	MULLER, R.	7907090455	50-320 P
MOODY, D. E.	7907180745	50-29 P	MULLER, R.	7907310251	ACRB
MOODY, D. E.	7907300461	50-29 Q	MULLER, R.	7907110047	50-320 Q
MOODY, D. E.	7907020207*	50-29 Q	MULLER, R.	7907110071	50-320 Q
MOODY, D. E.	7907090255	50-29 F	MULLER, R.	7907110160	50-320 Q
MOODY, D. E.	7907170168	50-29 R	MULLER, R.	7907110179	50-320 Q
MOON, B. T.	7907020108*	50-269 Q	MULLIKIN, K. B.	7907020456	71-279
MOON, B. T.	7907240123*	50-338 Q	MULLIKIN, K. B.	7907020457*	71-279
MOORE, M. H.	7907260065*	50-313 U	MULLIKIN, K. B.	7907310613	71-279
MOORE, G. W.	7907100547	50-334 R	MURPHY, J. J.	7907260960	71-9033
MOORE, G. W.	7907190552	50-334 F	MURPHY, S. L.	7907190254	NUREQ
MOORE, G. W.	7907230625	50-334 Q	MURPHY, P. H.	7907090453	50-556 Q
MOORE, G. C.	7907030377	50-302 P	MURPHY, P. H.	7907180628	50-456 Q
MOORE, G. C.	7907030454	50-302 P	MURPHY, P. H.	7907180644	50-454 Q
MOORE, G. C.	7907170119	50-302 P	MURPHY, C. E.	7907090434	50-281 Q

# PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MURPHY, C. E	7907240219*	50-400 Q
MURPHY, C. E	7907090416*	50-424 H
MURPHY, C. E	7907260516	50-395 Q
MURPHY, C. E	7907250434	50-391 Q
MURPHY, C. E	7907190103*	50-321 Q
MURPHY, C. E	7907180614*	50-390 Q
MURPHY, C. E	7907050095	50-327 Q
MURPHY, C. E	7907120523	50-424 Q
MURPHY, C. E	7907190137*	50-413 Q
MURPHY, C. E	7907050134	50-438 Q
MURPHY, C. E	7907180549	50-395 Q
MURPHY, C. E	7907110721	50-339 Q
MURPHY, C. E	7907200244	50-348 Q
MURPHY, C. E	7907200278	50-281 Q
MURPHY, C. E	7907050154*	50-413 Q
MURPHY, C. E	7907130432	50-518 Q
MURPHY, C. E	7907190307*	50-416 Q
MURPHY, C. E	7907230755	50-390 Q
MURPHY, C. E	7907240383	50-390 Q
MURPHY, C. E	7907240420*	50-324 Q
MURPHY, C. E	7907090182*	50-400 Q
MURPHY, C. E	7907110643	50-413 Q
MURPHY, C. E	7907240084	50-518 Q
MURPHY, C. E	7907130210*	50-395 Q
MURPHY, C. E	7907240181	50-438 Q
MURPHY, C. E	7907240272*	50-424 Q
MURPHY, C. E	7907090426*	50-491 Q
MURPHY, C. E	7907240197	50-390 Q
MURPHY, C. E	7907110863*	50-413 Q
MURPHY, C. E	7907240122	50-327 Q
MURPHY, C. E	7907270383*	50-369 Q
MURPHY, C. E	7907240155	50-369 Q
MURPHY, C. E	7907260133	50-553 Q
MURPHY, C. E	7907260145	50-395 Q
MURPHY, C. E	7907250103*	50-348 Q
MURPHY, C. E	7907270380*	50-369 Q
MURPHY, C. E	7907190120	50-413 Q
MURPHY, C. E	7907180592	50-390 Q
MURPHY, C. E	7907190085	50-321 Q
MURPHY, C. E	7907260317*	50-348 Q
MURPHY, C. E	7907190287	50-416 Q
MURPHY, C. E	7907240400	50-324 Q
MURPHY, C. E	7907240259	50-424 Q
MURPHY, C. E	7907260062*	50-287 Q
MURPHY, C. E	7907300580	50-424 Q
MURPHY, C. E	7907240268	50-424 Q
MURPHY, C. E	7907270375	50-369 Q
MURPHY, C. E	7907260495	50-348 Q
MURPHY, C. E	7907300355	50-390 Q
MURPHY, J	7907160092	50-320 P
MURRAY, T. D	7907170203	50-346 P
MURRAY, T. D.	7907060335	50-346 S
MURRAY, T. D	7907170005	50-346 P
MURRAY, T. D	7907100439	50-346 S
MURRAY, T. D	7907100448	50-346 S
MURRAY, T. D	7907100463	50-346 S
MURRAY, T. D	7907110513	50-346 R
MURRAY, T. D	7907170029	50-346 S
MURRAY, T. I	7907230303	50-346 S
MURRAY, T. D	7907310357	50-346 S
MURRAY, T. D	7907310422	50-346 S
MURRAY, B	7907190049*	50-298 Q
MURRAY, B.	7907090446*	50-313 Q
MUSKIE, E. B	7907260090*	50-309 U
MYERS, W. Q	7907240116	PRM
MYNATT, A.	7907100704	CONTRACT
MYNATT, A	7907100698	CONTRACT
MYNATT, A	7907100003	CONTRACT
MYNATT, A	7907120174	CONTRACT
MYNATT, A.	7907260636	CONTRACT
MYRABO, A. L	7907170003*	50-263 R
NAIDU, K. R	7907300046*	50-373 Q
NAPUDA, Q	7907130238*	50-387 Q
NARBUT, P. P	7907260557*	50-397 Q
NARBUT, P. P.	7907300451*	50-361 Q
NARDACCI, O. A	7907090469*	50-320 P
NARDACCI, O. A	7907100228	50-320 R
NAROVANAN, C	7907190781	PR
NARROW, L.	7907050498*	50-363 Q
NARROW, L.	7907300385*	50-410 Q
NARROW, L	7907160258*	50-412 Q
NASBIKAB, T. N	7907110390	50-320 P
NAUGHTON, W. F.	7907100367	50-295 Q
NAUGHTON, W. F.	7907100443	50-599 H
NAUGHTON, W. F	7907110467	50-10 F
NAUGHTON, W. F.	7907160294	50-254 P
NAUGHTON, W. F.	7907170038	50-454 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NEAL, S. L	7907050385*	50-488 U
NEAL, S. L	7907050380	50-488 U
NECHODOM, W. S	7907060467	XPORTLIC
NECHODOM, W. S	7907230504*	71-6581
NEBZI, L. N	7907110003*	50-320 Q
NEESE, A. S	7907230254	PR
NEIGHBORS, D	7907120053	50-280 P
NEIGHBORS, J. D	7907030045	50-280 P
NEIGHBORS, J. D	7907110738	50-280 P
NEIGHBORS, J. D	7907130071	50-280 P
NEIGHBORS, J. D	7907240612	50-280 Q
NEIGHBORS, J. D	7907260533	50-261 P
NEILL, R. H	7907190481	WASTE MGT
NEILSON, R. M	7907310068	NUREG
NEISLER, J. H	7907250301*	50-373 Q
NELP, W. B	7907190896	PRM
NELSON, P. R	7907030213*	FOIA
NELSON, C. C	7907110219	50-309 P
NELSON, C. C	7907250138	50-309 F
NEPOM, D. L	7907030187	50-344 P
NEBBITT, J. C	7907180495	50-29 J
NEWMAN, P	7907130100	PR
NEWMAN, J. R	7907130442	50-498 Q
NEWMAN, J. R	7907130471*	50-498 Q
NEWMAN, J. R	7907130486*	50-498 Q
NEWMAN, J. R	7907130560	50-466 Q
NEWMAN, J. R	7907190823	50-466 Q
NEWMAN, J. R	7907190586	50-466 Q
NEWMAN, J. R	7907190419	50-466 Q
NEWMAN, J. R	7907230088	50-466 Q
NEWMAN, J. R	7907200497	50-466 Q
NEWMAN, R. I	7907190414	40-3392
NICHOLS, T. C	7907090346	PRM
NICHOLAS, H. H	7907110494*	50-311 Q
NICHOLSON, T	7907020198	50-320 P
NIELSEN, L. A	7907180621*	50-285 P
NILSON, R	7907190872	71-3
NILSON, R	7907060499	70-1257
NILSON, R	7907180590	50-564 J
NIMITZ, R. L	7907030068*	50-333 Q
NIMITZ, R. L	7907230097*	50-220 Q
NIX, R. T	7907110517*	50-366 S
NIX, R. T	7907110407*	50-366 S
NIX, R. T	7907020294*	50-366 S
NIX, R. T	7907020308*	50-366 S
NIX, R. T	7907090363*	50-366 S
NIX, R. T	7907090376*	50-321 S
NIX, R. T	7907170060*	50-321 S
NIX, R. T	7907170091*	50-321 S
NIX, R. T	7907230473*	50-366 S
NIX, R. T	7907230486*	50-366 S
NIX, R. T	7907230519*	50-366 S
NIX, R. T	7907260813*	50-366 S
NIX, R. T	7907260833*	50-366 S
NIX, R. T	7907260847*	50-321 S
NOLAN, H. Q	7907110707*	50-320 H
NOLFF, C. E	7907060508	40-8602
NOONAN, V. S.	7907190268	50-289 P
NORDERHAUG, L. R	7907120094	50-224 Q
NORDERHAUG, L. R	7907190145	50-243 Q
NORDERHAUG, L. R	7907190138	50-312 Q
NORDERHAUG, L. R	7907270385	50-267 Q
NORDERHAUG, L. R	7907180273	70-734
NORDERHAUG, L. R	7907180282	70-1257
NORDERHAUG, L. R	7907250220	50-206 Q
NORELIUS, C. E	7907240164*	50-329 Q
NORGAARD, J. A	7907050167	71-128
NORIAN, P	7907090273	REVIEW GRP
NORNGHOLM, L. J	7907230570*	50-272 Q
NORRY, P	7907130424	50-320 H
NORTH, H. S	7907260549*	50-275 Q
NORTON, B	7907130110	50-275 Q
NOSENZO, L. V	7907130441*	SECY
NOSENZO, L. V	7907190012*	SECY
NOSENZO, L. V	7907060485	XPORTLIC
NOSENZO, L. V	7907060497	XPORTLIC
NOSENZO, L. V	7907180869*	SECY
NOSENZO, L. V	7907060491	XPORTLIC
NOSENZO, L. V	7907100047	XPORTLIC
NOSENZO, L. V	7907190163	XPORTLIC
NOSENZO, L. V	7907230149	XPORTLIC
NOSENZO, L. V	7907230168	XPORTLIC
NOSENZO, L. V	7907230179	XPORTLIC
NOSENZO, L. V	7907230193	XPORTLIC
NOSENZO, L. V	7907230443	XPORTLIC
NOSENZO, L. V	7907230445	XPORTLIC

# PERSONAL AUTHOR INDEX

415

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NOSENZO, L V	7907230448	XPORTLIC	D'REILLY, J P	7907100071	70-824
NOSENZO, L V	7907230457	XPORTLIC	D'REILLY, J P	7907100074	PRDJ
NOSENZO, L V	7907230668	XPORTLIC	D'REILLY, J P	7907100078	50-124 Q
NOSENZO, L V	7907230690	XPORTLIC	D'REILLY, J P	7907100081	50-62 Q
NOSENZO, L V	7907260025	XPORTLIC	D'REILLY, J P	7907100085	50-53 Q
NOSENZO, L V	7907310608	XPORTLIC	D'REILLY, J P	7907100089	50-406 Q
NOSENZO, L V	7907240485	XPORTLIC	D'REILLY, J P	7907100096	50-538 Q
NOSENZO, L V	7907250074	XPORTLIC	D'REILLY, J P	7907100097	50-241 Q
NOSENZO, L V	7907260353	XPORTLIC	D'REILLY, J P	7907100102	50-111 Q
NOSENZO, L V	7907260363	XPORTLIC	D'REILLY, J P	7907100110	70-893 Q
NOSENZO, L V	7907230686	XPORTLIC	D'REILLY, J P	7907100114	50-276 Q
NOSENZO, L V	7907240146	XPORTLIC	D'REILLY, J P	7907100143	50-348 Q
NOSENZO, L V	7907240162	XPORTLIC	D'REILLY, J P	7907100150	50-261 Q
NOSENZO, L V	7907240177	XPORTLIC	D'REILLY, J P	7907100167	50-413 Q
NOSENZO, L V	7907260552	XPORTLIC	D'REILLY, J P	7907100177	50-302 Q
NOSENZO, L V	7907260555	XPORTLIC	D'REILLY, J P	7907100184	50-250 Q
NOSENZO, L V	7907260365	XPORTLIC	D'REILLY, J P	7907100193	50-129 Q
NOSENZO, L V	7907260369	XPORTLIC	D'REILLY, J P	7907100196	50-321 Q
NOSENZO, L V	7907260372	XPORTLIC	D'REILLY, J P	7907100202	50-416 Q
NOSENZO, L V	7907260913	XPORTLIC	D'REILLY, J P	7907100204	50-395 Q
NOVAKOVICH, D	7907240115	XPORTLIC	D'REILLY, J P	7907100207	50-259 Q
NOVAH, T M	7907190194*	FOIA	D'REILLY, J P	7907100222	50-280 Q
NOVARRO, J P	7907110395	50-322 Q	D'REILLY, J P	7907100657	50-140 Q
NOVARRO, J P	7907050524	50-322 Q	D'REILLY, J P	7907060350	50-437 Q
NOVARRO, J P	7907110308	50-322 Q	D'REILLY, J P	7907060352	50-364 Q
NOVARRO, J P	7907120623	50-322 S	D'REILLY, J P	7907060353	50-413 Q
NOVARRO, J P	7907180561	50-322 A	D'REILLY, J P	7907060358	50-302 Q
NOWERS, E O	7907190768*	50-309 H	D'REILLY, J P	7907060359	50-321 Q
NOWICKI, S J	7907110728	50-219 P	D'REILLY, J P	7907060361	50-416 Q
NOYER, G E	7907160038*	COMMISSION	D'REILLY, J P	7907060362	50-395 Q
NUENT, E L	7907030109*	40-2259	D'REILLY, J P	7907060363	50-395 Q
NUENT, E L	7907030107	40-2259	D'REILLY, J P	7907060364	50-259 Q
NUENT, E L	7907090243	40-2259	D'REILLY, J P	7907060366	50-280 Q
NUENT, E L	7907300004	40-2259	D'REILLY, J P	7907110080	50-348 Q
NUNN, D E	7907100659*	50-361 S	D'REILLY, J P	7907110084	50-261 Q
NUSSBAUMER, D A	7907300544*	50-201 I	D'REILLY, J P	7907110088	50-400 Q
NUTE, L F	7907110714	10CFR	D'REILLY, J P	7907110091	50-369 Q
NUTE, L F	7907130076	50-329 T	D'REILLY, J P	7907110095	50-269 Q
NUTE, L F	7907130184	50-329 T	D'REILLY, J P	7907110097	50-389 Q
O'BRIEN, H A	7907240551	PRM	D'REILLY, J P	7907110103	50-250 Q
O'BRIEN, B F	7907190473	WASTE MGT	D'REILLY, J P	7907110105	50-424 Q
O'BRIEN, J H	7907120097	RES	D'REILLY, J P	7907110108	50-327 Q
O'BRIEN, J H	7907120146	RES	D'REILLY, J P	7907110127	50-339 Q
O'CONNELL, P	7907240542	PRM	D'REILLY, J P	79070700411	50-424 Q
O'HANLON, J P	7907170032	50-313 S	D'REILLY, J P	7907300008	50-338 Q
O'KELLY, A P	7907060125	50-522 Q	D'REILLY, J P	7907300085	50-437 Q
O'REILLY, J P	7907230001	50-250 Q	D'REILLY, J P	7907300086	50-348 Q
O'REILLY, J P	7907180087	50-321 Q	D'REILLY, J P	7907300090	50-261 Q
O'REILLY, J P	7907020332	50-437 Q	D'REILLY, J P	7907300093	50-269 Q
O'REILLY, J P	7907020333	50-348 Q	D'REILLY, J P	7907300095	50-302 Q
O'REILLY, J P	7907020336	50-280 Q	D'REILLY, J P	7907300096	50-250 Q
O'REILLY, J P	7907020342	50-321 Q	D'REILLY, J P	7907300098	50-321 Q
O'REILLY, J P	7907020343	50-259 Q	D'REILLY, J P	7907300101	50-395 Q
O'REILLY, J P	7907020349	50-269 Q	D'REILLY, J P	7907300102	50-416 Q
O'REILLY, J P	7907020352	50-261 Q	D'REILLY, J P	7907300105	50-259 Q
O'REILLY, J P	7907020354	50-395 Q	D'REILLY, J P	7907300114	50-280 Q
O'REILLY, J P	7907020356	50-395 Q	D'REILLY, J P	7907200162	50-348 Q
O'REILLY, J P	7907020357	50-302 Q	D'REILLY, J P	7907200165	50-261 Q
O'REILLY, J P	7907020366	50-250 Q	D'REILLY, J P	7907200167	50-324 Q
O'REILLY, J P	7907020367	50-413 Q	D'REILLY, J P	7907200170	50-413 Q
O'REILLY, J P	7907020368	50-416 Q	D'REILLY, J P	7907200186	50-269 Q
O'REILLY, J P	7907020417	50-369 Q	D'REILLY, J P	7907200188	50-302 Q
O'REILLY, J P	7907050198	50-302 Q	D'REILLY, J P	7907200192	50-250 Q
O'REILLY, J P	7907110310	50-437 Q	D'REILLY, J P	7907200196	50-321 Q
O'REILLY, J P	7907110312	50-348 Q	D'REILLY, J P	7907200198	50-424 Q
O'REILLY, J P	7907110314	50-261 Q	D'REILLY, J P	7907200200	50-416 Q
O'REILLY, J P	7907110318	50-413 Q	D'REILLY, J P	7907200204	50-395 Q
O'REILLY, J P	7907110319	50-269 Q	D'REILLY, J P	7907200205	50-395 Q
O'REILLY, J P	7907110322	50-302 Q	D'REILLY, J P	7907200206	50-259 Q
O'REILLY, J P	7907110325	50-250 Q	D'REILLY, J P	7907200210	50-327 Q
O'REILLY, J P	7907110329	50-321 Q	D'REILLY, J P	7907200223	50-280 Q
O'REILLY, J P	7907110331	50-416 Q	D'REILLY, J P	7907200257	50-437 Q
O'REILLY, J P	7907110332	50-395 Q	D'REILLY, J P	7907120426	50-321 Q
O'REILLY, J P	7907110333	50-395 Q	D'REILLY, J P	7907190144	50-348 Q
O'REILLY, J P	7907110335	50-259 Q	D'REILLY, J P	7907190148	50-261 Q
O'REILLY, J P	7907110344	50-280 Q	D'REILLY, J P	7907190153	50-269 Q
O'REILLY, J P	7907030140	50-259 Q	D'REILLY, J P	7907190159	50-413 Q
O'REILLY, J P	7907100023	50-437 Q	D'REILLY, J P	7907190168	50-302 Q
O'REILLY, J P	7907100025	50-537 Q	D'REILLY, J P	7907190172	50-250 Q
O'REILLY, J P	7907100030	50-332 Q	D'REILLY, J P	7907190175	50-321 Q
O'REILLY, J P	7907100032	70-1432	D'REILLY, J P	7907190180	50-416 Q
O'REILLY, J P	7907100036	50-437 Q	D'REILLY, J P	7907190184	50-395 Q
O'REILLY, J P	7907100040	70-1151	D'REILLY, J P	7907190187	50-395 Q
O'REILLY, J P	7907100043	70-27	D'REILLY, J P	7907190191	50-259 Q
O'REILLY, J P	7907100063	70-1201	D'REILLY, J P	7907190209	50-280 Q
O'REILLY, J P	7907100068	70-1113	D'REILLY, J P	7907060040	50-348 Q
O'REILLY, J P	7907100070	70-143	D'REILLY, J P	7907060043	50-261 Q
			D'REILLY, J P	7907060048	50-413 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
O'REILLY, J. P.	7907060053	50-302 Q	O'REILLY, J. P.	7907310019	50-250 Q
O'REILLY, J. P.	7907060056	50-250 Q	O'REILLY, J. P.	7907310020	50-321 Q
O'REILLY, J. P.	7907060059	50-321 Q	O'REILLY, J. P.	7907310024	50-416 Q
O'REILLY, J. P.	7907060060	50-416 Q	O'REILLY, J. P.	7907310026	50-395 Q
O'REILLY, J. P.	7907060061	50-395 Q	O'REILLY, J. P.	7907310027	50-299 Q
O'REILLY, J. P.	7907060062	50-395 Q	O'REILLY, J. P.	7907310043	50-280 Q
O'REILLY, J. P.	7907060064	50-259 Q	O'REILLY, J. P.	7907310046	50-404 Q
O'REILLY, J. P.	7907060069	50-280 Q	O'REILLY, J. P.	7907110259	50-348 Q
O'REILLY, J. P.	7907100161	50-269 Q	O'REILLY, J. P.	7907110263	50-269 Q
O'REILLY, J. P.	7907300499	50-302 H	O'REILLY, J. P.	7907110266	50-302 Q
O'REILLY, J. P.	7907020190	50-364 Q	O'REILLY, J. P.	7907110269	50-250 Q
O'REILLY, J. P.	7907020194	50-400 Q	O'REILLY, J. P.	7907110274	50-416 Q
O'REILLY, J. P.	7907020198	50-413 Q	O'REILLY, J. P.	7907110277	50-395 Q
O'REILLY, J. P.	7907020205	50-369 Q	O'REILLY, J. P.	7907180278	50-364 Q
O'REILLY, J. P.	7907020208	50-389 Q	O'REILLY, J. P.	7907180281	50-400 Q
O'REILLY, J. P.	7907020211	50-424 Q	O'REILLY, J. P.	7907180288	50-413 Q
O'REILLY, J. P.	7907020214	50-416 Q	O'REILLY, J. P.	7907180303	50-369 Q
O'REILLY, J. P.	7907020217	50-395 Q	O'REILLY, J. P.	7907180306	50-389 Q
O'REILLY, J. P.	7907020220	50-327 Q	O'REILLY, J. P.	7907180311	50-424 Q
O'REILLY, J. P.	7907020233	50-404 Q	O'REILLY, J. P.	7907180315	50-416 Q
O'REILLY, J. P.	7907250148	50-348 Q	O'REILLY, J. P.	7907180318	50-395 Q
O'REILLY, J. P.	7907250150	50-324 Q	O'REILLY, J. P.	7907180321	50-327 Q
O'REILLY, J. P.	7907250151	50-261 Q	O'REILLY, J. P.	7907180340	50-339 Q
O'REILLY, J. P.	7907250153	50-369 Q	O'REILLY, J. P.	7907180343	50-437 Q
O'REILLY, J. P.	7907250155	50-269 Q	O'REILLY, J. P.	7907180426	50-348 Q
O'REILLY, J. P.	7907250156	50-302 Q	O'REILLY, J. P.	7907180427	50-261 Q
O'REILLY, J. P.	7907250158	50-250 Q	O'REILLY, J. P.	7907180431	50-413 Q
O'REILLY, J. P.	7907250160	50-335 Q	O'REILLY, J. P.	7907180433	50-302 Q
O'REILLY, J. P.	7907250163	50-321 Q	O'REILLY, J. P.	7907180435	50-250 Q
O'REILLY, J. P.	7907250165	50-259 Q	O'REILLY, J. P.	7907180436	50-321 Q
O'REILLY, J. P.	7907250167	50-327 Q	O'REILLY, J. P.	7907180439	50-416 Q
O'REILLY, J. P.	7907250168	50-338 Q	O'REILLY, J. P.	7907180440	50-395 Q
O'REILLY, J. P.	7907250169	50-280 Q	O'REILLY, J. P.	7907180443	50-259 Q
O'REILLY, J. P.	7907190888	70-143 Q	O'REILLY, J. P.	7907180446	50-280 Q
O'REILLY, J. P.	7907310824	50-261 P	O'REILLY, J. P.	7907180447	50-437 Q
O'REILLY, J. P.	7907020371	50-437 Q	O'REILLY, J. P.	7907180597	50-269 Q
O'REILLY, J. P.	7907020374	50-348 Q	O'REILLY, J. P.	7907310223	50-348 Q
O'REILLY, J. P.	7907020375	50-261 Q	O'REILLY, J. P.	7907310227	50-302 Q
O'REILLY, J. P.	7907020379	50-413 Q	O'REILLY, J. P.	7907310229	50-261 Q
O'REILLY, J. P.	7907020382	50-269 Q	O'REILLY, J. P.	7907310234	50-269 Q
O'REILLY, J. P.	7907020384	50-302 Q	O'REILLY, J. P.	7907310240	50-250 Q
O'REILLY, J. P.	7907020386	50-250 Q	O'REILLY, J. P.	7907310245	50-413 Q
O'REILLY, J. P.	7907020389	50-416 Q	O'REILLY, J. P.	7907310254	50-321 Q
O'REILLY, J. P.	7907020391	50-395 Q	O'REILLY, J. P.	7907310258	50-416 Q
O'REILLY, J. P.	7907020393	50-259 Q	O'REILLY, J. P.	7907310263	50-259 Q
O'REILLY, J. P.	7907020401	50-280 Q	O'REILLY, J. P.	7907310282	50-437 Q
O'REILLY, J. P.	7907190518	50-321 Q	O'REILLY, J. P.	7907310303	50-338 Q
O'REILLY, J. P.	7907120033	50-348 Q	O'REILLY, J. P.	7907240464	50-160 Q
O'REILLY, J. P.	7907120036	50-261 Q	O'REILLY, J. P.	7907240466	50-538 Q
O'REILLY, J. P.	7907120051	50-413 Q	O'REILLY, J. P.	7907240468	50-111 Q
O'REILLY, J. P.	7907120061	50-269 Q	O'REILLY, J. P.	7907240470	50-406 Q
O'REILLY, J. P.	7907120071	50-302 Q	O'REILLY, J. P.	7907240474	50-83 Q
O'REILLY, J. P.	7907120075	50-250 Q	O'REILLY, J. P.	7907240476	50-124 Q
O'REILLY, J. P.	7907120079	50-321 Q	O'REILLY, J. P.	7907240478	50-129 Q
O'REILLY, J. P.	7907120084	50-416 Q	O'REILLY, J. P.	7907240481	50-332 Q
O'REILLY, J. P.	7907120096	50-395 Q	O'REILLY, J. P.	7907240484	50-13 Q
O'REILLY, J. P.	7907120098	50-395 Q	O'REILLY, J. P.	7907240486	70-824 Q
O'REILLY, J. P.	7907120104	50-269 Q	O'REILLY, J. P.	7907240487	70-1201 Q
O'REILLY, J. P.	7907120142	50-280 Q	O'REILLY, J. P.	7907240489	70-27 Q
O'REILLY, J. P.	7907120151	50-437 Q	O'REILLY, J. P.	7907240492	70-1113 Q
O'REILLY, J. P.	7907110209	70-143 Q	O'REILLY, J. P.	7907240495	70-143 Q
O'REILLY, J. P.	7907110211	50-348 Q	O'REILLY, J. P.	7907240498	70-1432 Q
O'REILLY, J. P.	7907110213	50-324 Q	O'REILLY, J. P.	7907310137	70-1319 Q
O'REILLY, J. P.	7907110217	50-269 Q	O'REILLY, J. P.	7907310360	50-348 Q
O'REILLY, J. P.	7907110220	50-302 Q	O'REILLY, J. P.	7907310362	50-261 Q
O'REILLY, J. P.	7907110224	50-250 Q	O'REILLY, J. P.	7907310369	50-269 Q
O'REILLY, J. P.	7907110228	50-321 Q	O'REILLY, J. P.	7907310371	50-413 Q
O'REILLY, J. P.	7907110230	50-259 Q	O'REILLY, J. P.	7907310378	50-302 Q
O'REILLY, J. P.	7907110234	50-280 Q	O'REILLY, J. P.	7907310379	50-250 Q
O'REILLY, J. P.	7907180723	70-1113 Q	O'REILLY, J. P.	7907310383	50-321 Q
O'REILLY, J. P.	7907180724	70-27 Q	O'REILLY, J. P.	7907310384	50-416 Q
O'REILLY, J. P.	7907180725	70-1201 Q	O'REILLY, J. P.	7907310385	50-395 Q
O'REILLY, J. P.	7907230405	70-824 Q	O'REILLY, J. P.	7907310386	50-395 Q
O'REILLY, J. P.	7907230408	50-160 Q	O'REILLY, J. P.	7907310387	50-259 Q
O'REILLY, J. P.	7907230409	50-538 Q	O'REILLY, J. P.	7907310389	50-280 Q
O'REILLY, J. P.	7907230410	50-111 Q	O'REILLY, J. P.	7907310391	50-437 Q
O'REILLY, J. P.	7907230412	50-406 Q	O'REILLY, J. P.	7907240281	50-259 Q
O'REILLY, J. P.	7907230413	50-83 Q	O'REILLY, P. D.	7907250604	TOPREF
O'REILLY, J. P.	7907230415	50-62 Q	O'TOOLE, J. D.	7907050280	PR
O'REILLY, J. P.	7907230416	50-124 Q	O'TOOLE, J. D.	7907160342	50-3 Q
O'REILLY, J. P.	7907230418	50-129 Q	OKES, D. L.	7907190663	50-348 P
O'REILLY, J. P.	7907310001	50-348 Q	OBORG, C. R.	7907100341	50-320 H
O'REILLY, J. P.	7907310002	50-364 Q	OBORG, C. R.	7907130139*	50-482 Q
O'REILLY, J. P.	7907310004	50-324 Q	OBORG, C. R.	7907250488*	50-482 Q
O'REILLY, J. P.	7907310009	50-269 Q	OBORG, C. R.	7907310603*	50-482 Q
O'REILLY, J. P.	7907310012	50-413 Q	OBORG, C. R.	7907110628*	50-482 Q
O'REILLY, J. P.	7907310018	50-302 Q	OBORG, C. R.	7907250226*	50-482 Q
			OEHLKERS, W. O.	7907090362*	50-312 Q



# PERSONAL AUTHOR INDEX

417

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DEBTMANN, M J	7907260196*	50-329 Q
DEBTMANN, M J	7907300328*	50-367 Q
DEBTMANN, M J	7907180587*	50-295 Q
OKRENT, D	7907230714	ACRS
OKRENT, D	7907260728	50-320 T
OLDHAM, W A	7907050417	50-201 R
OLDHAM, W A	7907190718	50-201 R
OLIVADOTTI, J R	7907030501	71-192
OLLER, R E	7907090474*	QA999
OLLER, R E	7907260158*	QA999
OLLER, R E	7907090397	QA999
OLMSTEAD, W J	7907180810	50-329 Q
OLMSTEAD, W J	7907190682	50-329 Q
OLMSTEAD, W J	7907260131	50-329 Q
OLSEN, A F	7907060116	71-6058
OLSHAN, L	7907250125	50-305 P
OLSHAN, L	7907180697	50-247 P
OLSHINSKI, J	7907020329	FOIA
OLSHINSKI, J A	7907020216	50-320 P
OLSON, N K	7907190380	WASTE MGT
OLSON, R C	7907090215	50-317 P
OLSON, R C	7907090222*	50-317 P
OLSON, R E	7907250204	50-522 Q
ON, K V	7907100700*	CONTRACT
ONCAVADE, M P	7907250184*	50-250 U
ONCAVADE, M P	7907250175*	50-250 U
ONSDORFF, K A	7907180573	50-272 Q
ONSDORFF, K A	7907180588*	50-272 Q
ONSDORFF, K A	7907240239	50-272 Q
ONSDORFF, K A	7907240243*	50-272 Q
ONSDORFF, K A	7907240342	50-272 Q
ONSDORFF, K A	7907240350*	50-272 Q
ONSDORFF, K A	7907200465	50-363 A
OPEKA, J F	7907130333	50-336 S
OPEKA, J F	7907230474	50-336 S
OPEKA, J F	7907100129	50-336 S
OPEKA, J F	7907090304	50-245 S
OPEKA, J F	7907090300	50-245 S
OPEKA, J F	7907100388	50-336 S
OPEKA, J F	7907170088	50-336 S
OPEKA, J F	7907170112	50-336 S
OPEKA, J F	7907170224	50-336 S
OPEKA, J F	7907180466	50-336 R
OPEKA, J F	7907200256	50-245 R
OPEKA, J F	7907260725	50-245 S
OPEKA, J F	7907260589	50-336 S
OPLINGER, Q Q	7907030324	XPORTLIC
OPLINGER, Q Q	7907060049	XPORTLIC
OPLINGER, Q Q	7907060051	XPORTLIC
OPLINGER, Q Q	7907060080	XPORTLIC
OPLINGER, Q Q	7907060262	XPORTLIC
OPLINGER, Q Q	7907050245	XPORTLIC
OPLINGER, Q Q	7907050248	XPORTLIC
OPLINGER, Q Q	7907050252	XPORTLIC
OPLINGER, Q Q	7907050314	XPORTLIC
OPLINGER, Q Q	7907060093	XPORTLIC
OPLINGER, Q Q	7907060086	XPORTLIC
OPLINGER, Q Q	7907060253	XPORTLIC
OPLINGER, Q Q	7907060285	XPORTLIC
OPLINGER, Q Q	7907060289	XPORTLIC
OPLINGER, Q Q	7907060091	XPORTLIC
OPLINGER, Q Q	7907030190	XPORTLIC
OPLINGER, Q Q	7907030320	XPORTLIC
OPLINGER, Q Q	7907050482	XPORTLIC
OPLINGER, Q Q	7907060045	XPORTLIC
OPLINGER, Q Q	7907030318	XPORTLIC
OPLINGER, Q Q	7907110053	XPORTLIC
OPLINGER, Q Q	7907060440	XPORTLIC
OPLINGER, Q Q	7907130053	XPORTLIC
OPLINGER, Q Q	7907130058	XPORTLIC
OPLINGER, Q Q	7907130068	XPORTLIC
OPLINGER, Q Q	7907130074	XPORTLIC
OPLINGER, Q Q	7907130087	XPORTLIC
OPLINGER, Q Q	7907180546	XPORTLIC
OPLINGER, Q Q	7907180550	XPORTLIC
OPLINGER, Q Q	7907180675	XPORTLIC
OPLINGER, Q Q	7907180678	XPORTLIC
OPLINGER, Q Q	7907180909	XPORTLIC
OPLINGER, Q Q	7907260191	XPORTLIC
OPLINGER, Q Q	7907260203	XPORTLIC
OPLINGER, Q Q	7907310154	XPORTLIC
OPLINGER, Q Q	7907050108	XPORTLIC
OPLINGER, Q Q	7907180660	XPORTLIC
OPLINGER, Q Q	7907180665	XPORTLIC
OPLINGER, Q Q	7907180668	XPORTLIC
OPLINGER, Q Q	7907190791	XPORTLIC
OPLINGER, Q Q	7907190797	XPORTLIC

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
OPLINGER, Q Q	7907190830	XPORTLIC
OPLINGER, Q Q	7907190837	XPORTLIC
OPLINGER, Q Q	7907190810	XPORTLIC
OPLINGER, Q Q	7907100343	XPORTLIC
OPLINGER, Q Q	7907190749	XPORTLIC
OPLINGER, Q Q	7907190758	XPORTLIC
OPLINGER, Q Q	7907300605	XPORTLIC
OPLINGER, Q Q	7907300606	XPORTLIC
OPLINGER, Q Q	7907180873	XPORTLIC
OPLINGER, Q Q	7907130085	50-329 T
OREFFICE, P	7907200400*	50-57 Q
ORLOSKY, P H	7907130405*	50-320 P
ORNSTEIN, H	7907180749	40-8064
ORTLOFF, Q D		
OST, F.	7907110436*	50-295 S
OSTI, A P.	7907190146	50-320 P
OSTRANDER, F W	7907240310	50-344 Q
OUZTB, J E	7907160195*	50-369 Q
OUZTB, J E	7907100419	50-320 H
OWSLEY, Q F	7907110451	TOPREP
OWZARSKI, P C	7907170197	NUREQ
PACHT, C	7907090415	XPORTLIC
PACK, L S	7907250204	50-522 Q
PACK, D R	7907240126	NUREQ
PAGLIARO, J A	7907100536	50-320 H
PANCIERA, N	7907240262*	QA999
PANETTA, L E	7907180673*	50-320 U
PAOLINO, R J	7907180399*	50-247 Q
PAPPAS, H	7907110068	50-10 Q
PAPPAS, H	7907060007	50-10 Q
PAPPAS, H	7907110198	DRQ
PAPPAS, H	7907120293	DRQ
PAPPAS, H	7907230421	DRQ
PAPPAS, H	7907060001	DRQ
PAPPAS, H	7907100487	DRQ
PAPPAS, H	7907130230	50-10 Q
PAPPAS, H	7907250343	DRQ
PAPPAS, H	7907270293	DRQ
PAPWORTH, L Q	7907060330*	50-409 S
PARELLI, M	7907110443*	50-237 B
PARIS, D	7907120083	50-596 T
PARKER, W Q	7907110560*	50-269 S
PARKER, W Q	7907110576	50-269 S
PARKER, W Q	7907110552	50-269 S
PARKER, W Q	7907110446	50-270 S
PARKER, W Q	7907110546	50-269 S
PARKER, W Q	7907110376	50-269 S
PARKER, W Q	7907110576	50-269 S
PARKER, W Q	7907110158	50-269 P
PARKER, W Q	7905240452	50-287 Q
PARKER, W Q	7907190533*	70-2623
PARKER, W Q	7906200115	50-269 Q
PARKER, W Q	7905230543	50-287 P
PARKER, W Q	7907050277	50-269 Q
PARKER, W Q	7907110627	50-269 Q
PARKER, W Q	7907110575*	50-269 Q
PARKER, W Q	7907100106	50-269 Q
PARKER, W Q	7907090382	50-369 Q
PARKER, W Q	7907190565	50-369 Q
PARKER, W Q	7907190750	50-369 Q
PARKER, W Q	7907180883	50-269 Q
PARKER, W Q	7907160185	50-369 Q
PARKER, W Q	7907190409	50-269 Q
PARKER, W Q	7907270378*	50-369 Q
PARKER, W Q	7907260550	50-269 Q
PARKER, W Q	7907090342	50-369 S
PARKER, W Q	7907260055	50-287 Q
PARKER, W Q	7907050312	50-269 F
PARKER, W Q	7907090262	50-269 S
PARKER, W Q	7907120559	50-369 K
PARKER, W Q	7907170159	50-269 S
PARKER, W Q	7907180476	50-269 R
PARKER, W Q	7907180485	50-269 S
PARKER, W Q	7907180502	50-270 S
PARKER, W Q	7907190228	50-269 F
PARKER, W Q	7907190533	50-269 P
PARKER, W Q	7907200245	50-269 Q
PARKER, W Q	7907230359	50-269 S
PARKER, W Q	7907260734	50-269 P
PARKER, W Q	7907240290	50-269 S
PARKER, W Q	7907240332	50-269 S
PARKER, W Q	7907250377	50-369 A
PARKER, W Q	7907300311	50-269 P
PARKER, R L	7907110437*	50-358 Q
PARKYN, J	7907180520*	50-409 R
PARLER, W	7907130376	50-320 Q
PARR, D. D.	7907050183	50-338 F
PARR, D. D.	7907110625	50-482 A

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARR, D D	7907110261	50-311 A	PETERSON, M R	7907230646	XPORTLIC
PARR, D D	7907110657	50-339 A	PETERSON, M R	7907230664	XPORTLIC
PARR, D D	7907110679	50-338 P	PETERSON, M R	7907230671	XPORTLIC
PARR, D D	7907190799	50-387 A	PETERSON, M R	7907230641	XPORTLIC
PARR, D D	7907110704	50-387 A	PETERSON, M R	7907230661	XPORTLIC
PARR, D D	7907250564	50-338 P			
PARR, D D	7907250571*	50-338 P	PETERSON, M R	7907230702	XPORTLIC
PARR, D D	7907250581*	50-338 A	PETERSON, M R	7907230235	XPORTLIC
PARR, D D	7907310463	50-387 A	PETERSON, M R	7907230600	XPORTLIC
PARR, D D	79072200248	50-338 P	PETERSON, M R	7907230636	XPORTLIC
PARSONS, T W	7907240039	50-264 H	PETERSON, M R	7907230678	XPORTLIC
PARTLOW, J G	7907090093	70-734	PETERSON, M R	7907230632	XPORTLIC
PARTLOW, J G	7907060199	70-1151	PETERSON, M R	7907230699	XPORTLIC
PARTLOW, J G	7907060206	70-371	PETERSON, M R	7907240015	XPORTLIC
PARTLOW, J G	7907060209	70-143	PETERSON, M R	7907240019	XPORTLIC
PARTLOW, J G	7907180228	70-371	PETERSON, M R	7907240024	XPORTLIC
			PETERSON, M R	7907240054	XPORTLIC
PARTLOW, J G	7907110431	70-27	PETERSON, M R	7907240056	XPORTLIC
PARTLOW, J G	7907100696	70-1113	PETERSON, M R	7907240059	XPORTLIC
PARTLOW, J G	7907090231	70-1151	PETERSON, M R	7907230629	XPORTLIC
PARTLOW, J G	7907190156	70-371	PETERSON, M R	7907230651	XPORTLIC
PARTLOW, J G	7907230597	70-734			
PASSIAVOS, M	7907300099	NUREQ	PETERSON, M R	7907240007	XPORTLIC
PATE, R J	7907110725*	50-361 Q	PETERSON, M R	7907240010	XPORTLIC
PATE, R J	7907260978*	50-361 Q	PETERSON, M R	7907250242	XPORTLIC
PATON, W D	7907190398	50-389 Q	PETERSON, M R	7907180277	XPORTLIC
PATTERSON, G K	7907170204	NUREQ	PETERSON, M R	7907180284	XPORTLIC
PATTI, F J	7906210238*	50-397 A	PETERSON, M R	7907310047	XPORTLIC
PAUL, J	7907190849	PR	PETERSON, M R	7907310052	XPORTLIC
PAUL, L W	7907250562*	FOIA	PETERSON, M R	7907310058	XPORTLIC
PAUL, R	7907230619*	COMMISSION	PETERSON, M R	7907190772	XPORTLIC
PAUL, R A	7907100335	50-320 H	PETRICK, N A	7907110511	50-482 Q
PAULUS, T J	7907120070	RES	PETRUSKA, M	7907030149	FOIA
PAULUS, R C	7907030118	50-320 S	PHILLIPS, J H	7907110570	71-235
PAULUS, R C	7907120162	50-320 S	PHILLIPS, L R	7907300469	50-320 P
PAULUS, R	7907170153	50-320 S	PIGOTT, D R	7907130392	50-361 Q
PAULUS, R C	7907240340	50-320 S	PIKE, W J	7907110687*	50-338 Q
PAVINCICH, W M	7907250382*	50-311 E	PILANT, J M	7907260162	50-298 Q
PAVLIC, J M	7907500017	FOIA	PILANT, J M	7907090392*	50-298 Q
PAYNE, H R	7907300306	RES	PILANT, J M	7907060402	50-298 Q
PECK, S O	7907270388	NUREQ	PILANT, J M	7907030423	50-298 Q
PEEPLES, M	7907030356	50-592 Q	PILANT, J M	7907110424	50-298 F
PEEPLES, W P	7907310257	PRM	PILANT, J M	7907170194	50-298 P
PEERY, M W	7907200234*	70-27	PILANT, J M	7907200260	50-298 P
PEERY, M W	7906290386	50-320 P	PILANT, J M	7907200353	50-298 F
PENDLETON, R C	7907230190	PR	PILANT, J M	7907240325	50-298 F
PENNER, P	7907030116	50-461 A	PILANT, J M	7907260752	50-298 F
PENNER, P	7907190166	50-461 A	PITTMAN, J D	7907060473	50-466 H
PEOPLES, D L	7907060371*	50-295 Q	PLASKON, R E	7907300512	50-516 Q
PERKINS, J	7907260859*	50-387 Q	PLATE, C	7907020324	71-130
PERKINS, T N	7907130448*	50-220 R	PLESSET, M B	7907190562	ACRB
PERLMAN, J	7907250230	CONTRACT	PLESSET, M B	7907030295	ACRB
PERROTTI, D J	7907100594	50-320 H	PLESSET, M B	7907030284	ACRB
PERRY, J C	7907110425*	50-344	PLIML, G J	7907060347*	50-295 Q
PETERSON, B	7907130488	50-295 Q	PLUMLEE, K E	7907030068*	50-333 Q
PETERSON, M R	7907250108	XPORTLIC	PLUMLEE, K E	7907310178*	50-29 Q
PETERSON, M R	7907250113	XPORTLIC	PLUMSTEAD, R F.	7907060009	71-66
PETERSON, M R	7907190034	XPORTLIC	POCHAL, W E.	7907240190	XPORTLIC
PETERSON, M R	7907190705	XPORTLIC	POCHAL, W F.	7907190001	XPORTLIC
PETERSON, M R	7907190709	XPORTLIC	POCHAL, W F.	7907240111	XPORTLIC
PETERSON, M R	7907190720	XPORTLIC	POIRIER, M R	7907170154*	50-445 M
PETERSON, M R	7907190764	XPORTLIC	POIRIER, M R	7907190213	50-445 M
PETERSON, M R	7907190778	XPORTLIC	POIRIER, M R	7907170117	50-445 M
PETERSON, M R	7907190783	XPORTLIC	POLAK, R J	7907170117	50-445 M
PETERSON, M R	7907230135	XPORTLIC	POLK, P J	7907230399	40-8729
PETERSON, M R	7907240017	XPORTLIC	POLK, P J.	7907060481	50-333 P
PETERSON, M R	7907310114	XPORTLIC	POLK, P J.	7907060047	50-333 P
PETERSON, M R	7907240488	XPORTLIC	POLK, P J	7907190877	50-333 P
PETERSON, M R	7907190633	XPORTLIC	POLZER, W L	7907240041	50-333 P
PETERSON, M R	7907190636	XPORTLIC	PORTER, W L.	7907190192	NUREQ
PETERSON, M R	7907190683	XPORTLIC	PORTER, W L.	7907300109*	70-2623
PETERSON, M R	7907190643	XPORTLIC		7907190526	70-2623
PETERSON, M R	7907230177	XPORTLIC	PORTER, W L	7907190622	70-2623
PETERSON, M R	7907190676	XPORTLIC	POSTA, A K	7907030145	NUREQ
PETERSON, M R	7907190618	XPORTLIC	POTAPOVS, U	7907110069*	GA999
PETERSON, M R	7907190624	XPORTLIC	POTAPOVS, U	7907110060	GA999
PETERSON, M R	7907190630	XPORTLIC	POTAPOVS, U	7907240263*	GA999
PETERSON, M R	7907190640	XPORTLIC	POTAPOVS, U	7907250190	GA999
PETERSON, M R	7907190644	XPORTLIC	POTAPOVS, U.	7907130199*	GA999
PETERSON, M R	7907190648	XPORTLIC	POTAPOVS, U.	7907130369*	GA999
PETERSON, M R	7907190653	XPORTLIC	POTAPOVS, U	7907050104*	GA999
PETERSON, M R	7907190657	XPORTLIC	POTAPOVS, U	7907050101*	GA999
PETERSON, M R	7907190663	XPORTLIC	POTAPOVS, U.	7907090470	GA999
PETERSON, M R	7907190668	XPORTLIC	POTAPOVS, U	7907100730*	GA999
PETERSON, M R	7907230171	XPORTLIC	POTAPOVS, U	7907250193*	GA999
PETERSON, M R	7907250431	XPORTLIC	POTAPOVS, U	7907030032*	GA999
PETERSON, M R	7907250546	XPORTLIC	POTAPOVS, U	7907030019	GA999
			POTAPOVS, U.	7907030029	GA999
			POTAPOVS, U	7907030036	GA999

# PERSONAL AUTHOR INDEX

419

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
POTAPOVS, U	7907060041	QA999
POTAPOVS, U	7907090476	QA999
POTAPOVS, U	7907260144*	QA999
POTAPOVS, U	7907080530	QA999
POTAPOVS, U	7907090462	QA999
POTAPOVS, U	7907130335	QA999
POTAPOVS, U	7907250098	QA999
POTAPOVS, U	7907230061*	QA999
POTAPOVS, U	7907190732	QA999
POTAPOVS, U	7907230297*	QA999
POTAPOVS, U	7907130186	QA999
POTAPOVS, U	7907250149	QA999
POTAPOVS, U	7907050084	QA999
POTAPOVS, U	7907090381	QA999
POTAPOVS, U	7907100721	QA999
POTAPOVS, U	7907130221	QA999
POTAPOVS, U	7907230730	QA999
POTAPOVS, U	7907260045*	QA999
POTAPOVS, U	7907260130*	QA999
POTAPOVS, U	7907250348	QA999
POTAPOVS, U	7907250558	QA999
POTAPOVS, U	7907230055	QA999
POTAPOVS, U	7907230286	QA999
POTAPOVS, U	7907260100	QA999
POTAPOVS, U	7907240261	QA999
POTAPOVS, U	7907250563	QA999
POTAPOVS, U	7907260010	QA999
POTCHEN, E J	7907200499	PRM
POTTER, J P	7907230652*	70-143
POWELL, W L	7907180845	71-239
POWERS, K H	7907190729	REGOD
PRADDS, R	7907260011	30-382
PREGIBON, M M	7907190762	PR
PREISTER, D J	7907180777	50-445
PRICE, D S	7907310169*	50-259
PROFFITT, W L	7907190432	50-339
PROFFITT, W L	7907170129	50-280
PRYOR, R J	7907030434	NUREG
PRYOR, R J	7907310038	NUREG
PRZYBYLA, L J	7907110437*	50-358
PURCELL, J F	7907130039	50-367
PUSCHEL, M A	7907030428	50-155
QUIRO, C	7907030142	50-295
QUIGLEY, W B	7907190118	PR
QUILTY, J	7907160298	50-10
QUINN, C R	7907190539	50-237
QUINTENZ, T E	7907270202*	50-219
QUIRK, J	7907200194	TOPREP
QUIRK, J	7907200209	TOPREP
QUITTSCHREIBER	7907100226	50-336
RADER, R M	7907020012	27-39
RADER, R M	7907110432	50-358
RADER, R M	7907310077	50-358
RADLEY, H H	7907300500*	50-201
RAOAN, K M	7907030317	FOIA
RAOONE, S	7907130407	50-280
RAINEY, J L	7907090094	40-2061
RANDALL, J D	7907310392	50-128
RANDALL, R O	7907020207*	50-29
RANDOLPH, J.	7907310621*	COMMISSION
RANDOLPH, M L	7907300421	RES
RATTE, C A	7907190819	WASTE MGT
RAY, J J	7907120338	ACRB
RAYMOND, W J	7907200420*	50-57
RE, J R	7907060472	50-514
READ, J B	7907120203	50-320
REAVIS, L A	7907180481*	50-269
REBBAPIAGODA, R	7907100107	50-320
REBELOWSKI, J	7907180483*	50-247
REBELOWSKI, T	7907180437*	50-286
REDDEN, J. A	7907240310	50-344
REED, C	7907060341	PR
REED, C.	7906290493	50-320
REED, C	7907120782*	FOIA
REED, C.	7907260057	PRM
REED, C	7907050004	50-295
REED, C	7907060251	50-10
REED, C	7907160273*	50-454
REED, C.	7907270115*	50-304
REED, C.	7907180101	50-10
REED, C.	7907160195	50-454
REED, C	7907240274*	50-10
REED, C	7907310475	50-10
REED, C.	7907240078*	50-373
REED, C	7907300338*	50-295
REED, C.	7907250583*	50-295
REED, C.	7907190010	50-373

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REED, C	7907300089*	50-373
REED, C	7907300401	50-295
REED, C	7907050330	50-599
REED, C	7907050374	50-454
REED, C	7907090305	50-10
REED, C	7907130322	50-10
REED, C	7907170053	50-295
REED, C	7907190475	50-275
REED, C	7907200381	50-10
REED, C	7907200426	50-295
REED, C	7907230158	50-454
REED, C	7907300330	50-10
REED, P R	7907160204	50-320
REED, P R	7907160214	50-320
REED, P R	7907160219	50-320
REES, K Y	7907261014	PR
REEVES, E A	7907300562	50-348
REGAN, D M	7907030546	40-8698
REGAN, W H	7907120253*	50-322
REGAN, W H	7907050055	50-387
REGAN, W H	7907050200	50-461
REGAN, W H	7907060424	50-219
REGAN, W H	7907060430*	50-219
REHM, T A	7907060050	COMMISSION
REHM, T A	7907110138	COMMISSION
REHM, T A.	7907240516	COMMISSION
REHM, T A	7907190253	COMMISSION
REHM, T A	7907250249	COMMISSION
REICHEL, L	7907250173*	COMMISSION
REID, R W	7907180889*	50-346
REID, R W	7907060240	50-336
REID, R W	7907060241*	50-336
REID, R W	7907110675	50-285
REID, R W	7907030172	50-225
REID, R W	7907030263	50-54
REID, R W	7907030269*	50-54
REID, R W	7907020319*	50-269
REID, R W	7907030144	50-317
REID, R W	7907110648	50-346
REID, R W	7907180692	50-317
REID, R W	7907020263	50-346
REID, R W	7907050467	50-59
REID, R W	7907060155	50-309
REID, R W	7907060141	50-336
REID, R W	7907090177	50-335
REID, R W	7907090184*	50-335
REID, R W	7907090200*	50-335
REID, R W	7907100020	50-223
REID, R W	7907100024*	50-223
REID, R W	7907300001	50-302
REID, R W	7907060093	50-160
REID, R W	7907060098*	50-160
REID, R W	7907060104*	50-160
REID, R W	7907100304*	50-320
REID, R W	7907190840	50-386
REID, R W	7907110597	50-313
REID, R W	7907300163	50-124
REID, R W	7907180884*	50-346
REID, R W	7907110736	50-317
REID, R W	7907180876	50-346
REID, R W.	7907180873*	50-346
REID, R W	7907260379	50-20
REID, R W	7907260581*	50-20
REID, R W.	7907180897	50-57
REID, R W.	7907180863*	50-57
REID, R W	7907190789	50-336
REID, R W	7907310614	50-131
REID, R W	7907310617*	50-131
REID, R W	7907310611	50-309
REID, R W	7907240549*	50-129
REID, R W.	7907240573	50-129
REID, R W.	7907310144	50-313
REID, R W.	7907260084	50-317
REID, R W.	7907260092*	50-317
REID, R W.	7907260105*	50-317
REID, R W	7907300142	50-346
REID, R W.	7907300147*	50-346
REID, R W.	7907300137*	50-346
REID, R W.	7907250589	50-269
REID, R W.	7907250606*	50-269
REID, R W.	7907200224*	50-269
REID, R W.	7907230495	50-269
REID, R W	7907230502*	50-269
REID, R W	7907230532*	50-269
REID, R W.	7907240093	50-336
REID, R W	7907240105*	50-336

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REID, R W	7907170130*	50-27 P	RINACA, J M	7907180591	50-338 Q
REID, R W	7907300560	50-313 F	RING, D C	7907250404	50-293 P
REID, R W	7907300446*	50-312 P	RING, D E	7907240381*	REG00
REID, R W	7907300438*	FOIA	RING, L E	7907240377*	REG00
REID, R W	7907300476*	50-302 P	RING, L E	7907240368*	REG00
REINHUTH, O W	7907030137*	50-320 P	RING, L E	7907240311	REG00
REINSM, R M	7907190237	50-320 Q	RINGLE, J C	7907180559	50-243 P
REIS, H F	7907130442	50-498 Q	RISCHLING, J L	7907250268*	50-314 S
REIS, H F	7907130471*	50-498 Q	RISCHLING, J L	7907300337*	50-316 S
REIS, H F	7907130486*	50-498 Q	RITSHER, J A	7907180264	FR
REIS, H F	7907190472	50-250 Q	RITSHER, J A	7907180378	50-443 Q
REIS, E J	7907130408	27-39	RITSHER, J A	7907180895*	50-443 Q
REIS, E J	7907050320	50-400 Q	RITSHER, J A	7907180726	50-443 Q
REIS, E J	7907130507	50-400 Q	RITSHER, J A	7907030355	50-443 I
REIS, E J	7907190617	50-400 Q	RITSHER, J A	7907180112	50-443 I
REIS, E J	7907220247	50-488 Q	RITSHER, J A	7907250042	50-568 Q
REIS, E J	7907200253*	50-488 Q	RITZMAN, R L	7907190483	NUREQ
REKEMEYER, P C	7907190081	40-299	RIVARD, W C	7907170167	NUREQ
REMICK, F J	7907120249	50-295 T	RIVERA, J V	7907190839	PR
REMICK, F J	7907120201	50-295 T	ROBERTSON, J S	7907230523*	70-27
REMICK, F J	7907300184	50-295 T	ROBERDS, H W	7907090474*	QA999
REMLEY, M E	7907240048	71-6038	ROBERDS, H W	7907090478*	QA999
REMLEY, M E	7907110616	70-25	ROBINSON, N	7907020098	FOIA
REMBERGER, D L	7907190801	PRM	ROBINSON, E L	7907110617	71-214
REMBERGER, D L	7907120456*	50-460 Q	ROBINSON, H B	7907090323	50-261 P
REMBERGER, D L	7907030088*	50-397 Q	ROCKELLE, J K	7907170140*	50-327 A
REMBERGER, D L	7907090237	50-397 Q	RODDI, J P	7907180901	50-274 A
REMBERGER, D L	7907180069	50-397 Q	RODRIGUEZ, J P	7907100598*	50-206 R
REMBERGER, D L	7907180076	50-508 Q	RODRIGUEZ, R J	7907180506	50-312 R
REMBERGER, D L	7907090275	50-460 Q	ROE, D B	7907180297	50-392 Q
REMBERGER, D L	7907240320*	50-397 S	ROE, D B	7907030240	50-392 A
REMBERGER, D L	7907310289	50-397 K	ROE, L E	7907240176	50-346 P
REMBERGER, D L	7907200331	50-513 A	ROE, L E	7907170201	50-346 P
REMBERGER, D L	7907250310	50-397 S	ROE, L E	7907110417	50-346 S
REMBERGER, D L	7907260511	50-397 A	ROE, L E	7907090258	50-346 S
RENDER, V T	7907110036	PR	ROE, L E	7907300417*	50-346 S
RENFROW, R R	7907110652	50-329 T	ROE, L E	7907130380	50-346 P
RENFROW, R R	7907110950	50-329 T	ROE, L E	7907100584	50-346 P
RENZETTI, J L	7907260668	PRM	ROE, L E	7907170075	50-346 F
RESNIKOFF, M	7907230246*	50-201 P	ROE, L E	7907240351	50-346 F
RESNIKOFF, M	7907180778	50-201 S	ROGER, J H	7907230829	50-338 Q
RESNIKOFF, M	7907130039	50-295 Q	ROGER, W H	7907120119	50-316 Q
REVELEY, W T	7907180603	50-322 Q	ROGER, W F	7907020800	XPORTLIC
REVELEY, W T	7907180755*	50-322 Q	ROGER, W F	7907020801*	XPORTLIC
REVELEY, W T	7907180718	50-322 Q	ROGER, C L	7907250281*	50-295 S
REYES, L	7907020149*	50-346 Q	ROGER, W H	7907060348*	50-321 S
REYES, L	7907020076*	50-346 Q	ROGER, M	7907030054*	70-2662
REYES, L A	7907240191*	50-409 Q	ROGOW, B S	7907090061	50-250 Q
REYES, L A	7907240152*	50-266 G	ROGOW, B S	7907090066*	50-250 Q
REYNOLDS, Q L	7907190158*	50-358 Q	ROHMER, P S	7907060455	RES
REYNOLDS, N S	7907060447	50-445 Q	ROISHMAN, A Z	7907030314*	FOIA
REYNOLDS, N S	7907060483	50-445 Q	ROISHMAN, A Z	7907060222	70-2623
REYNOLDS, W B	7907190304	50-329 Q	ROISHMAN, A Z	7907060228*	70-2623
REYNOLDS, L E	7907060168	27-47	ROISHMAN, A Z	7907110486	50-237 Q
REYNOLDS, L E	7907180812	71-5805	ROISHMAN, A Z	7907060019	70-2623
REYNOLDS, L E	7907300187	71-6244	ROISHMAN, A Z	7907060024*	70-2623
RHODE, Q K	7907300372*	50-410 Q	ROISHMAN, A Z	7907060028*	70-2623
RHODE, Q K	7907050373	50-410 Q	ROISHMAN, A Z	7907060033*	70-2623
RHODE, Q K	7907060339	50-410 A	ROISHMAN, A Z	7907200185	50-237 Q
RHODE, Q K	7907250351	50-410 A	ROISHMAN, A Z	7907110109	70-2623
RHYNE, W R	7907190483	NUREQ	ROISHMAN, A Z	7907110119*	70-2623
RIB, L N	7907190225*	50-16 P	ROISHMAN, A Z	7907110134*	70-2623
RIBICOFF, A	7907180162*	COMMISSION	ROISHMAN, A Z	7907110243	70-2623
RICE, E R	7907190413	WASTE MGT	ROISHMAN, A Z	7907110265*	70-2623
RICE, D W	7907190218	NUREQ	ROISHMAN, A Z	7907110297*	70-2623
RICHARDSON, K W	7907180458	50-510 H	ROISHMAN, A Z	7907160287*	70-2623
RICHARDS, H	7905230296	50-320 P	ROISHMAN, A Z	7907250519*	70-2623
RICHTER, H J	7907170136	NUREQ	ROISHMAN, A Z	7907160280	70-2623
RICHTER, H J	7907190254	NUREQ	ROISHMAN, A Z	7907190625	70-2623
RICHTER, H J	7907170217	NUREQ	ROISHMAN, A Z	7907190638	70-2623
RICKARD, C L	7907250369*	QA999	ROISHMAN, A Z	7907190677	FOIA
RIDGWAY, K R	7907260264*	50-409 Q	ROLLINS, J D	7907130233*	70-2623
RIDGWAY, K R	7907300479	50-155 Q	ROLLINS, J D	7907300200	71-6698
RIDOUT, E F	7907060445	FOIA	ROMANO, F	7907130007*	50-352 Q
RIDOUT, E F	7907060456	FOIA	ROMNEY, K M	7907030393*	50-317 S
RIEGLE, D	7907260368*	50-255 U	ROOD, H	7907050131	50-361 A
RIEHL, W A	7907110358*	50-320 P	ROOD, H	7907030246	50-566 A
RIEHL, W A	7907110382*	50-320 P	ROOD, H	7907120475	50-361 F
RIEHL, W A	7907110411*	50-320 P	ROOD, H	7907180694	50-361 Q
RIGBERO, B A	7907110131	50-358 Q	ROOD, H	7907180580	50-361 Q
RILEY, J L	7907190065*	70-2623	ROONEY, M A	7907120458*	70-1308
RILEY, J L	7907180762	70-2623	ROONEY, V L	7907060470	50-298 P
RILEY, J L	7907190593	70-2623	ROONEY, V L	7907130421*	50-260 P
RILEY, B W	7907100540	50-320 H	ROOT, L D	7907050220	50-331 P
RINACA, J M	7907130189	50-338 Q	ROOT, L D	7907100560	50-331 P
RINACA, J M	7907060390	50-338 Q	ROBARIO, J C	7907270080	PRM
RINACA, J M	7907180774	50-338 Q	ROSE, P E	7907300561	PR

# PERSONAL AUTHOR INDEX

421

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROSENFIELD, A R	7907300381	RES	RYAN, R G	7907180142	FOIA
ROSENTHAL, A S	7907160097	PROJ	RYAN, R G	7907270239	AGREEMENT
ROSENBERG, A B	7907130139*	50-482 G	RYBARCZYK, R G	7907190434	WASTE MGT
ROSENBERG, A B	7907110747*	50-482 G	SABOL, A R	7907230572*	50-387 Q
ROSENTHAL, J E	7907260466*	50-320 F	SABOL, A R	7907110672*	50-387 Q
ROSMUSSEN, T L	7907190725	FR	SABOL, A R	7907190011*	50-387 Q
ROSLIE, E	7907260171	50-344 Q	SABOL, A R	7907200484*	50-387 Q
ROSLIE, E	7907240295	50-344 Q	SACHS, R G	7907300047	NUREQ
ROSS, D M	7907310480	71-361	SACKETT, K E	7907240126	NUREQ
ROSS, D A	7907030379	50-219 S	SADLON, S	7907160353*	50-3 S
ROSS, D A	7907030381*	50-219 S	SAENGER, E L	7907240572	PRM
ROSS, D A	7907250350	50-219 R	SALTZMAN, J	7907120074	50-280 J
ROSS, D A	7907260587	50-219 S	SALTZMAN, R B	7907160097	PROJ
ROSS, D A	7907260593*	50-219 S	SAMPFELS, M D	7907180879	50-445 H
ROSS, W J	7907260022	50-272 P	SAMPFELS, M D	7907020005	50-445 H
ROSS, D	7907160361	50-269 P	SANDERS, W F	7907130306*	50-286 Q
ROSS, D F	7907020279	50-320 Q	SANTORO, M P	7907190710	PRM
ROSS, D F	7907120656	50-247 Q	SATTERWHITE, D	7907090443	RES
ROSS, D F	7907020414	FOIA	BATTERFIELD, R	7907160243*	50-275 Q
ROSS, D F	7907020397	50-287 P	SAVER, R C	7907230039*	50-338 Q
ROSS, D F	7907020489	FOIA	SAVIONAC, N F	7907230234	PRM
ROSS, D F	7907020510	FOIA	SCALET, D.	7907240446*	50-471 D
ROSS, D F	7907180170*	50-3 P	SCARAND, R A	7907060512	40-8584
ROSS, D F	7907180916	TOPREP	SCARAND, R A	7907110253	40-3453
ROSS, D F	7907020119	50-320 Q	SCARAND, R A	7907110264*	40-3453
ROSS, D F	7907020188	50-335 P	SCARAND, R A	7907110275	40-299
ROSS, D	7907300400	50-346 Q	SCARAND, R A	7907020508	40-8602
ROSS, D F	7907300488*	50-346 Q	SCARAND, R A	7907020509*	40-8602
ROSS, D F	7907300407	50-346 S	SCARAND, R A	7907230062	40-8102
ROSSBACH, L	7907110245	40-4492	SCARAND, R A	7907230101	40-8721
ROSSD, D J	7907130069	50-329 T	SCARAND, R A	7907120089	40-8722
ROSSD, D J	7907180268	50-329 T	SCARAND, R A	7907120103*	40-8722
ROSTOCZY, Z R	7907020482	FOIA	SCARTH, E D.	7907180879	50-445 H
ROTH, M W	7907190452*	50-309 H	SCHEKNE, R	7907200246	50-320 P
ROTH, M V	7907180713*	50-171 U	SCHEKNE, R	7907200243	50-320 P
ROTH, J	7907230128*	70-738	SCHEKNE, R	7907200218	50-320 F
ROTDW, D	7907250475	70-2623	SCHEKUTZ, C E	7907300172	XPORLTC
ROUBE, L C	7907110257	70-364	SCHAEFFER, J C	7907050163*	50-346 Q
ROUBE, L C	7907080072	70-364	SCHAEHEL, R	7907300369	TOPREP
ROUBE, L C	7907050042	70-1193	SCHENDEL, K R	7907100636	40-8304
ROUBE, L C	7907050068	70-1143	SCHENDEL, K R	7907180859	40-8304
ROUBE, L C	7907190670	70-1308	SCHENDEL, K R	7907300201	40-8502
ROUBE, L C	7907110224	70-364	SCHERER, A E	7907060184	PR
ROUBE, L C	7907090121	70-364	SCHERER, A E	7907160282	50-470 K
ROWE, B S	7907270396	71-24	SCHERER, A E	7907110502	TOPREP
ROZBA, R B	7907170204	NUREQ	SCHERBERGER, R F	7907030104	XPORLTC
RUBV, R	7907060136	50-289 F	SCHIERLING, H	7907120185	50-320 H
RUDOLPH, J E	7907030311	FOIA	SCHMIDT, A D	7907110408	50-251 S
RUDOLPH, J J	7907060336*	50-346 S	SCHMIDT, A D	7907110722	50-250 Q
RUEBHAUSEN, O M	7907300415*	50-201 I	SCHMIDT, A D	7907090303	50-250 Q
RUEBHAUSEN, O M	7907300536*	50-201 I	SCHMIDT, A D	7907090350	50-251 S
RUEYER, D A	7907020156	50-368 F	SCHMIDT, A D	7907120634	50-335 S
RUFF, A B	7907230768*	50-390 Q	SCHMIDT, A D	7907180312	50-335 S
RUFF, A B	7907240163*	50-369 Q	SCHMIDT, A D	7907170098	50-250 S
RUHLMAN, W A	7907240192*	50-339 Q	SCHMIDT, A D	7907170158	50-251 S
RUHLMAN, W A	7906290383	50-320 P	SCHMIDT, A D	7907170179	50-250 S
RUHLMAN, W A	7907230002*	50-250 Q	SCHMIDT, A D	7907180557	50-251 S
RUITER, G H	7907050309*	50-305 S	SCHMIDT, A D	7907250335	50-335 S
RUITER, G H	7907050313*	50-305 S	SCHNAUTZ, C E	7907030291	XPORLTC
RUITER, G H	7907090287*	50-305 S	SCHNAUTZ, C E	7907250033	XPORLTC
RUITER, G H	7907090294*	50-305 S	SCHNEIDER, R R	7907060420	50-220 Q
RUITER, G H	7907090299*	50-305 S	SCHNEIDER, R R	7907130129	50-220 Q
RUITER, G H	7907090312*	50-305 S	SCHNEIDER, R R	7907230038*	50-220 Q
RUITER, G H	7907170085*	50-305 S	SCHNEIDER, R R	7907300148	50-220 Q
RUITER, G H	7907170090*	50-305 S	SCHNEIDER, R R	7907050338	50-220 S
RUITER, G H	7907170033*	50-305 S	SCHNEIDER, R R	7907130381	50-220 S
RUNION, C	7907300525*	50-201 I	SCHNEIDER, R R	7907130444	50-220 S
RUNNELS, H	7907110086*	50-320 Q	SCHNEIDER, R R	7907170225	50-220 P
RUNYON, J	7907160298	50-10 H	SCHNEIDER, R R	7907200458	50-220 P
RUSHMORE, J W	7907030283	50-220 J	SCHNEIDER, F W	7907020200	50-272 Q
RUSHMORE, J W	7907030304	50-220 J	SCHNEIDER, F W	7907030456	50-272 Q
RUSNACK, W	7907300544*	50-201 I	SCHNEIDER, F W	7907110402	50-272 P
RUSSELL, A F	7907190198	50-361 Q	SCHOLL, R F	7907260442	50-320 P
RUSSELL, M G	7907270090	REGOD	SCHOPFMAN, M A	7907110412*	50-251 S
RUSSELL, L S	7907030390	50-317 S	SCHOPFMAN, M A	7907090311*	50-250 S
RUSSELL, L B	7907200403	50-318 S	SCHOPFMAN, M A	7907090371*	50-251 S
RUSSELL, L B	7907200410	50-318 S	SCHOPFMAN, M A	7907170101*	50-250 S
RUSSELL, L B	7907250292	50-317 S	SCHOPFMAN, M A	7907120641*	50-335 S
RUSSELL, L B	7907250300	50-318 S	SCHOPFMAN, M A	7907170164*	50-251 S
RUSSELL, L B	7907260656	50-318 S	SCHOPFMAN, M A	7907170195*	50-250 S
RUTHMEYER, T J	7907120274	50-358 Q	SCHOPFMAN, M A	7907180565*	50-251 S
RUTLAND, O	7907090320	50-312 Q	SCHOPFMAN, M A	7907250341*	50-335 S
RYAN, T O	7907090662	50-445 Q	SCHREIBER, D L	7907090002*	50-522 Q
RYAN, R G	7907110404	50-320 A	SCHULTZ, D P	7907190728	PR
RYAN, R G	7907190509	WASTE MGT	SCHULTZ, W H	7907100469	50-320 H
RYAN, R G	7907120748	FOIA	SCHUMACHER, P M	7907170187	NUREQ
			SCHUMACHER, M C	7907180354*	50-315 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SCHUMACHER, M C	7907180500*	50-295 Q	SCHWENCER, A	7907240554	50-286 P
SCHUTT, R	7907110708	50-596 G	SCHWENCER, A	7907240556	50-272 P
SCHWARZ, M D	7907130442	50-498 Q	SCHWENCER, A	7907240557	50-244 P
SCHWARZ, M D	7907130471*	50-498 Q	SCHWENCER, A	7907240560	50-206 P
SCHWARZ, M D	7907130486*	50-498 Q	SCHWENCER, A	7907240562	50-280 P
SCHWAB, Q	7907250561*	QA999	SCHWENCER, A	7907240564	50-266 P
SCHWEIKER, R S	7907310104*	50-463 U	SCHWENCER, A	7907240567	50-305 P
SCHWENK, E B	7907300068	NURE0	SCHWENCER, A	7907240569	50-29 P
SCHWENK, E B	7907300489	RES	SCHWENCER, A	7907240603	50-247 P
SCHWENDIMAN, L C	7907170197	NURE0	SCHWENCER, A	7907240611*	50-247 P
SCHWENK, E B	7907300554	RES	SCHWENCER, A	7907240615*	50-247 P
SCHWEIBINZ, E R	7907180474*	50-546 Q	SCHWENCER, A	7907240618*	50-247 P
SCHWEIBINZ, E R	7907250216*	50-483 Q	SCHWENCER, A	7907250555	50-250 P
SCHWENCER, A	7907260431*	50-272 Q	SCHWENCER, A	7907250543*	50-250 P
SCHWENCER, A	7907310196*	50-272 P	SCHWENCER, A	7907250557*	50-250 P
SCHWENCER, A	7906250325	50-320 P	SCHWENCER, A	7907270189	50-295 P
SCHWENCER, A	7906250326*	50-320 P	SCHWENCER, A	7907270193*	50-295 P
SCHWENCER, A	7906250327*	50-320 P	SCHWENCER, A	7907270204*	50-295 P
SCHWENCER, A	7906250328*	50-320 P	SCHWENCER, A	7907260177	50-315 P
SCHWENCER, A	7907310568	50-348 P	SCHWENCER, A	7907260195*	50-315 P
SCHWENCER, A	7907310569	50-295 P	SCHWENCER, A	7907260230*	50-315 P
SCHWENCER, A	7907310576	50-3 P	SCHWENCER, A	7907260068	50-344 P
SCHWENCER, A	7907310579	50-261 P	SCHWENCER, A	7907260088*	50-344 P
SCHWENCER, A	7907310580	50-213 P	SCHWENCER, A	7907260102*	50-344 P
SCHWENCER, A	7907310583	50-334 P	SCHWENCER, A	7907180061	50-261 P
SCHWENCER, A	7907310584	50-250 P	SCHWENCER, A	7907180068*	50-261 P
SCHWENCER, A	7907310588	50-315 P	SCHWENCER, A	7907050218	50-247 Q
SCHWENCER, A	7907310590	50-286 P	SCHWENCER, A	7907160012*	FDIA
SCHWENCER, A	7907310593	50-344 P	SCDLNICK, M	7907250362*	50-244 P
SCHWENCER, A	7907310594	50-272 P	SCOTT, J M	7907090499*	50-466 Q
SCHWENCER, A	7907310596	50-338 P	SCOTT, J M	7907240512*	50-466 Q
SCHWENCER, A	7907130152	50-250 Q	SCOTT, J M	7907090482	50-466 Q
SCHWENCER, A	7907060239	50-344 P	SCOTT, J M	7907110496	50-466 Q
SCHWENCER, A	7907110717	50-286 F	SCOTT, J M	7907240503*	50-466 Q
SCHWENCER, A	7907130090	50-250 P	SCOTT, J M	7907180836	50-466 Q
SCHWENCER, A	7907130167	50-261 P	SCOTT, J M	7907190696	50-466 Q
SCHWENCER, A	7907180217	50-3 P	SCOTT, H W	7907190806	PR
SCHWENCER, A	7907240592	50-348 Q	SCOTT, W J	7907060248	50-295 Q
SCHWENCER, A	7907240593	50-295 Q	SCOTT, W J	7907200175	50-295 Q
SCHWENCER, A	7907240596	50-261 Q	SCOTT, W J	7907130495	50-599 Q
SCHWENCER, A	7907240599	50-213 Q	SCOTT, W J	7907130505*	50-599 Q
SCHWENCER, A	7907240600	50-334 Q	SCOTT, W J	7907190339	50-599 Q
SCHWENCER, A	7907240602	50-250 Q	SCOTT, W J	7907190716	50-599 Q
SCHWENCER, A	7907240605	50-315 Q	SCOTT, Q H	7907190488	NURE0
SCHWENCER, A	7907240607	50-282 Q	SCROGINS, R M	7907160184	50-287 U
SCHWENCER, A	7907240608	50-266 Q	SCROGINS, R M	7907120692	50-320 P
SCHWENCER, A	7907240610	50-344 Q	SCROGINS, R M	7907180080	50-320 H
SCHWENCER, A	7907240613	50-272 Q	SEAY, J L	7907090403*	QA999
SCHWENCER, A	7907240614	50-244 Q	SEAY, W M	7907060316*	50-327 A
SCHWENCER, A	7907240616	50-206 Q	SEELINGER, J L	7907190516	50-289 S
SCHWENCER, A	7907240619	50-280 Q	SEELINGER, J L	7907190598	50-289 S
SCHWENCER, A	7907240622	50-266 Q	SEELY, S	7907180870	50-568 H
SCHWENCER, A	7907240625	50-305 Q	SEIDLE, W C	7907050570	50-458 S
SCHWENCER, A	7907240626	50-29 Q	SEIDLE, W C	7907050572	50-498 S
SCHWENCER, A	7907090216	50-261 P	SEIDLE, W C	7907050573	50-481 S
SCHWENCER, A	7907090217*	50-261 P	SEIDLE, W C	7907050574	50-382 S
SCHWENCER, A	7907090221*	50-261 P	SEIDLE, W C	7907050575	50-445 S
SCHWENCER, A	7907130196	50-282 R	SEIDLE, W C	7907270288	50-482 Q
SCHWENCER, A	7907130133	50-250 P	SEIDLE, W C	7907110603	50-498 Q
SCHWENCER, A	7907130209	50-315 P	SEIDLE, W C	7907110671	50-445 Q
SCHWENCER, A	7907110577	50-286 P	SEIDLE, W C	7907110414	50-382 Q
SCHWENCER, A	7907110581	50-285 P	SEIDLE, W C	7907110619	50-482 Q
SCHWENCER, A	7907110587*	50-285 P	SEIDLE, W C	7907310119	50-466 Q
SCHWENCER, A	7907130097	50-266 F	SEIDLE, W C	7907110732	50-482 Q
SCHWENCER, A	7907110571	50-272 P	SEIDLE, W C	7907110656	50-445 Q
SCHWENCER, A	7907310177	50-272 P	SEIDLE, W C	7907110670	50-382 Q
SCHWENCER, A	7907310183*	50-272 P	SEIDLE, W C	7907110682	50-482 Q
SCHWENCER, A	7907310329	50-266 P	SEIDLE, W C	7907030259	50-458 S
SCHWENCER, A	7907110730	50-250 P	SEIDLE, W C	7907030262	50-445 S
SCHWENCER, A	7907130311	50-334 P	SEIDLE, W C	7907030264	50-482 S
SCHWENCER, A	7907130316*	50-334 P	SEIDLE, W C	7907030267	50-382 S
SCHWENCER, A	7907130329*	50-334 P	SEIDLE, W C	7907030268	50-498 S
SCHWENCER, A	7907190609	50-247 P	SEIDLE, W C	7907250498	50-445 Q
SCHWENCER, A	7907190614*	50-247 P	SEIDLE, W C	7907250477	50-482 Q
SCHWENCER, A	7907190623*	50-247 P	SEIDLE, W C	7907260477	50-498 Q
SCHWENCER, A	7907240589	50-272 F	SEIDLE, W C	7907020303	50-458 S
SCHWENCER, A	7907240597*	50-272 P	SEIDLE, W C	7907020305	50-498 S
SCHWENCER, A	7907180158	50-3 P	SEIDLE, W C	7907020306	50-482 S
SCHWENCER, A	7907190647	50-348 P	SEIDLE, W C	7907020307	50-382 S
SCHWENCER, A	7907190652*	50-348 P	SEIDLE, W C	7907020309	50-445 S
SCHWENCER, A	7907190661*	50-348 P	SEIDLE, W C	7907250221	50-482 Q
SCHWENCER, A	7907240538	50-344 P	SEIDLE, W C	7907230347	50-482 Q
SCHWENCER, A	7907240539	50-261 P	SEIDLE, W C	7907240047	50-498 Q
SCHWENCER, A	7907240540	50-295 P	SEIDLE, W C	7907240051	50-382 Q
SCHWENCER, A	7907240544	50-213 P	SEIDLE, W C	7907260559	50-445 Q
SCHWENCER, A	7907240546	50-250 P	SEIDLE, W C	7907300035	50-498 Q
SCHWENCER, A	7907240547	50-315 P	SEIDLE, W C	7907310598	50-482 Q
SCHWENCER, A	7907240550	50-282 P	SEIDLE, W C	7907310561	50-498 Q

# PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEIDLE, W C	7907030205	50-458 S	SEYFRIT, K V	7907190393	50-458 Q
SEIDLE, W C	7907030209	50-498 S	SEYFRIT, K V	7907190395	50-498 Q
SEIDLE, W C	7907030210	50-482 S	SEYFRIT, K V	7907190399	50-462 Q
SEIDLE, W C	7907030212	50-382 S	SEYFRIT, K V	7907190400	50-382 Q
SEIDLE, W C	7907030215	50-445 S	SEYFRIT, K V	7907190403	50-298 Q
SEIDLE, W C	7907300229	50-445 Q	SEYFRIT, K V	7907190407	50-285 Q
SEIDLE, W C	7907130334	50-458 S	SEYFRIT, K V	7907190408	50-267 Q
SEIDLE, W C	7907130336	50-498 S	SEYFRIT, K V	7907190411	50-445 Q
SEIDLE, W C	7907130337	50-482 S	SEYFRIT, K V	7907060010	50-313 Q
SEIDLE, W C	7907130340	50-382 S	SEYFRIT, K V	7907060013	50-458 Q
SEIDLE, W C	7907130341	50-445 S	SEYFRIT, K V	7907060015	50-498 Q
SEIDLE, W C	7907270294	50-445 Q	SEYFRIT, K V	7907060016	50-482 Q
SEIDLE, W C	7907180683	50-458 S	SEYFRIT, K V	7907060017	50-382 Q
SEIDLE, W C	7907180685	50-498 S	SEYFRIT, K V	7907060018	50-298 Q
SEIDLE, W C	7907180688	50-482 S	SEYFRIT, K V	7907060020	50-285 Q
SEIDLE, W C	7907180689	50-382 S	SEYFRIT, K V	7907060022	50-267 Q
SEIDLE, W C	7907180690	50-445 S	SEYFRIT, K V	7907060023	50-445 Q
SEIDLE, W C	7907240514	50-458 S	SEYFRIT, K V	7907050557	50-556 Q
SEIDLE, W C	7907240517	50-498 S	SEYFRIT, K V	7907050560	50-458 Q
SEIDLE, W C	7907240518	50-482 S	SEYFRIT, K V	7907050561	50-466 Q
SEIDLE, W C	7907240519	50-382 S	SEYFRIT, K V	7907050562	50-498 Q
SEIDLE, W C	7907240521	50-445 S	SEYFRIT, K V	7907050563	50-482 Q
SEIDLE, W C	7907300242	50-445 Q	SEYFRIT, K V	7907050565	50-382 Q
SEKULER, S N	7907110499	50-237 Q	SEYFRIT, K V	7907050566	50-445 Q
SEKULER, S N	7907180154	50-295 Q	SEYFRIT, K V	7907020443	50-313 Q
SEKULER, S N	7907130004	50-295 Q	SEYFRIT, K V	7907020444	50-298 Q
SEKULER, S N	7907310138	50-295 Q	SEYFRIT, K V	7907020445	50-285 Q
SELBY, J D	7907050569	50-329 H	SEYFRIT, K V	7907020446	50-267 Q
SELGRADE, E L	7907110165	50-471 Q	SEYFRIT, K V	7907050506	50-458 Q
SELGRADE, E L	7907180366	50-471 Q	SEYFRIT, K V	7907050509	50-498 Q
SELGRADE, E L	7907180374*	50-471 Q	SEYFRIT, K V	7907050512	50-482 Q
SELL, T C	7907110192*	50-320 Q	SEYFRIT, K V	7907050514	50-382 Q
SELLS, D E	7907110601	50-596 D	SEYFRIT, K V	7907050517	50-445 Q
SELLS, D E	7907200242	50-387 D	SEYFRIT, K V	7907050483	50-458 Q
SELLS, D E	7907300504	50-387 A	SEYFRIT, K V	7907050485	50-498 Q
SELMAN, R L	7907270072	PRM	SEYFRIT, K V	7907050487	50-482 Q
SELVADIO, K A	7907020132	FOIA	SEYFRIT, K V	7907050488	50-382 Q
SETBER, J L	7907190351	WASTE MOT	SEYFRIT, K V	7907050489	50-445 Q
BEWELL, R D	7907180886	40-8698	SEYFRIT, K V	7907120370	50-313 Q
BEWELL, R D	7907310221	40-8698	SEYFRIT, K V	7907120373	50-298 Q
SEYFRIT, K V	7907250355*	QA999	SEYFRIT, K V	7907120375	50-285 Q
SEYFRIT, K V	7907130126	50-482 Q	SEYFRIT, K V	7907120377	50-267 Q
SEYFRIT, K V	7906130210	70-2560	SEYFRIT, K V	7907020013	50-313 Q
SEYFRIT, K V	7906130213	70-1406	SEYFRIT, K V	7907020014	50-285 Q
SEYFRIT, K V	7906130217	70-1401	SEYFRIT, K V	7907020015	50-267 Q
SEYFRIT, K V	7906130219	70-2163	SEYFRIT, K V	7907020017	50-131 Q
SEYFRIT, K V	7907090394	QA999	SEYFRIT, K V	7907020018	50-274 Q
SEYFRIT, K V	7907100245	50-131 Q	SEYFRIT, K V	7907020020	50-188 Q
SEYFRIT, K V	7907100248	50-274 Q	SEYFRIT, K V	7907020022	50-148 Q
SEYFRIT, K V	7907100251	50-262 Q	SEYFRIT, K V	7907020023	50-252 Q
SEYFRIT, K V	7907100254	50-112 Q	SEYFRIT, K V	7907020024	50-112 Q
SEYFRIT, K V	7907100259	50-59 Q	SEYFRIT, K V	7907020026	50-262 Q
SEYFRIT, K V	7907100262	50-192 Q	SEYFRIT, K V	7907020028	50-72 Q
SEYFRIT, K V	7907100263	50-72 Q	SEYFRIT, K V	7907020030	50-59 Q
SEYFRIT, K V	7907100267	50-284 Q	SEYFRIT, K V	7907020033	50-192 Q
SEYFRIT, K V	7907100268	50-282 Q	SEYFRIT, K V	7907020035	50-284 Q
SEYFRIT, K V	7907100271	50-148 Q	SEYFRIT, K V	7907050418	40-8027
SEYFRIT, K V	7907100273	50-188 Q	SEYFRIT, K V	7907230437	50-131 Q
SEYFRIT, K V	7907100282	50-313 Q	SEYFRIT, K V	7907230439	50-274 Q
SEYFRIT, K V	7907100289	50-298 Q	SEYFRIT, K V	7907230501	50-284 Q
SEYFRIT, K V	7907100290	50-285 Q	SEYFRIT, K V	7907230506	50-188 Q
SEYFRIT, K V	7907100293	50-267 Q	SEYFRIT, K V	7907230507	50-59 Q
SEYFRIT, K V	7907060325	50-313 Q	SEYFRIT, K V	7907230508	50-148 Q
SEYFRIT, K V	7907060327	50-298 Q	SEYFRIT, K V	7907230510	50-112 Q
SEYFRIT, K V	7907060328	50-285 Q	SEYFRIT, K V	7907230512	50-192 Q
SEYFRIT, K V	7907060329	50-267 Q	SEYFRIT, K V	7907230514	50-72 Q
SEYFRIT, K V	7907260122	50-313 P	SEYFRIT, K V	7907250323	QA999
SEYFRIT, K V	7907260125	50-298 P	SEYFRIT, K V	7907120586	50-267 Q
SEYFRIT, K V	7907260126	50-285 P	SEYFRIT, K V	7907120588	50-285 Q
SEYFRIT, K V	7907260129	50-267 P	SEYFRIT, K V	7907120590	50-313 Q
SEYFRIT, K V	7907030122	50-458 Q	SEYFRIT, K V	7907120596	50-458 Q
SEYFRIT, K V	7907030123	50-498 Q	SEYFRIT, K V	7907120598	50-498 Q
SEYFRIT, K V	7907030124	50-482 Q	SEYFRIT, K V	7907120600	50-482 Q
SEYFRIT, K V	7907030126	50-382 Q	SEYFRIT, K V	7907120602	50-382 Q
SEYFRIT, K V	7907030128	50-285 Q	SEYFRIT, K V	7907120604	50-445 Q
SEYFRIT, K V	7907030129	50-445 Q	SEYFRIT, K V	7907240238	50-298 Q
SEYFRIT, K V	7907200343	50-313 Q	SEYFRIT, K V	7907100385	50-313 Q
SEYFRIT, K V	7907200345	50-458 Q	SEYFRIT, K V	7907100389	50-298 Q
SEYFRIT, K V	7907200348	50-498 Q	SEYFRIT, K V	7907100393	50-285 Q
SEYFRIT, K V	7907200356	50-482 Q	SEYFRIT, K V	7907100398	50-267 Q
SEYFRIT, K V	7907200357	50-382 Q	SEYFRIT, K V	7907110242	50-458 Q
SEYFRIT, K V	7907200360	50-298 Q	SEYFRIT, K V	7907110246	50-498 Q
SEYFRIT, K V	7907200361	50-285 Q	SEYFRIT, K V	7907110249	50-482 Q
SEYFRIT, K V	7907200363	50-267 Q	SEYFRIT, K V	7907110252	50-382 Q
SEYFRIT, K V	7907200365	50-445 Q	SEYFRIT, K V	7907110256	50-445 Q
SEYFRIT, K V	7907250347*	QA999	SEYFRIT, K V	7907120591	50-298 Q
SEYFRIT, K V	7907190390	50-313 Q	SEYFRIT, K V	7907180249	50-458 Q

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEYFRIT, K. V.	7907180252	50-498 Q	SHEA, J. R.	7907230188	SECY
SEYFRIT, K. V.	7907180255	50-464 Q	SHEA, J. R.	7907100306	XPORTLIC
SEYFRIT, K. V.	7907180257	50-482 Q	SHEA, J. R.	7907190805	XPORTLIC
SEYFRIT, K. V.	7907180262	50-382 Q	SHEA, J. R.	7907190814	XPORTLIC
SEYFRIT, K. V.	7907180266	50-445 Q	SHEA, J. R.	7907190825	XPORTLIC
SEYFRIT, K. V.	7907180269	50-556 Q	SHEA, J. R.	7907250038	XPORTLIC
SEYFRIT, K. V.	7907100514	50-458 Q	SHEA, J. R.	7907250088	XPORTLIC
SEYFRIT, K. V.	7907100516	50-498 Q	SHEA, J. R.	7907250096	XPORTLIC
SEYFRIT, K. V.	7907100517	50-482 Q	SHEA, J. R.	7907250101	XPORTLIC
SEYFRIT, K. V.	7907100518	50-382 Q	SHEA, J. R.	7907190684	XPORTLIC
SEYFRIT, K. V.	7907100520	50-445 Q	SHEA, J. R.	7907190692	XPORTLIC
SEYFRIT, K. V.	7907180376	50-313 Q	SHEA, J. R.	7907190697	XPORTLIC
SEYFRIT, K. V.	7907180379	50-298 Q	SHEA, J. R.	7907240008	XPORTLIC
SEYFRIT, K. V.	7907180381	50-285 Q	SHEA, J. R.	7907240012	XPORTLIC
SEYFRIT, K. V.	7907180385	50-267 Q	SHEA, J. R.	7907240031	XPORTLIC
SEYFRIT, K. V.	7907110289	50-458 Q	SHEA, J. R.	7907240036	XPORTLIC
SEYFRIT, K. V.	7907110292	50-498 Q	SHEA, J. R.	7907240039	XPORTLIC
SEYFRIT, K. V.	7907110293	50-482 Q	SHEA, J. R.	7907190715	XPORTLIC
SEYFRIT, K. V.	7907110296	50-382 Q	SHEA, J. R.	7907190681	XPORTLIC
SEYFRIT, K. V.	7907110300	50-445 Q	SHEA, J. R.	7907190687	XPORTLIC
SEYFRIT, K. V.	7907310207	50-313 Q	SHEA, J. R.	7907230210	XPORTLIC
SEYFRIT, K. V.	7907310210	50-298 Q	SHEA, J. R.	7907230227	XPORTLIC
SEYFRIT, K. V.	7907310212	50-285 Q	SHEA, J. R.	7907180860*	SECY
SEYFRIT, K. V.	7907310217	50-267 Q	SHEA, J. R.	7907180880	XPORTLIC
SEYFRIT, K. V.	7907310610	50-274 Q	SHEA, J. R.	7907260852	XPORTLIC
SEYFRIT, K. V.	7907310615	50-131 Q	SHEA, J. J.	7907120494	50-244 P
SEYFRIT, K. V.	7907310619	50-313 Q	SHEA, J. J.	7907120091	50-245 P
SEYFRIT, K. V.	7907310623	50-298 Q	SHEA, K. H.	7907300227*	FOIA
SEYFRIT, K. V.	7907190489	50-313 Q	SHEALY, H. G.	7907190321	WASTE MGT
SEYFRIT, K. V.	7907190493	50-458 Q	SHELOBSKY, T.	7907020461	50-336 , Q
SEYFRIT, K. V.	7907190495	50-498 Q	SHELLEY, W. J.	7906140590*	40-8006
SEYFRIT, K. V.	7907190499	50-482 Q	SHELLEY, W. J.	7907060035	40-8027
SEYFRIT, K. V.	7907190500	50-382 Q	SHELLEY, W. J.	7907190378	PROJ
SEYFRIT, K. V.	7907190502	50-298 Q	SHELLEY, W. J.	7907310173	40-8027
SEYFRIT, K. V.	7907190503	50-285 Q	SHEHANSKI, P.	7907020442	50-320 P
SEYFRIT, K. V.	7907190506	50-267 Q	SHEPARD, L. G.	7907110488	PROJ
SEYFRIT, K. V.	7907190508	50-445 Q	SHEPARD, A. M.	7907240212*	50-443 Q
SEYFRIT, K. V.	7907240299	50-313 Q	SHERON, B. W.	7907250200	TOPREP
SEYFRIT, K. V.	7907240302	50-458 Q	SHERON, B. W.	7907300377	50-320 P
SEYFRIT, K. V.	7907240305	50-498 Q	SHERWOOD, G. G.	7907050066*	FOIA
SEYFRIT, K. V.	7907240309	50-482 Q	SHERWOOD, G. G.	7907050082*	FOIA
SEYFRIT, K. V.	7907240312	50-382 Q	SHERWOOD, G. G.	7907190596	FR
SEYFRIT, K. V.	7907240316	50-298 Q	SHERWOOD, G. G.	7907060175	FR
SEYFRIT, K. V.	7907240401	50-285 Q	SHERWOOD, G. G.	7907250141	REG00B
SEYFRIT, K. V.	7907240405	50-267 Q	SHERWOOD, G. G.	7907250127	REG00D
SEYFRIT, K. V.	7907240410	50-445 Q	SHERWOOD, G. G.	7907060324	TOPREP
SEYFRIT, K. V.	7907260325	50-313 Q	SHEWMON, P. O.	7907020484	50-320 Q
SEYFRIT, K. V.	7907260328	50-298 Q	SHEWMON, P. O.	7907120321	50-409 T
SEYFRIT, K. V.	7907260332	50-285 Q	SHEWMON, P. O.	7907230654	ACRE
SEYFRIT, K. V.	7907260334	50-267 Q	SHEWMON, P. O.	7907060369*	50-295 Q
SEYFRIT, K. V.	7907260231	50-313 Q	SHIELDS, W. J.	7907300593	50-546 Q
SEYFRIT, K. V.	7907260235	50-298 Q	SHIMSHAK, R. E.	7907110608	50-409 P
SEYFRIT, K. V.	7907260239	50-285 Q	SHINEFLUG, M.	7907190645	50-454 Q
SEYFRIT, K. V.	7907260242	50-267 Q	SHIPLETT, J. J.	7907020459	71-168
SEYFRIT, K. V.	7907270371	50-458 Q	SHIBSIA, J. A.	7907110319	50-272 B
SEYFRIT, K. V.	7907270394	50-498 Q	SHIVELY, C. N.	7907050102*	50-368 S
SEYFRIT, K. V.	7907270395	50-482 Q	SHIVELY, C. N.	7907050107*	50-368 S
SEYFRIT, K. V.	7907270397	50-382 Q	SHIVELY, C. N.	7907030398*	50-313 S
SEYFRIT, K. V.	7907270398	50-445 Q	SHIVELY, C. N.	7907090292*	50-368 S
SHAH, M. T.	7907190510	NUREG	SHIVELY, C. N.	7907090297*	50-368 S
SHACKELFORD, B. W.	7907270382*	70-1738	SHIVELY, C. N.	7907090279*	50-313 R
SHAHER, W. D.	7907050140*	50-298 Q	SHIVELY, C. N.	7907120650*	50-368 S
SHAH, V. L.	7907260288	NUREG	SHIVELY, C. N.	7907120654*	50-368 S
SHALLER, D. V.	7907200317	50-315 R	SHIVELY, C. N.	7907120660*	50-368 S
SHALLER, D. V.	7907200329	50-316 R	SHIVELY, C. N.	7907160296*	50-368 S
SHALLER, D. V.	7907190515	50-315 S	SHIVELY, C. N.	7907160308*	50-368 S
SHALLER, D. V.	7907190532	50-316 S	SHIVELY, C. N.	7907190388*	50-313 R
SHALLER, D. V.	7907250253	50-316 S	SHIVELY, C. N.	7907190544*	50-368 R
SHALLER, D. V.	7907300325	50-316 S	SHIVELY, C. N.	7907230354*	50-313 R
SHANE, B. C.	7907110519*	50-358 Q	SHIVELY, C. N.	7907300307*	50-368 S
SHANE, B. C.	7907190134*	50-358 Q	SHIVELY, C. N.	7907310453*	50-313 S
SHAPAR, H. K.	7907110624*	50-338 Q	SHMIDT, T. R.	7907130027	REG00D
SHAPAR, H. K.	7907240454	50-443 H	SHNIPER, J.	7907250489*	50-352 A
SHAUB, E. T.	7907100291	50-320 H	SHOCKLEY, M. T.	7907250499	FOIA
SHAUB, E. T.	7907100260	50-320 H	SHOENAKER, C. L.	7907060276	50-317 J
SHAUB, E. T.	7907180734*	70-820	SHON, F. J.	7907060495	50-556 Q
SHEA, J. F.	7907250547	50-201 P	SHOFFMAN, M. A.	7907180328*	50-335 S
SHEA, J. F.	7907300336	50-201 P	SHORB, E. H.	7907020310	50-367 A
SHEA, J. R.	7907240416	SECY	SHORB, E. H.	7907090424	50-367 Q
SHEA, J. R.	7811300307	XPORTLIC	SHORB, E. H.	7907160242	50-367 Q
SHEA, J. R.	7907030169*	FOIA	SHORT, T. E.	7907020213	50-285 Q
SHEA, J. R.	7907130427	SECY	SHORT, T. E.	7907060258	50-285 Q
SHEA, J. R.	7907030172*	FOIA	SHORT, T. E.	7907060268	50-285 Q
SHEA, J. R.	7907230230	XPORTLIC	SHORT, T. E.	7907060284	50-285 P
SHEA, J. R.	7907190009	SECY	SHORT, T. E.	7907030344	50-285 P
SHEA, J. R.	7907260919	50-245 P	SHORT, T. E.	7907030485	50-285 P
SHEA, J. R.	7907060443	XPORTLIC			



# PERSONAL AUTHOR INDEX

425

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHORT, T E	7907030444*	50-285 P	SMITH, R H	7907280837*	FOIA
SHORT, T E	7907090198	50-285 P	SMITH, J D	7907020115*	50-346 Q
SHORT, T E	7907090291	50-285 P	SMITH, J D	7907110134*	50-305 Q
SHORT, T E	7907090230*	50-285 P			
SHORT, T E	7907160310	50-285 P	SMITH, C V	7907090038	SECY
			SMITH, R D	7907090386	27-39
SHORT, T E	7907200364	50-285 F	SMITH, R D	7907230605	27-48
SHORT, T E	7907180395	50-285 R	SMOAK, W H	7907240559	PRM
SHORT, T E	7907180584*	50-285 P	SNIDER, R P	7907250609	TOPREP
SHORT, T E	7907180593*	50-285 P			
SHORT, T E	7907250262	50-285 F	SNIEZEK, J H	7907180129	IDE
SHORT, T E	7907260772	50-285 F	SNOW, B	7907090256	50-244 R
SHRADER, D	7907050425*	50-387 Q	SNYDER, O L	7907250483	50-352 A
SHUM, E Y	7907100705	70-27	SNYDER, O L	7907120561	50-320 H
SICILIAN, J M	7907030434	NUREQ	SNYDER, O L	7907250352*	FOIA
SIEDLE, W C	7907050184	50-482 Q	SNYDER, O L	7907190154	50-352 A
			SNYDER, O L	7907050186	50-387 Q
SIEDLE, W C	7907050174	50-498 Q	SOBON, L J	7907160320	TOPREP
SIEFKEN, L J	7907270388	NUREQ	SOBON, L J	7907030448	TOPREP
SIEGFRIED, K A	7907020479	50-341 Q	SOBON, L J	7907170173	TOPREP
SIEGFRIED, K A	7907020480*	50-341 Q			
SILBERG, J E	7907090393	50-387 Q			
			SOBON, L J	7907120354	TOPREP
SILBERG, J E	7907130157	50-387 Q	SOBON, L J	7907310313	TOPREP
SILBERG, J E	7907090171	50-320 Q	SOFER, G A	7907230511*	71-6581
SILBERG, J E	7907240335	50-387 Q	SOHINKI, S H	7907260003	50-466 Q
SILBERG, J E	7907310327	50-482 A	SOHINKI, S H	7906210417	50-466 Q
SILVERMAN, L	7907190198	50-361 Q			
			SOHINKI, S H	7907100640	50-466 Q
SIMPSON, M A	7907310474	50-336 Q	SOHINKI, S H	7907180358	50-592 Q
SIMPSON, J C	7907190379	50-392 Q	SOHINKI, S H	7907130833	50-466 Q
SIMPSON, J C	7907090301	50-392 Q	SOHINKI, S H	7907130586	50-466 Q
SINKIN, S A	7907120002	50-498 Q	SOHINKI, S H	7907310128	50-466 Q
SINKIN, S A	7907120004*	50-498 Q			
			SOHINKI, S H	7907130526	50-592 Q
SJODREN, R M	7907170118*	50-309 R	SOHINKI, S H	7907130538	50-466 Q
SJODREN, R M	7907170152*	50-271 R	SOHINKI, S H	7907310118	50-466 Q
SJODREN, R M	7907170172*	50-29 R	SOHINKI, S H	7907180731	50-437 Q
SKORUPSKI, S B	7907090018	71-268	SOHINKI, S H	7907170251	50-466 Q
SKOVHOLT, D	7907260494	50-320 H			
			SOHINKI, S H	7907270073	50-466 Q
SKOVHOLT, D	7907260478	50-320 U	SOLON, L R	7907020322*	PR
SKOVHOLT, D	7907020148	50-320 F	SOLON, L R	7907020320	PR
SKRUTSKI, R M	7907110081	50-338 Q	SOMERVILLE, G K	7907060261	40-8714
SKRUPA, J O	7907230162	XPORTRIC	SOSENSEN, D K	7907300257	PR
SLABACK, L A	7907270162	PRM			
			SOTR, J P	7907230006*	50-387 Q
SLAWSON, R N	7907030159	FOIA	SPANGLER, R O	7907020117*	50-313 Q
SLOBODIEN, M J	7907160098	50-320 P	SPANGLER, R O	7907020153*	50-313 Q
SLOBODIEN, M J	7906200417	50-320 H	SPANGLER, R O	7907020078*	50-313 Q
SMITH, E T	7907060356*	50-280 H	SPANGLER, R O	7907120007*	50-313 Q
SMITH, H P	7907260678	PRM			
			SPENCER, S H	7907260594*	50-244 B
SMITH, R D	7907260204	PR	SPENCER, M S	7907170134	NUREQ
SMITH, K C	7907060252*	TOPREP	SPENCER, O S	7907120394	50-460 Q
SMITH, T	7907310567	40-8692	SPENCER, O S	7907090368	50-397 Q
SMITH, G	7907110554*	50-249 B	SPENCER, O S	7907110705	50-361 Q
SMITH, R M	7907180368	50-522 Q			
			SPENCER, O S	7907110626	50-397 Q
SMITH, R I	7907100544*	50-311 A	SPENCER, O S	7907260518	50-361 Q
SMITH, R I	7907100543	50-311 A	SPENCER, O S	7907300098	50-508 Q
SMITH, F M	7907080273	71-6387	SPENCER, O S	7907260554	50-397 Q
SMITH, B M	7907080149	NUREQ	SPENCER, O S	7907260965	50-361 Q
SMITH, I W	7907180654	50-305 Q			
			SPENCER, O S	7907300442	50-361 Q
SMITH, P A	7907260377	CONTRACT	SPENCER, O S	7907270296	50-508 Q
SMITH, D H	7907080383	50-471 Q	SPENCER, O S	7907300110*	50-508 Q
SMITH, D H	7907240431	50-471 D	SPENCER, R L	7907190507*	50-10 Q
SMITH, D H	7907110695	50-471 Q	SPENCER, R L	7907180323*	50-295 Q
SMITH, B H	7907250144	50-471 Q			
			SPENCER, R L	7907240127*	50-373 Q
SMITH, B H	7907020004	50-471 Q	SPENCER, R L	7907300486	50-237 Q
SMITH, B H	7907180601	50-272 Q	SPENCER, R L	7907310076*	50-254 Q
SMITH, R H	7907250500*	FOIA	SPENCER, R L	7907180296*	50-346 Q
SMITH, G	7907050084*	70-2662	SPENCER, R L	7907180455*	50-254 Q
SMITH, G C	7907090430	50-320 P			
			SPENCER, R L	7907300491	50-254 Q
SMITH, G H	7907310023	50-29 Q	SPENCER, R L	7907180425*	50-331 Q
SMITH, G C	7907100278	50-320 H	SPENCER, R L	7907240152*	50-266 Q
SMITH, G C	7907180177	50-320 H	SPENCER, R L	7907260822*	50-237 Q
SMITH, G H	7907310167*	50-29 Q	SPENCER, R L	7907300392	50-295 Q
SMITH, G H	7907030062*	50-333 Q			
			SPITZNAU, L	7907260176	PR
SMITH, G H	7907310027*	50-29 Q	SPITZNAU, A E	7907170052*	50-334 R
SMITH, G H	7907230113*	70-938	SPRE, J W	7907270400	NUREQ
SMITH, G H	7907310158*	50-29 Q	SPRENGER, D J	7907100335	50-320 H
SMITH, G C	7907100269	50-320 H	STAATS, E. B.	7907180130	50-320 U
SMITH, G H	7907110655	40-7983			
			STAFFA, R W	7907190095*	50-321 Q
SMITH, G H	7907110453	50-245 Q	STAFFA, R W	7907100135	50-424 Q
SMITH, G H	7907230044*	50-220 Q	STAFFA, R W	7907100160	50-321 Q
SMITH, G H	7907300044	50-244 Q	STAFFA, R W	7907100173	50-424 Q
SMITH, G H	7907230089	70-938	STAFFA, R W	7907180163	50-424 Q
SMITH, G H	7907230006*	50-387 Q			
			STAFFA, R W	7907090144	50-424 Q
SMITH, G H	7907230029	50-220 Q	STAFFA, R W	7907180058	50-321 Q
SMITH, G H	7907230003	50-387 Q	STAFFA, R W	7907240270*	50-424 Q
SMITH, G H	7907230089	50-277 Q	STAFFA, R W	7907190355	50-321 Q
SMITH, T H	7907110544*	50-272 Q	STAFFA, R W	7907240269*	50-424 Q
SMITH, R H	7907250407*	FOIA			
			STAFFA, R W	7907260136	50-366 Q
SMITH, R H	7907250402*	FOIA	STAFFA, R W	7907250086	50-366 Q
SMITH, R H	7907250415*	FOIA	STAFFA, R W	7907100437	50-321 Q
			STAHL, T J	7907180371	PR

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STAHL, C R	7907110699	50-327 A
STAHL, C	7907260048	50-390 A
STALLINGS, C M	7907190816	50-338 S
STALLINGS, C M	7907230447	50-338 S
STALLINGS, C M	7907090248	50-338 S
STALLINGS, C M	7907100131	50-338 Q
STALLINGS, C M	7907100062	50-280 Q
STALLINGS, C M	7907190061*	50-280 Q
STALLINGS, C M	7907180145	50-280 Q
STALLINGS, C M	7907180670*	50-280 Q
STALLINGS, C M	7907310276	50-281 S
STALLINGS, C M	7907090195	50-280 Q
STALLINGS, C M	7907190252	50-280 Q
STALLINGS, C M	7907310190*	50-338 Q
STALLINGS, C M	7907330478*	50-338 Q
STALLINGS, C M	7907230014*	50-338 Q
STALLINGS, C M	7907300342*	50-280 Q
STALLINGS, C M	7907310010*	50-338 Q
STALLINGS, C M	7907090282	50-281 S
STALLINGS, C M	7907030300	50-338 P
STALLINGS, C M	7907030421	50-338 S
STALLINGS, C M	7907310451	50-338 P
STALLINGS, C M	7907050286	50-280 R
STALLINGS, C M	7907050298	50-338 Q
STALLINGS, C M	7907060291	50-280 S
STALLINGS, C M	7907060331	50-338 G
STALLINGS, C M	7907050391	50-338 P
STALLINGS, C M	7907090269	50-338 S
STALLINGS, C M	7907090307	50-338 P
STALLINGS, C M	7907090338	50-338 P
STALLINGS, C M	7907090372	50-280 S
STALLINGS, C M	79071005B1	50-338 P
STALLINGS, C M	7907300456	50-280 Q
STALLINGS, C M	7907110531	50-338 S
STALLINGS, C M	7907130266	50-338 R
STALLINGS, C M	7907170002	50-280 R
STALLINGS, C M	7907170215	50-338 S
STALLINGS, C M	7907170019	50-338 P
STALLINGS, C M	7907190556	50-339 A
STALLINGS, C M	7907200327	50-281 P
STALLINGS, C M	7907250260	50-338 Q
STALLINGS, C M	7907230571	50-338 S
STALLINGS, C M	7907260804	50-338 P
STALLINGS, C M	7907270185	50-338 P
STALLINGS, C M	7907270191	50-338 P
STALLINGS, C M	7907310440	50-280 P
STALLINGS, C M	7907300309	50-338 S
STALLINGS, C M	7907310255	50-280 P
STALLINGS, C M	7907310424	50-280 S
STALLINGS, C M	7907310430	50-338 S
STALLINGS, C M	7907310446	50-339 A
STAMPLEY, M L	7907050321	50-416 K
STANLEY, W S	7907100654*	50-289 R
STANLEY, W S	7907180475*	50-289 S
STANLEY, W S	7907180482*	50-289 S
STARKEY, R B	7907090323	50-261 P
STARKEY, R B	7907100378*	50-261 S
STARKEY, R B	7907130333*	50-261 S
STARKEY, R B	7907240353*	50-261 S
STARR, P	7907100537*	50-380 J
STEARNS, R G	7907190205	NUREQ
STEGER, D B	7907260580	50-592 Q
STEGER, D B	7907310377	50-206 A
STELLO, V	7907190628	50-313 Q
STELLO, V	7907100132*	50-320 T
STELLO, V	7907310271*	50-338 U
STELLO, V	7907310277*	50-338 U
STELLO, V	7907180787	50-338 Q
STELLO, V	7907050477	50-334 P
STELLO, V	7907270023*	50-261 Q
STELLO, V	7907050242	50-219 P
STELLO, V	7907180143*	50-219 Q
STELLO, V	7907270016*	50-261 Q
STELLO, V	7907300121	50-344 P
STELLO, V	7907050099	50-482 Q
STELLO, V	7907050112*	50-482 Q
STELLO, V	7907180794*	50-338 Q
STELLO, V	7907180803*	50-338 Q
STENNIS, J C	7907130484	50-416 A
STEPHEN, W R	7907180735	71-39
STEPHENSON, B B	7907030404	50-237 S
STEPHENSON, B B	7907110442	50-237 S
STEPHENSON, B B	7907100300	50-249 S
STEPHENSON, B B	7907110430	50-237 S
STEPHENSON, B B	7907110348	50-249 S
STEPHENSON, B B	7907170074	50-10 R

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STEPHENSON, B B	7907250284	50-10 S
STEPHENSON, B B	7907250364	50-249 S
STEPHENSON, B B	7907260709	50-237 S
STEPHENSON, W A	7907190445*	50-302 R
STEPTOE, P	7907180332	PR
STEPTOE, P	7907050423	50-237 Q
STEPTOE, P	7907050457	50-295 Q
STEPTOE, P	7907190446	50-599 Q
STEPTOE, P	7907090478	50-295 Q
STERN, W C	7907180838	XPORTLIC
STERN, W C	7907310040	XPORTLIC
STERNBERG, D M	7907110092*	50-133 Q
STERNBERG, D M	7907270141*	50-275 Q
STERNBERG, D M	7907300135*	50-344 Q
STERNBERG, D M	7907270276*	50-344 Q
STERNBERG, D M	7907270290*	50-397 Q
STERNBERG, D M	7907270280*	50-275 Q
STERNBERG, D M	7907300233*	50-344 Q
STERRETT, D H	7907130264*	70-2623
STEVENSON, A E	7907160336*	COMMISSION
STEVENSON, M Q	7907250538	NUREQ
STEVENSON, R L	7907100735	70-1113
STEWART, R B	7907250412*	40-8729
STEWART, R B	7907250405*	40-8729
STEWART, W P	7907130499*	50-302 Q
STEWART, W P	7907180186	50-302 Q
STEWART, W P	7907230721*	50-302 Q
STEWART, W P	7907270401*	50-302 Q
STEWART, W P	7907100393	50-302 P
STEWART, W P	7907030452	50-302 S
STEWART, W P	7907030483	50-302 S
STEWART, W P	7907090232	50-302 S
STEWART, W P	7907180544	50-302 S
STEWART, W P	7907100515	50-302 P
STEWART, W P	7907130364	50-302 S
STEWART, W P	7907180518	50-302 S
STEWART, W P	7907190528	50-302 F
STEWART, W P	7907180548	50-302 S
STEWART, W P	7907190440	50-302 R
STEWART, W P	7907300344	50-302 S
STEWART, W P	7907300343	50-302 Q
STEWART, W P	7907030384	50-302 P
STEWART, W L	7907200394	50-280 S
STEWART, W L	7907060298*	50-280 S
STEWART, W L	7907090380*	50-280 S
STEWART, W L	7907090384*	50-280 S
STEWART, W L	7907310427*	50-280 S
STEWART, R C	7907050187*	50-482 Q
STEWART, R C	7907260561*	50-445 Q
STODDY, D G	7907240417	50-471 Q
STOHR, J P	7907030220*	FOIA
STOHR, J P	7907300050*	50-244 Q
STOICK, A F	7907060502	40-8663
STOLZ, K	7907190785	PR
STOLZ, J F	7907250051	50-368 P
STOLZ, J F	7907250061*	50-368 P
STOLZ, J F	7907250072*	50-368 P
STOLZ, J F	7907250080*	50-368 P
STOLZ, J F	7907300560	50-313 F
STOLZENBERG, M D	7907110187	FOIA
STONE, S T	7907270372	50-338 Q
STONE, R	7907250157	50-250 U
STODDLEY, D G	7907180334	50-471 Q
STODDLEY, D G	7907180829	50-471 Q
STODDLEY, D G	7907190582	50-471 Q
STODDLEY, D G	7907190587*	50-471 Q
STODDLEY, D G	7907190438	50-471 Q
STODDLEY, D G	7907120009	50-471 Q
STODDLEY, D G	7907240314	50-471 Q
STODDLEY, D G	7907240423*	50-471 Q
STOUT, J W	7907260424	50-217 P
STRAND, N O	7907030084*	50-397 Q
STRAND, N O	7907300114*	50-508 Q
STRATTON, L E	7907230771*	27-39
STRATHMAN, R A	7907170115*	50-336 S
STRATHMAN, R A	7907170229*	50-336 S
STREETER, J F	7907110136*	50-305 Q
STREETER, J F	7907180627*	50-358 Q
STREETER, J F	7907260300*	50-155 Q
STREETER, J F	7907300339*	50-263 Q
STREETER, J F	7907240191*	50-409 Q
STREETER, J F	7907240630*	50-305 Q
STRELOW, R	7907180691	PR
STRELOW, R	7907300238	PR
STROUPE, E P	7907250294	TOPREP
STURGEON, V L	7907260583*	50-592 Q
BULLIVAN, J W	7907030100	FOIA

# PERSONAL AUTHOR INDEX

42

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SULLIVAN, J. W.	7907060462	40-1739	THADANI, A.	7907120207	50-29 P
SULLIVAN, T. J.	7907130104	REG00	THOM, T.	7907170126*	50-259 R
SULLIVAN, T. J.	7907130034	REG00	THOMAS, J. L.	7907230478	50-297 P
SULLIVAN, T. J.	7907300014	REG00	THOMAS, E. B.	7907230077	50-220 P
SULLIVAN, R. F.	7907230790*	50-259 Q	THOMAS, G.	7907180091	50-320 P
SUMMERS, R. J.	7907100254	50-320 H	THOMAS, R. H.	7907260717*	50-213 B
SUTHERLAND, J. T.	7907130500*	50-302 Q	THOMAS, W. N.	7907250316	50-281 P
SUTHERLAND, J. T.	7907110583*	50-269 Q	THOMAS, R. D.	7907100546	50-320 H
SUTHERLAND, J. T.	7907160259*	70-143	THOMAS, C. O.	7907260890	50-356 A
SUTHERLAND, J. T.	7907180679*	50-280 Q	THOMPSON, D.	7907030118	50-320 B
SUTHERLAND, J. T.	7907200233	70-27	THOMPSON, D.	7907250481*	FOIA
SUTHERLAND, J. T.	7907230708	50-280 Q	THOMPSON, D.	7907250512*	FOIA
SUTHERLAND, J. T.	7907230623*	70-143	THOMPSON, D.	7907120162	50-320 B
SUTHERLAND, J. T.	7907260004	50-280 Q	THOMPSON, D.	7907170153	50-320 B
SUTHERLAND, J. T.	7907110589*	50-400 Q	THOMPSON, D.	7907130328	50-320 B
SUTHERLAND, J. T.	7907240132	50-553 Q	THOMPSON, D.	7907130342	50-320 H
SUTHERLAND, J. T.	7907130422	50-302 Q	THOMSEN, F. T.	7907090009	50-522 Q
SUTHERLAND, J. T.	7907270402*	50-302 Q	THOMSEN, F. T.	7907130344	50-522 Q
SUTHERLAND, J. T.	7907260532	50-327 Q	THOMSEN, F. T.	7907060125	50-522 Q
SUTHERLAND, J. T.	7907300021	50-280 Q	THOMSEN, F. T.	7907180619	50-522 Q
SUTHERLAND, J. T.	7907110574	50-269 Q	THOMSEN, F. T.	7907180629	50-522 Q
SUTHERLAND, J. T.	7907180652	50-280 Q	THOMSEN, F. T.	7907170138	50-522 H
SUTHERLAND, J. T.	7907230607	70-143	THOMSEN, L. H.	7907230057*	50-220 Q
SUTHERLAND, J. T.	7907300265	50-280 Q	THOMSEN, L.	7907270385*	50-320 Q
SUTHERLAND, J. C.	7907270393	50-302 Q	THORNBUROUGH, R.	7907060237*	COMMISSION
BUTTER, S. L.	7907030243	RES	THORNBUROUGH, H. D.	7907260139*	50-329 Q
BUTTER, S. L.	7907170197	NUREG	THORNBUROUGH, H. D.	7907180120	1&E
BUTTON, J. W.	7907280197*	QA999	THORNBUROUGH, H. D.	7907120681	FOIA
BUTTON, J. W.	7907240265*	QA999	THRASH, C. Q.	7907110342	50-466 Q
SWAN, W. B.	7907130443*	50-518 Q	THRASH, C. Q.	7907170701	50-466 Q
SWAN, W. B.	7907130225*	50-395 Q	THRASH, C. Q.	7907170823	50-466 Q
SWANBY, O. T.	7907300137	40-3453	THRUSH, J. E.	7907050040	50-320 P
SWANSON, D. O.	7907190391	NUREG	TIBBITTS, D. L.	7907110268	50-375 B
SWANSON, N. E.	7907100662	50-395 B	TILLISON, A. C.	7907060413*	50-324 B
SWANSON, D. T.	7903230309	50-70 Q	TILLISON, D. D.	7907110508	50-508 A
SWANSON, D. T.	7905150023	50-338 Q	TIPPEL, J.	7907250333*	50-295 Q
SWANSON, D. T.	7907110618	50-338 Q	TIPPEL, J.	7907250528	50-295 Q
SWANSON, D. T.	7907310566	50-338 Q	TOLALSTON, A. L.	7907230213*	50-295 Q
SWANSON, D. J.	7907170242	50-338 Q	TOLALSTON, A. L.	7907310800*	50-361 A
SWANSON, D. T.	7907130130	50-338 Q	TOLIAS, H. L.	7907060442	NUREG
SWANSON, E. R.	7907260526*	50-301 Q	TOLIN, W. J.	7907050155*	50-324 Q
SWANSON, E. R.	7907310189*	50-116 Q	TOLIN, W. J.	7907200241*	50-83 Q
SWEET, J. H.	7907160060*	COMMISSION	TOLIN, W. J.	7907300070*	70-1151
SWINGLE, K. F.	7907260228	PR	TOLLISON, A. C.	7907050329*	50-325 B
SYNAR, M.	7907310578*	COMMISSION	TOLLISON, A. C.	7907060409*	50-324 B
SZHAJIKOWSKI, R. W.	7907120449	70-1308	TOLLISON, A. C.	7907060412*	50-325 B
TADHAVI-TAFRESH	7907110734	NUREG	TOLLISON, A. C.	7907060416*	50-325 B
TAM, P.	7907110170	50-320 Q	TOLLISON, A. C.	7907090233*	50-324 B
TAM, P.	7907110236	50-320 Q	TOLLISON, A. C.	7907190487*	50-325 B
TAM, P.	7907050145	NUREG	TOLLISON, A. C.	7907130345*	50-325 B
TAMBLING, T.	7907020149*	50-346 Q	TOLLISON, A. C.	7907130363*	50-325 B
TAMBLING, T.	7907020076*	50-346 Q	TOLLISON, A. C.	7907160364*	50-324 B
TAMBLING, T.	7907180296*	50-346 Q	TOLLISON, A. C.	7907160400*	50-324 B
TAMPLIN, A. R.	7907280485*	70-2623	TOLLISON, A. C.	7907160381*	50-324 B
TAMPLIN, A. R.	7907280497*	70-2623	TOLLISON, A. C.	7907190382*	50-324 B
TAMPLIN, A. R.	7907280491*	70-2623	TOLLISON, A. C.	7907190534*	50-324 B
TANAKA, N.	7907240289	XPORTLIC	TOLLISON, A. C.	7907230320*	50-325 B
TARAB, D. N.	7907230238	XPORTLIC	TOLLISON, A. C.	7907230563*	50-324 B
TARAB, D. N.	7907260629	PRM	TOLLISON, A. C.	7907230618*	50-324 B
TARAB, D. N.	7907170110	NUREG	TOLLISON, A. C.	7907240363*	50-325 B
TASAKA, K.	7907020137	50-320 P	TOLLISON, A. C.	7907230343*	50-325 B
TAYLOR, R. E.	7907130175*	50-329 Q	TOLLISON, A. C.	7907240371*	50-324 B
TAYLOR, J. H.	7907230493*	50-244 Q	TOLLISON, A. C.	7907300428*	50-324 B
TAYLOR, J. H.	7907060249	TOPREP	TOMLINSON, D. P.	7907250226*	50-482 Q
TAYLOR, J. H.	7907100580	TOPREP	TOMLINSON, D. P.	7907050195*	50-298 Q
TAYLOR, J. H.	7907120589	50-320 Q	TOMLINSON, D. P.	7907300256*	50-445 Q
TAYLOR, J. H.	7907170021	TOPREP	TONGUE, T. H.	7907100445	50-320 H
TAYLOR, J. H.	7907180534	TOPREP	TOOHER, J. L.	7907190220*	50-437 Q
TAYLOR, J. H.	7907200288	TOPREP	TOOHER, J. L.	7907190215*	50-437 Q
TAYLOR, C. W.	7907090361	70-143	TOFF, A. B.	7907020481	40-8726
TAYLOR, R. Q.	7907110693*	50-445 Q	TORREY, M. D.	7907170167	NUREG
TAYLOR, R. Q.	7907250518*	50-445 Q	TOYERBIER, R. E.	7907030163*	FOIA
TAYLOR, R. Q.	7907300236*	50-445 Q	TOYH, A. B.	7907050527*	50-423 Q
TEASDALE, J. P.	7907120046	50-483 H	TOYH, A. B.	7907110015*	50-423 Q
TEATES, C. D.	7907240527	PRM	TOYH, D.	7907280507*	70-2623
TEDESCO, R. L.	7907020127	50-320 P	TOURTELLOTTE, J.	7907190673	70-2623
TEDESCO, R. L.	7907050405*	50-500 Q	TOWNSEND, O.	7907230538*	50-201 I
TEDESCO, R. L.	7907110022	50-320 P	TOWNSEND, O.	7907230521*	50-201 I
TEDESCO, R. L.	7907310581*	50-338 Q	TOWNSEND, O.	7907230517*	50-201 I
TELEGADAS, K.	7907020155	50-320 P	TOWNSEND, O.	7907300509*	50-201 I
TEMPLE, J. Q.	7907130102	50-329 T	TOWNSEND, O.	7907300513*	50-201 I
TERC, N.	7907230006*	50-387 Q	TOWNSEND, D.	7907300418*	50-201 I
TERPILAK, M. B.	7906210407	REG00	TRAHILL, T. R.	7907060345*	50-295 Q
TERPILAK, M. B.	7907240461	PRM	TRAHILL, C. H.	7907300868	50-344 P
TERPILAK, M. B.	7907260249	REG00	TRAHILL, C. H.	7907300154	50-266 P
TERRY, B. H.	7907240267*	50-294 Q	TRAHILL, C. H.	7907020236	50-344 P
THADANI, A.	7907020341	FOIA			

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TRAMMELL, C M	7907110082	50-344 P	ULLRICH, W T	7907190406	50-278 S
TRAMMELL, C M	7907300024	50-344 P	ULLRICH, W T	7907190331	50-277 S
TRAMMELL, C M	7907250071	50-344 P	ULMAN, M B	7907050393	50-300 Q
TRAMMELL, C M	7907300141	50-261 P	ULMAN, M B	7907030185	50-445 Q
TRAMMELL, C M	7907250094	50-301 P	ULMAN, M B	7907130517	50-344 Q
TRAUTVETTER, C	7907020459	71-168	ULMAN, M B	7907130164	50-445 Q
TRAVIS, C C	7907300282	REB	ULMAN, M B	7907180555	50-445 Q
TREASE, H W	7907230175	PR	UNDERHILL, D W	7907110004	50-320 D
TREBY, S A	7907190666*	70-1308	URBAN, M J	7907190479	50-592 Q
TRIBLE, P	7907230757*	50-280 U	URBAN, M J	7907030369	50-592 A
TRIMBLE, D C	7907060407	50-313 P	UTLEY, E E	7907020476	50-261 Q
TRIMBLE, D C	7907060417	50-313 Q	UTLEY, E E	7907100217	50-261 Q
TRIMBLE, D C	7907180225	50-313 Q	UTLEY, E E	7907190608	50-324 Q
TRIMBLE, D C	7907060411	50-368 Q	UTLEY, E E	7907190111	50-261 Q
TRIMBLE, D C	7907050098	50-368 S	UTLEY, E E	7907190578	50-261 Q
TRIMBLE, D C	7907030376	50-313 S	UTLEY, E E	7907190591	50-261 Q
TRIMBLE, D C	7907060322	50-313 S	UTLEY, E E	7907190368	50-324 Q
TRIMBLE, D C	7907050211	50-313 J	UTLEY, E E	7907190376	50-261 Q
TRIMBLE, D C	7907090278	50-313 R	UTLEY, E E	7907110406	50-324 P
TRIMBLE, D C	7907090289	50-368 S	UTLEY, E E	7907060176	50-261 P
TRIMBLE, D C	7907060321	50-320 P	UTLEY, E E	7907130379	50-324 P
TRIMBLE, D C	7907110573	50-313 P	UTLEY, E E	7907170020	50-261 S
TRIMBLE, D C	7907120645	50-368 S	UTLEY, E E	7907190376	50-261 Q
TRIMBLE, D C	7907160283	50-368 S	UTLEY, E E	7907270230	50-324 Q
TRIMBLE, D C	7907170125	50-313 P	VAHRENWALD, J	7907250283*	50-265 S
TRIMBLE, D C	7907190385	50-313 R	VAHRENWALD, J	7907110445*	50-254 S
TRIMBLE, D C	7907190541	50-368 R	VAHRENWALD, J	7907250378*	50-254 S
TRIMBLE, D C	7907200272	50-313 P	VALORE, C	7907180681	50-272 Q
TRIMBLE, D C	7907230349	50-313 S	VALORE, C	7907240231	50-272 Q
TRIMBLE, D C	7907230573	50-368 F	VAN BRUNT, E E	7907270405	50-528 Q
TRIMBLE, D C	7907300297	50-368 S	VAN BRUNT, E E	7907090239	50-528 Q
TRIMBLE, D C	7907310444	50-313 S	VAN BRUNT, E E	7907030370	50-592 D
TRIPP, L E	7907190306*	50-286 Q	VAN BRUNT, E E	7907120561	50-528 B
TRIPP, L E	7907190829*	50-387 Q	VAN BRUNT, E E	7907130426	50-592 B
TRIPP, L E	7907270381*	50-220 Q	VAN DOORN, P K	7907050103*	50-327 Q
TRIPP, L E	7907240615*	50-334 Q	VAN DOORN, P K	7907240186*	50-438 Q
TRIDJANAWSKI, R E	7907190428	50-320 H	VAN HOUTEN, R	7907180171	NUREQ
TROSTEN, L M	7907190371	PRQJ	VAN PELT, W R	7907180384	PR
TROUP, Q L	7907190447	50-320 H	VAN BICKEL, J	7907190574*	50-331 R
TROWBRIDGE, Q F	7907060052	50-400 Q	VAN BICKEL, J	7907200373*	50-331 B
TROWBRIDGE, Q F	7907160269	50-400 Q	VANDERHOLT, H E	7907110049*	50-320 Q
TROWBRIDGE, Q F	7907160275*	50-400 Q	VANDEL, T E	7907180481*	50-481 Q
TRZYNA, Q	7907110441*	50-295 S	VANMIDDLESWORTH	7907160208*	50-320 P
TULENKO, J S	7907180102*	50-320 P	VANN, J	7907190449	WASTE MGT
TURNER, E A	7907310618	50-498 Q	VANBICKEL, J	7907230389*	50-331 B
TURNER, E A	7907310607	50-498 Q	VANANINI, E E	7907260571*	COMMISSION
TURNER, E A	7907240125*	50-498 Q	VARGA, S A	7907160023*	50-269 Q
TURNER, E A	7907170147	50-498 B	VARGA, S A	7907160037*	50-307 Q
TURNER, E A	7907260657	50-498 B	VARGA, S A	7907160046*	50-312 Q
TUTHILL, S J	7907300094*	50-331 Q	VARGA, S A	7907160009	50-313 Q
TUTHILL, S J	7907300099*	50-331 Q	VARGA, S A	7907120209	50-322 A
TYLER, D A	7907190833	NUREQ	VARGA, S A	7907180241*	50-322 A
UDALL, M K	7907260489	50-320 U	VARGA, S A	7907050136	50-458 A
UDALL, M K	7907090668*	SECY	VARGA, S A	7907270281	50-397 A
UDALL, M K	7907110016*	50-320 D	VARGA, S A	7907110081	50-454 A
UHRIG, R E	7907090105	50-389 Q	VARGA, S A	7907310457	TOPREP
UHRIG, R E	7907060156	PR	VASSALLO, D B	7907030401*	50-500 Q
UHRIG, R E	7907190392	50-335 Q	VASSALLO, D B	7907050399*	50-500 Q
UHRIG, R E	7907090121	50-335 Q	VASSALLO, D B	7907050325*	50-400 Q
UHRIG, R E	7907060263	50-250 Q	VASSALLO, D B	7907310572*	50-338 Q
UHRIG, R E	7907180286	PR	VASSALLO, D B	7906260134	TOPREP
UHRIG, R E	7907190603	REG00	VASSALLO, D B	7907060466*	50-549 Q
UHRIG, R E	7907180280	50-250 Q	VASSALLO, D B	7907060066	50-443 I
UHRIG, R E	7907180180	50-250 Q	VASSALLO, D B	7907310441	50-482 H
UHRIG, R E	7907190094	50-250 Q	VASSALLO, D B	7907310005	50-339 A
UHRIG, R E	7907130305	50-250 Q	VASSALLO, D B	7907310468	50-404 A
UHRIG, R E	7907130321	50-335 Q	VASSALLO, D B	7907270001*	50-338 P
UHRIG, R E	7907130415	50-335 Q	VENTO, D F	7907160254*	COMMISSION
UHRIG, R E	7907240020*	50-250 Q	VERDEY, E H	7907260508*	50-250 Q
UHRIG, R E	7907190233	50-250 Q	VERDUZCO, Q H	7907050146*	50-267 Q
UHRIG, R E	7907090140	50-250 Q	VERRELLI, D M	7907110692	50-321 P
UHRIG, R E	7907190401	50-335 Q	VERRELLI, D M	7907230318	50-321 D
UHRIG, R E	7907190060	50-389 Q	VESELS, R D	7907190372	WASTE MGT
UHRIG, R E	7907190583	50-389 Q	VINARDI, Q B	7907300020	PR
UHRIG, R E	7907260035	50-250 P	VINCIGUERRA, J V	7907300434*	50-201 I
UHRIG, R E	7907190142	50-250 Q	VINJAMURI, K	7907300057	NUREQ
UHRIG, R E	7907310191	50-389 Q	VISING, Q	7907020269	50-313 P
UHRIG, R E	7907310184	50-389 Q	VIVIAN, W	7907190214*	50-16 P
UHRIG, R E	7907310199	50-389 Q	VOGEL, C E	7907060152	70-1151
UHRIG, R E	7907120599	50-389 A	VOGT-LOWELL, R J	7907090130*	50-335 Q
UHRIG, R E	7907090220	50-335 P	VOGT-LOWELL, R J	7907240184*	50-250 Q
UHRIG, R E	7907170170	TOPREP	VOGT-LOWELL, R J	7907180244*	50-366 Q
UHRIG, R E	7907240362	50-250 Q	VOIGHT, A F	7907240592	71-6601
UHRIG, R E	7907260661	50-250 F	VOIGHT, H H	7907050450	50-341 Q
ULLRICH, W T	7907190003	50-277 S	VOIGHT, H H	7907190139	50-452 Q
ULLRICH, W T	7907300115	50-277 S	VOIGHT, H H	7907050599	50-546 Q
ULLRICH, W T	7907190367	50-278 S			

# PERSONAL AUTHOR INDEX

4

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VOIGT, H. H.	7907190485	50-341 G	WEINSTEIN, P. P.	7907190678	PR
VOIGT, H. H.	7907050123	50-341 K	WEIR, G. J.	7907190775	PR
VOIGT, H. H.	7907200214	50-341 Q	WEISBARD, A. J.	7907190804	50-329 Q
VOIGT, H. H.	7907240354	50-482 H	WEISEMANN, R. A.	7907130245*	TOPREP
VOLKER, D. H.	7907090007*	50-201 U	WEISER, J. L.	7907100045	50-320 P
WACHTER, L. J.	7907020346	50-263 Q	WEISS, E. R.	7906220144	50-287 Q
WACHTER, L. J.	7907060250	50-263 Q	WEISS, E. R.	7906220168*	50-287 Q
WACHTER, L. J.	7907110291	50-282 Q	WEISS, E. R.	7907190178	FOIA
WACHTER, L. J.	7907100116	50-263 Q	WEISS, E. R.	7904110054	FOIA
WACHTER, L. J.	7907160148	50-282 Q	WEISS, E. R.	7906010118	FOIA
WACHTER, L. J.	7907300455	50-282 Q	WEISS, E. R.	7907190724	50-289 P
WAGNER, A. G.	7907270043*	50-364 Q	WEISS, E. R.	7907100039	FOIA
WAGNER, A. G.	7907230039*	50-338 Q	WEISS, E. R.	7907090410	FOIA
WAITE, R. T.	7907060203	70-1319	WEISS, E. R.	7907090442	FOIA
WALBRIDGE, W. C.	7907020293	50-312 Q	WEISS, E. R.	7907190259	50-320 P
WALBRIDGE, W. C.	7907180871	50-312 Q	WEISS, E. R.	7907190097	50-320 P
WALBRIDGE, W. C.	7907100509	50-312 P	WEISS, E. R.	7907050539	50-271 Q
WALKER, R. S.	7907160063*	COMMUNICATION	WEISSMAN, B. A.	7907090301	50-392 Q
WALKER, R. D.	7907240127*	50-373 Q	WEISS, D.	7907020473*	70-143
WALKER, R. D.	7907300486	50-237 Q	WEISS, D.	7907190026	71-4949
WALKER, R. D.	7907260822*	50-237 Q	WEISS, D.	7907090045	70-820
WALLACE, A.	7907060278	50-599 A	WEISS, D.	7907180480	70-2443
WALLACE, J. A.	7907110241	50-331 Q	WEISS, D.	7907180515	70-1151
WALLACE, J. J.	7907130438*	50-303 R	WEISS, D.	7907020478	70-824
WALLIS, G. B.	7907170136	NUREQ	WEISS, D.	7907230499*	71-6581
WALLIS, G. B.	7907170217	NUREQ	WEISS, D.	7907230496*	71-6581
WALTERS, D. K.	7907260151*	50-395 Q	WEISS, D.	7907230492	71-6581
WALTON, G. A.	7907100548	50-320 H	WEISS, E.	7907110718	ORQ
WALTON, G. A.	7907300385*	50-410 G	WELDEN, R. C.	7907180873	WASTE MGT
WAMBACH, T. V.	7907300357	50-213 P	WELLS, B. R.	7907020037	71-257
WAMBACH, T. V.	7907300572	50-244 P	WELLS, B. R.	7907020038*	71-257
WANDKE, N. E.	7907300506	50-295 P	WELT, Q.	7907250339*	QA999
WANDKE, N. E.	7907110440	50-295 S	WELT, Q.	7907250334*	QA999
WANDKE, N. E.	7907110435	50-295 S	WENNER, S.	7907120083	50-596 T
WANDKE, N. E.	7907250274	50-295 S	WENZINGER, E. C.	7907260498*	50-320 P
WANG, A.	7907300189	TOPREP	WERLING, J. A.	7907190117	50-334 P
WARD, W. H.	7907050369	50-482 A	WERLING, J. A.	7907090263	50-334 S
WARD, W. H.	7907090321	50-482 A	WERLING, J. A.	7907090265*	50-334 S
WARD, J. O.	7907270065	PRM	WERLING, J. A.	7907110446	50-334 S
WARD, E. C.	7907030272	50-282 R	WERLING, J. A.	7907110447*	50-334 S
WARD, E. C.	7907090202	50-282 S	WERLING, J. A.	7907170108	50-334 S
WARD, K. D.	7907050117*	50-305 Q	WERLING, J. A.	7907170111*	50-334 S
WARD, K. D.	7907180357*	50-454 Q	WERLING, J. A.	7907170114*	50-334 S
WAREMBOURG, D.	7907050351	50-267 P	WERLING, J. A.	7907270229	50-334 S
WAREMBOURG, D.	7907060212	50-267 R	WESCOTT, H. H.	7907180451*	50-451 Q
WAREMBOURG, D.	7907120692	50-267 S	WESCOTT, H. H.	7907260169*	50-341 Q
WAREMBOURG, D.	7907120101	50-267 R	WESMAN, R. H.	7906200127*	50-269 Q
WAREMBOURG, D.	7907170156	50-267 P	WESCOTT, J. M.	7907261011*	50-461 Q
WAREMBOURG, D.	7907180487	50-267 P	WESTERMAN, T. F.	7907050145*	50-267 Q
WAREMBOURG, D.	7907130388	50-267 S	WESTERMAN, T. F.	7907050168*	50-267 Q
WAREMBOURG, D.	7907180442	50-267 S	WESTERMAN, T. F.	7907270118*	50-267 Q
WAREMBOURG, D.	7907180568	50-267 S	WESTERMAN, T. F.	7907300484*	50-298 Q
WAREMBOURG, D.	7907200264	50-267 P	WESTERMAN, T. F.	7907120007*	50-313 Q
WARNICK, R. F.	7907270407*	50-315 Q	WESTERMAN, T. F.	7907020206	50-285 Q
WARNICK, R. F.	7907240200*	50-282 Q	WETHY, C. M.	7907090280	50-335 S
WARNICK, R. F.	7907250083*	50-266 Q	WETTERHAHN, M. J.	7907170237	50-358 Q
WARNICK, R. F.	7907270133*	50-263 Q	WETTERHAHN, M. J.	7907060471	50-272 Q
WARNICK, R. F.	7907240112*	50-301 Q	WETTERHAHN, M. J.	7907130309	50-272 Q
WARNICK, R. F.	7907100390	50-320 H	WETTERHAHN, M. J.	7907130314*	50-272 Q
WARNICK, R. F.	7907180411*	50-255 Q	WETTERHAHN, M. J.	7907240235	50-272 Q
WARNICK, R. F.	79072310222*	50-358 Q	WETTERHAHN, M. J.	7907240283*	50-272 Q
WASSERBACH, A. E.	7907120332*	50-280 R	WETTERHAHN, M. J.	7907240291*	50-272 Q
WATFORD, M. L.	7907130456*	50-261 H	WHARTON, R. J.	7907170253	50-361 Q
WATSON, B.	7907050193*	50-546 H	WHEELER, L. N.	7907120399	50-94 J
WATSON, E. C.	7907110235*	70-364	WHITEBELL, D. E.	7907130292	71-6698
WATSON, A. P.	7907300282	REG	WHITE, B. G.	7907190834	50-445 H
WATT, J. J.	7907190199*	FOIA	WHITE, J. A.	7907110454	TOPREP
WATTERHAHN, M. J.	7907110423	50-358 Q	WHITE, W. H.	7907300375*	50-16 R
WATTERHAHN, M. J.	7907110428*	50-358 Q	WHITE, W. H.	7907300362	50-16 R
WATTS, J.	7907110526	50-341 K	WHITE, J. Q.	7907190586	50-466 Q
WEAVER, J.	7907110079*	50-320 Q	WHITE, L. D.	7907050228	50-244 Q
WEAVER, J.	7907110086*	50-320 Q	WHITE, L. D.	7907050396	50-244 Q
WEBB, R. E.	7907260721*	50-320 P	WHITE, L. D.	7907050230	50-244 Q
WEBSTER, A.	7907020497*	50-556 H	WHITE, L. D.	7907260481	50-244 Q
WEBSTER, A.	7907020502*	50-556 H	WHITE, L. D.	7907300389	50-244 Q
WEBSTER, E. W.	7907260225	PR	WHITE, L. D.	7907030477	50-244 P
WEBSTER, E. H.	7907250147*	50-335 Q	WHITE, L. D.	7907050361	50-244 F
WEBSTER, E. H.	7907050071*	50-338 Q	WHITE, L. D.	7907110334	50-244 F
WEEKS, E. D.	7907180402	50-133 R	WHITE, L. D.	7907060441	50-244 Q
WEEKS, J. R.	7907260412*	50-272 Q	WHITE, L. D.	7907090253	50-244 P
WEIGAND, J. Q.	7907260763	50-458 S	WHITE, L. D.	7907090268*	50-244 P
WEIMER, J. A.	7907260562	50-320 P	WHITE, L. D.	7907050234	50-244 P
WEIMER, J. A.	7907260546	50-320 P	WHITE, L. D.	7907120594	50-244 P
WEIMER, J. A.	7907260567	50-320 P	WHITE, L. D.	7907130250	50-244 P
WEINER, B. H.	7907240317*	50-471 Q	WHITE, L. D.	7907160401	50-244 S
WEINSTEIN, S.	7907120632	50-522 A	WHITE, L. D.	7907200236	50-244 P
			WHITE, L. D.	7907200236*	50-244 P

## PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WHITE, L. D.	7907260594	50-244 S	WITHERS, B. D.	7907110422	50-344 S
WHITENER, H. L.	7907090071*	50-338 Q	WITHERS, B. D.	7907120608	50-344 R
WHITENER, H. L.	7907060454*	50-269 H	WIFFORD, A. W.	7907180547	50-322 A
WHITENER, H. L.	7907130359*	50-327 Q	WOLF, W.	7907260213	PR
WHITESELL, D. E.	7907130213*	QA999	WOLF, J. F.	7907120249	50-295 T
WHITESELL, D. E.	7907100733*	QA999	WOLF, J. F.	7907120201	50-295 T
WHITESELL, D. E.	7907250197*	QA999	WOLF, J. F.	7907300184	50-295 T
WHITESELL, D. E.	7907030039*	QA999	WOLF, J. F.	7907200228	50-261 Q
WHITESELL, D. E.	7907250102*	QA999	WOLFE, S. J.	7907100650	50-437 Q
WHITESELL, D. E.	7907190742*	QA999	WOLFE, S. J.	7907050057*	50-556 A
WHITESELL, D. E.	7907250154*	QA999	WOLFE, S. J.	7907020009	50-466 Q
WHITESELL, D. E.	7907240265*	QA999	WOLFE, S. J.	7907190114	50-466 Q
WHITESELL, D. E.	7907260090*	QA999	WOLFE, S. J.	7907060495	50-556 Q
WHITMORE, H. E.	7907100627*	50-128 I	WOLFE, S. J.	7907050033	50-556 A
WHITNER, C. F.	7907100943	50-321 P	WOLFE, S. J.	7907020001	50-466 Q
WHITNER, C. F.	7907050357	50-321 I	WOLFE, S. J.	7907190481	50-448 H
WHITNER, C. F.	7907120301	50-366 P	WOLFE, S. J.	7907190490	50-466 Q
WHITNER, C. F.	7907170066	50-321 P	WOLFF, T. A.	7907130457	40-8725
WHITNER, C. F.	7907260691	50-321 P	WOLFSON, J. L.	7907050030	50-320 P
WHITNER, C. F.	7907260746	50-366 P	WOLLETT, S. A.	7907190755	CONTRACT
WHITNEY, O. O.	7907270187	50-366 P	WOLLETT, S. A.	7907190795	CONTRACT
WHITNEY, O. O.	7907200252*	50-293 R	WOLLETT, S. A.	7907250232	CONTRACT
WHITTEMORE, F. C.	7907090401	50-322 Q	WOLLETT, S. A.	7907310051	CONTRACT
WHITTEMORE, F. C.	7907180741	50-322 Q	WOLLETT, S. A.	7907230719	CONTRACT
WHITTEMORE, F. C.	7907180761	50-322 Q	WOLMAN, A.	7907300444*	50-201 I
WHITT, W.	7907030140*	50-298 Q	WOLTNER, E.	7907130050*	70-1100
WIDNER, H. A.	7907190243	50-321 Q	WOLTNER, E.	7907240297*	70-33
WIGGINS, E.	7907260924	CONTRACT	WONG, B. M.	7907260300*	50-155 Q
WIGGINS, E.	7907250590	CONTRACT	WONG, B. M.	7907180455*	50-254 Q
WIGGINS, E.	7907260849	CONTRACT	WONG, B. M.	7907300491	50-254 Q
WIGGINS, E.	7907260789	CONTRACT	WOOD, E. C.	7907110361	50-309 S
WIGGINS, E.	7907260769	CONTRACT	WOODHEAD, C. P.	7907180113	50-219 Q
WIGGINS, E.	7907310073	CONTRACT	WOODHEAD, C. P.	7907200240	50-466 Q
WIGGINTON, D.	7907240493*	50-315 P	WOODY, D. E.	7907170116	50-309 R
WIGGINTON, D.	7907180710	50-334 P	WOOLEVER, E. J.	7907050398	50-412 Q
WIGGINTON, D.	7907250087	50-334 P	WOOLEVER, E. J.	7907230452*	50-412 Q
WIGGINTON, D.	7907180194	50-334 P	WOOLEVER, E. J.	7907170162	50-412 Q
WIGGINTON, D.	7907250611	50-315 P	WOOLEVER, E. J.	7907130410	50-334 P
WIKEEN, D. B.	7907120830	PR	WOOLEVER, E. J.	7907180829	50-412 S
WILCOX, W. H.	7907300475*	COMMISSION	WOOLETT, S. A.	7907180316	CONTRACT
WILCOX, J. D.	7907090438*	50-281 Q	WOOTON, R. O.	7907260716*	50-320 P
WILSON, P.	7907230180*	COMMISSION	WORSHAM, J. I.	7907020005	50-445 M
WILL, R. C.	7907190496	WASTE MOT	WRAY, J. R.	7907100477	50-320 H
WILL, R. C.	7907180360	PR	WRIGHT, S. F.	7907190420	NUREQ
WILLEY, W. R.	7907030240	50-592 A	WRIGHT, H. D.	7907130251*	QA999
WILLENSEN, B.	7907250313*	50-265 S	WRIGHT, H. D.	7907130246*	QA999
WILLIAMS, J. F.	7907300275	PR	WRIGHT, H. D.	7907130228*	QA999
WILLIAMS, L. E.	7907230138	PR	WRIGHT, R. L.	7907100238	50-346 P
WILLIAMS, P. R.	7907260659	PRM	WRIGHT, B. L.	7907060290	XPORTLIC
WILLIS, C. A.	7907260382	REQD	WRIGHT, R. H.	7907050143*	50-438 Q
WILLIAM, D.	7907300384	FOIA	WRIGHT, R. H.	7907260142*	50-553 Q
WILLIAMS, D. H.	7907120601	50-368 P	WRIGHT, G. C.	7907240127*	50-373 Q
WILLIS, E.	7907170031*	50-324 R	WRIGHT, G. C.	7907180411*	50-255 Q
WILLIAMS, M. O.	7907170057*	50-298 S	WU, B. J. C.	7907110483	RES
WILLIAMS, M. O.	7907170065*	50-298 S	WULLER, G. E.	7907190250	50-461 Q
WILLIAMS, F. J.	7907160237	50-316 Q	WYATT, J. H.	7907060012	50-382 H
WILLIAMS, F. J.	7907160377*	50-313 Q	YAEGER, H. E.	7907090337	50-250 S
WILLIAMS, F. J.	7907160177	50-336 Q	YBARRONDO, L. J.	7907110316	RES
WILLSE, J. T.	7907260541	50-320 P	YIN, E. T.	7907300071*	50-255 Q
WILLSEY, H. B.	7907120361	50-277 P	YIN, I. T.	7907130354*	50-315 Q
WILSON, W. E.	7907170123	50-27 P	YIN, I. T.	7907180382*	50-282 Q
WILSON, T. L.	7907260535	50-320 P	YOBBAQV, J. J.	7907230200	PR
WILSON, T. L.	7907260568	50-320 P	YORE, J. R.	7907060370	50-514 Q
WILSON, B. D.	7907030297	XPORTLIC	YOUNG, R. H.	7907090306*	50-245 S
WILSON, B. D.	7907120394	XPORTLIC	YOUNG, R. H.	7907200259*	50-245 R
WILSON, B. D.	7907110744	XPORTLIC	YOUNG, F. W.	7907110404	50-320 A
WILSON, B. D.	7907230521	XPORTLIC	YOUNG, H. W.	7907100524	50-320 H
WILSON, B. D.	7907230656	XPORTLIC	YOUNG, T.	7907270141*	50-275 Q
WILSON, B. D.	7907300025	XPORTLIC	YOUNG, T.	7907270280*	50-275 Q
WILSON, F.	7907250573*	FOIA	YOUNG, T.	7907060523	50-382 Q
WILSON, K. R.	7907110340*	50-269 S	YUAN, Y.	7907270366	NUREQ
WILSON, K. R.	7907110450*	50-270 S	YUHAS, G. P.	7907110460*	50-245 Q
WILSON, K. R.	7907110357*	50-269 S	YUSPEH, A. R.	7907090393	50-387 C
WILSON, K. R.	7907110393*	50-269 S	YUSPEH, A. R.	7907060523	50-382 Q
WILSON, K. R.	7907110382*	50-269 S	YUSPEH, A. R.	7907130157	50-387 Q
WILSON, F. R.	7907120635	50-344 J	YUSPEH, A. R.	7907240335	50-387 Q
WILSON, J.	7907170004*	50-280 R	ZADINA, E.	7907190756	PR
WILSON, J. N.	7907120241*	50-322 A	ZARAKAS, P.	7907300457	50-247 Q
WILSON, J. N.	7907110524	50-322 F	ZAROLIA, B. M.	7907120734	50-320 P
WILSON, J. N.	7907110276	50-322 A	ZAVADOSKI, R. W.	7907270406*	50-302 Q
WIRTH, S.	7907180298	50-10 H	ZEBRAK, I. L.	7907110708	50-596 Q
WISLA, S. F.	7907260577	71-6601	ZECH, Q. Q.	7907230208*	50-295 Q
WISOFF, C. P.	7907190521	PR	ZECH, Q. Q.	7907230239*	50-295 Q
WISSINK, R. O.	7907270058	PRM	ZECH, Q. Q.	7907260403*	50-272 Q
WISSINK, R. O.	7907090241	REQD	ZECH, Q. Q.	7907190674	50-272 P
WITHERS, B. D.	7907050370	50-344 S	ZECH, Q. Q.	7907180203	50-272 Q
			ZEFF, D. W.	7907060120	70-1201

# PERSONAL AUTHOR INDEX

431

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ZEFF, D W	7907060410	70-1201
ZEFF, D W	7907300243	70-1201
ZEFF, D W	7907250060	71-9019
ZEHMS, E H	7907190391	NUREG
ZELAC, R E	7907310101	PR
ZOLICZYNSKI, J B	7907030249*	50-59 R
ZOLICZYNSKI, J	7907090317*	50-59 P
ZIELEN, A J	7907270366	NUREG
ZIEMANN, D L	7907060072	50-29 P
ZIEMANN, D L	7907060496	50-219 P
ZIEMANN, D L	7907310559	50-206 P
ZIEMANN, D L	7907310560	50-29 P
ZIEMANN, D L	7907060498	50-255 P
ZIEMANN, D L	7907060217	50-255 P
ZIEMANN, D L	7907060221*	50-255 P
ZIEMANN, D L	7907060230*	50-255 P
ZIEMANN, D L	7907060233	50-244 P
ZIEMANN, D L	7907110637	50-255 P
ZIEMANN, D L	7907100009	50-219 P
ZIEMANN, D L	7907100012*	50-219 P
ZIEMANN, D L	7907110480	50-219 P
ZIEMANN, D L	7907130134	50-219 P
ZIEMANN, D L	7907130140*	50-219 P
ZIEMANN, D L	7907130154*	50-219 P
ZIEMANN, D L	7907120169	50-245 P
ZIEMANN, D L	7907120179*	50-245 P
ZIEMANN, D L	7907120199*	50-245 P
ZIEMANN, D L	7907190796	50-409 P
ZIEMANN, D L	7907190807	50-244 P
ZIEMANN, D L	7907190759	50-255 P
ZIEMANN, D L	7907290145	50-10 P
ZIEMANN, D L	7907310226	50-244 P
ZIEMANN, D L	7907310231	50-245 P
ZIEMANN, D L	7907310264	50-219 P
ZIEMANN, D L	7907310267	50-409 P
ZIEMANN, D L	7907310273	50-155 P
ZIEMANN, D L	7907310278	50-213 P
ZIEMANN, D L	7907310281	50-29 P
ZIEMANN, D L	7907310287	50-206 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ZIEMANN, D L	7907110723	50-213 P
ZIEMANN, D L	7907110623	50-155 P
ZIEMANN, D L	7907110631	50-10 P
ZIEMANN, D L	7907110647	50-409 P
ZIEMANN, D L	7907110651	50-244 P
ZIEMANN, D L	7907110658	50-206 P
ZIEMANN, D L	7907110661	50-29 P
ZIEMANN, D L	7907110666	50-219 P
ZIEMANN, D L	7907110673	50-245 P
ZIEMANN, D L	7907110676	50-213 P
ZIEMANN, D L	7907110682	50-219 P
ZIEMANN, D L	7907250308	50-244 P
ZIEMANN, D L	7907250312*	50-244 P
ZIEMANN, D L	7907250322*	50-244 P
ZIEMANN, D L	7907250176	50-10 P
ZIEMANN, D L	7907250179	50-155 P
ZIEMANN, D L	7907250179	50-213 P
ZIEMANN, D L	7907250181	50-409 P
ZIEMANN, D L	7907250183	50-219 P
ZIEMANN, D L	7907250185	50-245 P
ZIEMANN, D L	7907250186	50-244 P
ZIEMANN, D L	7907250187	50-206 P
ZIEMANN, D L	7907250188	50-29 P
ZIEMANN, D L	7907300030	50-206 P
ZIEMANN, D L	7907300033*	50-206 P
ZIEMANN, D L	7907300035*	50-206 P
ZIMA, O E	7907250514	NUREG
ZIMMER, Q A	7907110483	REB
ZIMMERMAN, R P	7907200469*	50-293 Q
ZITTEL, H E	7907090429	REB
ZITTEL, H E	7907120082	REB
ZITTEL, H E	7907300368	REB
ZUBER, Z	7907240480	TOPREP
ZUDANG, Z	7907090244	ACRB
ZUDANG, J J	7907230268*	50-295 Q
ZUDANG, J J	7907230361*	50-295 Q
ZUFELT, E	7907100609*	50-333 R





# CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
<b>CITIZEN GROUP/INDIVIDUAL/MEDIA</b>		
American Friends Service Committee	7907250458*	50-320 P
Sassafraz Audubon Society	7907100559	50-546 Q
Citizens Against Nuclear Dangers	7907240298	50-387 Q
	7907240303*	50-387 Q
	7907240298	50-387 Q
	7907240303*	50-387 Q
	7907180664	50-387 Q
Citizens Association for Sound Energy	7907180768	50-445 Q
Citizens for a Better Environment	7907130276	50-295 Q
CBB News, CBB, Inc	7907200246	50-320 P
	7907200243	50-320 P
	7907200218	50-320 P
Citizens Concerned About Nuclear Power, Inc.	7907120002	50-498 Q
	7907120004*	50-498 Q
	7907120002	50-498 Q
	7907120004*	50-498 Q
Concerned Citizens of Rhode Island	7907180870	50-548 H
Citizens for Energy & Employment	7907020479	50-341 Q
	7907020480*	50-341 Q
Carolina Environmental Study Group	7907190065*	70-2623
	7907180762	70-2623
	7907190593	70-2623
Citizens for Fair Utility Regulation	7907170243	50-445 Q
	7907180612	50-445 Q
	7907170243	50-445 Q
	7907180612	50-445 Q
	7907160207	50-445 Q
Citizens Energy Forum	7907180638	50-338 Q
	7907130331	50-338 Q
	7907160156	50-338 Q
	7907170254	50-338 Q
	7907060438	50-338 Q
	7907060444*	50-338 Q
	7907060438	50-338 Q
	7907060444*	50-338 Q
	7907180606	50-338 Q
Intervenor Cleston	7907110653	50-471 Q
Civil Liberties Union, New York, Cornell Chapter	7907020132	FOIA
Coalition for Safe Power	7907280171	50-344 Q
	7907280295	50-344 Q
DeKalb Area Alliance for Responsible Energy	7907190645	50-434 Q
Deseret News Salt Lake City, UT	7907020098	FOIA
Doc-Search Associates	7907190437	FOIA
Intervenor J.F. Doherty	7907110073	50-466 Q
	7907190658	50-466 Q
	7907190664*	50-466 Q
	7907190671*	50-466 Q
	7907190736*	50-466 Q
	7907190083	50-596 Q
Ecology Action of Oswego	7907240235	50-596 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Environmental Coalition on Nuclear Power	7907100715	50-272 Q
	7907060452	50-387 Q
	7907300447	50-289 Q
Environmental Defense Fund	7907180277	50-592 Q
	7907030240	50-592 A
The Evening & Sunday Bulletin, Philadelp hia, PA	7907020137	50-320 P
Iowa Socialist Party	7907110610	50-599 Q
Island Closeup News Service	7907250385	50-322 A
Jefferson Pilot Broadcasting	7907250394	50-287 V
KRON TV	7907090320	50-312 Q
Little Egypt Prairie Alliance	7907060146	FOIA
Mid-America Coalition for Energy Alternatives	7907030369	50-482 A
	7907090321	50-482 H
Marrack, D., Intervenor	7907110358	50-466 Q
Miami Valley Power Project	7907110475*	50-358 Q
	7907110131	50-358 Q
	7907190136*	50-358 Q
	7907190152*	50-358 Q
	7907190158*	50-358 Q
Mid-Hudson Nuclear Opponents, Inc.	7907060506	50-556 Q
	7907160169	50-596 Q
North Anna Environmental Coalition	7907180827*	50-338 Q
NBC, Inc., NBC Television Stations Div.	7907250499	FOIA
Natural Resources Defense Council	7907090043*	SECY
	7907160150*	70-143
	7907160137*	COMMISBION
	7907090049*	SECY
	7907160134*	70-143
	7907030314*	FOIA
	7907190734	FOIA
	7907030112	FOIA
	7907030274	FOIA
	7907060222	70-2623
	7907060228*	70-2623
	7907110486	50-237 Q
	7907200203*	50-237 Q
	7907060037*	70-2623
	7907060019	70-2623
	7907060024*	70-2623
	7907060028*	70-2623
	7907060033*	70-2623
	7907250507*	70-2623
	7907200185	50-237 Q
	7907250480*	70-2623
	7907250485*	70-2623
	7907250497*	70-2623
	7907110109	70-2623
	7907110119*	70-2623
	7907110134*	70-2623
	7907110243	70-2623
	7907110265*	70-2623
	7907110297*	70-2623
	7907160287*	70-2623
	7907250475	70-2623

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907250491*	70-2623		7907050093*	QA999
	7907250519*	70-2623	Burns & Roe Co	7906210231*	50-397 A
	7907140280	70-2623		7906210234*	50-397 A
	7907190625	70-2623	Certified Testing Laboratories, Inc	7907060009	71-66
	7907190638	70-2623		7907060011*	71-66
	7907250435*	FOIA	Coastal Science Associates	7907120783	50-320 P
	7907190677	FOIA	Consolidated X-Ray Service, Inc	7907050412	71-181
Mark Oncavage	7907250184*	50-230 U		7907050416*	71-181
	7907250173*	50-250 U	Creare, Inc	7907050520	RES
Prairie Alliance	7907030116	50-461 A	CTL Engineers, Inc	7907190740	PR
	7907190165	50-461 A	Ebasco Services, Inc (subs of Enserch Corp.)	7907230173*	COMMISSION
	7907030116	50-461 A		7907260011	50-382 K
	7907190166	50-461 A			
Palmetto Alliance	7907090445*	50-269 O	EQ & Q, Inc.	7907110113	RES
Pollution Environmental Problems	7907030142	50-295 P		7907110185	50-320 P
Public Interest Research Group	7907090459*	50-466 O		7907090443	RES
Potomac Alliance	7907120335*	50-280 O		7907110149	RES
	7907120356*	50-280 O		7907050359*	REVIEW QRP
	7907120355*	50-280 O			
	7907120356*	50-280 O		7907090137	RES
	7907060501	50-338 O		7907110316	RES
	7907180256	50-338 O		7907190691	RES
	7907180265*	50-338 O		7907300464	50-320 P
	7907180265*	50-338 O		7907310320	RES
	7907180271*	50-338 O	Elbert P. Epler	7907050460	ACRS
	7907180279*	50-338 O	W. L. Fauth & Associates, Inc	7907020106	FOIA
	7907180256	50-338 O	Fox Consulting Engineers & Geologists,	7907060132	40-4492
	7907180265*	50-338 O	F. M. Fox & Associates		
	7907180271*	50-338 O	Henry Pratt Co	7907120734	50-320 P
	7907180279*	50-338 O	Ichthyological Associates, Inc	7907090469*	50-320 P
	7907060457	50-338 O			
	7907060454*	50-338 O	Information & Communication Applications,	7907100228	50-320 R
	7907060457	50-338 O	Inc	7907060094*	COMMISSION
	7907060454*	50-338 O	International Generation & Transmission Co., Inc	7907110497*	PROJ
	7907130368	50-338 O			
	7907130371*	50-338 O	KMC, Inc	7907110488	PROJ
	7907250085	50-338 O		7907090157*	SECV
	7907180744	50-338 O			
Safe Energy for New Haven	7907160106	50-596 O	Marsh & McLennan, Inc	7907230201*	COMMISSION
	7907160113*	50-596 O	Maryland Shipbuilding & Drydock Co	7907090295	50-320 J
	7907160106	50-596 O		7907190021*	71-31
	7907160113*	50-596 O	Nuclear Assurance Corp	7907190017	71-31
Salem County Board of Chosen Freeholders	7907250039*	50-272 H		7907300208*	71-6698
Sierra Club	7907230246*	50-201 P			
	7907180778	50-201 S		7907130232*	70-2623
Slagitionians Concerned About Nuclear Plants	7907060489	50-522 O	Nuclear Engineering Co., Inc (subs of Teledyne, Inc.)	7907300200	71-6698
Silver Lake News Pembroke, MA	7907250404	50-293 P	New York Testing Laboratories, Inc	7907300203*	71-6698
San Luis Obispo Mothers for Peace	7907130347	50-275 O		7907250599*	FOIA
St. John the Baptist Parish Police Jury	7907250026	50-382 O	Nuclear Services Corp		
	7907060136	50-289 P	NUS Corp	7907060351*	50-295 O
The Sun Baltimore, MD	7907060314*	50-346 O		7907180636	FOIA
Toledo Coalition for Safe Energy	7907130513	50-346 O	ORI, Inc	7907110526	50-341 K
	7907130515*	50-346 O	Pan American World Airways, Inc	7907020143	FOIA
	7907130521*	50-346 O	Pioneer Nuclear, Inc.	7907180732	71-96
	7907240512*	50-466 O		7907250412*	40-8729
Texas Public Interest Research Group	7907050516	50-466 O		7907250405*	40-8729
	7907090452	50-466 O	Plateau Resources, Ltd.	7907250399	40-8729
	7907110496	50-466 O		7907130100	PR
	7907240503*	50-466 O		7907180836	40-8698
	7907180836	50-466 O		7907310221	40-8698
	7907190696	50-466 O	Q C Services, Inc	7907020460	71-175
	7907190112	50-320 P		7907020462*	71-175
Trends Publishing, Inc.	7907020091	50-22 P	H. Monroe Radley	7907300500*	50-201 I
Tribune-Review Greenburg, PA	7906220164	50-287 O	Ramsay Engineering Company	7907270107	XPORTLIC
Union of Concerned Scientists				7907240223	XPORTLIC
	7906220168*	50-287 O			
United Press International	7907190178	FOIA	Rocky Mountain Energy Co.	7907240277*	XPORTLIC
U.S. News & World Report	7907060157	70-1193		7907240331	40-8432
Utility Users for Reasonable Rates	7907160060*	COMMISSION	Scientific Associates, Inc	7907100096	40-8432
	7907050086*	50-272 O	Bergent & Lundy, Inc.	7907190483	NUREG
				7907050377	QA999
ENGINEERING/CONSTRUCTION/CONSULTANTS/SERVICES			Scallop Corp., Scallop Materials Service Div	7907090415	XPORTLIC
ACE Federal Reporters, Inc	7907310474	50-336 O		7907090423*	XPORTLIC
	7907200482	ACRS	Space Science Services, Inc	7907030162	71-215
Aerospace Corp	7907190391	NUREG		7907030168*	71-215
Allied - General Nuclear Services	7907120308	50-332 S	Stone & Webster, Inc	7907230330	50-493 K
Approach Fish, Inc	7907190852*	REQDB			
Aramco Services Co	7907110739	XPORTLIC	Tech/Ops (Technical Operations, Inc.)	7907230374*	50-493 K
Bechtel Power Corp (subs of Bechtel Corp.)	7907230059*	QA999	United Engineers & Constructors, Inc (subs. of Raytheon Co.)	7907120171*	RES
	7907260683*	50-361 A	Universal Testing Labs, Inc.	7907020456	71-279
	7907260677*	50-361 A		7907020457*	71-279
	7907260689*	50-361 A			
	7907260677*	50-361 A	Urban Systems Research & Engineering, Inc.	7907310622*	71-279
Bechtel Associates Professional Corp.	7907250324*	50-329 S		7907310613	71-279
Billings Energy Corp	7907160094	50-320 P	United States Testing Co., Inc.	7907120632	50-322 A
Black & Veatch	7907050097*	QA999	Woodward-Clyde Consultants	7907190756	PR
				7907190422	WASTE MGT
				7907260471*	50-361 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
<b>EDUCATIONAL INSTITUTIONS</b>					
Clemson Univ	7907250582*	27-47	Texas, Univ of	7907170186	50-192 J
Cornell Univ	7907110036	PR	Tennessee, Univ of	7907160208*	50-320 P
Dartmouth College	7907170136	NUREQ	Virginia, Univ of	7907270153	PR
	7907190254	NUREQ	Utah, Univ. of	7907240327	PRM
	7907170217	NUREQ		7907230190	PR
Duke Univ	7907060164	PR	Washington, Univ of	7907170239	ACRB
Georgia Institute of Technology	7907240532	PRM	Wisconsin, Univ of, Madison	7907190330	WASTE MGT
Iowa State Univ	7907270056	PRM	Vanderbilt Univ	7907190205	NUREQ
Johns Hopkins Univ	7907240532	71-6601	Worcester Polytechnic Inst	7907200311	50-134 P
	7907190785	PR	Washington Univ	7907050030	50-320 P
Lehigh Univ	7907110727	50-219 P	Washington State Univ	7907170123	50-27 P
Michigan State Univ	7907270147	PR	West Virginia Univ	7907180298	PR
	7907240267*	50-294 Q	Yale Univ	7907110024	PR
	7907200497	PRM			
	7907300275	PR	<b>FOREIGN GOVERNMENTS AND AGENCIES</b>		
Mississippi State Univ	7907270158	PR	Canada, Atomic Energy Control Board	7907200479*	50-320 H
Massachusetts Institute of Technology	7907230107*	70-93B		7907100043	XPORTLIC
	7907100632	50-20 S	European Communities, Commission of	7907030337*	XPORTLIC
	7907110528	50-20 S		7907130234	XPORTLIC
North Carolina State Univ	7907230478	50-297 P		7907130240*	XPORTLIC
Notre Dame, Univ of	7907190678	PR		7907030196	XPORTLIC
Oregon State Univ	7907180559	50-243 P		7907030333	XPORTLIC
	7907180570*	50-243 P		7907130508	XPORTLIC
Pennsylvania State Univ	7907030163*	FOIA		7907120047	XPORTLIC
	7907260635	PRM		7907110701	XPORTLIC
	7907130420	50-5 F		7907090408	XPORTLIC
Purdue Univ	7907270167	PR		7907300165	XPORTLIC
New York, State Univ of, Buffalo	7907200400*	50-57 Q		7907310103	XPORTLIC
	7907020485	70-267		7907310113	XPORTLIC
	7907310486	71-226	Japan	7907300162	XPORTLIC
New York, State Univ of, Stony Brook	7907200507	PRM		7907090437*	50-320 P
New York, State Univ of	7907190326	NUREQ	Sweden	7907300294	XPORTLIC
	7907190374	NUREQ		7907300304	XPORTLIC
	7907190420	NUREQ	Thailand	7907060026*	50-320 P
	7907190433	NUREQ			
			<b>LEGAL/LAW FIRMS/INSURANCE COMPANIES</b>		
Temple Univ	7907310101	PR	Abbott, W B	7907180324	50-471 Q
Texas A & M Univ	7907100627*	50-128 I		7907190738*	50-471 Q
	7907030249*	50-59 R	American Nuclear Insurers	7907060203	70-1319
	7907090317*	50-59 P		7907090226*	NUREQ
	7907300551	PR		7907130103	PR
	7907030247	50-59 R		7907170235*	50-320 J
	7907170040	50-128 S		7907030389	50-320 Q
	7907090314	50-59 P		7907030489	50-320 J
	7907100340*	50-128 P		7907090357	50-293 Q
	7907100346*	50-128 P		7907100557	50-320 J
	7907100352*	50-128 P		7907170232	50-320 J
	7907100368*	50-128 P		7907250315	50-219 J
	7907310393*	50-128 R		7907260684	50-320 Q
	7907090236	50-59 J	Asher, T R PC	7907310573	50-574 A
	7907100318	50-128 P	Baker & Botts	7907110152	50-445 H
	7907100359*	50-128 P		7907090056	50-498 H
	7907100596	50-128 F		7907110353*	50-466 Q
	7907100624	50-128 I		7907110342	50-466 Q
	7907100324*	50-128 P		7907130442	50-498 Q
	7907180465	50-128 P		7907130471*	50-498 Q
Texas Tech Univ.	7907310392	50-128 R		7907130486*	50-498 Q
Arkansas, Univ of	7907260127*	50-445 U		7907130442	50-498 Q
California, Univ of, Berkeley	7907050024	FOIA		7907130471*	50-498 Q
	7907190642	PRM		7907130486*	50-498 Q
	7907090322	50-224 H		7907130546	50-466 Q
California, Univ. of, Davis	7907160370	50-224 H		7907130560	50-466 Q
Cincinnati, Univ of, Medical School	7907270128	PR		7907190701	50-466 Q
California, Univ of, Los Angeles	7907240572	PRM		7907190823	50-466 Q
	7907090046	50-142 P		7907190586	50-466 Q
	7907110734	NUREQ		7907190435	50-445 H
California, Univ of, Santa Barbara	7907190353	NUREQ		7907190419	50-466 Q
Connecticut, Univ of	7907260509	50-320 H		7907230088	50-466 Q
Illinois, Univ of, Urbana-Champaign	7907260176	PR		7907200497	50-466 Q
	7907110018	PR	Blum & Shelley	7907190058	70-2623
	7907270111	PR	Berlack, Israel & Liberman	7907100328	50-320 Q
Iowa, Univ. of	7907230175	PR		7907030338	FOIA
Kansas, Univ. of	7907270131	50-148 R	Buttel & Kass	7907160116	50-549 Q
Kentucky, Univ. of	7907230132	PR		7907160125*	50-549 Q
Maryland, Univ. of	7907310591	RES		7907060102*	50-482 Q
Maine, Univ. of	7907190833	NUREQ	Blake & Uhlig	7907060107*	50-482 Q
Michigan, Univ. of	7907190214*	50-16 P	Chickering & Gregory	7907130392	50-361 Q
Miami, FL, Univ. of	7907240559	PRM	Conner, Moore & Corber	7907110432	50-358 Q
Minnesota, Univ of, Minneapolis	7907240594	PRM		7907110423	50-358 Q
Missouri, Univ. of	7907050322	50-186 S		7907110428*	50-358 Q
New Mexico, Univ of	7907240551	PRM		7907170237	50-358 Q
Oklahoma, Univ. of	7907310056	PR		7907310097	50-358 Q
	7907190281	NUREQ		7907180707	FOIA
Oregon, Univ of, School of Law	7907060073	FOIA		7907060006	50-358 Q
Puerto Rico, Univ. of	7907190839	PR		7907100708	50-358 Q
South Carolina, Univ of	7907260215	PR		7907020012	27-39

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907060471	50-272 Q	Laudig, B	7907250464	50-546 A
	7907130309	50-272 Q	Lead, Roger M	7907130038	50-522 Q
	7907130314*	50-272 Q		7907130045	50-522 Q
	7907240255	50-272 Q		7907130038	50-522 Q
	7907240283*	50-272 Q		7907130045	50-522 Q
	7907240291*	50-272 Q		7907130024	50-522 Q
Dignan, T Q	7907250042	50-568 Q		7907130029	50-522 Q
Debovoise & Lieberman	7907300415*	50-201 I		7907130024	50-522 Q
	7907300090	70-2623			
	7907060111	71-6698	Leva, Hawes, Bymington, Martin & Oppenheimer	7907130029	50-522 Q
	7907180879	50-445 M		7907180691	50-522 Q
	7907130217	70-2623			
	7907060447	50-445 Q	LeBoeuf, Lamb, Leiby & MacRae	7907300238	FR
	7907060483	50-445 Q		7907190371	FRQJ
	7907020005	50-445 M		7907050450	50-341 Q
	7907260014	50-445 M		7907190139	50-452 Q
Eckert, Seamans, Cherin & Mellott	7907250421	50-437 Q		7907050559	50-346 Q
	7907250428*	50-437 Q		7907190485	50-341 Q
Evergreen Legal Services	7907060518	50-522 Q		7907030442	50-285 F
	7907190318	50-522 Q		7907050123	50-341 M
	7907190324*	50-522 Q		7907200214	50-341 Q
	7907190318	50-522 Q		7907090228	50-285 F
	7907190324*	50-522 Q		7907090267	50-244 P
Feldman, J H, Jr	7907110508*	50-358 Q		7907180577	50-285 P
Feldman & Feldman	7907110089	50-356 P		7907240354	50-482 H
	7907250042	50-568 Q		7907230077	50-220 P
Gad, R K	7907130114	50-382 Q	Lowenstein, Newman, Reis, Axelrad & Toll	7907230224	50-244 P
Gillespie & Jones	7907130195	50-382 Q		7907110668	50-250 Q
	7907020116	FOIA		7907090471	50-498 M
Hale & Door	7907120019	50-338 Q		7907130081	50-344 Q
Hunton & Williams	7907130082	50-338 Q		7907130442	50-498 Q
	7907090401	50-322 Q		7907130471*	50-498 Q
	7907110726	50-338 Q		7907130486*	50-498 Q
	7907110746	50-338 Q		7907130442	50-498 Q
	7907130294	50-338 Q		7907130471	50-498 Q
	7907180330	50-338 Q		7907130486*	50-498 Q
	7907180339	50-338 Q		7907130546	50-466 Q
	7907110726	50-338 Q		7907130550	50-466 Q
	7907110746	50-338 Q		7907180739	50-344 Q
	7907130294	50-338 Q		7907190827	50-466 Q
	7907180330	50-338 Q		7907190586	50-466 Q
	7907180339	50-338 Q		7907190435	50-445 M
	7907180600	50-463 Q		7907190472	50-250 Q
	7907180603	50-322 Q		7907190419	50-466 Q
	7907130189	50-338 Q		7907230088	50-466 Q
	7907060390	50-338 Q	Marsh & McLennan, M & M Nuclear Consultan t's, Inc. Div	7907200497	50-466 Q
	7907130056	50-463 Q		7907030459	50-744 J
	7907130070*	50-463 Q		7907180493	50-535 J
	7907130056	50-463 Q	Mayerson, H	7907250489*	50-352 A
	7907130070*	50-463 Q	Mayer, Brown & Piatt	7907120449	70-1308
	7907180741	50-322 Q		7907120458*	70-1308
	7907180774	50-338 Q		7907120465*	70-1308
	7907180589	50-338 Q	Myer, Bowman, Stroup & Flack	7907030138	50-424 A
	7907180591	50-338 Q	McGrath, E J	7907060124	FRQJ
	7907180761	50-322 Q	McCutchen, Doyle, Brown & Emerson	7907020011	FRQJ
	7907060169	50-338 P		7907180728	FRQJ
Hirschkop & Grad P.C	7907110708	50-596 Q		7907240248	FRQJ
Huber, Magill, Lawrence & Ferrell	7907180875	WASTE HOT		7907060518	50-522 Q
Hooker, Alley & Weldon	7907180352	FR	Means, Donald S	7907190318	50-522 Q
Isham, Lincoln & Beale	7907090062	50-445 Q		7907190324*	50-522 Q
	7907050423	50-237 Q		7907190318	50-522 Q
	7907180285	50-239 Q		7907190324*	50-522 Q
	7907050457	50-295 Q	Miller, Mannix, Lemery & Kiffin	7907060507*	50-556 Q
	7907090453	50-556 Q		7907060510*	50-556 Q
	7907060513	50-556 Q		7907060509*	50-556 Q
	7907060367	50-556 Q	Miller, Mannix, Lemery & Kiffin	7907060510*	50-556 Q
	7907160120	50-556 Q	Morgan, Lewis & Bockius	7907050092*	FOIA
	7907180595	50-556 Q		7907120637	50-409 Q
	7907160120	50-556 Q	Myer, Bauman, Stroup & Flack	7907240341	50-424 Q
	7907180595	50-556 Q	Bruce Norton	7907130110	50-275 Q
	7907180346	50-295 Q		7907030187	50-344 P
	7907060344	50-295 Q	Napom & Ross	7907100719*	50-443 Q
	7907130047	50-255 Q	O'Neil, Backus, Spielman	7907060125	50-522 Q
	7907060503	50-556 Q	Paine, Lowe, Coffin, Herman & O'Kelly	7907110733	50-522 Q
	7907110580	50-329 Q	Perkins, Cole, Stone, Olsen & Williams	7907090001	50-522 Q
	7907180844	50-454 Q		7907130344	50-522 Q
	7907180828	50-456 Q		7907060125	50-522 Q
	7907190446	50-599 Q		7907180619	50-522 Q
Johnson & Higgins Insurance	7907130425	50-556 Q		7907180629	50-522 Q
	7907130315	50-338 J		7907180619	50-522 Q
Kosik, L. S	7907110449	50-338 Q		7907180629	50-522 Q
	7907110456*	50-338 Q		7907170138	50-522 H
	7907110463*	50-338 Q	Reilly, Like & Schneider	7907090409*	50-322 Q
	7907110468*	50-338 Q		7907190182	50-322 Q
	7907110413	50-338 Q		7907200122	50-516 Q
	7907100681	50-338 Q	Ropes & Gray	7907180264	FR
	7907190127	50-338 Q		7907180334	50-471 Q

AUTHOR	ACCESSION	SUBJECT	AUTHOR	ACCESSION	SUBJECT
AFFILIATION	NUMBER	CATEGORY	AFFILIATION	NUMBER	CATEGORY
	7907180878	50-443 Q	LOCAL GOVERNMENT AND AGENCIES		
	7907180895*	50-443 Q	Albany, NY	7907110700	50-596 A
	7907180878	50-443 Q	Austin, TX	7907190130*	50-478 H
	7907180895*	50-443 Q		7907050444	50-445 H
	7907180829	50-471 Q	Cincinnati, OH	7907050544	50-338 Q
	7907180726	50-443 Q	Clarmont County, OH	7907120274	50-358 Q
	7907190587*	50-471 Q			
	7907190438	50-471 Q	Gardiner, NY	7907260712*	50-596 Q
	7907030355	50-443 I	Jefferson County, KY	7907050193*	50-544 H
	7907120009	50-471 Q	Kingston, NY	7907260701*	50-596 Q
	7907240423*	50-471 Q	Martin County, FL	7907190206	50-389 Q
	7907180112	50-443 I	Ottawa County, OH	7907130528*	50-346 Q
	7907270197	50-443 I	Scagit County, WA	7907060516	50-522 Q
			St Louis, MO	7907130033	PR
			Suffolk County, NY	7907090409*	50-322 Q
Ritcher, J A	7907250042	50-568 Q		7907120129*	50-516 Q
Rogow, B.	7907090061	50-250 Q			
	7907090066*	50-250 Q		7907120119	50-516 Q
	7907090061	50-250 Q		7907180755*	50-322 Q
	7907090066*	50-250 Q		7907130400	50-322 Q
onane & Rebel	7907110515*	50-358 Q	Zion, IL	7907060153	50-295 P
	7907190134*	50-358 Q			
Steel, Hector & Davis	7907160027	50-389 Q			
	7907230071	50-389 Q			
Sheldon, Harmon & Roisman	7904110054	FOIA			
	7906010118	FOIA	Bach Mai Hosp Emergency Relief Fund	7907060082	XPORTLIC
	7907190724	50-289 P	DO, Massachusetts		
	7907100039	FOIA	Bridgeton Hosp	7907190793	PR
	7907090410	50-334 P	Delaware Valley Hosp. PA/BR	7907190831	PR
	7907090442	FOIA	Grand Valley Hosp	7907230215	PR
			Greater Community Hosp	7907190849	PR
	7907190259	50-320 P	Guernsey Memorial Hosp OH/CA	7907190118	PR
	7907090410	FOIA	JFK Memorial Hosp	7907200506	PRM
	7907190097	50-320 P	Kettering Medical Center OH/KE	7907190717	PR
	7907050539	50-271 Q	Lutheran Medical Center MO/ST	7907190806	PR
	7907190542	50-568 Q	Lutheran Hosp IN/FO	7907190781	PR
	7907190547*	50-568 Q	Lutheran Hosp WI/MI	7907260204	PR
	7907190542	50-568 Q	Massachusetts General Hosp	7907260225	PR
Spiegel & McDiarmid	7907190547*	50-568 Q	Marshfield Clinic	7907190775	PR
	7907110343*	50-416 H	Mayo Clinic	7907260187	PR
	7907110337*	50-416 H	Meckelburg, R L MD	7907260586	PRM
	7907170154*	50-445 H	Michael Reese Hosp & Medical Center	7907230275	PR
	7907190213	50-445 H	Middlesex General Hosp	7907180371	PR
	7907110328*	50-416 H	Montefiore Hosp /Montefiore Hosp Assoc	7907240536	PRM
	7907060400	PRDJ	of Western PA PI/PA		
	7907170117	50-445 H	Mount Auburn Hosp	7907190654	PRM
			Norfolk General Hosp.	7907190521	PR
	7907170117	50-445 H			
	7907170117	50-445 H	Oklahoma Children's Memorial Hosp	7907260193	PR
	7907030298	50-416 Q	Peter Bent Brigham Hosp BG, Massachusetts	7907050548*	50-280 H
	7907190834	50-445 H	Riverview Hosp. WI	7907190780	RE00D
	7907050299	50-416 H	St Francis Hosp CO, Missouri	7907190719	PR
			St Francis MO/MA	7907300020	PR
Snell & Wilmer	7907050371	50-592 Q	St John Medical OH/ST	7907230200	PR
	7907060038	50-592 Q	Unity Hosp FR, Minnesota	7907230254	PR
	7907020007	50-592 Q	Vet. Admin Hosp LL, California	7907200494	PRM
	7907180119	50-592 Q	Vet. Admin Hosp Des Moines, IA	7907260198	PR
	7907180313	50-592 Q	Vet. Admin. Hosp AL, Louisiana	7907230148	PR
	7907130110	50-275 Q	Vet Admin. Medical Center CA/LE	7907260228	PR
	7907180078	50-592 Q	Vet. Admin Hosp Cleveland, OH	7907310088	PR
	7907020006	50-592 Q			
	7907190706	50-592 Q	Vet Admin. Hosp. BL, Utah	7907261014	PR
	7907020006	50-592 Q	Vet Admin. Hosp BA, Virginia	7907190733	PR
	7907190706	50-592 Q	Vet. Admin. Hosp WA/SE	7907200263	PRM
	7907190453	50-592 Q	Winchester Memorial Hosp., Virginia	7907240542	PRM
Shaw, Pittman, Potts, & Trowbridge	7907060052	50-400 Q	Winona Memorial Hosp.	7907190725	PR
	7907090393	50-387 Q			
	7907060583	50-382 Q			
	7907130157	50-387 Q			
	7907090171	50-320 Q	MANUFACTURERS/EQUIPMENT AND SUPPLIES		
	7907160269	50-400 Q	3M Co., Minnesota Mining & Mfg. Co	7907090241	RE00D
	7907160276*	50-400 Q	Allied Chemical Corp., Nuclear Services Div	7907180134	NUREG
	7907160269	50-400 Q			
	7907160276*	50-400 Q	Acme-Cleveland Co., Namco Controls Div	7907100662	50-393 S
	7907160269	50-400 Q	American Cyanamid Co.	7907310053*	COMMISSION
	7907160276*	50-400 Q	Atomic Energy of Canada, Ltd	7907060445	FOIA
	7907160269	50-400 Q			
	7907160276*	50-400 Q	Allied Chemical Corp.	7907060456	FOIA
			Amoco Oil Co. (subs. of Standard Oil Co of Indiana)	7907190414	40-3392
				7907050167	71-128
	7907160269	50-400 Q			
	7907160276*	50-400 Q	Air Products & Chemicals, Inc.	7907260958	PR
	7907190504	50-327 Q		7907240115	XPORTLIC
	7907240335	50-387 Q			
	7907310327	50-482 A	Amersham Corp.	7907240103	XPORTLIC
			Atlas Minerals	7907300137	40-3453
Sullivan & Cromwell	7907300149	FOIA		7907300537	40-3453
Visors, C.	7907180676	50-272 Q	Automation Industries, Inc.	7907190710	PRM
	7907180681	50-272 Q	Borg-Warner Corp	7907180820	XPORTLIC
	7907240231	50-272 Q			
Waters, McPherson, Hudzin & McNeill	7907280429	50-320 P	Bucyrus-Erie Co	7907060137	71-310
				7907300833	71-310
			Bunker-Ramo Corp., Amphetal North America Div.	7907130251*	GA999
West Texas Legal Services	7907170248	50-445 Q			
Worsham, Forsythe & Sampsels	7907180879	50-445 H		7907130246*	GA999
	7907020005	50-445 H		7907130228*	GA999
Wharton, R. J.	7907170283	50-361 Q			

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Babcock & Wilcox Co	7907250470*	FOIA		7907130093	50-329 T
	7907110340	50-320 P		7907180247	50-329 T
	7907110206	50-312 P		7907130102	50-329 T
	7907230493*	50-244 Q			
	7907130175*	50-329 Q		7907130076	50-329 T
	7907090419*	FOIA		7907130069	50-329 T
	7907260562	50-320 P		7907130184	50-329 T
	7907260564	50-320 P		7907130069	50-329 T
	7907180091	50-320 P		7907130184	50-329 T
	7907180102*	50-320 P			
				7907180268	50-329 T
	7907260535	50-320 P	Dow Chemical Co , Dow Chemical U S A	7907240338	50-264 H
	7907260546	50-320 P	Div		
	7907260541	50-320 P	Dow Corning Corp	7907260659	PRM
	7907260644	50-320 P	Dravo Corp	7907250561*	QA999
	7907260566	50-320 P	Eberline Instrument Corp	7907230032	XPORTLIC
	7907260568	50-320 P	Edlow International Co	7907240203	XPORTLIC
	7907260674	50-320 P		7907240209*	XPORTLIC
	7907260685	50-320 P		7907310037	XPORTLIC
	7907260530	50-320 P	Energy Fuels Nuclear, Inc	7907020464	40-8681
	7907260551	50-320 P		7907240575	40-8681
	7907260556	50-320 P		7907030221	40-8681
	7907260558	50-320 P		7907030231*	40-8681
	7907260560	50-320 P	Energy Products Group	7907050032	71-178
	7907260565	50-320 P	Energy Systems Group	7907120718	50-320 P
	7907260567	50-320 P	Exxon Nuclear Co , Inc (subs of Exxon Corp )	7907060467	XPORTLIC
	7907260570	50-320 P		7907110459*	TOPREP
	7907260572	50-320 P		7907250044	70-1257
	7907060249	TOPREP		7907190572	71-3
	7907060282*	TOPREP		7907110451	TOPREP
	7907030475	70-135		7907190577*	71-3
	7907060120	70-1201		7907060499	70-1237
	7907200293*	TOPREP		7907180609*	50-285 P
	7907100727*	QA999		7907230304*	71-6581
	7907060504	70-364		7907180621*	50-285 P
	7907230505*	70-27		7907230511*	71-6581
	7907110150*	50-320 O		7907110454	TOPREP
	7907060116	71-6058		7907180890	50-564 J
	7907060396	70-27		7907180749	40-8064
	7907060410	70-1201	Exxon Minerals Co , USA	7907300487	71-99
	7907020507*	FOIA	Foster Wheeler Corp	7907300490*	71-99
				7907240426*	REGOD
	7907090418	XPORTLIC	Fox Industries	7907240412*	REGOD
	7907300243	70-1201		7907240395*	REGOD
	7907250060	71-9019		7907240384*	REGOD
	7907100580	TOPREP			
	7907170021	TOPREP		7907240388*	REGOD
	7907120589	50-320 Q		7907240372*	REGOD
	7907180540*	TOPREP		7907190363	71-4949
	7907180534	TOPREP	General Atomic Co (subs. of Gulf Oil Corp.)		
	7907200288	TOPREP		7907250569*	QA999
	7907270182	50-269 P		7907050308	50-89 F
Babcock & Wilcox Co , Nuclear Material Div	7907180851	71-4949		7907180514	50-267 P
Combustion Engineering, Inc	7907060184	PR	Gas Rentals	7907110617	71-214
	7907120651	FOIA		7907110630*	71-214
	7907230291*	QA999	General Electric Co	7907230750	NUREG
	7907160282	50-470 K		7907050066*	FOIA
	7907160289*	50-470 K		7907050082*	FOIA
C-E Power Systems	7907130026*	70-1100		7907090409*	50-322 Q
	7907110502	TOPREP		7907060463	70-1113
CEI Nuclear Co	7907090362*	50-312 Q		7907190596	PR
	7907090367*	50-312 Q		7907180771	70-754
	7907090396*	50-312 Q		7907060211	70-1113
	7907090400*	50-312 Q		7907060223	70-1308
	7907090407*	50-312 Q		7907030297	XPORTLIC
	7907090412*	50-312 Q		7907120394	XPORTLIC
Chematron Corp	7907250140	PT21		7907160334*	TOPREP
Chevron Oil Co (subs. of Standard Oil Co. of California)	7907190809	PR		7907110744	XPORTLIC
Chicago Bridge & Iron Co.				7907200046*	70-1113
	7907090417*	FOIA		7907200064*	70-1113
	7907130158*	50-358 Q		7907160328	TOPREP
	7907090414*	50-395 Q	General Electric Co., Nuclear Energy Products Div	7907060175	PR
	7907020324	71-130			
	7907020326*	71-130		7907180797	70-1113
Chase Brass & Copper Co , Inc (subs. of Kennecott Copper Corp.)	7907250017	XPORTLIC		7907090378	70-754
Cleveland-Cliffs Iron Co.				7907060160	70-1308
	7907060265*	40-8714		7907190273	PRM
	7907060261	40-8714		7907250141	REGOD
Chem-Nuclear Systems, Inc.	7907060168	27-47			
				7907250129	REGOD
	7907180812	71-3805		7907190091	70-1308
	7907300187	71-6244		7907050386	71-9009
Colt Industries, Inc.	7907240260	PT21		7907050389*	71-9009
Conax Corp.	7907250382*	50-311 E			
Cordia Corp	7907190762	PR		7907060404	70-1113
	7907310567	40-8692		7906200240*	50-73 P
Cotter Corp.	7907130085	50-329 T		7907200194	TOPREP
Dow Chemical Co.	7907130093	50-329 T		7906200236	50-73 P
	7907180247	50-329 T		7907230521	XPORTLIC
	7907130085	50-329 T			
				7907230656	XPORTLIC

## CORPORATE SOURCE INDEX

439

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907300025	XPORTLIC		7907180786	70-143
	7907030448	TOPREP		7907160247	70-143
	7907200209	TOPREP		7907130121*	70-143
	7907170173	TOPREP		7907230615*	70-143
	7907060287	TOPREP		7907300215*	71-6698
	7907060324	TOPREP		7907190718	50-201 R
	7907110466	90-277 P	Nuclear Fuel Services, Inc , West Valley Reprocessing Plant	7907190727*	50-201 R
	7907310303	RES	NL Industries, Inc	7907260973	PRH
	7907310317*	TOPREP	Nuclear Packaging, Inc	7907050501	71-192
	7907120354	TOPREP	Nuclear Dynamics	7907060508	40-8602
	7907170143	TOPREP		7907060502	40-8663
	7907120383	90-73 P		7907060505*	40-8663
	7907190616	50-70 P	Ogle Petroleum, Inc	7907310366	40-8693
	7907180583	TOPREP	Offshore Power Systems (subs of Westinghouse Electric Corp )	7907250293	50-437 Q
	7907180586*	TOPREP		7907250380	50-437 A
	7907250320	TOPREP		7907170180	50-437 A
	7907250254	TOPREP		7907270173	50-437 A
	7907250392	TOPREP		7907030109*	40-2259
	7907250395*	TOPREP		7907030107	40-2259
	7907310313	TOPREP	Pathfinder Mines Corp	7907090243	40-2259
	7907230090	XPORTLIC		7907300004	40-2259
Deachart-Owen Industries, Inc , GO Wireline Services Div	7907020463	40-8712		7907190146	50-320 P
Gulf Research & Development Co	7907250192*	QA999	Pfizer, Inc	7907030303	XPORTLIC
Gulf & Western Industries, Inc	7907270396	71-24	Reuter-Stokes, Inc.	7907090389	XPORTLIC
Hittman Nuclear & Development Corp (subs of Hittman Corp )	7907180384	PR		7907230162	XPORTLIC
Hoffman-La Roche, Inc (subs of F Hoffman-La Roche & Co , Ltd )	7907240292	XPORTLIC	Rockwell International Corp	7907240048	71-6058
Hoke, Inc	7907240294	XPORTLIC		7907260025*	QA999
Huico, Inc	7907130194*	QA999		7907120399	50-94 J
	7907130191*	QA999	Sigma Chemical Co (subs of Sigma Aldrich Corp )	7907180838	XPORTLIC
Industrial Engineering Works	7907120299	50-518 B	ENUPPS-Standardized Nuclear Unit Power Plant System	7907310040	XPORTLIC
Industrial Fabricating	7907050447	71-156	Stock Equipment Co	7907110511	50-482 Q
Industrial Laboratories, Inc	7907050452*	71-156		7907030482*	TOPREP
	7907020037	71-257		7907030480	TOPREP
IRT Corp	7907020038*	71-257	Teledyne, Inc	7907180830	71-258
Isotope Products Laboratories	7907060517	71-247	Texas Instruments, Inc	7907300409*	50-247 P
	7907190855*	XPORTLIC	Trautvetter Corp	7907020437	71-168
	7907260591	XPORTLIC	Transnuclear, Inc.	7906140602*	XPORTLIC
International Telephone & Telegraph Corp	7907250339*	QA999		7907120683*	XPORTLIC
	7907250334*	QA999		7907230196*	SECY
Jacksonville Shipyards, Inc	7907050510*	71-209		7907180316	70-1375
	7907050504	71-209		7907120112	70-1375
Kerr-McGee Corp	7906140590*	40-8006		7907120382	XPORTLIC
	7907060035	40-8027		7907180563	XPORTLIC
	7907190378	PROJ		7907250093	XPORTLIC
	7907090054	40-8061		7907100093	XPORTLIC
obsolete code	7907310173	40-8027		7907230046	XPORTLIC
	7907030104	XPORTLIC		7907230052*	XPORTLIC
Eastman Kodak Co	7907240262*	QA999		7907310301	XPORTLIC
Litton Bionetics, Inc (subs of Litton Industries, Inc )	7907260138*	QA999	Chematron Corp , Tube Turns Div	7907090403*	QA999
Limitorque Corp	7907260116*	QA999	Ramsay Engineering Co , Texas Nuclear Div	7907180877	XPORTLIC
Lucky Mc Uranium Corp.	7907090254*	40-2259		7907180900*	XPORTLIC
	7907090257*	40-2259		7907230140	XPORTLIC
	7907090260*	40-2259		7907230146*	XPORTLIC
	7907090264*	40-2259		7907190093*	40-299
Maine Bag Co	7907020506*	50-309 H	Union Carbide Corp.	7907190397	71-9070
Marubeni America Corp (subs of Marubeni Corp )	7907180868	XPORTLIC		7907190081	40-299
	7907180861	XPORTLIC	United Nuclear Corp	7907230234	PRH
Matheson Gas Products	7907060469*	40-1739		7907110028	PR
Metals & Controls Corp	7907060475*	40-1739		7907060511*	40-8602
	7907020500	XPORTLIC		7907060494*	70-820
Metal Bellows Corp	7907020501*	XPORTLIC		7907060500	70-371
	7907120360	XPORTLIC		7907060493	70-820
Mitsui & Co , Ltd	7907120495*	XPORTLIC		7907180698*	70-820
	7907240213	XPORTLIC		7907190030*	71-4949
	7907240218*	XPORTLIC		7907250056	71-6601
	7907250236	XPORTLIC		7907020511	40-8681
Mitsubishi International Corp (subs of Mitsubishi Corp )	7907240289	XPORTLIC	E F Uranium Group, Inc	7907180735	71-39
Neutron Products, Inc	7907060439	FDIA	Halworth Co. (subs of IU International Corp )	7907120103	RES
	7907050238	71-121	Westinghouse Electric Corp.	7907120107	RES
Nuclear Fuel Services, Inc (subs of Getty Oil Co )	7907300525*	50-201 I		7907120131	RES
	7907180763	70-143		7907120138	RES
	7907060437	70-143		7907200305*	TOPREP
	7907060134	70-143		7907120126	RES
	7907130132*	70-143		7907120123	RES
	7907090368	70-143		7907020130*	50-320 P
	7907190384	70-143		7907060393	70-1151
	7907050417	50-201 R		7907120076	RES
	7907020472	70-143		7907310238	PRH
	7907060386	50-201 I		7907060152	70-1151
	7907090361	70-143		7907060482	70-1143
				7907120115	RES

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907190498	PR		7907130004	50-295 Q
	7907020483	70-2909		7907130009	50-295 Q
	7907030291	XPORTLIC		7907130004	50-295 Q
	7907240190	XPORTLIC		7907130009	50-295 Q
	7907060286	XPORTLIC		7907130059	50-295 Q
	7907180901	50-374 A		7907160325*	50-320 P
	7907020330	FOIA		7907310138	50-295 Q
	7907100702	70-1143		7907110125	50-471 Q
	7907250134	REGGD		7907110165	50-471 Q
	7907250553*	GA999		7907130495	50-599 Q
	7907190001	XPORTLIC		7907130505*	50-599 Q
	7907300062*	70-1151		7907190339	50-599 Q
	7907300172	XPORTLIC		7907130495	50-599 Q
	7907240111	XPORTLIC		7907130505*	50-599 Q
	7907250033	XPORTLIC		7907190339	50-599 Q
	7907240280	XPORTLIC		7907190714	50-599 Q
	7907240284*	XPORTLIC		7907190784*	50-599 Q
	7907060279	TOPREP		7907190716	50-599 Q
	7907100374	TOPREP		7907190784*	50-599 Q
	7907120109	RES	Kansas, State of	7907190344	WASTE MGT
	7907130248*	TOPREP	Massachusetts, State of	7907050507	50-471 Q
	7907130239	TOPREP		7907190444	WASTE MGT
	7907170199	50-374 A		7907090467	50-471 Q
	7907200299	TOPREP		7907180366	50-471 Q
	7907200352	TOPREP		7907180374*	50-471 Q
Western Nuclear, Inc (subs of Phelps Dodge Corp )	7907030296*	40-1162		7907180773	50-471 Q
	7907310150	40-1162		7907180817	50-471 Q
Wyoming Mineral Corp	7907030290	40-1162		7907180824*	50-471 Q
	7907100636	40-8304		7907190643	50-471 Q
	7907100639*	40-8304		7907190651*	50-471 Q
	7907180859	40-8304		7907190738*	50-471 Q
	7907300201	40-8502		7907190650	50-471 Q
			Maryland, State of	7907190394	WASTE MGT
PROFESSIONAL/INDUSTRIAL INSTITUTIONS, SOCIETIES				7907190427	WASTE MGT
American Board of Health Physics	7906210407	REGGD	Maine, State of	7907050120*	50-309 H
	7907240461	PRM	Michigan, State of	7907050281	50-329 H
	7907260249	REGGD		7907050283*	50-329 H
Atomic Industrial Forum	7907180804	PROJ	Minnesota, State of	7907190333	WASTE MGT
	7907110135*	50-320 Q			
American Nuclear Society	7907270217*	COMMISSION	Missouri, State of	7907120046	50-403 IF
Conference of Radiation Control Program Directors, Inc	7907290573*	FOIA	North Dakota, State of	7907190365	WASTE MGT
Health Physics Society	7907190147	PRM	Nebraska, State of	7907200262*	50-290 P
	7907260617	PRM	New Hampshire, State of	7907300570	PR
National Academy of Engineering	7907240176	NUREG	New Jersey, State of	7907190449	WASTE MGT
				7907180373	50-272 Q
National Academy of Sciences	7907240176	NUREG		7907180385*	50-272 Q
Portland Cement Association	7907270090	REGGD		7907240239	50-272 Q
	7907300393*	50-358 F		7907240243*	50-272 Q
				7907240342	50-272 Q
STATE GOVERNMENTS/AGENCIES				7907240350*	50-272 Q
California, State of	7907050554*	50-361 H	New Mexico, State of	7907200465	50-363 A
	7907260571*	COMMISSION		7907190401	WASTE MGT
	7907060149*	50-275 Q		7907130457	40-8725
	7907050551	50-361 H		7907130461*	40-8725
	7907270065	PRM	Nevada, State of	7907020481	40-8726
	7907020003	50-592 Q		7907230592*	FOIA
	7907190379	50-592 Q		7907230586*	FOIA
	7907190479	50-592 Q		7907250562*	FOIA
	7907190379	50-592 Q	New York, State of	7907300538*	50-201 I
	7907190479	50-592 Q		7907300536*	50-201 I
	7907030369	50-592 A		7907300521*	50-201 I
	7907100616	50-592 D		7907300517*	50-201 I
	7907090301	50-592 Q		7907300509*	50-201 I
	7907170080	50-312 P		7907300513*	50-201 I
	7907260583*	50-592 Q		7907300418*	50-201 I
	7907260580	50-592 Q		7907020322*	PR
	7907310377	50-206 A		7907020320	PR
Delaware, State of	7907260390*	50-272 Q		7907090007*	50-201 U
Florida, State of	7907190283	WASTE MGT		7907180240	50-596 Q
Georgia, State of	7907190351	WASTE MGT		7907030203	50-549 Q
Guam	7907260210	PR		7907050461	PR
	7907270080	PRM		7907230122	PR
Iowa, State of	7907060278	50-599 A		7907200145*	50-516 Q
Idaho, State of	7907190434	WASTE MGT		7907190766	PRM
Illinois, State of	7907230110	PR		7907190360	WASTE MGT
	7907190270	WASTE MGT		7907260476	50-596 Q
	7907060248	50-295 Q		7907260547	50-201 P
	7907190386	WASTE MGT		7907300336	50-201 P
	7907110499	50-237 Q	Ohio, State of	7907310049	PR
	7907180134	50-295 Q		7907180367	PR
	7907200175	50-295 Q	Oregon, State of	7907130479*	50-346 P
	7907180134	50-295 Q		7907130474*	50-346 P
	7907200175	50-295 Q		7907190491	WASTE MGT
	7907200175	50-295 Q			
	7907230771*	27-39	Pennsylvania, State of	7907240310	50-344 Q
				7907060237*	COMMISSION
				7907190434	WASTE MGT
				7907190473	WASTE MGT



## CORPORATE SOURCE INDEX

441

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Puerto Rico	7907260243	PR			
Rhode Island, State of	7907160083*	COMMISSION	Justice, Dept of	7907180478	50-387 A
South Carolina, State of	7907160088*	COMMISSION		7907230180*	COMMISSION
	7907190321	WASTE MGT		7907180040	50-445 M
	7907190380	WASTE MGT	State, Dept of	7907260038	50-445 M
	7907300566	PR			
South Dakota, State of	7907190486	WASTE MGT		7907130441*	SECY
Texas, State of	7907190302	WASTE MGT		7907190012*	SECY
	7907020002	50-466 O		7907060485	XPORTLIC
	7907180777	50-445 O		7907060497	XPORTLIC
	7907190846*	50-445 M		7907180869*	SECY
Utah, State of	7907270374	40-8681		7907060491	XPORTLIC
Virginia, State of	7907180415*	50-280 P		7907100047	XPORTLIC
	7907110429	TOPREP		7907190163	XPORTLIC
Vermont, State of	7907190312	WASTE MGT		7907230149	XPORTLIC
	7907190819	WASTE MGT		7907230168	XPORTLIC
				7907230179	XPORTLIC
				7907230193	XPORTLIC
Washington, State of	7907190413	WASTE MGT		7907230443	XPORTLIC
	7907190496	WASTE MGT		7907230445	XPORTLIC
	7907180360	PR		7907230448	XPORTLIC
				7907230457	XPORTLIC
				7907230668	XPORTLIC
U S FEDERAL GOVERNMENT AND AGENCIES				7907230690	XPORTLIC
Atomic Energy Commission	7907060479*	40-1739		7907260025	XPORTLIC
	7907060490*	40-1739		7907310808	XPORTLIC
	7907060486*	40-1739		7907240465	XPORTLIC
	7907300206*	FOIA		7907250074	XPORTLIC
	7907300216*	FOIA			
	7907300235*	FOIA		7907260353	XPORTLIC
	7907300249*	FOIA		7907260363	XPORTLIC
	7907300168*	FOIA		7907230686	XPORTLIC
	7907300180*	FOIA		7907240146	XPORTLIC
	7907300268*	FOIA		7907240162	XPORTLIC
	7907300492*	50-201 I		7907240177	XPORTLIC
	7907300497*	50-201 I	State, Dept of, Bureau of Oceans &	7907260592	XPORTLIC
	7907300466*	50-201 I	Internat'l Environ & Scientific Affairs		
	7907300440*	50-201 I		7907260555	XPORTLIC
	7907300434*	50-201 I		7907260365	XPORTLIC
				7907260369	XPORTLIC
	7907300424*	50-201 I		7907260372	XPORTLIC
	7907060484*	40-1739		7907260913	XPORTLIC
Congress (Joint & Rotating Committees, etc.)	7906060054	50-320 U	Transportation, Dept of	7907160045	COMMISSION
Defense Civil Preparedness Agency	7907100156	FOIA	Environmental Protection Agency	7907110192*	50-320 O
Defense, Dept of, Defense Nuclear Agency	7907090349	50-170 P		7907250362*	50-244 P
	7907090354*	50-170 P			
Agriculture, Dept of	7907100645	50-568 D		7907180162	FOIA
Commerce, Dept of	7907310605	50-294 P		7907180168	FOIA
	7907310602	50-294 P		7907130536*	50-346 O
Commerce, Dept of, National Oceanographic & Atmospheric Administration	7907020155	50-320 P		7907250449	50-320 P
				7907160182*	50-320 P
				7907110008*	50-320 O
Army, Dept of	7907250240*	XPORTLIC		7907100687	40-8698
	7907250238	XPORTLIC		7907100633	50-592 D
Army, Dept of, Corps of Engineers	7907190358*	40-8584	Federal Radiation Council	7907130397	50-302 P
	7907100571	REVIEW QRP		7907180173	FOIA
	7907260629	PRM			
Army, Dept of, Headquarters, Material Development & Readiness Command	7907110570	71-235	General Accounting Office	7907180124	FOIA
Army, Dept of, Electronic Proving Ground	7907050513	71-87		7907230584*	COMMISSION
Navy, Dept of	7907050519*	71-87	General Services Administration	7907180130	50-320 U
				7907120565*	50-568 A
				7907120563	50-568 D
	7907120381	PR	Health, Education & Welfare, Dept of	7907110007*	50-320 O
	7907090018	71-268		7907300574	PR
	7907180845	71-239	House of Rep	7907180673*	50-323 U
	7907120830	PR		7906260590*	50-230 U
	7907080499	71-116		7907230619*	COMMISSION
Navy, Dept of, Naval Facilities Engineeri ng Command	7907260668	PRM		7907310578*	COMMISSION
Navy, Dept of, US Marine Corps	7907130043	PR		7907260259*	PROJ
Energy, Dept of	7907180137	FOIA		7907230757*	50-280 U
	7907030311	FOIA		7907260489	50-320 U
	7907110009*	50-320 O		7907050383*	50-488 U
	7907190188	WASTE MGT			
	7907060492	DRQ		7907160254*	COMMISSION
	7907030159	FOIA		7907160303*	COMMISSION
	7907310480	71-361		7907050534	50-556 U
	7907120649*	PROJ		7907260065*	50-313 U
				7907160063*	COMMISSION
	7907100462	50-344 P		7907310136*	50-382 U
	7907020191	50-537 B		7907310164*	50-275 U
	7907020195*	50-537 B		7907050380	50-488 U
	7907120644	PROJ		7907160091*	50-416 U
Energy, Dept of, Clinch River Breeder Reactor Plant	7907270124	REQDD		7907310253*	50-382 U
Energy, Dept of, Environmental Measuremen ts Laboratory	7907180116	MUREQ	House of Rep., Armed Services	7907160086*	50-416 U
Interior, Dept of	7907110737	50-344 H	House of Rep., Interstate & Foreign Comm.	7907110003*	50-320 O
	7907180353	PR		7907090068*	SECY
	7907130404	50-592 D			
Interior, Dept of, Fish & Wildlife Service	7907190728	PR	House of Rep., Interior & Insular Affairs	7907090068*	SECY
				7907110079*	50-320 O
				7907110086*	50-320 O
	7907050546	40-8698		7907110016*	50-320 O

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Housing & Urban Development, Dept. of, Federal Disaster Assistance Admin	7907300475*	COMMISSION		7907030398*	50-313 G
National Aeronautics & Space Admin	7907110358*	50-320 P		7907060322	50-313 R
	7907110382*	50-320 P		7907090292*	50-368 B
	7907110411*	50-320 P		7907090297*	50-368 B
	7907110139	50-320 P		7907090211	50-313 J
President of US & Executive Offices	7907100092*	50-320 T		7907090278	50-313 R
President's Commission on the Accident at Three Mile Island	7907180085	50-320 T		7907090279*	50-313 R
	7907180077	50-320 T		7907090211	50-313 J
	7907180092	50-320 T		7907090289	50-368 B
	7907180099	50-320 T		7907060321	50-320 P
	7907180106	50-320 T		7907110573	50-313 F
	7907180109*	50-320 T		7907060321	50-320 P
	7907180022	50-320 T		7907020161*	50-368 P
	7907180013	50-320 T		7907120645	50-368 G
	7907180017	50-320 T		7907120650*	50-368 B
	7907180073	50-320 T		7907120654*	50-368 B
	7907180003	50-320 T		7907120660*	50-368 B
	7907180010	50-320 T		7907170125	50-313 P
Senate	7907180816*	50-338 G		7907170128*	50-313 P
	7907310556*	COMMISSION		7907160283	50-368 B
	7907310621*	COMMISSION		7907160296*	50-368 B
	7907260050*	50-309 U		7907160308*	50-368 B
	7907180713*	50-278 U		7907170125	50-313 P
	7907260368*	50-253 U		7907170128*	50-313 P
	7907180713*	50-278 U		7907190385	50-313 R
	7907130484	50-416 A		7907190388*	50-313 R
	7907310104*	50-463 U		7907190541	50-368 R
	7907250157	50-280 U		7907190544*	50-368 R
	7907310211*	50-382 U		7907200272	50-313 P
	7907310193*	50-546 U		7907230349	50-313 G
Senate, Commerce, Science & Transportation	7907160336*	COMMISSION		7907230354*	50-313 G
Senate, Environment & Public Works	7907090068*	SECY		7907230573	50-368 F
Senate, Governmental Affairs	7907110006*	50-320 G		7907300297	50-368 B
	7907230635*	COMMISSION		7907300307*	50-368 B
	7907160162*	COMMISSION		7907310439	50-368 P
U S Embassies	7907260382	REGGD		7907310444	50-313 G
UTILITIES/HOLDING COMPANIES/INVESTOR ASSOCIATIONS			AZPS - Arizona Public Service Co	7907310453*	50-313 G
AEP - American Electric Power Co, Inc	7907300480	50-315 G		79073270405	50-320 Q
	7907100470	50-315 P		7907090239	50-528 Q
ALPR - Alabama Power Co	7907110415*	50-348 S		7907120561	50-528 B
	7907110407	50-348 S		7907120561*	50-320 B
	7907110455	50-348 S		7907120561*	50-528 B
	7907110461*	50-348 S		7907120561*	50-528 B
	7907110465*	50-348 S		7907120561*	50-528 B
	7907180582*	50-348 P		7907130426	50-592 B
	7907180172	50-348 G		7907020221	50-293 G
	7907190165	50-364 G		7907200444*	50-293 G
	7907310326	50-348 G		7907190680	50-293 G
	7907090364	50-348 A		7907180334	50-471 G
	7907250100	50-348 G		7907180829	50-471 G
	7907090364	50-348 A		7907190582	50-471 G
	7907260506*	50-348 G		7907190587*	50-471 G
	7907030435	50-348 P		7907190438	50-471 G
	7907180473*	50-348 R		7907180009	50-471 G
	7907100286	50-348 S		7907240314	50-471 G
	7907100295*	50-348 S		7907240317*	50-471 G
	7907170049	50-348 S		7907240417	50-471 G
	7907170059*	50-348 S		7907240423*	50-471 G
	7907170071*	50-348 S		7907080250	50-293 P
	7907300323*	50-348 P		7907100647	50-293 G
	7907180469	50-348 R		7907110509	50-293 G
	7907180576	50-348 P		7907160304	50-293 F
	7907170183	50-348 P		7907230447	50-293 P
	7907250340	50-348 P		7907160315	50-293 B
	7907240359	50-348 B		7907160324*	50-293 G
	7907240367*	50-348 B		7907200509	50-293 G
	7907240376*	50-348 S		7907200514	50-293 G
	7907240379*	50-348 S		7907200522*	50-293 R
	7907300321	50-348 P		7907170191	50-293 B
APL - Arkansas Power & Light Co	7907300384	FOIA		7907190396	50-293 P
	7907120603*	50-368 P		7907200251	50-293 R
	7907120606*	50-368 P		7907190522	50-293 B
	7907120601	50-368 P		7907190525*	50-293 B
	7907020156	50-368 P		7907200275	50-293 G
	7907060407	50-313 P		7907240253	50-293 F
	7907060417	50-313 G		7907240257	50-293 B
	7907180225	50-313 G		7907260692*	50-293 B
	7907060411	50-368 G		7907260703*	50-293 B
	7907170032	50-313 S		7907260708	50-293 H
	7907050098	50-368 S		7907260679*	50-293 G
	7907050102*	50-368 S		7907260686	50-293 G
	7907050107*	50-368 S		7907260695	50-293 G
	7907030396	50-313 S		7907260738	50-293 G
				7907260745	50-293 G

## CORPORATE SOURCE INDEX

443

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
BGE - Baltimore Gas & Electric Co	7907260667	50-293 S		7907240369	50-254 R
	7907230449*	50-293 P		7907310475	50-10 P
	7907300310	50-293 S		7907240078*	50-373 G
	7907300312*	50-293 S		7907300506	50-295 P
	7907100033	50-317 Q			
				7907300338*	50-295 G
	7907090224*	50-317 P		7907050224	50-10 P
	7907100021	50-317 G		7907100449	50-10 P
	7907200461	50-317 Q		7907050290	50-249 F
	7907300091	50-317 G		7907250583*	50-295 G
	7907090225*	50-317 P			
				7907050284	50-237 P
	7907300124	50-317 Q		7907190023	50-254 P
	7907090225*	50-317 P		7907190010	50-373 G
	7907300124	50-317 Q		7907300089*	50-373 Q
	7907030390	50-317 S		7907190010	50-373 Q
	7907030393*	50-317 S			
				7907300089*	50-373 Q
	7907030288	50-317 Q		7907190010	50-373 Q
	7907060276	50-317 J		7907110458	50-254 S
	7907090215	50-317 P		7907110462*	50-254 S
	7907090219	50-317 P		7907030357	TDPREP
	7907090222*	50-317 P			
				7907260584*	TDPREP
	7907090215	50-317 P		7907250372*	50-249 S
	7907090219	50-317 P		7907030404	50-237 S
	7907090222*	50-317 P		7907030408*	50-237 S
	7907190308	50-293 S		7907250283*	50-265 S
	7907170062	50-317 P		7907300401	50-295 Q
				7907060272	50-237 Q
	7907190222	50-317 P		7907060273*	50-237 Q
	7907200403	50-318 S		7907060272	50-237 Q
	7907200409*	50-318 S		7907060273*	50-237 Q
	7907230271	50-317 R			
	7907230274*	50-317 R		7907050374	50-454 A
				7907110444	50-254 S
	7907230271	50-317 R		7907110445*	50-254 S
	7907200410	50-318 S		7907050374	50-454 A
	7907200415*	50-318 S		7907050330	50-599 A
	7907250292	50-317 S			
				7907190469	50-247 S
	7907250298*	50-317 S		7907100567	50-295 G
	7907250300	50-318 S		7907110440	50-295 S
	7907250304*	50-318 S		7907110441*	50-295 S
	7907260656	50-318 S		7907100567	50-295 Q
	7907260663*	50-318 S			
				7907050229	50-373 A
CEIL - Commonwealth Edison Co	7907260424	50-317 P		7907240322	50-254 R
	7907310390	50-317 P		7907090305	50-10 P
	7907120570*	50-237 P		7907110442	50-237 S
	7907060341	PR		7907110443*	50-237 S
	7906290493	50-320 Q			
				7907090305	50-10 P
	7907120732*	FDIA		7907110435	50-295 S
	7907260057	PRM		7907110436*	50-295 S
	7907060251	50-10 Q		7907090305	50-10 P
	7907050004	50-295 Q		7907100443	50-599 H
	7907060251	50-10 Q			
				7907170078*	50-10 R
	7907050004	50-295 Q		7907110430	50-237 S
	7907060251	50-10 Q		7907110433*	50-237 S
	7907270115*	50-304 Q		7907170078*	50-10 R
	7907160273*	50-454 Q		7907100300	50-249 S
	7907250313*	50-265 S			
				7907100311*	50-249 S
	7907090475	50-295 Q		7907110548	50-249 S
	7907060031	50-373 Q		7907110554*	50-249 S
	7907180101	50-10 Q		7907170078*	50-10 R
	7907060349*	50-295 Q		7907130322	50-10 P
	7907060360*	50-295 Q			
				7907110467	50-10 F
	7907060369*	50-295 Q		7907130322	50-10 P
	7907060371*	50-295 Q		7907160294	50-254 P
	7907180094	50-295 R		7907190543	50-254 P
	7907180101	50-10 Q		7907190545	50-254 P
	7907060349*	50-295 Q			
				7907130322	50-10 P
	7907060360*	50-295 Q		7907160294	50-254 P
	7907060369*	50-295 Q		7907250297	50-265 S
	7907060371*	50-295 Q		7907130322	50-10 P
	7907180094	50-295 R		7907120566	50-237 P
	7907180101	50-10 Q			
				7907170038	50-454 A
	7907160155	50-454 Q		7907170053	50-10 P
	7907060345*	50-295 Q		7907170074	50-10 R
	7907060347*	50-295 Q		7907100572*	50-295 Q
	7907060355*	50-295 Q		7907100578*	50-295 Q
	7907060345*	50-295 Q		7907170070	50-254 P
				7907200381	50-10 F
	7907060347*	50-295 Q		7907170053	50-295 Q
	7907060355*	50-295 Q			
				7907190475	50-295 P
	7907160155	50-454 Q		7907190482*	50-295 P
	7907240274*	50-10 Q		7907200381	50-10 F
	7907310475	50-10 P		7907170053	50-295 Q
				7907190475	50-295 P
	7907240274*	50-10 Q			
	7907310475	50-10 P			
	7907240369	50-254 R			
				7907190482*	50-295 P
	7907310475	50-10 P		7907200381	50-10 F

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907250284	50-10 S		7907100515*	50-324 H
	7907250291*	50-10 S		7907050243	50-329 B
	7907190200	50-249 F		7907120344*	50-255 P
				7907180305*	50-329 Q
	7907250364	50-254 S		7907130104	RE000
	7907250378*	50-254 S		7907130034	RE000
	7907250264	50-255 S		7907180756	50-155 F
	7907250274	50-255 S		7907110702	50-327 Q
	7907250281*	50-255 S		7907110715	50-255 Q
	7907190342	TDPREP		7907130146	50-329 Q
	7907190357*	TDPREP		7907300014	RE000
	7907190563	50-237 P		7907110278	50-255 Q
	7907190570*	50-237 P		7907110215	50-329 Q
	7907230295	50-237 P		7907190289	50-155 Q
	7907200426	50-293 P		7907160234	50-155 Q
	7907240230	50-373 A		7907190239	50-155 Q
	7907240345	50-237 P		7907160234	50-155 Q
	7907260707	50-237 S		7907190239	50-155 Q
	7907260720*	50-237 S		7907050569	50-329 H
	7907250344	50-249 S		7907190336	50-255 Q
	7907230158	50-454 K		7907100606*	50-329 S
	7907230173*	50-454 K		7907300531	50-329 Q
	7907230158	50-454 K		7907030476	50-255 Q
	7907230173*	50-454 K			
	7907230158	50-454 K		7907030479*	50-255 Q
	7907230173*	50-454 K		7907020256	50-329 R
	7907230158	50-454 K		7907100604	50-329 S
	7907230173*	50-454 K		7907020256	50-329 R
	7907230158	50-454 K		7907100604	50-329 S
	7907230173*	50-454 K		7907030428	50-155 P
	7907300330	50-10 F		7907030279	50-329 K
	7907270257*	50-3 J		7907030445*	50-329 K
CENY - Consolidated Edison Co of New York	7907050280	PR		7907030470	50-329 K
	7907120409	50-3 Q		7907030472*	50-329 K
	7907030322	50-3 P		7907030279	50-329 K
	7907180754	50-247 Q		7907030445*	50-329 K
	7907260577	71-6601		7907030470	50-329 K
	7907120512	50-247 Q		7907030472*	50-329 K
	7907300487	50-247 Q		7907050306	50-329 C
	7907050337	50-3 P		7907050315*	50-329 C
	7907100591	50-3 J		7907050306	50-329 C
	7907110420	50-247 S		7907050315*	50-329 C
	7907180494*	50-3 R		7907120331	50-255 P
	7907160353*	50-3 S		7907120337*	50-255 P
	7907160342	50-3 S		7907090366	50-329 K
	7907170094	50-3 H		7907090284	50-255 B
	7907190519	50-3 H		7907090288*	50-255 S
	7907160342	50-3 S		7907130393	50-155 R
	7907170094	50-3 H		7907130399*	50-155 R
	7907170132	50-247 P		7907100319	50-255 S
	7907190519	50-3 H		7907100330*	50-255 S
	7907160342	50-3 S		7907100527	50-329 B
	7907180569	50-3 R		7907170181*	50-255 R
	7907200389	50-247 S		7907110416	50-329 A
	7907200401*	50-247 S		7907170178	50-255 R
	7907180490	50-3 R		7907170004	50-329 C
	7907240389	50-247 B		7907170024	50-155 P
	7907240397*	50-247 S		7907170037	50-255 B
	7907250251	50-3 Q		7907170044*	50-255 B
	7907250337	50-247 Q		7907200378	50-155 B
	7907270255	50-3 J		7907200384*	50-155 S
	7907310449	50-3 F		7907190512	50-255 R
	7907310249	50-247 P		7907190415	50-155 F
	7907310449	50-3 F		7907190536	50-155 P
	7907300287	50-247 S		7907190540*	50-155 F
	7907300293*	50-247 S		7907190415	50-155 F
	7907300393	50-247 P		7907190536	50-155 F
	7907130153	50-358 Q		7907190550*	50-155 F
CQEC - Cincinnati Gas & Electric Co	7907190151	50-358 Q		7907240324	50-155 Q
	7907090425	50-358 Q		7907240328*	50-155 Q
	7907190687	50-358 Q		7907250325	50-329 S
	7907170084	50-358 K		7907260475	50-329 A
	7907170086*	50-358 K		7907250325	50-329 Q
	7907300387	50-358 F		7907260475	50-329 A
	7907230491	50-358 K		7907300318	50-155 F
	7907310429	50-358 A		7907300383	50-255 B
	7907310431*	50-358 A		7907300398*	50-255 B
	7907110251	50-440 Q		7907270215	50-155 Q
	7907110255	50-440 Q		7907270248	50-329 R
	7907110231	50-440 Q		7907310299	50-255 F
	7907250082*	50-440 Q	CPL - Carolina Power & Light Co.	7907310308*	50-255 P
	7907260017*	50-440 Q		7907310432	50-255 P
	7907250082*	50-440 Q		7907110543	50-329 B
	7907260017*	50-440 Q		7907110549*	50-329 B
	7907300384	FOIA		7907110470	50-329 B
				7907110477*	50-329 B
				7907090333	PRM
				7907230247	PRM

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907190566	50-324 Q		7907160392	50-324 S
	7907200273	PR		7907160400*	50-324 S
	7907020476	50-261 Q		7907160371	50-324 S
	7907050175	50-400 Q		7907160381*	50-324 S
	7907100217	50-261 Q		7907190576	50-261 Q
	7907050175	50-400 Q		7907190373	50-324 S
	7907180153	50-400 Q		7907190382*	50-324 S
	7907190190	50-400 Q		7907190531	50-324 S
	7907190553	50-400 Q		7907190534*	50-324 S
	7907190608	50-324 Q		7907190576	50-261 Q
	7907180153	50-400 Q		7907240321	50-324 J
	7907190190	50-400 Q		7907190576	50-261 Q
	7907190553	50-400 Q		7907240321	50-324 J
	7907240215*	50-400 Q		7907260460	50-400 A
	7907180153	50-400 Q		7907260467*	50-400 A
	7907190190	50-400 Q		7907230551	50-324 S
	7907190553	50-400 Q		7907230563*	50-324 S
	7907240215*	50-400 Q		7907230588	50-324 S
	7907180153	50-400 Q		7907230618*	50-324 S
	7907190190	50-400 Q		7907230315	50-325 S
	7907190553	50-400 Q		7907230320*	50-325 S
	7907240215*	50-400 Q		7907240357	50-325 S
	7907180153	50-400 Q		7907240363*	50-325 S
	7907190190	50-400 Q		7907260460	50-400 A
	7907190553	50-400 Q		7907260467*	50-400 A
	7907240215*	50-400 Q		7907260460	50-400 A
	7907190111	50-261 Q		7907260467*	50-400 A
	7907110578	50-400 Q		7907260460	50-400 A
	7907190578	50-261 Q		7907260467*	50-400 A
	7907190591	50-261 Q		7907260460	50-400 A
	7907240413*	50-324 Q		7907260467*	50-400 A
	7907190376	50-261 Q		7907260467*	50-400 A
	7907190368	50-324 Q		7907240348	50-261 S
	7907240210	50-400 Q		7907240353*	50-261 S
	7907310204	50-400 Q		7907240366	50-324 S
	7907250090	50-400 Q		7907240371*	50-324 S
	7907090323	50-261 P		7907230325	50-325 S
	7907050336	50-324 J		7907230343*	50-325 S
	7907090323	50-261 P		7907260727	50-155 P
	7907050336	50-324 J		7907270230	50-324 Q
	7907090323	50-261 P		7907300423	50-324 S
	7907030497	50-400 A		7907300428*	50-324 S
	7907030500*	50-400 A		7907060468	50-213 Q
	7907050310	50-325 S		7907310608*	50-213 Q
	7907050329*	50-325 S		7907030378	50-213 Q
	7907030497	50-400 A		7907060167	50-213 Q
	7907030500*	50-400 A		7907060171*	50-213 Q
	7907030497	50-400 A		7907300468	50-213 Q
	7907030500*	50-400 A		7907180543	50-213 F
	7907030497	50-400 A		7907170017	50-213 S
	7907030500*	50-400 A		7907180525	50-213 R
	7907030497	50-400 A		7907180527*	50-213 R
	7907030500*	50-400 A		7907230528	50-213 Q
	7907030497	50-400 A		7907260710	50-213 S
	7907110406	50-324 P		7907260717*	50-213 S
	7907060176	50-261 P		7907260578*	50-409 I
	7907170031*	50-324 R		7907110539*	50-409 P
	7907130456*	50-261 R		7907020454	50-409 Q
	7907060403	50-324 S		7907090473	50-409 Q
	7907060405	50-324 S		7907260486*	50-409 F
	7907060409*	50-324 S		7907050005	50-409 Q
	7907060413*	50-324 S		7907110385	50-409 Q
	7907130379	50-324 P		7907090274	50-409 Q
	7907060284	50-325 P		7907020177	50-409 P
	7907060406	50-325 S		7907060326	50-409 S
	7907060408	50-325 S		7907060330*	50-409 S
	7907060412*	50-325 S		7907060210	50-409 P
	7907060416*	50-325 S		7907260481	50-409 F
	7907130379	50-324 P		7907180520*	50-409 R
	7907100357	50-261 S		7907110608	50-409 P
	7907100378*	50-261 S		7907110535	50-409 P
	7907090227	50-324 S		7907170043	50-409 P
	7907090233*	50-324 S		7907170018	50-409 P
	7907190480	50-325 S		7907190580	50-409 P
	7907190487*	50-325 S		7907300388	50-409 P
	7907130451	50-261 R		7907180519	50-409 R
	7907130339	50-325 S		7907260576	50-409 I
	7907130345*	50-325 S		7907260788	50-409 P
	7907130360	50-325 S		7907050129*	50-341 X
	7907130363*	50-325 S		7907190092*	50-341 Q
	7907130348	50-261 S		7907050127*	50-341 X
	7907130353*	50-261 S		7907130417	50-341 F
	7907170020	50-261 S		7907170072	50-341 A
	7907170026*	50-261 S		7907300375*	50-16 R
	7907170025	50-324 R		7907300362	50-16 R
	7907160360	50-324 S		7907190133*	50-334 P
	7907160364*	50-324 S		7907190117	50-334 P

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907020083	50-334 Q		7907190750	50-369 Q
	7907110450	50-334 Q		7907090382	50-369 Q
	7907050398	50-412 Q			
	7907230452*	50-412 Q		7907190565	50-369 Q
				7907190750	50-369 Q
	7907230370	71-5026		7907190122	50-413 Q
	7907020168	50-334 P		7907190176	50-408 Q
	7907020172	50-334 P		7907130042	70-2623
	7907030416	50-334 R			
	7907100547	50-334 R		7907180883	50-269 Q
				7907250059	71-6275
	7907090263	50-334 S		7907160185	50-369 Q
	7907090265*	50-334 S		7907110555	50-413 Q
	7907170052*	50-334 R		7907130223*	70-2623
	7907170162	50-412 Q			
	7907110446	50-334 S		7907130252*	70-2623
				7907130257*	70-2623
	7907110447*	50-334 S		7907130264*	70-2623
	7907170108	50-334 S		7907130273*	70-2623
	7907170111*	50-334 S		7907190409	50-269 Q
	7907170114*	50-334 S			
	7907170047	50-334 R		7907090420	50-491 Q
				7907020019	70-2623
	7907130410	50-334 P		7907310456	71-5026
	7907130413*	50-334 P		7907310454	71-6275
	7907190552	50-334 F		7907310448	71-6601
	7907180529	50-412 S			
	7907230625	50-334 Q		7907190622	70-2623
				7907270378*	50-369 Q
	7907200476*	50-334 P		7907260550	50-269 Q
	7907270164	50-334 Q		7907090342	50-369 S
	7907200472	50-334 P		7907090353*	50-369 S
	7907270229	50-334 S			
	7907260438	50-334 Q		7907090342	50-369 S
				7907090353*	50-369 S
	7907300384	FOIA		7907260055	50-287 Q
	7907110560*	50-269 S		7907110545	50-269 S
	7907110537	50-269 S		7907050312	50-269 F
	7907110540*	50-269 S			
	7907110552	50-269 S		7907090262	50-269 S
	7907110448	50-270 S		7907090266*	50-269 S
	7907110480*	50-270 S		7907120562*	50-369 K
	7907110546	50-269 S		7907120559	50-369 K
	7907110557*	50-269 S		7907170159	50-269 S
	7907110546	50-269 S			
				7907170165*	50-269 S
	7907110557*	50-269 S		7907180476	50-269 S
	7907110546	50-269 S		7907180481*	50-269 S
	7907110557*	50-269 S		7907180485	50-269 S
	7907110374	50-269 S		7907180488*	50-269 S
	7907110393*	50-269 S			
				7907190228	50-269 F
	7907110376	50-269 S		7907190535	50-269 F
	7907110393*	50-269 S		7907180476	50-269 R
	7907110376	50-269 S		7907180481*	50-269 R
	7907110393*	50-269 S		7907180502	50-270 S
	7907110376	50-269 S			
				7907180505*	50-270 S
	7907110582*	50-269 S		7907190228	50-269 F
	7901170158	50-269 P		7907190535	50-269 P
	7905240452	50-287 Q		7907180476	50-269 R
	7907300109*	70-2623		7907180481*	50-269 R
	7907190533*	70-2623			
				7907190228	50-269 F
	7907190526	70-2623		7907190535	50-269 F
	7906200115	50-269 Q		7907200245	50-269 Q
	7907050118	50-488 Q		7907230359	50-269 S
	7907020503	50-413 Q		7907230363*	50-269 S
	7907050118	50-488 Q			
				7907260734	50-269 P
	7905230543	50-287 P		7907240290	50-269 S
	7907050151	50-413 Q		7907240332	50-269 S
	7907050277	50-269 Q		7907230377	50-369 A
	7907110627	50-269 Q		7907300311	50-269 P
	7907050277	50-269 Q			
	7907110627	50-269 Q		7907110490	50-302 S
	7907060058	70-2623		7907130499*	50-302 Q
	7907060063*	70-2623		7907180186	50-302 Q
				7907090105	50-389 Q
	7907060065*	70-2623		7907230721*	50-302 Q
	7907130088	70-2623			
	7907130094*	70-2623		7907250062	50-302 P
	7907130098*	70-2623		7907250066	71-6275
	7907160216	70-2623		7907250062	50-302 P
				7907270401*	50-302 Q
	7907160220*	70-2623		7907030455*	50-302 S
	7907160223*	70-2623			
	7907160232	70-2623		7907030486*	50-302 S
	7907160235*	70-2623		7907100393	50-302 P
	7907160238*	70-2623		7907030377	50-302 P
				7907090234*	50-302 S
	7907110579*	50-269 Q		7907030452	50-302 B
	7907110141*	50-320 Q			
	7907190667	50-413 Q		7907030483	50-302 S
	7907100106	50-269 Q		7907030454	50-302 P
	7907190132*	50-413 Q		7907090232	50-302 S
				7907180544	50-302 S
	7907190176	50-488 Q		7907180556*	50-302 S
	7907090382	50-369 Q			
	7907190565	50-369 Q		7907100515	50-302 P
				7907100519*	50-302 S
				7907130367*	50-302 S
				7907190448*	50-302 R
				7907180524*	50-302 S

FPC - Florida Power Corp

## 447

AUTHOR AFFILIATION				ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION				ACCESSION NUMBER	SUBJECT CATEGORY
FPL - Florida Power & Light Co				7907130364	50-302 S				7907100160	50-321 Q	
				7907180553*	50-302 S				7907100135	50-424 Q	
				7907180518	50-302 S				7907100173	50-424 Q	
				7907190528	50-302 F						
				7907180548	50-302 S				7907100135	50-424 Q	
									7907100173	50-424 Q	
				7907170119	50-302 P				7907180163	50-424 Q	
				7907170127*	50-302 P				7907180058	50-321 Q	
				7907190440	50-302 R				7907090144	50-424 Q	
				7907230524	50-302 J						
				7907300358*	50-302 S				7907240270*	50-424 Q	
									7907190355	50-321 Q	
				7907300344	50-302 S				7907020248	50-366 S	
				7907300343	50-302 Q				7907020253*	50-366 S	
				7907110408	50-251 S				7907260136	50-366 Q	
				7907110412*	50-251 S						
				7907060156	PR				7907240269*	50-424 Q	
									7907020259	50-366 S	
				7907230080*	50-389 Q				7907020264*	50-366 S	
				7907110722	50-250 Q				7907020283	50-366 S	
				7907190392	50-335 Q				7907020294*	50-366 S	
				7907060263	50-250 Q						
				7907050121	50-335 Q				7907020302	50-366 S	
				7907180286	PR				7907020308*	50-366 S	
				7907190603	REGD				7907250086	50-366 Q	
				7907120280	50-250 Q				7907100545	50-321 P	
				7907180180	50-250 Q				7907030194	50-366 S	
				7907120280	50-250 Q						
									7907090360	50-366 S	
				7907180180	50-250 Q				7907090363*	50-366 S	
				7907120280	50-250 Q				7907060234	50-321 R	
				7907180180	50-250 Q				7907060346	50-321 S	
				7907100094	50-250 Q				7907060348*	50-321 S	
				7907130305	50-250 Q						
									7907050372	50-366 S	
				7907240020*	50-250 Q				7907050376*	50-366 S	
				7907130305	50-250 Q				7907060234	50-321 R	
				7907240020*	50-250 Q				7907110357	50-366 S	
				7907130321	50-335 Q				7907110362	50-366 S	
				7907130415	50-335 Q						
								7907090330	50-366 S		
			7907160034*	50-389 Q				7907060236*	50-321 R		
			7907160044*	50-389 Q				7907050357	50-321 I		
			7907190233	50-250 Q				7907090373	50-321 S		
			7907090140	50-250 Q				7907090376*	50-321 S		
			7907190401	50-335 Q							
								7907100350	50-321 R		
			7907260035	50-250 P				7907100369	50-321 S		
			7907190060	50-389 Q				7907050357	50-321 I		
			7907190583	50-389 Q				7907060305	50-366 S		
			7907190142	50-250 Q				7907090336	50-366 S		
			7907090303	50-250 S							
								7907090344*	50-366 S		
			7907090311*	50-250 S				7907100350	50-321 R		
			7907310191	50-389 Q				7907120301	50-366 P		
			7907310184	50-389 Q				7907050357	50-321 I		
			7907310199	50-389 Q				7907100437	50-321 Q		
			7907090350	50-251 S							
								7907170133	50-321 S		
			7907090371*	50-251 S				7907170214	50-321 S		
			7907170101*	50-250 S				7907170218*	50-321 S		
			7907120599	50-389 A				7907100437	50-321 Q		
			7907090337	50-250 S				7907170222*	50-321 R		
			7907030384	50-302 P							
								7907180498	50-321 S		
			7907090280	50-335 S				7907180499*	50-321 S		
			7907090220	50-335 P				7907170100	50-366 S		
			7907120634	50-335 S				7907170105*	50-366 S		
			7907120641*	50-335 S				7907180545	50-366 S		
			7907180312	50-335 S							
								7907180551*	50-366 S		
			7907180328*	50-335 S				7907170066	50-321 P		
			7907170098	50-250 S				7907170069*	50-321 P		
			7907170179	50-250 S				7907170073*	50-321 P		
			7907170195*	50-250 S				7907170220	50-321 R		
			7907170188	50-251 S							
								7907170066	50-321 P		
			7907170164*	50-251 S				7907170069*	50-321 P		
			7907170170	TDPREP				7907170073*	50-321 P		
			7907180557	50-251 S				7907170220	50-321 R		
			7907180565*	50-251 S				7907190564	50-366 R		
			7907250335	50-335 S							
								7907170206	50-321 S		
			7907250341*	50-335 S				7907170209*	50-321 S		
			7907240362	50-250 Q				7907170089	50-366 S		
			7907260661	50-250 F				7907170096*	50-366 S		
			7907110482*	50-321 S				7907170216	50-366 S		
			7907110485*	50-321 S							
								7907170219*	50-366 S		
			7907110478	50-321 S				7907230480	50-366 S		
			7907110491*	50-321 S				7907230482*	50-366 S		
			7907110517*	50-366 S				7907170056	50-321 S		
			7907110506	50-366 S				7907170060*	50-321 S		
			7907110400	50-366 S							
								7907170087	50-321 S		
			7907110407*	50-366 S				7907170091*	50-321 S		
			7907110588	50-366 S				7907230195	50-366 K		
			7907110594*	50-366 S				7907230209*	50-366 K		
			7907100360*	50-321 R				7907230280	50-321 F		
			7907050394*	50-321 I							
								7907230335	50-321 S		
			7907190095*	50-321 Q				7907230541*	50-321 S		
			7907190243	50-321 Q				7907240339	50-321 P		
								7907250280	50-321 F		

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907230473*	50-366 S		7907030381*	50-219 S
	7907240339	50-321 P		7907100399	50-219 R
	7907200337	50-321 P		7907250354*	50-219 R
	7907200341*	50-321 P		7907280350	50-219 R
	7907230477	50-366 S		7907100107	50-320 P
	7907230486*	50-366 S			
	7907230546	50-366 S		7907260593*	50-219 S
	7907230553*	50-366 S		7907260587	50-219 S
	7907230467	50-366 S		7907270170	50-219 S
	7907240224	50-366 S		7907270202*	50-219 S
	7907260840	50-321 S	KSSE - Kansas Gas & Electric Co	7907110690*	50-482 Q
	7907260847*	50-321 S		7907260079	50-482 S
	7907230516	50-366 S		7907300027	50-482 S
	7907230519*	50-366 S		7907230355*	50-482 Q
	7907260799	50-366 S		7907270291*	50-482 Q
	7907260813*	50-366 S		7907260607	50-482 S
	7907260824	50-366 S		7907310357*	50-482 A
	7907260833*	50-366 S		7907180530	50-482 S
	7907260891	50-321 P	LAPL - Louisiana Power & Light Co	7907180537*	50-482 S
	7907260746	50-366 P		7907110677*	50-382 Q
	7907260751*	50-366 P		7907240118*	50-382 Q
	7907270187	50-366 P		7907260063	50-382 Q
	7907270195*	50-366 P		7907060012	50-382 H
GEP - General Public Utilities	7907110077	50-320 P		7907260070	50-382 Q
	7907100045	50-320 P		7907090227	50-382 S
	7907110111*	50-320 D		7907260621	50-382 S
	7907100334*	50-320 Q		7907200249	50-382 A
GPU - GPU Service Corp	7907020107	50-320 P		7907240214	50-382 F
	7907180055*	50-320 T		7907240346	50-382 K
	7907050564	50-320 U		7907240349*	50-382 K
	7907180030*	50-320 T		7907300347	50-382 K
	7907180041*	50-320 T	LIL - Long Island Lighting Co	7907110395	50-322 Q
	7907130284	50-320 P		7907050524	50-322 Q
GSU - Gulf States Utilities Co	7907260763	50-458 S		7907110308	50-322 Q
	7907260768*	50-458 S		7907180758*	50-322 Q
	7907180498	50-510 H		7907300512	50-516 Q
	7907310618	50-498 Q		7907180718	50-322 Q
HLP - Houston Lighting & Power Co	7907310607	50-498 Q		7907120623	50-322 S
	7907240125*	50-498 Q		7907180547	50-322 A
	7907190586	50-466 Q		7907180561	50-322 A
	7907170147	50-498 K	MEED - Metropolitan Edison Co	7907100236*	50-320 R
				7907110521*	50-320 Q
	7907170151*	50-498 K		7907100244*	50-320 R
	7907260657	50-498 S		7907100255*	50-320 R
	7907170147	50-498 K		7907180034*	50-320 T
	7907170151*	50-498 K		7907180037*	50-320 T
	7907260657	50-498 S			
	7907300094*	50-331 Q		7907180046*	50-320 T
IELP - Iowa Electric Light & Power Co	7907050220	50-331 P		7907110122*	50-320 Q
	7907110261	50-331 Q		7907110129*	50-320 Q
	7907300095*	50-331 Q		7907110146*	50-320 Q
	7907090242	50-331 P		7907090240	50-289 Q
	7907100560	50-331 P		7907110241*	50-320 Q
	7907100562	50-331 S		7907180854	50-320 Q
	7907190574*	50-331 R		7907190516	50-289 S
	7907200366	50-331 S		7907190598	50-289 S
	7907200373*	50-331 S		7907050379	50-320 P
	7907190571	50-331 R		7907100654*	50-289 R
	7907230555	50-331 S		7907050379	50-320 P
	7907230559*	50-331 S		7907110323	50-289 S
ILPR - Illinois Power Co	7907190250	50-461 N		7907100653	50-289 R
				7907110514	50-289 F
IMPR - Indiana & Michigan Power Co.	7907050046	50-315 Q		7907180472	50-289 S
				7907180475*	50-289 S
	7907030457	50-315 P		7907270194*	50-289 R
	7907200321*	50-315 R		7907180477	50-289 S
	7907200333*	50-316 R		7907180482*	50-289 S
	7907200317	50-315 R			
	7907200329	50-316 R		7907170077	50-289 F
				7907190568	50-289 F
	7907190515	50-315 S		7907190581*	50-289 F
	7907190520*	50-315 S		7907200302	50-289 P
	7907190532	50-316 S		7907230626	50-320 P
	7907190537*	50-316 S			
	7907230365	50-315 P		7907230633*	50-320 P
				7907170189	50-289 P
	7907280253	50-316 S		7907270190	50-289 R
	7907280268*	50-316 S		7907270269	50-320 P
	7907260697	50-315 P		7907270275*	50-320 P
	7907260705	50-315 J			
	7907260697	50-315 P	MPL - Mississippi Power & Light Co.	7907190332	50-416 Q
				7907190557	50-416 Q
	7907260705	50-315 J		7907190332	50-416 Q
	7907300325	50-316 S		7907190557	50-416 Q
	7907300337*	50-316 S		7907190303*	50-416 Q
JCPL - Jersey Central Power & Light Co.	7907060434*	50-219 P			
	7907050223	50-219 Q		7907030490	50-416 S
				7907030493*	50-416 S
	7907090390	50-363 Q		7907090324	50-416 S
	7907190223	50-363 Q		7907190523	50-416 S
	7907100402*	50-219 R		7907190524*	50-416 S
	7907020180	50-219 F			
	7907030779	50-214 S		7907030490	50-416 S
				7907030493*	50-416 S



## CORPORATE SOURCE INDEX

449

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907090324	50-416 B		7907270245	50-367 R
	7907190323	50-416 B	NHP - Niagara Mohawk Power Corp	7907300179*	50-220 G
	7907190324*	50-416 B		7907300181*	50-220 G
	7907050346	50-416 A		7907060420	50-220 G
	7907050321	50-416 K		7907130129	50-220 G
	7907050326*	50-416 K		7907020491	50-410 G
	7907060191	50-416 A		7907190679	PRM
	7907050321	50-416 K		7907300372*	50-410 G
	7907080324*	50-416 K		7907230038*	50-220 G
	7907060191	50-416 A		7907300148	50-220 G
	7907200390	50-416 A		7907030283	50-220 J
	7907250256	50-416 H		7907030304	50-220 J
NYAP - Maine Yankee Atomic Power Co	7907090102	50-309 G		7907050338	50-220 B
	7907050258	50-309 G		7907080354*	50-220 B
	7907050262	50-309 G		7907050373	50-410 G
	7907110561	50-309 B		7907060339	50-410 A
	7907110566*	50-309 B		7907130381	50-220 B
	7907170116	50-309 R		7907130382*	50-220 B
	7907170118*	50-309 R		7907130383*	50-220 B
	7907260590	50-309 P		7907130444	50-220 R
	7907300441	50-309 P		7907130448*	50-220 R
	7907310247	50-309 P		7907170225	50-220 R
NENE - Northeast Nuclear Energy Co (Northeast Utilities)	7907050270	PR		7907200438	50-220 P
	7907050160	50-213 G		7907250351	50-410 A
	7907100018	50-336 G		7907230151*	50-220 P
	7907050160	50-213 G	NPPD - Nebraska Public Power District	7907260654	50-220 P
	7907090385	50-423 G		7907260162	50-298 G
	7907130333	50-336 B		7907090392*	50-298 G
	7907130373*	50-336 B		7907060402	50-298 G
	7907230474	50-336 B		7907170054	50-298 B
	7907230487*	50-336 B		7907170057*	50-298 B
NEEP - New England Power Co	7907100380	50-568 A		7907170063	50-298 B
NEUT - Northeast Utilities	7907120657*	50-245 P		7907170065*	50-298 B
	7907110607	50-245 G		7907170079	50-298 B
	7907020225	50-293 G		7907170082*	50-298 B
	7907110640	50-336 G		7907030423	50-298 G
	7907030310	FDIA		7907170027	50-298 B
	7907080556	50-245 P		7907170061*	50-298 B
	7907080233	50-245 G		7907110424	50-298 F
	7907100129	50-336 B		7907170233	50-298 R
	7907020458	50-336 G		7907170234*	50-298 R
	7907190090	50-423 G		7907170194	50-298 P
	7907190106	50-423 G		7907170198*	50-298 P
	7907260183	50-245 G		7907200260	50-298 P
	7907050316	50-336 G		7907200353	50-298 F
	7907050318*	50-336 G		7907240325	50-298 F
	7907100406*	50-336 B		7907260752	50-298 F
	7907090304	50-245 B	NSP - Northern States Power Co	7907030275*	50-282 R
	7907090306*	50-245 B		7907020346	50-263 G
	7907090302*	50-245 B		7907060250	50-263 G
	7907050257	50-245 P		7907160242	50-367 G
	7907090300	50-245 B		7907110291	50-282 G
	7907050257	50-245 P		7907100116	50-263 G
	7907060282	50-336 G		7907160148	50-282 G
	7907090261*	50-245 P		7907090428	50-263 P
	7907120638	50-245 P		7907300549	50-484 G
	7907120647*	50-245 P		7907300455	50-282 G
	7907120638	50-245 P		7907030340	50-263 B
	7907120647*	50-245 P		7907030344*	50-263 B
	7907100388	50-336 B		7907030272	50-282 R
	7907170088	50-336 B		7907050300	50-282 B
	7907170092*	50-336 B		7907050303*	50-282 B
	7907170112	50-336 B		7907050404	50-282 B
	7907180470*	50-336 R		7907050414*	50-282 B
	7907170115*	50-336 B		7907030272	50-282 R
	7907200259*	50-245 R		7907090202	50-282 B
	7907200349	50-245 P		7907180516*	50-282 R
	7907170224	50-336 B		7907090202	50-282 B
	7907170229*	50-336 B		7907180516*	50-282 R
	7907180466	50-336 R		7907100618	50-263 F
	7907260737	50-213 P		7907100618	50-263 F
	7907200256	50-245 R		7907130469	50-282 B
	7907260725	50-245 B		7907130473*	50-282 B
	7907260737	50-213 P		7907160346	50-282 B
	7907260589	50-336 B		7907170001	50-263 R
	7907260592*	50-336 B		7907180511	50-282 R
	7907230578	50-213 F		7907190211	50-282 P
	7907310339	50-336 P		7907310381	50-263 F
NIPB - Northern Indiana Public Service Co	7907020310	50-367 A		7907310388	50-282 F
	7907090424	50-367 G	NYEQ - New York State Electric & Gas Corp.	7907170016*	50-596 C
	7907060232	50-367 R		7907170012	50-596 C
	7907130044*	50-367 R		7907310241	50-596 A
	7907130039	50-367 R		7907310266	50-596 B
	7907120587	50-367 R		7907310269*	50-596 B
	7907230566	50-367 R		7907310241	50-596 A

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
OEC - Ohio Edison Co	7907310266	50-596 B		7907050446	50-277 Q
	7907310269*	50-596 B		7907020090	50-277 Q
DPPD - Omaha Public Power District	7907130109	REQD		7907050446	50-277 Q
	7907130030	REQD		7907050221	50-277 S
	7907020213	50-285 Q		7907090089	50-277 Q
	7907060258	50-285 Q		7907180914	50-277 Q
	7907060268	50-285 Q		7907090089	50-277 Q
	7907060254	50-285 Q		7907180914	50-277 Q
	7907090293*	50-285 P		7907190003	50-277 S
	7907230543*	50-285 S		7907050446	50-352 Q
	7907030346	50-285 P		7907060244	50-352 Q
	7907030485	50-285 P		7907130516	50-352 Q
	7907030444*	50-285 P		7907050446	50-352 Q
	7907090198	50-285 P		7907060244	50-352 Q
	7907090291	50-285 P		7907130516	50-352 Q
	7907090230*	50-285 P		7907190080	50-277 Q
	7907160310	50-285 P		7907190074	50-352 Q
	7907180398*	50-285 R		7907300115	50-277 S
	7907200364	50-285 F		7907190367	50-278 S
	7907180395	50-285 R		7907190406	50-278 S
	7907180584*	50-285 P		7907190331	50-277 S
	7907180593*	50-285 P		7907090296	50-278 S
	7907230533	50-285 S		7907090298*	50-278 S
	7907180599*	50-285 P		7907190331	50-277 S
	7907250262	50-285 F		7907110533	50-277 P
	7907260772	50-285 F		7907120361	50-277 P
PACP - Pacific Power & Light Co	7907180368	50-522 Q		7907120368*	50-277 P
PABN - Power Authority State of New York	7907030058*	50-333 Q		7907120361	50-277 P
	7907130437	50-333 P		7907120368*	50-277 P
	7907130439*	50-333 P		7907120362	50-278 S
	7907190263	PRM		7907120597*	50-278 S
	7907120066	50-333 Q		7907170157	50-278 S
	7907190278	50-333 Q		7907170166*	50-278 S
	7907090094	50-220 Q		7907130374	50-171 J
	7907310107*	50-333 Q		7907130326	50-277 J
	7907050133	50-333 Q		7907130374	50-171 J
	7907120030	50-286 Q		7907130326	50-277 J
	7907240045	71-6375		7907130374	50-171 J
	7907050249	50-286 Q		7907230522	50-278 S
	7907190861	50-286 Q		7907130428	50-277 R
	7907240080	71-6144		7907130431*	50-277 R
	7907190694	50-286 Q		7907130428	50-277 R
	7907090421	50-333 Q		7907130431*	50-277 R
	7907030463	50-333 P		7907170102	50-277 S
	7907020228	50-286 Q		7907180504	50-277 S
	7907020270	50-333 P		7907180509*	50-277 S
	7907050363	50-333 P		7907180504	50-277 S
	7907100609*	50-333 R		7907180509*	50-277 S
	7907170010*	50-286 R		7907260632	50-171 R
	7907100601	50-333 F		7907260639*	50-171 R
	7907090383	50-286 Q		7907270206	50-277 S
	7907100590	50-286 P		7907270221*	50-277 S
	7907100423	50-286 S		7907270206	50-277 S
	7907100432*	50-286 R		7907270221*	50-277 S
	7907100607	50-333 R		7907270238	50-278 S
	7907130460	50-333 S		7907270247	50-278 S
	7907130467*	50-333 S	POE - Pacific Gas & Electric Co	7907130116	REQD
	7907170046	50-286 Q		7907130496	50-275 Q
	7907170007	50-286 R		7907130118*	50-275 Q
	7907170030	50-333 S		7907190381	50-275 Q
	7907170039*	50-333 S		7907270376	70-1738
	7907200301	50-286 F		7907270382*	70-1738
	7907200283	50-286 Q		7907270376	70-1738
	7907200291	50-286 R		7907270382*	70-1738
	7907230462	50-286 F		7907090398	50-275 Q
	7907240293	50-286 P		7907020452	50-275 Q
	7907230287	50-333 S		7907090161	50-133 Q
	7907230292*	50-333 S		7907130110	50-275 Q
	7907230494	50-333 P		7907230204	50-522 Q
	7907230497*	50-333 F		7907180728	FRQJ
	7907270218	50-286 Q		7907180409*	50-133 R
	7907260646	50-333 S		7907090206	50-275 A
	7907260652*	50-333 S		7907180402	50-133 R
	7907260741	50-333 S		7907190323	50-293 S
	7907260747*	50-333 S		7907230242	50-133 P
PECO - Philadelphia Electric Co	7907130077*	50-463 Q		7907240234	50-275 F
	7907250093*	50-277 Q	POGE - Portland General Electric Co.	7907260643	50-275 F
	7907200510	PR		7907100414*	50-514 R
	7907110719*	50-277 Q		7907100408	50-514 R
	7907090325	PRM		7907090245	50-344 S
	7907160139	REQD		7907030407	50-344 Q
	7907190859	PR		7907050051	50-514 Q
	7907110644*	50-277 Q		7907050400	50-344 Q
	7907230348*	50-352 Q		7907190366	50-344 Q
	7907050446	50-277 Q		7907190375*	50-344 Q
	7907020090	50-277 Q		7907190370*	50-344 Q

# CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907090183	50-344 C		7907050347	50-311
	7907090146	50-344 Q		7907090276	50-272
	7907190600*	50-344 F		7907090277*	50-272
	7907250204	50-522 Q		7907110519	50-272
	7907130081	50-344 Q		7907110402	50-272
	7907180739	50-344 Q		7907170028	50-311
	7907240364	50-514 Q		7907160307	50-272
	7907180539	50-522 Q		7907160311*	50-272
	7907180712	50-344 Q		7907190514	50-311
	7907030432	50-344 Q		7907190527	50-311
	7907050370	50-344 B		7907190588	50-311
	7907020230	50-514 A		7907250375	50-311
	7907030462	50-344 P		7907250247	50-311
	7907110422	50-344 B		7907250330	50-311
	7907110425*	50-344 B		7907260582	50-272
	7907110474	50-344 P		7907260586*	50-272
	7907120608	50-344 R		7907260713	50-272
	7907120613*	50-344 R		7907270160	50-272
	7907120635	50-344 J		7907270168	50-272
	7907110479	50-344 P		7907270168	50-272
	7907170175	50-344 P		7907260724*	50-272
	7907190590	50-344 F		7907310364	50-272
	7907240330	50-344 P		7907310372*	50-272
	7907300366	50-344 F			
	7907300373*	50-344 F			
PPL - Pennsylvania Power & Light Co	7907170051*	50-387 A	PSIN - Public Service Co of Indiana, Inc	7907090339	PRM
	7907230572*	50-387 Q		7907110267	50-346
	7907110672*	50-387 Q		7907100111	50-346
	7907050354	50-387 Q		7907100214	50-346
	7907190011*	50-387 Q		7907100111	50-346
	7907200484*	50-387 Q		7907100214	50-346
	7907260087	50-387 Q		7907300533	50-346
	7907260192	50-387 Q		7907100368	50-346
	7907260087	50-387 Q		7907120618	50-346
	7907260192	50-387 Q		7907120633	50-346
	7907260156	50-387 Q		7907190561	50-346
	7907030353*	50-387 K		7907120633	50-346
	7907030327	50-387 S		7907120633	50-346
	7907030349	50-387 K		7907120633	50-346
	7907170045	50-387 A	PSNH - Public Service Co of New Hampshire	7907240212*	50-443
	7907260651	50-387 B	PSOK - Public Service Co of Oklahoma	7907020197	50-556
	7907260457	50-387 A			
	7907270258	50-387 S		7907170193	50-556
PSC - Public Service Co of Colorado	7907260166	50-267 Q		7907200274	50-556
	7907240445	50-267 P	PSPL - Puget Sound Power & Light Co	7907090002*	50-522
	7907190699	50-267 Q		7907250204	50-522
	7907190707	50-267 Q		7907090002*	50-522
	7907300116*	50-267 Q		7907250204	50-522
	7907060229*	50-267 R		7907060201*	50-522
	7907050351	50-267 P		7907060196	50-522
	7907060212	50-267 R		7907170042	50-522
	7907120106*	50-267 R		7907060196	50-522
	7907120632	50-267 B		7907170042	50-522
	7907120638*	50-267 B			
	7907120663*	50-267 B	ROE - Rochester Gas & Electric Corp	7907050240*	50-244
	7907120101	50-267 R		7907050228	50-244
	7907180487	50-267 P		7907050396	50-244
	7907170136	50-267 P		7907110302	50-485
	7907200267*	50-267 P		7907180110	50-485
	7907130388	50-267 B		7907050230	50-244
	7907130391*	50-267 B		7907020487	50-485
	7907180442	50-267 B		7907230481	50-244
	7907180444*	50-267 B		7907090259*	50-244
	7907180568	50-267 B		7907090256	50-244
	7907180575*	50-267 B		7907300389	50-244
	7907200264	50-267 P		7907030477	50-244
	7907250332	50-267 P		7907050361	50-244
PSEG - Public Service Electric & Gas Co of New Jersey	7907300571*	50-311 B		7907110324	50-244
	7907230008*	50-311 Q		7907060441	50-244
	7907020200	50-272 Q		7907060450*	50-244
	7907050443	50-354 Q		7907090253	50-244
	7907050456	50-272 Q		7907090268*	50-244
	7907250382*	50-311 E		7907050234	50-244
	7907060044	71-328		7907120594	50-244
	7907180114	50-354 Q		7907130250	50-244
	7907160144	50-354 Q		7907160401	50-244
	7907130200	50-354 Q		7907160401	50-244
	7907090213	50-272 B		7907160401	50-244
	7907130319*	50-272 Q		7907160401	50-244
	7907090319	50-311 A		7907160401	50-244
	7907100544*	50-311 A		7907160401	50-244
	7907170226	50-272 R		7907260596*	50-244
	7907170227*	50-272 R			
	7907100543	50-311 A	SC - The Southern Co.	7907050384*	50-321
	7907050301	50-272 B		7907190727	REOD
	7907050302*	50-272 B	SCE - Southern California Edison Co	7907030469*	50-206
				7907050382*	50-361

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907050413	50-206 Q		7907100463	50-346 S
	7907130531	50-361 Q		7907100472*	50-346 S
	7907050390	50-206 Q		7907110513	50-346 R
	7907090238	50-361 Q		7907110520*	50-346 R
	7907090233	50-361 Q			
	7907190108*	50-361 Q		7907100584	50-346 P
	7907100659*	50-361 S		7907100587*	50-346 P
	7907100603*	50-206 S		7907170079	50-346 F
	7907030465	50-206 P		7907170029	50-346 S
	7907030474	50-206 P		7907170034*	50-346 S
	7907100676*	50-361 S		7907230303	50-346 S
	7907100680*	50-361 S		7907240351	50-346 P
	7907100676*	50-361 S		7907310389	50-346 S
	7907100680*	50-361 S		7907310373*	50-346 S
	7907300382	50-206 Q		7907310422	50-346 S
	7907090252	50-361 K	TU - Texas Utilities Co	7907310473*	50-346 S
	7907100375	50-206 R	TUCC - Texas Utilities Generating Co	7907180879	50-445 H
	7907050378	50-361 A		7907110660*	50-445 Q
	7907100602	50-206 S		7907310595	50-445 Q
	7907170212	50-206 P		7907110660*	50-445 Q
	7907100598*	50-206 R		7907310595	50-445 Q
	7907100629	50-206 P		7907310600	50-445 Q
	7907120607	50-361 S		7907300236*	50-445 Q
	7907120610*	50-361 S		7907270305*	50-445 Q
	7907130459	50-361 A		7907260647	50-445 S
	7907120607	50-361 S		7907030382	50-445 S
	7907120610*	50-361 S		7907090247	50-445 A
	7907130459	50-361 A		7907110346	50-445 S
	7907090261	50-206 P		7907180552	50-445 S
	7907260666	50-361 A		7907190216	50-445 S
	7907190549	50-206 P		7907180552	50-445 S
	7907100595	50-206 R		7907190216	50-445 S
	7907310274	50-361 A		7907230298	50-445 S
	7907310286*	50-361 A	TUS - Texas Utilities Services, Inc	7907230284	50-445 S
	7907310274	50-361 A	TVA - Tennessee Valley Authority	7907250318	50-445 A
	7907310286*	50-361 A		7907100564*	50-390 Q
	7907190551*	50-206 P		7907100569*	50-390 Q
	7907100387*	50-206 R		7907100564*	50-390 Q
SCEC - South Carolina Electric & Gas Co	7907090346	PRM		7907100569*	50-390 Q
	7907050442	50-206 Q		7907060316*	50-327 A
	7907100100	50-395 Q		7907240381*	REQD
	7907090406	50-395 Q		7907170131*	50-327 A
	7907190340	50-395 Q		7907240377*	REQD
	7907030217	50-395 F		7907240368*	REQD
	7907050365	50-395 A		7907180602*	50-390 Q
	7907170067	50-395 S		7907130001	DRD
SMUD - Sacramento Municipal Utility District	7907090347*	50-312 Q		7907090395	PRM
				7907230763*	50-259 Q
	7907090352*	50-312 Q		7907240311	REQD
	7907090358*	50-312 Q		7907100179	50-259 Q
	7907090341*	50-312 Q			
	7907090377	50-312 Q		7907250454*	50-391 Q
	7907020471	50-312 Q		7907190207	50-327 Q
	7907020293	50-312 Q		7907310170	50-327 Q
	7907180871	50-312 Q		7907190207	50-327 Q
	7907020513*	50-312 Q		7907310170	50-327 Q
	7907170011*	50-312 P		7907190207	50-327 Q
	7907170014*	50-312 P		7907310170	50-327 Q
	7907100509	50-312 P		7907310170	50-327 Q
	7907050215	50-312 F		7907190207	50-327 Q
	7907180508*	50-312 R			
	7907050317	50-312 P		7907310170	50-327 Q
	7907180506	50-312 R		7907190207	50-327 Q
	7907300300	50-312 F		7907310170	50-327 Q
	7907170008	50-312 P			
	7907300408	50-312 Q			
	7907250391	50-312 P		7907190207	50-327 Q
	7907260759	50-312 S		7907310170	50-327 Q
	7907270180	50-312 S		7907190207	50-327 Q
	7907310352	50-312 P		7907310170	50-327 Q
TOED - Toledo Edison Co	7907060336*	50-346 S		7907190207	50-327 Q
	7907050015	50-346 Q		7907310170	50-327 Q
	7907090088	50-346 Q		7907190207	50-327 Q
	7907240196	50-346 P		7907310170	50-327 Q
	7907170203	50-346 P		7907190207	50-327 Q
	7907180270*	50-346 Q		7907310170	50-327 Q
	7907170201	50-346 P		7907190196	50-347 Q
	7907060335	50-346 S		7907300360*	50-390 Q
	7907110417	50-346 S		7907090388	50-318 S
	7907170005	50-346 P		7907090395*	50-318 S
	7907090258	50-346 S		7907090388	50-318 S
	7907300417*	50-346 S			
	7907100439	50-346 S		7907090395*	50-318 S
	7907100444*	50-346 S		7907230056	50-259 Q
	7907130380	50-346 P		7906220369	50-259 R
	7907100448	50-346 S		7907060357*	50-259 P
				7907090351	50-327 S
	7907100458*	50-346 S			
				7907090369*	50-327 S
				7907090351	50-327 S
				7907090369*	50-327 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907090316	50-327 S		7907260819	50-259 P
	7907090316*	50-327 S		7907260828*	50-259 P
	7907090331	50-438 S		7907260837	50-259 P
	7907090343*	50-438 S		7907260838*	50-259 P
	7907090331	50-438 S		7907260843*	50-259 P
	7907090343*	50-438 S		7907260846*	50-259 P
	7907030381	50-390 S		7907260854*	50-259 P
	7907030348	50-438 Q		7907270156	50-259 P
	7907030450	50-438 Q		7907260827	50-296 P
	7907030348	50-438 Q		7907260831*	50-296 P
	7907030450	50-438 Q		7907260764	50-259 P
	7907110349	50-259 S		7907260770*	50-259 P
	7907110352	50-259 S		7907260819	50-259 P
	7907110516	50-260 S		7907260828*	50-259 P
	7907110522	50-260 S		7907260838*	50-259 P
	7907110525	50-260 S		7907260854*	50-259 P
	7907190548	50-296 S		7907270156	50-259 P
	7907060309	50-327 A	UNE - Union Electric Co	7907260795*	50-438 S
	7907050304	50-260 S		7907250331*	50-327 A
	7907050305*	50-260 S	VEPC - Virginia Electric & Power Co	7907300516	50-483 Q
	7907030492	50-327 A		7907120027*	50-338 Q
	7907060309	50-327 A		7907060333*	50-338 S
	7907060188	50-259 P		7907060334*	50-338 S
	7907060354	50-259 P		7907190816	50-338 S
	7907060188	50-259 P		7907250447	50-338 S
	7907060354	50-259 P		7907090248	50-338 S
	7907060188	50-259 P		7907020032	50-338 Q
	7907060354	50-259 P		7907120021*	50-338 Q
	7907060354	50-259 P		7907020477	50-404 Q
	7907060354	50-259 P		7907100131	50-338 Q
	7907060354	50-259 P		7907100062	50-280 Q
	7907170156*	50-259 R		7907190061*	50-280 Q
	7907110452	50-259 P		7907100062	50-280 Q
	7907100599	50-259 Q		7907190061*	50-280 Q
	7907100615	50-259 Q		7907100062	50-280 Q
	7907100479	50-260 S		7907100186	50-339 Q
	7907100482*	50-260 S		7907100183	50-404 Q
	7907100556	50-390 Q		7907100206	50-404 Q
	7907170190	50-259 P		7907100183	50-404 Q
	7907170036	50-390 S		7907100206	50-404 Q
	7907170041*	50-390 S		7907180145	50-280 Q
	7907170036	50-390 S		7907190511	50-339 Q
	7907170120	50-259 R		7907180670*	50-280 Q
	7907170124	50-327 A		7907310276	50-281 B
	7907170140*	50-327 A		7907090195	50-280 Q
	7907180484	50-390 S		7907190252	50-280 Q
	7907180491*	50-390 S		7907310190*	50-338 Q
	7907180533	50-390 S		7907130478*	50-338 Q
	7907180484	50-390 S		7907230014*	50-338 Q
	7907180491*	50-390 S		7907190347	50-339 Q
	7907180533	50-390 S		7907300342*	50-280 Q
	7907170058	50-259 Q		7907090359	50-339 B
	7907170107	50-259 S		7907310010*	50-338 Q
	7907170113*	50-259 S		7907200394	50-280 B
	7907170058	50-259 Q		7907090329	50-338 S
	7907170200	50-296 S		7907200392	50-280 B
	7907170205*	50-296 S		7907090282	50-281 B
	7907180566	50-296 Q		7907130407	50-280 P
	7907180497	50-390 S		7907030272*	50-338 P
	7907180501*	50-390 S		7907090310*	50-338 P
	7907180497	50-390 S		7907050292*	50-338 P
	7907180501*	50-390 S		7907090310*	50-338 P
	7907180531	50-260 S		7907030300	50-338 P
	7907180536*	50-260 S		7907030421	50-338 B
	7907200376	50-327 Q		7907030425*	50-338 B
	7907180496	50-390 S		7907030429*	50-338 S
	7907180513*	50-390 S		7907310451	50-338 P
	7907180496	50-390 S		7907030300	50-338 P
	7907180513*	50-390 S		7907050360	50-404 S
	7907250324	50-327 A		7907170004*	50-280 R
	7907250306	50-327 A		7907050286	50-280 R
	7907260779	50-438 S		7907050289*	50-280 R
	7907250272	50-259 P		7907060291	50-280 B
	7907260764	50-259 P		7907060296*	50-280 S
	7907260770*	50-259 P		7907050286	50-280 R
	7907260819	50-259 P		7907050289*	50-280 R
	7907260828*	50-259 P		7907050296	50-338 Q
	7907260837	50-259 P		7907060331	50-338 S
	7907260838*	50-259 P		7907060332*	50-338 S
	7907260838*	50-259 P		7907120562	50-339 S
	7907260843*	50-259 P		7907050291	50-338 P
	7907260846*	50-259 P		7907090269*	50-338 B
	7907260854*	50-259 P		7907090285*	50-338 S
	7907270156	50-259 P		7907090307	50-338 P
	7907260764	50-259 P		7907190272*	50-338 R
	7907260770*	50-259 P		7907050291	50-338 P
				7907090307	50-338 P

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907090372	50-280 S		7906210227	50-397 A
	7907090380*	50-280 S		7907240326*	50-397 B
	7907090384*	50-280 S		7907250314*	50-397 S
	7907090338	50-338 P		7906210238*	50-397 A
	7907300456	50-280 Q		7907300114*	50-508 Q
	7907100581	50-338 P		7907310294*	50-397 K
	7907110541*	50-338 S		7907240320*	50-397 B
	7907110531	50-338 S		7907110508	50-508 A
	7907170221*	50-338 S		7907310289	50-397 K
	7907130266	50-338 R		7907200331	50-513 A
	7907170002	50-280 R		7907250310	50-397 S
	7907170215	50-338 S		7907260511	50-397 A
	7907190432	50-339 A		7907260515*	50-397 A
	7907170129	50-280 J	WPSC - Wisconsin Public Service Corp	7907300452	50-305 Q
	7907170019	50-338 P		7907050307	50-305 S
	7907200327	50-281 P		7907050309*	50-305 S
	7907190556	50-339 A		7907050313*	50-305 S
	7907190558*	50-339 A		7907090281	50-305 S
	7907230576*	50-338 S		7907090287*	50-305 S
	7907230580*	50-338 S		7907090294*	50-305 S
	7907250260	50-338 Q		7907090299*	50-305 S
	7907250326	50-339 S		7907090309	50-305 S
	7907230571	50-338 S		7907090312*	50-305 S
	7907250316	50-281 P		7907130436	50-305 R
	7907260406	50-338 F		7907130438*	50-305 R
	7907260804	50-338 P		7907170081	50-305 S
	7907260406	50-338 F		7907170083*	50-305 S
	7907270185	50-338 P		7907170090*	50-305 S
	7907270191	50-338 P		7907170022	50-305 S
	7907270185	50-338 P		7907170033*	50-305 S
	7907270191	50-338 P		7907180521	50-305 P
	7907310440	50-280 P		7907190555	50-305 P
	7907310436*	50-338 S		7907190560*	50-305 P
	7907310255	50-280 P		7907300354	50-305 F
	7907310424	50-280 S	WWPC - Washington Water Power Co	7907060205*	50-522 A
	7907310427*	50-280 S	YAE - Yankee Atomic Electric Co	7907100433*	50-29 P
	7907310255	50-280 P		7907310163*	50-29 Q
	7907300309	50-338 S		7907090076	50-29 Q
	7907310255	50-280 P		7907050153	50-29 Q
	7907310430	50-338 S		7907190684	50-29 Q
	7907310255	50-280 P		7907180745	50-29 P
	7907310446	50-339 A		7907300461	50-29 Q
VYNP - Vermont Yankee Nuclear Power Corp	7907170013*	50-271 P		7907020202	50-29 Q
	7907020455	50-271 Q		7907020207*	50-29 Q
	7907050255	50-271 Q		7907100427	50-29 P
	7907170230	50-271 F		7907310437	50-29 P
	7907030373	50-271 Q		7907090255	50-29 F
	7907030375	50-271 P	YAE - Yankee Atomic Electric Co	7907100594	50-29 P
	7907120372	50-271 P		7907100485	50-29 S
	7907170009	50-271 P		7907100489*	50-29 S
	7907170149	50-271 F		7907100493	50-29 S
	7907170148	50-271 R		7907100500*	50-29 S
	7907170152*	50-271 R		7907130283	50-29 F
	7907260593	50-271 S		7907180495	50-29 J
	7907260599*	50-271 S		7907170145	50-29 P
	7907310434	50-271 P		7907170168	50-29 R
	7907300303	50-271 P		7907170172*	50-29 R
WIEP - Wisconsin Electric Power Co	7907230419	REQD			
	7907110240	50-266 Q	RESEARCH INSTITUTIONS AND LABORATORIES		
	7907130162	50-266 Q	Argonne National Laboratory	7907060245	RES
	7907260968	PR		7907110283	NUREQ
	7907030372	50-301 P		7907170231	NUREQ
	7907100338	50-502 C		7907250288	NUREQ
	7907100605	50-302 J		7907180182	NUREQ
	7907230267	50-266 S		7907300047	NUREQ
	7907250277*	50-266 S		7907190510	NUREQ
	7907250267	50-266 S		7907270366	NUREQ
	7907250277*	50-266 S		7907110706	50-295 Q
	7907170163*	50-266 K		7907090003*	50-522 Q
	7907160321	50-266 P		7907250403	NUREQ
	7907170160	50-266 R		7907050145	NUREQ
	7907160321	50-266 P	Benton City Technology	7907260711*	50-320 P
	7907170160	50-266 R	Battelle Memorial Institute, Columbus Laboratories		
	7907300286	50-266 Q		7907260716*	50-320 F
WPB - Washington Public Power Supply System	7907190801	PRM		7907110635	NUREQ
	7907120456*	50-460 Q		7907300381	RES
	7907030088*	50-397 Q		7907300029	71-590B
	7907030084*	50-397 Q		7907300448	RES
	7907090227	50-397 Q		7907300458	RES
	7907180069	50-397 Q		7907310452	71-605B
	7907090237	50-397 Q		7907300436	RES
	7907180076	50-508 Q		7907300467	RES
	7907090237	50-397 Q		7907190637	RES
	7907180076	50-508 Q		7907170187	NUREQ
	7907090237	50-397 Q		7907190711	NUREQ
	7907090275	50-460 Q		7907310219	RES
				7907310208	RES

## CORPORATE SOURCE INDEX

41

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907310555	RES	Los Alamos Scientific Laboratory	7907170167	NUREG
	7907110235*	70-364		7907120156	NUREG
	7907300068	NUREG		7907030434	NUREG
	7907310620	RES		7907190192	NUREG
	7907100684	70-2623		7907250538	NUREG
	7907030243	RES		7907300527	RES
	7907250514	NUREG	Lawrence Livermore Laboratory	7907310035	NUREG
	7907060365*	50-295 G		7907170204	NUREG
	7907300489	RES		7907120097	RES
	7907170197	NUREG		7907120146	RES
	7907300554	RES		7907050149	NUREG
Brookhaven National Laboratory	7907310068	NUREG		7907190218	NUREG
	7907260412*	50-272 G		7907250299	NUREG
	7907240085	NUREG		7907250307	NUREG
	7907300353	50-266 F		7907270404	NUREG
	7907110483	RES	Navy, Dept of, Naval Research Laboratory	7907100672	NUREG
	7907120039	TOPREP	Opinion Research Corp	7907090464*	FDIA
	7907130237*	70-2623	Oak Ridge National Laboratory	7907090429	RES
	7907100533	50-282 F		7907120082	RES
	7907310175	50-282 F		7907300368	RES
	7907100533	50-282 F		7907060446	RES
	7907310175	50-282 F		7907110064	RES
	7907310109	RES		7907060455	RES
	7907230513	50-10 F		7907120070	RES
	7907310186	50-10 F		7907300282	RES
	7907310133	RES		7907120062	RES
	7907310149	RES		7907030426	NUREG
	7907300585	RES		7907300306	RES
Energy Research Group, Inc	7907190405	WASTE MGT		7907060442	NUREG
Electric Power Research Institute	7907060289	50-448 A		7907190169	NUREG
				7907190488	NUREG
Franklin Institute	7907300166*	50-220 Q		7907300507	RES
	7907300160*	50-220 Q		7907190675	RES
	7907090244	ACRS		7907300421	RES
Gesellschaft für Reaktorsicherheit	7906210421*	50-466 G		7907300541	RES
Hanford Engineering Development Laboratory	7907050279*	71-6387		7907030441	NUREG
				7907190801	NUREG
	7907270357	NUREG	Rockwell International Energy Systems Group	7907300099	NUREG
	7907050273	71-6387		7907110616	70-25
	7907190341	NUREG			
Idaho National Engineering Laboratory	7907270400	NUREG	Sandia Laboratories	7907260470	50-320 P
	7907300057	NUREG		7907120056	RES
	7907170110	NUREG		7907260563	NUREG
	7907170121	NUREG		7907130027	REORG
	7907240126	NUREG		7907190014*	50-437 A
	7907270388	NUREG		7907110437*	50-358 Q
Kinetic Research, Inc	7907030317	FDIA	Woods Hole Oceanographic Institute	7907230211	PR





# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Commission	7907230611*	COMMISSION
	7907160166*	70-143
	7907160159*	70-143
	7907270220*	COMMISSION
	7907250276	10CFR
	7907030134*	FOIA
	7907090186*	SECY
	7907060147	50-309 H
	7907190210	50-16 P
	7907190219*	50-16 P
	7907090053*	SECY
	7907260319	50-320 H
	7907060368	COMMISSION
	7907300465	COMMISSION
	7907060414	COMMISSION
	7907180757*	FOIA
	7907180750*	FOIA
	7907180733*	FOIA
	7907180742*	FOIA
	7906110416	50-320 U
	7907110309	COMMISSION
	7907180896	27-39
	7907100666	50-201 H
	7907030360	10CFR
	7907060295	COMMISSION
	7907030366	10CFR
	7907130078	10CFR
	7907090011	10CFR
	7907090030	10CFR
	7907090032	10CFR
	7907090019	50-219 T
	7907100130*	50-320 T
	7907100270	50-320 P
	7907090015	50-334 T
	7907080461	50-336 Q
	7907250159	COMMISSION
	7907250610	COMMISSION
	7907260451	COMMISSION
	7907260464*	COMMISSION
	7907260473*	COMMISSION
	7907260482*	COMMISSION
	7907260491*	COMMISSION
	7907260496*	COMMISSION
	7907260513*	COMMISSION
	7907260521*	COMMISSION
	7907260569	COMMISSION
	7907310492	COMMISSION
	7907310500*	COMMISSION
	7907310508*	COMMISSION
	7907310516*	COMMISSION
	7907310527*	COMMISSION
	7907160329	50-320 H
	7907160229	10CFR
	7907160246	10CFR
	7907250171	COMMISSION

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907250180	COMMISSION
	7907270210	COMMISSION
	7907160316	50-320 P
	7907310341	COMMISSION
	7907310364	COMMISSION
	7907310606	COMMISSION
	7907310585	50-280 U
	7907160255	10CFR
	7907160045	COMMISSION
	7907250457	COMMISSION
	7907190068	50-367 Q
	7907030343	10CFR
	7907030354	10CFR
	7907030395	10CFR
	7907030407	10CFR
	7907030410	10CFR
	7907300493	COMMISSION
	7907300502	COMMISSION
	7907300511	COMMISSION
	7907300515	COMMISSION
	7907100087*	50-320 T
	7907020257	FOIA
	7907030261	NUREG
	7907030413	10CFR
	7907160041	COMMISSION
	7907160278	COMMISSION
	7907160312	COMMISSION
	7907310048	COMMISSION
	7907100122	50-320 T
	7907130512	COMMISSION
	7907160021	COMMISSION
	7907160035	COMMISSION
	7907160186	10CFR
	7907160211	10CFR
	7907160239	COMMISSION
	7907100124	50-320 T
	7907130527	COMMISSION
	7907130529	COMMISSION
	7907130532	COMMISSION
	7907130535	COMMISSION
	7907130537	COMMISSION
	7907130539	COMMISSION
	7907130541	COMMISSION
	7907130549	COMMISSION
	7907160056	COMMISSION
	7907030089	10CFR
	7907030309	10CFR
	7907100121	50-320 T
	7907130547	COMMISSION
	7907130550	COMMISSION
	7907130552	COMMISSION
	7907130554	COMMISSION
	7907130557	COMMISSION
	7907130561	COMMISSION
	7907130562	COMMISSION
	7907160052	COMMISSION
	7907160202	COMMISSION

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907160176	50-320 P		7907180127*	50-219 Q
	7907160071	COMMISSION		7907100679	50-466 Q
	7907180588	50-309 U		7907100188*	50-320 J
	7907140096	COMMISSION		7907180730*	FOIA
	7907180721	50-320 U		7907230185	10CFR
	7907180736*	50-320 U		7907270030	PR
	7907180751*	50-320 U		7907100041	50-320 Q
	7907180746*	50-320 U		7907140130	27-39
	7907180785*	50-320 U		7907180727	50-312 Q
	7907180588	50-309 U		7907190292	50-320 Q
	7907120499	10CFR		7907180907	50-443 Q
	7907120520	10CFR		7907100148	50-320 P
	7907180651	50-323 U		7907190662	50-344 Q
	7907180646	50-278 U		7907300391	50-346 Q
	7907180651	50-320 U		7907230198*	COMMISSION
	7907180696	50-171 U	Atomic Energy Commission (Pre 1975)	7907190231*	50-16 P
	7907140050	50-320 U		7907190235*	50-16 P
	7907140112	COMMISSION		7907190242*	50-16 P
	7907180651	50-320 U		7907190246*	50-16 Q
	7907140073	COMMISSION	Atomic Energy Commission, Directorate of Licensing (Pre-1975)	7907300211*	FOIA
	7907140141	COMMISSION		7907300253*	FOIA
	7907140168	COMMISSION		7907300263*	FOIA
	7907140172	10CFR		7907300532*	50-201 I
	7907170093	50-289 T		7907300427*	50-201 I
	7907160090	70-143		7907030156*	FOIA
	7907200449	50-320 H		7907030160*	FOIA
	7907190573	10CFR		7907190225*	50-16 P
	7907230472	COMMISSION		7907230250*	50-201 P
	7907230484	COMMISSION			
	7907230490	COMMISSION	Atomic Energy Commission-Deputy Director for Fuels and Materials (Pre-1975)	7907300544*	50-201 I
	7907230500	COMMISSION			
	7907230518	COMMISSION	NRC Three Mile Island Task Force	7907130405*	50-320 P
	7907230534	COMMISSION		7907130414*	50-320 P
	7907230457	50-320 H		7907030008	50-320 H
	7907230170	50-320 P		7907130343	50-320 H
	7907230554	COMMISSION		7907130398	50-320 H
	7907230627	COMMISSION		7907130358	50-320 H
	7907230241	50-201 P		7907130402	50-320 P
	7907230187	COMMISSION		7907160230*	50-320 H
	7907230607	NUREG		7907030006	50-320 H
Office of Congressional Affairs	79066070309	FOIA		7907130365	50-320 Q
Office of the General Counsel	79066060593*	50-250 U		7907130395	50-320 H
	7907300227*	FOIA		7907130396	50-320 Q
	7907300258*	FOIA		7907030001	50-320 H
	7907100168	50-320 P		7907030002	50-320 H
	7907100287	50-320 Q		7907030003	50-320 H
	7907100294*	50-320 Q		7907030004	50-320 H
	7907260694	50-596 Q		7907030028	50-320 H
	7907180387	27-39		7907030293	50-320 H
	7907090013*	10CFR		7907030302	50-320 H
	7907100165	50-320 P		7907030303	50-320 H
	7907100154	50-320 P		7907030040	50-320 H
	7907100209	50-320 H		7907030057	50-320 P
	7907310472	50-322 A		7907030071	50-320 U
	7907100194	50-320 H		7907030024	50-320 H
	7907100181	50-320 J		7907030043	50-320 T
	7907100095	50-320 E		7907030048	50-320 H
	7907100140*	50-320 Q		7907030052	50-320 H
	7907100082	50-320 T		7907030130	50-320 H
	7907100133	50-320 Q		7907030280	50-320 H
	7907160047	COMMISSION		7907030285	50-320 H
Office of the Secretary of the Commission	7907230178	COMMISSION		7907130261	50-320 P
	7907260396*	50-272 Q		7907130362	50-320 H
	7907160358*	COMMISSION		7907130253	50-320 H
	7907090063*	SECY		7907130318	50-320 H
	7907090164*	SECY		7907130346	50-320 H
	7907090169*	SECY		7907130352	50-320 Q
	7907090084*	SECY		7907160345	50-320 P
	7907090181*	SECY		7907130274	50-320 Q
	7907310351*	COMMISSION		7907130350	50-320 H
	7907090097*	SECY		7907130424	50-320 H
	7907090103*	SECY		7907130308	50-320 H
	7907090169*	SECY		7907130312	50-320 H
	7906260446	10CFR		7907020163	50-320 P
	7906260325	50-400 A		7907160335	50-320 P
	7906260292	50-269 P		7907160348	50-320 P
	7907120273	SECY		7907120737	50-320 P
	7907230752*	50-333 U	THI-2 Bulletins & Orders	7907300396	FOIA
	7907100067	50-320 Q	THI-2 Lessons Learned Task Force	7907130269	50-320 P
	7907020475	50-287 Q		7907020216	50-320 P
	7907060460	PRM		7907020064	50-320 P
	7907090058*	SECY		7907310064	50-320 P
	7907130204	PRM		7907310071*	50-320 P
	7907130229	PRM		7907200512	OEN TEC IB
	7907110613	PR			
	7907100180	50-320 H			
	7906260196	50-269 P	THI-2 Unresolved Safety Issues		

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ACRS - Advisory Committee on Reactor Safeguards	7907250064	ACRS		7907130037	50-454
	7907110350	50-320 O		7907130302	50-338
	7907020465	ACRS		7907180373	50-454
	7907020104	50-320 O		7907060246	50-456
	7907020099	50-320 O		7907100674	50-498
	7907100192	50-320 O		7907020016	50-329
	7907050061	ACRS		7907020009	50-466
	7907100226	50-336 O		7907190114	50-466
	7907050350	ACRS		7907060495	50-556
	7907060288	ACRS		7907130067	50-358
	7907100223	50-320 O		7907060495	50-556
	7907130519*	50-320 O		7907060472	50-514
	7907100238	50-346 P		7907120083	50-596
	7907100200	50-287 P		7907180772	50-344
	7907090458	50-320 P		7907050053	FOIA
				7907130287	50-70
	7907190562	ACRS		7907190631	50-70
	7907090456	50-320 P		7907300270	50-338
	7907020394	50-320 O		7907180596	50-387
	7907020404*	50-320 O		7907050053	50-556
	7907310251	ACRS		7907130287	50-70
	7907090455	50-320 P		7907190631	50-70
	7907190845*	50-409 O		7907180650	50-133
	7907110014*	50-320 O		7907090099	50-358
	7907110216	50-320 O		7907250070	70-2623
				7907120249	50-295
	7907110225	50-320 O		7907180654	50-305
	7907110216	50-320 O		7907180645	50-322
	7907110225	50-320 O		7907030265	50-358
	7907020484	50-320 O		7907030368	50-358
	7907110002	50-320 O		7907020001	50-466
	7907110004	50-320 O		7907030251	70-2623
	7907110248	50-320 O		7907120201	50-295
	7907110324	50-320 O		7907180294	50-358
	7907110011	50-320 O		7907030189	70-2623
	7907110049*	50-320 O		7907300184	50-295
	7907110020	50-320 O		7907120170	50-358
	7907110047	50-320 O		7907120121	70-2623
	7907110071	50-320 O		7907250105	70-2623
	7907110076	50-320 O		7907190451	50-445
	7907110330	50-320 O		7907250146	70-2623
	7907110101	50-320 P		7907190451	50-445
	7907110156	50-320 O		7907190450	50-466
	7907110160	50-320 O		7907190451	50-445
	7907190129	50-409 O		7907200228	50-261
	7907190135*	50-409 O		7907120303	50-358
	7907270264*	50-409 O		7907120400	50-358
	7907120338	ACRS		7907190499	50-471
	7907110236	50-320 O		7907250081	70-2623
	7907110170	50-320 O		7907240361	50-272
	7907110179	50-320 O		7907120158	50-358
	7907110236	50-320 O		7907240300	50-445
	7907130429	ACRS		7907250092	70-2623
	7907110187	50-320 O		7907120446	50-358
	7907130434	ACRS		7907250135	70-2623
	7907160068	COMMISSION		7907250162	70-2623
	7907030295	ACRS		7907120469	50-358
	7907030284	ACRS		7907120412	50-329
	7907190275	50-320 O		7907120364	50-329
	7907190284*	50-320 O		7907160138	50-329
	7907190298*	50-320 O		7907230540	50-329
	7907120321	50-409 T		7907120380	50-329
	7907230654	ACRS		7907160151	50-329
	7907230714	ACRS		7907190606	50-329
	7907260728	50-320 T		7907190594	50-329
				7907190853	50-329
Atomic Safety and Licensing Appeal Panel	7907110081	50-J38 O		7907230592	50-329
	7907160097	PROJ		7907300144	50-471
	7907180714	50-338 O		7907230526	50-329
Atomic Safety and Licensing Board Panel	7907240355	50-485 O		7907250194	50-471
	7907300444*	50-201 I		7907300113	50-522
	7907260761	50-387 O		7907230574	50-329
	7907050080	50-272 O		7907310044	50-471
	7907100650	50-437 O		7907270285	50-582
	7907050057*	50-556 A		7907270321	50-329
	7907130092	50-219 O		7907310054	50-471
	7907060370	50-514 O		7907270265	50-582
	7907060342	50-295 O		7907250174	50-329
	7907050453	50-344 O		7907300133	50-471
	7907170240	50-338 O		7907300153	50-329
	7907180258	50-338 O			
	7907310083	50-338 O			
	7907170240	50-338 O			
	7907180258	50-338 O			
	7907310083	50-338 O			
			Office of the Executive Director for Operations	7907180137	FOIA
				7812290248	NUREG
				7907090174	BECY

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7905040159	50-320 P		7907260832	CONTRACT
	7905040162*	50-320 P		7907270027	CONTRACT
	7907120710	50-320 P		7907270034	CONTRACT
	7905230310	50-320 P		7907250230	CONTRACT
	7907060050	COMMISSION		7907250231*	CONTRACT
	7906280255	PR		7907300498	CONTRACT
	7907130288	PRM		7907310073	CONTRACT
	7907060144	50-275 G	Purchasing Section	7907250121	CONTRACT
	7907120349*	50-275 H		7907310498	CONTRACT
	7907110646	50-320 H	Research Contracts Branch	7907090463*	FOIA
	7907060144	50-275 G		7907260608*	CONTRACT
	7907120349*	50-275 H		7907260602	CONTRACT
	7907090472	50-320 P		7907300559*	CONTRACT
	7907110138	COMMISSION		7907100008	CONTRACT
	7907260082	50-445 U		7907100013*	CONTRACT
	7907260520	50-320 U		7907110061	CONTRACT
	7907260358	50-255 U		7907110065*	CONTRACT
	7907240516	COMMISSION		7907230699*	CONTRACT
	7907180852	SECY		7907180322*	CONTRACT
	7907260059	50-313 U		7907270093	CONTRACT
	7907260246	PROJ		7907270101*	CONTRACT
	7907190253	COMMISSION		7907100704	CONTRACT
	7907260388	50-272 G		7907100707*	CONTRACT
	7907230739	50-280 U		7907230705	CONTRACT
	7907260009	50-309 U		7907100698	CONTRACT
	7907250249	COMMISSION		7907100700*	CONTRACT
	7907180809*	50-338 G		7907100711	CONTRACT
	7907310145	50-275 U		7907100716*	CONTRACT
	7907310261	50-338 U		7907270083*	CONTRACT
	7907310122	50-382 U		7907110332	CONTRACT
	7907310202	50-382 U		7907100003	CONTRACT
	7907310244	50-382 U		7907100006*	CONTRACT
	7907310122	50-382 U		7907110387	CONTRACT
	7907310202	50-382 U		7907110439*	CONTRACT
	7907310244	50-382 U		7907120139	CONTRACT
	7907310122	50-382 U		7907120152*	CONTRACT
	7907310202	50-382 U		7907120174	CONTRACT
	7907310244	50-382 U		7907120181*	CONTRACT
	7907310091	50-463 U		7907230694	CONTRACT
	7907310172	50-546 U		7907300534*	CONTRACT
Office of Administration	7907160263*	COMMISSION		7907190812*	CONTRACT
Division of Contracts	7907110547*	CONTRACT		7907090113	CONTRACT
	7907230713*	CONTRACT		7907190755	CONTRACT
	7907250130*	CONTRACT		7907190765*	CONTRACT
	7907090118*	CONTRACT		7907190777	CONTRACT
	7907050274*	CONTRACT		7907190786*	CONTRACT
	7907260818*	CONTRACT		7907190795	CONTRACT
	7907260857*	CONTRACT		7907250232	CONTRACT
	7907230722*	CONTRACT		7907250233*	CONTRACT
	7907240286*	CONTRACT		7907250594*	CONTRACT
	7907260380*	CONTRACT		7907270025*	CONTRACT
	7907250124*	CONTRACT		7907230728	CONTRACT
	7907300559*	CONTRACT		7907260027*	CONTRACT
	7907260845*	CONTRACT		7907260640*	CONTRACT
	7907270041*	CONTRACT		7907260618	CONTRACT
	7907300505*	CONTRACT		7907260626*	CONTRACT
	7907310090*	CONTRACT		7907310051	CONTRACT
	7907310504*	CONTRACT		7907270076	CONTRACT
	7907260934*	CONTRACT		7907310057*	CONTRACT
	7907190852*	CONTRACT		7907260636	CONTRACT
	7907260924	CONTRACT		7907270018	CONTRACT
	7907250127	CONTRACT		7907180327	CONTRACT
	7907050268	CONTRACT		7907180333*	CONTRACT
	7907300529	CONTRACT		7907180316	CONTRACT
	7907100723	CONTRACT		7907180349*	CONTRACT
	7907100728*	CONTRACT		7907180344	CONTRACT
	7907260809	CONTRACT		7907230719	CONTRACT
	7907250590	CONTRACT	Technical Assistance Contracts Branch	7907300271*	CONTRACT
	7907130061	CONTRACT		7907300261	CONTRACT
	7907130073*	CONTRACT		7907240282	CONTRACT
	7907260024	CONTRACT		7907300459	CONTRACT
	7907260801*	CONTRACT		7907300485*	CONTRACT
	7907260849	CONTRACT		7907260377	CONTRACT
	7907300510*	CONTRACT		7907260653	CONTRACT
	7907300557	CONTRACT		7907260660*	CONTRACT
	7907260781*	CONTRACT	Division of Technical Information & Document Control	7907190546	NUREG
	7907260789	CONTRACT	License Fee Management Branch	7907050177	70-27
	7907260769	CONTRACT		7907020473*	70-149
	7907270031*	CONTRACT		7907100664	70-371
	7907300473	CONTRACT		7907190026	71-4949
	7907300564	CONTRACT		7907110731	50-315 P
	7907190834	CONTRACT		7907090045	70-820
				7907060435	50-311 A
				7907180480	70-2443
				7907180515	70-1151
				7907270251	AN-8722

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Division of Rules and Records	7907250605	50-321 F		7907180682	FOIA
	7907310243	50-324 P		7907190007	FOIA
	7907250605	50-321 F		7907190269	50-320
	7907020478	70-824		7907190150	50-352
	7907310534	50-409 P		7907250476	50-352
	7907230497*	71-6581		7907190150	50-392
	7907310525	50-346 P		7907250476	50-352
	7907230496*	71-6581		7907190150	50-392
	7907230492	71-6581		7907250476	50-352
				7907190681	FOIA
	7907190530*	50-302 F		7907230223	FOIA
	7907230565*	COMMISSION		7907250556	50-201
	7907310589*	FOIA		7907200226	50-320
	7907050089*	FOIA			
	7906060069	50-309 P		7907190442	FOIA
				7907230004	FOIA
	7907030106	FOIA		7907250413	50-293
	7907020111	FOIA		7907250448	50-320
	7907020122	FOIA		7907250396	50-322
	7907030154	FOIA			
	7907030331	FOIA		7907190703	27-39
				7907250408	50-287
	7907030174	50-29 S		7907250515	FOIA
	7907060150	50-295 P		7907260447	FOIA
	7907030184	50-344 P		7907300156	FOIA
	7907020128	FOIA			
	7907050013	FOIA		7907300410	50-201
				7907250408	50-269
	7907060131	50-289 P			
	7907020100	FOIA	Office of International Programs	7907240416	SECY
	7907020105	FOIA		7811300307	XPORTLIC
	7907030165	FOIA		7907030169*	FOIA
	7907100162*	FOIA		7907130427	SECY
				7907030172*	FOIA
	7907030117	50-461 A			
	7907060465	40-1739		7907230230	XPORTLIC
	7907030139	50-295 P		7907050311	XPORTLIC
	7907030153	FOIA		7907060290	XPORTLIC
	7907020094	50-22 P		7907020486	FOIA
				7907050282	XPORTLIC
	7907060173	50-338 P			
	7907190124	50-498 H		7907190009	SECY
	7907030146	FOIA		7907260919	50-245
	7907060075	FOIA		7907060443	XPORTLIC
	7907030110	FOIA		7907230188	SECY
				7907100306	XPORTLIC
	7907030307	FOIA			
	7907060449	FOIA		7907190805	XPORTLIC
	7907020146	FOIA		7907190814	XPORTLIC
	7907050020	FOIA		7907190825	XPORTLIC
	7907090404	FOIA		7907250038	XPORTLIC
	7907090448	FOIA		7907250088	XPORTLIC
	7907100034	FOIA			
	7907020136	50-320 P		7907250096	XPORTLIC
	7907030335	FOIA		7907250101	XPORTLIC
	7907090327	50-330 Q		7907190686	XPORTLIC
				7907190692	XPORTLIC
	7907030264	FOIA		7907190697	XPORTLIC
	7907030315	FOIA			
	7907060142	FOIA		7907240008	XPORTLIC
	7907060162	70-1193		7907240012	XPORTLIC
	7907030237	50-426 A		7907240031	XPORTLIC
				7907240036	XPORTLIC
	7907030321	FOIA		7907240039	XPORTLIC
	7907030237	50-424 A			
	7907030108	FOIA		7907190715	XPORTLIC
	7907050019	50-320 P		7907190621	XPORTLIC
	7907050027	50-320 P		7907190627	XPORTLIC
				7907230210	XPORTLIC
	7907050035	50-320 P		7907230227	XPORTLIC
	7907050045	50-320 P			
	7907180715	FOIA	Assistant Director for Export/Import & International Safeguards	7907030324	XPORTLIC
	7907190629	FOIA			
	7907180784	50-320 P		7907060049	XPORTLIC
				7907060051	XPORTLIC
	7907190088	50-320 Q		7907060080	XPORTLIC
	7907190248	50-320 P		7907060262	XPORTLIC
	7907250438	50-320 P			
	7907190056	50-348 P		7907050245	XPORTLIC
	7907190031	FOIA		7907050248	XPORTLIC
				7907050252	XPORTLIC
	7907190171	50-461 A		7907050314	XPORTLIC
	7907190107	50-320 P		7907060053	XPORTLIC
	7907190115	50-320 P			
	7907190141	50-320 P		7907060086	XPORTLIC
	7907190183	FOIA		7907060253	XPORTLIC
				7907060255	XPORTLIC
	7907190752	FOIA		7907060259	XPORTLIC
	7907190803	50-320 P		7907060091	XPORTLIC
	7907250517	FOIA			
	7907250572	FOIA		7907030190	XPORTLIC
	7907190803	50-247 P			
				7907030320	XPORTLIC
	7907190731	50-289 P		7907050482	XPORTLIC
	7907110001	50-320 Q		7907060045	XPORTLIC
	7907190669	50-320 P		7907030318	XPORTLIC
	7907190731	50-289 P			
	7907190803	50-247 P		7907110053	XPORTLIC
				7907060440	XPORTLIC
	7907310565	50-574 A		7907130053	XPORTLIC
	7907250398	FOIA		7907130058	XPORTLIC
	7907190221	50-16 P			
	7907250484	50-546 A			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907130068	XPORTLIC		7907240010	XPORTLIC
	7907130074	XPORTLIC		7907250242	XPORTLIC
	7907130089	XPORTLIC		7907180277	XPORTLIC
	7907180546	XPORTLIC		7907180284	XPORTLIC
	7907180550	XPORTLIC		7907310047	XPORTLIC
	7907180675	XPORTLIC		7907310052	XPORTLIC
	7907180678	XPORTLIC		7907310058	XPORTLIC
	7907180909	XPORTLIC		7907190772	XPORTLIC
	7907260191	XPORTLIC	Office of the Executive Legal Director	7907110624*	50-338 Q
	7907260203	XPORTLIC		7907030131*	50-458 A
	7907310154	XPORTLIC		7907240454	50-443 M
	7907050108	XPORTLIC	Deputy Executive Legal Director Hearings Division	7907240462	50-466 Q
	7907180660	XPORTLIC		7907270008	50-261 Q
	7907180665	XPORTLIC	Branch 1	7903230309	50-70 Q
	7907180668	XPORTLIC		7903150023	50-338 Q
	7907180660*	SECY		7907020494	50-822 T
	7907190791	XPORTLIC		7907030207	50-344 Q
	7907190797	XPORTLIC		7907050204	50-376 Q
	7907190830	XPORTLIC		7907030179	50-344 Q
	7907190837	XPORTLIC		7907050474	50-382 Q
	7907190810	XPORTLIC		7907110618	50-338 Q
	7907100343	XPORTLIC		7907310488	50-361 Q
	7907180880	XPORTLIC		7906260534	50-522 Q
	7907190749	XPORTLIC		7906260536	50-522 Q
	7907190758	XPORTLIC		7906260536	50-522 Q
	7907260852	XPORTLIC		7907310566	50-338 Q
	7907300005	XPORTLIC		7907170242	50-338 Q
	7907300006	XPORTLIC		7907180206	50-382 Q
	7907180873	XPORTLIC		7907060521	50-344 Q
	7907250108	XPORTLIC		7907090001	50-522 Q
	7907250113	XPORTLIC		7907130161	50-463 Q
	7907190034	XPORTLIC		7907130130	50-338 Q
	7907190705	XPORTLIC		7907060520	50-344 Q
	7907190709	XPORTLIC		7907130051	50-344 Q
	7907190720	XPORTLIC		7907180284	50-463 Q
	7907190764	XPORTLIC		7907020025	70-1308
	7907190778	XPORTLIC		7907020029*	70-1308
	7907190783	XPORTLIC		7907180716	50-344 Q
	7907230135	XPORTLIC		7907180719*	50-344 Q
	7907240017	XPORTLIC		7907190660	70-1308
	7907310114	XPORTLIC		7907180555	50-445 Q
	7907310353	XPORTLIC		7907180579	50-382 Q
	7907310361	XPORTLIC		7907180611	50-522 Q
	7907240488	XPORTLIC		7907260490	50-522 Q
	7907190633	XPORTLIC	Branch 2	7907250468*	50-261 Q
	7907190636	XPORTLIC		7907250462	50-261 Q
	7907190683	XPORTLIC		7907050383	50-471 Q
	7907190843	XPORTLIC		7907170250	50-295 Q
	7907230177	XPORTLIC		7907240431	50-471 Q
	7907190676	XPORTLIC		7907110695	50-471 Q
	7907190615	XPORTLIC		7907250144	50-471 Q
	7907190624	XPORTLIC		7907230186	50-295 Q
	7907190630	XPORTLIC		7907020512	50-312 Q
	7907190640	XPORTLIC		7907060478	50-338 Q
	7907190644	XPORTLIC		7907020004	50-471 Q
	7907190648	XPORTLIC		7907060459	50-549 Q
	7907190653	XPORTLIC		7907130013	50-295 Q
	7907190657	XPORTLIC		7907020474	50-312 Q
	7907190663	XPORTLIC		7907090071	50-338 A
	7907190668	XPORTLIC		7907130128	50-338 Q
	7907230171	XPORTLIC		7907090071	50-338 A
	7907250422	XPORTLIC		7907130128	50-338 Q
	7907250431	XPORTLIC		7907160015	50-599 Q
	7907250546	XPORTLIC		7907180601	50-272 Q
	7907230646	XPORTLIC		7907190595	50-599 Q
	7907230664	XPORTLIC		7907190666*	70-1308
	7907230671	XPORTLIC		7907260121	50-596 Q
	7907230641	XPORTLIC		7907180667	50-272 Q
	7907230661	XPORTLIC		7907190387	50-599 Q
	7907230702	XPORTLIC		7907190457	50-250 Q
	7907250235	XPORTLIC		7907180528	50-338 Q
	7907230600	XPORTLIC		7907190695	50-596 Q
	7907230636	XPORTLIC		7907240304	50-346 Q
	7907230678	XPORTLIC		7907300420	50-346 H
	7907230632	XPORTLIC		7907300429	50-346 H
	7907230675	XPORTLIC		7907300416	50-346 Q
	7907230675	XPORTLIC		7907300425	50-346 Q
		LIC	Branch 3	7907130408	27-39
		LIC		7907260003	50-466 Q
		LIC		7906210417	50-466 Q
		LIC		7907050320	50-400 Q
		LIC		7907130507	50-400 Q

# U.S. NUCLEAR REGULATORY COMMISSION

## ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907090461	50-255 Q	Office of Inspection & Enforcement	7907250481*	FOIA
	7907130501	50-387 Q		7907250512*	FOIA
	7907130507	50-400 Q		7907310200	I&E
	7907100640	50-466 Q		7907030121	I&E
	7907180358	50-392 Q		7907120686*	FOIA
	7907200222	50-255 Q		7907270284*	50-397
	7907190722	50-592 Q		7907090491*	FOIA
	7907130533	50-466 Q		7902210141	I&E
	7907060383	50-560 Q		7907230229*	FOIA
	7907130556	50-466 Q		7907230235*	FOIA
	7907310128	50-466 Q		7907020124*	50-320
	7907180113	50-219 Q		7907020337	50-320
	7907060487	50-387 Q		7907180622*	COMMISSION
	7907130598	50-466 Q		7904270127*	I&E
	7907310118	50-466 Q		7907020097	FOIA
	7907130826	50-592 Q		7907020134	FOIA
	7907180731	50-437 Q		7907020065	50-269
	7907190617	50-400 Q		7907120439*	SECY
	7907170251	50-466 Q		7907020407	FOIA
	7907270073	50-466 Q		7907020411*	FOIA
	7907200247	50-488 Q		7907100686	50-331
	7907200253*	50-488 Q		7907090028	10CFR
	7907200247	50-488 Q		7907120698*	50-320
	7907200253*	50-488 Q		7907020469	50-313
	7907200247	50-488 Q		7907050011*	50-313
	7907200253*	50-488 Q		7907120637	50-320
	7907200240	50-466 Q		7907130178	50-220
Branch 4	7907020493	50-556 H		7907130182*	50-220
	7907120159	50-322 Q		7907020173	I&E
	7907170244	50-322 Q		7907020181	I&E
	7907060379	50-556 Q		7907190628	50-313
	7907310259	70-2623		7907100132*	50-320
	7907170247	50-369 Q		7907020185	50-320
	7907160131	50-277 Q		7907310271*	50-338
	7907180810	50-329 Q		7907310277*	50-338
	7907160131	50-277 Q		7907310271*	50-338
	7907020010	50-556 Q		7907310277*	50-338
	7907020008	70-2623		7907030118	50-320
	7907130023	70-2623		7907310185*	50-346
	7907060319	50-322 Q		7907060295	I&E
	7907180755*	50-322 Q		7907120162	50-320
	7907160196	50-516 Q		7907120387	I&E
	7907060322	50-582 Q		7907170153	50-320
	7907190602	50-599 Q		7907180125*	I&E
	7907190618	50-599 Q		7907180135*	I&E
	7907190602	50-599 Q		7907190128	I&E
	7907190618	50-599 Q		7907230164	I&E
	7907190602	50-599 Q		7907240340	50-320
	7907190618	50-599 Q		7907250430	I&E
	7907190673	70-2623		7907180129	I&E
	7907180188	50-277 Q	Division of Fuel Facility & Materials Safety	7907030137*	50-320
	7907180752	50-322 Q		7907260139*	50-329
	7907180188	50-277 Q	Division of Reactor Construction Inspection	7907180120	I&E
	7907190682	50-329 Q		7907120681	FOIA
	7907190723	70-2623		7902150354	I&E
	7907190398	50-389 Q	Division of Reactor Operations Inspection	7907180613*	COMMISSION
	7907260131	50-329 Q		7904270123	50-320
	7907200253	50-275 Q		7907100322*	50-320
Operations & Administrative Division	7907050395	50-800 Q		7907020492*	FOIA
	7907030185	50-445 Q		7907100312	50-320
	7907130517	50-344 Q		7907050008	FOIA
	7907130164	50-445 Q		7907240288	50-315
Anti-Trust Division	7907180555	50-445 Q		7907090427	50-206
	7907050319	50-498 H		7907300445	50-312
	7907160075	50-275 Q		7907250500*	FOIA
	7907260038	50-445 H		7907310171*	50-29
Office of Management and Program Analysis	7907030157*	FOIA	Region 1, Philadelphia, Office of the Director	7907030065*	50-333
	7907110401	50-320 P		7907030068*	50-333
	7907110659	NUREG		7907110689*	50-387
	7907030185*	FOIA		7907110696*	50-387
	7907270227	PROJ		7907110689*	50-347
	7907300248	NUREG		7907110696*	50-387
Office of State Programs	7907110404	50-320 A		7906290180*	70-1710
	7907130536*	50-346 Q		7907110703*	50-471
	7907110197	50-320 P		7906290180*	70-1710
	7907110390	50-320 P		7907300378*	50-410
	7907190509	WASTE MGT		7907050054*	70-2662
	7907120748	FOIA		7907230015*	50-311
	7907180142	FOIA		7907230023*	50-311
	7907180155	FOIA		7907230011*	50-311
	7907180150	FOIA		7907230442*	50-352
	7907270259	AGREEMENT			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907230585*	50-387 Q		7907260067	50-286 P
	7907230598*	50-387 Q		7907060388	50-287 Q
	7907230585*	50-387 Q		7907260054	50-287 P
	7907230598*	50-387 Q		7907060373	50-293 Q
	7907250483	50-352 A			
	7907130306*	50-284 Q		7907260033	50-293 P
	7907130238*	50-387 Q		7907060389	50-309 Q
	7907230727*	50-412 Q		7907260058	50-309 P
	7907230118*	70-938		7907060425	50-311 Q
	7907230128*	70-938		7907260072	50-311 A
	7907100249	50-320 H		7907060375	50-317 Q
	7907200406*	50-57 Q		7907260037	50-317 P
	7907200416*	50-57 Q		7907060375	50-317 Q
				7907260037	50-317 P
	7907090444	50-213 Q		7907260053	50-320 P
	7907090449*	50-213 Q		7907060387	50-322 Q
	7907160098	50-320 P		7907060399	50-333 Q
	7907120661	50-380 H		7907260064	50-333 P
	7907230707*	50-412 Q		7907060380	50-334 Q
	7907190019*	50-387 Q		7907260049	50-334 P
	7907190029*	50-387 Q		7907060392	50-245 Q
	7907190019*	50-387 Q		7907260060	50-245 P
	7907190029*	50-387 Q		7907060422	50-352 Q
	7907050527*	50-423 Q		7907060425	50-311 Q
	7907050498*	50-363 Q		7907060384	50-363 Q
	7907200460*	50-293 Q		7907060423	50-387 Q
	7907200453*	50-293 Q		7907060394	50-410 Q
	7907230557*	50-272 Q		7907060381	50-412 Q
	7907090430	50-320 P		7907060392	50-245 Q
	7907100254	50-320 H		7907060429	50-443 Q
	7907100291	50-320 H		7907060432	50-485 Q
	7907230479*	50-220 Q		7907060387	50-322 Q
	7907310023	50-29 Q		7907260013	70-33
	7907310121*	50-333 Q		7907260008	70-364
	7907250352*	FDIA		7907260019	70-371
	7906200417	50-320 H		7907260015	70-820
	7907020467	50-309 P		7907260021	70-1143
	7907200496*	50-387 Q		7907120177	50-320 H
	7907200303*	50-387 Q		7907240615*	50-334 Q
	7907200496*	50-387 Q		7907030021	50-3 Q
	7907200303*	50-387 Q		7907030078	50-29 Q
	7907100260	50-320 H		7907030023	50-213 Q
	7907110664*	40-7983		7907030030	50-219 Q
	7907310014*	50-213 Q		7907030044	50-220 Q
	7907110460*	50-245 Q		7907030074	50-244 Q
	7907190154	50-352 A		7907030041	50-245 Q
	7907110015*	50-423 Q		7907030021	50-3 Q
	7907240220*	50-443 Q		7907030077	50-271 Q
	7907200491*	50-387 Q		7907030064	50-272 Q
	7907230051*	50-220 Q		7907030053	50-277 Q
	7907230057*	50-220 Q		7907030050	50-286 Q
	7907100234	50-320 H		7907030037	50-320 Q
	7907180483*	50-247 Q		7907030016	50-293 Q
	7907100278	50-320 H		7907030038	50-309 Q
	7907050186	50-387 Q		7907030061	50-311 Q
	7907180445*	50-336 Q		7907030018	50-317 Q
	7907100230	50-57 Q		7907030037	50-320 Q
	7907100239	50-193 Q		7907030033	50-322 Q
	7907100233	50-201 Q		7907030049	50-333 Q
	7906200312	50-320 P		7907030025	50-334 Q
	7907030054	50-333 Q		7907030041	50-245 Q
	7907060376	50-3 Q		7907030055	50-352 Q
	7907060436	50-29 Q		7907030061	50-311 Q
	7907260080	50-29 P		7907030030	50-219 Q
	7907260012	50-201 P		7907030059	50-387 Q
	7907060377	50-213 Q		7907030046	50-410 Q
	7907260042	50-213 P		7907030027	50-412 Q
	7907060382	50-219 Q		7907030041	50-245 Q
	7907260052	50-219 P		7907030069	50-443 Q
	7907060395	50-220 Q		7907030072	50-485 Q
	7907260061	50-220 P		7907030033	50-322 Q
	7907060431	50-244 Q		7907200086	50-3 Q
	7907260073	50-244 P		7907200156	50-29 Q
	7907060392	50-245 Q		7907200093	50-213 Q
	7907260060	50-245 P		7907200103	50-219 Q
	7907060376	50-3 Q		7907200117	50-220 Q
	7907260040	50-247 P		7907200151	50-244 Q
	7907060433	50-271 Q		7907200115	50-245 Q
	7907260077	50-271 P		7907200086	50-3 Q
	7907060428	50-272 Q		7907200153	50-271 Q
	7907260071	50-272 P		7907200144	50-272 Q
	7907060401	50-277 Q		7907200131	50-277 Q
	7907260069	50-277 P		7907200126	50-286 Q
	7907060401	50-277 Q		7907200108	50-320 Q
	7907260069	50-277 P		7907200501	50-289 Q
	7907060398	50-286 Q		7907200078	50-292 Q



# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

48

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907200110	50-309 Q		7907020046	50-322 Q
	7907200142	50-311 Q		7907020050	50-352 Q
	7907200108	50-320 Q		7907020052	50-311 Q
	7907200107	50-322 Q		7907020045	50-363 Q
	7907200124	50-333 Q		7907020051	50-387 Q
	7907200095	50-334 Q		7907020048	50-410 Q
	7907200114	50-336 Q		7907020044	50-412 Q
	7907200134	50-352 Q		7907020047	50-423 Q
	7907200142	50-311 Q		7907020054	50-443 Q
	7907200104	50-363 Q		7907020042	50-471 Q
	7907200139	50-387 Q		7907020056	50-485 Q
	7907200121	50-410 Q		7907020046	50-322 Q
	7907200098	50-412 Q		7907020057	50-567 Q
	7907200114	50-336 Q		7907020059	50-568 Q
	7907200147	50-443 Q		7907270384	50-220 Q
	7907200150	50-485 Q		7907100576	50-320 H
	7907200107	50-322 Q		7907100579	50-320 H
	7907100548	50-320 H		7907100585	50-320 H
	7907190044	50-3 Q		7907110710	50-277 Q
	7907190123	50-29 Q		7907200477	50-387 Q
	7907190045	50-213 Q		7907200431	50-293 Q
	7907190052	50-219 Q		7907110361	50-3 Q
	7907190084	50-220 Q		7907100481	50-29 Q
	7907190116	50-244 Q		7907110363	50-213 Q
	7907190069	50-245 Q		7907110368	50-219 Q
	7907190044	50-3 Q		7907100475	50-220 Q
	7907190119	50-271 Q		7907100480	50-244 Q
	7907190104	50-272 Q		7907100473	50-245 Q
	7907190094	50-277 Q		7907110361	50-3 Q
	7907190087	50-286 Q		7907110394	50-271 Q
	7907190062	50-320 Q		7907100478	50-272 Q
	7907190040	50-293 Q		7907110381	50-277 Q
	7907190064	50-309 Q		7907100476	50-286 Q
	7907190102	50-311 Q		7907110370	50-289 Q
	7907190043	50-317 Q		7907100466	50-293 Q
	7907190062	50-320 Q		7907110373	50-309 Q
	7907190057	50-322 Q		7907110389	50-311 Q
	7907190089	50-333 Q		7907100467	50-317 Q
	7907190051	50-334 Q		7907110370	50-289 Q
	7907190069	50-245 Q		7907100471	50-322 Q
	7907190098	50-352 Q		7907110378	50-333 Q
	7907190102	50-311 Q		7907110364	50-334 Q
	7907190054	50-363 Q		7907100473	50-243 Q
	7907190099	50-387 Q		7907110379	50-352 Q
	7907190071	50-410 Q		7907110389	50-311 Q
	7907190047	50-412 Q		7907100468	50-363 Q
	7907190069	50-245 Q		7907110386	50-387 Q
	7907190109	50-443 Q		7907110375	50-410 Q
	7907190113	50-485 Q		7907110367	50-412 Q
	7907190057	50-322 Q		7907100473	50-245 Q
	7907060083	50-3 Q		7907110391	50-443 Q
	7907060140	50-29 Q		7907110392	50-465 Q
	7907060084	50-213 Q		7907100471	50-322 Q
	7907060095	50-219 Q		7907230647	50-3 Q
	7907060109	50-220 Q		7907230715	50-29 Q
	7907060133	50-244 Q		7907230650	50-213 Q
	7907060106	50-245 Q		7907230669	50-219 Q
	7907060083	50-3 Q		7907230685	50-220 Q
	7907060138	50-271 Q		7907230706	50-244 Q
	7907060126	50-272 Q		7907230681	50-245 Q
	7907060121	50-277 Q		7907230647	50-3 Q
	7907060114	50-286 Q		7907230712	50-271 Q
	7907060103	50-320 Q		7907230704	50-272 Q
	7907060079	50-293 Q		7907230693	50-277 Q
	7907060105	50-309 Q		7907230689	50-286 Q
	7907060128	50-311 Q		7907230677	50-320 Q
	7907060081	50-317 Q		7907230642	50-293 Q
	7907060103	50-320 Q		7907230679	50-309 Q
	7907100558	50-320 H		7907230700	50-311 Q
	7907060101	50-322 Q		7907230644	50-317 Q
	7907060115	50-333 Q		7907230677	50-320 Q
	7907060090	50-334 Q		7907230674	50-322 Q
	7907060106	50-245 Q		7907230691	50-333 Q
	7907060118	50-352 Q		7907230663	50-334 Q
	7907060128	50-311 Q		7907230681	50-245 Q
	7907060094	50-363 Q		7907230695	50-352 Q
	7907060123	50-387 Q		7907230700	50-311 Q
	7907060110	50-410 Q		7907230672	50-363 Q
	7907060092	50-412 Q		7907230697	50-387 Q
	7907060106	50-245 Q		7907230683	50-410 Q
	7907060130	50-443 Q		7907230665	50-412 Q
	7907060135	50-485 Q		7907230681	50-245 Q
	7907060101	50-322 Q		7907230709	50-485 Q
	7907020051	50-387 Q		7907230674	50-322 Q
	7907020052	50-311 Q		7907240171	70-698 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907240135	40-3392		7907060190	50-289 Q
	7907230400	50-20 Q		7907100308	50-322 Q
	7907230388	50-54 Q		7907100351	50-333 Q
	7907230392	50-77 Q		7907060182	50-334 Q
	7907230396	50-97 Q		7907060195	50-245 Q
	7907230398	50-199 Q		7907100353	50-352 Q
	7907230394	50-208 Q		7907100363	50-311 Q
	7907230006*	50-387 Q		7907060185	50-363 Q
	7907240160	70-33		7907100361	50-387 Q
	7907240143	70-34		7907100316	50-410 Q
	7907240139	70-135		7907100305	50-412 Q
	7907240161	70-371		7907060195	50-245 Q
	7907240171	70-498		7907100371	50-443 Q
	7907240165	70-820		7907100373	50-485 Q
	7907240142	70-1100		7907100308	50-322 Q
	7907240171	70-698		7907100429	50-311 Q
	7907240136	50-3 Q		7907100418	50-322 Q
	7907240211	50-29 Q		7907100424	50-352 Q
	7907240140	50-213 Q		7907100429	50-311 Q
	7907240150	50-219 Q		7907100416	50-363 Q
	7907240182	50-220 Q		7907100426	50-387 Q
	7907240203	50-244 Q		7907100422	50-410 Q
	7907240174	50-245 Q		7907100415	50-412 Q
	7907240136	50-3 Q		7907100420	50-423 Q
	7907240208	50-271 Q		7907100431	50-443 Q
	7907240202	50-272 Q		7907100413	50-471 Q
	7907240198	50-277 Q		7907100434	50-485 Q
	7907240185	50-286 Q		7907100418	50-322 Q
	7907240154	50-320 Q		7907100412	50-568 Q
	7907240128	50-293 Q		7907100407	50-596 Q
	7907240166	50-309 Q		7907100474	50-3 Q
	7907240131	50-317 Q		7907100513	50-29 Q
	7907240154	50-320 Q		7907100495	50-213 Q
	7907240194	50-333 Q		7907100498	50-219 Q
	7907240147	50-334 Q		7907100510	50-244 Q
	7907240174	50-245 Q		7907110027	50-245 Q
	7907120483	50-3 Q		7907100494	50-3 Q
	7907120555	50-29 Q		7907230001	50-250 Q
	7907120487	50-213 Q		7907100512	50-271 Q
	7907120496	50-219 Q		7907100508	50-272 Q
	7907120510	50-220 Q		7907110031	50-277 Q
	7907120578	50-244 Q		7907110029	50-286 Q
	7907120507	50-245 Q		7907180615	50-320 Q
	7907120483	50-3 Q		7907100491	50-293 Q
	7907120584	50-271 Q		7907100503	50-309 Q
	7907120539	50-272 Q		7907110035	50-311 Q
	7907120526	50-277 Q		7907100492	50-317 Q
	7907120519	50-286 Q		7907180615	50-320 Q
	7907180365	50-320 Q		7907100502	50-322 Q
	7907120476	50-293 Q		7907100506	50-333 Q
	7907120504	50-309 Q		7907110026	50-334 Q
	7907120536	50-311 Q		7907110027	50-245 Q
	7907120479	50-317 Q		7907100507	50-352 Q
	7907180365	50-320 Q		7907110035	50-311 Q
	7907120500	50-322 Q		7907100501	50-363 Q
	7907120516	50-333 Q		7907110033	50-387 Q
	7907120491	50-334 Q		7907100505	50-410 Q
	7907120509	50-336 Q		7907100497	50-412 Q
	7907120522	50-352 Q		7907110027	50-245 Q
	7907120536	50-311 Q		7907110038	50-443 Q
	7907120497	50-363 Q		7907110039	50-485 Q
	7907120528	50-387 Q		7907100502	50-322 Q
	7907120515	50-410 Q		7907310094	50-333 Q
	7907120489	50-412 Q		7907180753	50-3 Q
	7907120507	50-245 Q		7907180834	50-29 Q
	7907120543	50-443 Q		7907180758	50-213 Q
	7907120581	50-485 Q		7907180770	50-219 Q
	7907120500	50-322 Q		7907180782	50-220 Q
	7907060177	50-3 Q		7907180822	50-244 Q
	7907100381	50-29 Q		7907180779	50-245 Q
	7907060180	50-213 Q		7907180753	50-3 Q
	7907060187	50-219 Q		7907180831	50-271 Q
	7907060198	50-220 Q		7907180814	50-272 Q
	7907100376	50-244 Q		7907180799	50-277 Q
	7907060195	50-245 Q		7907180790	50-286 Q
	7907060177	50-3 Q		7907180746	50-293 Q
	7907100379	50-271 Q		7907180776	50-309 Q
	7907100367	50-272 Q		7907180811	50-311 Q
	7907060200	50-277 Q		7907180748	50-317 Q
	7907100348	50-286 Q		7907180773	50-322 Q
	7907060190	50-289 Q		7907180793	50-333 Q
	7907060172	50-293 Q		7907180764	50-334 Q
	7907060192	50-309 Q		7907180779	50-245 Q
	7907100363	50-311 Q		7907180802	50-352 Q
	7907060174	50-317 Q		7907180811	50-311 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

46

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907180767	50-363 Q		7907310528	50-277 Q
	7907180805	50-387 Q		7907310520	50-286 Q
	7907180788	50-410 Q		7907310505	50-289 Q
	7907180760	50-412 Q		7907310482	50-293 Q
	7907180779	50-245 Q		7907310506	50-309 Q
	7907180818	50-443 Q		7907310536	50-311 Q
	7907180823	50-485 Q		7907310483	50-317 Q
	7907180775	50-322 Q		7907310505	50-289 Q
	7907250474	50-2 Q		7907310502	50-322 Q
	7907250494	50-3 Q		7907310521	50-333 Q
	7907250460	50-5 Q		7907310490	50-334 Q
	7907250457	50-20 Q		7907310509	50-245 Q
	7907250357	50-22 Q		7907310530	50-352 Q
	7907250532	50-29 Q		7907310536	50-311 Q
	7907250440	50-47 Q		7907310495	50-363 Q
	7907250352	50-54 Q		7907310532	50-387 Q
	7907250467	50-57 Q		7907310513	50-410 Q
	7907250450	50-77 Q		7907310494	50-412 Q
	7907250453	50-97 Q		7907310509	50-245 Q
	7907250477	50-134 Q		7907310538	50-443 Q
	7907250453	50-97 Q		7907310539	50-485 Q
	7907250471	50-166 Q		7907310502	50-322 Q
	7907250437	50-170 Q		7907110538*	50-320 Q
	7907250442	50-184 Q			
	7907250348	50-193 Q		7907110542*	50-320 Q
	7907250456	50-199 Q		7907110538*	50-320 Q
	7907250451	50-208 Q		7907110542*	50-320 Q
	7907250496	50-213 Q		7907110529*	50-320 Q
	7907250503	50-219 Q		7907110696*	50-387 Q
	7907250510	50-220 Q		7907110680*	50-387 Q
	7907250469	50-223 Q		7907110703*	50-471 Q
	7907260257	50-225 Q		7907230023*	50-311 Q
	7907250527	50-244 Q		7907230444*	50-352 Q
	7907250509	50-245 Q		7907230598*	50-387 Q
	7907250494	50-3 Q		7907230579*	50-387 Q
	7907250529	50-271 Q		7907230453*	50-412 Q
	7907250522	50-272 Q		7907190029*	50-387 Q
	7907250521	50-277 Q		7907050527*	50-423 Q
	7907250520	50-286 Q		7907050498*	50-363 Q
	7907250490	50-293 Q		7907050494	50-363 Q
	7907250505	50-309 Q		7907300385*	50-410 Q
	7907250492	50-317 Q		7907050525	50-423 Q
	7907250513	50-333 Q		7907130299	50-286 Q
	7907250501	50-334 Q		7907190016*	50-387 Q
	7907250509	50-245 Q		7907300374*	50-410 Q
	7907270320	50-3 Q		7907160258*	50-412 Q
	7907270373	50-29 Q		7907110688	50-471 Q
	7907270326	50-213 Q		7907200503*	50-387 Q
	7907270333	50-219 Q		7907160252	50-412 Q
	7907270347	50-220 Q		7907110015*	50-423 Q
	7907270367	50-244 Q		7907240222*	50-443 Q
	7907270342	50-245 Q		7907240216*	50-443 Q
	7907270320	50-3 Q		7907180399*	50-247 Q
	7907270371	50-271 Q		7907110013	50-423 Q
	7907270363	50-272 Q		7907270381*	50-220 Q
	7907270358	50-277 Q		7907180389	50-247 Q
	7907270349	50-286 Q		7907270379	50-220 Q
	7907270316	50-293 Q		7907240609	50-334 Q
	7907270339	50-309 Q		7907240615*	50-334 Q
	7907270361	50-311 Q		7907100444	50-320 H
	7907270318	50-317 Q		7907120254	50-320 H
	7907270337	50-322 Q		7907110643	50-387 Q
	7907270352	50-333 Q		7907110510	50-289 Q
	7907270329	50-334 Q		7907300522	50-311 S
	7907270342	50-245 Q		7907190006	50-387 Q
	7907270353	50-352 Q		7907230558	50-387 Q
	7907270361	50-311 Q		7907190006	50-387 Q
	7907270335	50-363 Q		7907230558	50-387 Q
	7907270359	50-387 Q		7907230342	50-352 Q
	7907270344	50-410 Q		7907300364	50-410 Q
	7907270331	50-412 Q		7907230060	50-412 Q
	7907270342	50-245 Q		7907240204	50-443 Q
	7907270365	50-443 Q		7907230005	50-311 Q
	7907270368	50-485 Q		7907230440*	50-352 Q
	7907270337	50-322 Q		7907030220*	FOIA
	7907310487	50-3 Q			
	7907310547	50-29 Q		7907310178*	50-29 Q
	7907310489	50-213 Q		7907310167*	50-29 Q
	7907310499	50-219 Q		7907030068*	50-333 Q
	7907310511	50-220 Q		7907030062*	50-333 Q
	7907310542	50-244 Q		7907310027*	50-29 Q
	7907310509	50-245 Q		7907230128*	70-938
	7907310487	50-3 Q		7907230113*	70-938
	7907310544	50-271 Q		7907310158*	50-29 Q
	7907310533	50-272 Q		7907100269	50-320 H

Region 1, Philadelphia, Reactor  
Construction & Engineering Support Branch

Region 1, Philadelphia, Fuel Facility  
& Materials Safety Branch

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Region 1, Philadelphia, Reactor Operations Nuclear Support Branch	7907110455	40-7983		7907050203*	50-302 Q
	7907110460*	50-245 Q		7907020108*	50-287 Q
	7907110453	50-245 Q		7907020103*	50-302 Q
	7907230057*	50-220 Q		7907050155*	50-324 Q
	7907230044*	50-220 Q		7907160048*	50-312 Q
	7907300050*	50-244 Q		7907180640*	50-390 Q
	7907300044	50-244 Q		7907020139*	50-287 Q
	7907120234	50-320 H		7907020145*	50-302 Q
	7907230089	70-938		7907020072*	50-287 Q
	7907230029	50-220 Q		7907020069*	50-302 Q
	7907230006*	50-387 Q		7906200127*	50-269 Q
	7907250089	50-277 Q		7907020336	50-280 Q
	7907230003	50-387 Q		7907020342	50-321 Q
	7907200420*	50-57 Q		7907020343	50-259 Q
	7907130226	50-387 Q		7907020352	50-261 Q
	7907200469*	50-293 Q		7907020366	50-250 Q
	7907230549	50-272 Q		7907020367	50-413 Q
	7907230570*	50-272 Q		7907020366	50-250 Q
	7907230471	50-220 Q		7907020343	50-259 Q
	7907110426*	50-333 Q		7907020352	50-261 Q
	7907310130*	50-333 Q		7907020349	50-269 Q
	7907110544*	50-272 Q		7907020336	50-280 Q
	7907110494*	50-311 Q		7907020349	50-269 Q
	7907110544*	50-272 Q		7907020336	50-280 Q
	7907310115*	50-333 Q		7907020349	50-269 Q
	7907310017*	50-213 Q		7907020343	50-259 Q
	7907110489	50-311 Q		7907020366	50-250 Q
	7907110421	50-333 Q		7907020336	50-280 Q
	7907310011*	50-213 Q		7907020333	50-348 Q
	7907110534	50-272 Q		7907020342	50-321 Q
	7907180483*	50-247 Q		7907020352	50-261 Q
	7907180437*	50-286 Q		7907020343	50-259 Q
	7907180471	50-247 Q		7907020366	50-250 Q
	7907180445*	50-336 Q		7907020336	50-280 Q
	7907180430	50-286 Q		7907020352	50-261 Q
	7907180441	50-336 Q		7907020336	50-280 Q
	7907200804*	50-289 Q		7907020367	50-413 Q
	7907160456	50-320 H		7907020368	50-416 Q
	7907160551	50-320 H		7907020342	50-321 Q
	7907160563	50-320 H		7907020332	50-437 Q
	7907120224	50-320 H		7907020343	50-259 Q
	7907110633	50-277 Q		7907020367	50-413 Q
	7907200395	50-57 Q		7907020343	50-259 Q
	7907310006	50-213 Q		7907110590*	50-269 Q
	7907030213*	FOIA		7907240065*	50-280 Q
	7907030047	70-2622		7907240070*	50-250 Q
	7907050054*	70-2662		7907190070*	50-280 Q
	7907050047	70-2622		7907230790*	50-259 Q
	7907050054*	70-2662		7907050198	50-302 Q
	7907250407*	FOIA		7907090130*	50-335 Q
	7907130163*	50-184 Q		7907190143*	50-413 Q
	7907130035*	70-1100		7907230784*	50-259 Q
	7907130050*	70-1100		7907050103*	50-327 Q
	7907130160*	50-184 Q		7907050071*	50-338 Q
	7907130031*	70-1100		7907190149*	50-413 Q
	7907180720*	70-820		7907050143*	50-438 Q
	7907180734*	70-820		7907200411*	50-280 Q
	7907240297*	70-33		7907180791*	50-395 Q
	7907180709*	70-820		7907180801*	50-395 Q
	7907250524*	FOIA		7907110314	50-261 Q
	7907240296	70-33		7907110318	50-413 Q
	7907200490*	70-820		7907110319	50-269 Q
	7907200485	70-820		7907110325	50-250 Q
	7907270386*	50-220 Q		7907110329	50-321 Q
	7907130005	70-1100		7907110335	50-259 Q
	7907130156	50-184 Q		7907110344	50-280 Q
	7907180684	70-820		7907110743*	50-339 Q
	7907250402*	FOIA		7907110325	50-250 Q
	7907250415*	FOIA		7907110335	50-259 Q
	7907250537*	FOIA		7907110314	50-261 Q
	7907110665*	50-338 Q		7907110319	50-269 Q
	7907130504*	50-302 Q		7907110344	50-280 Q
	7907180087	50-321 Q		7907180693*	50-280 Q
	7907300010*	50-338 Q		7907090438*	50-281 Q
	7907310159*	50-259 Q		7907110344	50-280 Q
	7907310165*	50-259 Q		7907180693*	50-280 Q
	7907310159*	50-259 Q		7907110319	50-269 Q
	7907310159*	50-259 Q		7907110335	50-259 Q
	7907310165*	50-259 Q		7907110322	50-302 Q
	7907110329	50-321 Q			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907110314	50-241 Q		7907100085	50-63
	7907110335	50-259 Q		7907100102	50-111
	7907110325	50-250 Q		7907100078	50-124
	7907110344	50-280 Q		7907100193	50-129
				7907100657	50-160
	7907110743*	50-339 Q		7907100097	50-241
	7907110312	50-348 Q		7907100184	50-250
	7907110329	50-321 Q		7907100207	50-259
	7907110319	50-269 Q		7907100150	50-261
	7907110325	50-250 Q		7907100114	50-276
	7907110335	50-259 Q		7907100222	50-280
	7907110332	50-395 Q		7907100207	50-259
	7907110333	50-395 Q		7907100102	50-111
	7907110314	50-261 Q		7907100177	50-302
	7907110344	50-280 Q		7907100196	50-321
	7907110743*	50-339 Q		7907100150	50-261
	7907110344	50-280 Q		7907100207	50-259
	7907110743*	50-339 Q		7907100030	50-332
	7907110315	50-413 Q		7907100184	50-250
	7907110331	50-416 Q		7907100222	50-280
	7907110329	50-321 Q		7907240192*	50-339
	7907110310	50-437 Q		7907100143	50-348
	7907110335	50-259 Q		7907100196	50-321
	7907110318	50-413 Q		7907100657	50-160
	7907110335	50-259 Q		7907100184	50-250
	7907090434	50-281 Q		7907100207	50-259
	7907240429*	50-324 Q		7907100204	50-393
	7907240437*	50-324 Q		7907100081	50-62
	7907240452*	50-324 Q		7907100150	50-261
	7907240429*	50-324 Q		7907100222	50-280
	7907240437*	50-324 Q		7907100089	50-406
	7907240452*	50-324 Q		7907100167	50-413
	7907060454*	50-269 H		7907100202	50-416
	7907130359*	50-327 Q		7907100196	50-321
	7907180658*	50-348 Q		7907100023	50-437
				7907100036	50-437
	7907030140	50-259 Q			
	7907230740*	50-338 Q		7907100207	50-259
	7907310198*	50-338 Q		7907100167	50-413
	7907230740*	50-338 Q		7907100207	50-259
	7907310198*	50-338 Q		7907100207	50-259
	7907180634	50-348 Q		7907100025	50-537
	7907030140	50-259 Q		7907100096	50-538
	7907050157*	50-413 Q		7907100207	50-259
	7907030140	50-259 Q		7907100063	70-27
	7907200054*	70-1113		7907100083	50-83
				7907100070	70-143
	7907230488*	50-339 Q		7907100114	50-276
	7907240347*	50-339 Q		7907100081	50-62
	7907230768*	50-390 Q		7907100085	50-83
	7907190313*	50-416 Q		7907100071	70-824
	7907190319*	50-416 Q		7907100110	70-893
	7907190313*	50-416 Q		7907100085	50-83
	7907190319*	50-416 Q		7907100068	70-1113
	7907200074*	70-1113		7907100040	70-1151
	7907300070*	70-1151		7907100066	70-1201
	7907230724*	50-280 Q		7907100032	70-1432
	7907270043*	50-364 Q		7907240279*	50-280
	7906290406	50-320 P		7907270053*	50-261
	7907110657*	50-413 Q		7907240219*	50-400
	7907260023*	50-281 Q		7907050189*	50-400
	7907240225*	50-400 Q		7907060353	50-413
	7907240227*	50-400 Q		7907110088	50-400
	7907240225*	50-400 Q		7907110108	50-327
	7907240227*	50-400 Q		7907110103	50-250
	7907240225*	50-400 Q		7907240184*	50-250
	7907240227*	50-400 Q		7907110103	50-250
	7907240225*	50-400 Q		7907240184*	50-250
	7907240227*	50-400 Q		7907060364	50-259
	7907240275*	50-424 Q		7907110084	50-261
	7907240276*	50-424 Q		7907110093	50-269
	7907240285*	50-424 Q		7907060366	50-280
	7907240275*	50-424 Q		7907110095	50-269
	7907240276*	50-424 Q		7907060364	50-259
	7907240285*	50-424 Q		7907060358	50-302
	7907240186*	50-438 Q		7907060359	50-321
	7907230640*	70-143		7907110084	50-261
	7907230652*	70-143		7907110108	50-327
	7907100074	FRQJ			
	7907100085	50-83 Q		7907110103	50-250
	7907100150	50-261 Q		7907060366	50-280
	7907100167	50-413 Q		7907110127	50-339
				7907110080	50-348
	7907100184	50-250 Q		7907060352	50-364
				7907060359	50-321
	7907100196	50-321 Q		7907110091	50-369
	7907100207	50-259 Q		7907110097	50-389
	7907100222	50-280 Q		7907110108	50-327
	7907100081	50-62 Q			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907060362	50-395 Q		7907200196	50-321 Q
	7907060363	50-395 Q		7907200167	50-324 Q
	7907090189*	50-400 Q		7907200210	50-327 Q
	7907110088	50-400 Q		7907200192	50-250 Q
	7907050189*	50-400 Q		7907200223	50-280 Q
	7907110088	50-400 Q		7907200162	50-348 Q
	7907050189*	50-400 Q		7907200196	50-321 Q
	7907110088	50-400 Q		7907200186	50-269 Q
	7907050189*	50-400 Q		7907200192	50-250 Q
	7907110088	50-400 Q		7907200210	50-327 Q
	7907110127	50-339 Q		7907200204	50-395 Q
	7907060353	50-413 Q		7907200205	50-395 Q
	7907060361	50-416 Q		7907260516	50-395 Q
	7907110105	50-424 Q		7907200165	50-261 Q
	7907060350	50-437 Q		7907200223	50-280 Q
	7907110108	50-327 Q		7907200170	50-413 Q
	7907060353	50-413 Q		7907200200	50-416 Q
	7907110108	50-327 Q		7907200198	50-424 Q
	7907090433*	50-491 Q		7907200257	50-437 Q
	7907240201*	50-390 Q		7907200210	50-327 Q
	7907090433*	50-491 Q		7907200170	50-413 Q
	7907240129*	50-327 Q		7907200210	50-327 Q
	7907290147*	50-335 Q		7907100540	50-320 H
	7907240148*	50-553 Q		7907120426	50-321 Q
	7907300008	50-338 Q		7907190148	50-261 Q
	7907240163*	50-369 Q		7907190153	50-269 Q
	7907090411	50-424 Q		7907190159	50-413 Q
	7907090416*	50-424 H		7907190172	50-280 Q
	7907090411	50-424 Q		7907190175	50-321 Q
	7907090416*	50-424 H		7907190191	50-259 Q
	7907030090	50-261 Q		7907190209	50-280 Q
	7907030093	50-269 Q		7907190172	50-250 Q
	7907030096	50-250 Q		7907190191	50-259 Q
	7907030098	50-321 Q		7907190148	50-261 Q
	7907030105	50-259 Q		7907190153	50-269 Q
	7907030114	50-280 Q		7907190209	50-280 Q
	7907030096	50-250 Q		7907190153	50-269 Q
	7907260508*	50-250 Q		7907190191	50-259 Q
	7907030096	50-250 Q		7907190168	50-302 Q
	7907260508*	50-250 Q		7907100554	50-320 H
	7907030105	50-259 Q		7907190175	50-321 Q
	7907030090	50-261 Q		7907190148	50-261 Q
	7907030093	50-269 Q		7907190191	50-259 Q
	7907030114	50-280 Q		7907190172	50-250 Q
	7907030093	50-269 Q		7907190209	50-280 Q
	7907030105	50-259 Q		7907190144	50-348 Q
	7907030095	50-302 Q		7907190175	50-321 Q
	7907030098	50-321 Q		7907190153	50-269 Q
	7907030090	50-261 Q		7907190172	50-250 Q
	7907030105	50-259 Q		7907190191	50-259 Q
	7907030096	50-250 Q		7907190184	50-395 Q
	7907030114	50-280 Q		7907190187	50-395 Q
	7907030086	50-348 Q		7907190148	50-261 Q
	7907030098	50-321 Q		7907190209	50-280 Q
	7907030093	50-269 Q		7907190159	50-413 Q
	7907030096	50-250 Q		7907190180	50-416 Q
	7907030105	50-259 Q		7907190175	50-321 Q
	7907030101	50-395 Q		7907190191	50-259 Q
	7907030090	50-261 Q		7907190189	50-413 Q
	7907030114	50-280 Q		7907190191	50-259 Q
	7907030102	50-416 Q		7907060043	50-261 Q
	7907030098	50-321 Q		7907060048	50-413 Q
	7907030085	50-437 Q		7907060036	50-250 Q
	7907030105	50-259 Q		7907060059	50-321 Q
	7907300028*	50-280 Q		7907060064	50-259 Q
	7907300082*	50-280 Q		7907060069	50-280 Q
	7907300028*	50-280 Q		7907100161	50-269 Q
	7907300082*	50-280 Q		7907060036	50-250 Q
	7907260538*	50-327 Q		7907060064	50-259 Q
	7907250106*	50-348 Q		7907060043	50-261 Q
	7907260522*	50-395 Q		7907100161	50-269 Q
	7907200165	50-261 Q		7907060069	50-280 Q
	7907200170	50-413 Q		7907100161	50-269 Q
	7907200186	50-269 Q		7907060064	50-259 Q
	7907200192	50-250 Q		7907060055	50-302 Q
	7907200210	50-327 Q		7907060059	50-321 Q
	7907200223	50-280 Q		7907060043	50-261 Q
	7907200192	50-250 Q		7907060064	50-259 Q
	7907200206	50-259 Q		7907060036	50-250 Q
	7907200165	50-261 Q		7907060069	50-280 Q
	7907200186	50-269 Q		7907060040	50-348 Q
	7907200223	50-280 Q		7907060059	50-321 Q
	7907200186	50-269 Q		7907100161	50-269 Q
	7907200206	50-259 Q		7907060036	50-250 Q
	7907200188	50-302 Q		7907060064	50-259 Q

# U.S. NUCLEAR REGULATORY COMMISSION

## ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907060061	50-395 Q		7907020393	50-259 Q
	7907060062	50-395 Q		7907120036	50-261 Q
	7907060063	50-261 Q		7907120051	50-413 Q
	7907060069	50-280 Q		7907120061	50-269 Q
	7907060068	50-413 Q		7907120075	50-250 Q
	7907060060	50-416 Q		7907120079	50-321 Q
	7907060059	50-321 Q		7907120104	50-259 Q
	7907060064	50-259 Q		7907120142	50-280 Q
	7907060048	50-413 Q		7907120075	50-250 Q
	7907060064	50-259 Q		7907120104	50-259 Q
	7907300499	50-302 H		7907120036	50-261 Q
	7907020194	50-400 Q		7907120061	50-269 Q
	7907020198	50-413 Q		7907120142	50-280 Q
	7907020220	50-327 Q		7907120061	50-269 Q
	7907250158	50-250 Q		7907120104	50-259 Q
	7907250165	50-259 Q		7907120071	50-302 Q
	7907250151	50-261 Q			
	7907250155	50-269 Q		7907120079	50-321 Q
	7907250169	50-280 Q		7907120036	50-261 Q
	7907250155	50-269 Q		7907120104	50-259 Q
				7907120075	50-250 Q
	7907250165	50-259 Q			
	7907250156	50-302 Q		7907120142	50-280 Q
	7907250163	50-321 Q		7907120033	50-348 Q
	7907250150	50-324 Q		7907120079	50-321 Q
	7907020220	50-327 Q		7907120061	50-269 Q
				7907120075	50-250 Q
	7907250167	50-327 Q		7907120104	50-259 Q
	7907020220	50-327 Q		7907120096	50-395 Q
	7907250167	50-327 Q		7907120098	50-395 Q
	7907250160	50-335 Q		7907120036	50-261 Q
	7907250168	50-338 Q		7907120142	50-280 Q
	7907250148	50-348 Q		7907120051	50-413 Q
	7907020190	50-364 Q		7907120084	50-416 Q
	7907250163	50-321 Q		7907120079	50-321 Q
	7907020205	50-369 Q		7907120151	50-437 Q
	7907250153	50-369 Q		7907120104	50-259 Q
	7907020205	50-369 Q		7907120051	50-413 Q
	7907020208	50-389 Q		7907120104	50-259 Q
	7907250160	50-335 Q		7907110234	50-280 Q
	7907020220	50-327 Q		7907230415	50-62 Q
	7907250434	50-391 Q		7907230413	50-63 Q
	7907020217	50-395 Q		7907230410	50-111 Q
	7907020194	50-400 Q		7907230416	50-124 Q
	7907020233	50-404 Q		7907230418	50-129 Q
	7907020198	50-413 Q		7907230408	50-160 Q
	7907020214	50-416 Q		7907110226	50-250 Q
	7907020211	50-424 Q		7907110230	50-259 Q
	7907020220	50-327 Q		7907110217	50-269 Q
	7907020198	50-413 Q		7907230408	50-160 Q
	7907020220	50-327 Q		7907110234	50-280 Q
	7907190828	70-143		7907110217	50-269 Q
	7907310524	50-261 P		7907110230	50-259 Q
	7907020375	50-261 Q		7907230410	50-111 Q
	7907020379	50-413 Q		7907110220	50-302 Q
	7907020382	50-269 Q		7907110228	50-321 Q
	7907020386	50-250 Q		7907110213	50-324 Q
	7907020393	50-259 Q		7907110226	50-250 Q
	7907020401	50-280 Q			
	7907190518	50-321 Q		7907110234	50-280 Q
	7907020386	50-250 Q		7907110211	50-348 Q
	7907020393	50-259 Q		7907110228	50-321 Q
				7907230415	50-62 Q
	7907020375	50-261 Q			
	7907020382	50-269 Q		7907230412	50-406 Q
	7907020401	50-280 Q		7907230409	50-338 Q
	7907020382	50-269 Q		7907180724	70-27
	7907020393	50-259 Q		7907110209	70-143
				7907230405	70-824
	7907020384	50-302 Q		7907180723	70-1113
	7907190518	50-321 Q		7907180725	70-1201
	7907020375	50-261 Q		7907310019	50-250 Q
	7907020393	50-259 Q		7907310029	50-259 Q
	7907020386	50-250 Q		7907310007	50-269 Q
	7907020401	50-280 Q		7907310043	50-280 Q
	7907020374	50-348 Q		7907310009	50-269 Q
	7907190518	50-321 Q		7907310029	50-259 Q
	7907020382	50-269 Q		7907310018	50-302 Q
	7907020386	50-250 Q		7907310020	50-321 Q
	7907020393	50-259 Q		7907310004	50-324 Q
	7907020391	50-395 Q		7907310029	50-259 Q
	7907020375	50-261 Q		7907310019	50-250 Q
	7907020401	50-280 Q		7907310043	50-280 Q
	7907020379	50-413 Q		7907310001	50-348 Q
	7907020389	50-416 Q		7907310002	50-364 Q
	7907190518	50-321 Q		7907310020	50-321 Q
	7907020371	50-437 Q		7907310009	50-269 Q
	7907020393	50-259 Q		7907310029	50-259 Q
	7907020379	50-413 Q		7907310026	50-395 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907310004	50-324 Q		7907310234	50-249 Q
	7907310046	50-404 Q		7907310240	50-250 Q
	7907310012	50-413 Q		7907310243	50-259 Q
	7907310024	50-416 Q		7907310229	50-261 Q
	7907310020	50-321 Q		7907310245	50-413 Q
	7907310029	50-259 Q		7907310258	50-416 Q
	7907310012	50-413 Q		7907310254	50-321 Q
	7907310029	50-259 Q		7907310282	50-437 Q
	7907110263	50-249 Q		7907310263	50-259 Q
	7907110269	50-250 Q		7907310245	50-413 Q
	7907110263	50-269 Q		7907310263	50-259 Q
	7907110266	50-302 Q		7907310003	50-338 Q
	7907230711	50-302 Q		7907240484	50-13 Q
	7907110269	50-250 Q		7907240474	50-83 Q
	7907110259	50-348 Q		7907240484	50-13 Q
	7907110263	50-269 Q		7907240468	50-111 Q
	7907110269	50-250 Q		7907240476	50-124 Q
	7907110277	50-395 Q		7907240478	50-129 Q
	7907110274	50-416 Q		7907240464	50-160 Q
	7907180281	50-400 Q		7907240468	50-111 Q
	7907180288	50-413 Q		7907240481	50-332 Q
	7907180321	50-327 Q		7907240470	50-406 Q
	7907180340	50-339 Q		7907240466	50-538 Q
	7907180278	50-364 Q		7907240489	70-27
	7907180303	50-369 Q		7907240495	70-143
	7907180306	50-389 Q		7907240486	70-824
	7907180321	50-327 Q		7907240492	70-1113
	7907180318	50-395 Q		7907240487	70-1201
	7907180281	50-400 Q		7907310157	70-1319
	7907180340	50-339 Q		7907240498	70-1432
	7907180288	50-413 Q		7907310379	50-250 Q
	7907180315	50-416 Q		7907310387	50-259 Q
	7907180311	50-424 Q		7907310362	50-261 Q
	7907180343	50-437 Q		7907310369	50-269 Q
	7907180321	50-327 Q		7907310389	50-280 Q
	7907180288	50-413 Q		7907310369	50-269 Q
	7907180321	50-327 Q		7907310387	50-259 Q
	7907180427	50-261 Q		7907310378	50-302 Q
	7907180431	50-413 Q		7907310383	50-321 Q
	7907180435	50-250 Q		7907310362	50-261 Q
	7907180436	50-321 Q		7907310387	50-259 Q
	7907180443	50-259 Q		7907310379	50-250 Q
	7907180446	50-280 Q		7907310389	50-280 Q
	7907180597	50-269 Q		7907310360	50-348 Q
	7907180435	50-250 Q		7907310383	50-321 Q
	7907180443	50-259 Q		7907310369	50-269 Q
	7907180427	50-261 Q		7907310379	50-250 Q
	7907180597	50-269 Q		7907310387	50-259 Q
	7907180446	50-280 Q		7907310385	50-395 Q
	7907180597	50-269 Q		7907310386	50-395 Q
	7907180443	50-259 Q		7907310362	50-261 Q
	7907180433	50-302 Q		7907310389	50-280 Q
	7907180436	50-321 Q		7907310371	50-413 Q
	7907180427	50-261 Q		7907310384	50-416 Q
	7907180443	50-259 Q		7907310383	50-321 Q
	7907180435	50-250 Q		7907310391	50-437 Q
	7907180446	50-280 Q		7907310387	50-259 Q
	7907180426	50-348 Q		7907310371	50-413 Q
	7907180436	50-321 Q		7907310387	50-259 Q
	7907180597	50-269 Q		7907240281	50-259 Q
	7907180435	50-250 Q		7907110645*	50-338 Q
	7907180443	50-259 Q		7907110678*	50-338 Q
	7907180440	50-395 Q		7907110654*	50-338 Q
	7907180427	50-261 Q		7907190103*	50-321 Q
	7907180446	50-280 Q		7907190110*	50-321 Q
	7907180431	50-413 Q		7907190121*	50-321 Q
	7907180439	50-414 Q		7907190103*	50-321 Q
	7907180436	50-321 Q		7907190110*	50-321 Q
	7907180447	50-437 Q		7907190121*	50-321 Q
	7907180443	50-259 Q		7907180614*	50-390 Q
	7907180431	50-413 Q		7907180623*	50-390 Q
	7907180443	50-259 Q		7907180640*	50-390 Q
	7907310240	50-250 Q		7907180614*	50-390 Q
	53	50-259 Q		7907180623*	50-390 Q
	9	50-261 Q		7907180640*	50-390 Q
	7907310263	50-259 Q		7906200428	50-320 P
	7907310227	50-302 Q		7907050095	50-327 Q
	7907310254	50-321 Q		7907050103*	50-327 Q
	7907310229	50-261 Q		7907050095	50-327 Q
	7907310263	50-259 Q		7907050103*	50-327 Q
	7907310240	50-250 Q		7907190137*	50-413 Q
	7907310263	50-259 Q		7907190149*	50-413 Q
	7907310223	50-348 Q		7907190137*	50-413 Q
	7907310254	50-321 Q		7907190149*	50-413 Q

Region 2, Atlanta, Reactor Constructi  
on & Engineering Support Branch



# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

473

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907120523	50-424 Q		7907300040	50-302 Q
	7907120533*	50-424 Q		7907250106*	50-348 Q
	7907120523	50-424 Q		7907260145	50-395 Q
	7907120533*	50-424 Q		7907260151*	50-395 Q
	7907050134	50-438 Q		7907260133	50-553 Q
	7907050143*	50-438 Q		7907260142*	50-553 Q
	7907050134	50-438 Q		7907260133	50-553 Q
	7907050143*	50-438 Q		7907260142*	50-553 Q
	7907180549	50-395 Q		7907280103*	50-348 Q
	7907180801*	50-395 Q		7907270380*	50-369 Q
				7907190120	50-413 Q
	7907090438*	50-281 Q		7907190085	50-321 Q
	7907200290*	50-281 Q		7907180592	50-390 Q
	7907110721	50-339 Q		7907260542*	50-348 Q
	7907200250*	50-348 Q		7907260517*	50-348 Q
	7907110721	50-339 Q		7907190287	50-416 Q
	7907130443*	50-518 Q		7907240400	50-324 Q
	7907200278	50-281 Q		7907240259	50-424 Q
	7907240123*	50-338 Q		7907260076*	50-287 Q
	7907200244	50-348 Q		7907260062*	50-287 Q
	7907130443*	50-518 Q		7907300380	50-424 Q
	7907130432	50-518 Q		7907240268	50-424 Q
	7907050154*	50-413 Q		7907270373	50-369 Q
	7907050187*	50-413 Q		7907260495	50-348 Q
	7907050154*	50-413 Q		7907310178*	50-29 Q
	7907050187*	50-413 Q			
	7907130432	50-518 Q		7907130511*	50-302 Q
	7907230768*	50-390 Q		7907130500*	50-302 Q
	7907190319*	50-416 Q		7907050203*	50-302 Q
	7907240420*	50-324 Q		7906200415	50-320 P
	7907230755	50-390 Q		7907050158*	50-324 Q
				7907110596*	50-269 Q
	7907240383	50-390 Q		7907110583*	50-269 Q
	7907240391*	50-390 Q		7906200393	50-320 P
	7907230735	50-390 Q		7907180695*	50-280 Q
	7907240383	50-390 Q		7907160268*	70-143
	7907240391*	50-390 Q		7907180679*	50-280 Q
				7907180686*	50-280 Q
	7907190307*	50-416 Q		7907180679*	50-280 Q
	7907270036	50-364 Q		7907200233	70-27
	7907050182*	50-400 Q		7907200234*	70-27
	7907110657*	50-413 Q		7907160259*	70-143
	7907110643	50-413 Q		7906290389	50-320 P
				7906290386	50-320 P
	7907240285*	50-424 Q		7906290401	50-320 P
				7907230724*	50-280 Q
	7907240084	50-518 Q		7907230708	50-280 Q
	7907240099*	50-518 Q		7907260009*	50-280 Q
	7907130351	50-315 Q		7907260007*	50-280 Q
	7907130225*	50-395 Q		7907260023*	50-281 Q
	7907240084	50-518 Q		7907260005*	50-280 Q
	7907240099*	50-518 Q		7907260007*	50-280 Q
	7907240084	50-518 Q		7907260023*	50-281 Q
	7907240099*	50-518 Q			
	7907240084	50-518 Q		7907260023*	50-280 Q
	7907240099*	50-518 Q		7907260023*	50-280 Q
	7907130210*	50-395 Q		7907250652*	70-143
	7907240272*	50-424 Q		7907260004	50-280 Q
	7907240181	50-438 Q		7907230623*	70-143
	7907270048	50-261 Q		7907110598*	50-400 Q
	7907050189*	50-400 Q		7907110589*	50-400 Q
	7907240197	50-390 Q		7907100428	50-320 H
	7907240201*	50-390 Q		7907240148*	50-553 Q
	7907240197	50-390 Q		7907270406*	50-302 Q
	7907240201*	50-390 Q		7907240132	50-553 Q
	7907090426*	50-491 Q		7907130422	50-302 Q
	7907090433*	50-491 Q		7907270402*	50-302 Q
	7907090426*	50-491 Q		7907270403*	50-302 Q
	7907090433*	50-491 Q		7907300028*	50-280 Q
	7907090426*	50-491 Q		7907100447	50-320 H
	7907090433*	50-491 Q		7907260532	50-327 Q
	7907300032	50-261 Q		7907300021	50-280 Q
	7907240122	50-327 Q		7907100452	50-320 H
	7907240129*	50-327 Q		7907100477	50-320 H
	7907240122	50-327 Q		7907100824	50-320 H
	7907240129*	50-327 Q		7907110574	50-269 Q
	7907270383*	50-369 Q		7907180652	50-280 Q
	7907270387*	50-369 Q		7907100565	50-320 H
	7907270383*	50-369 Q		7907100573	50-320 H
	7907270387*	50-369 Q			
	7907110563*	50-413 Q		7907230607	70-143
	7907110568*	50-413 Q		7907300265	50-280 Q
	7907110563*	50-413 Q		7907270393	50-302 Q
	7907110568*	50-413 Q		7907300018*	50-338 Q
	7907240155	50-369 Q		7907310155	50-259 Q
	7907240163*	50-369 Q		7907020176	50-320 P
	7907260502	50-250 Q			

Region 2, Atlanta, Fuel Facility &amp; Materials Safety Branch

Region 2, Atlanta, Reactor Operations Nuclear Support Branch

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907160195*	50-369 Q		7907230498	70-27
	7907160072	50-287 Q		7907300060	70-1151
	7907160030*	50-287 Q			
	7907160040*	50-302 Q		7907200039	70-1113
	7906200120*	50-269 Q		7907200059	70-1113
	7907240070*	50-250 Q		7907050147	50-305 Q
	7907190078*	50-280 Q			
	7907230790*	50-259 Q		7907120166	50-320 H
				7907050552*	50-304 Q
	7907120560*	50-324 Q			
	7907230775*	50-259 Q		7907020115*	50-346 Q
	7907190066*	50-280 Q		7907020149*	50-346 Q
	7907230775*	50-259 Q		7907020076*	50-346 Q
	7907120558	50-324 Q		7907160059	50-346 Q
				7907050187*	50-482 Q
	7907090126	50-335 Q			
	7907050071*	50-338 Q		7907110136*	50-305 Q
	7907240029*	50-250 Q		7907270407*	50-315 Q
	7907050067	50-338 Q		7907130320*	50-341 Q
	7907200404	50-280 Q		7907180460*	50-546 Q
				7907180464*	50-546 Q
	7906290383	50-320 P			
	7907180244*	50-366 Q		7907180474*	50-546 Q
	7907060448	50-269 P		7907180464*	50-546 Q
	7907130356	50-327 Q		7907180474*	50-546 Q
	7907230024*	50-338 Q		7907260526*	50-301 Q
	7907230039*	50-338 Q		7907180627*	50-358 Q
	7907230740*	50-338 Q		7907260300*	50-155 Q
	7907310203*	50-338 Q		7907300096*	50-329 Q
	7907230024*	50-338 Q		7907180608*	50-358 Q
	7907230039*	50-338 Q		7907180627*	50-358 Q
	7907230740*	50-338 Q		7907180449*	50-451 Q
	7907310203*	50-338 Q			
	7907180233	50-366 Q		7907180451*	50-451 Q
	7907160191*	50-369 Q		7907050117*	50-305 Q
				7907110438*	70-925
	7907310194*	50-338 Q		7907190497*	50-10 Q
	7907240347*	50-339 Q		7907190507*	50-10 Q
	7907310194*	50-338 Q		7907190497*	50-10 Q
	7907230018*	50-338 Q		7907190507*	50-10 Q
	7907240119	50-338 Q		7907180319*	50-155 Q
				7907190497*	50-10 Q
	7907230018*	50-338 Q			
	7907240119	50-338 Q		7907190507*	50-10 Q
	7907240337	50-339 Q		7907190497*	50-10 Q
	7907130485*	50-338 Q		7907190507*	50-10 Q
	7907130490*	50-338 Q		7907100331	50-320 H
				7907180500*	50-295 Q
	7907230734	50-338 Q			
	7907300037*	50-261 Q		7907180354*	50-315 Q
	7907130483*	50-338 Q		7907180294*	50-295 Q
	7907240189	50-339 Q		7907180323*	50-295 Q
	7907240184*	50-250 Q		7907180294*	50-295 Q
				7907180323*	50-295 Q
	7907240276	50-280 Q			
	7907240170	50-250 Q		7907250443*	50-440 Q
	7907100419	50-320 H		7907250452*	50-440 Q
	7907300043*	50-302 Q		7907250443*	50-440 Q
	7907100435	50-320 H		7907250452*	50-440 Q
				7907130354*	50-315 Q
	7907250143	50-335 Q			
	7907250147*	50-335 Q		7907180598	50-358 Q
	7907300082*	50-280 Q		7907240186*	50-438 Q
	7907300075	50-280 Q		7907180560*	50-295 Q
	7907100535	50-320 H		7907180574*	50-295 Q
				7907180560*	50-295 Q
	7907100541	50-320 H			
	7907190050	50-280 Q		7907180574*	50-295 Q
	7907130455	50-338 Q		7907180345	50-315 Q
	7907230748	50-259 Q		7907260089	50-10 P
	7907240004	50-250 Q		7907260095	50-155 P
				7907260089	50-10 P
	7907230012	50-338 Q			
	7907310181	50-338 Q		7907260095	50-155 P
	7907230012	50-338 Q		7907260103	50-263 P
	7907310181	50-338 Q		7907260089	50-10 P
	7907230002*	50-250 Q		7907260110	50-266 P
				7907260103	50-263 P
	7907160253	50-302 Q			
	7907130145*	70-143		7907260089	50-10 P
	7907050150	50-324 Q			
	7906200127*	50-269 Q		7907260110	50-266 P
	7907230523*	70-27		7907260089	50-10 P
				7907260112	50-305 P
	7907230515*	70-27		7907260103	50-263 P
	7907300064*	70-1151			
	7907200054*	70-1113		7907260086	50-315 P
	7907200225	50-83 Q		7907260098	50-331 P
	7907200241*	50-83 Q		7907260106	50-346 P
				7907260097	50-409 P
	7907230483	50-339 Q		7907050479	70-925
	7907230488*	50-339 Q			
	7907200074*	70-1113		7907110068	50-10 Q
	7907300070*	70-1151		7907100438	50-320 H
	7907200049*	70-1113		7907120184	50-320 H
				7907240191*	50-409 Q
	7907200070*	70-1113		7907240630*	50-305 Q
	7907130091	50-324 Q			
	7907130111	70-143		7907250079*	50-266 Q

Region 2, Atlanta, Safeguards Branch

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

47

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907250083*	50-266 Q		7907190276	50-367 Q
	7907240200*	50-282 Q		7907190224	50-10 Q
	7907230276*	50-295 Q		7907190249	50-409 Q
	7907230351*	50-295 Q		7907190240	50-440 Q
	7907230364*	50-295 Q		7907190224	50-10 Q
	7907250079*	50-266 Q		7907190269	50-461 Q
	7907250083*	50-266 Q		7907261011*	50-461 Q
	7907230276*	50-295 Q		7907190269	50-461 Q
	7907230351*	50-295 Q		7907190295	50-483 Q
	7907230364*	50-295 Q		7907190280	50-484 Q
	7907240200*	50-282 Q		7907190295	50-483 Q
	7907240164*	50-329 Q		7907190288	50-546 Q
	7907240127*	50-373 Q		7907240241	50-10 Q
	7907230741	50-456 Q		7907240252	50-155 Q
	7907230746*	50-456 Q		7907240241	50-10 Q
	7907230741	50-456 Q		7907240252	50-155 Q
	7907230746*	50-456 Q		7907240432	50-263 Q
	7907240169	50-546 Q		7907270127	50-263 Q
	7907200287	50-295 Q		7907240241	50-10 Q
	7907200296	50-10 Q		7907240448	50-266 Q
	7907200292	50-10 Q		7907240432	50-263 Q
	7907200296	50-10 Q		7907240241	50-10 Q
	7907200310	50-155 Q		7907240448	50-266 Q
	7907200296	50-10 Q		7907240241	50-10 Q
	7907200308	50-253 Q		7907240450	50-305 Q
	7907200326	50-263 Q		7907300412*	50-305 Q
	7907200296	50-10 Q		7907240432	50-263 Q
	7907200336	50-266 Q		7907240427	50-315 Q
	7907200328	50-282 Q		7907120173	50-320 H
	7907200287	50-295 Q		7907240251	50-329 Q
	7907200336	50-266 Q		7907240422	50-331 Q
	7907200287	50-295 Q		7907240287	50-341 Q
	7907200338	50-305 Q		7907240441	50-346 Q
	7907200328	50-282 Q		7907240246	50-338 Q
	7907200320	50-315 Q		7907240428	50-367 Q
	7907100461	50-320 H		7907300326*	50-367 Q
	7907100469	50-320 H		7907240241	50-10 Q
	7907200307	50-329 Q		7907240254	50-409 Q
	7907200316	50-331 Q		7907240250	50-440 Q
	7907200314	50-341 Q		7907240241	50-10 Q
	7907200332	50-346 Q		7907240425	50-461 Q
	7907200300	50-358 Q		7907240444	50-483 Q
	7907200322	50-367 Q		7907240435	50-484 Q
	7907200287	50-295 Q		7907240444	50-483 Q
	7907200312	50-409 Q		7907240438	50-546 Q
	7907260264*	50-409 Q		7907060007	50-10 Q
	7907200303	50-440 Q		7907300339*	50-263 Q
	7907200287	50-295 Q		7907060007	50-10 Q
	7907200318	50-461 Q		7907020237	50-373 Q
	7907200334	50-483 Q		7907300194*	50-266 Q
	7907200325	50-484 Q		7907300092*	50-315 Q
	7907200334	50-483 Q		7907020249	50-329 Q
	7907200330	50-546 Q		7907300474	50-331 Q
	7907100536	50-320 H		7907310028*	50-331 Q
	7907240156	50-329 Q		7907020282	50-341 Q
	7907050163*	50-346 Q		7907020242	50-338 Q
	7907300071*	50-255 Q		7907020258	50-367 Q
	7907270133*	50-263 Q		7907020237	50-373 Q
	7907260169*	50-341 Q		7907020245	50-440 Q
	7907240043	40-8211		7907020237	50-373 Q
	7907260240*	50-10 Q		7907020254	50-461 Q
	7907260196*	50-329 Q		7907240238	50-483 Q
	7907110056	70-1379		7907240226	50-484 Q
	7907190224	50-10 Q		7907240238	50-483 Q
	7907190230	50-249 Q		7907240233	50-546 Q
	7907190224	50-10 Q		7907240245	ORQ
	7907190245	50-155 Q		7907300486	50-237 Q
	7907190224	50-10 Q		7907310086*	50-254 Q
	7907190230	50-249 Q		7907310096*	50-254 Q
	7907190245	50-155 Q		7907310096*	50-254 Q
	7907190285	50-263 Q		7907300086*	50-315 Q
	7907190230	50-249 Q		7907180462	50-331 P
	7907190296	50-266 Q		7907180296*	50-346 Q
	7907190230	50-249 Q		7907180522	50-456 Q
	7907190299	50-305 Q		7907310189*	50-116 Q
	7907190285	50-263 Q		7907180455*	50-254 Q
	7907190272	50-315 Q		7907300491	50-254 Q
	7907190244	50-329 Q		7907180455*	50-254 Q
	7907190267	50-331 Q		7907300491	50-254 Q
	7907190298	50-341 Q		7907300491	50-254 Q
	7907190290	50-346 Q		7907020406	ORQ
	7907190236	50-358 Q		7907020409	50-10 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907020423	50-155 Q		7907050451	50-263 Q
	7907020409	50-10 Q		7907050448	50-315 Q
	7907020423	50-155 Q		7907050522	50-331 Q
	7907020435	50-263 Q		7907050454	50-346 Q
	7907020409	50-10 Q		7907230432	50-151 Q
	7907020440	50-266 Q		7907050821	50-409 Q
	7907020435	50-263 Q		7907050428	70-8
	7907020409	50-10 Q		7907050432	70-36
	7907020440	50-266 Q		7907050421	70-152
	7907020409	50-10 Q		7907050422	70-572
	7907020441	50-305 Q		7907050437	70-925
	7907300526*	50-305 Q		7907050436	70-1220
	7907020435	50-263 Q		7907050438	70-1489
	7907020431	50-315 Q		7907120680	50-10 Q
	7907020421	50-329 Q		7907230421	ORQ
	7907020428	50-331 Q		7907120680	50-10 Q
	7907020426	50-341 Q		7907120700	50-155 Q
	7907020437	50-346 Q		7907300479	50-155 Q
	7907020416	50-358 Q		7907120680	50-10 Q
	7907020432	50-367 Q		7907120696	50-255 Q
	7907020409	50-10 Q		7907130136	50-263 Q
	7907020424	50-409 Q		7907120680	50-10 Q
	7907020419	50-440 Q		7907130165	50-266 Q
	7907020409	50-10 Q		7907130138	50-282 Q
	7907020429	50-461 Q		7907120691	50-299 Q
	7907020438	50-483 Q		7907130165	50-266 Q
	7907020433	50-484 Q		7907120691	50-299 Q
	7907020438	50-483 Q		7907130169	50-305 Q
	7907020436	50-546 Q		7907130138	50-282 Q
	7907120198	50-10 Q		7907120676	50-315 Q
	7907120225	50-155 Q		7907130113	50-329 Q
	7907120198	50-10 Q		7907130122	50-331 Q
	7907120225	50-155 Q		7907130119	50-341 Q
	7907120248	50-263 Q		7907130150	50-346 Q
	7907120198	50-10 Q		7907120693	50-358 Q
	7907120268	50-266 Q		7907130131	50-367 Q
	7907120248	50-263 Q		7907120680	50-10 Q
	7907120198	50-10 Q		7907130117	50-409 Q
	7907120268	50-266 Q		7907120694	50-440 Q
	7907120198	50-10 Q		7907120680	50-10 Q
	7907120269	50-305 Q		7907130125	50-461 Q
	7907120248	50-263 Q		7907130155	50-483 Q
	7907120238	50-315 Q		7907130142	50-484 Q
	7907120221	50-329 Q		7907130155	50-483 Q
	7907120231	50-331 Q		7907130147	50-546 Q
	7907120229	50-341 Q		7907130172	50-580 Q
	7907120257	50-346 Q		7907060303	50-10 Q
	7907120215	50-358 Q		7907060310	50-155 Q
	7907120242	50-367 Q		7907060303	50-10 Q
	7907120198	50-10 Q		7907060310	50-155 Q
	7907120227	50-409 Q		7907060318	50-263 Q
	7907120218	50-440 Q		7907060303	50-10 Q
	7907120198	50-10 Q		7907060004	50-266 Q
	7907120233	50-461 Q		7907060318	50-263 Q
	7907120262	50-483 Q		7907060303	50-10 Q
	7907120244	50-484 Q		7907060004	50-266 Q
	7907120262	50-483 Q		7907060303	50-10 Q
	7907120252	50-546 Q		7907060005	50-305 Q
	7907050441	50-10 Q		7907060318	50-263 Q
	7907110198	ORQ		7907060302	50-315 Q
	7907120293	ORQ		7907060308	50-329 Q
	7907050431	40-3392		7907060313	50-331 Q
	7907230433	50-2 Q		7907060312	50-341 Q
	7907050441	50-10 Q		7907060320	50-346 Q
	7907230425	50-87 Q		7907060306	50-358 Q
	7907230428	50-116 Q		7907060315	50-367 Q
	7907230435	50-123 Q		7907060303	50-10 Q
	7907230430	50-150 Q		7907060311	50-409 Q
	7907230432	50-151 Q		7907060307	50-440 Q
	7907050445	50-155 Q		7907060303	50-10 Q
	7907230436	50-156 Q		7907060314	50-461 Q
	7907230431	50-182 Q		7907060003	50-483 Q
	7907230434	50-186 Q		7907060317	50-484 Q
	7907050441	50-10 Q		7907060003	50-483 Q
	7907050445	50-155 Q		7907060319	50-546 Q
	7907050451	50-263 Q		7907060002	50-580 Q
		54 Q		7907020275	ORQ
		1 Q		7907050466	50-373 Q
		14 Q		7907060001	ORQ
		13 Q		7907050472	50-329 Q
		14 Q		7907050473	50-341 Q
		1 Q		7907050469	50-358 Q
		16 Q		7907050477	50-367 Q
		1 Q		7907050466	50-373 Q
		15 Q		7907050470	50-440 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

4

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907050466	50-373 Q		7907240120	50-305 Q
	7907050474	50-461 Q			
	7907050481	50-483 Q		7907240104	50-263 Q
	7907050478	50-484 Q		7907240097	50-315 Q
	7907050481	50-483 Q		7907240094	50-331 Q
				7907240108	50-346 Q
	7907050480	50-546 Q			
	7907050463	50-580 Q		7907240091	50-409 Q
	7907180392	50-10 Q		7907240016	50-87 Q
	7907100487	DRG		7907240022	50-116 Q
				7907240033	50-123 Q
	7907180392	50-10 Q		7907240026	50-150 Q
	7907180406	50-155 Q			
	7907180392	50-10 Q		7907240030	50-151 Q
	7907180406	50-155 Q		7907240066	50-156 Q
	7907180422	50-263 Q		7907240027	50-182 Q
				7907240035	50-186 Q
	7907180392	50-10 Q		7907310161	50-264 Q
	7907100526	50-266 Q			
	7907180422	50-263 Q		7907240025	50-294 Q
	7907180392	50-10 Q		7907240030	50-151 Q
	7907100526	50-266 Q		7907310311	50-10 Q
				7907310328	50-155 Q
	7907180392	50-10 Q		7907310311	50-10 Q
	7907100521	50-305 Q			
	7907180422	50-263 Q		7907310328	50-155 Q
	7907180390	50-315 Q		7907310342	50-263 Q
	7907180405	50-329 Q		7907310311	50-10 Q
				7907310354	50-266 Q
	7907180412	50-331 Q		7907310342	50-263 Q
	7907180410	50-341 Q			
	7907100523	50-346 Q		7907310311	50-10 Q
	7907180400	50-358 Q		7907310354	50-266 Q
	7907180420	50-367 Q		7907310355	50-305 Q
				7907310342	50-263 Q
	7907180392	50-10 Q			
	7907180408	50-409 Q		7907310305	50-315 Q
	7907180403	50-440 Q		7907310331	50-329 Q
	7907180392	50-10 Q		7907310335	50-331 Q
	7907180418	50-461 Q		7907310334	50-341 Q
				7907310348	50-346 Q
	7907100528	50-483 Q			
	7907180423	50-484 Q		7907310319	50-358 Q
	7907100528	50-483 Q		7907310340	50-367 Q
	7907100525	50-546 Q		7907310311	50-10 Q
	7907100522	50-580 Q		7907310332	50-409 Q
				7907310325	50-440 Q
	7907240064	50-373 Q		7907310311	50-10 Q
	7907130236	50-10 Q			
	7907130262	50-155 Q		7907310337	50-461 Q
	7907130236	50-10 Q		7907310349	50-483 Q
	7907130262	50-155 Q		7907310349	50-483 Q
	7907130282	50-263 Q		7907310345	50-546 Q
				7907310344	50-580 Q
	7907130236	50-10 Q		7907310403	50-10 Q
	7907130297	50-266 Q		7907310406	50-155 Q
	7907130282	50-263 Q		7907310403	50-10 Q
	7907130236	50-10 Q			
				7907310406	50-155 Q
	7907130297	50-266 Q		7907310414	50-263 Q
	7907130236	50-10 Q			
	7907130300	50-305 Q		7907310403	50-10 Q
	7907130282	50-263 Q		7907310419	50-266 Q
	7907130271	50-315 Q		7907310414	50-263 Q
	7907130260	50-329 Q		7907310403	50-10 Q
	7907130268	50-331 Q		7907310419	50-266 Q
	7907130267	50-341 Q		7907310403	50-10 Q
	7907130291	50-346 Q		7907310420	50-305 Q
	7907130258	50-358 Q		7907310414	50-263 Q
	7907130279	50-367 Q		7907310402	50-315 Q
	7907130236	50-10 Q		7907310407	50-329 Q
	7907130265	50-409 Q		7907310410	50-331 Q
	7907130259	50-440 Q		7907310409	50-341 Q
	7907130236	50-10 Q		7907310417	50-346 Q
	7907130270	50-461 Q		7907310405	50-358 Q
	7907130293	50-483 Q		7907310412	50-367 Q
	7907130281	50-484 Q		7907310403	50-10 Q
	7907130293	50-483 Q		7907310408	50-409 Q
	7907130289	50-546 Q		7907310404	50-440 Q
	7907130286	50-580 Q		7907310403	50-10 Q
	7907130230	50-10 Q		7907310411	50-461 Q
	7907240081	50-10 Q		7907310418	50-483 Q
	7907280343	DRG			
	7907240081	50-10 Q		7907310413	50-484 Q
				7907310418	50-483 Q
	7907240089	50-155 Q		7907310416	50-546 Q
	7907240081	50-10 Q		7907310415	50-580 Q
	7907240089	50-155 Q		7907260153	50-10 Q
	7907240104	50-263 Q		7907260336	50-10 Q
	7907240081	50-10 Q		7907260153	50-10 Q
				7907260336	50-10 Q
	7907240113	50-266 Q			
	7907240104	50-263 Q		7907260168	50-155 Q
	7907240081	50-10 Q		7907260354	50-153 Q
	7907240113	50-266 Q		7907260153	50-10 Q
	7907240081	50-10 Q		7907260336	50-10 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

478

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907260153	50-10 Q		7907250229	50-315 Q
	7907260336	50-10 Q		7907250227	50-329 Q
	7907260153	50-10 Q		7907250224	50-358 Q
	7907260336	50-10 Q		7907250217	50-10 Q
	7907260148	50-155 Q		7907250225	50-440 Q
	7907260354	50-155 Q		7907250217	50-10 Q
	7907260199	50-263 Q	Region 3, Chicago, Reactor Constructi on & Engineering Support Branch	7907050553*	50-304 Q
	7907260402	50-263 Q		7907050549	50-304 Q
	7907260153	50-10 Q		7907300041*	50-373 Q
	7907260336	50-10 Q		7907300046*	50-373 Q
	7907260220	50-266 Q		7907300041*	50-373 Q
	7907260422	50-266 Q		7907300046*	50-373 Q
	7907260199	50-263 Q		7907300038	50-373 Q
	7907260402	50-263 Q		7907180456	50-546 Q
	7907260153	50-10 Q		7907260524	50-301 Q
	7907260336	50-10 Q		7907300088	50-329 Q
	7907260220	50-266 Q		7907180429	50-451 Q
	7907260422	50-266 Q		7907050112	50-305 Q
	7907260153	50-10 Q		7907180307	50-155 Q
	7907260336	50-10 Q		7907180382*	50-282 Q
	7907260224	50-305 Q		7907250436	50-440 Q
	7907260425	50-305 Q		7907180357*	50-454 Q
	7907260199	50-263 Q		7907180369	50-282 Q
	7907260402	50-263 Q		7907180335*	50-315 Q
	7907260148	50-315 Q		7907180336	50-454 Q
	7907260398	50-315 Q		7907180325	50-315 Q
	7907260148	50-315 Q		7907240112*	50-301 Q
	7907260398	50-315 Q		7907250213*	50-483 Q
	7907260174	50-329 Q		7907250216*	50-483 Q
	7907260351	50-329 Q		7907240138*	50-237 Q
	7907260174	50-329 Q		7907240172*	50-546 Q
	7907260351	50-329 Q		7907250212	50-483 Q
	7907260184	50-331 Q		7907240134	50-237 Q
	7907260391	50-331 Q		7907110716	50-373 S
	7907260181	50-341 Q		7907250301*	50-373 Q
	7907260389	50-341 Q		7907110716	50-373 S
	7907260214	50-346 Q		7907250301*	50-373 Q
	7907260416	50-346 Q		7907130187	50-483 S
	7907260164	50-358 Q		7907300071*	50-255 Q
	7907260348	50-358 Q		7907270104	50-304 Q
	7907260194	50-367 Q		7907250290	50-373 Q
	7907260399	50-367 Q		7907300067	50-255 Q
	7907260153	50-10 Q		7907160264	50-454 Q
	7907260336	50-10 Q		7907260160	50-341 Q
	7907260153	50-10 Q		7907260999	50-461 Q
	7907260336	50-10 Q		7907310206*	50-315 Q
	7907260178	50-409 Q		7907180463	50-440 S
	7907260359	50-409 Q		7907310197	50-315 Q
	7907260167	50-440 Q		7907090098	50-341 S
	7907260349	50-440 Q		7907190086	50-341 Q
	7907260167	50-440 Q		7907300481	50-305 Q
	7907260349	50-440 Q		7907250077	50-440 Q
	7907260153	50-10 Q		7907260006	50-440 Q
	7907260336	50-10 Q		7907300077	50-373 Q
	7907260153	50-10 Q		7907100284	50-320 H
	7907260336	50-10 Q	Region 3, Chicago, Fuel Facility & Materials Safety Branch	7907190073*	50-10 Q
	7907260153	50-10 Q		7907100302	50-320 H
	7907260336	50-10 Q		7907100309	50-320 H
	7907260153	50-10 Q		7907190042	50-10 Q
	7907260189	50-461 Q		7907100315	50-320 H
	7907260394	50-461 Q		7907100325	50-320 H
	7907260189	50-461 Q		7907100347	50-320 H
	7907260394	50-461 Q		7907130310	50-341 Q
	7907260217	50-483 Q		7907110438*	70-925
	7907260418	50-483 Q		7907100589	50-320 H
	7907260201	50-484 Q		7907110434	70-925
	7907260407	50-484 Q		7907180500*	50-295 Q
	7907260217	50-483 Q		7907100335	50-320 H
	7907260418	50-483 Q		7907180492	50-295 Q
	7907260211	50-546 Q		7907100341	50-320 H
	7907260413	50-546 Q		7907180587*	50-295 Q
	7907260211	50-546 Q		7907100405	50-320 H
	7907260413	50-546 Q		7907180554	50-295 Q
	7907260206	50-580 Q		7907100441	50-320 H
7907260410	50-580 Q			7907250282*	50-409 Q
7907260206	50-580 Q			7907100445	50-320 H
7907260410	50-580 Q			7907190851	40-8616
7907250217	50-10 Q			7907190865*	40-8616
7907270293	ORQ			7907250209*	50-255 Q
7907250217	50-10 Q			7907250211*	50-255 Q
7907250228	50-155 Q			7907250270	50-409 Q
7907250217	50-10 Q			7907260281*	50-186 Q
7907250228	50-155 Q			7907250206	50-255 Q
7907250217	50-10 Q				

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

479

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Region 3, Chicago, Reactor Operations Nuclear Support Branch	7907260223	50-10 Q		7907110681*	50-445 Q
	7907300430*	50-305 Q		7907110693*	50-445 Q
	7907260182	50-329 Q		7907110681*	50-445 Q
	7907260272	50-186 Q		7907110693*	50-445 Q
	7907300419	50-305 Q		7907110747*	50-482 Q
	7907300191	50-266 Q		7907090394	QA999
	7907300403	50-305 Q		7907090439	50-313 Q
	7907300326	50-367 Q		7907110733*	50-482 Q
	7907250576	50-295 Q		7907110740*	50-482 Q
	7907110120	50-305 Q		7907100259	50-59 Q
	7907260290	50-155 Q		7907100263	50-72 Q
	7907270392	50-315 Q		7907100256	50-112 Q
	7907270399*	50-315 Q		7907100259	50-59 Q
	7907270392	50-315 Q		7907100245	50-131 Q
	7907270399*	50-315 Q		7907100271	50-148 Q
	7907180425*	50-331 Q		7907100273	50-188 Q
	7907180416	50-331 Q		7907100262	50-192 Q
	7907190492	50-10 Q		7907100268	50-252 Q
	7907180274	50-295 Q		7907100251	50-262 Q
	7907100355	50-320 H		7907100293	50-267 Q
	7907100365	50-320 H		7907100248	50-274 Q
	7907100382	50-320 H		7907100267	50-284 Q
	7907100390	50-320 H		7907100290	50-285 Q
	7907180411*	50-255 Q		7907100289	50-298 Q
	7907180394	50-255 Q		7907100283	50-313 Q
	7907100400	50-320 H		7907100263	50-72 Q
	7907240191*	50-409 Q		7907250488*	50-482 Q
	7907240630*	50-305 Q		7907240263*	QA999
	7907240152*	50-266 Q		7907060329	50-267 Q
	7907240106	50-301 Q		7907260129	50-267 P
	7907240152*	50-266 Q		7907060328	50-285 Q
	7907240187	50-409 Q		7907260126	50-285 P
	7907250076	50-266 Q		7907060327	50-298 Q
	7907240195	50-282 Q		7907260125	50-298 P
	7907250076	50-266 Q		7907060325	50-313 Q
	7907240195	50-282 Q		7907260122	50-313 P
	7907240623	50-305 Q		7907060325	50-313 Q
	7907240144	50-266 Q		7907100410	50-320 H
	7907240124	50-373 Q		7907260081*	QA999
	7907260252	50-409 Q		7907030128	50-285 Q
	7907300331	50-263 Q		7907030126	50-382 Q
	7907260822*	50-237 Q		7907030129	50-445 Q
	7907310222*	50-358 Q		7907030122	50-456 Q
	7907260810	50-237 Q		7907030124	50-482 Q
	7907260815*	50-237 Q		7907030123	50-498 Q
	7907260810	50-237 Q		7907190049*	50-298 Q
	7907260815*	50-237 Q		7907200363	50-267 Q
	7907310080	50-254 Q		7907200361	50-285 Q
	7907300083	50-315 Q		7907200360	50-298 Q
	7907310015	50-331 Q		7907200343	50-313 Q
	7907180296*	50-346 Q		7907200357	50-382 Q
	7907310180	50-116 Q		7907200365	50-445 Q
	7907300392	50-295 Q		7907200348	50-458 Q
	7907310213	50-358 Q		7907200356	50-482 Q
	7907180304	50-254 Q		7907200354	50-498 Q
	7907300017	50-331 Q		7907250347*	QA999
	7907300280	50-295 Q		7907270118*	50-267 Q
	7907240273	50-10 Q		7907300478*	50-298 Q
	7907300283*	50-263 Q		7907300484*	50-298 Q
	7907300274	50-263 Q		7907190408	50-267 Q
Region 3, Chicago, Safeguards Branch	7907050159	50-346 Q			
	7907240266	50-294 Q		7907110742	50-285 Q
	7907180263	50-346 Q		7907190407	50-285 Q
	7907250367*	QA999		7907190403	50-298 Q
	7907110069*	QA999		7907190390	50-313 Q
	7907110060	QA999		7907190400	50-382 Q
	7907250355*	QA999		7907190411	50-445 Q
	7907130135*	50-482 Q		7907260561*	50-445 Q
	7907130139*	50-482 Q		7907190393	50-458 Q
	7907130126	50-482 Q		7907190399	50-482 Q
Region 4, Dallas, Office of the Director	7907020117*	50-313 Q		7907190395	50-498 Q
	7907050140*	50-298 Q		7907060022	50-267 Q
	7907020153*	50-313 Q		7907060020	50-285 Q
	7907020078*	50-313 Q		7907060018	50-298 Q
	7906130217	70-1401		7907060010	50-313 Q
	7906130213	70-1406		7907060017	50-382 Q
	7906130219	70-2185		7907060023	50-445 Q
	7906130210	70-2560		7907060013	50-458 Q
	7907050146*	50-267 Q		7907060016	50-482 Q
	7907050187*	50-482 Q		7907060015	50-498 Q
	7907110606*	50-498 Q		7907180643	50-298 Q
	7907050179*	50-498 Q		7907180653*	50-298 Q
	7907050168*	50-267 Q		7907300055*	50-498 Q
	7907120003*	50-313 Q		7907050565	50-382 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907050566	50-445 Q		7907180249	50-458 Q
	7907050560	50-458 Q		7907180233	50-466 Q
	7907050561	50-466 Q		7907180237	50-482 Q
	7907050563	50-482 Q		7907180252	50-498 Q
	7907050562	50-498 Q		7907180269	50-556 Q
	7907050557	50-556 Q		7907180385	50-267 Q
	7907050574	50-382 S		7907180381	50-285 Q
	7907050575	50-445 S		7907180379	50-298 Q
	7907050570	50-458 S		7907180374	50-313 Q
	7907050573	50-481 S		7907100518	50-382 Q
	7907310603*	50-482 Q		7907100520	50-445 Q
	7907050572	50-498 S		7907100514	50-458 Q
	7907310574*	50-498 Q		7907100517	50-482 Q
	7907310552*	50-313 Q		7907100516	50-498 Q
	7907020446	50-267 Q		7907310217	50-267 Q
	7907020445	50-285 Q		7907310212	50-285 Q
	7907020444	50-298 Q		7907310210	50-298 Q
	7907020443	50-313 Q		7907310207	50-313 Q
	7907310537	50-313 Q		7907110296	50-382 Q
	7907020443	50-313 Q		7907110300	50-445 Q
	7907050514	50-382 Q		7907110289	50-458 Q
	7907050517	50-445 Q		7907110293	50-482 Q
	7907050506	50-458 Q		7907110292	50-498 Q
	7907050512	50-482 Q		7907270288	50-482 Q
	7907050509	50-498 Q		7907310615	50-131 Q
	7907120377	50-267 Q		7907310610	50-274 Q
	7907120375	50-285 Q		7907310623	50-298 Q
	7907120373	50-298 Q		7907310619	50-313 Q
	7907120370	50-313 Q		7907190506	50-267 Q
	7907050488	50-382 Q		7907190503	50-285 Q
	7907050489	50-445 Q		7907190502	50-298 Q
	7907050483	50-458 Q		7907190489	50-313 Q
	7907050487	50-482 Q		7907190500	50-382 Q
	7907050485	50-498 Q		7907190508	50-445 Q
	7907250328	QA999		7907190493	50-458 Q
	7907050418	40-8027		7907190498	50-482 Q
	7907020030	50-59 Q		7907190495	50-498 Q
	7907230507	50-59 Q		7907240485	50-267 Q
	7907020028	50-72 Q		7907240401	50-285 Q
	7907230514	50-72 Q		7907240316	50-298 Q
	7907020024	50-112 Q		7907240299	50-313 Q
	7907230510	50-112 Q		7907240312	50-382 Q
	7907020030	50-59 Q		7907240410	50-445 Q
	7907230507	50-59 Q		7907240302	50-458 Q
	7907020017	50-131 Q		7907240309	50-482 Q
	7907230437	50-131 Q		7907240305	50-498 Q
	7907020022	50-148 Q		7907260334	50-267 Q
	7907230508	50-148 Q		7907260332	50-285 Q
	7907020020	50-188 Q		7907260328	50-298 Q
	7907230506	50-188 Q		7907260325	50-313 Q
	7907020033	50-192 Q		7907260242	50-267 Q
	7907230512	50-192 Q		7907260239	50-285 Q
	7907020023	50-252 Q		7907260235	50-298 Q
	7907020026	50-262 Q		7907260231	50-313 Q
	7907020015	50-267 Q		7907270397	50-382 Q
	7907020018	50-274 Q		7907270398	50-445 Q
	7907230439	50-274 Q		7907270391	50-458 Q
	7907020035	50-284 Q		7907270395	50-482 Q
	7907230801	50-284 Q		7907270394	50-498 Q
	7907020014	50-285 Q		7907180226*	50-382 Q
	7907020013	50-313 Q		7907050184	50-482 Q
	7907020028	50-72 Q		7907110612*	50-498 Q
	7907230514	50-72 Q		7907110603	50-498 Q
	7907120586	50-267 Q		7907050174	50-498 Q
	7907120588	50-285 Q		7907110671	50-445 Q
	7907240258	50-298 Q		7907110414	50-382 Q
	7907120590	50-313 Q		7907110418*	50-382 Q
	7907120602	50-382 Q		7907110619	50-482 Q
	7907120604	50-445 Q		7907110628*	50-482 Q
	7907120596	50-458 Q		7907310119	50-466 Q
	7907120600	50-482 Q		7907310126*	50-466 Q
	7907120598	50-498 Q		7907110732	50-482 Q
	7907250360*	QA999		7907110670	50-382 Q
	7907100398	50-267 Q		7907110656	50-445 Q
	7907100399	50-285 Q		7907110682	50-482 Q
	7907100389	50-298 Q		7907250518*	50-445 Q
	7907100385	50-313 Q		7907030267	50-382 Q
	7907110252	50-382 Q		7907030262	50-445 Q
	7907110256	50-445 Q		7907030259	50-458 Q
	7907110242	50-458 Q		7907030266	50-482 Q
	7907110249	50-482 Q		7907030268	50-498 Q
	7907110246	50-498 Q		7907250498	50-445 Q
	7907120591	50-298 Q		7907260492*	50-498 Q
	7907180262	50-382 Q		7907250222*	50-482 Q
	7907180266	50-445 Q			

Region 4, Dallas, Reactor Construction  
& Engineering Support Branch



# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

481

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907250226*	50-482 Q		7907030226	50-267 S
	7907250479	50-482 Q		7907030224	50-285 S
	7907260477	50-498 Q		7907030223	50-298 S
	7907260485*	50-498 Q		7907030218	50-313 S
	7907260477	50-498 Q		7907130330	50-267 S
	7907260485*	50-498 Q		7907130327	50-285 S
	7907020307	50-382 S		7907130325	50-298 S
	7907020309	50-445 S		7907130307	50-313 S
	7907020303	50-458 S		7907240271	50-313 Q
	7907020306	50-482 S		7907180677	50-267 S
	7907020305	50-498 S		7907180674	50-285 S
	7907250221	50-482 Q		7907180671	50-298 S
	7907240051	50-382 Q		7907180669	50-313 S
	7907260559	50-445 Q		7907130206*	QA999
	7907230347	50-482 Q	Region 4, Dallas, Vendor Inspection Branch	7907130213*	QA999
	7907240047	50-498 Q		7907130199*	QA999
	7907300055	50-498 Q		7907130370*	QA999
	7907240047	50-498 Q		7907130372*	QA999
	7907300055	50-498 Q		7907130369*	QA999
	7907310598	50-482 Q		7907050104*	QA999
	7907310561	50-498 Q		7907050109*	QA999
	7907030212	50-382 S		7907050101*	QA999
	7907030215	50-445 S		7907090470	QA999
	7907030205	50-458 S		7907090474*	QA999
	7907030210	50-482 S		7907100733*	QA999
	7907030209	50-498 S		7907100730*	QA999
	7907300229	50-445 Q		7907250196*	QA999
	7907130340	50-382 S		7907250197*	QA999
	7907130341	50-445 S		7907250195*	QA999
	7907130334	50-458 S		7907030303*	QA999
	7907130337	50-482 S		7907260147*	QA999
	7907130336	50-498 S		7907260158*	QA999
	7907270294	50-445 Q		7907030039*	QA999
	7907180689	50-382 S		7907090466*	QA999
	7907180690	50-445 S		7907030019	QA999
	7907180683	50-458 S		7907030026*	QA999
	7907180688	50-482 S		7907030029	QA999
	7907180685	50-498 S		7907030036	QA999
	7907240519	50-382 S		7907060041	QA999
	7907240521	50-445 S			
	7907240514	50-458 S		7907060046*	QA999
	7907240518	50-482 S			
	7907240517	50-498 S		7907090474*	QA999
Region 4, Dallas, Fuel Facility & Materials Safety Branch	7906140594*	40-8006		7907130349*	QA999
				7907260144*	QA999
	7906140597*	40-8006			
	7906140584	40-8006		7907050530	QA999
	7907090446*	50-313 Q		7907050536*	QA999
	7907190049*	50-298 Q		7907090462	QA999
	7907250190	QA999		7907130335	QA999
				7907250102*	QA999
	7907310574*	50-498 Q		7907250098	QA999
	7907310552*	50-313 Q		7907230061*	QA999
Region 4, Dallas, Reactor Operations Nuclear Support Branch	7907160062	50-313 Q		7907230067*	QA999
	7907160017*	50-313 Q		7907230074*	QA999
	7907050138	50-298 Q		7907190742*	QA999
	7907200220*	50-192 Q		7907190732	QA999
	7907050142	50-267 Q		7907230302*	QA999
	7907200213	50-192 Q		7907230308*	QA999
	7907050165	50-267 Q		7907230297*	QA999
	7907120001	50-313 Q		7907250154*	QA999
	7907120007*	50-313 Q			
	7907120001	50-313 Q		7907130292	71-6698
	7907120007*	50-313 Q		7907130186	QA999
	7907050191	50-298 Q		7907240264*	QA999
	7907050195*	50-298 Q		7907240265*	QA999
				7907250149	QA999
	7907020204	50-285 Q		7907050084	QA999
	7907090379	50-298 Q		7907090381	QA999
	7907030254	50-267 S		7907100721	QA999
	7907030258	50-285 S		7907130221	QA999
	7907030252	50-298 S		7907230736*	QA999
	7907190038	50-298 Q			
	7907030256	50-313 S		7907230730	QA999
	7907020301	50-267 S		7907090397	QA999
	7907270110	50-267 Q		7907260090*	QA999
	7907020298	50-285 S		7907260045*	QA999
				7907260130*	QA999
	7907020299	50-298 S			
	7907020297	50-313 S		7907230348	QA999
	7907300103	50-267 Q		7907250558	QA999
	7907300472	50-298 Q		7907230055	QA999
	7907180653*	50-298 Q		7907230286	QA999
	7907030183	50-267 S		7907260100	QA999
	7907030181	50-285 S			
	7907030177	50-298 S		7907240261	QA999
	7907030175	50-313 S			
				7907250363	QA999
				7907260010	QA999

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

482

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Region 5, San Francisco, Office of the Director	7907120406*	50-460 G		7907020267	50-361 Q
				7907030195	50-206 S
	7904130344	50-133 G		7907180738	50-361 S
				7907190101	50-361 Q
	7904160043	50-133 Q		7907020271	50-397 Q
	7907160067	50-312 Q		7907030200	50-397 S
	7907020123*	50-312 Q		7907180541	50-397 S
	7907030092*	50-397 Q		7907020271	50-397 Q
	7907030094*	50-397 Q		7907030200	50-397 S
	7907030091*	50-397 Q		7907020271	50-397 Q
	7907020157*	50-312 Q		7907030200	50-397 S
	7907020080*	50-312 Q		7907020271	50-397 Q
	7908020227	50-133 S		7907030200	50-397 S
	7907030392*	50-397 Q		7907020271	50-397 Q
	7908020256	50-133 S		7907030200	50-397 S
	7907110725*	50-361 Q		7907020262	50-528 Q
	7907110712*	50-361 Q		7907030186	50-528 S
	7907110634*	50-397 Q		7907020262	50-528 Q
	7907270141*	50-275 Q		7907030186	50-528 S
	7907190484*	50-224 Q		7907020262	50-528 Q
	7907300135*	50-344 Q		7907030186	50-528 S
	7907260649*	50-361 Q		7907030191	50-133 S
	7907300101*	50-508 Q		7907120365	50-206 Q
	7907260549*	50-275 Q		7907030244	50-397 S
	7907260557*	50-397 Q		7907030232	50-133 S
	7906200092	50-133 Q		7907030238	50-206 S
	7907200379	50-397 Q		7907030232	50-133 S
	7907200372	50-206 Q		7907030242	50-312 S
	7907200370	50-344 Q		7907030232	50-133 S
	7907200374	50-361 Q		7907030235	50-344 S
	7907260978*	50-361 Q		7907030238	50-206 S
	7907200374	50-361 Q		7907030244	50-397 S
	7907260978*	50-361 Q		7907030229	50-528 S
	7907030073	50-397 Q		7907020453	50-397 Q
	7907200379	50-397 Q		7907020448	50-133 Q
	7907120471*	50-460 Q			
	7907200379	50-397 Q		7907020450	50-206 Q
	7907120471*	50-460 Q		7907020448	50-133 Q
				7907020451	50-312 Q
	7907200379	50-397 Q		7907020448	50-133 Q
	7907200367	50-528 Q		7907020449	50-344 Q
	7907260534*	50-206 Q		7907020450	50-206 Q
	7907270015*	50-206 Q		7907020453	50-397 Q
	7907020291	50-397 S		7907020447	50-528 Q
				7907120017	50-397 Q
	7907020282	50-133 S			
	7907020287	50-206 S		7907120008	50-133 Q
	7907020282	50-133 S		7907120012	50-206 Q
	7907020288	50-312 S		7907120006	50-275 Q
	7907100546	50-320 H		7907120015	50-312 Q
				7907120006	50-275 Q
	7907020282	50-133 S			
	7907020284	50-344 S		7907120010	50-344 Q
	7907020287	50-206 S		7907120014	50-361 Q
	7907020291	50-397 S		7907120017	50-397 Q
	7907020280	50-528 S		7907120009	50-528 Q
				7907230602	50-27 Q
	7907190436	50-397 Q			
	7907190417	50-133 Q		7907230542	50-70 Q
	7907190426	50-206 Q		7907230536	50-89 Q
	7907190423	50-275 Q		7907230547	50-94 Q
	7907190431	50-312 Q		7907230568	50-113 Q
				7907110200	50-133 Q
	7907190423	50-275 Q			
	7907190425	50-344 Q		7907230601	50-139 Q
	7907190428	50-361 Q		7907230594	50-142 Q
	7907190436	50-397 Q		7907230562	50-106 Q
	7907190416	50-528 Q		7907230536	50-89 Q
				7907230544	50-187 Q
	7907060036	50-397 Q			
	7907060029	50-133 Q		7907110205	50-206 Q
	7907060032	50-206 Q		7907230584	50-224 Q
	7907060029	50-133 Q		7907230527	50-228 Q
	7907060034	50-312 Q		7907230562	50-106 Q
				7907230564	50-288 Q
	7907060029	50-133 Q			
	7907060030	50-344 Q		7907110208	50-312 Q
	7907060032	50-206 Q		7907230590	50-326 Q
	7907060036	50-397 Q		7907110201	50-344 Q
	7907060027	50-528 Q		7907230520	50-360 Q
				7907230561	50-394 Q
	7907020271	50-397 Q			
	7907030200	50-397 S		7907230547	50-94 Q
	7907030195	50-206 S			
	7907020265	50-275 Q		7907230599	50-433 Q
	7907030198	50-312 S		7907100453	70-25
				7907100454	70-734
	7907020265	50-275 Q		7907100457	70-754
	7907030193	50-344 S			
	7907020267	50-361 Q		7907100450	70-984
	7907030195	50-206 S		7907100457	70-754
	7907180738	50-361 S		7907100460	70-1257
				7907120630	50-397 Q
	7907190101	50-361 Q		7907120617	50-133 Q

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

48

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907120624	50-206 Q		7907130383	50-528 S
	7907120621	50-275 Q		7907230774	50-27 Q
	7907120627	50-312 Q		7907230749	50-70 Q
	7907120621	50-275 Q		7907230747	50-89 Q
	7907120622	50-344 Q		7907230754	50-94 Q
				7907230759	50-106 Q
	7907120625	50-361 Q		7907230761	50-113 Q
	7907120630	50-397 Q			
	7907120615	50-528 Q		7907230777	50-133 Q
	7907050543	50-397 S		7907230772	50-139 Q
	7907060226	50-397 Q		7907230766	50-142 Q
				7907230747	50-89 Q
	7907050531	50-133 S		7907230783	50-187 Q
	7907060216	50-133 Q			
	7907050538	50-206 S		7907230781	50-204 Q
	7907060219	50-206 Q		7907230764	50-224 Q
	7907050531	50-133 S		7907230745	50-228 Q
				7907230759	50-106 Q
	7907060216	50-133 Q		7907230760	50-288 Q
	7907050541	50-312 S			
	7907060224	50-312 Q		7907230783	50-312 Q
	7907050531	50-133 S		7907230765	50-326 Q
	7907060216	50-133 Q		7907300462	50-344 Q
				7907230744	50-360 Q
	7907050533	50-344 S			
	7907060218	50-344 Q		7907230754	50-94 Q
	7907050538	50-206 S		7907310166	50-394 Q
	7907060219	50-206 Q		7907230769	50-433 Q
	7907050538	50-206 S		7907180711	50-397 Q
				7907270377	50-133 Q
	7907060219	50-206 Q		7907180706	50-206 Q
	7907050543	50-397 S			
	7907060224	50-397 Q		7907180700	50-275 Q
				7907180708	50-312 Q
				7907180700	50-275 Q
	7907050543	50-397 S		7907180703	50-344 Q
	7907060226	50-397 Q		7907180704	50-361 Q
	7907050543	50-397 S		7907180711	50-397 Q
	7907060226	50-397 Q		7907180699	50-528 Q
	7907050543	50-397 S		7907310396	50-133 Q
				7907310399	50-206 Q
	7907060226	50-397 Q			
	7907050528	50-528 S		7907310396	50-133 Q
	7907060213	50-528 Q		7907310400	50-312 Q
	7907050528	50-528 S		7907310396	50-133 Q
	7907060213	50-528 Q		7907310397	50-344 Q
				7907310399	50-206 Q
	7907050528	50-528 S			
	7907060213	50-528 Q		7907310401	50-397 Q
	7907050497	50-397 Q		7907310395	50-528 Q
	7907050492	50-275 Q		7907260286	50-397 Q
	7907050495	50-361 Q		7907260270	50-133 Q
				7907260277	50-206 Q
	7907050497	50-397 Q			
	7907050491	50-528 Q		7907260270	50-133 Q
	7907100534	50-397 Q		7907260278	50-312 Q
	7907100529	50-133 Q		7907260270	50-133 Q
	7907100531	50-206 Q		7907260274	50-344 Q
				7907260277	50-206 Q
	7907100529	50-133 Q			
	7907100532	50-312 Q		7907240315	50-397 S
	7907100529	50-133 Q		7907260286	50-397 Q
	7907100530	50-344 Q		7907260267	50-528 Q
	7907100531	50-206 Q		7907120396	50-460 Q
	7907100534	50-397 Q		7907120419*	50-460 Q
	7907110019	50-528 Q			
	7907100651	50-361 S		7907120396	50-460 Q
	7907100673	50-361 S		7907120419*	50-460 Q
	7907100651	50-361 S		7907030094*	50-397 Q
				7907050392*	50-397 Q
	7907100673	50-361 S		7907110725*	50-361 Q
	7907130222	50-397 Q			
	7907130203	50-133 Q		7907050388	50-397 Q
	7907130212	50-206 Q		7907110705	50-361 Q
	7907130205	50-275 Q		7907110634*	50-397 Q
				7907110626	50-397 Q
	7907130218	50-312 Q			
	7907130205	50-275 Q		7907300256*	50-445 Q
	7907130208	50-344 Q			
	7907100592	50-361 S		7907300242	50-445 Q
	7907130216	50-361 Q		7907300250*	50-445 Q
				7907300242	50-445 Q
	7907100592	50-361 S		7907300250*	50-445 Q
	7907130216	50-361 Q		7907260518	50-361 Q
	7907130222	50-397 Q		7907260649*	50-361 Q
	7907130198	50-528 Q		7907260818	50-361 Q
	7907130390	50-397 S		7907260649*	50-361 Q
				7907300098	50-508 Q
	7907130384	50-133 S			
	7907130387	50-206 S		7907300107*	50-508 Q
	7907130384	50-133 S		7907300098	50-508 Q
	7907130384	50-133 S		7907300107*	50-508 Q
	7907130389	50-312 S		7907260554	50-397 Q
	7907130384	50-133 S		7907260557*	50-397 Q
	7907130386	50-344 S			
	7907130387	50-206 S		7907260978*	50-361 Q
	7907130390	50-397 S		7907260965	50-361 Q

Region 5, San Francisco, Reactor  
Construction & Engineering Support Branch

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907300442	50-361 Q		7907120118	70-992
	7907300451*	50-361 Q		7907100717*	70-2838
	7907300442	50-361 Q		7907060512	40-8584
	7907300451*	50-361 Q		7907230738	70-143
	7907270296	50-508 Q		7907020466	70-1100
	7907270306*	50-508 Q		7907110183	40-2061
	7907270296	50-508 Q		7907110237	70-364
	7907270306*	50-508 Q		7907110272*	70-364
	7907300110*	50-508 Q		7907230725	70-36
Region 5, San Francisco, Fuel Facility & Materials Safety Branch	7907300260*	70-25	Fuel Reprocess & Recycle Branch	7907230718	70-1113
	7907300245	70-25		7907050072	70-364
	7907260543	50-275 Q		7907050042	70-1193
	7907260549*	50-275 Q		7907050068	70-1143
	7907180261*	70-754		7907190670	70-1308
	7907260528	50-206 Q		7907110232	70-364
	7907260534*	50-206 Q		7907110238	50-201 P
Region 5, San Francisco, Reactor Operations Nuclear Support Branch	7907180243	70-754		7907130079	50-201 P
	7907110092*	50-133 Q		7907110224	70-364
	7907130171	50-70 Q		7907090121	70-364
	7907130179*	50-70 Q		7907090123*	70-364
	7907110078	50-133 Q	Licensing Management Branch	7907180894	70-1257
	7907270141*	50-275 Q		7907050074*	70-364
	7907270140	50-275 Q		7907090093	70-754
	7907300119	50-344 Q	Radioisotopes Licensing Branch (Pre 790501)	7907100692	70-2838
	7907300125*	50-344 Q	Transportation Branch	7907240308*	71-110
	7907300135*	50-344 Q		7907030166*	71-215
	7907190478	50-224 Q		7907260364*	71-205
	7907270270	50-344 Q		7907260366*	71-74
	7907270276*	50-344 Q		7907260428*	71-154
	7907270009	50-206 Q		7907090432*	50-263 P
	7907270015*	50-206 Q		7907260386*	71-156
	7907270290*	50-397 Q		7907090422*	50-263 P
	7907270268	50-275 Q		7907260355*	71-39
	7907270280*	50-275 Q		7907110709	71-99
	7907270287	50-397 Q		7907060021	71-9070
	7907300404	50-312 Q		7907050227	71-6244
	7907300450*	50-312 P		7907050232*	71-6244
	7907300219	50-344 Q		7907060113	71-5
	7907300233*	50-344 Q		7907100613	71-5450
Region 5, San Francisco, Safeguards Branch	7907120094	50-224 Q		7907090031	71-6104
	7907190145	50-243 Q		7907100608	71-6400
	7907190138	50-312 Q		7907110621	71-5026
	7907270385	50-267 Q		7907100634	71-6375
	7907250220	50-206 Q		7907110621	71-5026
	7907180273	70-734		7907100641	71-6642
	7907180282	70-1257		7907100621	71-9010
	7907120740	50-289 Q		7907100619	71-9074
Office of I&E, Executive Officer for Management & Analysis	7907120746	50-320 Q		7907100623	71-9081
	7907130328	50-320 S		7907130080	71-9
Office of I & E Executive Officer for Operations Support	7907130342	50-320 H		7907160228	71-54
	7907060165*	70-1193		7907130083	71-67
Office of Nuclear Material Safety & Safeguards	7907090038	SECV		7907110419	71-96
	7907090080	SECV		7907060070	71-325
	7907090091	SECV		7907060071*	71-325
	7907090106*	SECV		7907110145	71-327
	7905020344	DRQ		7907110151*	71-327
	7907120466*	SECV		7907060067	71-328
	7907120422	SECV		7907060068*	71-328
	7907120016	27-47		7907190024	71-5026
	7907120022*	27-47		7907110054	71-6275
	7907090008	50-201 U		7907180717	71-6601
Division of Fuel Cycle & Material Safety	7907110622	NUREG		7907110288	71-116
	7907160351*	COMMISSION		7907110476	71-189
	7907310526*	50-361 Q		7907110472	71-198
	7907050493*	70-2443		7907110410	71-248
	7907050490	70-2443		7907110444	71-264
	7907050493*	70-1207		7907110469	71-40
	7907120195	70-143		7907130063	71-46
	7907100726	70-2219		7907020488	71-102
Fuel Process. & Fab Branch	7907110611	70-371		7907250333	71-5149
	7907110605	70-1151		7907120099	71-5395
	7907060039	70-33		7907120267	71-5455
	7907160227	70-27		7907250333	71-5149
	7907090365	70-1113		7907190037	71-3754
	7907100705	70-27		7907110304	71-5768
	7907100735	70-1113		7907120092	71-5901
				7907250333	71-5149
				7907250305	71-5977
				7907090457	71-5980
				7907110304	71-5768
				7907060507	71-6144
				7907250333	71-5149
				7907090447	71-6280
				7907100663	71-6291

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

48

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907100668	71-6291		7907260469*	71-89
	7907250333	71-5149		7907240475	71-5768
	7907090436	71-6574		7907240407	71-5901
	7907090457	71-8980		7907250280	71-5910
	7907090454	71-9001		7907240385	71-5977
	7907100665	71-9005		7907240394	71-5980
	7907120128	71-9017		7907240494	71-6280
	7907300345	71-9018		7907240501	71-6357
	7907310176	71-9018		7907310142	71-6574
	7907310169	71-9019		7907240390	71-6697
	7907310176	71-9018		7907240485	71-9001
	7907110304	71-5768		7907240439	71-9017
	7907230622	71-11		7907240458	71-9022
	7907230630*	71-11		7907310162	71-9033
	7907230214	71-28		7907230244	71-5908
	7907230228*	71-28		7907260539	71-6144
	7907230655	71-32		7907230115	71-284
	7907230658*	71-32		7907230120*	71-284
	7907230634	71-34		7907300314	71-292
	7907230639*	71-34		7907300317*	71-292
	7907180457	71-37		7907230104	71-294
	7907180459*	71-37		7907230111*	71-294
	7907230293	71-59		7907230156	71-298
	7907230278	71-47		7907230159*	71-298
	7907230283*	71-47		7907190601	71-304
	7907230258	71-51		7907190604*	71-304
	7907230267*	71-51		7907230279	71-305
	7907230662	71-55		7907230281*	71-305
	7907230666*	71-55		7907190610	71-306
	7907230673	71-57		7907190613*	71-306
	7907230680*	71-57		7907230269	71-307
	7907230300*	71-59		7907230272*	71-307
	7907240584	71-75		7907230262	71-314
	7907240590*	71-75		7907230266*	71-314
	7907240595	71-76		7907230096	71-319
	7907240601*	71-76		7907230099*	71-319
	7907240247	71-77		7907230126	71-320
	7907240256*	71-77		7907230130*	71-320
	7907230007	71-80		7907230326	71-322
	7907230009*	71-80		7907230331*	71-322
	7907190279	71-93		7907230309	71-326
	7907190286*	71-93		7907230319*	71-326
	7907230787	71-103		7907230238	71-5942
	7907230792*	71-103		7907240313	71-6581
	7907230786	71-104		7907260454*	71-133
	7907230789*	71-104		7907240522*	71-148
	7907230776	71-105		7907260373*	71-157
	7907230782*	71-105		7907240037*	71-226
	7907240499	71-110		7907240236*	71-153
	7907230037	71-113		7907240009	71-15
	7907230049*	71-113		7907240014*	71-15
	7907240537	71-119		7907250027	71-22
	7907240845*	71-119		7907250029*	71-22
	7907230028	71-120		7907260350	71-39
	7907230033*	71-120		7907260341	71-74
	7907230054	71-123		7907260465	71-89
	7907230069*	71-123		7907260446	71-133
	7907240107	71-127		7907250423	71-137
	7907240110*	71-127		7907250426*	71-137
	7907240577	71-130		7907240531*	71-140
	7907240580*	71-130		7907260432	71-151
	7907240553	71-132		7907260439*	71-151
	7907240561*	71-132		7907260401	71-152
	7907240566	71-134		7907260411*	71-152
	7907240571*	71-134		7907240228	71-153
	7907240524	71-140		7907260421	71-154
	7907230237	71-145		7907260379	71-156
	7907230248*	71-145		7907260370	71-157
	7907240513	71-148		7907230019	71-161
	7907230645	71-150		7907250023*	71-161
	7907230653*	71-150		7907230692	71-162
	7907180448	71-61		7907230698*	71-162
	7907180452*	71-61		7907240042	71-166
	7907180453	71-87		7907240044*	71-166
	7907180454*	71-87		7907240046	71-168
	7907180743	71-102		7907240049*	71-168
	7907180841	71-5942		7907240038	71-184
	7907180848*	71-5942		7907240040*	71-184
	7907250244	71-3		7907260361	71-205
	7907250246*	71-3		7907230019	71-216
	7907230251	71-4949		7907230025*	71-216
	7907230255*	71-4949		7907230030	71-217
	7907260574	71-5341		7907230036*	71-217
	7907260527	71-6078		7907240018	71-218
	7907260575	71-6172		7907240023*	71-218

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907240028	71-219		7907020509*	40-8602
	7907240034*	71-219		7907110245	40-4492
	7907230042	71-225		7907100710	40-8584
	7907230047*	71-225			
	7907240032	71-226		7907020470	40-6659
	7907250377	71-281		7907020468	40-1162
	7907250400*	71-281		7907110178	40-8585
	7907250386	71-310		7907110175	40-8722
	7907250393*	71-310		7907100706	40-8102
	7907180701	71-361		7907110188	40-8663
	7907180821	71-4986		7907230082	40-8102
	7907200239	71-4986			
	7907180837	71-5364		7907230785	40-8102
	7907180795	71-3450		7907230770	40-8452
				7907230101	40-8721
	7907180918	71-6144		7907120089	40-8722
	7907180865	71-6357		7907120105*	40-8722
	7907180847	71-6601			
	7907240301	71-9010			
	7907240307	71-9010	Office of Nuclear Reactor Regulation	7907110365	50-320 A
				7907240404	SECY
	7907180783	71-9033		7812290071	NUREG
	7907180832	71-9044		7907240393	SECY
	7907180855	71-9070		7907130536*	50-346 Q
	7907180808	71-9081			
	7907180917	71-9081		7907090020	NUREG
				7907090021	NUREG
	7907180702	71-9108		7907090023	NUREG
	7907190002	71-9113		7907090025	NUREG
	7907260337	71-210		7907090027	NUREG
	7907250459	71-334			
	7907250463*	71-334		7907090029	NUREG
				7907090033	NUREG
	7907230595	71-31		7907090034	NUREG
	7907230591	71-79		7907090037	NUREG
	7907250359	71-136		7907090039	NUREG
	7907250368	71-163			
	7907250374	71-177			
	7907230614	71-228		7907090042	NUREG
	7907230469	71-236		7907090044	NUREG
	7907230476	71-246		7907090048	NUREG
	7907230613	71-251		7907090080	NUREG
	7907230616	71-252		7907090082	NUREG
	7907230587	71-262		7907090085	NUREG
	7907230583	71-263		7907090087	NUREG
	7907230604	71-265		7907090089	NUREG
	7907230606	71-308		7907090064	NUREG
	7907230620	71-316		7907090067	NUREG
	7907230610	71-318		7907090069	NUREG
	7907230609	71-321		7907090070	NUREG
High Level & Transuranic Waste Branch (Pre 790501)	7907060208	WASTE MGT		7907090074	NUREG
Low Level Waste Branch (Pre 790501)	7907160344*	COMMISSION		7907090075	NUREG
	7907250367*	FOIA		7907090078	NUREG
Division of Safeguards	7907110572*	50-237 Q		7907090079	NUREG
	7907160122*	70-143		7907090082	NUREG
	7907050464	70-33		7907090086	NUREG
	7907110427	70-135		7907090087	NUREG
Material Control Licensing Branch	7907060209	70-143		7907090090	NUREG
	7907060206	70-371		7907090092	NUREG
	7907180228	70-371		7907090096	NUREG
	7907060206	70-371		7907090100	NUREG
	7907060199	70-1151		7907090104	NUREG
	7907110431	70-27		7907090107	NUREG
	7907100696	70-1113		7907090109	NUREG
	7907090231	70-1151		7907090111	NUREG
Material Control & Accountability Development Branch	7907190156	70-371		7907090112	NUREG
				7907090114	NUREG
	7907230597	70-734		7907090116	NUREG
Physical Security Licensing Branch	7907050091	70-143			
	7907060042	70-2623		7907090117	NUREG
	7907060193	70-27		7907090119	NUREG
	7907100661	70-754		7907090120	NUREG
	7907110893	70-135		7907090122	NUREG
	7907110600	70-734		7907090125	NUREG
	7907090134	70-754		7907090127	NUREG
High Level Waste Licensing Management Branch	7907190805	WASTE MGT		7907090128	NUREG
				7907090131	NUREG
				7907090132	NUREG
				7907090135	NUREG
Low Level Waste Licensing Branch	7907190293	WASTE MGT			
	7907240491*	27-39		7907090136	NUREG
	7907120031*	27-47		7907090142	NUREG
				7907090143	NUREG
	7907040386	27-39		7907090145	NUREG
	7907230743	27-39		7907090147	NUREG
	7907240472	27-39			
	7907230605	27-48		7907090148	NUREG
Plutonium Recovery Licensing Branch	7907110275	40-299		7907090149	NUREG
				7907090150	NUREG
				7907090151	NUREG
	7907110253	40-3453		7907090152	NUREG
	7907110264*	40-3453			
	7907130524	40-3453			
	7907060074	40-8452		7907090154	NUREG
	7907020508	40-8602		7907090155	NUREG
				7907090156	NUREG

## 4E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907090159	NUREQ		7907090431	50-269 Q
	7907090160	NUREQ		7907090440*	50-269 Q
	7907090163	NUREQ		7907020498	50-309 H
	7907090165	NUREQ		7907020504	50-309 H
	7907090167	NUREQ		7907050124	50-309 H
	7907090170	NUREQ		7907050542	50-280 H
	7907090172	NUREQ		7907060159*	50-309 Q
	7907090175	NUREQ		7907060163*	50-309 Q
	7907090176	NUREQ		7907060293	50-280 H
	7907090178	NUREQ		7907050542	50-280 H
	7907090179	NUREQ		7907060293	50-280 H
	7907090180	NUREQ		7907130465	50-346 P
	7907090185	NUREQ		7907100678	50-443 Q
	7907090187	NUREQ			
	7907090191	NUREQ		7907100689*	50-443 Q
	7907090193	NUREQ		7907130148	50-443 Q
	7907090194	NUREQ		7907190173	50-443 Q
	7907090197	NUREQ		7907100678	50-443 Q
	7907090199	NUREQ		7907100689*	50-443 Q
	7907090201	NUREQ			
	7907090203	NUREQ		7907130148	50-443 Q
	7907090204	NUREQ		7907190173	50-443 Q
	7907090205	NUREQ		7907130465	50-346 P
	7907090207	NUREQ		7907130418*	50-260 P
	7907090208	NUREQ		7907130277	50-320 H
	7907090209	NUREQ		7907060145*	50-336 P
	7907090210	NUREQ		7907090450	50-313 P
				7907100027*	50-223 P
	7907090211	NUREQ		7907110553*	50-219 P
	7907090212	NUREQ		7907130146*	50-219 P
	7907090270	NUREQ			
	7907180072	50-320 P		7907180160*	50-219 Q
	7907260493	50-320 H		7907100277	50-320 P
	7907160232	50-320 P		7907100288*	50-320 P
	7904270288	50-320 P		7907100292*	50-320 P
	7907110306	50-320 P		7907100277	50-320 P
	7907120180	50-320 P			
	7907020182	50-320 P		7907100288*	50-320 P
				7907050190	50-346 H
	7904270421	50-320 P		7907090016	NUREQ
	7907100024	50-320 P		7907190096	50-313 P
	7907100038	50-320 P			
	7905070092	50-320 P		7907180680	50-327 A
	7907100031	50-320 P		7907130002	50-352 Q
				7907120188*	50-245 P
	7905240076	WASTE NOT		7907060513	50-346 Q
	7907100714*	50-443 Q		7907110017	50-346 P
	7907100281	50-320 P			
	7907120408	50-280 P		7907110025*	50-346 P
	7907060343	50-280 H		7907110030	50-346 Q
				7907230464	50-346 P
	7907050028*	50-263 P		7907110194	50-320 Q
	7907250037	50-272 H		7907180150	FOIA
	7907260641	50-320 S			
	7907240440*	50-471 D		7907190075	50-309 H
	7907020312	50-287 P		7907180889*	50-346 P
				7907130014*	50-352 Q
	7907020316*	50-287 P		7907130020*	50-352 Q
	7907060179	50-3 P		7907190229	50-352 H
	7907020312	50-269 P			
	7907020316*	50-269 P		7907130014*	50-352 Q
	7907310235	50-269 P		7907130020*	50-352 Q
				7907190229	50-352 H
	7907020312	50-269 P		7907190208	50-437 Q
	7907020316*	50-269 P		7907110685	50-309 H
	7907310235	50-269 P			
	7907060179	50-3 P		7907190020	50-309 H
	7907020312	50-269 P		7907110697	50-320 H
				7907130323*	50-334 P
	7907020316*	50-269 P		7907190620*	50-247 P
	7907310235	50-269 P		7907130243	50-320 P
	7907180693*	50-317 P			
	7907060179	50-3 P		7907120513	50-280 Q
	7907030173	SECY		7907120532*	50-280 Q
				7907120513	50-280 Q
				7907120532*	50-280 Q
	7907090460	50-280 H		7907180906	50-309 H
	7907180221*	50-3 Q			
	7907120284	50-280 Q		7907190025	50-309 H
	7907190048	50-309 H		7907190760	50-309 H
	7907120284	50-280 Q		7907190656*	50-348 P
				7907110307	50-416 H
	7907190048	50-309 H		7907110320*	50-416 H
	7907120284	50-280 Q			
	7907190048	50-309 H		7907110307	50-416 M
	7907160320	50-320 H		7907110320*	50-416 M
	7907050542	50-280 H		7907190167*	50-237 F
				7907310039*	50-339 A
	7907060293	50-280 H		7907260096*	50-317 P
	7907130465	50-346 P			
	7907090431	50-269 Q		7907300573	50-269 P
	7907090440*	50-269 Q		7907130464	50-280 Q
	7907090431	50-269 Q		7907250118*	50-331 P
				7907270198*	50-295 P
	7907090440*	50-269 Q		7907300539	50-409 Q
	7907090440*	50-269 Q			
	7907050542	50-280 H		7907300543*	50-409 Q
	7907060293	50-280 H		7907020514	50-313 Q
	7907050542	50-280 H			
	7907060293	50-280 H			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907240101*	50-336 P		7907240433	50-70 P
	7907180787	50-338 Q		7907190350	40-8584
	7907240370	50-331 Q		7907190046*	50-329 A
	7907300426	50-312 P	Hydrology Meteorology Branch	7907090003*	50-322 Q
	7907300435*	50-312 P		7907190004	50-293 P
	7907300463*	50-302 P	Assistant Director for Environmental Technology	7907260497	50-320 H
	7907190291	50-320 P	Cost Benefit Analysis Branch	7907190494	50-471 Q
	7907300454	50-302 P			
	7907300414	50-312 H	Environmental Specialists Branch	7907020439	50-320 P
	7907300583*	50-312 H		7907090463	50-320 P
	7907270364*	50-331 P	Division of Operating Reactors	7907090477	50-320 Q
	7907300460*	50-302 P		7907060477	50-334 P
	7907300406*	50-346 Q		7907270023*	50-261 Q
	7907300431*	50-346 Q		7907060270	50-334 P
Antitrust & Indemnity Group	7907230213*	50-295 Q		7907230208*	50-295 Q
	7907120074	50-280 J		7907230226*	50-295 Q
Program Support Branch	7907310280*	50-361 A		7907230239*	50-295 Q
	7904270414	50-320 P		7907230345*	50-295 Q
Technical & Administrative Support Branch	7905020115	50-320 P		7907230356*	50-295 Q
	7905030130	50-320 P		7907230208*	50-295 Q
	7907190256	50-320 H		7907230226*	50-295 Q
Division of Site Safety & Environmental Analysis	7907160099	50-320 P		7907230239*	50-295 Q
	7907120729	50-320 T		7907230345*	50-295 Q
	7907120203	50-320 H		7907230356*	50-295 Q
	7907120261*	50-322 A		7907060242	50-219 P
	7907240446*	50-471 D		7907060243*	50-219 P
	7907130022*	50-327 A		7907090024	50-219 T
	7907020420	50-320 P		7907100015*	50-219 P
	7907130190	50-320 P		7907100017*	50-219 P
Accident Analysis Branch	7907090326	50-592 D		7907180143*	50-219 Q
	7907050145	NUREG		7907110121*	50-269 P
	7907120185	50-320 H		7907110684	50-320 P
	7907100051	50-320 P		7907190035*	REVIEW ORP
	7907260120	50-369 A		7907270016*	50-261 Q
Effluent Treatment Systems Branch	7907060426*	50-219 P		7907300121	50-344 P
Assistant Director for Environmental Projects	7901110268	50-437 D		7907300232	TOPREP
Environmental Projects Branch 1	7907020495	50-568 A		7907060099	50-482 Q
	7907130015	50-327 A		7907060112*	50-482 Q
	7907130019*	50-327 A		7907240100*	50-336 P
	7907130015	50-327 A		7907180794*	50-338 Q
	7907130019*	50-327 A		7907180803*	50-338 Q
	7907130084	50-568 D		7907180794*	50-338 Q
	7907250193	50-568 D		7907180803*	50-338 Q
	7907250198	50-568 D	Assistant Director for Engineers & Projects (Pre 790625)	7907240057	NUREG
	7907250199	50-568 D		7907260573	50-320 H
	7907250201	50-568 D		7907180235	50-309 P
	7907250202	50-568 D		7907130028	50-263 Q
	7907250203	50-568 D		7907180657	50-133 P
	7907250203	50-568 D		7907180644	50-220 P
	7907250207	50-568 D		7907180619	50-3 P
	7907250208	50-568 D		7907180610	50-249 P
	7907250210	50-568 D		7907250008	50-250 P
	7907130086	50-568 D		7907250004	50-254 P
	7907250193	50-568 D		7907250018	50-259 P
	7907250198	50-568 D		7907180620	50-261 P
	7907250199	50-568 D		7907180647	50-263 P
	7907250201	50-568 D		7907250004	50-254 P
	7907250202	50-568 D		7907250021	50-266 P
	7907250203	50-568 D		7907250007	50-269 P
	7907250205	50-568 D		7907180663	50-271 P
	7907250207	50-568 D		7907180659	50-272 P
	7907250208	50-568 D		7907250014	50-277 P
	7907250210	50-568 D		7907250020	50-280 P
	7907060427	50-358 D		7907180649	50-285 P
	7907110023	50-599 A		7907250013	50-286 P
	7907110684	50-599 A		7907180639	50-289 P
	7907110023	50-599 A		7907180607	50-293 P
	7907110684	50-599 A		7907250006	50-295 P
	7907110023	50-599 A		7907180648	50-298 P
	7907110684	50-599 A		7907250021	50-266 P
	7907110684	50-599 A		7907180628	50-302 P
Environmental Projects Branch 2	7907230687	50-382 A		7907250006	50-295 P
	7907120253*	50-382 A		7907250025	50-305 P
	7907110601	50-596 D		7907250012	50-282 P
	7907050055	50-387 A		7907180641	50-309 P
	7907200242	50-387 D		7907180659	50-272 P
	7907050200	50-461 A		7907250015	50-312 P
	7907060424	50-219 P		7907180637	50-313 P
	7907060430*	50-219 P		7907250009	50-315 P
Assistant Director for Site Technology Branch	7907300504	50-387 A		7907250001	50-317 P
	7907130010*	50-352 Q		7907180632	50-321 P
	7907100690	50-410 A		7907180624	50-324 P
	7907030283*	50-566 A		7907180636	50-331 P
	7907110223	50-425 A		7907180655	50-333 P
	7907190739	40-4492		7907180626	50-334 P
	7907190744*	40-4492			



# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

46

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Engineering Branch	7907180631	50-335 P	Operating Reactors Branch 4 (Pre 790625)	7907250110*	50-277 P
	7907180642	50-336 P		7907250115*	50-277 P
	7907180230	50-344 P		7907250116*	50-277 P
	7907180641	50-346 P		7907250107	50-277 P
	7907180604	50-348 P		7907250110*	50-277 P
	7907180632	50-321 P		7907250115*	50-277 P
	7907100057	50-320 P		7907250116*	50-277 P
	7907100123	50-320 P		7907250112	50-331 P
	7907240627*	50-293 Q		7907250117*	50-331 P
	7907230226*	50-295 Q		7907250122*	50-331 P
	7907230268*	50-295 Q		7907310470	50-293 P
	7907230341*	50-295 Q		7907180401	50-220 Q
	7907230226*	50-295 Q		7907180407*	50-220 Q
	7907230268*	50-295 Q		7907230318	50-321 D
	7907230341*	50-295 Q		7907230335	50-324 P
	7907190268	50-289 P		7907260645	50-254 P
	7907230343*	50-295 Q		7907230317*	50-249 P
	7907180134	NUREG		7907260031	50-10 P
	7907060087	50-271 P		7907250067	50-331 P
	7907060488	50-293 F		7907110675	50-285 F
Environmental Evaluation Branch (Pre 790625)	7907030113	50-298 P	Operating Reactors Branch 3 (Pre 790625)	7907060240	50-336 Q
	7907060481	50-333 P		7907060241*	50-336 Q
	7907060078	50-293 F		7907050172	50-225 P
	7907050022	50-263 P		7907030263	50-54 P
	7907050026*	50-263 P		7907030269*	50-84 P
	7907050033*	50-263 P		7907030270*	50-84 P
	7907060470	50-298 P		7907030271*	50-84 P
	7907060047	50-333 P		7907020319*	50-287 P
	7907100648	50-298 P		7907030144	50-317 P
	7907030051	50-324 P		7907030147*	50-317 P
	7907060127	50-271 P		7907180692	50-317 P
	7907090374	50-293 Q		7907030144	50-317 P
	7907170068	50-298 P		7907030147*	50-317 P
	7907170076*	50-298 P		7907180692	50-317 P
	7907170095*	50-298 P		7907110648	50-346 Q
	7907170109*	50-298 P		7907110219	50-309 P
	7907060117	50-333 Q		7907020223	50-346 P
	7907180245	50-333 F		7907050467	50-59 P
	7907240616	50-293 Q		7907060155	50-309 Q
	7907130406	50-260 P		7907060141	50-336 P
Operating Reactors Branch 3 (Pre 790625)	7907130411*	50-260 P		7907090196*	50-335 P
	7907130421*	50-260 P		7907090177	50-335 P
	7907130054	50-324 P		7907090184*	50-335 P
	7907060085	50-259 P		7907090280*	50-335 P
	7907130048	50-259 P		7907100020	50-223 P
	7907060085	50-259 P		7907100024*	50-223 P
	7907130048	50-259 P		7907300001	50-302 P
	7907060085	50-259 P		7907300011*	50-302 P
	7907130048	50-259 P		7907060093	50-160 P
	7907190297	50-324 P		7907060098*	50-160 P
	7907190277	50-333 P		7907060104*	50-160 P
	7907190266	50-254 Q		7907100304*	50-320 P
	7907110683	50-263 P		7907190840	50-356 P
	7907240387	50-263 P		7907110597	50-313 P
	7907110698	50-277 P		7907190105*	50-313 P
	7907120180	50-277 P		7907300163	50-124 P
	7907120190*	50-277 P		7907180884*	50-346 P
	7907120190*	50-277 P		7907240392*	50-263 P
	7907120200*	50-277 P		7907240396*	50-263 P
	7907110698	50-277 P		7907240563*	50-263 P
	7907120180	50-277 P		7907110736	50-317 P
Operating Reactors Branch 3 (Pre 790625)	7907120190*	50-277 P		7907180876	50-346 P
	7907120200*	50-277 P		7907180893*	50-346 P
	7907110692	50-321 P		7907260579	50-20 P
	7907110745	50-324 Q		7907260581*	50-20 P
	7907120052	50-324 Q		7907180857	50-57 P
	7907120058*	50-324 Q		7907180863*	50-57 P
	7907120052	50-324 Q		7907180867*	50-57 P
	7907120058*	50-324 Q		7907240399	50-289 P
	7907180396	50-263 P		7907190789	50-336 Q
	7907240374	50-220 P		7907310614	50-131 P
	7907240380*	50-220 P		7907310617*	50-131 P
	7907240382*	50-220 P		7907240378*	50-220 P
	7907110741	50-298 F		7907310611	50-309 P
	7907180887	50-331 P		7907240549*	50-129 P
	7907310462	50-254 P		7907240573	50-129 P
	7907250120	50-259 P		7907240578*	50-129 P
	7907310224	50-321 P		7907310144	50-313 P
	7907310232*	50-321 P		7907260084	50-317 P
	7907310236*	50-321 P		7907260092*	50-317 P
	7907310239*	50-321 P		7907260105*	50-317 P
	7907310218	50-324 Q		7907300142	50-346 P
	7907310459	50-333 P		7907300147*	50-346 P
Operating Reactors Branch 3 (Pre 790625)	7907240041	50-333 P		7907300152*	50-346 P
	7907250107	50-277 P			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907300157*	50-346 P		7907110199	50-302 P
	7907250589	50-269 P		7907110210*	50-302 P
	7907250595*	50-269 P		7907300072	50-263 S
	7907250600*	50-269 P		7907110096	50-261 P
	7907250601*	50-269 P		7907110106*	50-261 P
	7907250606*	50-269 P		7907110114	50-269 P
	7907250589	50-269 P		7907180846	50-409 F
	7907250595*	50-269 P		7907180881	50-245 P
	7907250600*	50-269 P		7907180864	50-259 Q
	7907250601*	50-269 P		7907180899	50-261 P
	7907250606*	50-269 P		7907180898	50-293 P
	7907250589	50-269 P		7907180864	50-259 Q
	7907250595*	50-269 P		7907180905	50-302 P
	7907250600*	50-269 P		7907310315	50-348 Q
	7907250601*	50-269 P		7907310323*	50-348 Q
	7907250606*	50-269 P		7907190126	50-286 P
	7907250138	50-309 F		7907190131*	50-286 P
	7907250502*	50-269 P		7907180842	GEN TEC 1B
	7907200224*	50-269 P		7907300189	TOPREP
	7907230495	50-269 P		7907190155	50-237 F
	7907230502*	50-269 P		7907240479	50-266 P
	7907230532*	50-269 P		7907310466	50-266 P
	7907200224*	50-269 P		7907310550*	50-266 P
	7907230495	50-269 P		7907180888	50-277 P
	7907230502*	50-269 P		7907240479	50-266 P
	7907230532*	50-269 P		7907310466	50-266 P
	7907200224*	50-269 P		7907310550*	50-266 P
	7907230495	50-269 P		7907190470	GEN TEC 1B
	7907230502*	50-269 P		7907310597	50-244 F
	7907230532*	50-269 P	Operating Reactors Branch 1 (Pre 790625)	7907020243	50-338 P
	7907020267	50-313 P		7907120053	50-280 P
	7907240093	50-336 P		7906250325	50-320 P
	7907240103*	50-336 P		7906250326*	50-320 P
	7907200211	50-269 P		7906250327*	50-320 P
	7907170130*	50-27 P		7906250328*	50-320 P
	7907180064*	50-261 P		7907310576	50-3 P
Assistant Director for Operating Reactor Projects	7907260431*	50-272 Q		7907310580	50-213 P
Operating Reactors Branch 1	7907260403*	50-272 Q		7907310576	50-3 P
	7907300568	50-344 P		7907310584	50-250 P
	7907310196*	50-272 P		7907310579	50-261 P
	7907240493*	50-315 P		7907310594	50-272 P
	7907300514	50-250 P		7907310590	50-286 P
	7907300562	50-348 P		7907310569	50-295 P
	7907250125	50-305 P		7907310588	50-315 P
	7907300154	50-266 P		7907310583	50-334 P
Operating Reactors Branch 3	7907300518	50-333 P		7907310596	50-338 P
	7907270309	50-366 P		7907310593	50-344 P
	7907270322*	50-366 P		7907310568	50-348 P
	7907270328*	50-366 P		7907130152	50-250 Q
	7907270332*	50-366 P		7907020236	50-344 P
	7907270355	50-331 P		7907060239	50-344 P
	7907270360*	50-331 P		7907110717	50-286 F
	7907270369*	50-331 P		7907180217	50-3 Q
	7907270336	50-366 P		7907240626	50-29 Q
	7907270341*	50-366 P		7907240618	50-206 Q
	7907270346*	50-366 P		7907240599	50-213 Q
	7907270350*	50-366 P		7907240614	50-244 Q
Operating Reactors Branch 4	7907300341	50-254 P		7907180217	50-3 Q
	7907300560	50-313 F		7907130090	50-250 P
	7907300446*	50-312 P		7907240602	50-250 Q
	7907300476*	50-302 P		7907130090	50-250 P
	7907300438*	FOIA		7907240602	50-250 Q
Operating Reactors Branch 2	7907300355	50-390 Q		7907130167	50-261 P
	7907300567	50-213 P		7907130174*	50-261 P
	7907300572	50-244 P		7907240596	50-261 Q
Assistant Director for Site & Safeguards Reactor Safeguards Licensing Branch	7907120452*	SECY		7907240622	50-266 Q
	7907230191*	COMMISSION		7907240613	50-272 Q
Assistant Director for Systems Engineering Reactor Systems Branch	7907020434	50-320 P		7907240619	50-280 Q
	7907130123	50-334 P		7907240607	50-282 Q
	7907260458*	50-320 P		7907240608	50-286 Q
	7907120642	50-320 P		7907240593	50-295 Q
	7907120643	50-320 P		7907240622	50-266 Q
	7907120732	50-320 P		7907240593	50-295 Q
	7907030039*	QA999		7907240625	50-305 Q
	7907260466*	50-320 P		7907240607	50-282 Q
	7907060266	GEN TEC 1B		7907240605	50-315 Q
	7907230343*	50-295 Q		7907240600	50-334 Q
	7907230361*	50-295 Q		7907240610	50-344 Q
	7907230345*	50-295 Q		7907240592	50-348 Q
	7907230361*	50-295 Q		7907090216	50-261 P
	7907240414	50-263 P		7907090217*	50-261 P
	7907110142	50-280 P		7907090218*	50-261 P
	7907110148*	50-280 P		7907090221*	50-261 P
	7907110142	50-280 P			
	7907110148*	50-280 P			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

4

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907030045	50-280 P		7907270204*	50-295 P
	7907130194	50-282 R		7907300024	50-344 P
	7907130133	50-250 P		7907260177	50-315 P
	7907130141*	50-250 P		7907260195*	50-315 P
				7907260208*	50-315 P
	7907130133	50-250 P		7907260230*	50-315 P
	7907130141*	50-250 P		7907260177	50-315 P
	7907190674	50-272 P		7907260195*	50-315 P
	7907110738	50-280 P		7907260208*	50-315 P
	7907130209	50-315 P		7907260230*	50-315 P
	7907130097	50-266 F		7907250071	50-344 P
	7907110577	50-286 P		7907260068	50-344 P
	7907110581	50-286 P		7907260088*	50-344 P
	7907110587*	50-286 P		7907260094*	50-344 P
	7907110592*	50-286 P		7907260102*	50-344 P
	7907130097	50-266 F		7907260533	50-261 P
	7907180697	50-247 P		7907180061	50-261 P
	7907110571	50-272 P		7907180068*	50-261 P
	7907310177	50-272 P		7907180194	50-334 P
	7907310183*	50-272 P		7907300141	50-261 P
	7907310187*	50-272 P		7907250094	50-301 P
	7907130071	50-280 P		7907260022	50-272 P
	7907180697	50-247 P		7907060072	50-29 P
	7907310329	50-266 P	Operating Reactors Branch 2 (Pre 790628)		
	7907310336*	50-266 P		7907310560	50-29 P
	7907310329	50-266 P		7907310559	50-206 P
	7907310336*	50-266 P			
	7907180710	50-334 P		7907060496	50-219 P
	7907110082	50-344 P		7907060218	50-247 Q
	7907110694	50-250 P		7907060498	50-285 P
				7907110728	50-219 P
	7907110730	50-250 P			
				7907190842	50-409 Q
	7907110694	50-250 P		7907060233	50-244 P
	7907110730	50-250 P		7907120494	50-244 P
	7907130311	50-334 P		7907060217	50-255 P
	7907130316*	50-334 P		7907060221*	50-255 P
	7907130329*	50-334 P		7907060225*	50-255 P
	7907190609	50-247 P		7907060230*	50-255 P
	7907190614*	50-247 P		7907110637	50-255 P
	7907190623*	50-247 P		7907100007	50-219 P
	7907240389	50-272 P		7907100012*	50-219 P
	7907240397*	50-272 P		7907110480	50-219 P
	7907240603*	50-272 P		7907130134	50-219 P
	7907240612	50-280 Q		7907130140*	50-219 P
	7907180158	50-3 P		7907130154*	50-219 P
	7907240369	50-29 P		7907120169	50-245 P
	7907240360	50-206 P		7907120179*	50-245 P
	7907240344	50-213 P		7907120199*	50-245 P
	7907240337	50-244 P		7907190807	50-244 P
	7907180158	50-3 P		7907190796	50-409 P
	7907240346	50-230 P		7907250145	50-10 P
	7907240339	50-261 P		7907310281	50-29 P
	7907240364	50-246 P		7907310273	50-155 P
	7907240356	50-272 P		7907310287	50-206 P
	7907240362	50-280 P		7907310278	50-213 P
	7907240350	50-282 P		7907310264	50-219 P
	7907240354	50-286 P		7907250145	50-10 P
	7907240340	50-293 P		7907310226	50-244 P
	7907240364	50-266 P		7907310231	50-245 P
	7907240340	50-293 P		7907190759	50-255 P
	7907240367	50-305 P		7907310273	50-158 P
	7907240350	50-282 P		7907310267	50-409 P
	7907240347	50-313 P		7907110723	50-213 P
	7907190647	50-348 P		7907110729*	50-213 P
	7907190652*	50-348 P		7907120091	50-245 P
	7907190661*	50-348 P		7907110631	50-10 P
	7907240338	50-344 P		7907110661	50-29 P
	7907240403	50-247 P			
	7907240411*	50-247 P		7907110623	50-155 P
	7907240415*	50-247 P		7907110658	50-206 P
	7907240418*	50-247 P		7907110676	50-213 P
				7907110666	50-219 P
	7907180203	50-272 Q		7907110631	50-10 P
				7907110651	50-244 P
	7907250057	50-334 P		7907110673	50-245 P
	7907250535	50-250 P		7907110623	50-155 P
	7907250543*	50-250 P		7907110647	50-409 P
	7907250549*	50-250 P			
				7907110662	50-219 P
	7907250557*	50-250 P		7907270262	50-409 Q
				7907250308	50-244 P
				7907250312*	50-244 P
				7907250319*	50-244 P
	7907270189	50-293 P		7907250322*	50-244 P
	7907270193*	50-293 P		7907250176	50-10 P
	7907270204*	50-293 P		7907250188	50-29 P
	7907270189	50-293 P			
	7907270193*	50-293 P			

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907250178	50-155 P		7907240406*	REQOD
	7907250187	50-206 P		7907050131	50-361 A
	7907300030	50-206 P		7907060247	50-389 A
	7907300033*	50-206 P		7906270273	DRG
	7907300035*	50-206 P		7907120475	50-361 F
	7907250179	50-213 P		7907120485*	50-361 F
	7907250183	50-219 P		7907120485*	50-361 F
	7907250176	50-10 P		7907030246	50-566 A
	7907250186	50-244 P		7907180694	50-361 Q
	7907250189	50-243 P		7907110268	50-395 A
	7907250178	50-155 P		7907110164	50-445 A
	7907250181	50-409 P		7907110176*	50-445 A
	7907120739	FOIA		7907110164	50-445 A
Reactor Safety Branch	7907160355	FOIA		7907110176*	50-445 A
Systematic Evaluation Programs Branch, (Pre 790625)				7907180580	50-341 Q
	7907160102	50-320 P		7907240424	50-363 A
	7907160078	50-320 P		7907190008	50-437 A
	7906190135	50-10 P		7907180912	TOPREP
	7907160361	50-287 P		7907240620	50-382 A
	7907250609	TOPREP		7907180892	50-445 A
	7907260505	50-213 P		7907300290	50-437 Q
	7907250055	50-244 P		7907270389	50-445 A
	7907260961	50-255 P	Light Water Reactors Branch 3	7907050183	50-338 F
Division of Project Management	7907110687*	50-338 Q		7907130041	50-482 A
	7907110359	50-320 A		7907110625	50-482 A
	7907160109	50-369 A		7907130041	50-482 A
	7907050401*	50-500 Q		7907110281	50-311 A
	7907020279	50-320 Q		7907110679	50-338 P
	7907020442	50-320 P		7907110667	50-339 A
	7907160237	50-316 Q		7907110037	50-482 A
	7907160368	50-302 Q		7907130065	50-592 A
	7907160373	50-313 Q		7907130084	50-596 A
	7907160377*	50-313 Q		7907190799	50-387 A
	7907160365	50-346 Q		7907030097	50-482 A
	7907160177	50-336 Q		7907030099	50-311 A
	7907050399*	50-500 Q		7907110704	50-387 A
	7907120656	50-247 Q		7907110711*	50-387 A
	7907120226*	50-322 A		7907110704	50-387 A
	7907100691	50-275 A		7907110711*	50-387 A
	7907020414	FOIA		7907250564	50-338 P
	7907020397	50-303 P		7907250571*	50-338 P
	7907020489	FOIA		7907250578*	50-338 P
	7907020510	FOIA		7907250581*	50-338 A
	7907050029	50-495 A		7907250564	50-338 P
	7907050034*	50-495 A		7907250571*	50-338 P
	7907180916	TOPREP		7907250578*	50-338 P
	7907180170*	50-3 P		7907250581*	50-338 A
	7907110794	50-528 A		7907240434	50-373 E
	7907120333	50-275 H		7907310463	50-387 A
	7907020119	50-320 Q		7907250052	50-311 A
	7907020188	50-335 P		7907200248	50-338 P
	7907230324	50-320 P		7907250069	50-596 A
	7907300400	50-346 Q		7907300550	50-596 A
	7907300488*	50-346 Q		7907250069	50-596 A
	7907300407	50-346 S		7907300550	50-596 A
	7907300411	50-346 S		7907300582	50-482 A
Assistant Director for Light Water Reactors	7907050325*	50-400 Q	Light Water Reactors Branch 4	7907160023*	50-287 Q
	7907050325*	50-400 Q		7907160037*	50-302 Q
	7907310572*	50-338 Q		7907160046*	50-312 Q
	7906260134	TOPREP		7907160007	50-313 Q
	7907060466*	50-549 Q		7905230663	50-329 A
	7907060066	50-443 I		7905240952	50-329 A
	7907310441	50-482 H		7907120209	50-322 A
	7907310005	50-339 A		7907120241*	50-322 A
	7907310468	50-404 A		7907050136	50-458 A
Light Water Reactors Branch 1	7907270001*	50-338 P		7907110524	50-322 F
	7907180913	GEN TEC IS		7907270281	50-397 A
	7907240373	50-461 A		7907110276	50-322 A
	7907250051	50-368 P		7907110051	50-454 A
	7907250061*	50-368 P		7907130057	50-329 A
	7907250072*	50-368 P		7907110051	50-454 A
	7907250080*	50-368 P		7907110699	50-327 A
	7907300560	50-313 F		7907190028	50-329 A
	7907240583	50-341 F		7907310457	TOPREP
	7907180199	50-461 A		7907240053	50-329 A
Light Water Reactors Branch 2	7907250611	50-315 P	Assistant Director for Quality Assurance & Operations	7907260494	50-320 H
	7907260890	50-556 A		7907260478	50-320 U
	7907110438*	50-338 Q	Operator Licensing Branch	7907110365	50-320 A
	7907160012*	FOIA		7907100685	50-452 A
	7907160018*	FOIA	Quality Assurance Branch	7907020148	50-320 P
	7907240419*	REQOD		7907260500	50-320 H

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Assistant Director for Standard & Advanced Reactors	7907110112	50-443 A		7907100108	REGDD
	7907060186	50-416 A		7907100112	REGDD
	7907260143	50-267 P		7907100115	REGDD
	7907260149*	50-267 P		7907100118	REGDD
Advanced Reactors Branch	7907260155*	50-267 P		7907100098	REGDD
	7907090214	50-267 P		7907100134	REGDD
	7907240449	50-267 P		7907100096	REGDD
	7907240456*	50-267 P		7907100147	REGDD
Standardization Branch	7906220115	50-320 P		7907100064	REGDD
	7907190325	50-10 P		7907100073	REGDD
	7907020505	FOIA		7907110229	REGDD
	7907050038*	50-495 A		7907110233	REGDD
Division of Systems Safety	7907250604	TOPREP		7907100246	REGDD
	7907180189	50-320 B		7907100152	REGDD
	7907300471	50-289 P		7907100157	REGDD
	7907050063*	FOIA		7907100166	REGDD
	7907050085*	FOIA		7907100171	REGDD
	7907120800*	50-320 P		7907110260	REGDD
	7907110154	50-320 P		7907110250	REGDD
	7907020127	50-320 P		7907100178	REGDD
	7907120742	50-287 P		7907100182	REGDD
	7907120193	50-320 H		7907100185	REGDD
	7907020329	FOIA		7907100189	REGDD
	7907020341	FOIA		7907100191	REGDD
	7907030135	50-320 P		7907100193	REGDD
	7907020490	FOIA		7907100199	REGDD
	7907050025	50-320 P		7907110190	REGDD
	7907110258	50-320 P		7907100091	REGDD
	7907190140	50-400 A		7907100213	REGDD
	7907190059	50-320 H		7907100215	REGDD
	7907090223	NUREG		7907100218	REGDD
	7907130303	50-320 P		7907100220	REGDD
	7907190474	GEN TEC IS		7907110273	REGDD
	7907190260	50-320 P		7907110280	REGDD
	7907200508	GEN TEC IS		7907100224	REGDD
	7907300437	50-346 P		7907110287	REGDD
Mechanical Engineering Branch	7907260700	50-320 P		7907100231	REGDD
	7907120240	50-320 H		7907100235	REGDD
	7907110262	50-311 A		7907100253	REGDD
	7907020144	50-320 P		7907110193	REGDD
Assistant Director for Plant Systems	7907260453*	50-320 P		7907100197	REGDD
	7907110218	50-320 P		7907100227	REGDD
	7907160243*	50-275 Q		7907100274	REGDD
	7907260449*	50-320 P		7907100275	REGDD
	7907260442	50-320 P		7907100280	REGDD
	7907050405*	50-300 Q		7907110237	REGDD
	7907110022	50-320 P		7907100077	REGDD
	7907310581*	50-338 Q		7907100297	REGDD
Assistant Director for Reactor Safety	7907130018	50-322 A		7907100299	REGDD
	7907190304	50-320 P		7907100054	REGDD
	7907160249	FOIA			
	7907160005	FOIA			
Analysis Branch	7907160084	50-320 P		7907100058	REGDD
	7907260503	50-320 H		7907100104	REGDD
	7907020482	FOIA		7907100301	REGDD
	7907090273	REVIEW QRP		7907100310	REGDD
	7907240443	TOPREP		7907100321	REGDD
	7907250200	TOPREP		7907100205	REGDD
	7907190306	50-320 H		7907100317	REGDD
	7907300469	50-320 P			
	7907300377	50-320 P		7907100083	REGDD
	7907160118	50-320 P		7907100088	REGDD
	7907310587*	50-338 P		7907100079	REGDD
	7905230296	50-320 P		7907100126	REGDD
	7907310465*	TOPREP		7907100149	REGDD
	7907300369	TOPREP			
	7907230174*	50-320 P		7907100336	REGDD
	7907260483	50-320 P		7907100383	REGDD
	7907180415	50-322 A		7907100120	REGDD
	7907090251	50-322 A		7907100174	REGDD
	7907230063	50-322 A		7907100358	REGDD
	7907300171	50-322 A			
	7907230097	50-387 A		7907100403	REGDD
	7907050059*	FOIA		7907100342	REGDD
	7907190194*	FOIA		7907110083	REGDD
	7907190202*	FOIA		7907100101	REGDD
Reactor Systems Branch	7907190199*	FOIA		7907100242	REGDD
	7907120207	50-29 P		7907100349	REGDD
	7907100048	REGDD		7907110204	REGDD
	7907100050	REGDD		7907110214	REGDD
Office of Standards Development	7907100059	REGDD		7907110128	REGDD
				7907100372	REGDD
				7907100323	REGDD
				7907100377	REGDD
				7907100386	REGDD
				7907100261	REGDD
				7907100345	REGDD

# U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

494

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7907100141	REGOD		7907110500	REGOD
	7907100394	REGOD		7907110512*	REGOD
	7907100392	REGOD		7907110591*	REGOD
	7907100370	50-320 F		7907120055*	REGOD
	7907100362	REGOD		7907120067*	REGOD
				7907170236	REGOD
	7907110090	REGOD		7907170238	REGOD
	7907100073	REGOD		7907190818	REGOD
	7907100158	REGOD		7907130295	50-320 H
	7907110099	REGOD		7907120040	REGOD
	7907110117	REGOD	Division of Engineering Standards	7907160301*	70-2623
			Fuel Process Systems Standards Branch	7907190311	50-320 H
	7907110072	REGOD	Division of Siting, Health & Safeguards		
	7907110094	REGOD	Standards		
	7907110405	REGOD			
	7907100225	REGOD			
	7907100329	REGOD			
	7907100354	REGOD	Site Safety Standards Branch	7907020158	50-320 P
	7907100366	REGOD	Occupational Health Standards Branch	7907120743	50-320 P
	7907100397	REGOD	Radiological Health Standards Branch	7907120208	50-320 H
	7907110158	REGOD		7907190301	50-320 H
	7907100250	REGOD			
	7907100163	REGOD	Office of Nuclear Regulatory Research	7907120278*	SECY
	7907110161	REGOD		7907160092	50-320 P
	7907110168	REGOD		7907120289*	SECY
	7907110173	REGOD		7907050058	ORG
	7907100401	REGOD		7907090441	50-320 H
	7907110221	REGOD		7907120165	RES
	7907110123	REGOD		7907060089	COMMISSION
	7907110282	REGOD		7907160271*	50-320 H
	7907110140	REGOD		7907160194	50-320 P
	7907110181	REGOD		7907090435	50-320 P
	7907100144	REGOD	Administrative and Resource Control	7907160184	50-287 U
	7907100333	REGOD	Staff		
	7907110133	REGOD		7907120692	50-320 P
	7907110155	REGOD			
	7907110244	REGOD			
	7907100128	REGOD		7907180080	50-320 H
	7907100211	REGOD			
	7907110144	REGOD	Program Coordination Branch	7907160260	50-320 H
	7907110147	REGOD		7907160225	50-320 H
	7907100138	REGOD	Probabilistic Analysis Branch	7907160266*	50-320 H
			Environmental Effects Research Branch	7907160204	50-320 P
	7907110104	REGOD		7907160214	50-320 P
	7907110184	REGOD		7907160219	50-320 P
	7907110110	REGOD	Division of Reactor Safety Research	7907050089*	FOIA
	7907100240	REGOD		7905240950	REVIEW GRP
	7907100265	REGOD		7907050335	REVIEW GRP
				7907090271	REVIEW GRP
	7907100257	REGOD		7907090272*	REVIEW GRP
	7907110270	REGOD		7907190033	REVIEW GRP
	7907090138	SECY	Experimental Fast Reactor Safety Research	7907160200	50-320 O
	7907050406	50-320 P	Branch		
	7907240421	SECY	Analysis Development Branch	7907240480	TOPREP
	7906130475	ORG	Fuel Behavior Branch	7906220227	REVIEW GRP
	7907110010*	50-320 O		7907180171	NUREG
	7907110718	ORG	Research Support Branch	7907110187	FOIA
				7907300080	REVIEW GRP

# REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index titled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
79-RD-54	7907100387*	50-206 R	
7904300436	7907300436	RES	
7907030243	7907030243	RES	PNL-2260-10
7907030320	7907030320	RES	
7907060245	7907060245	RES	
7907060446	7907060446	RES	
7907060455	7907060455	RES	
7907070137	7907070137	RES	CAAP-TR-049
7907090429	7907090429	RES	
7907090443	7907090443	RES	
7907110064	7907110064	RES	DRNL/ED/EAB-79/
7907110113	7907110113	RES	RE-A-78-211
7907110149	7907110149	RES	RE-A-78-155
7907110316	7907110316	RES	
7907110483	7907110483	RES	BNL-NUREQ-26003
7907120056	7907120056	RES	
7907120062	7907120062	RES	DRNL/FTR-601
7907120070	7907120070	RES	
7907120076	7907120076	RES	
7907120082	7907120082	RES	
7907120097	7907120097	RES	
7907120103	7907120103	RES	
7907120107	7907120107	RES	
7907120109	7907120109	RES	
7907120115	7907120115	RES	
7907120123	7907120123	RES	
7907120126	7907120126	RES	
7907120138	7907120138	RES	
7907120146	7907120146	RES	MC 79-272
7907120165	7907120165	RES	
7907190637	7907190637	RES	
7907190675	7907190675	RES	DRNL/ED/EAB-79/
7907190691	7907190691	RES	
7907300282	7907300282	RES	DRNL/HABRD-38
7907300306	7907300306	RES	DRNL/ENG/FTR-60
7907300353	7907300353	50-266 F	
7907300368	7907300368	RES	DRNL/ED/EIB-92
7907300381	7907300381	RES	
7907300421	7907300421	RES	DRNL/HABRD-40
7907300448	7907300448	RES	
7907300458	7907300458	RES	
7907300467	7907300467	RES	
7907300489	7907300489	RES	
7907300507	7907300507	RES	DRNL/HABRD-39
7907300527	7907300527	RES	
7907300541	7907300541	RES	DRNL/FTR-633
7907300554	7907300554	RES	
7907300585	7907300585	RES	
7907310109	7907310109	RES	
7907310133	7907310133	RES	
7907310149	7907310149	RES	
7907310175	7907310175	50-282 F	
7907310186	7907310186	50-10 F	
7907310208	7907310208	RES	
7907310219	7907310219	RES	

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
7907310303	7907310303	RES	
7907310320	7907310320	RES	
BAW-1538 REV 1	7907200293*	TOPREP	
BCL-585-12	7907120344*	50-255 P	
CEB-GDS-79-1	7907170140*	50-327 A	
EF-125	7907300375*	50-14 R	
EPA-520/6-74-002	7907110192*	50-320 O	
GRS-A-59	7906210421*	50-466 O	
IPS-400	7907250382*	50-311 E	
NEDQ-12724	7906200240*	50-73 F	
NEDQ-25090	7907160334*	TOPREP	
NUREQ-0030 V2 N2	7907110659	NUREQ	
NUREQ-0020 V3 N5	7907030261	NUREQ	
NUREQ-0094	7907110365	50-320 A PB-255 664	
NUREQ-0195	7907110404	50-320 A PB-267 288	
NUREQ-0197	7907110390	50-320 P PB-269 387	
NUREQ-0200 V3 N6	7907250607	NUREQ	
NUREQ-0240	7907160351*	COMMISSION	
NUREQ-0321	7907110359	50-320 A PB 272 040	
NUREQ-0325	7907110401	50-320 F	
NUREQ-0380 V3 N7	7907300248	NUREQ	
NUREQ-0396	7907130536*	50-346 O EPA 520/1-78-01	
NUREQ-0460	7812290071	NUREQ	
NUREQ-0540 V1 N5	7907190546	NUREQ	
NUREQ-0555	7907090016	NUREQ	
NUREQ-0555 1 1	7907090020	NUREQ	
NUREQ-0555 1 2	7907090021	NUREQ	
NUREQ-0555 10 1	7907090207	NUREQ	
NUREQ-0555 10 2	7907090208	NUREQ	
NUREQ-0555 10 3	7907090209	NUREQ	
NUREQ-0555 10.4 1	7907090210	NUREQ	
NUREQ-0555 10.4 2	7907090211	NUREQ	
NUREQ-0555 10.4 3	7907090212	NUREQ	
NUREQ-0555 2.1	7907090223	NUREQ	
NUREQ-0555 2.2 1	7907090025	NUREQ	
NUREQ-0555 2.2 2	7907090027	NUREQ	
NUREQ-0555 2.2 3	7907090029	NUREQ	
NUREQ-0555 2.3 1	7907090033	NUREQ	
NUREQ-0555 2.3 2	7907090034	NUREQ	
NUREQ-0555 2.3 3	7907090037	NUREQ	
NUREQ-0555 2.4 1	7907090039	NUREQ	
NUREQ-0555 2.4 2	7907090042	NUREQ	
NUREQ-0555 2.5 1	7907090044	NUREQ	
NUREQ-0555 2.5 2	7907090048	NUREQ	
NUREQ-0555 2.5 3	7907090050	NUREQ	
NUREQ-0555 2.6	7907090052	NUREQ	
NUREQ-0555 2.7	7907090055	NUREQ	
NUREQ-0555 2.8	7907090057	NUREQ	
NUREQ-0555 3.1	7907090059	NUREQ	
NUREQ-0555 3.2	7907090064	NUREQ	
NUREQ-0555 3.3 1	7907090067	NUREQ	
NUREQ-0555 3.3 2	7907090069	NUREQ	
NUREQ-0555 3.4 1	7907090070	NUREQ	
NUREQ-0555 3.4 2	7907090074	NUREQ	
NUREQ-0555 3.5	7907090075	NUREQ	

## REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREQ-0555 3 6 1	7907090078	NUREQ		NUREQ/CR-0647	7907300057	NUREQ	TREE-1332
NUREQ-0555 3 6 2	7907090079	NUREQ		NUREQ/CR-0650	7907300145	NUREQ	
NUREQ-0555 3 6 3	7907090082	NUREQ		NUREQ/CR-0655	7907300441	NUREQ	
NUREQ-0555 3 7	7907090086	NUREQ		NUREQ/CR-0661 V9	7907260563	NUREQ	SAND 79-0359
NUREQ-0555 3 8	7907090097	NUREQ		NUREQ/CR-0664	7907300426	NUREQ	
NUREQ-0555 4 1 1	7907090090	NUREQ		NUREQ/CR-0667	7907310068	NUREQ	BNL-NUREG-50966
NUREQ-0555 4 1 2	7907090092	NUREQ		NUREQ/CR-0668	7907230914	NUREQ	PNL-2379
NUREQ-0555 4 1 3	7907090096	NUREQ		NUREQ/CR-0678	7907060442	NUREQ	
NUREQ-0555 4 2 1	7907090100	NUREQ		NUREQ/CR-0679	7907170204	NUREQ	UCRL-52561
NUREQ-0555 4 2 2	7907090104	NUREQ		NUREQ/CR-0684	7907050149	NUREQ	UCRL-52481
NUREQ-0555 4 3 1	7907090107	NUREQ		NUREQ/CR-0688	7907240085	NUREQ	BNL-NUREG-50978
NUREQ-0555 4 3 2	7907090117	NUREQ		NUREQ/CR-0705	7907170110	NUREQ	TREE-1325
NUREQ-0555 4 4 1	7907090111	NUREQ		NUREQ/CR-0711	7907180116	NUREQ	EML-355
NUREQ-0555 4 4 2	7907090112	NUREQ		NUREQ/CR-0727	7907180134	NUREQ	
NUREQ-0555 4 5	7907090114	NUREQ		NUREQ/CR-0741	7907250288	NUREQ	ANL-CT-79-30
NUREQ-0555 4 6	7907090116	NUREQ		NUREQ/CR-0745	7907170197	NUREQ	PNL-2623
NUREQ-0555 5 1.1	7907090117	NUREQ		NUREQ/CR-0748	7907190218	NUREQ	UCRL-52499
NUREQ-0555 5 1.2	7907090119	NUREQ		NUREQ/CR-0759	7907110283	NUREQ	ANL-79-19
NUREQ-0555 5 1.3	7907090120	NUREQ		NUREQ/CR-0762	7907250538	NUREQ	LA-7769-PR
NUREQ-0555 5 10	7907090156	NUREQ		NUREQ/CR-0764	7907190488	NUREQ	ORNL/NUREG/TH-3
NUREQ-0555 5 2 1	7907090122	NUREQ		NUREQ/CR-0766	7907190341	NUREQ	HEDL-TME 79-3
NUREQ-0555 5 2.2	7907090125	NUREQ		NUREQ/CR-0770	7907170231	NUREQ	ANL/EB-71
NUREQ-0555 5 3 1 1	7907090127	NUREQ		NUREQ/CR-0771	7907100672	NUREQ	RQ
NUREQ-0555 5 3 1 2	7907090128	NUREQ		NUREQ/CR-0776	7907120156	NUREQ	LA-77933-MB
NUREQ-0555 5 3 2 1	7907090131	NUREQ		NUREQ/CR-0789	7907190501	NUREQ	ORNL/NUREG/TH-3
NUREQ-0555 5 3 2 2	7907090132	NUREQ		NUREQ/CR-0800	7907300068	NUREQ	PNL-2977
NUREQ-0555 5 3 3 1	7907090135	NUREQ		NUREQ/CR-0807	7907030434	NUREQ	LA-7812-MB
NUREQ-0555 5 3 3 2	7907090136	NUREQ		NUREQ/CR-0811	7907190483	NUREQ	BAI-OR-79-140-0
NUREQ-0555 5 4 1	7907090142	NUREQ		NUREQ/CR-0812	7907110727	50-219	P
NUREQ-0555 5 4 2	7907090143	NUREQ		NUREQ/CR-0814	7907240126	NUREQ	TREE-1228
NUREQ-0555 5 4.3	7907090145	NUREQ		NUREQ/CR-0816	7907190510	NUREQ	ANL-CT-79-33
NUREQ-0555 5 4.4	7907090147	NUREQ		NUREQ/CR-0822	7907190254	NUREQ	
NUREQ-0555 5 5	7907090148	NUREQ		NUREQ/CR-0828	7907300047	NUREQ	ANL-79-18
NUREQ-0555 5 6 1	7907090149	NUREQ		NUREQ/CR-0839	7907110734	NUREQ	R7
NUREQ-0555 5 6 2	7907090150	NUREQ		NUREQ/CR-0840	7907270388	NUREQ	TREE-1281
NUREQ-0555 5 6 3	7907090151	NUREQ		NUREQ/CR-0842	7907190192	NUREQ	LA-UR-79-1025
NUREQ-0555 5 7	7907090152	NUREQ		NUREQ/CR-0845	7907110635	NUREQ	BMI-2028
NUREQ-0555 5 8 1	7907090270	NUREQ		NUREQ/CR-0850	7907170217	NUREQ	
NUREQ-0555 5 8 2	7907090154	NUREQ		NUREQ/CR-0851	7907310035	NUREQ	LA-7856-MB
NUREQ-0555 5 9	7907090155	NUREQ		NUREQ/CR-0863	7907170167	NUREQ	LA-NUREG-6623
NUREQ-0555 6 1	7907090159	NUREQ		NUREQ/CR-0872	7907170187	NUREQ	BMI-2027
NUREQ-0555 6 2	7907090160	NUREQ		NUREQ/CR-0874	7907190205	NUREQ	
NUREQ-0555 6 3	7907090163	NUREQ		NUREQ/CR-0875	7907190281	NUREQ	
NUREQ-0555 6 4	7907090165	NUREQ		NUREQ/CR-0882	7907190326	NUREQ	
NUREQ-0555 6 5 1	7907090167	NUREQ		NUREQ/CR-0887	7907190833	NUREQ	
NUREQ-0555 6 5.2	7907090170	NUREQ		NUREQ/CR-0888	7907190433	NUREQ	
NUREQ-0555 6 6	7907090172	NUREQ		NUREQ/CR-0889	7907190480	NUREQ	
NUREQ-0555 6 7	7907090175	NUREQ		NUREQ/CR-0890	7907190374	NUREQ	
NUREQ-0555 7 1	7907090176	NUREQ		NUREQ/CR-0895	7907240176	NUREQ	
NUREQ-0555 7 2	7907090178	NUREQ		NUREQ/CR-0897	7907190711	NUREQ	BMI-2029
NUREQ-0555 8 1	7907090179	NUREQ		NUREQ/CR-0900	7907190391	NUREQ	ATR-79(7B14)-1
NUREQ-0555 8 2.1	7907090180	NUREQ		NUREQ/CR-0906	7907190393	NUREQ	
NUREQ-0555 8 2.2	7907090185	NUREQ		ORO-4207-12	7907310393*	50-128	R
NUREQ-0555 8 3	7907090187	NUREQ		PGE-1012	7907300373*	50-344	F
NUREQ-0555 8 4	7907090191	NUREQ		PNL-2833	7907110235*	70-364	
NUREQ-0555 9 1 1	7907090193	NUREQ		PNL-2898	7907310620	RES	
NUREQ-0555 9 1.2	7907090194	NUREQ		PNL-SA-7618	7907310555	RES	
NUREQ-0555 9 1 3	7907090197	NUREQ		Q	7907240228*	50-400	Q
NUREQ-0555 9 2	7907090199	NUREQ		RT-508	7907200267*	50-267	P
NUREQ-0555 9 3 1	7907090201	NUREQ		SECY 78-163	7907090038	SECY	
NUREQ-0555 9 3.2	7907090203	NUREQ		SECY-78-110	7907240416	SECY	
NUREQ-0555 9 3 3	7907090204	NUREQ		SECY-78-613A	7907090080	SECY	
NUREQ-0555 9 3.4	7907090205	NUREQ		SECY-78-613B	7907090091	SECY	
NUREQ-0562	7907180171	NUREQ		SECY-78-616	7907240404	SECY	
NUREQ-0574	7907240057	NUREQ		SECY-78-616A	7907240393	SECY	
NUREQ-0578	7907310071*	50-320	P	SECY-78-655A	7907190009	SECY	
UREQ/CR-0135	7907230750	NUREQ	OEAP-10207-42	SECY-78-690	7907090138	SECY	
UREQ/CR-0312	7907170136	NUREQ		SECY-78-690A	7907090174	SECY	
UREQ/CR-0388	7907260470	50-320	P SAND 78-0269	SECY-79-100	7907130427	SECY	
UREQ/CR-0498	7907180182	NUREQ	ANL/EB-72	SECY-79-215	7907180278*	SECY	
UREQ/CR-0500	7907170121	NUREQ	TREE-1270	SECY-79-278	7907120466*	SECY	
UREQ/CR-0538	7907250299	NUREQ	UCRL-52547	SECY-79-278A	7907120422	SECY	
UREQ/CR-0550	7907270357	NUREQ	HEDL-TME 78-7	SECY-79-300	7907240421	SECY	
UREQ/CR-0553	7907270366	NUREQ	ANL/EB-72	SECY-79-368	7907230188	SECY	
UREQ/CR-0566	7907190169	NUREQ	ORNL/NUREG/NBIC	SECY-79-72A	7907180860*	SECY	
NUREG/CR-0577	7907270404	NUREQ	UCRL-52632	BR 8-001-NP	7907030482*	TOPREP	
NUREG/CR-0579	7907250307	NUREQ	UCRL-52626	WC AP-9405	7907200305*	TOPREP	
NUREG/CR-0597	7907280403	NUREQ	ANL/EB-75	XN-NF-439	7907190377*	71-3	P
NUREG/CR-0615	7907300099	NUREQ	ORNL/NUREG/NBIC	XN-NF-507	7907180621*	50-285	P
NUREG/CR-0618	7907270400	NUREQ	TREE-1329	XN-NF-78-30(A)A01	7907110459*	TOPREP	
				XN-NF-79-45	7907180609*	50-285	P



# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7904270127	7904270123	79/04/20	I&E
7905040162	7905040159	79/04/20	50-320 P
7905240084	7905240076	79/04/24	WASTE MGT
7906140590	7906140584	79/04/20	40-8006
7906140594	7906140584	79/04/20	40-8006
7906140597	7906140584	79/04/20	40-8006
7906140602	7906140575	79/05/02	XPORTLIC
7906200120	7906200115	79/05/14	50-269 Q
7906200127	7906200115	79/05/14	50-269 Q
7906200240	7906200236	79/06/13	50-73 P
7906210231	7906210227	79/06/01	50-397 A
7906210234	7906210227	79/06/01	50-397 A
7906210238	7906210227	79/06/01	50-397 A
7906210421	7906210417	79/05/02	50-466 Q
7906220168	7906220164	79/05/10	50-287 Q
7906250326	7906250325	79/05/11	50-320 P
7906250327	7906250325	79/05/11	50-320 P
7906250328	7906250325	79/05/11	50-320 P
7906260590	7906260586	79/05/17	50-250 U
7906260593	7906260586	79/05/17	50-250 U
7906290180	7906290145	79/05/02	70-1710
7907020029	7907020025	79/06/11	70-1308
7907020038	7907020037	79/05/17	71-257
7907020049	7907020045	79/04/20	50-302 Q
7907020072	7907020045	79/04/20	50-269 Q
7907020076	7907020045	79/04/20	50-346 Q
7907020078	7907020045	79/04/20	50-313 Q
7907020080	7907020045	79/04/20	50-312 Q
7907020103	7907020097	79/04/20	50-302 Q
7907020108	7907020097	79/04/20	50-269 Q
7907020115	7907020097	79/04/20	50-346 Q
7907020117	7907020097	79/04/20	50-313 Q
7907020123	7907020097	79/04/20	50-312 Q
7907020124	7907020119	79/06/16	50-320 Q
7907020130	7907020127	79/04/10	50-320 P
7907020139	7907020134	79/04/20	50-269 Q
7907020145	7907020134	79/04/20	50-302 Q
7907020149	7907020134	79/04/20	50-346 Q
7907020153	7907020134	79/04/20	50-313 Q
7907020157	7907020134	79/04/20	50-312 Q
7907020161	7907020156	79/02/28	50-368 P
7907020195	7907020191	79/06/29	50-537 B
7907020207	7907020202	79/06/26	50-29 Q
7907020253	7907020248	79/06/15	50-366 S
7907020264	7907020259	79/06/18	50-366 S
7907020294	7907020283	79/06/21	50-366 S
7907020308	7907020302	79/06/21	50-366 S
7907020316	7907020312	79/05/18	50-269 P
7907020319	7907020312	79/05/18	50-269 P
7907020322	7907020320	78/11/09	FR
7907020326	7907020324	79/05/16	71-130
7907020404	7907020394	79/05/16	50-320 Q
7907020411	7907020407	79/05/10	FOIA
7907020457	7907020456	79/05/21	71-279
7907020462	7907020460	79/05/18	71-175

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907020473	7907020472	79/05/10	70-143
7907020480	7907020479	79/05/25	50-341 Q
7907020492	7907020490	79/05/30	FOIA
7907020497	7907020493	79/05/02	50-556 H
7907020501	7907020500	79/05/21	XPORTLIC
7907020502	7907020493	79/05/02	50-556 H
7907020506	7907020504	79/05/24	50-309 H
7907020507	7907020505	79/06/01	FOIA
7907020509	7907020508	79/05/10	40-8602
7907020513	7907020512	79/05/29	50-312 Q
7907030026	7907030019	79/04/26	GA999
7907030032	7907030029	79/04/26	GA999
7907030039	7907030036	79/04/26	GA999
7907030058	7907030054	79/05/21	50-333 Q
7907030062	7907030054	79/05/21	50-333 Q
7907030065	7907030054	79/05/21	50-333 Q
7907030068	7907030054	79/05/21	50-333 Q
7907030084	7907030073	79/05/31	50-397 Q
7907030088	7907030073	79/05/31	50-397 Q
7907030091	7907030073	79/05/31	50-397 Q
7907030092	7907030073	79/05/31	50-397 Q
7907030094	7907030073	79/05/31	50-397 Q
7907030109	7907030107	79/05/13	40-2259
7907030131	7907030117	79/06/11	50-458 A
7907030134	7907030117	79/06/11	FOIA
7907030137	7907030135	79/05/25	50-320 P
7907030141	7907030135	79/05/25	50-320 P
7907030147	7907030144	79/05/18	50-317 P
7907030155	7907030153	79/06/13	FOIA
7907030156	7907030154	79/03/28	FOIA
7907030157	7907030153	79/06/13	FOIA
7907030160	7907030154	79/03/28	FOIA
7907030163	7907030154	79/03/28	FOIA
7907030166	7907030162	79/05/23	71-215
7907030168	7907030162	79/05/23	71-215
7907030169	7907030165	79/06/11	FOIA
7907030172	7907030165	79/06/11	FOIA
7907030213	7907030154	79/03/28	FOIA
7907030220	7907030154	79/03/28	FOIA
7907030231	7907030221	79/06/19	40-8681
7907030249	7907030247	79/06/21	50-59
7907030253	7907030246	79/05/29	50-566 A
7907030269	7907030263	79/05/17	50-54 P
7907030270	7907030263	79/05/17	50-54 P
7907030271	7907030263	79/05/17	50-54 P
7907030275	7907030272	79/06/29	50-282 R
7907030296	7907030290	79/06/13	40-1162
7907030314	7907030311	79/05/01	FOIA
7907030337	7907030333	79/05/17	XPORTLIC
7907030344	7907030340	79/06/28	50-263 S
7907030353	7907030349	79/06/29	50-367 K
7907030381	7907030379	79/06/27	50-219 S
7907030393	7907030390	79/06/25	50-317 S
7907030398	7907030396	79/06/27	50-313 S

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7907030408	7907030404	79/06/22	50-237	S	7907050392	7907050388	79/04/26	50-397	Q
7907030425	7907030421	79/06/29	50-338	S	7907050394	7907050357	79/07/02	50-321	I
7907030429	7907030421	79/06/29	50-338	S	7907050399	7907050395	79/05/07	50-500	O
7907030444	7907030442	79/06/29	50-285	P	7907050401	7907050395	79/05/07	50-500	O
7907030445	7907030279	79/06/28	50-329	K	7907050405	7907050395	79/05/07	50-500	O
7907030455	7907030452	79/06/28	50-302	S	7907050414	7907050404	79/06/29	50-282	S
7907030459	7907030465	79/06/20	50-206	F	7907050416	7907050412	79/05/21	71-181	
7907030472	7907030470	79/06/28	50-329	K	7907050425	7907050186	79/05/15	50-387	Q
7907030479	7907030476	79/06/25	50-255	S	7907050452	7907050447	79/05/16	71-156	
7907030482	7907030480	79/04/09	TOPREP		7907050493	7907050490	79/04/02	70-2443	
7907030486	7907030483	79/06/28	50-302	S	7907050498	7907050494	79/04/24	50-363	Q
7907030493	7907030490	79/06/20	50-416	B	7907050510	7907050504	79/05/18	71-209	
7907030500	7907030497	79/06/28	50-400	A	7907050519	7907050513	79/05/17	71-87	
7907050011	7907050008	79/06/04	50-313	Q	7907050527	7907050525	79/04/24	50-423	Q
7907050026	7907050022	79/05/15	50-263	P	7907050536	7907050530	79/04/26	GA999	
7907050028	7907050022	79/05/15	50-263	P	7907050548	7907050542	79/05/24	50-280	H
7907050033	7907050022	79/05/15	50-263	P	7907050552	7907050549	79/04/18	50-304	Q
7907050034	7907050029	79/06/01	50-495	A	7907050553	7907050549	79/04/18	50-304	Q
7907050038	7907050029	79/06/01	50-495	A	7907050554	7907050551	79/05/13	50-361	H
7907050054	7907050047	79/04/03	70-2662		7907060011	7907060009	79/03/04	71-66	
7907050057	7907050053	79/06/18	50-556	A	7907060024	7907060019	79/05/21	70-2623	
7907050059	7907050053	79/06/18	FOIA		7907060026	7907060025	79/05/30	50-320	P
7907050063	7907050053	79/06/18	FOIA		7907060028	7907060019	79/05/21	70-2623	
7907050066	7907050053	79/06/18	FOIA		7907060033	7907060019	79/05/21	70-2623	
7907050071	7907050067	79/05/03	50-338	Q	7907060037	7907060019	79/05/21	70-2623	
7907050074	7907050072	79/02/05	70-364		7907060046	7907060041	79/04/26	GA999	
7907050082	7907050053	79/06/18	FOIA		7907060063	7907060058	79/05/21	70-2623	
7907050085	7907050053	79/06/18	FOIA		7907060065	7907060058	79/05/21	70-2623	
7907050086	7907050080	79/03/15	50-272	Q	7907060068	7907060067	79/06/01	71-328	
7907050089	7907050053	79/06/18	FOIA		7907060071	7907060070	79/06/01	71-328	
7907050092	7907050053	79/06/18	FOIA		7907060094	7907060089	79/06/05	COMMISSION	
7907050093	7907050084	79/05/22	GA999		7907060098	7907060093	79/03/30	50-160	P
7907050097	7907050084	79/05/22	GA999		7907060102	7907060099	79/06/18	50-482	Q
7907050101	7907050084	79/05/22	GA999		7907060104	7907060093	79/05/30	50-160	P
7907050102	7907050098	79/06/26	50-368	S	7907060107	7907060099	79/06/18	50-482	Q
7907050103	7907050095	79/05/01	50-327	Q	7907060112	7907060099	79/06/18	50-482	Q
7907050104	7907050084	79/05/22	GA999		7907060145	7907060141	79/05/25	50-336	P
7907050107	7907050098	79/06/26	50-368	S	7907060149	7907060144	79/05/30	50-275	Q
7907050109	7907050084	79/05/22	GA999		7907060159	7907060155	79/05/24	50-309	Q
7907050117	7907050112	79/05/10	50-305	Q	7907060163	7907060155	79/05/24	50-309	Q
7907050127	7907050123	79/06/29	50-341	K	7907060165	7907060162	79/06/25	70-1193	
7907050128	7907050124	79/05/24	50-309	H	7907060171	7907060167	79/06/29	50-213	Q
7907050129	7907050123	79/06/29	50-341	K	7907060201	7907060196	79/07/02	50-522	A
7907050140	7907050138	79/04/15	50-298	Q	7907060205	7907060196	79/07/02	50-522	A
7907050143	7907050134	79/03/03	50-438	Q	7907060221	7907060217	79/05/29	50-255	F
7907050144	7907050142	79/04/26	50-267	Q	7907060225	7907060217	79/05/29	50-255	F
7907050154	7907050151	79/03/18	50-413	Q	7907060228	7907060222	79/05/08	70-2623	
7907050155	7907050150	79/04/17	50-324	Q	7907060229	7907060212	79/06/29	50-267	R
7907050157	7907050151	79/05/18	50-413	Q	7907060230	7907060217	79/05/29	50-255	F
7907050163	7907050159	79/04/01	50-344	Q	7907060236	7907060234	79/06/27	50-321	R
7907050168	7907050165	79/05/01	50-267	Q	7907060237	7907060235	79/05/25	COMMISSION	
7907050179	7907050174	79/03/01	50-498	Q	7907060241	7907060240	79/05/11	50-336	Q
7907050182	7907050175	79/05/22	50-400	Q	7907060243	7907060242	79/05/30	50-219	F
7907050187	7907050184	79/04/24	50-482	Q	7907060252	7907060249	79/04/23	TOPREP	
7907050189	7907050175	79/05/22	50-400	Q	7907060265	7907060261	79/04/26	40-8714	
7907050193	7907050190	79/05/30	50-546	H	7907060273	7907060272	79/06/26	50-237	Q
7907050195	7907050191	79/05/03	50-298	Q	7907060298	7907060291	79/07/02	50-280	B
7907050203	7907050198	79/04/30	50-302	Q	7907060299	7907060293	79/05/24	50-280	H
7907050232	7907050227	79/05/25	71-6244		7907060316	7907060309	79/06/28	50-327	A
7907050240	7907050234	79/07/03	50-244	P	7907060330	7907060326	79/06/27	50-409	B
7907050261	7907050257	79/06/29	50-245	P	7907060332	7907060331	79/07/02	50-338	B
7907050274	7907050268	79/08/17	CONTRACT		7907060333	7907060331	79/07/02	50-338	B
7907050279	7907050273	79/03/23	71-6387		7907060334	7907060331	79/07/02	50-338	B
7907050283	7907050281	79/03/30	50-329	H	7907060336	7907060335	79/06/28	50-344	B
7907050289	7907050286	79/07/02	50-280	R	7907060345	7907060344	79/05/29	50-295	Q
7907050292	7907050291	79/07/03	50-338	P	7907060347	7907060344	79/05/29	50-295	Q
7907050302	7907050301	79/06/28	50-272	S	7907060348	7907060346	79/06/27	50-321	B
7907050303	7907050300	79/06/29	50-282	S	7907060349	7907060344	79/05/29	50-295	Q
7907050305	7907050304	79/06/28	50-260	B	7907060351	7907060344	79/05/29	50-295	Q
7907050309	7907050307	79/06/29	50-305	S	7907060355	7907060344	79/05/29	50-295	Q
7907050313	7907050307	79/06/29	50-305	B	7907060356	7907060343	79/05/09	50-280	H
7907050315	7907050306	79/06/29	50-329	C	7907060357	7907060354	79/06/29	50-259	P
7907050318	7907050316	79/06/25	50-336	Q	7907060360	7907060344	79/05/29	50-295	Q
7907050325	7907050320	79/05/09	50-400	Q	7907060365	7907060344	79/05/29	50-295	Q
7907050325	7907050320	79/05/09	50-400	Q	7907060369	7907060344	79/05/29	50-295	Q
7907050326	7907050321	79/06/27	50-416	K	7907060371	7907060344	79/05/29	50-295	Q
7907050329	7907050310	79/06/28	50-325	B	7907060409	7907060403	79/07/03	50-324	B
7907050354	7907050338	79/06/28	50-220	S	7907060412	7907060406	79/07/03	50-325	B
7907050359	7907050335	REVIEW	GRP		7907060413	7907060403	79/07/03	50-324	B
7907050376	7907050372	79/06/27	50-366	B	7907060416	7907060408	79/07/03	50-325	B
7907050382	7907050378	79/06/27	50-361	A	7907060419	7907060414	79/05/09	COMMISSION	
7907050384	7907050387	79/07/02	50-321	I	7907060426	7907060424	79/06/06	50-219	P
7907050385	7907050380	79/06/01	50-488	U	7907060430	7907060424	79/06/06	50-219	P
7907050389	7907050386	79/05/16	71-9009		7907060434	7907060424	79/06/06	50-219	P

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

499

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907060444	7907060438	79/06/05	50-338 Q
7907060450	7907060441	79/07/02	50-244 Q
7907060454	7907060448	79/05/10	50-269 H
7907060464	7907060457	79/06/05	50-338 Q
7907060466	7907060459	79/05/29	50-349 Q
7907060467	7907060465	79/06/12	40-1739
7907060475	7907060465	79/06/12	40-1739
7907060479	7907060465	79/06/12	40-1739
7907060484	7907060465	79/06/12	40-1739
7907060486	7907060465	79/06/12	40-1739
7907060490	7907060465	79/06/12	40-1739
7907060494	7907060493	79/05/18	70-820
7907060505	7907060502	79/05/25	40-8663
7907060509	7907060506	79/05/10	50-356 Q
7907060510	7907060506	79/05/10	50-356 Q
7907060511	7907060508	79/05/25	40-8602
7907060514	7907060513	79/06/01	50-346 Q
7907090002	7907090001	79/06/01	50-522 Q
7907090003	7907090001	79/06/01	50-522 Q
7907090007	7907090005	79/05/29	50-201 U
7907090013	7907090011	79/08/30	10CFR
7907090043	7907090038	79/05/30	SECY
7907090049	7907090038	79/05/30	SECY
7907090053	7907090038	79/05/30	SECY
7907090058	7907090038	79/05/30	SECY
7907090063	7907090038	79/05/30	SECY
7907090066	7907090061	79/06/05	50-250 Q
7907090068	7907090038	79/05/30	SECY
7907090084	7907090080	79/08/30	SECY
7907090097	7907090091	79/05/30	SECY
7907090103	7907090091	79/05/30	SECY
7907090106	7907090091	79/05/30	SECY
7907090118	7907090113	79/08/31	CONTRACT
7907090123	7907090121	79/05/31	70-364
7907090130	7907090126	79/08/01	50-335 Q
7907090137	7907090138	79/05/30	SECY
7907090144	7907090138	79/05/30	SECY
7907090169	7907090138	79/05/30	SECY
7907090181	7907090174	79/05/30	SECY
7907090184	7907090177	79/05/27	50-335 P
7907090186	7907090174	79/05/30	SECY
7907090189	7907090174	79/05/30	SECY
7907090196	7907090177	79/08/27	50-335 P
7907090200	7907090177	79/05/27	50-335 P
7907090217	7907090216	79/08/24	50-261 P
7907090218	7907090216	79/05/24	50-261 P
7907090221	7907090216	79/05/24	50-261 P
7907090222	7907090219	79/07/03	50-317 P
7907090224	7907090219	79/07/03	50-317 P
7907090225	7907090219	79/07/03	50-317 P
7907090226	7907090223	79/06/08	NUREG
7907090230	7907090228	79/07/05	50-285 P
7907090233	7907090229	79/07/05	50-324 S
7907090234	7907090232	79/07/02	50-302 S
7907090254	7907090243	79/05/23	40-2259
7907090257	7907090243	79/05/23	40-2259
7907090259	7907090256	79/06/12	50-244 R
7907090260	7907090243	79/05/23	40-2259
7907090264	7907090243	79/05/23	40-2259
7907090265	7907090263	79/07/02	50-334 S
7907090266	7907090262	79/07/02	50-269 S
7907090268	7907090267	79/07/06	50-244 P
7907090272	7907090271	79/06/30	REVIEW CRP
7907090277	7907090276	79/06/30	50-272 S
7907090279	7907090278	79/06/28	50-313 R
7907090285	7907090269	79/07/03	50-338 S
7907090287	7907090281	79/07/02	50-305 S
7907090288	7907090284	79/07/03	50-255 S
7907090292	7907090289	79/06/28	50-368 S
7907090293	7907090291	79/06/29	50-285 P
7907090294	7907090281	79/07/02	50-305 S
7907090297	7907090289	79/06/28	50-368 S
7907090298	7907090296	79/06/27	50-278 S
7907090299	7907090281	79/07/02	50-305 S
7907090302	7907090300	79/06/29	50-245 S
7907090306	7907090304	79/06/27	50-245 S
7907090310	7907090307	79/07/03	50-338 P
7907090311	7907090303	79/06/14	50-250 S
7907090312	7907090309	79/07/03	50-305 S
7907090317	7907090314	79/06/28	50-59 P
7907090318	7907090316	79/06/22	50-327 S
7907090341	7907090327	79/06/22	50-312 Q
7907090343	7907090331	79/06/22	50-438 S

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907090344	7907090336	79/07/02	50-366 S
7907090347	7907090327	79/06/22	50-312 Q
7907090352	7907090327	79/06/22	50-312 Q
7907090353	7907090342	79/06/22	50-369 S
7907090354	7907090349	79/07/02	50-170 P
7907090356	7907090348	79/07/03	50-260 S
7907090358	7907090327	79/06/22	50-312 Q
7907090362	7907090327	79/06/22	50-312 Q
7907090363	7907090360	79/06/26	50-366 S
7907090367	7907090327	79/06/22	50-312 Q
7907090369	7907090351	79/06/21	50-327 S
7907090371	7907090350	79/06/25	50-281 S
7907090376	7907090373	79/07/02	50-321 S
7907090380	7907090372	79/07/05	50-280 S
7907090384	7907090372	79/07/05	50-280 S
7907090392	7907090379	79/03/21	50-298 Q
7907090395	7907090388	79/06/01	50-518 S
7907090396	7907090327	79/06/22	50-312 Q
7907090400	7907090327	79/06/22	50-312 Q
7907090403	7907090397	79/05/29	0A999
7907090407	7907090327	79/06/22	50-312 Q
7907090409	7907090401	79/05/15	50-322 Q
7907090412	7907090327	79/06/22	50-312 Q
7907090414	7907090406	79/05/24	50-395 Q
7907090416	7907060411	79/04/16	50-424 H
7907090417	7907090327	79/06/22	FOIA
7907090419	7907090327	79/06/22	FOIA
7907090423	7907090415	79/05/27	XPORTLIC
7907090426	7907090420	79/06/06	50-491 Q
7907090432	7907090428	79/06/08	50-263 P
7907090433	7907090420	79/06/06	50-491 Q
7907090437	7907090435	79/06/21	50-320 P
7907090438	7907090434	79/05/08	50-281 Q
7907090440	7907090431	79/05/24	50-269 Q
7907090445	7907090431	79/05/24	50-269 Q
7907090446	7907090439	79/05/17	50-313 Q
7907090449	7907090444	79/04/16	50-213 Q
7907090451	7907090448	79/06/21	FOIA
7907090459	7907090452	79/05/12	50-466 Q
7907090463	7907090448	79/06/21	FOIA
7907090464	7907090448	79/06/21	FOIA
7907090466	7907090462	79/04/27	0A999
7907090469	7907090465	79/05/30	50-320 P
7907090474	7907090470	79/04/06	0A999
7907090478	7907090476	79/04/26	0A999
7907100006	7907100003	03/79/05	CONTRACT
7907100012	7907100009	79/05/30	50-219 P
7907100013	7907100008	79/04/01	CONTRACT
7907100015	7907100009	79/05/30	50-219 P
7907100017	7907100009	79/05/30	50-219 P
7907100024	7907100020	79/05/29	50-223 P
7907100027	7907100020	79/05/29	50-223 P
7907100087	7907100082	79/06/15	50-320 T
7907100092	7907100082	79/06/15	50-320 T
7907100130	7907100122	79/06/20	50-320 T
7907100132	7907100124	79/06/21	50-320 T
7907100140	7907100133	79/06/15	50-320 Q
7907100162	7907100156	79/06/25	FOIA
7907100188	7907100181	79/06/06	50-320 J
7907100236	7907100228	79/05/01	50-320 R
7907100244	7907100228	79/05/01	50-320 R
7907100255	7907100228	79/05/01	50-320 R
7907100288	7907100277	79/05/30	50-320 P
7907100292	7907100277	79/05/30	50-320 P
7907100294	7907100287	79/04/14	50-320 Q
7907100295	7907100286	79/07/06	50-348 S
7907100304	7907100277	79/05/30	50-320 S
7907100311	7907100300	79/07/03	50-249 S
7907100322	7907100312	79/05/29	50-320 Q
7907100324	7907100318	79/07/02	50-128 P
7907100330	7907100319	79/07/06	50-255 S
7907100334	7907100328	79/06/19	50-320 Q
7907100340	7907100318	79/07/02	50-128 P
7907100346	7907100318	79/07/02	50-128 P
7907100352	7907100318	79/07/02	50-128 P
7907100359	7907100318	79/07/02	50-128 P
7907100360	7907100350	79/07/02	50-321 R
7907100368	7907100318	79/07/02	50-128 P
7907100378	7907100387	79/07/05	50-261 S
7907100387	7907100375	79/06/27	50-206 R
7907100402	7907100399	79/07/02	50-219 R
7907100406	7907100388	79/07/03	50-336 S

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7907100414	7907100408	79/04/12	50-514	R	7907110393	7907110342	79/05/31	50-466	Q
7907100432	7907100423	79/07/03	50-286	B	7907110398	7907110139	79/04/03	50-320	P
7907100433	7907100427	79/06/26	50-29	P	7907110382	7907110139	79/04/03	50-320	P
					7907110393	7907110376	78/06/08	50-269	S
7907100444	7907100439	79/07/03	50-346	B					
7907100458	7907100448	79/07/03	50-346	B	7907110407	7907110400	78/11/27	50-366	B
7907100472	7907100463	79/07/03	50-346	B	7907110411	7907110139	79/04/03	50-320	P
7907100482	7907100479	79/07/03	50-260	B	7907110412	7907110408	78/08/07	50-251	S
7907100489	7907100485	79/07/06	50-29	B	7907110415	7907110409	78/07/17	50-348	S
					7907110418	7907110414	79/05/11	50-382	Q
7907100500	7907100493	79/07/06	50-29	B					
7907100519	7907100515	79/07/03	50-302	P	7907110425	7907110422	79/07/05	50-344	S
7907100537	7907100181	79/06/06	50-320	J	7907110426	7907110421	79/05/08	50-333	Q
7907100538	7907100527	79/07/06	50-329	S	7907110428	7907110423	79/05/14	50-358	Q
7907100544	7907100543	79/06/23	50-311	A	7907110433	7907110430	79/07/03	50-237	S
					7907110436	7907110435	79/07/02	50-295	S
7907100564	7907100556	79/07/06	50-390	Q					
7907100569	7907100556	79/07/06	50-390	Q	7907110437	7907110432	79/05/09	50-358	Q
7907100572	7907100567	79/06/28	50-295	Q	7907110438	7907110434	79/05/10	70-925	
7907100578	7907100567	79/06/28	50-295	Q	7907110439	7907110387	79/05/23	CONTRACT	
7907100587	7907100584	79/07/09	50-346	P	7907110441	7907110440	79/06/28	50-295	B
					7907110443	7907110442	79/07/02	50-237	B
7907100598	7907100595	79/07/05	50-206	R					
7907100603	7907100602	79/07/03	50-206	B	7907110445	7907110444	79/06/27	50-254	S
					7907110447	7907110446	79/07/06	50-334	S
7907100606	7907100604	79/06/25	50-329	S					
7907100609	7907100607	79/07/05	50-333	R	7907110450	7907110448	78/05/01	50-270	S
7907100627	7907100624	79/07/02	50-128	I	7907110456	7907110449	79/05/09	50-358	Q
7907100639	7907100636	79/05/22	40-8304		7907110459	7907110451	79/05/23	TOPREP	
7907100654	7907100653	79/07/05	50-289	R	7907110460	7907110453	79/05/09	50-245	Q
					7907110461	7907110455	78/09/26	50-348	S
7907100659	7907100651	79/06/29	50-361	B					
7907100676	7907100673	79/06/29	50-361	S	7907110462	7907110458	79/06/20	50-254	S
7907100680	7907100673	79/06/29	50-361	S	7907110463	7907110449	79/05/09	50-358	Q
7907100689	7907100678	79/05/24	50-443	Q	7907110465	7907110455	78/09/26	50-348	S
7907100700	7907100698	79/05/11	CONTRACT		7907110468	7907110449	79/05/09	50-358	Q
					7907110473	7907110449	79/05/09	50-358	Q
7907100707	7907100704	79/05/09	CONTRACT						
7907100714	7907100678	79/05/24	50-443	Q	7907110477	7907110470	78/05/12	50-325	B
7907100716	7907100711	79/05/05	CONTRACT		7907110482	7907110478	78/03/02	50-321	B
7907100717	7907100692	79/05/03	70-2838		7907110485	7907110478	78/03/02	50-321	B
7907100719	7907100678	79/05/24	50-443	Q	7907110491	7907110478	78/03/02	50-321	B
					7907110494	7907110489	79/05/08	50-311	Q
7907100727	7907100721	79/05/22	0A999						
7907100728	7907100723	79/05/30	CONTRACT		7907110497	7907110488	79/06/15	PROJ	
7907100730	7907100721	79/05/22	0A999		7907110503	7907110413	79/05/16	50-358	Q
7907100733	7907100721	79/05/22	0A999		7907110512	7907110500	79/05/30	REGOD	
7907110003	7907110002	79/05/30	50-320	D	7907110515	7907110413	79/05/16	50-358	Q
					7907110517	7907110506	78/11/17	50-366	S
7907110006	7907110004	79/05/30	50-320	Q					
7907110007	7907110004	79/05/30	50-320	Q	7907110520	7907110513	79/07/06	50-346	R
7907110008	7907110004	79/05/30	50-320	Q	7907110521	7907110510	79/06/08	50-320	Q
7907110009	7907110004	79/05/30	50-320	Q	7907110529	7907110510	79/06/08	50-320	Q
7907110010	7907110004	79/05/30	50-320	Q	7907110538	7907110510	79/06/08	50-320	Q
					7907110539	7907110535	79/07/06	50-409	P
7907110014	7907110011	79/05/31	50-320	Q					
7907110015	7907110013	79/05/15	50-423	Q	7907110540	7907110537	78/04/21-	50-269	S
7907110016	7907110011	79/05/31	50-320	Q	7907110541	7907110531	79/07/09	50-368	S
7907110021	7907110017	79/06/01	50-346	P	7907110542	7907110510	78/06/08	50-320	Q
7907110025	7907110017	79/06/01	50-346	P	7907110544	7907110534	79/05/10	50-272	Q
					7907110547	7907110532	79/05/16	CONTRACT	
7907110049	7907110047	79/07/06	50-320	Q					
7907110065	7907110061	79/04/01	CONTRACT		7907110549	7907110543	78/02/23	50-325	B
7907110069	7907110060	79/04/02	0A999		7907110553	7907110480	79/05/30	50-219	P
7907110079	7907110076	79/06/04	50-320	Q	7907110554	7907110548	79/07/03	50-249	B
7907110086	7907110076	79/06/04	50-320	Q	7907110557	7907110546	78/05/19	50-269	B
					7907110560	7907110552	78/04/26	50-269	B
7907110092	7907110078	79/05/04	50-133	Q					
7907110106	7907110096	79/06/04	50-261	P	7907110563	7907110555	79/06/04	50-413	Q
7907110111	7907110101	79/06/05	50-320	Q	7907110566	7907110561	79/06/28	50-309	S
7907110119	7907110109	79/05/31	70-2623		7907110568	7907110555	79/06/04	50-413	Q
7907110121	7907110114	79/06/04	50-269	P	7907110572	7907110499	79/05/17	50-237	Q
					7907110579	7907110574	79/06/04	50-269	Q
7907110122	7907110101	79/06/05	50-320	Q					
7907110129	7907110101	79/06/05	50-320	Q	7907110582	7907110576	78/09/19	50-269	B
					7907110583	7907110574	79/06/04	50-269	Q
7907110134	7907110109	79/05/31	70-2623						
7907110135	7907110101	79/06/05	50-320	Q	7907110587	7907110581	79/05/31	50-286	P
7907110136	7907110120	79/05/04	50-305	Q	7907110589	7907110578	79/05/31	50-400	Q
7907110141	7907110101	79/06/05	50-320	Q	7907110590	7907110574	79/06/04	50-269	Q
7907110148	7907110142	79/05/30	50-280	P	7907110591	7907110500	79/05/31	REGOD	
					7907110592	7907110581	79/05/31	50-286	P
7907110150	7907110101	79/06/05	50-320	Q					
7907110151	7907110145	79/06/01	71-327		7907110594	7907110588	78/11/27	50-366	B
7907110166	7907110160	79/06/08	50-320	Q	7907110596	7907110574	79/06/04	50-269	Q
7907110176	7907110164	79/05/31	50-445	A	7907110598	7907110578	79/05/31	50-400	Q
7907110192	7907110187	79/06/14	50-320	Q	7907110606	7907110603	79/04/30	50-498	Q
					7907110612	7907110603	79/04/30	50-498	Q
7907110210	7907110199	79/05/30	50-302	P					
7907110235	7907110224	79/05/25	70-364		7907110624	7907110618	79/05/14	50-398	Q
7907110241	7907110236	79/06/13	50-320	Q	7907110628	7907110619	79/05/11	50-482	Q
7907110264	7907110253	79/04/23	40-3453		7907110630	7907110617	79/05/24	71-214	
7907110265	7907110243	79/06/01	70-2623		7907110634	7907110626	79/05/09	50-397	Q
					7907110638	7907110618	79/05/14	50-338	Q
7907110272	7907110257	79/05/30	70-364						
7907110297	7907110243	79/06/01	70-2623		7907110644	7907110633	79/06/15	50-277	Q
7907110320	7907110307	79/06/11	50-416	M	7907110645	7907110618	79/05/14	50-338	Q
7907110328	7907110307	79/06/11	50-416	M	7907110654	7907110618	79/05/14	50-338	Q
7907110337	7907110307	79/06/11	50-416	M	7907110657	7907110643	79/05/17	50-413	Q
					7907110660	7907110656	79/05/21	50-445	Q
7907110343	7907110307	79/06/11	50-416	M					
					7907110664	7907110655	79/05/08	40-7983	

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

501

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907110665	7907110618	79/05/14	50-338 Q	7907120649	7907120644	79/07/05	PROJ
7907110672	7907110663	79/06/05	50-387 Q	7907120650	7907120645	79/07/06	50-369 B
7907110677	7907110670	79/03/21	50-382 Q	7907120654	7907120645	79/07/06	50-369 B
7907110678	7907110618	79/05/14	50-338 Q	7907120657	7907120638	79/07/02	50-245 P
7907110680	7907110663	79/06/05	50-387 Q	7907120658	7907120652	79/07/03	50-267 B
7907110681	7907110671	79/05/10	50-445 Q	7907120660	7907120645	79/07/06	50-369 B
7907110687	7907110618	79/05/14	50-338 Q	7907120663	7907120652	79/07/03	50-267 B
7907110689	7907110663	79/06/05	50-387 Q	7907120683	7907120382	79/05/23	XPORTLIC
7907110690	7907110682	79/09/21	50-482 Q	7907120686	7907120681	79/09/22	FOIA
7907110691	7907110685	79/06/06	50-309 H	7907120698	7907120692	79/06/08	50-320 P
7907110693	7907110671	79/05/10	50-445 Q	7907120752	7907120748	79/05/22	FOIA
7907110696	7907110663	79/06/05	50-387 Q	7907120800	7907120718	79/04/03	50-320 P
7907110703	7907110688	79/09/04	50-471 Q	7907130007	7907130002	79/05/31	50-352 Q
7907110707	7907110697	79/06/06	50-320 H	7907130010	7907130002	79/05/31	50-352 Q
7907110711	7907110704	79/06/11	50-387 A	7907130014	7907130002	79/05/31	50-352 Q
7907110712	7907110705	79/04/27	50-361 Q	7907130019	7907130015	79/05/31	50-327 A
7907110719	7907110710	79/06/13	50-277 Q	7907130020	7907130002	79/05/31	50-352 Q
7907110725	7907110705	79/04/27	50-361 Q	7907130022	7907130015	79/05/31	50-327 A
7907110729	7907110723	79/06/07	50-213 P	7907130026	7907130005	79/06/07	70-1100
7907110735	7907110732	79/05/17	50-482 Q	7907130031	7907130005	79/06/07	70-1100
7907110740	7907110732	79/05/17	50-482 Q	7907130039	7907130005	79/06/07	70-1100
7907110743	7907110721	79/05/08	50-339 Q	7907130044	7907130039	79/07/02	50-367 R
7907110747	7907110732	79/05/17	50-482 Q	7907130050	7907130005	79/06/07	70-1100
7907120003	7907120001	79/05/01	50-313 Q	7907130070	7907130056	79/06/05	50-463 Q
7907120004	7907120002	79/05/14	50-498 Q	7907130073	7907130061	78/06/04	CONTRACT
7907120007	7907120001	79/05/01	50-313 Q	7907130077	7907130056	79/06/05	50-463 Q
7907120021	7907120019	79/05/11	50-338 Q	7907130094	7907130088	79/05/21	70-2623
7907120022	7907120014	79/05/23	27-47	7907130098	7907130088	79/05/21	70-2623
7907120027	7907120019	79/05/11	50-338 Q	7907130118	7907130110	79/06/01	50-275 Q
7907120031	7907120016	79/03/23	27-47	7907130121	7907130111	79/06/13	70-143
7907120055	7907120040	79/06/04	REQD	7907130132	7907130111	79/06/13	70-143
7907120058	7907120052	79/06/07	50-324 Q	7907130135	7907130126	79/04/11	50-482 Q
7907120067	7907120040	79/06/04	REQD	7907130139	7907130126	79/04/11	50-482 Q
7907120105	7907120089	79/06/06	40-8722	7907130140	7907130134	79/05/30	50-219 P
7907120106	7907120101	79/07/05	50-267 R	7907130141	7907130133	79/05/30	50-250 P
7907120129	7907120119	79/05/28	50-516 Q	7907130145	7907130111	79/06/13	70-143
7907120152	7907120139	79/05/23	CONTRACT	7907130146	7907130134	79/05/30	50-219 P
7907120171	7907120165	79/05/29	REB	7907130154	7907130134	79/05/30	50-219 P
7907120179	7907120169	79/06/01	50-245 P	7907130158	7907130153	79/05/25	50-358 Q
7907120181	7907120174	79/05/23	CONTRACT	7907130160	7907130156	79/06/08	50-184 Q
7907120188	7907120169	79/06/01	50-245 P	7907130163	7907130156	79/06/08	50-184 Q
7907120190	7907120180	79/06/06	50-277 P	7907130174	7907130167	79/05/22	50-261 P
7907120199	7907120169	79/06/01	50-245 P	7907130175	7907130166	79/05/22	50-329 Q
7907120200	7907120180	79/06/06	50-277 P	7907130179	7907130171	79/05/04	50-70 Q
7907120226	7907120209	79/05/14	50-322 A	7907130182	7907130178	79/06/05	50-220 Q
7907120241	7907120209	79/05/14	50-322 A	7907130191	7907130186	79/05/21	GA999
7907120253	7907120209	79/05/14	50-322 A	7907130194	7907130186	79/05/21	GA999
7907120261	7907120209	79/05/14	50-322 A	7907130199	7907130186	79/05/21	GA999
7907120278	7907120273	79/05/09	SECY	7907130206	7907130186	79/05/21	GA999
7907120289	7907120278	79/05/09	SECY	7907130210	7907130200	79/06/12	50-395 Q
7907120332	7907120284	79/03/26	50-280 H	7907130213	7907130186	79/05/21	GA999
7907120337	7907120331	79/07/02	50-255 P	7907130223	7907130217	79/06/04	70-2623
7907120344	7907120331	79/07/02	50-255 P	7907130225	7907130200	79/06/12	50-395 Q
7907120349	7907120333	79/06/14	50-275 H	7907130228	7907130221	79/05/22	GA999
7907120368	7907120361	79/07/06	50-277 P	7907130232	7907130217	79/06/04	70-2623
7907120406	7907120396	79/04/03	50-460 Q	7907130237	7907130217	79/06/04	70-2623
7907120415	7907120408	79/05/01	50-280 P	7907130238	7907130226	79/04/16	50-387 Q
7907120419	7907120396	79/04/03	50-460 Q	7907130240	7907130234	79/05/16	XPORTLIC
7907120439	7907120422	79/05/07	SECY	7907130242	7907130217	79/06/04	70-2623
7907120452	7907120422	79/05/07	SECY	7907130244	7907130217	79/06/04	70-2623
7907120456	7907120396	79/04/03	50-460 Q	7907130245	7907130239	79/07/09	TOPREP
7907120458	7907120449	79/06/05	70-1308	7907130246	7907130221	79/05/22	GA999
7907120465	7907120449	79/06/05	70-1308	7907130251	7907130221	79/05/22	GA999
7907120466	7907120422	79/05/07	SECY	7907130252	7907130217	79/06/04	70-2623
7907120471	7907120396	79/04/03	50-460 Q	7907130257	7907130217	79/06/04	70-2623
7907120485	7907120475	79/05/29	50-361 F	7907130264	7907130217	79/06/04	70-2623
7907120495	7907120360	79/05/01	XPORTLIC	7907130272	7907130266	79/07/10	50-338 R
7907120532	7907120513	79/06/08	50-280 Q	7907130273	7907130217	79/06/04	70-2623
7907120533	7907120523	79/05/02	50-424 Q	7907130306	7907130299	79/04/28	50-286 Q
7907120555	7907120513	79/06/08	50-280 Q	7907130314	7907130309	79/06/19	50-272 Q
7907120556	7907120513	79/06/08	50-280 Q	7907130316	7907130311	79/06/06	50-334 P
7907120560	7907120558	79/05/01	50-324 Q	7907130319	7907130309	79/06/19	50-272 Q
7907120562	7907120559	79/07/09	50-369 H	7907130320	7907130310	79/05/04	50-341 Q
7907120564	7907120561	79/06/27	50-528 B	7907130323	7907130311	79/06/06	50-334 P
7907120565	7907120563	79/06/27	50-568 A	7907130329	7907130311	79/06/06	50-334 P
7907120570	7907120566	79/07/06	50-237 P	7907130345	7907130339	79/07/09	50-325 B
7907120597	7907120592	79/07/06	50-278 B	7907130347	7907130335	79/04/27	GA999
7907120603	7907120601	79/01/11	50-368 P	7907130393	7907130348	79/07/10	50-261 B
7907120606	7907120601	79/01/11	50-368 P	7907130394	7907130351	79/05/18	50-315 Q
7907120610	7907120607	79/07/06	50-361 B	7907130399	7907130356	79/05/10	50-327 Q
7907120613	7907120608	79/07/05	50-344 R	7907130363	7907130360	79/07/09	50-325 B
7907120641	7907120634	79/07/03	50-335 B	7907130367	7907130364	79/07/09	50-302 B
7907120647	7907120638	79/07/02	50-245 P				

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907130369	7907130221	79/05/22	0A999
7907130370	7907130221	79/05/22	0A999
7907130371	7907130368	79/06/06	50-338 Q
7907130372	7907130221	79/05/22	0A999
7907130373	7907130333	79/07/09	50-336 S
7907130382	7907130381	79/07/07	50-220 S
7907130385	7907130381	79/07/09	50-220 S
7907130391	7907130388	79/07/10	50-267 S
7907130399	7907130393	79/07/06	50-155 R
7907130403	7907130402	79/06/06	50-320 P
7907130411	7907130406	79/05/25	50-260 P
7907130413	7907130410	79/07/11	50-334 P
7907130414	7907130402	79/06/06	50-320 P
7907130418	7907130406	79/05/25	50-260 P
7907130421	7907130406	79/05/25	50-260 P
7907130431	7907130428	79/07/10	50-277 R
7907130438	7907130436	79/07/06	50-303 R
7907130439	7907130437	79/04/18	50-353 P
7907130441	7907130427	79/02/08	SECY
7907130443	7907130432	79/05/10	50-518 Q
7907130448	7907130444	79/07/10	50-220 R
7907130456	7907130451	79/07/09	50-261 R
7907130461	7907130457	79/05/25	40-8725
7907130467	7907130460	79/07/09	50-333 S
7907130471	7907130442	79/06/05	50-498 Q
7907130473	7907130469	79/07/09	50-282 S
7907130474	7907130465	79/05/24	50-346 P
7907130478	7907130435	79/06/14	50-338 Q
7907130479	7907130465	79/05/24	50-346 P
7907130483	7907130455	79/06/14	50-338 Q
7907130485	7907130455	79/06/14	50-338 Q
7907130486	7907130442	79/06/05	50-498 Q
7907130490	7907130455	79/06/14	50-338 Q
7907130499	7907130422	79/05/29	50-302 Q
7907130500	7907130422	79/05/29	50-302 Q
7907130504	7907130422	79/05/29	50-302 Q
7907130505	7907130495	79/06/04	50-599 Q
7907130511	7907130422	79/05/29	50-302 Q
7907130515	7907130513	79/07/09	50-346 Q
7907130519	7907130512	79/06/21	50-320 Q
7907130521	7907130513	79/07/09	50-346 Q
7907130528	7907130513	79/07/09	50-346 Q
7907130536	7907130513	79/07/09	50-346 Q
7907160012	7907160005	79/09/01	FOIA
7907160017	7907160009	79/04/20	50-313 Q
7907160018	7907160005	79/09/01	FOIA
7907160023	7907160009	79/04/20	50-269 Q
7907160030	7907160009	79/04/20	50-269 Q
7907160031	7907160021	79/06/21	COMMISSION
7907160034	7907160027	79/06/01	50-389 Q
7907160037	7907160009	79/04/20	50-302 Q
7907160038	7907160039	79/06/21	COMMISSION
7907160040	7907160009	79/04/20	50-302 Q
7907160044	7907160027	79/06/01	50-389 Q
7907160046	7907160009	79/04/20	50-312 Q
7907160048	7907160009	79/04/20	50-312 Q
7907160050	7907160056	79/08/23	COMMISSION
7907160063	7907160050	79/08/28	COMMISSION
7907160083	7907160073	79/06/29	COMMISSION
7907160086	7907160071	79/06/27	50-416 U
7907160088	7907160073	79/06/27	COMMISSION
7907160091	7907160071	79/06/27	50-416 U
7907160113	7907160106	79/08/29	50-596 Q
7907160122	7907160090	79/06/29	70-143
7907160125	7907160116	79/06/05	50-549 Q
7907160134	7907160090	79/06/29	70-143
7907160137	7907160090	79/06/29	COMMISSION
7907160150	7907160090	79/06/29	70-143
7907160159	7907160090	79/06/29	70-143
7907160162	7907160141	79/06/29	COMMISSION
7907160166	7907160090	79/06/29	70-143
7907160182	7907160176	79/06/26	50-320 P
7907160191	7907160189	79/06/04	50-369 Q
7907160192	7907160188	79/06/29	COMMISSION
7907160195	7907160185	79/06/04	50-369 Q
7907160208	7907160204	79/06/04	50-320 P
7907160220	7907160216	79/05/21	70-2623
7907160223	7907160216	79/05/21	70-2623
7907160230	7907160225	79/06/08	50-320 H
7907160235	7907160232	79/05/21	70-2623
7907160238	7907160232	79/05/21	70-2623
7907160243	7907160237	79/04/24	50-275 Q
7907160254	7907160239	79/06/21	COMMISSION

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907160288	7907160252	79/05/07	50-412 Q
7907160299	7907160247	79/05/23	70-143
7907160263	7907160239	79/06/21	COMMISSION
7907160266	7907160260	79/06/06	50-320 H
7907160268	7907160247	79/05/23	70-143
7907160271	7907160260	79/06/06	50-320 H
7907160273	7907160264	79/06/06	50-454 Q
7907160276	7907160269	79/06/12	50-400 Q
7907160287	7907160280	79/06/05	70-2623
7907160289	7907160282	79/06/29	50-470 K
7907160296	7907160283	79/07/09	50-368 S
7907160301	7907160280	79/06/05	70-2623
7907160303	7907160278	79/06/28	COMMISSION
7907160308	7907160283	79/07/09	50-368 S
7907160311	7907160307	79/07/10	50-272 R
7907160324	7907160315	79/07/09	50-293 S
7907160325	7907160316	79/06/05	50-320 P
7907160334	7907160328	79/06/28	TOPREP
7907160336	7907160312	79/06/18	COMMISSION
7907160344	7907160312	79/06/18	COMMISSION
7907160351	7907160312	79/06/18	COMMISSION
7907160353	7907160342	79/07/09	50-3 S
7907160358	7907160312	79/06/18	COMMISSION
7907160364	7907160360	79/07/12	50-324 S
7907160377	7907160373	79/04/25	50-313 Q
7907160381	7907160371	79/07/13	50-324 S
7907160400	7907160392	79/07/12	50-324 S
7907160404	7907160401	79/07/10	50-244 S
7907170003	7907170001	79/07/13	50-263 R
7907170004	7907170002	79/07/11	50-280 R
7907170010	7907170007	79/07/11	50-286 R
7907170011	7907170008	79/07/13	50-312 P
7907170013	7907170009	79/07/10	50-271 P
7907170014	7907170008	79/07/13	50-312 P
7907170016	7907170012	79/07/12	50-596 C
7907170026	7907170020	79/07/10	50-261 S
7907170031	7907170025	79/07/10	50-324 R
7907170033	7907170022	79/07/12	50-305 S
7907170034	7907170029	79/07/10	50-346 S
7907170039	7907170030	79/07/11	50-333 S
7907170041	7907170036	79/07/09	50-390 S
7907170044	7907170037	79/07/12	50-255 S
7907170051	7907170045	79/07/11	50-387 A
7907170052	7907170047	79/07/10	50-334 R
7907170057	7907170054	79/08/30	50-298 R
7907170059	7907170049	79/07/09	50-348 S
7907170060	7907170060	79/07/11	50-321 S
7907170061	7907170027	79/08/30	50-298 S
7907170065	7907170063	79/08/30	50-298 S
7907170069	7907170066	79/07/09	50-321 P
7907170071	7907170049	79/07/09	50-348 S
7907170073	7907170066	79/07/09	50-321 P
7907170076	7907170068	79/08/23	50-298 P
7907170078	7907170074	79/07/10	50-10 R
7907170082	7907170079	79/06/08	50-298 S
7907170085	7907170081	79/07/10	50-305 S
7907170086	7907170084	79/07/13	50-358 K
7907170090	7907170081	79/07/10	50-305 S
7907170091	7907170087	79/07/11	50-321 S
7907170092	7907170088	79/07/09	50-336 S
7907170093	7907170068	79/05/23	50-298 P
7907170096	7907170089	79/07/10	50-366 S
7907170101	7907170098	79/07/10	50-280 S
7907170105	7907170100	79/07/06	50-366 S
7907170109	7907170068	79/05/23	50-298 P
7907170111	7907170108	79/07/08	50-334 S
7907170113	7907170107	79/07/11	50-259 S
7907170114	7907170108	79/07/08	50-334 S
7907170115	7907170112	79/07/09	50-336 S
7907170118	7907170116	79/07/12	50-309 R
7907170126	7907170120	79/07/10	50-259 P
7907170127	7907170119	79/07/13	50-302 P
7907170128	7907170123	79/07/09	50-313 P
7907170130	7907170123	79/07/09	50-327 P
7907170131	7907170124	79/07/10	50-327 A
7907170140	7907170124	79/07/10	50-327 A
7907170151	7907170147	79/07/16	50-498 K
7907170152	7907170148	79/07/12	50-271 R
7907170158	7907170117	79/06/12	50-445 M
7907170163	7907170160	79/07/10	50-266 R
7907170164	7907170158	79/07/10	50-281 S
7907170165	7907170159	79/07/13	50-269 S
7907170166	7907170157	79/07/06	50-278 S

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

503

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907170172	7907170168	79/07/12	50-29 R	7907180508	7907180506	79/07/09	50-312 R
7907170181	7907170178	79/07/10	50-295 R	7907180509	7907180504	79/07/11	50-277 S
7907170195	7907170179	79/07/10	50-250 S	7907180513	7907180496	79/07/12	50-390 S
7907170198	7907170194	79/07/10	50-298 P	7907180516	7907180511	79/07/13	50-262 R
7907170205	7907170200	79/07/11	50-296 S	7907180520	7907180519	79/07/12	50-409 R
7907170209	7907170206	79/07/10	50-321 S	7907180524	7907180518	79/07/10	50-302 S
7907170218	7907170214	79/07/03	50-321 S	7907180527	7907180525	79/07/11	50-213 R
7907170219	7907170216	79/07/10	50-366 S	7907180536	7907180531	79/07/12	50-260 S
7907170221	7907170215	79/07/12	50-338 S	7907180537	7907180530	79/07/13	50-482 S
7907170222	7907170220	79/07/09	50-321 R	7907180540	7907180534	79/07/11	TOPREP
7907170227	0407170226	79/06/20	50-272 R	7907180551	7907180545	79/07/06	50-366 S
7907170229	7907170224	79/07/13	50-336 S	7907180553	7907180548	79/07/12	50-302 S
7907170234	7907170233	79/07/09	50-298 R	7907180556	7907180544	79/07/02	50-302 S
7907170235	7907170232	79/07/11	50-320 J	7907180560	7907180554	79/05/24	50-295 Q
7907180030	7907180022	79/05/30	50-320 T	7907180563	7907180557	79/07/11	50-251 S
7907180034	7907180022	79/05/30	50-320 T	7907180570	7907180559	79/07/11	50-243 P
7907180037	7907180022	79/05/30	50-320 T	7907180574	7907180554	79/05/24	50-295 Q
7907180041	7907180022	79/05/30	50-320 T	7907180575	7907180568	79/07/12	50-267 S
7907180046	7907180022	79/05/30	50-320 T	7907180582	7907180576	79/07/11	50-348 P
7907180055	7907180022	79/05/30	50-320 T	7907180584	7907180577	79/07/17	50-285 P
7907180064	7907180061	79/06/29	50-261 P	7907180585	7907180573	79/06/14	50-272 Q
7907180068	7907180061	79/06/29	50-261 P	7907180586	7907180583	79/07/13	TOPREP
7907180102	7907180091	79/04/09	50-320 P	7907180587	7907180584	79/05/24	50-295 Q
7907180109	7907180106	79/05/19	50-320 T	7907180593	7907180577	79/07/17	50-285 P
7907180125	7907180120	79/07/11	1&E	7907180599	7907180577	79/07/17	50-285 P
7907180127	7907180113	79/06/08	50-219 Q	7907180602	7907180592	79/06/08	50-390 Q
7907180135	7907180129	79/07/13	1&E	7907180608	7907180598	79/05/16	50-358 Q
7907180143	7907180113	79/06/08	50-219 Q	7907180609	7907180577	79/07/17	50-285 P
7907180160	7907180113	79/06/08	50-219 Q	7907180613	7907180588	79/06/27	COMMISSION
7907180170	7907180198	79/06/11	50-3 P	7907180614	7907180592	79/06/08	50-390 Q
7907180221	7907180217	79/05/22	50-3 Q	7907180621	7907180577	79/07/17	50-285 P
7907180226	7907180206	79/05/30	50-382 Q	7907180622	7907180588	79/06/27	COMMISSION
7907180244	7907180233	79/05/10	50-366 Q	7907180623	7907180592	79/06/08	50-390 Q
7907180261	7907180243	79/06/01	70-754	7907180627	7907180593	79/05/16	50-358 Q
7907180265	7907180256	79/06/01	50-338 Q	7907180633	7907180588	79/06/27	50-280 U
7907180270	7907180263	79/07/02	50-346 Q	7907180640	7907180592	79/06/08	50-390 Q
7907180271	7907180256	79/06/01	50-338 Q	7907180643	7907180643	79/06/08	50-298 Q
7907180279	7907180256	79/06/01	50-338 Q	7907180658	7907180634	79/05/10	50-348 Q
7907180294	7907180274	79/05/16	50-295 Q	7907180670	7907180652	79/06/08	50-280 Q
7907180296	7907180287	79/06/15	50-346 Q	7907180673	7907180651	79/06/28	50-320 U
7907180305	7907180285	79/05/04	50-329 Q	7907180679	7907180652	79/06/08	50-280 Q
7907180319	7907180307	79/05/15	50-155 Q	7907180686	7907180652	79/06/08	50-280 Q
7907180322	7907180316	79/06/28	CONTRACT	7907180687	7907180681	79/06/15	50-272 Q
7907180323	7907180274	79/05/16	50-295 Q	7907180693	7907180692	79/05/18	50-317 P
7907180328	7907180312	79/07/09	50-335 S	7907180695	7907180652	79/06/08	50-280 Q
7907180333	7907180327	79/06/26	CONTRACT	7907180698	7907180684	79/06/12	70-820
7907180335	7907180325	79/05/18	50-315 Q	7907180709	7907180684	79/06/12	70-820
7907180349	7907180344	79/07/10	CONTRACT	7907180713	7907180696	79/06/28	50-171 U
7907180354	7907180345	79/05/18	50-315 Q	7907180719	7907180716	79/06/14	50-344 Q
7907180357	7907180336	79/05/17	50-454 Q	7907180720	7907180684	79/06/12	70-820
7907180374	7907180366	79/05/23	50-471 Q	7907180730	7907180715	79/06/29	FOIA
7907180382	7907180369	79/05/16	50-282 Q	7907180733	7907180715	79/06/29	FOIA
7907180398	7907180395	79/07/12	50-285 R	7907180734	7907180684	79/06/12	70-820
7907180399	7907180389	79/05/17	50-247 Q	7907180736	7907180721	79/06/27	50-320 U
7907180407	7907180401	79/06/19	50-220 Q	7907180742	7907180715	79/06/29	FOIA
7907180409	7907180402	79/07/10	50-133 R	7907180750	7907180715	79/06/29	FOIA
7907180411	7907180394	79/05/18	50-255 Q	7907180751	7907180721	79/06/27	50-320 U
7907180425	7907180416	79/05/10	50-331 Q	7907180755	7907180741	79/06/07	50-322 Q
7907180437	7907180430	79/05/17	50-286 Q	7907180757	7907180715	79/06/29	FOIA
7907180444	7907180442	79/07/12	50-267 S	7907180766	7907180721	79/06/27	50-320 U
7907180445	7907180441	79/05/17	50-336 Q	7907180765	7907180721	79/06/27	50-320 U
7907180449	7907180429	79/05/09	50-451 Q	7907180791	7907180549	79/05/04	50-395 Q
7907180451	7907180429	79/05/09	50-451 Q	7907180794	7907180787	79/06/25	50-338 Q
7907180452	7907180448	79/06/12	71-61	7907180801	7907180549	79/05/04	50-395 Q
7907180454	7907180453	79/06/12	71-87	7907180803	7907180787	79/06/25	50-338 Q
7907180455	7907180304	79/06/15	50-254 Q	7907180809	7907180787	79/06/25	50-338 Q
7907180459	7907180457	79/06/11	71-37	7907180816	7907180787	79/06/25	50-338 Q
7907180460	7907180456	79/05/04	50-546 Q	7907180824	7907180817	79/06/07	50-471 Q
7907180464	7907180456	79/05/04	50-546 Q	7907180827	7907180817	79/06/25	50-338 Q
7907180470	7907180466	79/07/13	50-336 R	7907180848	7907180841	79/06/12	71-5942
7907180473	7907180469	79/07/11	50-348 R	7907180860	7907180852	79/06/12	SECY
7907180474	7907180456	79/05/04	50-546 Q	7907180863	7907180857	79/06/07	50-37 P
7907180475	7907180472	79/07/05	50-289 S	7907180867	7907180857	79/06/07	50-37 P
7907180481	7907180476	79/07/13	50-269 R	7907180869	7907180852	79/06/12	SECY
7907180482	7907180477	79/07/06	50-289 S	7907180884	7907180876	79/06/05	50-346 P
7907180483	7907180471	79/05/16	50-247 Q	7907180889	7907180876	79/06/05	50-346 P
7907180488	7907180485	79/07/13	50-269 S	7907180893	7907180876	79/06/05	50-346 P
7907180491	7907180484	79/07/10	50-390 S	7907180895	7907180878	79/06/06	50-443 Q
7907180494	7907180490	79/07/13	50-3 R	7907180900	7907180877	79/06/12	XPORTLIC
7907180499	7907180498	79/07/06	50-321 R	7907190011	7907190006	79/06/14	50-387 Q
7907180500	7907180492	79/05/15	50-295 Q	7907190012	7907190009	79/05/29	SECY
7907180501	7907180497	79/07/11	50-390 S	7907190014	7907190008	79/06/05	50-437 A
7907180505	7907180500	79/07/13	50-270 S				

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

504

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907190016	7907190006	79/06/14	50-387 Q
7907190019	7907190006	79/06/14	50-387 Q
7907190021	7907190017	79/05/30	71-31
7907190029	7907190006	79/06/14	50-387 Q
7907190030	7907190026	79/05/30	71-4949
7907190035	7907190033	79/06/21	50-329 GRP
7907190046	7907190039	79/06/21	50-329 A
7907190049	7907190038	79/05/31	50-298 Q
7907190055	7907190048	79/05/22	50-309 H
7907190061	7907190050	79/06/06	50-280 Q
7907190065	7907190058	79/06/05	70-2623
7907190066	7907190050	79/06/06	50-280 Q
7907190070	7907190050	79/06/06	50-280 Q
7907190073	7907190042	79/04/29	50-10 Q
7907190078	7907190050	79/06/06	50-280 Q
7907190079	7907190075	79/06/05	50-309 H
7907190082	7907190025	79/06/11	50-309 H
7907190092	7907190086	79/06/14	50-341 Q
7907190093	7907190081	79/05/31	40-299
7907190095	7907190085	79/06/08	50-321 Q
7907190103	7907190085	79/06/08	50-321 Q
7907190105	7907190096	79/05/31	50-313 P
7907190108	7907190101	79/06/11	50-361 Q
7907190110	7907190085	79/06/08	50-321 Q
7907190121	7907190085	79/06/08	50-321 Q
7907190130	7907190124	79/06/13	50-498 H
7907190131	7907190126	79/06/08	50-286 P
7907190132	7907190120	79/06/07	50-413 Q
7907190133	7907190117	79/03/05	50-334 P
7907190134	7907190127	79/06/08	50-358 Q
7907190135	7907190129	79/06/08	50-409 Q
7907190136	7907190127	79/06/08	50-358 Q
7907190137	7907190120	79/06/07	50-413 Q
7907190143	7907190120	79/06/07	50-413 Q
7907190149	7907190120	79/06/07	50-413 Q
7907190152	7907190127	79/06/08	50-358 Q
7907190158	7907190127	79/06/08	50-358 Q
7907190160	7907190155	79/06/07	50-352 A
7907190167	7907190155	79/06/12	50-237 F
7907190194	7907190183	79/07/06	FOIA
7907190199	7907190183	79/07/06	FOIA
7907190202	7907190183	79/07/06	FOIA
7907190214	7907190210	79/04/12	50-16 P
7907190215	7907190208	79/06/05	50-437 Q
7907190219	7907190210	79/04/12	50-16 P
7907190220	7907190208	79/06/05	50-437 Q
7907190225	7907190221	79/07/09	50-16 P
7907190231	7907190221	79/07/09	50-16 P
7907190235	7907190221	79/07/09	50-16 P
7907190242	7907190221	79/07/09	50-16 P
7907190246	7907190221	79/07/09	50-16 Q
7907190284	7907190275	79/06/20	50-320 Q
7907190286	7907190279	79/06/11	71-95
7907190298	7907190292	79/06/21	50-320 Q
7907190303	7907190287	79/06/14	50-416 Q
7907190307	7907190287	79/06/14	50-416 Q
7907190313	7907190287	79/06/14	50-416 Q
7907190319	7907190287	79/06/14	50-416 Q
7907190324	7907190318	79/06/14	50-522 Q
7907190357	7907190342	79/07/16	TOPREP
7907190358	7907190350	79/06/05	40-8584
7907190370	7907190366	79/05/08	50-344 Q
7907190375	7907190366	79/05/08	50-344 Q
7907190382	7907190373	79/07/16	50-324 S
7907190388	7907190385	79/07/11	50-313 R
7907190445	7907190440	79/07/16	50-302 R
7907190452	7907190020	79/06/06	50-309 H
7907190482	7907190475	79/07/12	50-295 F
7907190484	7907190478	79/05/17	50-224 Q
7907190487	7907190480	79/07/06	50-325 S
7907190497	7907190492	79/05/14	50-10 Q
7907190507	7907190492	79/05/14	50-10 Q
7907190520	7907190515	79/07/13	50-315 S
7907190524	7907190523	79/06/20	50-416 S
7907190525	7907190522	79/07/16	50-293 S
7907190530	7907190528	79/07/10	50-302 F
7907190533	7907190526	79/05/08	70-2623
7907190534	7907190531	79/07/16	50-324 S
7907190537	7907190532	79/07/13	50-316 S
7907190540	7907190536	79/07/16	50-155 P
7907190544	7907190541	79/07/11	50-368 R
7907190547	7907190542	79/07/13	50-568 Q
7907190550	7907190535	79/07/16	50-155 P

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907190551	7907190549	79/07/12	50-206 P
7907190558	7907190556	79/07/17	50-339 A
7907190560	7907190555	79/07/13	50-308 P
7907190570	7907190563	79/07/16	50-237 P
7907190574	7907190571	79/07/14	50-331 R
7907190577	7907190572	79/05/22	71-3
7907190581	7907190568	79/07/13	50-289 F
7907190587	7907190582	79/06/11	50-471 Q
7907190600	7907190590	79/07/17	50-344 F
7907190604	7907190601	79/06/20	71-304
7907190613	7907190610	79/06/20	71-306
7907190614	7907190609	79/06/07	50-247 P
7907190620	7907190609	79/06/07	50-247 P
7907190623	7907190609	79/06/07	50-247 P
7907190631	7907190643	79/06/08	50-471 Q
7907190632	7907190647	79/06/11	50-348 P
7907190636	7907190647	79/06/11	50-348 P
7907190661	7907190647	79/06/11	50-348 P
7907190664	7907190658	79/06/06	50-466 Q
7907190666	7907190660	79/06/14	70-1308
7907190671	7907190658	79/06/06	50-466 Q
7907190727	7907190718	79/04/27	50-201 R
7907190736	7907190658	79/06/06	50-466 Q
7907190738	7907190650	79/06/14	50-471 Q
7907190742	7907190732	79/05/08	0A999
7907190744	7907190739	79/05/29	40-4492
7907190765	7907190755	79/05/31	CONTRACT
7907190768	7907190760	79/06/11	50-309 H
7907190784	7907190716	79/06/15	50-599 Q
7907190786	7907190777	79/05/31	CONTRACT
7907190812	7907190795	79/05/31	CONTRACT
7907190845	7907190842	79/05/24	50-409 Q
7907190846	7907190834	79/06/26	50-445 M
7907190852	7907190818	79/06/27	REGOOD
7907190855	7907190843	79/06/25	XPORTRIC
7907190862	7907190854	79/06/15	CONTRACT
7907190865	7907190851	79/06/01	40-8616
7907200046	7907200039	79/06/27	70-1113
7907200049	7907200039	79/06/27	70-1113
7907200054	7907200039	79/06/27	70-1113
7907200064	7907200059	79/06/28	70-1113
7907200070	7907200059	79/06/28	70-1113
7907200074	7907200059	79/06/28	70-1113
7907200145	7907200122	79/05/10	50-516 Q
7907200203	7907200185	79/05/22	50-237 Q
7907200220	7907200213	79/04/25	50-192 Q
7907200224	7907200211	79/06/28	50-269 P
7907200234	7907200233	79/05/10	70-27
7907200241	7907200225	79/05/11	50-83 Q
7907200250	7907200244	79/05/09	50-348 Q
7907200252	7907200251	79/07/12	50-293 R
7907200253	7907200247	79/06/26	50-488 Q
7907200259	7907200256	79/07/16	50-245 R
7907200262	7907200260	79/07/13	50-298 P
7907200267	7907200264	79/07/12	50-267 P
7907200290	7907200278	79/05/09	50-281 Q
7907200293	7907200288	79/07/16	TOPREP
7907200305	7907200299	79/07/11	TOPREP
7907200321	7907200317	79/07/11	50-315 R
7907200333	7907200329	79/07/11	50-316 R
7907200341	7907200337	79/07/13	50-321 P
7907200373	7907200366	79/07/13	50-331 S
7907200384	7907200378	79/07/13	50-155 S
7907200400	7907200395	79/06/18	50-57 Q
7907200401	7907200389	79/07/10	50-247 S
7907200406	7907200395	79/06/18	50-57 Q
7907200409	7907200403	79/07/13	50-318 S
7907200411	7907200404	79/08/07	50-280 Q
7907200415	7907200410	79/07/16	50-318 S
7907200416	7907200395	79/06/18	50-57 Q
7907200420	7907200395	79/06/18	50-57 Q
7907200444	7907200431	79/06/19	50-293 Q
7907200453	7907200431	79/06/19	50-293 Q
7907200460	7907200431	79/06/19	50-293 Q
7907200469	7907200431	79/07/18	50-334 P
7907200476	7907200472	79/07/05	50-320 H
7907200479	7907200457	79/07/05	50-320 H
7907200484	7907200477	79/06/18	50-387 Q
7907200490	7907200485	79/05/17	70-620
7907200491	7907200477	79/06/18	50-387 Q
7907200496	7907200477	79/06/18	50-387 Q
7907200503	7907200477	79/06/18	50-387 Q
7907200504	7907200501	79/05/31	50-289 Q



# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

505

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907230002	7907230001	79/06/28	50-250 Q	7907230363	7907230359	79/07/17	50-269 S
7907230006	7907230003	79/06/25	50-387 Q	7907230364	7907230364	79/05/29	50-295 Q
7907230008	7907230005	79/06/21	50-311 Q	7907230374	7907230350	79/07/16	50-495 K
7907230009	7907230007	79/06/11	71-80	7907230440	7907230342	79/06/18	50-352 Q
				7907230442	7907230342	79/06/18	50-352 Q
7907230011	7907230005	79/06/21	50-311 Q				
7907230014	7907230012	79/06/20	50-338 Q	7907230444	7907230342	79/06/18	50-352 Q
7907230015	7907230005	79/06/21	50-311 Q	7907230449	7907230447	79/07/06	50-293 P
7907230018	7907230012	79/06/20	50-338 Q	7907230452	7907230060	79/06/18	50-412 Q
7907230023	7907230005	79/06/21	50-311 Q	7907230453	7907230060	79/06/18	50-412 Q
				7907230473	7907230467	79/07/12	50-366 S
7907230024	7907230012	79/06/20	50-338 Q				
7907230025	7907230019	79/06/29	71-216	7907230479	7907230471	79/05/02	50-220 Q
7907230033	7907230028	79/06/11	71-120	7907230482	7907230480	79/07/10	50-366 S
7907230036	7907230030	79/06/29	71-217	7907230486	7907230477	79/07/13	50-366 S
7907230038	7907230029	79/06/22	50-220 Q	7907230487	7907230474	79/07/18	50-336 S
				7907230488	7907230493	79/05/11	50-339 Q
7907230039	7907230012	79/06/20	50-338 Q				
7907230044	7907230029	79/06/22	50-220 Q	7907230493	7907230481	79/06/01	50-244 Q
7907230047	7907230042	79/06/29	71-225	7907230496	7907230492	79/06/27	71-6581
7907230049	7907230037	79/06/11	71-113	7907230497	7907230494	79/07/20	50-333 P
7907230051	7907230029	79/06/22	50-220 Q	7907230499	7907230492	79/06/27	71-6581
				7907230502	7907230495	79/06/22	50-269 P
7907230052	7907230046	79/06/05	XPORTLIC				
7907230057	7907230029	79/06/22	50-220 Q	7907230504	7907230492	79/06/27	71-6581
7907230059	7907230055	79/06/15	QA999	7907230505	7907230498	79/06/14	70-27
7907230061	7907230055	79/06/15	QA999	7907230511	7907230492	79/06/27	71-6581
7907230067	7907230055	79/06/15	QA999	7907230515	7907230498	79/06/14	70-27
				7907230517	7907230495	79/06/22	50-269 P
7907230069	7907230054	79/06/11	71-123				
7907230074	7907230055	79/06/15	QA999	7907230519	7907230516	79/07/18	50-366 S
7907230080	7907230071	79/06/22	50-389 Q	7907230523	7907230495	79/06/14	70-27
7907230099	7907230096	79/06/20	71-319	7907230532	7907230495	79/06/22	50-269 P
7907230107	7907230089	79/06/18	70-938	7907230541	7907230539	79/07/12	50-321 S
				7907230543	7907230533	79/07/16	50-265 S
7907230111	7907230104	79/06/20	71-294				
7907230113	7907230089	79/06/18	70-938	7907230553	7907230546	79/07/13	50-366 S
				7907230557	7907230549	79/04/27	50-272 Q
7907230118	7907230089	79/06/18	70-938				
7907230120	7907230115	79/06/20	71-284	7907230559	7907230555	79/07/17	50-331 S
7907230128	7907230089	79/05/18	70-938	7907230563	7907230551	79/07/18	50-324 S
7907230130	7907230126	79/06/20	71-320	7907230565	7907230584	79/07/06	COMMISSION
7907230146	7907230140	79/06/18	XPORTLIC	7907230570	7907230549	79/04/27	50-272 Q
				7907230572	7907230558	79/06/14	50-387 Q
7907230151	7907230077	79/07/19	50-220 P				
7907230159	7907230154	79/06/20	71-298	7907230576	7907230571	79/07/20	50-338 S
7907230173	7907230158	79/07/20	50-454 K	7907230579	7907230558	79/06/14	50-387 Q
7907230174	7907230170	79/07/05	50-320 P	7907230580	7907230571	79/07/20	50-338 S
7907230180	7907230178	79/07/06	COMMISSION	7907230585	7907230558	79/06/14	50-387 Q
				7907230586	7907230554	79/07/06	COMMISSION
7907230191	7907230187	79/07/10	COMMISSION				
7907230196	7907230188	79/06/04	RECY	7907230598	7907230588	79/06/14	50-387 Q
7907230198	7907230187	79/07/10	COMMISSION	7907230611	7907230554	79/07/06	COMMISSION
7907230201	7907230187	79/07/10	COMMISSION	7907230615	7907230607	79/06/19	70-143
7907230208	7907230186	79/05/29	50-295 Q	7907230618	7907230588	79/07/18	50-324 S
				7907230619	7907230554	79/07/06	COMMISSION
7907230209	7907230195	79/07/11	50-366 K				
7907230213	7907230186	79/05/27	50-295 Q	7907230623	7907230607	79/06/19	70-143
7907230225	7907230214	79/06/11	71-28	7907230630	7907230622	79/06/11	71-11
7907230226	7907230186	79/05/27	50-295 Q	7907230633	7907230626	79/07/16	50-320 P
7907230229	7907230223	79/03/12	FOIA	7907230635	7907230627	79/07/06	COMMISSION
				7907230639	7907230634	79/06/11	71-34
7907230233	7907230224	79/07/19	50-244 P				
7907230235	7907230223	79/03/27	FOIA	7907230640	7907230607	79/06/19	70-143
7907230239	7907230186	79/05/29	50-295 Q	7907230652	7907230607	79/06/19	70-143
7907230246	7907230241	79/07/06	50-201 P	7907230653	7907230645	79/06/11	71-150
7907230248	7907230237	79/06/11	71-145	7907230658	7907230655	79/06/11	71-32
				7907230660	7907230657	79/06/08	COMMISSION
7907230250	7907230241	79/07/06	50-201 P				
7907230255	7907230251	79/06/13	71-4949	7907230666	7907230662	79/06/11	71-35
7907230266	7907230262	79/06/20	71-314	7907230680	7907230673	79/06/11	71-37
7907230267	7907230258	79/06/11	71-81	7907230686	7907230692	79/06/29	71-162
7907230268	7907230186	79/05/29	50-295 Q	7907230699	7907230694	79/05/23	CONTRACT
				7907230707	7907230060	79/06/18	50-412 Q
7907230272	7907230269	79/06/20	71-307				
7907230274	7907230271	79/07/15	50-317 R	7907230713	7907230705	79/05/10	CONTRACT
7907230276	7907230186	79/05/29	50-295 Q	7907230721	7907230711	79/06/26	50-302 Q
7907230281	7907230279	79/06/20	71-305	7907230722	7907230719	79/07/12	CONTRACT
7907230283	7907230278	79/06/11	71-47	7907230724	7907230708	79/05/16	50-280 Q
				7907230727	7907230060	79/06/18	50-412 Q
7907230291	7907230286	79/06/18	QA999				
7907230292	7907230287	79/07/20	50-333 S	7907230736	7907230730	79/05/25	QA999
7907230297	7907230286	79/06/18	QA999	7907230740	7907230734	79/05/16	50-338 Q
7907230300	7907230293	79/06/11	71-59	7907230746	7907230741	79/05/30	50-456 Q
7907230302	7907230286	79/06/18	QA999	7907230752	7907230739	79/06/19	50-280 U
				7907230757	7907230739	79/06/19	50-280 U
7907230308	7907230286	79/06/18	QA999				
7907230319	7907230309	79/06/20	71-326	7907230763	7907230748	79/06/18	50-289 Q
				7907230768	7907230755	79/05/14	50-390 Q
7907230320	7907230315	79/07/18	50-325 S				
7907230331	7907230326	79/06/20	71-322	7907230771	7907230743	79/06/01	27-39
7907230343	7907230325	79/07/19	50-325 S	7907230775	7907230748	79/06/18	50-259 Q
7907230345	7907230186	79/05/29	50-295 Q	7907230782	7907230776	79/06/11	71-105
7907230348	7907230342	79/06/18	50-352 Q	7907230784	7907230748	79/06/18	50-259 Q
				7907230789	7907230786	79/06/11	71-104
7907230351	7907230186	79/05/29	50-295 Q				
7907230354	7907230349	79/07/16	50-313 S	7907230790	7907230748	79/06/18	50-259 Q
7907230355	7907230347	79/06/08	50-482 Q	7907230792	7907230787	79/06/11	71-103
7907230356	7907230186	79/05/29	50-295 Q	7907240014	7907240009	79/06/29	71-15
7907230361	7907230186	79/05/29	50-295 Q	7907240020	7907240004	79/06/19	50-250 Q
				7907240023	7907240018	79/06/29	71-218

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

506

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7907240027	7907240004	79/06/19	50-250	Q	7907240380	7907240374	79/06/11	50-220	P
7907240034	7907240028	79/06/27	71-219		7907240381	7907240311	79/05/24	REG00	
7907240037	7907240032	79/06/27	71-226		7907240382	7907240374	79/06/11	50-220	P
7907240040	7907240038	79/06/27	71-184		7907240384	7907240311	79/05/24	REG00	
7907240044	7907240042	79/06/27	71-166		7907240388	7907240311	79/05/21	REG00	
7907240049	7907240046	79/06/27	71-168		7907240391	7907240383	79/05/14	50-370	Q
7907240055	7907240004	79/06/19	50-250	Q	7907240392	7907240387	79/06/05	50-263	P
7907240070	7907240004	79/06/19	50-250	Q	7907240395	7907240311	79/05/24	REG00	
7907240078	7907240064	79/06/27	50-373	Q	7907240396	7907240387	79/06/05	50-263	P
7907240099	7907240064	79/06/18	50-318	Q	7907240397	7907240389	79/07/13	50-247	S
7907240100	7907240093	79/06/25	50-336	P	7907240406	7907240311	78/05/24	REG00	
7907240101	7907240093	79/06/25	50-336	P	7907240411	7907240403	79/06/12	50-247	P
7907240105	7907240093	79/06/25	50-336	P	7907240412	7907240311	79/08/24	REG00	
7907240110	7907240107	79/06/11	71-127		7907240413	7907240400	79/06/15	50-324	Q
7907240112	7907240106	79/05/29	50-301	Q	7907240415	7907240403	79/06/12	50-247	P
7907240118	7907240051	79/06/08	50-382	Q	7907240418	7907240403	79/06/12	50-247	P
7907240123	7907240119	79/05/14	50-338	Q	7907240419	7907240311	79/05/24	REG00	
7907240125	7907240047	79/06/08	50-498	Q	7907240420	7907240400	79/06/15	50-324	Q
7907240127	7907240124	79/06/01	50-373	Q	7907240423	7907240417	79/06/29	50-471	Q
7907240129	7907240122	79/05/24	50-327	Q	7907240426	7907240311	79/05/24	REG00	
7907240138	7907240134	79/05/31	50-237	Q	7907240429	7907240400	79/06/15	50-324	Q
7907240148	7907240132	79/05/25	50-553	Q	7907240437	7907240400	79/06/15	50-324	Q
7907240152	7907240144	79/06/01	50-266	Q	7907240440	7907240431	79/05/14	50-471	D
7907240163	7907240155	79/05/25	50-369	Q	7907240446	7907240431	79/05/14	50-471	D
7907240164	7907240156	79/06/01	50-329	Q	7907240452	7907240400	79/06/15	50-324	Q
7907240172	7907240169	79/05/30	50-546	Q	7907240456	7907240449	79/06/05	50-267	P
7907240184	7907240170	79/05/23	50-250	Q	7907240491	7907240472	79/06/05	27-39	
7907240186	7907240181	79/05/21	50-438	Q	7907240493	7907240480	79/06/12	50-315	P
7907240191	7907240187	79/05/27	50-409	Q	7907240503	7907240462	79/06/01	50-466	Q
7907240192	7907240189	79/05/21	50-339	Q	7907240508	7907240499	79/06/11	71-110	
7907240200	7907240195	79/05/30	50-282	Q	7907240512	7907240462	79/06/01	50-466	Q
7907240201	7907240197	79/05/23	50-390	Q	7907240522	7907240513	79/06/11	71-148	
7907240209	7907240205	79/06/26	XP0RTLIC		7907240531	7907240524	79/06/11	71-140	
7907240212	7907240204	79/06/18	50-443	Q	7907240543	7907240537	79/06/11	71-119	
7907240215	7907240210	79/06/12	50-400	Q	7907240549	7907240573	79/06/13	50-129	P
7907240216	7907240204	79/06/18	50-443	Q	7907240561	7907240553	79/06/11	71-132	
7907240218	7907240213	79/06/21	XP0RTLIC		7907240563	7907240387	79/06/05	50-263	P
7907240219	7907240210	79/06/12	50-400	Q	7907240571	7907240566	79/06/11	71-134	
7907240220	7907240204	79/06/18	50-443	Q	7907240578	7907240573	79/06/13	50-129	P
7907240222	7907240204	79/06/18	50-443	Q	7907240580	7907240577	79/06/11	71-130	
7907240225	7907240210	79/06/12	50-400	Q	7907240590	7907240584	79/06/11	71-75	
7907240227	7907240210	79/06/12	50-400	Q	7907240597	7907240589	79/06/07	50-272	P
7907240236	7907240228	79/06/27	71-153		7907240601	7907240595	79/06/11	71-76	
7907240243	7907240239	79/06/25	50-272	Q	7907240603	7907240589	79/06/07	50-272	P
7907240256	7907240247	79/06/11	71-77		7907240615	7907240609	79/05/25	50-334	Q
7907240262	7907240261	79/06/28	QA999		7907240627	7907240616	79/05/25	50-293	Q
7907240263	7907240261	79/06/28	QA999		7907240630	7907240623	79/05/31	50-305	Q
7907240264	7907240261	79/06/28	QA999		7907250023	7907250019	79/06/29	71-161	
7907240265	7907240261	79/06/28	QA999		7907250029	7907250027	79/06/29	71-22	
7907240267	7907240266	79/06/05	50-294	Q	7907250039	7907250037	79/05/15	50-272	H
7907240269	7907240268	79/06/26	50-424	Q	7907250061	7907250051	79/06/12	50-368	P
7907240270	7907240259	79/06/18	50-424	Q	7907250072	7907250051	79/06/12	50-368	P
7907240272	7907240259	79/06/18	50-424	Q	7907250079	7907250076	79/03/30	50-266	Q
7907240274	7907240273	79/07/02	50-10	Q	7907250080	7907250051	79/06/12	50-368	P
7907240275	7907240259	79/06/18	50-424	Q	7907250082	7907250077	79/06/27	50-440	Q
7907240277	7907240223	79/06/21	XP0RTLIC		7907250083	7907250076	79/03/30	50-266	Q
7907240278	7907240259	79/06/18	50-424	Q	7907250093	7907250098	79/06/25	50-277	Q
7907240279	7907240276	79/05/22	50-280	Q	7907250102	7907250098	79/03/02	QA999	
7907240283	7907240285	79/06/30	50-272	Q	7907250103	7907250100	79/06/22	50-348	Q
7907240284	7907240280	79/06/21	XP0RTLIC		7907250106	7907250100	79/06/22	50-348	Q
7907240285	7907240289	79/06/18	50-424	Q	7907250110	7907250107	79/06/15	50-277	P
7907240286	7907240282	79/06/06	CONTRACT		7907250115	7907250107	79/06/15	50-277	P
7907240291	7907240255	79/06/30	50-272	Q	7907250116	7907250107	79/06/15	50-277	P
7907240297	7907240296	79/05/16	70-33		7907250117	7907250112	79/06/15	50-331	P
7907240303	7907240298	79/05/22	50-587	Q	7907250118	7907250112	79/06/15	50-331	P
7907240317	7907240314	79/06/27	50-471	Q	7907250120	7907250121	79/06/13	CONTRACT	
7907240320	7907240313	79/07/18	50-397	S	7907250124	7907250127	79/03/14	CONTRACT	
7907240326	7907240315	79/07/18	50-397	S	7907250147	7907250143	79/03/24	50-335	Q
7907240328	7907240324	79/07/18	50-155	Q	7907250154	7907250149	79/05/21	QA999	
7907240347	7907240337	79/05/14	50-339	Q	7907250173	7907250171	79/06/05	CONMISSION	
7907240349	7907240346	79/07/19	50-382	K	7907250175	7907250157	79/03/31	50-250	U
7907240350	7907240342	79/06/26	50-272	Q	7907250184	7907250157	79/03/31	50-250	U
7907240353	7907240348	79/07/19	50-261	S	7907250192	7907250190	79/06/03	QA999	
7907240363	7907240357	79/07/16	50-325	S	7907250195	7907250190	79/06/03	QA999	
7907240367	7907240359	79/07/19	50-348	S	7907250196	7907250190	79/06/03	QA999	
7907240368	7907240311	79/05/24	REG00		7907250197	7907250190	79/06/03	QA999	
7907240371	7907240366	79/07/19	50-324	S	7907250209	7907250206	79/06/06	50-255	Q
7907240372	7907240311	79/08/24	REG00		7907250211	7907250206	79/06/06	50-255	Q
7907240376	7907240359	79/07/19	50-348	S	7907250213	7907250212	79/03/30	50-483	Q
7907240377	7907240311	79/05/24	REG00		7907250216	7907250212	79/03/30	50-483	Q
7907240378	7907240374	79/06/11	50-220	P	7907250222	7907250221	79/06/07	50-482	Q
7907240379	7907240359	79/07/19	50-348	S	7907250226	7907250221	79/06/07	50-482	Q

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

507

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907250231	7907250230	79/06/29	CONTRACT
7907250233	7907250232	79/06/01	CONTRACT
7907250240	7907250238	79/06/29	EXPORTLIC
7907250246	7907250244	79/06/13	71-3
7907250268	7907250253	79/07/19	50-316 B
7907250277	7907250267	79/07/03	50-264 B
7907250281	7907250274	79/07/13	50-295 B
7907250282	7907250270	79/06/03	50-409 Q
7907250283	7907250264	79/07/13	50-265 B
7907250291	7907250284	79/07/13	50-10 B
7907250298	7907250292	79/07/19	50-317 B
7907250301	7907250290	79/06/05	50-373 Q
7907250304	7907250300	79/07/19	50-318 B
7907250312	7907250308	79/06/15	50-244 P
7907250313	7907250297	79/07/05	50-265 B
7907250314	7907250310	79/07/16	50-397 B
7907250317	7907250306	79/07/18	50-327 A
7907250319	7907250308	79/06/15	50-244 P
7907250322	7907250308	79/06/15	50-244 P
7907250329	7907250325	79/07/20	50-329 B
7907250331	7907250324	79/07/17	50-327 A
7907250334	7907250328	79/06/22	QA999
7907250339	7907250328	79/06/22	QA999
7907250341	7907250335	79/07/13	50-335 B
7907250347	7907250328	79/06/22	QA999
7907250354	7907250350	79/07/13	50-219 R
7907250355	7907250328	79/06/22	QA999
7907250360	7907250328	79/06/22	QA999
7907250362	7907250353	79/07/19	50-244 P
7907250367	7907250328	79/06/22	QA999
7907250372	7907250364	79/07/19	50-249 B
7907250378	7907250366	79/07/13	50-254 B
7907250382	7907250375	79/07/17	50-311 E
7907250393	7907250384	79/06/29	71-310
7907250395	7907250392	79/07/20	TOPREP
7907250400	7907250397	79/06/29	71-281
7907250402	7907250398	79/07/09	FOIA
7907250405	7907250399	79/06/04	48-8729
7907250407	7907250398	79/07/09	FOIA
7907250412	7907250399	79/06/04	48-8729
7907250415	7907250398	79/07/09	FOIA
7907250426	7907250423	79/06/29	71-137
7907250428	7907250421	79/06/01	50-437 Q
7907250435	7907250398	79/07/09	FOIA
7907250443	7907250436	79/05/15	50-440 Q
7907250452	7907250436	79/05/15	50-440 Q
7907250454	7907250434	79/06/11	50-391 Q
7907250458	7907250449	1/79/04	50-320 P
7907250463	7907250459	79/07/03	71-334
7907250468	7907250462	79/04/26	50-261 Q
7907250470	7907250398	79/07/09	FOIA
7907250480	7907250475	79/06/04	70-2623
7907250481	7907250398	79/07/09	FOIA
7907250485	7907250475	79/06/04	70-2623
7907250488	7907250479	79/06/04	50-482 Q
7907250489	7907250483	79/04/10	50-352 A
7907250491	7907250475	79/06/04	70-2623
7907250497	7907250475	79/06/04	70-2623
7907250500	7907250398	79/07/09	FOIA
7907250507	7907250475	79/06/04	70-2623
7907250512	7907250398	79/07/09	FOIA
7907250518	7907250498	79/06/01	50-445 Q
7907250519	7907250475	79/06/04	70-2623
7907250524	7907250398	79/07/09	FOIA
7907250533	7907250528	79/06/14	50-293 Q
7907250537	7907250398	79/07/09	FOIA
7907250543	7907250535	79/06/15	50-250 P
7907250549	7907250535	79/06/15	50-250 P
7907250552	7907250398	79/07/09	FOIA
7907250553	7907250548	79/06/07	QA999
7907250557	7907250535	79/06/15	50-250 P
7907250561	7907250558	79/06/12	QA999
7907250562	7907250556	79/07/11	FOIA
7907250567	7907250556	79/07/11	FOIA
7907250569	7907250563	79/06/28	QA999
7907250571	7907250564	79/06/14	50-338 P
7907250573	7907250564	79/07/11	FOIA
7907250578	7907250564	79/06/14	50-338 P
7907250581	7907250564	79/06/14	50-338 A
7907250582	7907250556	79/07/11	27-47
7907250583	7907250576	79/06/29	50-295 Q
7907250586	7907250556	79/07/11	FOIA
7907250592	7907250556	79/07/11	FOIA

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907250594	7907250590	79/06/01	CONTRACT
7907250595	7907250589	79/06/19	50-269 P
7907250599	7907250556	79/07/11	FOIA
7907250600	7907250589	79/06/19	50-269 P
7907250601	7907250589	79/06/19	50-269 P
7907250606	7907250589	79/06/19	50-269 P
7907260005	7907260004	79/05/18	50-280 Q
7907260007	7907260004	79/05/18	50-280 Q
7907260017	7907260006	79/07/06	50-440 Q
7907260023	7907260004	79/05/18	50-281 Q
7907260027	7907260024	79/06/04	CONTRACT
7907260029	7907260010	79/06/28	QA999
7907260045	7907260010	79/06/28	QA999
7907260050	7907260009	79/06/19	50-309 U
7907260062	7907260055	79/06/26	50-287 Q
7907260065	7907260059	79/06/13	50-313 U
7907260076	7907260055	79/06/26	50-287 Q
7907260081	7907260010	79/06/28	QA999
7907260088	7907260068	79/06/22	50-344 P
7907260090	7907260010	79/06/28	QA999
7907260091	7907260082	79/06/04	50-448 U
7907260092	7907260084	79/06/14	50-317 P
7907260094	7907260068	79/06/22	50-344 P
7907260096	7907260084	79/06/14	50-317 P
7907260102	7907260068	79/06/22	50-344 P
7907260105	7907260084	79/06/14	50-317 P
7907260116	7907260100	79/06/21	QA999
7907260127	7907260062	79/06/04	50-445 U
7907260128	7907260121	79/06/19	50-596 Q
7907260130	7907260100	79/06/21	QA999
7907260138	7907260100	79/06/21	QA999
7907260139	7907260131	79/06/26	50-329 Q
7907260142	7907260133	79/03/30	50-553 Q
7907260144	7907260100	79/06/21	QA999
7907260147	7907260100	79/06/21	QA999
7907260149	7907260143	79/06/06	50-267 P
7907260151	7907260145	79/05/30	50-395 Q
7907260155	7907260143	79/05/06	50-267 P
7907260158	7907260100	79/06/21	QA999
7907260167	7907260160	79/06/07	50-341 Q
7907260195	7907260177	79/06/21	50-315 P
7907260196	7907260182	79/06/07	50-329 Q
7907260208	7907260177	79/06/21	50-315 P
7907260230	7907260177	79/06/21	50-315 P
7907260240	7907260223	79/06/07	50-10 Q
7907260259	7907260246	79/06/13	PROJ
7907260264	7907260252	79/06/05	50-409 Q
7907260281	7907260272	79/06/29	50-186 Q
7907260300	7907260250	79/03/08	50-155 Q
7907260346	7907260341	79/06/29	71-74
7907260355	7907260350	79/06/29	71-39
7907260364	7907260361	79/06/29	71-205
7907260368	7907260358	79/06/07	50-255 U
7907260373	7907260370	79/06/29	71-157
7907260380	7907260377	79/06/12	CONTRACT
7907260386	7907260379	79/06/29	71-156
7907260390	7907260388	79/06/18	50-272 Q
7907260396	7907260388	79/06/18	50-272 Q
7907260403	7907260388	79/06/18	50-272 Q
7907260411	7907260401	79/06/29	71-152
7907260412	7907260388	79/06/18	50-272 Q
7907260428	7907260421	79/06/29	71-154
7907260431	7907260388	79/06/18	50-272 Q
7907260439	7907260432	79/06/29	71-151
7907260449	7907260442	79/07/25	50-320 P
7907260453	7907260442	79/07/25	50-320 P
7907260454	7907260446	79/06/29	71-133
7907260458	7907260442	79/07/25	50-320 P
7907260464	7907260451	79/06/01	COMMISSION
7907260466	7907260442	79/07/25	50-320 P
7907260467	7907260460	79/07/18	50-400 A
7907260469	7907260465	79/06/29	71-89
7907260473	7907260451	79/06/01	COMMISSION
7907260482	7907260451	79/06/01	COMMISSION
7907260485	7907260477	79/06/04	50-498 Q
7907260486	7907260481	79/06/29	50-409 F
7907260491	7907260451	79/06/01	COMMISSION
7907260492	7907260477	79/06/04	50-498 Q
7907260496	7907260451	79/06/01	COMMISSION
7907260506	7907260495	79/07/03	50-348 Q
7907260508	7907260502	79/03/29	50-250 Q
7907260513	7907260451	79/06/01	COMMISSION
7907260515	7907260511	79/07/20	50-397 A

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

508

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907260517	7907260495	79/07/03	50-348 G	7907270195	7907270187	79/07/23	50-366 P
7907260521	7907260451	79/06/01	COMMISSION	7907270198	7907270189	79/06/18	50-295 P
7907260522	7907260516	79/05/31	50-395 G	7907270202	7907270170	79/07/20	50-219 S
7907260524	7907260524	79/05/07	50-301 G	7907270204	7907270189	79/06/18	50-295 P
7907260534	7907260528	79/06/01	50-206 G	7907270217	7907270210	79/06/05	COMMISSION
7907260538	7907260532	79/05/30	50-327 G	7907270220	7907270210	79/06/05	COMMISSION
7907260542	7907260495	79/07/03	50-348 G	7907270221	7907270206	79/07/20	50-277 S
7907260549	7907260543	79/05/25	50-275 G	7907270237	7907270235	79/07/23	50-3 J
7907260557	7907260554	79/05/25	50-397 G	7907270264	7907270262	79/06/13	50-409 O
7907260561	7907260559	79/06/08	50-445 G	7907270275	7907270269	79/07/20	50-320 P
7907260571	7907260569	79/06/01	COMMISSION	7907270276	7907270270	79/05/21	50-344 G
7907260578	7907260576	79/07/17	50-409 I	7907270280	7907270268	79/06/14	50-275 G
7907260581	7907260579	79/06/06	50-20 P	7907270284	7907270281	79/05/29	50-397 A
7907260583	7907260580	79/07/23	50-592 O	7907270290	7907270287	79/06/14	50-397 G
7907260584	7907050357	79/06/21	TOPREP	7907270291	7907270288	79/07/03	50-482 G
7907260586	7907260582	79/07/20	50-272 S	7907270305	7907270294	79/07/05	50-445 G
7907260592	7907260587	79/07/18	50-336 S	7907270306	7907270296	79/06/21	50-508 G
7907260593	7907260587	79/07/20	50-219 S	7907270322	7907270309	79/07/03	50-366 P
7907260594	7907260594	79/07/23	50-244 S	7907270328	7907270309	79/07/03	50-366 P
7907260599	7907260595	79/07/25	50-271 S	7907270332	7907270309	79/07/03	50-366 P
7907260608	7907260602	78/10/31	CONTRACT	7907270341	7907270336	79/07/05	50-366 P
7907260626	7907260618	79/06/08	CONTRACT	7907270346	7907270336	79/07/05	50-366 P
7907260631	7907260627	79/07/20	50-296 P	7907270350	7907270336	79/07/05	50-366 P
7907260639	7907260632	79/07/19	50-171 R	7907270360	7907270355	79/07/05	50-331 P
7907260640	7907260636	79/06/20	CONTRACT	7907270364	7907270355	79/07/05	50-331 P
7907260649	7907260518	79/05/21	50-361 G	7907270369	7907270355	79/07/05	50-331 P
7907260652	7907260646	79/07/23	50-333 S	7907270378	7907270375	79/07/02	50-369 G
7907260660	7907260653	79/06/25	CONTRACT	7907270380	7907270375	79/07/02	50-369 G
7907260663	7907260656	79/07/20	50-318 S	7907270381	7907270379	79/08/18	50-220 G
7907260671	7907260666	79/07/11	50-361 A	7907270382	7907270376	79/05/23	70-1738
7907260677	7907260666	79/07/11	50-361 A	7907270383	7907270375	79/07/02	50-369 G
7907260679	7907260667	79/07/20	50-293 S	7907270384	7907270384	79/06/13	50-220 G
7907260683	7907260666	79/07/11	50-361 A	7907270387	7907270375	79/07/02	50-369 G
7907260689	7907260666	79/07/11	50-361 A	7907270399	7907270392	79/08/08	50-315 G
7907260692	7907260686	79/07/19	50-293 S	7907270401	7907270393	79/07/03	50-302 G
7907260701	7907260694	79/04/19	50-596 O	7907270402	7907270393	79/07/03	50-302 G
7907260703	7907260695	79/07/19	50-293 S	7907270403	7907270393	79/07/03	50-302 G
7907260711	7907260700	79/07/11	50-320 P	7907270406	7907270393	79/07/03	50-302 G
7907260712	7907260694	79/04/19	50-596 O	7907270407	7907270392	79/05/08	50-315 G
7907260716	7907260700	79/07/11	50-320 P	7907300010	7907300008	79/08/25	50-338 G
7907260717	7907260710	79/07/23	50-213 S	7907300011	7907300001	79/05/29	50-302 P
7907260720	7907260709	79/07/19	50-237 S	7907300018	7907300008	79/08/25	50-338 G
7907260721	7907260700	79/07/11	50-320 P	7907300028	7907300021	79/05/31	50-280 G
7907260724	7907260713	79/07/20	50-272 S	7907300033	7907300030	79/06/18	50-204 P
7907260747	7907260741	79/07/23	50-333 S	7907300035	7907300030	79/06/18	50-204 P
7907260751	7907260746	79/07/19	50-366 P	7907300037	7907300032	79/05/24	50-261 G
7907260768	7907260763	78/06/27	50-458 S	7907300041	7907300038	79/05/01	50-373 G
7907260770	7907260764	79/07/20	50-259 P	7907300043	7907300040	79/05/30	50-302 G
7907260781	7907260769	02/79/06	CONTRACT	7907300046	7907300038	79/05/01	50-373 G
7907260795	7907260779	79/07/19	50-438 S	7907300050	7907300044	79/05/23	50-244 G
7907260801	7907260789	79/06/04	CONTRACT	7907300058	7907300055	79/06/08	50-498 G
7907260813	7907260799	79/07/18	50-366 S	7907300062	7907300060	79/06/15	70-1151
7907260815	7907260810	79/06/13	50-237 G	7907300064	7907300060	79/06/15	70-1151
7907260818	7907260809	79/05/31	CONTRACT	7907300070	7907300060	79/06/15	70-1151
7907260822	7907260810	79/06/13	50-237 G	7907300071	7907300067	79/06/06	50-255 G
7907260828	7907260819	79/07/20	50-259 P	7907300082	7907300075	79/05/31	50-280 G
7907260833	7907260824	79/07/18	50-366 S	7907300086	7907300083	79/06/13	50-315 G
7907260838	7907260819	79/07/20	50-259 P	7907300089	7907300077	79/07/10	50-373 G
7907260843	7907260837	79/07/20	50-259 P	7907300092	7907300083	79/06/13	50-315 G
7907260845	7907260832	01/79/06	CONTRACT	7907300094	7907300017	79/06/19	50-331 G
7907260846	7907260837	79/07/20	50-259 P	7907300095	7907300017	79/06/19	50-331 G
7907260847	7907260840	79/07/18	50-321 S	7907300096	7907300088	79/05/08	50-329 G
7907260854	7907260819	79/07/20	50-259 P	7907300101	7907300098	79/05/22	50-508 G
7907260857	7907260849	79/06/05	CONTRACT	7907300107	7907300098	79/05/22	50-508 G
7907260859	7907260761	79/05/02	50-387 G	7907300109	7907300090	79/05/11	70-2623
7907260934	7907260924	79/04/11	CONTRACT	7907300110	7907300098	79/05/22	50-508 G
7907260978	7907260965	79/06/01	50-361 G	7907300114	7907300098	79/05/22	50-508 G
7907270011	7907260999	79/06/06	50-461 G	7907300115	7907300103	79/06/06	50-267 G
7907270015	7907270009	79/06/01	50-206 G	7907300125	7907300117	79/05/16	50-344 G
7907270016	7907270008	79/06/20	50-261 G	7907300135	7907300119	79/05/16	50-344 G
7907270023	7907270008	79/06/20	50-261 G	7907300147	7907300142	79/06/18	50-346 P
7907270025	7907270018	79/06/21	CONTRACT	7907300152	7907300142	79/06/18	50-346 P
7907270041	7907270034	79/06/26	CONTRACT	7907300157	7907300142	79/06/18	50-346 P
7907270043	7907270036	79/05/15	50-364 G	7907300160	7907300148	79/06/11	50-220 G
7907270051	7907270027	79/06/21	CONTRACT	7907300166	7907300148	79/06/11	50-220 G
7907270053	7907270049	79/05/22	50-261 G	7907300168	7907300156	79/07/18	FOIA
7907270083	7907270076	79/06/11	CONTRACT	7907300175	7907300148	79/06/11	50-220 G
7907270101	7907270093	79/05/07	CONTRACT	7907300180	7907300156	79/07/18	FOIA
7907270115	7907270104	79/06/05	50-304 G	7907300181	7907300148	79/06/11	50-220 G
7907270118	7907270110	79/06/05	50-267 G	7907300194	7907300191	79/06/13	50-266 G
7907270133	7907270127	79/06/07	50-263 G	7907300205	7907300200	79/06/08	71-6698
7907270141	7907270140	79/05/15	50-275 G	7907300206	7907300156	79/07/18	FOIA
7907270173	7907270189	79/06/18	50-295 P	7907300208	7907300200	79/06/08	71-6698
7907270194	7907270190	79/07/17	50-289 R	7907300211	7907300156	79/07/18	FOIA

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907300215	7907300200	79/06/00	71-469B	7907300569	7907300564	79/06/14	CONTRACT
7907300216	7907300156	79/07/18	FOIA	7907300571	7907300522	79/06/14	50-311 S
7907300227	7907300156	79/07/18	FOIA	7907300583	7907300414	79/07/03	50-312 H
7907300233	7907300233	79/06/19	50-344 Q	7907310008	7907310006	79/06/29	50-213 Q
7907300235	7907300156	79/07/18	FOIA	7907310010	7907310003	79/07/05	50-338 Q
7907300236	7907300229	79/06/20	50-445 Q	7907310011	7907310006	79/06/29	50-213 Q
7907300249	7907300156	79/07/18	FOIA	7907310014	7907310006	79/06/29	50-213 Q
7907300250	7907300242	79/05/14	50-445 Q	7907310017	7907310006	79/06/29	50-213 Q
7907300253	7907300156	79/07/18	FOIA	7907310027	7907310023	79/05/02	50-29 Q
7907300256	7907300242	79/05/14	50-445 Q	7907310028	7907310015	79/06/13	50-331 Q
7907300258	7907300253	79/07/18	FOIA	7907310039	7907310005	79/06/13	50-339 A
7907300260	7907300245	79/05/14	70-25	7907310053	7907310048	79/06/18	COMMISSION
7907300262	7907300233	79/07/18	FOIA	7907310057	7907310051	79/06/08	CONTRACT
7907300268	7907300156	79/07/18	FOIA	7907310071	7907310064	79/07/18	50-320 P
7907300271	7907300261	79/06/04	CONTRACT	7907310086	7907310080	79/06/13	50-234 Q
7907300285	7907300274	79/06/01	50-263 Q	7907310090	7907310073	79/07/10	CONTRACT
7907300293	7907300287	79/07/24	50-247 S	7907310096	7907310080	79/06/13	50-234 Q
7907300307	7907300297	79/07/18	50-368 S	7907310104	7907310091	79/06/29	50-463 U
7907300312	7907300310	79/07/24	50-293 S	7907310107	7907310094	79/06/29	50-333 Q
7907300317	7907300314	79/06/20	71-292	7907310115	7907310094	79/06/29	50-333 Q
7907300323	7907300321	79/07/20	50-348 P	7907310121	7907310094	79/06/29	50-333 Q
7907300328	7907300326	79/06/13	50-367 Q	7907310126	7907310117	79/05/16	50-466 Q
7907300337	7907300325	79/07/25	50-316 S	7907310130	7907310094	79/06/29	50-333 Q
7907300338	7907300280	79/06/21	50-295 Q	7907310136	7907310122	79/06/29	50-382 U
7907300339	7907300331	79/06/11	50-263 Q	7907310158	7907310023	79/05/02	50-29 Q
7907300342	7907300265	79/06/21	50-280 Q	7907310159	7907310155	79/03/29	50-259 Q
7907300358	7907300344	79/07/20	50-302 S	7907310163	7907310023	79/05/02	50-29 Q
7907300360	7907300355	79/07/03	50-390 Q	7907310164	7907310145	79/04/29	50-275 U
7907300372	7907300364	79/06/18	50-410 Q	7907310165	7907310155	79/03/29	50-259 Q
7907300373	7907300366	79/07/27	50-344 F	7907310167	7907310023	79/05/02	50-29 Q
7907300374	7907300364	79/06/18	50-410 Q	7907310171	7907310023	79/05/02	50-29 Q
7907300375	7907300362	79/07/26	50-16 R	7907310178	7907310023	79/05/02	50-29 Q
7907300378	7907300364	79/06/18	50-410 Q	7907310183	7907310177	79/06/01	50-272 P
7907300385	7907300364	79/06/18	50-410 Q	7907310185	7907310172	79/06/29	50-346 U
7907300395	7907300387	79/07/13	50-358 F	7907310187	7907310177	79/06/01	50-272 P
7907300398	7907300383	79/07/24	50-255 S	7907310189	7907310180	79/06/14	50-116 Q
7907300406	7907300400	79/07/06	50-346 Q	7907310190	7907310181	79/06/20	50-338 Q
7907300409	7907300393	79/07/24	50-247 P	7907310193	7907310172	79/06/29	50-346 U
7907300412	7907300403	79/06/13	50-305 Q	7907310194	7907310181	79/06/20	50-338 Q
7907300415	7907300410	79/06/15	50-201 I	7907310196	7907310177	79/06/01	50-272 P
7907300417	7907300411	79/07/11	50-346 S	7907310198	7907310181	79/06/20	50-338 Q
7907300418	7907300410	79/06/15	50-201 I	7907310203	7907310181	79/06/20	50-338 Q
7907300424	7907300410	79/06/15	50-201 I	7907310206	7907310197	79/06/14	50-315 Q
7907300427	7907300410	79/06/15	50-201 I	7907310211	7907310202	79/06/29	50-382 U
7907300428	7907300423	79/07/27	50-324 S	7907310222	7907310213	79/06/14	50-358 Q
7907300430	7907300419	79/06/11	50-305 Q	7907310232	7907310224	79/06/12	50-321 P
7907300431	7907300425	79/07/11	50-346 Q	7907310236	7907310224	79/06/12	50-321 P
7907300434	7907300410	79/06/15	50-201 I	7907310239	7907310224	79/06/12	50-321 P
7907300435	7907300426	79/06/27	50-312 P	7907310253	7907310244	79/06/29	50-382 U
7907300438	7907300425	79/07/11	FOIA	7907310269	7907310246	79/07/27	50-596 B
7907300440	7907300410	79/06/15	50-201 I	7907310271	7907310261	79/06/29	50-338 U
7907300444	7907300410	79/06/15	50-201 I	7907310277	7907310261	79/06/29	50-338 U
7907300446	7907300426	79/06/27	50-312 P	7907310280	7907310274	79/07/17	50-361 A
7907300450	7907300445	79/06/27	50-312 P	7907310286	7907310274	79/07/17	50-361 A
7907300451	7907300442	79/06/14	50-361 Q	7907310294	7907310269	79/07/06	50-377 K
7907300460	7907300454	79/07/03	50-302 P	7907310308	7907310299	79/07/26	50-255 P
7907300463	7907300454	79/07/03	50-302 P	7907310317	7907310313	79/07/23	TOPREP
7907300466	7907300410	79/06/15	50-201 I	7907310323	7907310315	79/06/06	50-348 Q
7907300475	7907300465	79/05/07	COMMISSION	7907310336	7907310329	79/06/04	50-266 P
7907300476	7907300454	79/07/03	50-302 P	7907310357	7907310327	79/07/30	50-482 A
7907300478	7907300472	79/06/06	50-298 Q	7907310365	7907310327	79/07/30	50-482 A
7907300484	7907300472	79/06/06	50-298 Q	7907310372	7907310364	79/07/24	50-272 S
7907300485	7907300459	79/06/07	CONTRACT	7907310373	7907310359	79/07/19	50-346 S
7907300488	7907300416	79/07/11	50-346 Q	7907310393	7907310392	79/07/23	50-128 R
7907300490	7907300487	79/05/30	71-99	7907310427	7907310424	79/07/27	50-280 S
7907300492	7907300410	79/06/15	50-201 I	7907310431	7907310429	79/07/30	50-388 A
7907300494	7907300416	79/07/11	50-346 Q	7907310436	7907310430	79/07/27	50-338 S
7907300497	7907300410	79/06/15	50-201 I	7907310453	7907310444	79/07/25	50-313 S
7907300500	7907300410	79/06/15	50-201 I	7907310465	7907310437	79/06/14	TOPREP
7907300505	7907300498	79/06/30	CONTRACT	7907310473	7907310422	79/07/19	50-346 S
7907300509	7907300410	79/06/15	50-201 I	7907310500	7907310492	79/06/01	COMMISSION
7907300510	7907300510	79/06/14	CONTRACT	7907310504	7907310498	79/07/10	CONTRACT
7907300513	7907300410	79/06/15	50-201 I	7907310508	7907310492	79/06/01	COMMISSION
7907300517	7907300410	79/06/15	50-201 I	7907310514	7907310492	79/06/01	COMMISSION
7907300521	7907300410	79/06/15	50-201 I	7907310526	7907310488	79/05/16	50-361 Q
7907300523	7907300410	79/06/15	50-201 I	7907310527	7907310492	79/06/01	COMMISSION
7907300526	7907300481	79/06/21	50-305 Q	7907310550	7907310466	79/06/13	50-266 P
7907300532	7907300410	79/06/15	50-201 I	7907310551	7907310541	79/06/06	COMMISSION
7907300534	7907300529	79/05/23	CONTRACT	7907310552	7907310537	79/06/20	50-313 Q
7907300536	7907300410	79/06/15	50-201 I	7907310556	7907310541	79/06/06	COMMISSION
7907300538	7907300410	79/06/15	50-201 I	7907310572	7907310566	79/05/18	50-438 Q
7907300544	7907300410	79/06/15	50-201 I	7907310574	7907310561	79/06/18	50-498 Q
7907300545	7907300539	79/06/19	50-409 Q	7907310578	7907310564	79/06/06	COMMISSION
7907300559	7907300557	79/06/05	CONTRACT	7907310581	7907310566	79/05/18	50-338 Q

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907310587	7907310566	79/05/18	50-338 P
7907310589	7907310573	79/05/14	FOIA
7907310603	7907310598	79/06/14	50-482 G

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7907310617	7907310614	79/06/08	50-131 P
7907310621	7907310606	79/06/06	COMMISSION
7907310622	7907310613	79/06/06	71-279

## APPENDIX A

### DEFINITIONS OF DOCKET 50 CATEGORIES

#### A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Correspondence and documents relating to unresolved design and construction issues.
2. Meeting announcements and summaries of meeting discussions on issues of item 1.
3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
4. NRC questions, requests for additional information, and applicant responses.
5. Applicant's Quality Assurance Manual.
6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
7. Federal Register notices that do not apply to other categories.
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Scheduling of license application submission or review.
10. Reports of site visits.
11. Backup technical documents (i.e., topical reports) submitted in support of the application.
12. Early site review information.
13. Construction Permit, amendments and correspondence relating to construction permit.
14. Environmental review information.
15. Construction permit.

#### B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt.
5. Hazards Summary Report submitted by utility (now designated PSAR).

6. Safety Analysis Report submitted by utility (now designated PSAR).
7. Certificates of Service of PSAR.

**C. Utility Environmental Report (ER), Amendments and Correspondence**

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal Register notice citing availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

**D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence**

1. Draft and Final Environmental (Impact) Statements (DES and FES).
2. Supplements to DES and FES.
3. Correspondence relating to the DES or FES.
4. Comments from other federal, state, and local government agencies.
5. Transmittal letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Notices of availability of above.
9. Draft of detailed statement.

**E. NRC Safety Evaluation Report (SER), Supplements and Correspondence**

1. Safety Evaluation Report (SER).
2. Supplements to SER.
3. Correspondence relating to SER.



4. Notices advising of the availability of 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
8. Transmittal letters.
9. Comments from other agencies relative to safety review.
10. NRC-AEC Hazard Analysis Reports (now designated SER).

#### **F. Security, Medical, Emergency, and Fire-Protection Plans**

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

1. Correspondence relating to plans.
2. Supplements, changes, and revisions to plans.
3. Fire Hazard Protection Plan and Surveys.

#### **G. Adjudicatory Correspondence**

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and anti-trust hearings (Category N).

1. ASLB hearing and review documents.
2. Correspondence to and from intervenors.
3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
4. Board orders and decisions.
5. Requests to make appearances at hearings.
6. Transmittal of supporting documents (i.e., SER, FES) to the board.
7. Federal Register notices regarding hearings.
8. Requests for a hearing.
9. Petitions from participants (including petition for request for extension).
10. Corrections to transcripts.
11. Professional qualifications, if presented at a hearing.

12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.
13. Hearing index

#### **H. General correspondence**

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Qualification statements of new employees.
2. Change of address notifications
3. Changes in organization.
4. Changes in service lists, "Certificate of Service" documents (without a document attached).
5. NRC requests to applicant for additional copies of documents.
6. Correspondence from the public in support of or requesting information about the facility.
7. Letters of "concern" (NOT "opposition") and response thereto.
8. Correspondence on strictly administrative matters.
9. Correspondence regarding the local Public Document Room.
10. Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).
11. Press releases from applicant.
12. Any other material that fits the criteria given above.
13. Professional qualifications (resumes).

#### **I. Financial Information**

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

#### **J. Insurance and Indemnity Information**

1. All correspondence and documentation regarding indemnity and insurance.
2. Endorsements to insurance policies.
3. NELPIA -- Nuclear Energy Liability Property Insurance information.

#### **K. Utility Final Safety Analysis Report (FSAR) and Amendments**

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR).
2. Amendments and changes to the FSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of items.
5. Hazards Final Summary Report (now designated FSAR).
6. Certificates of Service of FSAR.

#### **L. Limited Work Authorization and Related Correspondence**

This category is limited to items issued before the construction permit is granted.

1. Limited Work Authorizations.
2. Environmental exemptions.
3. Correspondence relating to 1 and 2.
4. All information concerning site preparation prior to the issuance of a construction permit.

#### **M. Antitrust Correspondence**

1. All material concerning antitrust except hearing transcripts (category N)
2. All material marked with an A immediately following the docket number. The A signifies antitrust proceedings.

#### **N. Antitrust Hearing Transcripts**

This category contains only word-for-word transcripts of hearings in antitrust matters. In most cases they will be marked with an A following the docket number. Related correspondence falls in category M.

#### **O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence**

1. Correspondence and letter reports relating to ACRS reviews
2. Correspondence from ACRS
3. Announcements of ACRS meetings

4. Transmittal letters to ACRS
5. ACRS reports.

**P. Operating License Stage Documents and Correspondence**

Thus file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

1. Operating license, amendments, proposed amendments, and changes.
2. Technical specifications and changes.
3. Announcements of issuance of 1 and 2.
4. Transmittal letters.
5. All general technical correspondence relating to technical specifications or operating license.
6. License conditions.
7. Operator licenses or administrative information bearing on the licensing of operators.
8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
10. Information on the Standard Review Plan (SRP).
11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
12. Requests for issuance of operating license.
13. Requests for copies of items 1 and 2 and responses.
14. Correspondence on generic technical issues.
15. Owner's group meeting announcements and reports.
16. Orders for modification of license.
17. Requests for extension date of license or license modification.
18. Quality assurance information.
19. Environmental matters (technical).
20. Emergency core cooling system.
21. Radioactive waste information.

**Q. Inspection Reports, IE Bulletins and Correspondence**

1. Inspection reports.
2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
7. In-service inspections.
8. Regulatory Operations (RO) Bulletins.

**R. Periodic Operating Reports and Related Correspondence**

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual reports (other than financial)
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Gray Book Information.
4. Operational Logbooks:
  - Logbooks on Environmental Data
  - Logbooks of Radiological Data
  - Operations Log on Plant Systems Core
  - Plant Status Summary Sheets
5. Correspondence or other documents relating to the above listed items.

**S. Reportable Occurrences, LERs and Related Correspondence**

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

#### **T. Hearing Transcripts on Non-Antitrust Matters**

This category contains word-for-word transcripts, corrections to the transcript, attachments and Vu-Graphs. Examples of non-antitrust matters include:

1. ASLB hearings.
2. Commission Meetings.
3. Commission Briefings.
4. Telephone conversations.

#### **U. Congressional/Executive Correspondence**

1. Testimony before Congress.
2. Preparatory and backup documents for Congressional testimony.
3. Letters to and from Congress and the Executive Branch.
4. Responses to letters from members of Congress and the Executive Branch.
5. Correspondence to and from the NRC Office of Congressional Affairs.

#### **V. Operator Examinations**

1. NRC Examination Results.
2. Power Plant Examination Summary Sheet.
3. Related correspondence.

## **APPENDIX B**

### **DEFINITIONS OF NONDOCKETED CATEGORIES**

#### **10CFR – Commission Meeting Records**

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

#### **ACRS – Advisory Committee on Reactor Safeguards**

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

#### **AGREEMENT – State Agreements and Programs**

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### **COMMISSION – NRC Commissioners**

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

#### **CONTRACT – NRC Contracts and Modifications**

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

#### **FOIA – Freedom of Information Act Requests and Releases**

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:



1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

#### **GEN TECH IS — Generic Technical Issues**

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

#### **I&E — Inspection and Enforcement**

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

**NOTE:** For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

#### **NUREG — NUREG Reports and Related Correspondence**

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:

- a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
  3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

#### **ORG – Correspondence with Other Organizations**

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

**NOTE:** For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### **PR – Proposed Rule**

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.

4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

#### **PRM — Petition for Rulemaking**

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.
3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

**NOTE:** For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### **PROJ — Projects—Predocket Licensing**

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

##### **A. Application/Construction Stage**

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

**B. Utility PSAR and Amendments**

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

**G. Adjudicatory Correspondence**

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

**M. Antitrust Correspondence**

1. Submittals and related material pertaining to the antitrust review.

**Q. Inspection Reports**

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

**2. Government-owned reactors**

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

**PT21 – Noncompliance Reports and Related Correspondence**

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

**QA999 – Quality Assurance Inspections**

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling

criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include.

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### **REGGD — Regulatory Guides**

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

**NOTE:** For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### **RES — Research and Technical Assistance Reports**

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.

7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

#### **REVIEW GRP – NRC Research Review Groups**

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

#### **RM – Rulemakings**

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

## **SECY    Position Papers Before the Commission**

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

**NOTE:** For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

## **TOPREP    Vendor Reports and Related Correspondence**

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

**NOTE:** For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

## **WASTE MGT -- Nuclear Waste Management**

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

## **XPORTLIC – Export and Import Licenses**

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE. For transcripts of Commission meetings and papers submitted for Commission consideration or information, see 10CFR category.



U.S. NUCLEAR REGULATORY COMMISSION  
BIBLIOGRAPHIC DATA SHEET

1 REPORT NUMBER (Assigned by DDC)

NUREG-0540 Vol.1 No.7

4. TITLE AND SUBTITLE (Add Volume No., if appropriate)

Title List of Documents Made Publicly Available

2 (Leave blank)

3 RECIPIENT'S ACCESSION NO.

7. AUTHOR(S)

5. DATE REPORT COMPLETED

MONTH August YEAR 1979

9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

DATE REPORT ISSUED

MONTH September YEAR 1979

6 (Leave blank)

8. (Leave blank)

12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

same as #9

10 PROJECT/TASK/WORK UNIT NO

11. CONTRACT NO.

13. TYPE OF REPORT

Monthly

PERIOD COVERED (Inclusive dates)

July 1-31, 1979

15. SUPPLEMENTARY NOTES

14 (Leave blank)

16. ABSTRACT (200 words or less)

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through U.S. DOE's Technical Information Center under the title Power Reactor Docket Information (PRDI). This document replaces PRDI, which will no longer be prepared. It is indexed by a Personal Author Index, Corporate Source Index, U.S. NRC Organizational Source Index and Personal Author Index.

17. KEY WORDS AND DOCUMENT ANALYSIS

17a DESCRIPTORS

b. IDENTIFIERS/OPEN-ENDED TERMS

AVAILABILITY STATEMENT

Unlimited

19. SECURITY CLASS (This report)  
Unclassified20. SECURITY CLASS (This page)  
Unclassified

21. NO. OF PAGES

22. PRICE  
\$